

Unit Job History

Michels Corporation
Report Printed: 15-Aug-2023 09:56:42 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: T0366 - 2000 FORD 3930										
04-Jun-2008 0'	175	0	1282	24-015-005	Repair Power Steering Pump	01-Jul-2008 12:34:53	BBKH0E	I	DON	0.00
04-Jun-2008 0'	175	0	1282	24-030	Repair Electrical Group	01-Jul-2008 12:34:53	BBKH0E	I	DON	37.37
04-Jun-2008 0'	175	0	1282	38-100-001	Service DO NOT USE - PMI Service	04-Jun-2008 08:59:05	BBKH0E	P	DON	32.59
08-Jul-2008 09	175	0	2017	03-002-027	Replace Seat Frames & Springs	08-Jul-2008 11:36:52	BBKH0E	M	DON	111.68
16-Jul-2008 11	182	0	2186	03-034-001	Replace Headlamps / Fog Lamps	16-Jul-2008 14:40:15	BBKH0E	I	DON	9.84
28-Apr-2009 1	230	0	12445	03-002-027	Replace Seat Frames & Springs	06-May-2009 15:33:12	BBKH0E	I	DON	137.93
28-Apr-2009 1	230	0	12445	24-015-005	Repair Power Steering Pump	05-May-2009 09:21:23	BBKH0E	I	DON	114.66
28-Apr-2009 1	230	0	12445	24-040	Repair Engine / Motor Systems Group	30-Apr-2009 12:01:15	BBKH0E	I	DON	210.51
28-Apr-2009 1	230	0	12445	38-100-001	Service DO NOT USE - PMI Service	05-May-2009 09:21:35	BBKH0E	P	DON	43.03
18-Aug-2009 0	231	0	19445	06-100-001	Inspect DO NOT USE - PMI Service	18-Aug-2009 10:33:56	BBKH0E	P	DON	39.95
15-Apr-2010 1	235	0	38685	03-031-001	Replace Generator/Alternator	16-Apr-2010 07:57:42	BBKH0E	I	DON	230.13
15-Apr-2010 1	235	0	38685	14-315-007	Install Implement	15-Apr-2010 17:26:41	BBKH0E	Q	DON	69.19
31-Aug-2010 0	242	0	48982	31-315-007	Rotate Implement	31-Aug-2010 13:06:52	BBKH0E	Q	DON	117.26
20-May-2011 1	261	0	65893	14-513-004	Install Specialty Attachment	20-May-2011 17:05:48	BBKH0E	Q	DON	27.72
20-May-2011 1	261	0	65893	24-513-004	Repair Specialty Attachment	13-Jul-2011 13:48:50	BBKH0E	Q	DON	128.16
20-May-2011 1	261	0	65893	25-513-004	Remove Specialty Attachment	05-Jul-2011 15:00:00	BBKH0E	J	DON	106.37
30-Apr-2012 0	298	0	86965	14-513-004	Install Specialty Attachment	30-Apr-2012 14:07:30	BBKH0E	Q	DON	41.30
30-Apr-2012 0	298	0	86965	25-513-004	Remove Specialty Attachment	30-Apr-2012 12:43:44	BBKH0E	J	DON	16.59
18-May-2012 0	302	0	88334	31-513-004	Rotate Specialty Attachment	19-May-2012 09:41:08	BBKH0E	Q	DON	68.36
18-May-2012 0	302	0	88334	38-100	Service PMI	18-May-2012 14:00:53	BBKH0E	P	DON	45.79
08-Jun-2012 0'	303	0	89735	24-044-008	Repair Engine Shutdown	08-Jun-2012 09:00:00	BBKH0E	O	DON	104.56
05-Jul-2012 12	303	0	91459	14-513-004	Install Specialty Attachment	11-Mar-2013 09:46:45	BBKH0E	Q	CAN	0.00
11-Mar-2013 0	304	0	115291	06-100-301	Inspect Annual Service	11-Mar-2013 09:46:45	BVLOFC	P	DON	27.74
22-Aug-2013 0	304	0	129883	03-063-003	Replace Transceiver - GPS Tracker	22-Aug-2013 00:00:00	BBKH0E	C	DON	244.36
02-Apr-2014 0	305	0	155220	03-032-001	Replace Battery	02-Apr-2014 17:00:00	LAKEVL	F	DON	21.01
11-Sep-2015 0'	306	0	214256	03-032-001	Replace Battery	16-Sep-2015 06:18:21	BBKH0E	I	DON	111.43
11-Sep-2015 0'	306	0	214256	38-100-PMMA	Service A PMI	16-Sep-2015 06:18:17	BBKH0E	P	DON	123.68
12-Jun-2017 11	321	0	292466	03-002-027	Replace Seat Frames & Springs	12-Jul-2017 17:08:45	BBKH0E	I	DON	183.06

Unit Job History

Michels Corporation
Report Printed: 15-Aug-2023 09:56:42 By User: RHEENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: T0366 - 2000 FORD 3930										
12-Jun-2017 11	321	0	292466	03-026-016	Replace Gear Shifter & Linkage	12-Jul-2017 17:08:40	BBKH0E	I	DON	266.32
12-Jun-2017 11	321	0	292466	24-026-016	Repair Gear Shifter & Linkage	12-Jul-2017 17:08:35	BBKH0E	I	DON	674.19
12-Jun-2017 11	321	0	292466	24-034-006	Repair Warning Lamps - Special Application	12-Jul-2017 17:08:28	BBKH0E	I	DON	189.50
12-Jun-2017 11	321	0	292466	06-100-PMA	Inspect A PMI	12-Jul-2017 17:08:23	BBKH0E	P	DON	254.38
20-Nov-2017 1	324	0	313201	14-513-004	Install Specialty Attachment	03-Apr-2018 17:03:12	BBKH0E	Q	DON	261.06
13-Jul-2018 05	324	0	343615	06-032-002	Inspect Starter	13-Jul-2018 18:37:00	BHVEEQ	J	DON	323.62
13-Jul-2018 05	324	0	343615	24-052-005	Repair Transmitter - CB	16-Jul-2018 10:21:41	BHVEEQ	O	DON	26.76
27-Jul-2018 13	335	0	345718	03-031-001	Replace Generator/Alternator	27-Aug-2018 13:07:33	BBKH0E	I	DON	91.07
27-Jul-2018 13	335	0	345718	03-032-001	Replace Battery	27-Aug-2018 13:07:21	BBKH0E	I	DON	315.87
27-Jul-2018 13	335	0	345718	06-315	Inspect Tractor - Farm / Implement	03-Aug-2018 06:18:07	BBKH0E	I	DON	153.33
27-Jul-2018 13	335	0	345718	24-037-011	Repair Relay - Multiple Use	27-Aug-2018 13:07:28	BBKH0E	I	DON	143.60
24-Jan-2019 06	335	0	369663	03-013-007	Replace Brake Lines & Fittings - Hydraulic & A	29-Jan-2019 07:52:12	BBKH0E	I	DON	471.51
24-Jan-2019 06	335	0	369663	06-100-PMB	Inspect B PMI	29-Jan-2019 10:05:11	BBKH0E	P	DON	293.80
24-Jan-2019 06	335	0	369663	14-032-001	Install Battery	28-Jan-2019 11:23:25	BBKH0E	I	DON	208.50
24-Jan-2019 06	335	0	369663	14-032-009	Install Switch - Master Disconnect	28-Jan-2019 14:30:27	BBKH0E	I	DON	139.26
24-Jan-2019 06	335	0	369663	21-509-002	Fabricate Safety Guard	25-Jan-2019 17:01:11	BBKH0E	I	DON	80.62
24-Jan-2019 06	335	0	369663	24-026-009	Repair Cover Assembly	25-Jan-2019 15:40:29	BBKH0E	I	DON	238.26
24-Jan-2019 06	335	0	369663	24-032	Repair Cranking System	29-Jan-2019 09:54:19	BBKH0E	I	DON	123.40
24-Jan-2019 06	335	0	369663	24-034-001	Repair Headlamps / Fog Lamps	24-Jan-2019 15:41:58	BBKH0E	I	DON	53.41
24-Jan-2019 06	335	0	369663	24-034-006	Repair Warning Lamps - Special Application	24-Jan-2019 17:00:30	BBKH0E	I	DON	61.42
24-Jan-2019 06	335	0	369663	38-065-006	Service Filters, Strainers, Screens & Housing	29-Jan-2019 08:48:30	BBKH0E	I	DON	50.28
07-Oct-2019 06	406149	0	406149	03-031-001	Replace Generator/Alternator	11-Oct-2019 11:16:19	BBKH0E	I	DON	225.29
07-Oct-2019 06	406149	0	406149	03-031-006	Replace Belt - Alternator	11-Oct-2019 11:16:12	BBKH0E	I	DON	157.34
07-Oct-2019 06	406149	0	406149	03-032-001	Replace Battery	11-Oct-2019 11:16:15	BBKH0E	I	DON	208.78
08-Jun-2021 0	511333	0	511333	24-063-003	Repair Transceiver - GPS Tracker	08-Jun-2021 07:59:35	ELEEC03	Q	DON	13.96
19-Apr-2022 1	582776	0	582776	03-063-003	Replace Transceiver - GPS Tracker	19-Apr-2022 13:27:36	ELEEC02	Q	DON	328.50
10-Aug-2023 1	347	0	695646	03-032-001	Replace Battery	11-Aug-2023 05:34:41	BHVEEQ	I	DON	287.89
10-Aug-2023 1	347	0	695646	06-100-PMA	Inspect A PMI	11-Aug-2023 05:34:38	BBKH0E	P	DON	58.90
10-Aug-2023 1	347	0	695646	38-100-PMA	Service A PMI	11-Aug-2023 05:34:40	BBKH0E	P	DON	117.56

Unit Job History

Michels Corporation
Report Printed: 15-Aug-2023 09:56:42 By User: RHENNING

Unit No: T0366

Count: 58

8,250.38