

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Q1279 - 2017 JOHN DEERE 310HL										
05-Jan-2017 11	2	0	272040	14-059-002	Install Pintle Hook Assembly	06-Apr-2017 10:42:57	BBKHOE	Q	DON	439.60
05-Jan-2017 11	2	0	272040	14-063-003	Install Transceiver - GPS Tracker	06-Apr-2017 10:42:51	BBKHOE	Q	DON	258.29
05-Jan-2017 11	2	0	272040	IS-310	In-Service Backhoe (Rubber Tire)	06-Apr-2017 10:43:02	BBKHOE	Q	DON	343.14
17-Jan-2017 07	2	0	276514	38-017-011	Service Tire - Foam Filled	17-Jan-2017 07:23:23	BTIRE	F	DON	1,034.22
08-Nov-2017 1	965	0	311855	03-041-006	Replace Filter - Inner	09-Nov-2017 12:48:29	ROGSHP	P	DON	22.95
08-Nov-2017 1	965	0	311855	03-041-007	Replace Filter - Outer	09-Nov-2017 12:51:08	ROGSHP	P	DON	28.91
08-Nov-2017 1	965	0	311855	07-100-PMA	Lubricate A PMI	09-Nov-2017 12:34:54	ROGSHP	P	DON	27.47
08-Nov-2017 1	965	0	311855	07-100-PMB	Lubricate B PMI	10-Nov-2017 06:10:06	ROGSHP	P	DON	106.88
08-Mar-2018 1	980	0	326612	03-065-007	Replace Hoses & Fittings	20-Mar-2018 13:42:37	LAVSHP	I	DON	385.24
08-Mar-2018 1	980	0	326612	03-310-017	Replace Cutting Edges	20-Mar-2018 13:43:07	LAVSHP	I	DON	268.32
08-Mar-2018 1	980	0	326612	06-310	Inspect Backhoe (Rubber Tire)	20-Mar-2018 13:42:30	LAVSHP	S	DON	303.25
08-Mar-2018 1	980	0	326612	10-310-001	Rebush Boom (Main)	20-Mar-2018 13:42:46	LAVSHP	I	DON	2,385.56
08-Mar-2018 1	980	0	326612	10-310-002	Rebush Boom (Dipper)	20-Mar-2018 13:42:40	LAVSHP	I	DON	1,356.36
08-Mar-2018 1	980	0	326612	35-042	Diagnose Cooling System	20-Mar-2018 13:42:43	LAVSHP	I	DON	339.99
08-Mar-2018 1	980	0	326612	35-065	Diagnose Hydraulic Systems - Special Applicati	20-Mar-2018 13:42:34	LAVSHP	I	DON	194.69
11-Oct-2018 01	1,654	0	356137	03-065-007	Replace Hoses & Fittings	16-Oct-2018 11:43:56	LAVSHP	B	DON	420.27
24-Oct-2018 1	2,043	0	358012	03-017-001	Replace Tire - Pneumatic	05-Nov-2018 08:59:56	BTIRE	P	DON	2,241.99
24-Oct-2018 1	2,043	0	358012	03-065-007	Replace Hoses & Fittings	05-Nov-2018 08:59:47	LAVSHP	B	DON	1,550.18
24-Oct-2018 1	2,043	0	358012	03-112-006	Replace Outrigger Assembly	30-Oct-2018 16:54:42	LAVSHP	B	DON	48.31
24-Oct-2018 1	2,043	0	358012	11-065-004	Rebuild Cylinder	05-Nov-2018 08:59:56	LAVSHP	I	DON	937.95
29-Nov-2018 1	2,232	0	362283	03-310-017	Replace Cutting Edges	29-Nov-2018 11:48:34	LAVSHP	E	DON	341.96
06-Dec-2018 1	2,286	0	363378	01-042-012	Adjust Clamps and Hoses	27-Dec-2018 14:02:42	LAVSHP	I	DON	185.38
06-Dec-2018 1	2,286	0	363378	03-310-005	Replace Boom Lock	27-Dec-2018 14:02:39	LAVSHP	I	DON	67.49
06-Dec-2018 1	2,286	0	363378	03-310-007	Replace Outrigger Pads	27-Dec-2018 14:02:57	LAVSHP	I	DON	811.06
06-Dec-2018 1	2,286	0	363378	06-049-001	Inspect ECM Fault Code	06-Dec-2018 17:43:23	LAVSHP	I	DON	29.95
06-Dec-2018 1	2,286	0	363378	06-310	Inspect Backhoe (Rubber Tire)	27-Dec-2018 14:02:54	LAVSHP	P	DON	181.32
06-Dec-2018 1	2,286	0	363378	24-027-039	Repair Cooler Assembly	27-Dec-2018 14:02:49	LAVSHP	I	DON	193.20
06-Dec-2018 1	2,286	0	363378	24-065-013	Repair Pump - Gear Type	27-Dec-2018 14:02:52	LAVSHP	I	DON	194.11
06-Dec-2018 1	2,286	0	363378	24-065-020	Repair Control Valve	27-Dec-2018 14:02:30	LAVSHP	I	DON	251.16

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Q1279 - 2017 JOHN DEERE 310HL										
06-Dec-2018	2,286	0	363378	24-310-006	Repair Outriggers	27-Dec-2018 14:02:33	LAVSHP	I	DON	167.44
06-Dec-2018	2,286	0	363378	34-042-008	Reseal Oil Cooler	27-Dec-2018 14:02:45	LAVSHP	I	DON	189.57
06-Dec-2018	2,286	0	363378	34-065-004	Reseal Cylinder	27-Dec-2018 14:02:37	LAVSHP	I	DON	2,092.59
06-Dec-2018	2,286	0	363378	35-049-001	Diagnose ECM Fault Code	27-Dec-2018 14:03:00	LAVSHP	B	DON	1,544.98
17-Jan-2019	2,291	0	370758	06-100-PMC	Inspect C PMI	08-Feb-2019 14:59:33	LAVSHP	P	DON	658.17
17-Jan-2019	2,291	0	370758	06-310	Inspect Backhoe (Rubber Tire)	08-Feb-2019 14:59:29	LAVSHP	P	DON	38.84
17-Jan-2019	2,291	0	370758	03-017-011	Replace Tire - Foam Filled	18-Jan-2019 09:29:00	BTIRE	P	DON	1,966.03
13-Nov-2019	3,330	0	412486	03-310-017	Replace Cutting Edges	13-Nov-2019 13:13:16	LAVSHP	I	DON	236.49
13-Nov-2019	3,330	0	412486	06-100-PMA	Inspect A PMI	13-Nov-2019 12:14:54	LAVSHP	P	DON	11.42
13-Nov-2019	3,330	0	412486	38-100-PMA	Service A PMI	13-Nov-2019 12:50:35	LAVSHP	I	DON	97.18
13-Dec-2019	3,392	0	416878	06-100-PMA	Inspect A PMI	17-Dec-2019 07:12:57	ROGSHP	P	DON	0.00
13-Dec-2019	3,392	0	416878	38-100-PMA	Service A PMI	13-Dec-2019 15:56:44	ROGSHP	P	DON	285.33
15-Jan-2020	3,442	0	421928	06-100-PMB	Inspect B PMI	20-Jan-2020 13:46:44	LAVSHP	P	DON	36.99
15-Jan-2020	3,442	0	421928	38-100-PMC	Service C PMI	20-Jan-2020 13:46:41	LAVSHP	P	DON	739.22
20-May-2020	3,568	0	441620	06-100-PMB	Inspect B PMI	20-May-2020 10:39:36	ME1371	P	DON	11.51
20-May-2020	3,568	0	441620	38-100-PMB	Service B PMI	20-May-2020 10:07:20	ME1371	P	DON	105.89
10-Jun-2020	3,610	0	444805	24-065-007	Repair Hoses & Fittings	10-Jun-2020 14:44:55	ME1371	B	DON	7.02
27-Jul-2020	3,659	0	452680	06-100-PMA	Inspect A PMI	27-Jul-2020 11:49:48	ROGSHP	P	DON	48.18
21-Sep-2020	3,757	0	462453	03-024-005	Replace Universal Joint	24-Sep-2020 11:56:59	LAVSHP	I	DON	242.23
21-Sep-2020	3,757	0	462453	03-065-007	Replace Hoses & Fittings	21-Sep-2020 14:54:34	LAVSHP	I	DON	73.28
21-Sep-2020	3,757	0	462453	06-100-009	Inspect Safety Check	21-Sep-2020 11:19:42	LAVSHP	P	DON	42.95
19-Jan-2021	3,763	0	483138	03-017-001	Replace Tire - Pneumatic	27-Jan-2021 11:58:05	LAVSHP	O	DON	3,624.38
18-Mar-2021	3,715	0	495155	06-100-PMA	Inspect A PMI	19-Mar-2021 12:29:21	SCHED	P	DON	150.55
18-Mar-2021	3,715	0	495155	38-100-PMA	Service A PMI	19-Mar-2021 13:12:02	ROGSHP	P	DON	337.90
02-Sep-2021	4,106	0	529192	03-034-007	Replace Signaling Devices	10-Sep-2021 10:55:40	TRK401	I	DON	200.22
02-Sep-2021	4,106	0	529192	06-100-PMA	Inspect A PMI	02-Sep-2021 15:08:21	SCHED	P	DON	5.30
02-Sep-2021	4,106	0	529192	38-100-PMA	Service A PMI	02-Sep-2021 14:59:48	TRK401	O	DON	107.16
07-Oct-2021	4,127	0	537607	01-043-023	Adjust Tank - DEF	11-Oct-2021 11:19:18	OTSSHP	Q	DON	16.40
07-Oct-2021	4,127	0	537607	03-051-009	Replace Fire Extinguisher	11-Oct-2021 12:42:19	OTSSHP	I	DON	261.94

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Q1279 - 2017 JOHN DEERE 310HL										
07-Oct-2021 1:	4,127	0	537607	03-063-003	Replace Transceiver - GPS Tracker	11-Oct-2021 13:37:26	SCHED	Q	DON	294.19
07-Oct-2021 1:	4,127	0	537607	06-100-PMA	Inspect A PMI	11-Oct-2021 11:14:02	SCHED	P	DON	183.53
07-Oct-2021 1:	4,127	0	537607	24-013	Repair Brakes	11-Oct-2021 10:18:25	OTSSHP	I	DON	3,542.39
07-Oct-2021 1:	4,127	0	537607	24-034-002	Repair Stop, Tail, Turn & License	11-Oct-2021 11:25:53	OTSSHP	I	DON	6.03
07-Oct-2021 1:	4,127	0	537607	24-310-005	Repair Boom Lock	12-Oct-2021 13:15:43	OTSSHP	I	DON	65.60
18-Jan-2022 0:	4,360	0	559831	03-034-002	Replace Stop, Tail, Turn & License	18-Jan-2022 10:35:03	OTSSHP	I	DON	7.00
18-Jan-2022 0:	4,360	0	559831	03-051-009	Replace Fire Extinguisher	18-Jan-2022 10:43:57	OTSSHP	I	DON	234.54
18-Jan-2022 0:	4,360	0	559831	03-310-007	Replace Outtrigger Pads	18-Jan-2022 10:27:09	OTSSHP	I	DON	268.28
18-Jan-2022 0:	4,360	0	559831	06-100-PMA	Inspect A PMI	18-Jan-2022 07:53:00	OTSSHP	P	DON	19.81
18-Jan-2022 0:	4,360	0	559831	38-100-PMA	Service A PMI	18-Jan-2022 11:34:42	OTSSHP	P	DON	282.88
07-Apr-2022 1	4,365	0	580406	03-002-061	Replace Seat Cushion	07-Apr-2022 16:17:52	OTSSHP	O	DON	386.08
23-May-2022 1	4,515	0	590662	24-065-007	Repair Hoses & Fittings	26-May-2022 08:44:41	OTSSHP	B	DON	1,130.55
22-Jun-2022 1:	4,609	0	597984	06-100-PMA	Inspect A PMI	22-Jun-2022 17:37:14	ME1371	P	DON	36.41
22-Jun-2022 1:	4,609	0	597984	38-100-PMA	Service A PMI	22-Jun-2022 17:16:06	ME1371	P	DON	137.46
26-Sep-2022 0	4,743	0	619079	01-065-017	Adjust Reservoir/Tank	06-Oct-2022 08:31:48	OTSSHP	I	DON	52.88
26-Sep-2022 0	4,743	0	619079	03-017-011	Replace Tire - Foam Filled	20-Oct-2022 06:52:08	OTSSHP	I	DON	2,830.32
26-Sep-2022 0	4,743	0	619079	03-024-005	Replace Universal Joint	14-Oct-2022 10:59:51	OTSSHP	I	DON	349.62
26-Sep-2022 0	4,743	0	619079	03-027-045	Replace Filter Assembly	06-Oct-2022 08:08:33	OTSSHP	I	DON	36.40
26-Sep-2022 0	4,743	0	619079	06-013	Inspect Brakes	14-Oct-2022 09:12:36	OTSSHP	O	DON	73.94
26-Sep-2022 0	4,743	0	619079	06-100-PMA	Inspect A PMI	26-Sep-2022 08:42:41	OTSSHP	P	DON	50.05
26-Sep-2022 0	4,743	0	619079	24-013-030	Repair Switch - Parking Brake	06-Oct-2022 07:53:56	OTSSHP	I	DON	177.12
26-Sep-2022 0	4,743	0	619079	24-034-002	Repair Stop, Tail, Turn & License	26-Sep-2022 09:18:15	OTSSHP	I	DON	11.55
26-Sep-2022 0	4,743	0	619079	24-518-001	Repair Steps	26-Sep-2022 09:04:12	OTSSHP	I	DON	15.77
13-Feb-2023 1:	4,752	0	652299	03-032-001	Replace Battery	13-Feb-2023 17:53:59	TRK400	O	DON	421.33
16-Feb-2023 1	4,752	0	653302	06-100-PMB	Inspect B PMI	01-Mar-2023 14:40:43	SCHED	P	DON	0.00
16-Feb-2023 1	4,752	0	653302	06-100-WTN	Inspect Winterization Inspection	16-Feb-2023 16:00:21	LAVSHP	P	DON	132.09
16-Feb-2023 1	4,752	0	653302	38-100-PMC	Service C PMI	17-Feb-2023 06:03:52	LAVSHP	P	DON	233.44
16-Feb-2023 1	4,752	0	653302	03-065-007	Replace Hoses & Fittings	17-Feb-2023 11:57:54	LAVSHP	I	DON	27.25
17-Apr-2023 0	4,769	0	667484	03-360-016	Replace Axle Oil Clutch	17-Apr-2023 11:09:33	TRK401	O	DON	271.06

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Q1279 - 2017 JOHN DEERE 310HL										
17-Apr-2023	0	4,769	667484	95-MSC-004	Travel Time - To/From Job Site	17-Apr-2023 09:52:10	TRK401	B	DON	203.64
12-May-2023	0	4,871	673990	06-100-PMA	Inspect A PMI	12-May-2023 10:50:33	ME1371	P	DON	20.09
14-Aug-2023	1	4,878	696619	02-310	Clean Backhoe (Rubber Tire)	14-Dec-2023 16:00:06	BWASH	Z	DON	508.69
14-Aug-2023	1	4,878	696619	06-100-PMB	Inspect B PMI	21-Dec-2023 14:19:13	BBKHOE	P	DON	66.62
14-Aug-2023	1	4,878	696619	OS-310	Out-Service Backhoe (Rubber Tire)	21-Dec-2023 14:19:16	BBKHOE	Z	DON	193.60