

Unit Job History

| WO Open Date | Meter 1 | Meter 2 | Work Order | Job Code | Job Description | Date Completed | Job Location | Job Reason | Job Status | Total Cost |
|---|---------|---------|------------|------------|--|----------------------|--------------|------------|------------|------------|
| Unit No: E1401 - 2016 CAT TH514C | | | | | | | | | | |
| 02-Sep-2016 | 5 | 0 | 258158 | 06-266 | Inspect Forklift | 12-Sep-2016 08:00:28 | BHVYEQ | I | DON | 873.26 |
| 02-Sep-2016 | 5 | 0 | 258158 | 12-510-002 | Refinish Tool Box | 12-Sep-2016 09:15:03 | BBODY | C | DON | 82.81 |
| 02-Sep-2016 | 5 | 0 | 258158 | 14-052-014 | Install Cellular Telephone Accessories | 19-Sep-2016 17:17:40 | BSETUP | C | DON | 36.78 |
| 02-Sep-2016 | 5 | 0 | 258158 | 14-266-002 | Install Fork Assembly | 07-Sep-2016 17:00:32 | BHVYEQ | J | DON | 145.53 |
| 02-Sep-2016 | 5 | 0 | 258158 | 15-510-002 | Paint Prep Tool Box | 12-Sep-2016 07:38:06 | BSAND | C | DON | 6.99 |
| 02-Sep-2016 | 5 | 0 | 258158 | 21-510-002 | Fabricate Tool Box | 12-Sep-2016 07:58:29 | BWELD | C | DON | 489.88 |
| 06-Oct-2016 | 110 | 0 | 262075 | 24-002-028 | Repair Adjuster - Front Seat | 17-Oct-2016 07:34:14 | BHVYEQ | I | DON | 313.40 |
| 25-Oct-2016 | 245 | 0 | 264480 | 38-100-PMA | Service A PMI | 26-Oct-2016 07:56:38 | BHVYEQ | P | DON | 187.63 |
| 22-Nov-2016 | 396 | 0 | 267422 | 24-002 | Repair Cab & Sheet Metal | 22-Nov-2016 10:10:39 | BHVYEQ | I | DON | 150.50 |
| 09-Dec-2016 | 506 | 0 | 269192 | 06-100-PMB | Inspect B PMI | 10-Dec-2016 10:13:03 | BHVYEQ | P | DON | 291.73 |
| 09-Dec-2016 | 506 | 0 | 269192 | 06-100-PMA | Inspect A PMI | 10-Dec-2016 10:13:07 | BHVYEQ | P | DON | 1.11 |
| 19-Jan-2017 | 762 | 0 | 274141 | 38-100-PMA | Service A PMI | 20-Jan-2017 07:47:51 | BHVYEQ | P | DON | 248.81 |
| 08-Feb-2017 | 1,008 | 0 | 276641 | 06-100-PMA | Inspect A PMI | 27-Feb-2017 08:16:15 | BHVYEQ | P | DON | 510.04 |
| 08-Feb-2017 | 1,008 | 0 | 276641 | 24-065-007 | Repair Hoses & Fittings | 09-Feb-2017 06:16:56 | BHVYEQ | O | DON | 75.91 |
| 08-Feb-2017 | 1,008 | 0 | 276641 | 03-065-008 | Replace Line / Tubing Assembly | 18-Feb-2017 10:07:17 | BHVYEQ | O | DON | 583.73 |
| 01-Apr-2017 | 1,252 | 0 | 283495 | 06-100-PMA | Inspect A PMI | 01-Apr-2017 07:51:35 | BHVYEQ | P | DON | 272.45 |
| 02-Jun-2017 | 1,521 | 0 | 291291 | 14-266-002 | Install Fork Assembly | 16-Jun-2017 08:12:19 | BHVYEQ | I | DON | 185.73 |
| 02-Jun-2017 | 1,521 | 0 | 291291 | 25-266-002 | Remove Fork Assembly | 16-Jun-2017 08:22:01 | BHVYEQ | I | DON | 47.69 |
| 02-Jun-2017 | 1,521 | 0 | 291291 | 34-013 | Reseal Brakes | 16-Jun-2017 11:38:23 | BHVYEQ | W | DON | 0.00 |
| 02-Jun-2017 | 1,521 | 0 | 291291 | 02-266 | Clean Forklift | 16-Jun-2017 11:35:16 | BHVYEQ | J | DON | 343.75 |
| 02-Jun-2017 | 1,521 | 0 | 291291 | 06-100-PMA | Inspect A PMI | 16-Jun-2017 11:37:10 | BHVYEQ | P | DON | 1,058.50 |
| 02-Jun-2017 | 1,521 | 0 | 291291 | 24-027 | Repair Transmission - Main, Automatic | 16-Jun-2017 11:39:29 | BHVYEQ | W | DON | 0.00 |
| 02-Aug-2017 | 1,764 | 0 | 299397 | 06-100-FRK | Inspect Forklift Inspection | 03-Aug-2017 06:30:37 | BHVYEQ | P | DON | 22.17 |
| 02-Aug-2017 | 1,764 | 0 | 299397 | 06-100-PMB | Inspect B PMI | 03-Aug-2017 17:00:38 | BHVYEQ | P | DON | 513.04 |
| 22-Sep-2017 | 1,995 | 0 | 306035 | 06-100-PMA | Inspect A PMI | 22-Sep-2017 09:51:22 | BHVYEQ | P | DON | 122.95 |
| 22-Sep-2017 | 1,995 | 0 | 306035 | 24-266-002 | Repair Fork Assembly | 22-Sep-2017 08:24:30 | BHVYEQ | O | DON | 71.65 |
| 16-Nov-2017 | 2,315 | 0 | 312888 | 06-100-PMC | Inspect C PMI | 29-Nov-2017 16:38:39 | BHVYEQ | P | DON | 558.76 |
| 30-Nov-2017 | 2,315 | 0 | 314214 | 25-513-002 | Remove Quick Attachment | 30-Nov-2017 14:34:49 | BHVYEQ | J | DON | 131.90 |
| 02-Feb-2018 | 2,590 | 0 | 322203 | 38-100-PMA | Service A PMI | 03-Feb-2018 09:30:16 | BHVYEQ | P | DON | 348.27 |

Unit Job History

| WO Open Date | Meter 1 | Meter 2 | Work Order | Job Code | Job Description | Date Completed | Job Location | Job Reason | Job Status | Total Cost |
|----------------------------------|---------|---------|------------|----------|---|----------------------|--------------|------------|------------|------------|
| Unit No: E1401 - 2016 CAT TH514C | | | | | | | | | | |
| 09-Mar-2018 | 1 | 2,840 | 0 | 326787 | 06-100-PMA Inspect A PMI | 10-Mar-2018 08:54:46 | BHVYEQ | P | DON | 304.84 |
| 20-Apr-2018 | 1 | 2,840 | 0 | 332254 | 06-100-PMA Inspect A PMI | 21-Apr-2018 09:11:30 | BHVYEQ | P | DON | 311.42 |
| 01-May-2018 | 1 | 2,840 | 0 | 333725 | 03-015-004 Replace Steering Linkage | 19-May-2018 10:04:01 | BHVYEQ | I | DON | 761.60 |
| 01-May-2018 | 1 | 2,840 | 0 | 333725 | 06-100-PMC Inspect C PMI | 10-May-2018 06:53:47 | BHVYEQ | P | DON | 688.72 |
| 25-Jun-2018 | 1 | 3,447 | 0 | 341294 | 03-042-004 Replace Water Pump | 28-Jun-2018 14:49:50 | BHVYEQ | I | DON | 447.31 |
| 25-Jun-2018 | 1 | 3,447 | 0 | 341294 | 03-042-013 Replace Fan Belt | 28-Jun-2018 14:49:30 | BHVYEQ | I | DON | 227.48 |
| 25-Jun-2018 | 1 | 3,447 | 0 | 341294 | 03-045-027 Replace Idler Pulley | 27-Jun-2018 08:12:53 | BHVYEQ | I | DON | 276.46 |
| 25-Jun-2018 | 1 | 3,447 | 0 | 341294 | 38-100-PMA Service A PMI | 26-Jun-2018 06:43:17 | BHVYEQ | P | DON | 260.91 |
| 13-Aug-2018 | 1 | 3,717 | 0 | 347958 | 06-100-PMA Inspect A PMI | 13-Aug-2018 15:44:02 | BHVYEQ | P | DON | 0.00 |
| 13-Aug-2018 | 1 | 3,717 | 0 | 347958 | 38-100-PMA Service A PMI | 13-Aug-2018 15:44:14 | BHVYEQ | P | DON | 230.30 |
| 01-Oct-2018 | 1 | 3,963 | 0 | 354469 | 06-100-PMA Inspect A PMI | 01-Oct-2018 16:33:39 | BHVYEQ | P | DON | 242.84 |
| 14-Nov-2018 | 1 | 3,963 | 0 | 360660 | 06-100-PMA Inspect A PMI | 15-Nov-2018 08:09:48 | BHVYEQ | P | DON | 170.74 |
| 21-Dec-2018 | 1 | 3,963 | 0 | 365801 | 38-040 Service Engine / Motor Systems Group | 21-Dec-2018 14:34:50 | BSDRIL | N | DON | 43.38 |
| 03-Jan-2019 | 1 | 4,514 | 0 | 366688 | 06-100-PMA Inspect A PMI | 04-Jan-2019 07:43:16 | BHVYEQ | P | DON | 208.88 |
| 03-Jan-2019 | 1 | 4,514 | 0 | 366688 | 06-100-PMB Inspect B PMI | 04-Jan-2019 07:42:23 | BHVYEQ | P | DON | 249.75 |
| 15-Jan-2019 | 0 | 4,514 | 0 | 368274 | 03-017-011 Replace Tire - Foam Filled | 07-Feb-2019 05:05:20 | BHVYEQ | N | DON | 6,449.11 |
| 12-Feb-2019 | 1 | 4,782 | 0 | 372225 | 03-017-011 Replace Tire - Foam Filled | 13-Feb-2019 07:15:38 | BHVYEQ | N | DON | 61.85 |
| 12-Feb-2019 | 1 | 4,782 | 0 | 372225 | 06-100-PMA Inspect A PMI | 13-Feb-2019 07:26:21 | BHVYEQ | P | DON | 256.41 |
| 22-Mar-2019 | 1 | 4,782 | 0 | 377825 | 06-100-PMA Inspect A PMI | 25-Mar-2019 06:47:53 | BHVYEQ | P | DON | 260.16 |
| 05-Apr-2019 | 1 | 4,782 | 0 | 379966 | 03-031-001 Replace Generator/Alternator | 08-Apr-2019 08:32:44 | BHVYEQ | I | DON | 961.24 |
| 01-May-2019 | 1 | 5,260 | 0 | 383775 | 38-100-PMC Service C PMI | 01-May-2019 13:15:49 | BHVYEQ | P | DON | 259.88 |
| 01-May-2019 | 1 | 5,260 | 0 | 383775 | 03-031-006 Replace Belt - Alternator | 03-May-2019 08:46:38 | BHVYEQ | I | DON | 0.00 |
| 01-May-2019 | 1 | 5,260 | 0 | 383775 | 06-100-PMC Inspect C PMI | 03-May-2019 08:52:28 | BHVYEQ | P | DON | 553.37 |
| 15-May-2019 | 1 | 5,260 | 0 | 385993 | 24-111-010 Repair Belly Pan | 15-May-2019 17:02:31 | BHVYEQ | O | DON | 44.97 |
| 27-Jun-2019 | 1 | 5,260 | 0 | 392206 | 38-100-PMA Service A PMI | 28-Jun-2019 08:14:38 | BHVYEQ | P | DON | 179.15 |
| 26-Aug-2019 | 1 | 5,825 | 0 | 400221 | 06-100-PMA Inspect A PMI | 26-Aug-2019 09:17:21 | BHVYEQ | P | DON | 54.50 |
| 26-Aug-2019 | 1 | 5,825 | 0 | 400221 | 38-100-PMA Service A PMI | 26-Aug-2019 13:43:07 | BHVYEQ | P | DON | 255.59 |
| 25-Sep-2019 | 1 | 5,998 | 0 | 404617 | 03-042-013 Replace Fan Belt | 26-Sep-2019 06:28:40 | BHVYEQ | I | DON | 168.31 |
| 11-Oct-2019 | 0 | 6,088 | 0 | 407084 | 06-100-PMC Inspect C PMI | 22-Oct-2019 07:07:28 | BHVYEQ | P | DON | 189.01 |

Unit Job History

| WO Open Date | Meter 1 | Meter 2 | Work Order | Job Code | Job Description | Date Completed | Job Location | Job Reason | Job Status | Total Cost |
|----------------------------------|---------|---------|------------|------------|--|----------------------|--------------|------------|------------|------------|
| Unit No: E1401 - 2016 CAT TH514C | | | | | | | | | | |
| 11-Oct-2019 0 | 6,088 | 0 | 407084 | 38-100-PMC | Service C PMI | 14-Oct-2019 07:53:33 | BHVYEQ | P | DON | 487.93 |
| 11-Oct-2019 0 | 6,088 | 0 | 407084 | 03-013-026 | Replace Handle - Parking Brake Release | 22-Oct-2019 07:12:38 | BHVYEQ | I | DON | 342.82 |
| 28-Oct-2019 0 | 6,088 | 0 | 409715 | 03-031-001 | Replace Generator/Alternator | 31-Oct-2019 07:48:06 | BHVYEQ | I | DON | 197.02 |
| 28-Oct-2019 0 | 6,088 | 0 | 409715 | 03-032-001 | Replace Battery | 31-Oct-2019 07:48:05 | BHVYEQ | B | DON | 384.43 |
| 21-Nov-2019 1 | 6,088 | 0 | 413827 | 03-001-023 | Replace Ductwork and Dash Louvres | 02-Dec-2019 06:57:55 | BHVYEQ | I | DON | 22.79 |
| 21-Nov-2019 1 | 6,088 | 0 | 413827 | 03-002-037 | Replace Seat Assembly | 22-Nov-2019 16:01:44 | BHVYEQ | N | DON | 987.53 |
| 21-Nov-2019 1 | 6,088 | 0 | 413827 | 03-013-025 | Replace Lever - Pedal Assy Park Brake | 22-Nov-2019 11:34:36 | BHVYEQ | I | DON | 108.73 |
| 21-Nov-2019 1 | 6,088 | 0 | 413827 | 03-013-027 | Replace Cable - Parking Brake | 27-Nov-2019 16:10:02 | BHVYEQ | I | DON | 38.14 |
| 21-Nov-2019 1 | 6,088 | 0 | 413827 | 03-034-015 | Replace Headlamp Switch | 25-Nov-2019 16:05:22 | BHVYEQ | I | DON | 164.92 |
| 21-Nov-2019 1 | 6,088 | 0 | 413827 | 03-065-008 | Replace Line / Tubing Assembly | 26-Nov-2019 14:38:41 | BHVYEQ | I | DON | 1,432.73 |
| 21-Nov-2019 1 | 6,088 | 0 | 413827 | 24-002-035 | Repair Windshield Wiper & Washer | 02-Dec-2019 07:42:23 | BHVYEQ | I | DON | 304.58 |
| 21-Nov-2019 1 | 6,088 | 0 | 413827 | 38-100-PMA | Service A PMI | 22-Nov-2019 07:35:37 | BHVYEQ | P | DON | 190.67 |
| 17-Jan-2020 1 | 6,088 | 0 | 421689 | 06-100-PMA | Inspect A PMI | 20-Jan-2020 06:55:23 | BHVYEQ | P | DON | 35.34 |
| 17-Jan-2020 1 | 6,088 | 0 | 421689 | 38-100-PMA | Service A PMI | 20-Jan-2020 06:54:49 | BHVYEQ | P | DON | 167.70 |
| 03-Mar-2020 1 | 6,088 | 0 | 429252 | 24-049-003 | Repair ECM Wiring Harness | 10-Apr-2020 09:59:42 | BHVYEQ | I | DON | 337.74 |
| 03-Mar-2020 1 | 6,088 | 0 | 429252 | 38-100-PMA | Service A PMI | 03-Mar-2020 17:01:10 | BHVYEQ | P | DON | 205.71 |
| 10-Apr-2020 0 | 7,221 | 0 | 435383 | 06-100-PMA | Inspect A PMI | 20-Apr-2020 08:11:05 | BHVYEQ | P | DON | 0.00 |
| 10-Apr-2020 0 | 7,221 | 0 | 435383 | 38-100-PMA | Service A PMI | 10-Apr-2020 16:39:18 | BHVYEQ | P | DON | 273.68 |
| 15-May-2020 1 | 7,221 | 0 | 441075 | 03-014-004 | Replace Cab & Body Mountings | 28-Jul-2020 05:55:02 | BHVYEQ | O | DON | 434.26 |
| 15-May-2020 1 | 7,221 | 0 | 441075 | 06-100-PMA | Inspect A PMI | 28-Jul-2020 05:56:51 | BHVYEQ | P | DON | 0.00 |
| 15-May-2020 1 | 7,221 | 0 | 441075 | 21-513-004 | Fabricate Specialty Attachment | 28-May-2020 14:55:12 | BWELD | N | DON | 131.58 |
| 15-May-2020 1 | 7,221 | 0 | 441075 | 24-266-003 | Repair Mast | 28-Jul-2020 05:56:51 | BHVYEQ | I | DON | 235.47 |
| 15-May-2020 1 | 7,221 | 0 | 441075 | 34-045-024 | Reseal Seal - Crankshaft (Front) | 28-Jul-2020 05:56:51 | BHVYEQ | I | DON | 44.83 |
| 15-May-2020 1 | 7,221 | 0 | 441075 | 38-100-PMA | Service A PMI | 19-May-2020 07:06:58 | BHVYEQ | P | DON | 529.11 |
| 15-May-2020 1 | 7,221 | 0 | 441075 | 38-100-PMC | Service C PMI | | BHVYEQ | P | CAN | 0.00 |
| 28-Aug-2020 1 | 7,809 | 0 | 458766 | 38-100-PMB | Service B PMI | 31-Aug-2020 09:39:54 | BHVYEQ | P | DON | 105.26 |
| 28-Aug-2020 1 | 7,809 | 0 | 458766 | 06-100-PMB | Inspect B PMI | 28-Aug-2020 17:11:00 | BHVYEQ | P | DON | 180.69 |
| 31-Aug-2020 1 | 7,809 | 0 | 459146 | 24-002-071 | Repair Side Window | 08-Sep-2020 08:01:36 | BHVYEQ | I | DON | 459.45 |
| 31-Aug-2020 1 | 7,809 | 0 | 459146 | 03-266-002 | Replace Fork Assembly | 15-Sep-2020 17:01:33 | BHVYEQ | I | DON | 3,544.39 |

Unit Job History

| WO Open Date | Meter 1 | Meter 2 | Work Order | Job Code | Job Description | Date Completed | Job Location | Job Reason | Job Status | Total Cost |
|----------------------------------|---------|---------|------------|------------|---|----------------------|--------------|------------|------------|------------|
| Unit No: E1401 - 2016 CAT TH514C | | | | | | | | | | |
| 11-Dec-2020 0 | 8,219 | 0 | 476469 | 26-513-004 | Weld Specialty Attachment | 28-Dec-2020 08:38:53 | BHVYEQ | N | DON | 81.05 |
| 11-Dec-2020 0 | 8,219 | 0 | 476469 | 38-100-PMA | Service A PMI | 15-Dec-2020 04:57:11 | BHVYEQ | P | DON | 522.18 |
| 11-Dec-2020 0 | 8,219 | 0 | 476469 | 24-002-028 | Repair Adjuster - Front Seat | 11-Dec-2020 07:57:39 | BHVYEQ | I | DON | 53.31 |
| 11-Dec-2020 0 | 8,219 | 0 | 476469 | 24-002-064 | Repair Washer Fluid Reservoir | 11-Dec-2020 11:10:24 | BHVYEQ | I | DON | 109.97 |
| 11-Dec-2020 0 | 8,219 | 0 | 476469 | 24-266-002 | Repair Fork Assembly | 14-Dec-2020 10:50:07 | BHVYEQ | I | DON | 3,497.27 |
| 15-Jan-2021 0 | 8,219 | 0 | 482432 | 14-063-003 | Install Transceiver - GPS Tracker | 15-Jan-2021 11:17:52 | ELEC03 | Q | DON | 307.94 |
| 01-Feb-2021 0 | 8,460 | 0 | 485720 | 03-031-006 | Replace Belt - Alternator | 02-Feb-2021 11:18:10 | BHVYEQ | I | DON | 318.60 |
| 01-Feb-2021 0 | 8,460 | 0 | 485720 | 03-001-026 | Replace Belt - A/C Compressor | 04-Feb-2021 14:10:36 | BHVYEQ | I | DON | 168.88 |
| 01-Feb-2021 0 | 8,460 | 0 | 485720 | 06-100-PMC | Inspect C PMI | 04-Feb-2021 14:50:21 | BHVYEQ | P | DON | 104.99 |
| 01-Feb-2021 0 | 8,460 | 0 | 485720 | 38-100-PMC | Service C PMI | 02-Feb-2021 07:34:48 | BHVYEQ | P | DON | 653.68 |
| 01-Feb-2021 0 | 8,460 | 0 | 485720 | 03-001-010 | Replace Compressor Assembly - Air Cond | 04-Feb-2021 14:10:13 | BHVYEQ | I | DON | 1,830.34 |
| 01-Feb-2021 0 | 8,460 | 0 | 485720 | 03-030-001 | Replace Outrigger Interlock Switch | 12-Mar-2021 12:25:29 | BHVYEQ | I | DON | 13.68 |
| 01-Feb-2021 0 | 8,460 | 0 | 485720 | 03-034-014 | Replace Auxiliary Work / Flood Light | 12-Mar-2021 12:25:23 | BHVYEQ | I | DON | 16.44 |
| 01-Feb-2021 0 | 8,460 | 0 | 485720 | 14-002-010 | Install Mirrors | | BHVYEQ | I | CAN | 0.00 |
| 12-Mar-2021 1 | 8,643 | 0 | 493853 | 24-002-027 | Repair Seat Frames & Springs | 12-Mar-2021 16:33:48 | BHVYEQ | O | DON | 191.07 |
| 12-Mar-2021 1 | 8,643 | 0 | 493853 | 38-100-PMA | Service A PMI | 12-Mar-2021 16:31:22 | BHVYEQ | P | DON | 218.89 |
| 12-Mar-2021 1 | 8,643 | 0 | 493853 | 03-030-001 | Replace Outrigger Interlock Switch | 23-Mar-2021 06:16:18 | BHVYEQ | I | DON | 31.05 |
| 12-Mar-2021 1 | 8,643 | 0 | 493853 | 03-034-014 | Replace Auxiliary Work / Flood Light | 23-Mar-2021 06:16:18 | BHVYEQ | I | DON | 31.74 |
| 12-Mar-2021 1 | 8,643 | 0 | 493853 | 06-100-PMA | Inspect A PMI | 23-Mar-2021 06:16:16 | SCHED | P | DON | 0.00 |
| 29-Mar-2021 1 | 8,727 | 0 | 497224 | 35-027 | Diagnose Transmission - Main, Automatic | 02-Apr-2021 05:34:39 | BHVYEQ | N | DON | 1,875.97 |
| 26-Apr-2021 0 | 8,866 | 0 | 502719 | 38-100-PMA | Service A PMI | 26-Apr-2021 11:28:55 | BHVYEQ | P | DON | 425.95 |
| 26-Apr-2021 0 | 8,866 | 0 | 502719 | 06-100-FRK | Inspect Forklift Inspection | 26-Apr-2021 06:36:58 | SCHED | P | DON | 0.00 |
| 26-Apr-2021 0 | 8,866 | 0 | 502719 | 06-100-PMB | Inspect B PMI | 26-Apr-2021 06:36:56 | SCHED | P | DON | 0.00 |
| 17-May-2021 0 | 8,967 | 0 | 507010 | 03-049-003 | Replace ECM Wiring Harness | 30-Sep-2021 08:41:29 | BHVYEQ | N | DON | 523.50 |
| 17-May-2021 0 | 8,967 | 0 | 507010 | 06-100-PMA | Inspect A PMI | 30-Sep-2021 09:17:54 | SCHED | P | DON | 0.00 |
| 17-May-2021 0 | 8,967 | 0 | 507010 | 24-112-006 | Repair Outrigger Assembly | | BHVYEQ | I | CAN | 0.00 |
| 17-May-2021 0 | 8,967 | 0 | 507010 | 38-100-PMA | Service A PMI | 18-Jun-2021 16:03:25 | BHVYEQ | P | DON | 219.09 |
| 30-Sep-2021 0 | 9,516 | 0 | 535407 | 38-100-PMA | Service A PMI | 30-Sep-2021 12:18:51 | BHVYEQ | P | DON | 224.83 |
| 30-Sep-2021 0 | 9,516 | 0 | 535407 | 06-100-PMA | Inspect A PMI | 19-Oct-2021 10:31:26 | SCHED | P | DON | 0.00 |

Unit Job History

| WO Open Date | Meter 1 | Meter 2 | Work Order | Job Code | Job Description | Date Completed | Job Location | Job Reason | Job Status | Total Cost |
|----------------------------------|---------|---------|------------|------------|-------------------------------------|----------------------|--------------|------------|------------|------------|
| Unit No: E1401 - 2016 CAT TH514C | | | | | | | | | | |
| 02-Nov-2021 | 0 | 9,669 | 543360 | 03-002-023 | Replace Handles - Inner & Outer | 11-Nov-2021 14:44:40 | BHVYEQ | I | DON | 102.44 |
| 06-Dec-2021 | 0 | 9,853 | 551270 | 38-100-PMA | Service A PMI | 06-Dec-2021 06:49:09 | BHVYEQ | P | DON | 174.04 |
| 06-Dec-2021 | 0 | 9,853 | 551270 | 06-100-PMA | Inspect A PMI | 10-Dec-2021 08:15:18 | BHVYEQ | P | DON | 17.63 |
| 06-Dec-2021 | 0 | 9,853 | 551270 | 24-002-018 | Repair Cab Or Front Door Mechanism | 06-Dec-2021 07:22:01 | BHVYEQ | I | DON | 22.68 |
| 06-Dec-2021 | 0 | 9,853 | 551270 | 24-112 | Repair Stabilization | 06-Dec-2021 08:20:25 | BHVYEQ | I | DON | 40.30 |
| 06-Dec-2021 | 0 | 9,853 | 551270 | 24-054-002 | Repair Alarm - Reverse Signal | 06-Dec-2021 09:41:53 | BHVYEQ | I | DON | 72.07 |
| 06-Dec-2021 | 0 | 9,853 | 551270 | 24-034-014 | Repair Auxiliary Work / Flood Light | 06-Dec-2021 11:11:34 | BHVYEQ | I | DON | 61.88 |
| 07-Jan-2022 | 0 | 10,010 | 557605 | 03-031-006 | Replace Belt - Alternator | 07-Jan-2022 11:03:47 | BHVYEQ | N | DON | 179.19 |
| 07-Jan-2022 | 0 | 10,010 | 557605 | 35-049-003 | Diagnose ECM Wiring Harness | 21-Jan-2022 06:47:01 | BHVYEQ | N | DON | 276.21 |
| 01-Feb-2022 | 0 | 10,164 | 563183 | 03-017-005 | Replace Tire - Solid | 16-Mar-2022 06:37:22 | BHVYEQ | N | DON | 6,795.06 |
| 01-Feb-2022 | 0 | 10,164 | 563183 | 03-513-001 | Replace Forks | 02-Feb-2022 12:02:54 | BHVYEQ | I | DON | 4,821.07 |
| 01-Feb-2022 | 0 | 10,164 | 563183 | 06-100-PMC | Inspect C PMI | 08-Feb-2022 06:56:57 | BHVYEQ | P | DON | 21.71 |
| 01-Feb-2022 | 0 | 10,164 | 563183 | 38-100-PMC | Service C PMI | 02-Feb-2022 10:05:09 | BHVYEQ | I | DON | 714.85 |
| 05-Apr-2022 | 1 | 10,527 | 579798 | 24-001-001 | Repair Air Conditioning Assembly | 11-May-2022 07:05:23 | BHVYEQ | O | DON | 83.24 |
| 05-Apr-2022 | 1 | 10,527 | 579798 | 03-049-002 | Replace ECM Module | | BHVYEQ | I | CAN | 0.00 |
| 05-Apr-2022 | 1 | 10,527 | 579798 | 03-031-001 | Replace Generator/Alternator | 19-Apr-2022 07:05:04 | BHVYEQ | I | DON | 933.05 |
| 05-Apr-2022 | 1 | 10,527 | 579798 | 03-032-001 | Replace Battery | 16-May-2022 09:25:46 | BHVYEQ | O | DON | 550.35 |
| 21-Jul-2022 | 07 | 11,169 | 604096 | 38-100-PMB | Service B PMI | 22-Jul-2022 14:58:25 | BHVYEQ | P | DON | 560.63 |
| 21-Jul-2022 | 07 | 11,169 | 604096 | 06-100-PMB | Inspect B PMI | 16-Aug-2022 16:41:03 | BHVYEQ | P | DON | 104.20 |
| 21-Jul-2022 | 07 | 11,169 | 604096 | 06-100-PMA | Inspect A PMI | 16-Aug-2022 16:41:05 | BHVYEQ | P | DON | 0.00 |
| 21-Jul-2022 | 07 | 11,169 | 604096 | 14-001-005 | Install Auxiliary Fan - Defroster | 22-Jul-2022 13:54:12 | BHVYEQ | I | DON | 167.89 |
| 21-Jul-2022 | 07 | 11,169 | 604096 | 03-013-001 | Replace Front Brakes & Drums | 31-Aug-2022 05:13:04 | BHVYEQ | I | DON | 664.12 |
| 21-Jul-2022 | 07 | 11,169 | 604096 | 24-002-028 | Repair Adjuster - Front Seat | 03-Aug-2022 16:10:26 | BHVYEQ | I | DON | 387.18 |
| 10-Oct-2022 | 0 | 11,447 | 622941 | 06-100-PMA | Inspect A PMI | 13-Oct-2022 12:52:59 | BHVYEQ | P | DON | 100.87 |
| 10-Oct-2022 | 0 | 11,447 | 622941 | 24-002-035 | Repair Windshield Wiper & Washer | 13-Oct-2022 12:43:33 | BHVYEQ | I | DON | 67.04 |
| 10-Oct-2022 | 0 | 11,447 | 622941 | 24-013-034 | Repair Parking Brake - Complete | 13-Oct-2022 12:43:25 | BHVYEQ | I | DON | 336.66 |
| 10-Oct-2022 | 0 | 11,447 | 622941 | 24-034-002 | Repair Stop, Tail, Turn & License | 13-Oct-2022 12:43:39 | BHVYEQ | I | DON | 31.62 |
| 10-Oct-2022 | 0 | 11,447 | 622941 | 34-021-108 | Reseal Pinion Seal | 13-Oct-2022 12:43:20 | BHVYEQ | I | DON | 1,239.44 |
| 10-Oct-2022 | 0 | 11,447 | 622941 | 35-034-002 | Diagnose Stop, Tail, Turn & License | 13-Oct-2022 12:43:27 | BHVYEQ | I | DON | 165.82 |

Unit Job History

| WO Open Date | Meter 1 | Meter 2 | Work Order | Job Code | Job Description | Date Completed | Job Location | Job Reason | Job Status | Total Cost |
|----------------------------------|---------|---------|------------|------------|--|----------------------|--------------|------------|------------|------------|
| Unit No: E1401 - 2016 CAT TH514C | | | | | | | | | | |
| 10-Oct-2022 0: | 11,447 | 0 | 622941 | 38-032-004 | Service Battery Cables and Ends | 13-Oct-2022 12:43:30 | BHVYEQ | I | DON | 29.50 |
| 10-Oct-2022 0: | 11,447 | 0 | 622941 | 38-100-PMA | Service A PMI | 13-Oct-2022 12:43:36 | BHVYEQ | N | DON | 217.21 |
| 07-Nov-2022 C | 11,549 | 0 | 630239 | 06-100-FRK | Inspect Forklift Inspection | 08-Nov-2022 11:16:34 | BHVYEQ | P | DON | 32.22 |
| 07-Nov-2022 C | 11,549 | 0 | 630239 | 24-031 | Repair Charging System | 08-Nov-2022 14:20:34 | BHVYEQ | I | DON | 967.27 |
| 07-Nov-2022 C | 11,549 | 0 | 630239 | 24-043-029 | Repair Sensor - DEF | 07-Nov-2022 08:07:39 | BHVYEQ | I | DON | 44.72 |
| 17-Nov-2022 C | 11,578 | 0 | 633197 | 03-002-010 | Replace Mirrors | 17-Nov-2022 07:13:28 | BHVYEQ | O | DON | 66.64 |
| 13-Dec-2022 I | 11,686 | 0 | 639051 | 03-027-038 | Replace Electronic Controls, Transmission, Aut | 15-Dec-2022 08:16:12 | BHVYEQ | I | DON | 1,593.89 |
| 13-Dec-2022 I | 11,686 | 0 | 639051 | 06-100-PMB | Inspect B PMI | 15-Dec-2022 08:15:57 | BHVYEQ | P | DON | 342.23 |
| 13-Dec-2022 I | 11,686 | 0 | 639051 | 24-112-002 | Repair Hydraulics - Stabilization | 14-Dec-2022 09:20:20 | BHVYEQ | I | DON | 76.51 |
| 13-Dec-2022 I | 11,686 | 0 | 639051 | 38-100-PMA | Service A PMI | 14-Dec-2022 07:29:27 | BHVYEQ | P | DON | 234.57 |
| 30-Dec-2022 0 | 11,735 | 0 | 641971 | 03-002-010 | Replace Mirrors | 30-Dec-2022 06:25:53 | BHVYEQ | O | DON | 66.64 |
| 01-Feb-2023 0 | 11,904 | 0 | 649621 | 03-049-003 | Replace ECM Wiring Harness | | BHVYEQ | I | CAN | 0.00 |
| 01-Feb-2023 0 | 11,904 | 0 | 649621 | 03-053-008 | Replace Hoses & Tubings & Fittings | 20-Feb-2023 14:01:18 | BHVYEQ | O | DON | 1,575.11 |
| 01-Feb-2023 0 | 11,904 | 0 | 649621 | 38-100-PMA | Service A PMI | 24-Mar-2023 12:18:07 | BDDRIL | P | DON | 152.88 |
| 10-Apr-2023 I | 12,252 | 0 | 665972 | 03-002-010 | Replace Mirrors | 26-Jul-2023 07:53:41 | LOMMAR | I | DON | 59.88 |
| 10-Apr-2023 I | 12,252 | 0 | 665972 | 03-002-024 | Replace Glass / Windshield | 26-Jul-2023 07:53:37 | LOMMAR | B | DON | 418.62 |
| 10-Apr-2023 I | 12,252 | 0 | 665972 | 03-013-026 | Replace Handle - Parking Brake Release | 08-Jun-2023 08:21:45 | LOMMAR | I | DON | 374.95 |
| 10-Apr-2023 I | 12,252 | 0 | 665972 | 03-065-006 | Replace Filters, Strainers, Screens & Housing | 26-Jul-2023 07:53:44 | LOMMAR | I | DON | 696.37 |
| 10-Apr-2023 I | 12,252 | 0 | 665972 | 03-099-003 | Replace Plug - Connector | 23-May-2023 14:32:53 | LOMMAR | I | DON | 89.75 |
| 10-Apr-2023 I | 12,252 | 0 | 665972 | 06-100-PMB | Inspect B PMI | 07-Jun-2023 11:13:40 | BDDRIL | P | DON | 0.00 |
| 10-Apr-2023 I | 12,252 | 0 | 665972 | 38-100-PMB | Service B PMI | 07-Jun-2023 11:13:40 | BDDRIL | N | DON | 214.70 |
| 02-Aug-2023 I | 12,698 | 0 | 693682 | 03-017-011 | Replace Tire - Foam Filled | 02-Aug-2023 15:19:06 | LOMMAR | O | DON | 119.44 |
| 08-Aug-2023 I | 12,720 | 0 | 695031 | 35-049-001 | Diagnose ECM Fault Code | 10-Oct-2023 07:55:36 | LOMMAR | O | DON | 164.63 |
| 09-Aug-2023 C | 12,726 | 0 | 695357 | 03-017-011 | Replace Tire - Foam Filled | 10-Aug-2023 16:27:47 | BTIRE | O | DON | 3,777.28 |
| 16-Oct-2023 I | 12,946 | 0 | 713183 | 03-051-009 | Replace Fire Extinguisher | 30-Oct-2023 10:23:33 | BDDRIL | I | DON | 46.27 |
| 16-Oct-2023 I | 12,946 | 0 | 713183 | 06-100-PMC | Inspect C PMI | 30-Oct-2023 10:07:08 | BDDRIL | P | DON | 34.03 |
| 16-Oct-2023 I | 12,946 | 0 | 713183 | 24-065-004 | Repair Cylinder | 30-Oct-2023 09:25:42 | BDDRIL | O | DON | 4,376.29 |
| 16-Oct-2023 I | 12,946 | 0 | 713183 | 38-100-PMA | Service A PMI | 30-Oct-2023 09:12:15 | BDDRIL | P | DON | 206.46 |
| 31-Jan-2024 0: | 13,459 | 0 | 735856 | 06-100-PMB | Inspect B PMI | 31-Jan-2024 14:36:41 | BDDRIL | P | DON | 25.62 |

Unit Job History

| WO Open Date | Meter 1 | Meter 2 | Work Order | Job Code | Job Description | Date Completed | Job Location | Job Reason | Job Status | Total Cost |
|----------------------------------|---------|---------|------------|------------|-------------------------|----------------------|--------------|------------|------------|------------|
| Unit No: E1401 - 2016 CAT TH514C | | | | | | | | | | |
| 31-Jan-2024 01 | 13,459 | 0 | 735856 | 38-100-PMA | Service A PMI | 31-Jan-2024 16:40:25 | BDDRIL | P | DON | 201.31 |
| 02-Feb-2024 1 | 13,475 | 0 | 736364 | 03-041-008 | Replace Hose Air Intake | 12-Apr-2024 15:29:51 | LOMMAR | N | DON | 49.92 |
| 02-Feb-2024 1 | 13,475 | 0 | 736364 | 03-049-004 | Replace ECM Sensor | 12-Apr-2024 15:29:49 | LOMMAR | B | DON | 900.10 |
| 02-Feb-2024 1 | 13,475 | 0 | 736364 | 35-049-001 | Diagnose ECM Fault Code | 12-Apr-2024 15:29:46 | LOMMAR | B | DON | 3,577.41 |
| 02-Feb-2024 1 | 13,475 | 0 | 736364 | 03-032-002 | Replace Starter | 12-Apr-2024 15:29:54 | LOMMAR | N | DON | 905.78 |
| 02-Feb-2024 1 | 13,475 | 0 | 736364 | 03-032-008 | Replace Relay | 12-Apr-2024 15:29:57 | LOMMAR | N | DON | 112.13 |
| 02-Feb-2024 1 | 13,475 | 0 | 736364 | 03-032-001 | Replace Battery | 12-Apr-2024 15:29:59 | LOMMAR | N | DON | 346.58 |
| 02-Feb-2024 1 | 13,475 | 0 | 736364 | 03-065-004 | Replace Cylinder | 08-Apr-2024 09:26:16 | BDDRIL | N | DON | 2,457.18 |

Unit No: E1401

Count: 182

87,806.44