

Unit Job History

| WO Open Date | Meter 1 | Meter 2 | Work Order | Job Code | Job Description | Date Completed | Job Location | Job Reason | Job Status | Total Cost |
|---------------------------------------|---------|---------|------------|------------|---------------------------------------|----------------------|--------------|------------|------------|------------|
| Unit No: E1599 - 2019 JOHN DEERE 320G | | | | | | | | | | |
| 22-Feb-2019 0 | 3 | 0 | 373649 | 01-044-007 | Adjust Throttle Controls | 25-Feb-2019 08:10:40 | BBKHOE | C | DON | 264.93 |
| 22-Feb-2019 0 | 3 | 0 | 373649 | 14-032-009 | Install Switch - Master Disconnect | 25-Feb-2019 07:31:38 | BBKHOE | H | DON | 135.24 |
| 22-Feb-2019 0 | 3 | 0 | 373649 | 14-063-003 | Install Transceiver - GPS Tracker | 25-Feb-2019 07:32:49 | BBKHOE | C | DON | 303.41 |
| 22-Feb-2019 0 | 3 | 0 | 373649 | 14-509-002 | Install Safety Guard | 25-Feb-2019 07:48:04 | BBKHOE | C | DON | 71.57 |
| 22-Feb-2019 0 | 3 | 0 | 373649 | 25-034-013 | Remove Bracket - Tail Light | 25-Feb-2019 07:34:45 | BBKHOE | C | DON | 1.16 |
| 22-Feb-2019 0 | 3 | 0 | 373649 | 21-360-001 | Fabricate Bucket and Attachments | 01-Mar-2019 11:09:46 | BBKHOE | H | DON | 61.94 |
| 22-Feb-2019 0 | 3 | 0 | 373649 | 14-052-005 | Install Transmitter - CB | 26-Feb-2019 11:01:41 | BHVYEQ | Q | DON | 256.73 |
| 14-Oct-2019 0 | 1,362 | 0 | 407366 | 03-002-022 | Replace Rear Door Mechanism | 18-Oct-2019 14:52:37 | BBKHOE | I | DON | 551.21 |
| 11-Nov-2019 0 | 1,542 | 0 | 412030 | 03-032-009 | Replace Switch - Master Disconnect | 11-Nov-2019 08:56:23 | BHVYEQ | O | DON | 91.87 |
| 06-Feb-2020 0 | 1,917 | 0 | 425072 | 24-360-003 | Repair Drive Train | 06-Feb-2020 13:43:47 | BHVYEQ | B | DON | 391.73 |
| 16-Mar-2020 1 | 2,113 | 0 | 431211 | 03-001-008 | Replace Motor - Blower | 20-Mar-2020 13:21:55 | BBKHOE | I | DON | 516.63 |
| 16-Mar-2020 1 | 2,113 | 0 | 431211 | 03-021-101 | Replace Axle Housing | 19-Mar-2020 17:00:24 | BBKHOE | I | DON | 1,338.73 |
| 16-Mar-2020 1 | 2,113 | 0 | 431211 | 24-360-011 | Repair Quick-Attach Coupling Assembly | 23-Mar-2020 15:50:58 | BBKHOE | I | DON | 290.00 |
| 16-Mar-2020 1 | 2,113 | 0 | 431211 | 38-100-PMC | Service C PMI | 23-Mar-2020 12:00:30 | BBKHOE | P | DON | 667.34 |
| 16-Mar-2020 1 | 2,113 | 0 | 431211 | 02-360 | Clean Loader / Skid-Steer | 19-Mar-2020 13:21:42 | BWASH | N | DON | 430.19 |
| 16-Mar-2020 1 | 2,113 | 0 | 431211 | 03-052-013 | Replace Antenna and Mounting | 23-Mar-2020 17:00:12 | BBKHOE | B | DON | 55.13 |
| 16-Mar-2020 1 | 2,113 | 0 | 431211 | 03-360-003 | Replace Drive Train | 19-Mar-2020 16:27:32 | BBKHOE | P | DON | 869.79 |
| 16-Mar-2020 1 | 2,113 | 0 | 431211 | 06-100-PMA | Inspect A PMI | 24-Mar-2020 06:02:51 | BBKHOE | P | DON | 178.67 |
| 16-Mar-2020 1 | 2,113 | 0 | 431211 | 03-065-004 | Replace Cylinder | 20-Mar-2020 10:17:04 | BBKHOE | P | DON | 2,492.41 |
| 14-Sep-2020 0 | 3,141 | 0 | 461270 | 03-017-001 | Replace Tire - Pneumatic | 14-Sep-2020 09:59:48 | BTIRE | P | DON | 2,207.95 |
| 09-Mar-2021 1 | 3,950 | 0 | 492951 | 02-360 | Clean Loader / Skid-Steer | 11-Mar-2021 17:00:43 | BWASH | N | DON | 378.53 |
| 09-Mar-2021 1 | 3,950 | 0 | 492951 | 03-001-008 | Replace Motor - Blower | 15-Mar-2021 08:39:01 | BBKHOE | P | DON | 639.15 |
| 09-Mar-2021 1 | 3,950 | 0 | 492951 | 03-360-003 | Replace Drive Train | 15-Mar-2021 13:49:17 | BBKHOE | P | DON | 654.58 |
| 09-Mar-2021 1 | 3,950 | 0 | 492951 | 06-100-PMA | Inspect A PMI | 19-Mar-2021 06:03:50 | SCHED | P | DON | 311.34 |
| 09-Mar-2021 1 | 3,950 | 0 | 492951 | 06-100-PMB | Inspect B PMI | 09-Mar-2021 15:21:34 | SCHED | P | DON | 0.00 |
| 09-Mar-2021 1 | 3,950 | 0 | 492951 | 10-360-011 | Rebush Quick-Attach Coupling Assembly | 16-Mar-2021 15:34:21 | BBKHOE | N | DON | 1,000.25 |
| 09-Mar-2021 1 | 3,950 | 0 | 492951 | 03-032-009 | Replace Switch - Master Disconnect | 16-Mar-2021 10:18:39 | BBKHOE | I | DON | 170.89 |
| 09-Mar-2021 1 | 3,950 | 0 | 492951 | 38-100-PMC | Service C PMI | 16-Mar-2021 08:42:38 | BBKHOE | P | DON | 759.07 |
| 30-Nov-2021 C | 4,909 | 0 | 549687 | 03-017-001 | Replace Tire - Pneumatic | 01-Dec-2021 07:47:53 | BTIRE | I | DON | 442.18 |

Unit Job History

| WO Open Date | Meter 1 | Meter 2 | Work Order | Job Code | Job Description | Date Completed | Job Location | Job Reason | Job Status | Total Cost |
|--|---------|---------|------------|----------|-----------------|---|--------------|------------|------------|------------|
| Unit No: E1599 - 2019 JOHN DEERE 320G | | | | | | | | | | |
| 06-Dec-2021 | 0 | 4,909 | 0 | 551315 | 03-017-001 | Replace Tire - Pneumatic | BTIRE | I | DON | 442.18 |
| 14-Dec-2021 | 1 | 4,909 | 0 | 553591 | 03-017-001 | Replace Tire - Pneumatic | BTIRE | O | DON | 674.89 |
| 24-Mar-2022 | 0 | 5,455 | 0 | 576899 | 03-063-003 | Replace Transceiver - GPS Tracker | BBKHOE | Q | DON | 310.92 |
| 24-Mar-2022 | 0 | 5,455 | 0 | 576899 | 03-065-004 | Replace Cylinder | BBKHOE | I | DON | 1,388.28 |
| 24-Mar-2022 | 0 | 5,455 | 0 | 576899 | 02-360 | Clean Loader / Skid-Steer | BWASH | N | DON | 413.85 |
| 24-Mar-2022 | 0 | 5,455 | 0 | 576899 | 06-100-PMA | Inspect A PMI | BBKHOE | P | DON | 169.40 |
| 24-Mar-2022 | 0 | 5,455 | 0 | 576899 | 03-065-005 | Replace Drive - Motor / Pump | BBKHOE | P | DON | 283.11 |
| 24-Mar-2022 | 0 | 5,455 | 0 | 576899 | 38-100-PMC | Service C PMI | BBKHOE | P | DON | 1,130.70 |
| 24-Mar-2022 | 0 | 5,455 | 0 | 576899 | 24-360-003 | Repair Drive Train | BBKHOE | P | DON | 9,650.57 |
| 24-Mar-2022 | 0 | 5,455 | 0 | 576899 | 24-360-011 | Repair Quick-Attach Coupling Assembly | BBKHOE | P | DON | 1,926.90 |
| 24-Mar-2022 | 0 | 5,455 | 0 | 576899 | 24-002-018 | Repair Cab Or Front Door Mechanism | BBKHOE | P | DON | 306.84 |
| 24-Mar-2022 | 0 | 5,455 | 0 | 576899 | 24-002-021 | Repair Panel - Rear Door | BBKHOE | I | CAN | 0.00 |
| 24-Mar-2022 | 0 | 5,455 | 0 | 576899 | 03-001-008 | Replace Motor - Blower | BBKHOE | I | DON | 689.25 |
| 24-Mar-2022 | 0 | 5,455 | 0 | 576899 | 24-360-009 | Repair Bucket Tooth / Cutting Edge | BBKHOE | P | DON | 380.18 |
| 24-Mar-2022 | 0 | 5,455 | 0 | 576899 | 06-100-PMB | Inspect B PMI | BBKHOE | P | DON | 0.00 |
| 20-Apr-2022 | 1 | 5,455 | 0 | 583132 | 03-052 | Replace Electrical Accessories | BHVYEQ | O | CAN | 0.00 |
| 05-May-2022 | 1 | 5,455 | 0 | 586692 | 03-001-016 | Replace Filter - Cab Ventilation | BHVYEQ | P | DON | 82.65 |
| 05-May-2022 | 1 | 5,455 | 0 | 586692 | 03-065-006 | Replace Filters, Strainers, Screens & Housing | BHVYEQ | P | DON | 138.55 |
| 03-Jun-2022 | 0 | 5,747 | 0 | 593275 | 03-041-007 | Replace Filter - Outer | BBKHOE | P | DON | 82.11 |
| 27-Jul-2022 | 13 | 5,947 | 0 | 605456 | 38-045 | Service Power Plant | BBKHOE | P | DON | 38.66 |
| 27-Jul-2022 | 13 | 5,947 | 0 | 605456 | 03-041-006 | Replace Filter - Inner | BBKHOE | P | DON | 70.21 |
| 27-Jul-2022 | 13 | 5,947 | 0 | 605456 | 03-041-007 | Replace Filter - Outer | BBKHOE | P | DON | 82.11 |
| 27-Jul-2022 | 13 | 5,947 | 0 | 605456 | 03-001-016 | Replace Filter - Cab Ventilation | BBKHOE | P | DON | 40.42 |
| 20-Sep-2022 | 1 | 6,159 | 0 | 617976 | 24-360-011 | Repair Quick-Attach Coupling Assembly | BBKHOE | O | DON | 200.75 |
| 30-Sep-2022 | 1 | 6,190 | 0 | 620709 | 03-002-024 | Replace Glass / Windshield | BHVYEQ | E | DON | 673.74 |
| 30-Sep-2022 | 1 | 6,190 | 0 | 620709 | 24-065-004 | Repair Cylinder | BHVYEQ | O | DON | 638.73 |
| 06-Oct-2022 | 0 | 6,204 | 0 | 622175 | 03-017-001 | Replace Tire - Pneumatic | BTIRE | O | DON | 483.24 |
| 18-Oct-2022 | 1 | 6,243 | 0 | 625108 | 03-031-001 | Replace Generator/Alternator | BHVYEQ | O | DON | 541.31 |
| 09-Nov-2022 | 1 | 6,323 | 0 | 631144 | 03-002-024 | Replace Glass / Windshield | BHVYEQ | E | DON | 546.20 |

Unit Job History

| WO Open Date | Meter 1 | Meter 2 | Work Order | Job Code | Job Description | Date Completed | Job Location | Job Reason | Job Status | Total Cost |
|--|---------|---------|------------|----------|-----------------|---------------------------------------|--------------|------------|------------|------------|
| Unit No: E1599 - 2019 JOHN DEERE 320G | | | | | | | | | | |
| 08-Dec-2022 | 1 | 6,394 | 0 | 637952 | 03-044-002 | Replace Filters | BBKHOE | N | DON | 213.16 |
| 08-Dec-2022 | 1 | 6,394 | 0 | 637952 | 03-045-011 | Replace Filter Assembly - Oil | BBKHOE | N | DON | 36.81 |
| 08-Dec-2022 | 1 | 6,394 | 0 | 637952 | 24-360-006 | Repair Lift Arm Assembly | BBKHOE | O | DON | 59.36 |
| 14-Dec-2022 | 1 | 6,408 | 0 | 639292 | 03-002-024 | Replace Glass / Windshield | BHVYEQ | E | DON | 863.62 |
| 27-Jan-2023 | 1 | 6,512 | 0 | 648576 | 03-017-001 | Replace Tire - Pneumatic | BTIRE | O | DON | 18.01 |
| 01-Feb-2023 | 0 | 6,530 | 0 | 649638 | 03-002-024 | Replace Glass / Windshield | BBKHOE | E | DON | 778.03 |
| 01-Feb-2023 | 0 | 6,530 | 0 | 649638 | 03-032-001 | Replace Battery | BBKHOE | O | DON | 200.41 |
| 01-Feb-2023 | 0 | 6,530 | 0 | 649638 | 03-049-004 | Replace ECM Sensor | BHVYEQ | O | DON | 141.65 |
| 24-Feb-2023 | 1 | 6,607 | 0 | 655219 | 03-001-016 | Replace Filter - Cab Ventilation | BHVYEQ | O | DON | 85.80 |
| 13-Mar-2023 | 1 | 6,656 | 0 | 658966 | 24-017-001 | Repair Tire - Pneumatic | BTIRE | E | DON | 444.41 |
| 13-Mar-2023 | 1 | 6,656 | 0 | 658966 | 13-017-001 | Assemble Tire - Pneumatic | BTIRE | E | DON | 451.47 |
| 23-Mar-2023 | 0 | 6,692 | 0 | 661144 | 02-002 | Clean Cab & Sheet Metal | BHVYEQ | P | DON | 247.01 |
| 23-Mar-2023 | 0 | 6,692 | 0 | 661144 | 02-360 | Clean Loader / Skid-Steer | BWASH | N | DON | 311.27 |
| 23-Mar-2023 | 0 | 6,692 | 0 | 661144 | 03-001-008 | Replace Motor - Blower | BBKHOE | I | DON | 715.72 |
| 23-Mar-2023 | 0 | 6,692 | 0 | 661144 | 03-032-009 | Replace Switch - Master Disconnect | BBKHOE | P | DON | 114.56 |
| 23-Mar-2023 | 0 | 6,692 | 0 | 661144 | 03-042-006 | Replace Thermostat | BBKHOE | I | DON | 197.22 |
| 23-Mar-2023 | 0 | 6,692 | 0 | 661144 | 03-049-004 | Replace ECM Sensor | BHVYEQ | I | DON | 289.05 |
| 23-Mar-2023 | 0 | 6,692 | 0 | 661144 | 06-100-PMA | Inspect A PMI | BBKHOE | P | DON | 90.32 |
| 23-Mar-2023 | 0 | 6,692 | 0 | 661144 | 06-100-PMB | Inspect B PMI | BBKHOE | P | DON | 0.00 |
| 23-Mar-2023 | 0 | 6,692 | 0 | 661144 | 14-063-001 | Install Antenna - RF | BHVYEQ | P | DON | 335.33 |
| 23-Mar-2023 | 0 | 6,692 | 0 | 661144 | 24-360-006 | Repair Lift Arm Assembly | BBKHOE | I | DON | 2,336.64 |
| 23-Mar-2023 | 0 | 6,692 | 0 | 661144 | 24-360-011 | Repair Quick-Attach Coupling Assembly | BBKHOE | P | DON | 914.46 |
| 23-Mar-2023 | 0 | 6,692 | 0 | 661144 | 24-002-069 | Repair Support Hood Lift-Gas Charged | BHVYEQ | I | DON | 268.79 |
| 23-Mar-2023 | 0 | 6,692 | 0 | 661144 | 38-100-PMC | Service C PMI | BBKHOE | P | DON | 777.41 |
| 23-Mar-2023 | 0 | 6,692 | 0 | 661144 | 03-360-003 | Replace Drive Train | BBKHOE | I | DON | 798.81 |
| 23-Mar-2023 | 0 | 6,692 | 0 | 661144 | 26-014 | Weld Frame | BHVYEQ | N | DON | 102.37 |
| 11-May-2023 | 0 | 6,801 | 0 | 676594 | 03-017-001 | Replace Tire - Pneumatic | BTIRE | B | DON | 0.00 |
| 08-Jun-2023 | 0 | 6,846 | 0 | 679891 | 03-041-007 | Replace Filter - Outer | BBKHOE | O | DON | 180.12 |
| 08-Jun-2023 | 0 | 6,846 | 0 | 679891 | 03-045-011 | Replace Filter Assembly - Oil | BBKHOE | O | DON | 70.08 |

Unit Job History

| WO Open Date | Meter 1 | Meter 2 | Work Order | Job Code | Job Description | Date Completed | Job Location | Job Reason | Job Status | Total Cost |
|--|---------|---------|------------|------------|---|----------------------|--------------|------------|------------|------------|
| Unit No: E1599 - 2019 JOHN DEERE 320G | | | | | | | | | | |
| 08-Jun-2023 0 | 6,846 | 0 | 679891 | 03-001-016 | Replace Filter - Cab Ventilation | 08-Jun-2023 09:37:54 | BBKHOE | O | DON | 68.40 |
| 17-Jul-2023 14 | 6,958 | 0 | 688802 | 24-513-002 | Repair Quick Attachment | 17-Jul-2023 14:55:46 | BBKHOE | O | DON | 66.42 |
| 25-Aug-2023 1 | 7,082 | 0 | 700071 | 13-017-001 | Assemble Tire - Pneumatic | 25-Aug-2023 16:39:52 | BTIRE | O | DON | 525.90 |
| 11-Sep-2023 1 | 7,121 | 0 | 704172 | 03-017-001 | Replace Tire - Pneumatic | 11-Sep-2023 13:20:27 | BTIRE | E | DON | 342.16 |
| 06-Oct-2023 1 | 7,199 | 0 | 710849 | 03-065-006 | Replace Filters, Strainers, Screens & Housing | 06-Oct-2023 13:53:31 | BBKHOE | O | DON | 146.72 |
| 24-Oct-2023 1 | 7,246 | 0 | 715360 | 03-065-007 | Replace Hoses & Fittings | 27-Oct-2023 15:49:08 | BHVYEQ | B | DON | 415.00 |
| 09-Nov-2023 1 | 7,298 | 0 | 719422 | 03-017-001 | Replace Tire - Pneumatic | 09-Nov-2023 14:53:42 | BTIRE | O | DON | 358.59 |
| 10-Nov-2023 1 | 7,303 | 0 | 719784 | 23-513-004 | Burn / Cut Specialty Attachment | 22-Feb-2024 04:56:27 | BWELD | T | DON | 658.56 |
| 01-Dec-2023 1 | 7,352 | 0 | 723981 | 03-002-024 | Replace Glass / Windshield | 11-Dec-2023 06:55:45 | BBKHOE | E | DON | 414.23 |
| 05-Jan-2024 1 | 7,441 | 0 | 730624 | 03-002-024 | Replace Glass / Windshield | 10-Jan-2024 10:51:24 | BBKHOE | E | DON | 792.69 |
| 26-Jan-2024 1 | 7,476 | 0 | 734955 | 03-360-011 | Replace Quick-Attach Coupling Assembly | 29-Jan-2024 17:12:12 | TRK005 | N | DON | 4,843.23 |
| 29-Jan-2024 1 | 7,480 | 0 | 735453 | 03-041-006 | Replace Filter - Inner | 09-Feb-2024 07:55:42 | BHVYEQ | P | DON | 72.08 |
| 29-Jan-2024 1 | 7,480 | 0 | 735453 | 03-041-007 | Replace Filter - Outer | 09-Feb-2024 07:55:26 | BHVYEQ | P | DON | 79.46 |
| 29-Jan-2024 1 | 7,480 | 0 | 735453 | 03-044-002 | Replace Filters | 09-Feb-2024 07:55:07 | BHVYEQ | P | DON | 177.00 |
| 29-Jan-2024 1 | 7,480 | 0 | 735453 | 03-045-011 | Replace Filter Assembly - Oil | 09-Feb-2024 07:54:34 | BHVYEQ | P | DON | 31.36 |
| 29-Jan-2024 1 | 7,480 | 0 | 735453 | 03-065-006 | Replace Filters, Strainers, Screens & Housing | 09-Feb-2024 07:56:12 | BHVYEQ | P | DON | 147.14 |
| 29-Jan-2024 1 | 7,480 | 0 | 735453 | 03-002-024 | Replace Glass / Windshield | 30-Jan-2024 15:33:12 | BBKHOE | E | DON | 421.84 |
| 20-Feb-2024 0 | | 0 | 740005 | 06-100-PMA | Inspect A PMI | 09-Jul-2024 05:33:20 | BBKHOE | P | DON | 171.53 |
| 20-Feb-2024 0 | | 0 | 740005 | 02-360 | Clean Loader / Skid-Steer | 20-Feb-2024 14:14:22 | BWASH | N | DON | 181.06 |
| 20-Feb-2024 0 | | 0 | 740005 | 03-014-003 | Replace Engine Mountings | 05-Jul-2024 13:45:59 | BBKHOE | N | DON | 586.90 |
| 20-Feb-2024 0 | | 0 | 740005 | 03-045-013 | Replace Oil Pan | 03-Jul-2024 10:04:28 | BBKHOE | N | DON | 701.64 |
| 20-Feb-2024 0 | | 0 | 740005 | 03-052-013 | Replace Antenna and Mounting | 08-Jul-2024 05:59:44 | BBKHOE | N | DON | 50.48 |
| 20-Feb-2024 0 | | 0 | 740005 | 03-360-008 | Replace Operator Controls | 08-Jul-2024 05:58:49 | BBKHOE | N | DON | 414.17 |
| 20-Feb-2024 0 | | 0 | 740005 | 38-100-PMC | Service C PMI | 05-Jul-2024 15:00:01 | BBKHOE | P | DON | 446.99 |
| 20-Feb-2024 0 | | 0 | 740005 | 06-100-PMB | Inspect B PMI | | SCHED | P | CAN | 0.00 |
| 20-Feb-2024 0 | | 0 | 740005 | 25-042-002 | Remove Radiator | 05-Jul-2024 11:17:33 | BBKHOE | N | DON | 512.59 |
| 20-Feb-2024 0 | | 0 | 740005 | 25-045-020 | Remove Engine Assembly | 08-Jul-2024 05:59:14 | BBKHOE | N | DON | 314.00 |
| 20-Feb-2024 0 | | 0 | 740005 | 25-065-005 | Remove Drive - Motor / Pump | 05-Jul-2024 05:39:27 | BBKHOE | N | DON | 194.82 |
| 20-Feb-2024 0 | | 0 | 740005 | 25-001-001 | Remove Air Conditioning Assembly | 05-Jul-2024 12:00:02 | BBKHOE | N | DON | 376.16 |

Unit Job History

| WO Open Date | Meter 1 | Meter 2 | Work Order | Job Code | Job Description | Date Completed | Job Location | Job Reason | Job Status | Total Cost |
|--|---------|---------|------------|------------|---------------------------------|----------------------|--------------|------------|------------|------------|
| Unit No: E1599 - 2019 JOHN DEERE 320G | | | | | | | | | | |
| 20-Feb-2024 0 | 0 | 740005 | 740005 | OS-360 | Out-Service Loader / Skid-Steer | 08-Jul-2024 10:37:42 | BBKHOE | N | DON | 35.09 |
| 20-Feb-2024 0 | 0 | 740005 | 740005 | 02-002-044 | Clean Cab - Complete | 08-Jul-2024 09:41:06 | BBKHOE | N | DON | 84.36 |

Unit No: E1599 Count: 118 **61,590.88**