Unit Job History

Michels Corporation
Report Printed: 09-Sep-2021 12:38:55 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: N1066 - 2016 CAT 336FL										
12-May-2016 1	1	0	244326	14-063-003	Install Transceiver - GPS Tracker	12-May-2016 10:24:22	BHVYEQ	Q	DON	539.74
12-May-2016 1	1	0	244326	15-053-005	Paint Prep Markings - Vehicle - Decals	12-May-2016 10:25:07	BHVYEQ	Q	DON	209.48
06-Jun-2016 0(	2	0	250756	03-514-002	Replace Shanks or Teeth	06-Jun-2016 06:00:00	U60952	N	DON	855.79
14-Jul-2016 06	241	0	252142	06-100-PMB	Inspect B PMI	14-Jul-2016 06:00:00	U60952	P	DON	137.53
20-Aug-2016 1	241	0	256411	35-065-001	Diagnose Hydraulic Systems	20-Aug-2016 11:23:20	U60951	F	DON	607.67
21-Aug-2016 0	538	0	264265	03-CMP	Replace Component Part	21-Aug-2016 06:00:00	U60952	N	DON	85.56
01-Sep-2016 0	538	0	258149	06-100-PMB	Inspect B PMI	01-Sep-2016 06:00:00	U60952	P	DON	137.17
16-Nov-2016 1	798	0	266900	06-100-PMB	Inspect B PMI	17-Nov-2016 10:01:24	BHVYEQ	P	DON	434.07
26-Jun-2017 1(	1,323	0	294425	02-330	Clean Excavator	05-Jul-2017 07:17:18	BSETUP	J	DON	289.83
26-Jun-2017 1(	1,323	0	294425	03-001-002	Replace Heating & Ventilating	28-Jun-2017 16:16:57	BHVYEQ	I	DON	17.66
26-Jun-2017 1(	1,323	0	294425	03-001-026	Replace Belt - A/C Compressor	30-Jun-2017 12:00:03	BHVYEQ	I	DON	157.07
26-Jun-2017 1(	1,323	0	294425	03-002-010	Replace Mirrors	28-Jun-2017 17:00:27	BHVYEQ	I	DON	121.18
26-Jun-2017 1(	1,323	0	294425	03-042-013	Replace Fan Belt	30-Jun-2017 11:20:57	BHVYEQ	I	DON	204.70
26-Jun-2017 1(	1,323	0	294425	03-065-007	Replace Hoses & Fittings	28-Jun-2017 16:16:44	BHVYEQ	I	DON	140.61
26-Jun-2017 1(	1,323	0	294425	06-100-PMA	Inspect A PMI	30-Jun-2017 11:20:48	BHVYEQ	P	DON	0.00
26-Jun-2017 1(	1,323	0	294425	06-100-PMB	Inspect B PMI	30-Jun-2017 11:20:53	BHVYEQ	P	DON	486.55
26-Jun-2017 1(	1,323	0	294425	14-051-009	Install Fire Extinguisher	05-Jul-2017 07:38:40	BHVYEQ	Q	DON	98.54
26-Jun-2017 1(	1,323	0	294425	38-100-PMB	Service B PMI	27-Jun-2017 11:31:03	BHVYEQ	P	DON	423.25
09-Aug-2017 0	1,545	0	315210	03-330-002	Replace Undercarriage (Tracks&Rollers)	07-Dec-2017 14:42:21	70955E	F	DON	13,080.41
28-Sep-2017 1.	1,545	0	307202	03-111-001	Replace Track	02-Oct-2017 13:23:11	70955E	F	DON	13,080.41
28-Sep-2017 1.	1,545	0	307202	06-100-PMA	Inspect A PMI	02-Oct-2017 13:18:47	70955E	P	DON	0.00
17-Nov-2017 0	1,845	0	324439	06-100-PMA	Inspect A PMI	17-Nov-2017 00:00:00	BVLOFC	P	DON	0.00
14-Feb-2018 1.	2,312	0	343971	06-100-PMA	Inspect A PMI	16-Jul-2018 15:59:49	U70956	P	DON	126.29
10-May-2018 (	2,893	0	347045	06-100-PMA	Inspect A PMI	07-Aug-2018 06:51:02	U70956	P	DON	59.09
22-Jan-2019 1:	3,680	0	369392	03-065-007	Replace Hoses & Fittings	18-Feb-2019 08:37:28	WSHSHP	I	DON	267.58
22-Jan-2019 1:	3,680	0	369392	21-059-006	Fabricate Towing Hitch Assembly	18-Feb-2019 08:37:28	WSHSHP	E	DON	3,628.57
22-Jan-2019 1:	3,680	0	369392	24-330-001	Repair Bucket and Attachments	18-Feb-2019 08:37:28	WSHSHP	E	DON	930.07
29-Apr-2019 1	3,945	0	408628	06-100-PMA	Inspect A PMI	29-Apr-2019 23:00:00	PIPE03	P	DON	93.93
01-May-2019 1	3,933	0	383824	03-054-002	Replace Alarm - Reverse Signal	17-Oct-2019 16:40:47	PIPE03	O	DON	167.18

Unit Job History

Michels Corporation

Report Printed: 09-Sep-2021 12:38:55 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: N1066 - 2016 CAT 336FL										
01-May-2019 1	3,933	0	383824	03-111-002	Replace Roller	17-Oct-2019 16:40:47	PIPE03	B	DON	1,566.58
01-May-2019 1	3,933	0	383824	24-513-002	Repair Quick Attachment	17-Oct-2019 16:40:47	PIPE03	B	DON	375.27
14-Jun-2019 1(	4,270	0	390312	03-049-004	Replace ECM Sensor	25-Jun-2019 11:54:33	WSHSHP	B	DON	644.62
14-Jun-2019 1(	4,270	0	390312	95-MSC	Travel Miscellanous	25-Jun-2019 11:54:33	WSHSHP	B	DON	116.31
26-Jun-2019 2(	4,340	0	409680	06-100-PMA	Inspect A PMI	26-Jun-2019 23:00:00	PIPE03	P	DON	104.81
28-Aug-2019 1	4,640	0	413009	06-100-PMA	Inspect A PMI	28-Aug-2019 23:00:00	PIPE03	P	DON	197.22
28-Oct-2019 1(	5,015	0	431738	06-100-PMA	Inspect A PMI	28-Oct-2019 23:00:00	PIPE03	P	DON	104.86
30-Nov-2019 1		0	414580	03-002-031	Replace Body Moldings - Exterior	17-Mar-2020 08:31:21	WSHSHP	I	DON	707.76
30-Nov-2019 1		0	414580	03-045-023	Replace Engine Belts	17-Mar-2020 08:31:21	WSHSHP	I	DON	481.08
30-Nov-2019 1		0	414580	03-054-002	Replace Alarm - Reverse Signal	17-Mar-2020 08:31:21	WSHSHP	I	DON	177.97
30-Nov-2019 1		0	414580	03-065-007	Replace Hoses & Fittings	17-Mar-2020 08:31:21	WSHSHP	I	DON	1,773.44
30-Nov-2019 1		0	414580	06-100-009	Inspect Safety Check	17-Mar-2020 08:31:21	WSHSHP	P	DON	195.53
30-Nov-2019 1		0	414580	12-330-012	Refinish Counter Weight Assembly	17-Mar-2020 08:31:21	WSHSHP	I	DON	0.00
30-Nov-2019 1		0	414580	24-043-001	Repair Emission Controls	17-Mar-2020 08:31:21	WSHSHP	I	DON	5,242.61
30-Nov-2019 1		0	414580	95-MSC	Travel Miscellanous	17-Mar-2020 08:31:21	WSHSHP	P	DON	882.58
01-Apr-2020 0		0	433891	37-049-002	Calibrate ECM Module	02-Apr-2020 07:27:01	WSHSHP	P	DON	262.07
01-Jun-2021 1(		0	509974	03-032-001	Replace Battery	04-Jun-2021 07:59:55	BHVYEQ	N	DON	455.26
25-Jun-2021 0:		0	515200	03-063-003	Replace Transceiver - GPS Tracker	25-Jun-2021 16:18:30	SCHED	Q	DON	281.59
03-Aug-2021 1		0	522626	25-051-009	Remove Fire Extinguisher	10-Aug-2021 12:28:29	BHVYEQ	Z	DON	15.55
03-Aug-2021 1		0	522626	25-063-003	Remove Transceiver - GPS Tracker	11-Aug-2021 05:16:02	BHVYEQ	Z	DON	199.31
03-Aug-2021 1		0	522626	OS-100-008	Out-Service Out-Service Inspection	10-Aug-2021 07:37:27	BHVYEQ	Z	DON	498.16
11-Aug-2021 C		0	524315	02-330	Clean Excavator	12-Aug-2021 06:05:55	BWASH	Z	DON	551.68
11-Aug-2021 C		0	524315	12-330	Refinish Excavator		BBODY	Z	WFA	0.00
11-Aug-2021 C		0	524315	15-330	Paint Prep Excavator		BBODY	Z	WND	707.19

Unit No: N1066 **Count: 53** **51,921.38**