Unit Job History

Michels Corporation

Report Printed: 04-Aug-2021 09:56:04 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2660 - 2014 F150 SUPERCREW										
28-May-2014 1	26	0	159475	06-100-009	Inspect Safety Check	29-May-2014 13:35:27	BTRUCK	C	DON	26.59
28-May-2014 1	26	0	159475	14-002-063	Install Computer Stand / Dock	28-May-2014 16:47:22	BDETL	C	DON	612.15
28-May-2014 1	26	0	159475	14-034-006	Install Warning Lamps - Special Application	26-Jun-2014 12:29:50	BSETUP	C	DON	310.83
28-May-2014 1	26	0	159475	14-052-003	Install Radio Equipment	28-May-2014 16:30:00	BDETL	C	DON	956.30
28-May-2014 1	26	0	159475	14-052-014	Install Cellular Telephone Accessories	28-May-2014 16:52:50	BDETL	C	DON	54.56
28-May-2014 1	26	0	159475	14-052-015	Install Power Inverter/Converter	28-May-2014 14:28:27	BDETL	C	DON	270.94
28-May-2014 1	26	0	159475	14-053-005	Install Markings - Vehicle - Decals	29-May-2014 06:04:36	BDETL	C	DON	85.08
28-May-2014 1	26	0	159475	14-053-014	Install Floor Mats	28-May-2014 17:01:47	BDETL	C	DON	77.99
28-May-2014 1	26	0	159475	14-071-011	Install Scuff Liner / Bed Mat	28-May-2014 14:51:03	BDETL	C	DON	76.22
28-May-2014 1	26	0	159475	14-078-009	Install Mud Flaps and Hanger Brackets	29-May-2014 07:04:11	BDETL	C	DON	104.78
28-May-2014 1	26	0	159475	14-078-014	Install Tarpaulin/ Tonneau Cover	28-May-2014 15:24:43	BDETL	C	DON	421.09
31-Jul-2014 06	4,605	0	173577	06-100-PMA	Inspect A PMI	31-Jul-2014 17:00:00	BVLOFC	P	DON	48.11
06-Oct-2014 0	4,605	0	178765	24-017	Repair Tires, Tubes, Liners & Valves	06-Oct-2014 17:00:00	BVLOFC	F	DON	24.65
06-Oct-2014 0	10,274	0	181528	06-100-PMA	Inspect A PMI	06-Oct-2014 17:00:00	BVLOFC	P	DON	49.88
06-Oct-2014 0	10,274	0	181528	14-017	Install Tires, Tubes, Liners & Valves	06-Oct-2014 17:00:00	BVLOFC	F	DON	61.21
09-Feb-2015 1	10,274	0	190702	03-052-014	Replace Cellular Telephone Accessories	09-Feb-2015 13:18:02	BSETUP	J	DON	1.60
03-Mar-2015 1	22,519	0	193199	06-100-PMB	Inspect B PMI	03-Mar-2015 14:23:40	BTRUCK	P	DON	19.16
03-Mar-2015 1	22,519	0	193199	38-045	Service Power Plant	03-Mar-2015 15:34:43	BTRUCK	P	DON	84.80
21-Apr-2015 0	27,244	0	198457	06-100-PMB	Inspect B PMI	21-Apr-2015 10:14:11	BTRUCK	P	DON	12.37
21-Apr-2015 0	27,244	0	198457	24-017-001	Repair Tire - Pneumatic	22-Apr-2015 08:18:51	BTRUCK	I	DON	0.00
21-Apr-2015 0	27,244	0	198457	38-045	Service Power Plant	21-Apr-2015 09:51:48	BTRUCK	P	DON	45.06
20-May-2015 1	30,377	0	201685	03-002-035	Replace Windshield Wiper & Washer	20-May-2015 13:42:58	BTRUCK	I	DON	24.46
20-May-2015 1	30,377	0	201685	06-100-PMB	Inspect B PMI	20-May-2015 13:37:09	BTRUCK	P	DON	13.51
20-May-2015 1	30,377	0	201685	38-045	Service Power Plant	20-May-2015 14:16:46	BTRUCK	P	DON	58.82
19-Aug-2015 0	37,908	0	227271	06-100-PMA	Inspect A PMI	19-Aug-2015 00:00:00	BVLOFC	P	DON	54.82
28-Sep-2015 1	37,908	0	216305	06-100-PMB	Inspect B PMI	29-Sep-2015 13:43:16	BTRUCK	P	DON	69.28
28-Sep-2015 1	37,908	0	216305	24-032	Repair Cranking System	29-Sep-2015 11:12:23	BTRUCK	O	DON	113.09
28-Sep-2015 1	37,908	0	216305	38-045	Service Power Plant	29-Sep-2015 13:59:58	BTRUCK	P	DON	42.21
05-Jan-2016 1	43,598	0	227582	03-013-001	Replace Front Brakes & Drums	05-Jan-2016 15:17:08	BVLOFC	O	DON	586.50

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2660 - 2014 F150 SUPERCREW										
31-Mar-2016 1	43,598	0	239605	14-078-014	Install Tarpaulin/ Tonneau Cover	31-Mar-2016 12:16:03	BSETUP	C	DON	526.74
31-Mar-2016 1	43,598	0	239605	14-510-002	Install Tool Box	31-Mar-2016 12:07:44	BSETUP	C	DON	431.12
23-May-2016 1	55,221	0	245471	06-100-PMA	Inspect A PMI	23-May-2016 14:13:34	BVLOFC	P	DON	51.06
23-May-2016 1	55,221	0	245471	03-017-001	Replace Tire - Pneumatic	23-May-2016 14:17:23	BVLOFC	O	DON	985.28
01-Aug-2016 1	64,685	0	253998	06-100-PMA	Inspect A PMI	03-Aug-2016 00:00:00	BVLOFC	P	DON	50.81
01-Aug-2016 1	64,685	0	253998	31-017-001	Rotate Tire - Pneumatic	03-Aug-2016 00:00:00	BVLOFC	P	DON	25.69
01-Aug-2016 1	64,685	0	253998	34-021-001	Reseal Axle Assembly - Driven, Front Steering	03-Aug-2016 00:00:00	BVLOFC	I	DON	786.10
01-Aug-2016 1	64,685	0	253998	38-022	Service Axles - Driven, Rear	03-Aug-2016 00:00:00	BVLOFC	P	DON	145.17
01-Aug-2016 1	64,685	0	253998	38-027	Service Transmission - Main, Automatic	03-Aug-2016 00:00:00	BVLOFC	P	DON	236.84
26-Sep-2016 1	70,699	0	260754	06-100-PMA	Inspect A PMI	26-Sep-2016 13:06:49	BVLOFC	P	DON	50.81
20-Mar-2017 1	86,913	0	281749	38-045	Service Power Plant	21-Mar-2017 11:28:14	BTRUCK	P	DON	44.07
20-Mar-2017 1	86,913	0	281749	06-100-PMB	Inspect B PMI	21-Mar-2017 11:05:14	BTRUCK	P	DON	41.27
20-Mar-2017 1	86,913	0	281749	24-032-002	Repair Starter	21-Mar-2017 13:59:50	BTRUCK	O	DON	29.92
20-Mar-2017 1	86,913	0	281749	03-013-002	Replace Rear Brakes & Drums	21-Mar-2017 14:03:13	BTRUCK	I	DON	269.25
11-Apr-2017 0	86,913	0	284707	03-013-001	Replace Front Brakes & Drums		BVLOFC	O	CAN	0.00
11-Apr-2017 0	86,913	0	284707	03-013-002	Replace Rear Brakes & Drums		BVLOFC	O	CAN	0.00
11-Apr-2017 0	86,913	0	284707	06-100-PMA	Inspect A PMI		BTRUCK	P	CAN	0.00
03-Aug-2017 1	97,066	0	299525	03-013-001	Replace Front Brakes & Drums	04-Aug-2017 08:19:00	BVLOFC	O	DON	611.57
03-Aug-2017 1	97,066	0	299525	06-100-PMA	Inspect A PMI	04-Aug-2017 08:17:00	BTRUCK	P	DON	51.97
14-Oct-2017 0		0	334382	06-100-PMA	Inspect A PMI	13-Jun-2018 12:26:34	BVLOFC	P	DON	0.00
22-Nov-2017 0	106,220	0	313477	03-053-005	Replace Markings - Vehicle - Decals	22-Nov-2017 11:41:37	BSETUP	I	DON	166.31
02-Jan-2018 0	109,444	0	317735	03-032-001	Replace Battery	02-Jan-2018 11:33:18	BTRUCK	O	DON	116.57
02-Jan-2018 0	109,444	0	317735	03-078-009	Replace Mud Flaps and Hanger Brackets	02-Jan-2018 16:20:48	BTRUCK	I	DON	28.77
02-Jan-2018 0	109,444	0	317735	06-100-PMB	Inspect B PMI	02-Jan-2018 14:46:19	BTRUCK	P	DON	64.05
02-Jan-2018 0	109,444	0	317735	38-045	Service Power Plant	02-Jan-2018 15:29:06	BTRUCK	P	DON	54.27
30-Mar-2018 1	117,910	0	329390	02-002	Clean Cab & Sheet Metal	05-Apr-2018 13:10:02	BSETUP	I	DON	183.28
30-Mar-2018 1	117,910	0	329390	03-002-035	Replace Windshield Wiper & Washer	02-Apr-2018 12:00:04	BTRUCK	I	DON	30.81
30-Mar-2018 1	117,910	0	329390	06-042-002	Inspect Radiator	04-Apr-2018 05:14:09	BTRUCK	I	DON	26.93
30-Mar-2018 1	117,910	0	329390	06-100-PMB	Inspect B PMI	02-Apr-2018 10:43:20	BTRUCK	P	DON	59.28

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2660 - 2014 F150 SUPERCREW										
30-Mar-2018 1	117,910	0	329390	14-034-006	Install Warning Lamps - Special Application	05-Apr-2018 06:40:14	BSETUP	I	DON	18.74
30-Mar-2018 1	117,910	0	329390	24-045-026	Repair Tensioner - Engine Belts	03-Apr-2018 11:01:01	BTRUCK	O	DON	155.85
30-Mar-2018 1	117,910	0	329390	31-017-001	Rotate Tire - Pneumatic	02-Apr-2018 11:27:34	BTRUCK	I	DON	24.62
30-Mar-2018 1	117,910	0	329390	38-045	Service Power Plant	02-Apr-2018 11:48:34	BTRUCK	P	DON	42.67
19-Jun-2018 0	119,284	0	340285	06-100-PMB	Inspect B PMI	19-Jun-2018 11:00:59	BTRUCK	P	DON	39.58
19-Jun-2018 0	119,284	0	340285	38-045	Service Power Plant	19-Jun-2018 11:16:50	BTRUCK	P	DON	50.27
19-Sep-2018 1	130,597	0	352839	06-100-PMB	Inspect B PMI	24-Sep-2018 11:52:38	BTRUCK	P	DON	30.57
19-Sep-2018 1	130,597	0	352839	38-045	Service Power Plant	24-Sep-2018 11:59:25	BTRUCK	P	DON	35.01
27-Nov-2018 1	134,861	0	361910	24-027-033	Repair Range Selector Or Manual Linkage	29-Nov-2018 11:31:28	BTRUCK	O	DON	7.79
27-Nov-2018 1	134,861	0	361910	24-032	Repair Cranking System	29-Nov-2018 08:24:12	BTRUCK	O	DON	258.10
27-Nov-2018 1	134,861	0	361910	38-045	Service Power Plant	28-Nov-2018 12:00:18	BTRUCK	P	DON	47.99
27-Nov-2018 1	134,861	0	361910	06-100-PMB	Inspect B PMI	28-Nov-2018 11:29:10	BTRUCK	P	DON	46.15
27-Nov-2018 1	134,861	0	361910	24-042-012	Repair Clamps and Hoses	29-Nov-2018 10:49:44	BTRUCK	I	DON	168.89
27-Nov-2018 1	134,861	0	361910	31-017-001	Rotate Tire - Pneumatic	29-Nov-2018 11:17:16	BTRUCK	P	DON	15.11
14-Jan-2019 1	137,491	0	368094	24-017-001	Repair Tire - Pneumatic	15-Jan-2019 10:38:27	BTRUCK	O	DON	90.00
14-Jan-2019 1	137,491	0	368094	24-045-021	Repair Electronic Engine Controls	15-Jan-2019 16:12:02	BTRUCK	O	DON	157.65
31-Jan-2019 0	138,472	0	370592	06-100-PMB	Inspect B PMI	27-Feb-2019 10:09:29	BTRUCK	P	DON	106.29
31-Jan-2019 0	138,472	0	370592	24-032-001	Repair Battery	31-Jan-2019 12:00:58	BTRUCK	O	DON	141.56
31-Jan-2019 0	138,472	0	370592	24-045-021	Repair Electronic Engine Controls	27-Feb-2019 10:09:26	BTRUCK	O	DON	3,799.77
16-May-2019 (	148,890	0	386087	03-002-035	Replace Windshield Wiper & Washer	17-May-2019 14:02:51	BTRUCK	I	DON	39.18
16-May-2019 (	148,890	0	386087	03-013-002	Replace Rear Brakes & Drums	17-May-2019 16:42:54	BTRUCK	I	DON	401.27
16-May-2019 (	148,890	0	386087	03-017-001	Replace Tire - Pneumatic	20-May-2019 05:51:20	BTRUCK	I	DON	940.42
16-May-2019 (	148,890	0	386087	06-100-PMB	Inspect B PMI	17-May-2019 13:12:46	BTRUCK	P	DON	46.28
16-May-2019 (	148,890	0	386087	24-013-001	Repair Front Brakes & Drums	17-May-2019 16:07:34	BTRUCK	O	DON	480.67
16-May-2019 (	148,890	0	386087	38-045	Service Power Plant	17-May-2019 13:32:18	BTRUCK	P	DON	42.04
16-Aug-2019 0	158,994	0	399005	03-002-035	Replace Windshield Wiper & Washer	16-Aug-2019 14:52:55	BTRUCK	I	DON	27.92
16-Aug-2019 0	158,994	0	399005	06-100-PMB	Inspect B PMI	16-Aug-2019 14:09:12	BTRUCK	P	DON	31.92
16-Aug-2019 0	158,994	0	399005	24-002-016	Repair Compartment Lid - Tail & Lift Gate - Re	16-Aug-2019 16:33:06	BTRUCK	O	DON	59.38
16-Aug-2019 0	158,994	0	399005	31-017-001	Rotate Tire - Pneumatic	16-Aug-2019 15:24:49	BTRUCK	I	DON	17.50

Unit Job History

Michels Corporation

Report Printed: 04-Aug-2021 09:56:04 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2660 - 2014 F150 SUPERCREW										
16-Aug-2019 0	158,994	0	399005	38-045	Service Power Plant	16-Aug-2019 14:43:08	BTRUCK	P	DON	50.89
10-Dec-2019 1	173,426	0	416175	03-032-001	Replace Battery	10-Dec-2019 11:22:16	BVLOFC	O	DON	188.40
10-Dec-2019 1	173,426	0	416175	03-034-001	Replace Headlamps / Fog Lamps	10-Dec-2019 11:23:28	BVLOFC	O	DON	763.36
22-Sep-2020 1:	182,905	0	462706	03-017-001	Replace Tire - Pneumatic	22-Sep-2020 13:02:32	BVLOFC	O	DON	917.88
22-Sep-2020 1:	182,905	0	462706	06-100-PMA	Inspect A PMI	22-Sep-2020 13:02:32	BTRUCK	P	DON	0.00
22-Sep-2020 1:	182,905	0	462706	38-100-PMA	Service A PMI	22-Sep-2020 13:02:32	BVLOFC	P	DON	71.14
14-Oct-2020 1:	183,302	0	466555	03-002-024	Replace Glass / Windshield	19-Oct-2020 11:59:06	BVLOFC	O	DON	364.13
27-Oct-2020 1	183,302	0	469028	03-063-003	Replace Transceiver - GPS Tracker	27-Oct-2020 14:11:49	BTRUCK	Q	DON	233.11
27-Jul-2021 13	207,641		521161	06-100-009	Inspect Safety Check	28-Jul-2021 08:02:18	BTRUCK	I	DON	54.96
28-Jul-2021 11	207,641		521389	25-052-003	Remove Radio Equipment	28-Jul-2021 16:34:36	BSETUP	Z	DON	116.57
28-Jul-2021 11	207,641		521389	25-053-005	Remove Markings - Vehicle - Decals	28-Jul-2021 14:51:07	BSETUP	Z	DON	53.85
28-Jul-2021 11	207,641		521389	02-002	Clean Cab & Sheet Metal	29-Jul-2021 08:55:14	BSETUP	Z	DON	298.04

Unit No: B2660 **Count: 99** **19,809.46**