Unit Job History

Michels Corporation

Report Printed: 18-Aug-2021 05:42:38 By User: RHENNING

Unit No: N0883 - 2013 JOHN DEERE 290G

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
05-Jun-2013 0	3	0	118990	14-063	Install Satellite Communications System	05-Jun-2013 11:59:34	BHVYEQ	I	DON	509.11
03-Oct-2013 1	3	0	132763	03-514-002	Replace Shanks or Teeth	04-Oct-2013 10:48:10	BHVYEQ	J	DON	861.53
10-Dec-2013 1	264	0	142240	03-065-007	Replace Hoses & Fittings	10-Dec-2013 14:48:39	BVLOFC	F	DON	495.64
11-Sep-2014 1	1,137	0	172080	06-100-PMA	Inspect A PMI	11-Sep-2014 16:04:48	BHVYEQ	P	DON	344.22
11-Sep-2014 1	1,137	0	172080	14-330-001	Install Bucket and Attachments	11-Sep-2014 13:07:15	BHVYEQ	P	DON	26.34
28-May-2015 (	1,862	0	202289	02-330	Clean Excavator	04-Jun-2015 14:09:19	BWASH	J	DON	140.56
28-May-2015 (	1,862	0	202289	03-330-003	Replace Final Drive	01-Jun-2015 17:00:14	BHVYEQ	I	DON	58.40
28-May-2015 (	1,862	0	202289	06-100-PMB	Inspect B PMI	04-Jun-2015 14:59:16	BHVYEQ	P	DON	123.43
28-May-2015 (	1,862	0	202289	24-514	Repair Bucket	05-Jun-2015 11:15:42	BWELD	N	DON	2,593.32
28-May-2015 (	1,862	0	202289	38-100-PMB	Service B PMI	02-Jun-2015 07:08:54	BHVYEQ	P	DON	1,689.79
24-Aug-2015 1	2,352	0	213884	24-330-013	Repair Operator Controls	24-Aug-2015 13:04:48	BVLOFC	O	DON	203.35
15-Sep-2015 1	2,502	0	217248	24-330	Repair Excavator	15-Sep-2015 15:42:12	BVLOFC	O	DON	328.51
01-Oct-2015 0		0	219790	24-043-001	Repair Emission Controls	01-Oct-2015 07:55:25	BVLOFC	O	DON	685.35
04-Apr-2016 1	2,945	0	240010	03-063-003	Replace Transceiver - GPS Tracker	04-Apr-2016 17:39:20	BHVYEQ	Q	DON	765.67
06-May-2016 1	3,050	0	243739	03-514-002	Replace Shanks or Teeth	17-May-2016 07:49:45	LAVSHP	O	DON	1,097.56
06-May-2016 1	3,050	0	243739	24-330-001	Repair Bucket and Attachments	10-May-2016 07:24:39	LAVSHP	O	DON	438.92
06-May-2016 1	3,050	0	243739	35-465-003	Diagnose Camera Assembly	17-May-2016 07:50:07	LAVSHP	O	DON	24.86
01-Jul-2016 10	3,151	0	250444	06-100-PMB	Inspect B PMI	07-Jul-2016 07:52:25	LAVSHP	P	DON	726.15
18-Jul-2016 11	3,151	0	252259	03-330-002	Replace Undercarriage (Tracks&Rollers)	26-Jul-2016 21:26:01	LAVSHP	O	DON	1,364.65
18-Jul-2016 11	3,151	0	252259	03-465-003	Replace Camera Assembly	28-Jul-2016 07:29:59	LAVSHP	O	DON	485.79
18-Jul-2016 11	3,151	0	252259	35-001-001	Diagnose Air Conditioning Assembly	28-Jul-2016 07:29:39	LAVSHP	O	DON	44.63
02-Aug-2016 1	3,151	0	254159	03-065-034	Replace Switch - Pressure	19-Aug-2016 08:25:53	LAVSHP	I	DON	176.09
02-Aug-2016 1	3,151	0	254159	03-099-004	Replace Wiring Harness	19-Aug-2016 08:26:11	LAVSHP	I	DON	272.53
02-Aug-2016 1	3,151	0	254159	06-001-001	Inspect Air Conditioning Assembly	19-Aug-2016 08:25:46	LAVSHP	O	DON	101.91
07-Oct-2016 0	3,448	0	262151	06-100-PMA	Inspect A PMI	11-Oct-2016 09:36:41	LAVSHP	P	DON	375.51
07-Oct-2016 0	3,448	0	262151	24-002-020	Repair Side Door Mechanism	11-Oct-2016 09:37:03	LAVSHP	I	DON	115.22
07-Oct-2016 0	3,448	0	262151	24-034-014	Repair Auxiliary Work / Flood Light	11-Oct-2016 09:36:46	LAVSHP	I	DON	6.73
10-Mar-2017 0	3,475	0	280476	03-002-003	Replace Running Boards / Step Tubes	27-Mar-2017 13:53:33	LAVSHP	I	DON	153.39
10-Mar-2017 0	3,475	0	280476	03-002-010	Replace Mirrors	27-Mar-2017 13:53:39	LAVSHP	I	DON	124.08

Unit Job History

Michels Corporation

Report Printed: 18-Aug-2021 05:42:38 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: N0883 - 2013 JOHN DEERE 290G										
10-Mar-2017 0	3,475	0	280476	03-518-004	Replace Railing	27-Mar-2017 13:53:47	LAVSHP	I	DON	406.19
10-Mar-2017 0	3,475	0	280476	06-330	Inspect Excavator	27-Mar-2017 13:53:27	LAVSHP	S	DON	161.96
10-Mar-2017 0	3,475	0	280476	24-042-012	Repair Clamps and Hoses	27-Mar-2017 13:53:42	LAVSHP	I	DON	79.81
10-Mar-2017 0	3,475	0	280476	24-065-007	Repair Hoses & Fittings	27-Mar-2017 13:53:45	LAVSHP	I	DON	239.42
10-Mar-2017 0	3,475	0	280476	24-330-015	Repair Quik-Attatch Assembly	27-Mar-2017 13:53:36	LAVSHP	I	DON	79.81
10-Mar-2017 0	3,475	0	280476	26-330-001	Weld Bucket and Attachments	27-Mar-2017 13:53:50	LAVSHP	I	DON	319.23
10-Mar-2017 0	3,475	0	280476	95-MSC-004	Travel Travel Time - To/From Job Site	27-Mar-2017 13:53:30	LAVSHP	J	DON	106.94
09-May-2017 1	3,476	0	288267	03-032-001	Replace Battery	09-May-2017 17:57:56	LAVSHP	I	DON	482.80
09-May-2017 1	3,476	0	288267	06-032-001	Inspect Battery	09-May-2017 17:23:16	LAVSHP	O	DON	6.93
23-Aug-2017 1	3,602	0	302264	03-002-024	Replace Glass / Windshield	25-Aug-2017 07:10:26	LAVSHP	E	DON	525.44
23-Aug-2017 1	3,602	0	302264	35-049-001	Diagnose ECM Fault Code	28-Aug-2017 11:51:39	LAVSHP	B	DON	1,075.02
23-Aug-2017 1	3,602	0	302264	95-MSC-004	Travel Travel Time - To/From Job Site	28-Aug-2017 11:51:35	LAVSHP	J	DON	142.06
02-Oct-2017 1:	3,640	0	307193	03-002-010	Replace Mirrors	02-Oct-2017 13:03:02	LAVSHP	E	DON	99.99
24-Oct-2017 1:	3,762	0	310046	06-100-PMA	Inspect A PMI	25-Oct-2017 10:01:53	LAVSHP	P	DON	247.43
24-Oct-2017 1:	3,762	0	310046	14-052-005	Install Transmitter - CB	01-Nov-2017 10:39:26	LAVSHP	O	DON	72.63
24-Oct-2017 1:	3,762	0	310046	24-002-024	Repair Glass / Windshield	24-Oct-2017 17:07:58	LAVSHP	B	DON	62.21
21-Dec-2017 0	3,945	0	317056	02-330	Clean Excavator	13-Jan-2018 09:00:03	BWASH	J	DON	192.97
21-Dec-2017 0	3,945	0	317056	03-065-005	Replace Drive - Motor / Pump	05-Feb-2018 11:30:39	BHVYEQ	I	DON	182.49
21-Dec-2017 0	3,945	0	317056	03-065-007	Replace Hoses & Fittings	08-Jan-2018 10:58:22	BHVYEQ	I	DON	1,969.28
21-Dec-2017 0	3,945	0	317056	03-330-001	Replace Bucket and Attachments	12-Jan-2018 12:02:16	BHVYEQ	I	DON	5,942.00
21-Dec-2017 0	3,945	0	317056	03-330-002	Replace Undercarriage (Tracks&Rollers)	03-Jan-2018 13:43:02	BHVYEQ	I	DON	18,300.70
21-Dec-2017 0	3,945	0	317056	06-100-PMB	Inspect B PMI	15-Jan-2018 09:38:59	BHVYEQ	P	DON	474.76
21-Dec-2017 0	3,945	0	317056	14-051-009	Install Fire Extinguisher	10-Jan-2018 06:01:51	BHVYEQ	J	DON	166.06
21-Dec-2017 0	3,945	0	317056	14-052-005	Install Transmitter - CB	10-Jan-2018 13:06:38	BHVYEQ	O	DON	933.15
21-Dec-2017 0	3,945	0	317056	14-065-004	Install Cylinder	12-Jan-2018 10:44:58	BHVYEQ	I	DON	230.51
21-Dec-2017 0	3,945	0	317056	24-065-004	Repair Cylinder	18-Jan-2018 15:23:41	BHVYEQ	I	DON	3,544.70
21-Dec-2017 0	3,945	0	317056	25-065-004	Remove Cylinder	08-Jan-2018 15:32:52	BHVYEQ	I	DON	57.90
21-Dec-2017 0	3,945	0	317056	38-100-PMB	Service B PMI	09-Jan-2018 16:31:47	BHVYEQ	P	DON	832.45
19-Mar-2018 0	4,163	0	327770	35-049-003	Diagnose ECM Wiring Harness	26-Mar-2018 10:40:41	LAVSHP	B	DON	267.77

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: N0883 - 2013 JOHN DEERE 290G										
19-Mar-2018 0	4,163	0	327770	06-033-007	Inspect Glow Plug	26-Mar-2018 10:40:48	LAVSHP	I	DON	323.22
19-Mar-2018 0	4,163	0	327770	35-049-001	Diagnose ECM Fault Code	26-Mar-2018 10:40:45	LAVSHP	B	DON	76.27
19-Mar-2018 0	4,163	0	327770	03-033-007	Replace Glow Plug	26-Mar-2018 10:40:51	LAVSHP	I	DON	605.78
14-May-2018 1	4,217	0	335704	06-100-PMA	Inspect A PMI	14-May-2018 17:19:20	LAVSHP	P	DON	109.07
03-Oct-2018 0		0	354838	06-100-PMA	Inspect A PMI	03-Oct-2018 12:38:21	LAVSHP	P	DON	495.99
07-Nov-2018 1	4,528	0	359867	06-100-PMA	Inspect A PMI	07-Nov-2018 17:49:44	LAVSHP	P	DON	107.49
01-Mar-2019 1	4,704	0	374738	03-032-001	Replace Battery	01-Mar-2019 13:52:50	LAVSHP	B	DON	570.63
18-Mar-2019 1	4,750	0	377048	06-049-001	Inspect ECM Fault Code	20-Mar-2019 15:00:20	LAVSHP	I	DON	37.92
18-Mar-2019 1	4,750	0	377048	06-100-PMA	Inspect A PMI	18-Mar-2019 17:14:41	LAVSHP	P	DON	565.11
18-Mar-2019 1	4,750	0	377048	24-043-004	Repair Turbocharger	21-Mar-2019 11:56:23	LAVSHP	I	DON	46.68
24-Apr-2019 1	4,750	0	382628	02-330	Clean Excavator	24-Apr-2019 11:15:47	LAVSHP	E	DON	45.57
17-Jun-2019 1(	5,365	0	390474	06-100-PMC	Inspect C PMI	17-Jun-2019 17:23:46	LAVSHP	P	DON	46.89
17-Jun-2019 1(	5,365	0	390474	38-100-PMC	Service C PMI	17-Jun-2019 16:06:31	LAVSHP	P	DON	1,518.42
07-Aug-2019 0	5,587	0	397634	03-330-001	Replace Bucket and Attachments	08-Aug-2019 13:57:33	LAVSHP	Q	DON	180.86
07-Aug-2019 0	5,587	0	397634	06-100-PMA	Inspect A PMI	07-Aug-2019 11:19:34	LAVSHP	P	DON	54.47
07-Aug-2019 0	5,587	0	397634	38-100-PMA	Service A PMI	08-Aug-2019 10:57:25	LAVSHP	P	DON	332.94
12-Aug-2019 1	5,598	0	398313	35-049-001	Diagnose ECM Fault Code	29-Aug-2019 10:13:57	LAVSHP	B	DON	580.87
12-Aug-2019 1	5,598	0	398313	95-MSC-004	Travel Travel Time - To/From Job Site	29-Aug-2019 10:12:35	LAVSHP	B	DON	128.21
12-Aug-2019 1	5,598	0	398313	03-043-004	Replace Turbocharger	29-Aug-2019 10:12:41	LAVSHP	I	DON	4,431.72
12-Aug-2019 1	5,598	0	398313	06-100-PMB	Inspect B PMI	29-Aug-2019 10:12:38	LAVSHP	P	DON	0.00
12-Aug-2019 1	5,598	0	398313	02-043-009	Clean Diesel Particulate Filter - DPF	29-Aug-2019 10:12:31	LAVSHP	I	DON	1,162.51
18-Oct-2019 1	5,923	0	408232	38-100-PMB	Service B PMI	04-Nov-2019 15:06:41	LAVSHP	P	DON	1,650.53
18-Oct-2019 1	5,923	0	408232	95-MSC-004	Travel Travel Time - To/From Job Site	04-Nov-2019 15:06:38	LAVSHP	P	DON	119.22
18-Oct-2019 1	5,923	0	408232	06-100-PMB	Inspect B PMI	04-Nov-2019 15:08:18	LAVSHP	P	DON	0.00
15-Nov-2019 0	6,230	0	412987	24-513-002	Repair Quick Attachment	15-Nov-2019 00:00:00	BVLOFC	O	DON	929.78
03-Dec-2019 1	6,301	0	415052	06-100-PMA	Inspect A PMI	03-Dec-2019 17:30:37	LAVSHP	P	DON	20.00
03-Dec-2019 1	6,301	0	415052	38-100-PMA	Service A PMI	03-Dec-2019 18:58:10	LAVSHP	I	DON	349.86
05-May-2020 1		0	439372	03-001-022	Replace Switch - Fan Speed	08-May-2020 11:38:08	LAVSHP	I	DON	482.24
05-May-2020 1		0	439372	35-042	Diagnose Cooling System	08-May-2020 11:38:50	LAVSHP	B	DON	405.63

Unit Job History

Michels Corporation

Report Printed: 18-Aug-2021 05:42:38 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: N0883 - 2013 JOHN DEERE 290G										
05-May-2020 1		0	439372	95-MSC-004	Travel Travel Time - To/From Job Site	08-May-2020 11:38:11	LAVSHP	B	DON	168.40
30-Jun-2020 0		0	448194	06-065-001	Inspect Hydraulic Systems	30-Jun-2020 08:48:07	ME1371	O	DON	19.57
17-Sep-2020 0		0	461933	03-002-010	Replace Mirrors	17-Sep-2020 13:14:13	LAVSHP	P	DON	110.93
17-Sep-2020 0		0	461933	06-100-PMA	Inspect A PMI	17-Sep-2020 10:40:14	LAVSHP	P	DON	64.33
17-Sep-2020 0		0	461933	38-100-PMA	Service A PMI	17-Sep-2020 12:30:39	LAVSHP	P	DON	283.07
16-Oct-2020 0		0	466908	03-031-001	Replace Generator/Alternator	27-Oct-2020 14:53:16	LAVSHP	I	DON	1,179.85
16-Oct-2020 0		0	466908	06-100-PMA	Inspect A PMI	27-Oct-2020 14:53:11	LAVSHP	P	DON	71.50
16-Oct-2020 0		0	466908	35-031-001	Diagnose Generator/Alternator	27-Oct-2020 14:53:49	LAVSHP	B	DON	359.87
16-Oct-2020 0		0	466908	95-MSC-004	Travel Travel Time - To/From Job Site	27-Oct-2020 14:53:19	LAVSHP	B	DON	175.76
16-Dec-2020 1		0	477653	03-033-007	Replace Glow Plug	29-Dec-2020 07:41:15	LAVSHP	I	DON	1,075.05
16-Dec-2020 1		0	477653	03-042-014	Replace Coolant Overflow Reservoir	29-Dec-2020 07:41:21	LAVSHP	I	DON	649.64
16-Dec-2020 1		0	477653	35-044	Diagnose Fuel System	29-Dec-2020 07:41:25	LAVSHP	B	DON	1,141.27
27-Jan-2021 0(		0	484795	24-065-008	Repair Line / Tubing Assembly	29-Jan-2021 00:00:00	BVLOFC	O	DON	350.40
27-Jan-2021 0(		0	484795	95-MSC	Travel Miscellanous	29-Jan-2021 00:00:00	BVLOFC	N	DON	201.01
03-Mar-2021 1		0	491467	03-001-008	Replace Motor - Blower	03-Mar-2021 10:26:15	BVLOFC	I	DON	1,252.93
03-Mar-2021 1		0	491467	95-MSC	Travel Miscellanous	03-Mar-2021 10:26:15	BVLOFC	N	DON	216.36
04-Mar-2021 1		0	491873	38-100-PMA	Service A PMI	04-Mar-2021 15:01:50	ME1371	P	DON	427.14
04-Mar-2021 1		0	491873	06-100-PMA	Inspect A PMI	04-Mar-2021 12:03:00	ME1371	P	DON	18.20
13-Jul-2021 14		0	518388	02-002-011	Clean Cab Accessories - Interior	15-Jul-2021 07:43:09	BHVYEQ	I	DON	127.53
13-Jul-2021 14		0	518388	23-330-001	Burn / Cut Bucket and Attachments	15-Jul-2021 15:47:55	BHVYEQ	Z	DON	234.13
13-Jul-2021 14		0	518388	25-051-009	Remove Fire Extinguisher	09-Aug-2021 13:40:26	BHVYEQ	Z	DON	0.00
13-Jul-2021 14		0	518388	25-052-003	Remove Radio Equipment	14-Jul-2021 10:17:24	BHVYEQ	Z	DON	83.13
13-Jul-2021 14		0	518388	25-063-003	Remove Transceiver - GPS Tracker	14-Jul-2021 11:33:18	BHVYEQ	Z	DON	52.37
13-Jul-2021 14		0	518388	06-100-008	Inspect Out-Service Inspection	14-Jul-2021 08:16:55	BHVYEQ	Z	DON	234.92
13-Jul-2021 14		0	518388	03-032-001	Replace Battery	15-Jul-2021 12:00:09	BHVYEQ	I	DON	378.27
13-Jul-2021 14		0	518388	35-045-021	Diagnose Electronic Engine Controls	14-Jul-2021 15:53:29	BHVYEQ	I	DON	139.21
13-Jul-2021 14		0	518388	03-043-004	Replace Turbocharger	09-Aug-2021 12:00:52	BHVYEQ	I	DON	4,833.57
13-Jul-2021 14		0	518388	24-065-001	Repair Hydraulic Systems	09-Aug-2021 07:21:04	BHVYEQ	I	DON	145.79
13-Jul-2021 14		0	518388	02-330	Clean Excavator	23-Jul-2021 10:33:13	BWASH	Z	DON	347.27

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: N0883 - 2013 JOHN DEERE 290G										
10-Aug-2021 1	6,335	0	524190	12-330	Refinish Excavator		BBODY	Z	WND	424.13
10-Aug-2021 1	6,335	0	524190	15-330	Paint Prep Excavator		BBODY	Z	WND	652.53

Unit No: N0883 **Count: 118** **82,331.90**