Unit Job History

Michels Corporation

Report Printed: 11-Oct-2021 08:57:35 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B1570 - 2011 F250 CREWCAB										
12-Jun-2010 1(	31	0	43198	06-100-002	Inspect DO NOT USE - DOT Federal Insp	16-Jun-2010 06:52:10	BTRUCK	I	DON	37.24
12-Jun-2010 1(	31	0	43198	14-014-010	Install Toolbox Mounting	16-Jun-2010 12:37:31	BBODY	Q	DON	49.30
12-Jun-2010 1(	31	0	43198	14-034-006	Install Warning Lamps - Special Application	16-Jun-2010 07:54:52	BTRUCK	I	DON	371.09
12-Jun-2010 1(	31	0	43198	14-051-009	Install Fire Extinguisher	16-Jun-2010 08:09:37	BTRUCK	I	DON	177.47
12-Jun-2010 1(	31	0	43198	14-052-003	Install Radio Equipment	15-Jun-2010 11:10:15	BBODY	Q	DON	947.89
12-Jun-2010 1(	31	0	43198	14-053-005	Install Markings - Vehicle - Decals	15-Jun-2010 11:45:53	BBODY	Q	DON	18.01
12-Jun-2010 1(	31	0	43198	14-079-002	Install Headache Rack	12-Jun-2010 11:00:09	BBODY	Q	DON	12.40
12-Jun-2010 1(	31	0	43198	14-079-003	Install Strap, Anti-Static	16-Jun-2010 08:17:18	BTRUCK	I	DON	8.37
01-Aug-2010 0	12,050	0	49624	06-100	Inspect PMI	01-Nov-2010 13:22:13	U91010	J	DON	171.08
01-Aug-2010 0	12,050	0	49624	03-016-004	Replace Stabilizer (Sway) Bar - Front	01-Nov-2010 13:22:13	U91010	I	DON	400.88
01-Feb-2011 0	20,333	0	61585	06-100-001	Inspect DO NOT USE - PMI Service	16-Jan-2012 11:32:26	U91010	J	DON	122.73
01-Feb-2011 0	20,333	0	61585	31-017	Rotate Tires, Tubes, Liners & Valves	16-Jan-2012 11:32:26	U91010	J	DON	0.00
01-Feb-2011 0	20,333	0	61585	24-015	Repair Steering	09-Mar-2011 10:41:16	U91010	I	DON	150.75
01-Feb-2011 0	20,333	0	61585	38-017	Service Tires, Tubes, Liners & Valves	16-Jan-2012 11:32:26	U91010	I	DON	1,151.83
01-Feb-2011 0	20,333	0	61585	03-519-002	Replace Rear Bumper	16-Jan-2012 11:32:26	U91010	F	DON	770.82
01-Feb-2011 0	20,333	0	61585	03-033-002	Replace Distributor / Coil Pack	16-Jan-2012 11:32:26	U91010	F	DON	79.50
01-Feb-2011 0	20,333	0	61585	03-002-024	Replace Glass / Windshield	16-Jan-2012 11:32:26	U91010	O	DON	359.51
01-Feb-2011 0	20,333	0	61585	02-001-013	Clean Evaporator Core	16-Jan-2012 11:32:26	U91010	F	DON	408.75
01-Apr-2012 0	41,779	0	87221	03-017-001	Replace Tire - Pneumatic	23-Jan-2013 11:59:44	U91012	J	DON	949.57
01-Apr-2012 0	41,779	0	87221	06-100-001	Inspect DO NOT USE - PMI Service	23-Jan-2013 11:59:44	U91012	J	DON	272.62
21-Sep-2012 1	61,177	0	98358	14-063	Install Satellite Communications System	21-Sep-2012 15:09:35	BTRUCK	J	DON	289.99
16-Jan-2013 0(		0	120495	03-013-001	Replace Front Brakes & Drums	16-Jan-2013 18:00:00	U21009	F	DON	73.65
16-Jan-2013 0(		0	120495	03-013-002	Replace Rear Brakes & Drums	16-Jan-2013 18:00:00	U21009	F	DON	73.65
14-Feb-2013 0		0	118744	03-016	Replace Suspension	14-Feb-2013 18:00:00	U21009	F	DON	628.50
18-Feb-2013 1	61,177	0	108435	14-052-003	Install Radio Equipment	18-Feb-2013 13:58:39	BBODY	C	DON	0.00
23-Apr-2013 0	61,177	0	117645	03-017-001	Replace Tire - Pneumatic	23-Apr-2013 12:00:00	U21009	F	DON	52.50
09-May-2013 (	90,826	0	119359	03-001-002	Replace Heating & Ventilating	23-May-2013 12:00:00	U21009	F	DON	1,257.64
09-May-2013 (	90,826	0	119359	03-013-001	Replace Front Brakes & Drums	23-May-2013 12:00:00	U21009	F	DON	191.63
09-May-2013 (	90,826	0	119359	03-013-002	Replace Rear Brakes & Drums	23-May-2013 12:00:00	U21009	F	DON	314.94

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B1570 - 2011 F250 CREWCAB										
09-May-2013 (	90,826	0	119359	03-033-003	Replace Spark Plugs	23-May-2013 12:00:00	U21009	F	DON	413.96
09-May-2013 (	90,826	0	119359	03-033-004	Replace Spark Plug Wires	23-May-2013 12:00:00	U21009	F	DON	648.17
09-May-2013 (	90,826	0	119359	03-041-007	Replace Filter - Outer	23-May-2013 12:00:00	U21009	J	DON	8.00
09-May-2013 (	90,826	0	119359	03-044-003	Replace Fuel Pump	23-May-2013 12:00:00	U21009	I	DON	989.10
09-May-2013 (	90,826	0	119359	38-042	Service Cooling System	23-May-2013 12:00:00	U21009	F	DON	75.00
09-May-2013 (	90,826	0	119359	38-045-020	Service Engine Assembly	23-May-2013 12:00:00	U21009	F	DON	75.26
19-Aug-2013 0	99,009	0	127909	03-063-003	Replace Transceiver - GPS Tracker	19-Aug-2013 00:00:00	BTRUCK	C	DON	221.44
27-Aug-2013 0	99,009	0	131604	03-018-001	Replace Front Axle Hubs & Bearings	05-Sep-2013 12:00:00	U31014	I	DON	444.57
27-Aug-2013 0	99,009	0	131604	03-021-001	Replace Axle Assembly - Driven, Front Steering	05-Sep-2013 12:00:00	U31014	B	DON	646.83
27-Aug-2013 0	99,009	0	131604	03-002-025	Replace Glass Channels	05-Sep-2013 12:00:00	U31014	I	DON	85.87
01-Sep-2013 0		0	178182	06-100-007	Inspect In-Service Inspection	29-Oct-2014 09:01:56	U31014	P	DON	104.27
23-Sep-2013 0	99,009	0	135625	03-002-024	Replace Glass / Windshield	25-Sep-2013 12:00:00	U31014	O	DON	746.97
23-Sep-2013 0	99,009	0	135625	03-017-001	Replace Tire - Pneumatic	25-Sep-2013 12:00:00	U31014	O	DON	117.00
20-Nov-2013 0	99,009	0	139375	24-016	Repair Suspension	23-Nov-2013 12:00:00	U31014	F	DON	448.55
09-Jan-2014 0(	106,785	0	144665	03-015-003	Replace Steering Gear	10-Jan-2014 12:00:00	U31014	F	DON	0.00
09-Jan-2014 0(	106,785	0	144665	03-025-001	Replace Transfer Case Assembly	10-Jan-2014 12:00:00	U31014	F	DON	1,507.31
09-Jan-2014 0(	106,785	0	144665	03-042-012	Replace Clamps and Hoses	10-Jan-2014 12:00:00	U31014	F	DON	62.85
09-Jan-2014 0(	106,785	0	144665	03-015-004	Replace Steering Linkage	10-Jan-2014 12:00:00	U31014	F	DON	0.00
09-Jan-2014 0(	106,785	0	144665	03-042-002	Replace Radiator	10-Jan-2014 12:00:00	U31014	F	DON	1,168.72
04-Mar-2014 1	109,763	0	148826	02-002-044	Clean Cab - Complete	12-Mar-2014 06:59:17	BDETL	J	DON	527.72
04-Mar-2014 1	109,763	0	148826	03-002-010	Replace Mirrors	17-Mar-2014 13:19:51	BTRUCK	I	DON	696.83
04-Mar-2014 1	109,763	0	148826	03-002-024	Replace Glass / Windshield	13-Mar-2014 12:44:43	BTRUCK	C	DON	273.74
04-Mar-2014 1	109,763	0	148826	03-002-030	Replace Interior Moldings	25-Mar-2014 17:00:46	BTRUCK	I	DON	152.64
04-Mar-2014 1	109,763	0	148826	03-002-035	Replace Windshield Wiper & Washer	12-Mar-2014 17:01:03	BTRUCK	I	DON	22.36
04-Mar-2014 1	109,763	0	148826	03-013-001	Replace Front Brakes & Drums	01-Apr-2014 07:55:55	BTRUCK	I	DON	438.65
04-Mar-2014 1	109,763	0	148826	03-013-027	Replace Cable - Parking Brake	21-Mar-2014 06:27:25	BTRUCK	I	DON	110.13
04-Mar-2014 1	109,763	0	148826	03-015-004	Replace Steering Linkage	17-Mar-2014 15:54:53	BTRUCK	I	DON	31.14
04-Mar-2014 1	109,763	0	148826	03-016-003	Replace Shock Absorber - Front	17-Mar-2014 07:32:28	BTRUCK	I	DON	187.25
04-Mar-2014 1	109,763	0	148826	03-016-006	Replace Shock Absorber - Rear	15-Mar-2014 09:28:50	BTRUCK	I	DON	186.66

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B1570 - 2011 F250 CREWCAB										
04-Mar-2014 1	109,763	0	148826	03-024-005	Replace Universal Joint	31-Mar-2014 16:42:01	BTRUCK	I	DON	853.56
04-Mar-2014 1	109,763	0	148826	03-032-001	Replace Battery	01-Apr-2014 15:40:33	BTRUCK	I	DON	97.36
04-Mar-2014 1	109,763	0	148826	03-034-002	Replace Stop, Tail, Turn & License	02-Apr-2014 06:33:45	BTRUCK	I	DON	15.42
04-Mar-2014 1	109,763	0	148826	03-079-002	Replace Headache Rack	11-Mar-2014 13:55:36	BDETL	I	DON	392.84
04-Mar-2014 1	109,763	0	148826	03-519-001	Replace Front Bumper	11-Mar-2014 11:58:12	BDETL	I	DON	0.00
04-Mar-2014 1	109,763	0	148826	03-519-002	Replace Rear Bumper	11-Mar-2014 11:58:17	BDETL	I	DON	163.59
04-Mar-2014 1	109,763	0	148826	06-034-006	Inspect Warning Lamps - Special Application	02-Apr-2014 10:10:05	BTRUCK	I	DON	45.70
04-Mar-2014 1	109,763	0	148826	06-100-DOT	Inspect DOT Federal Inspection	12-Mar-2014 15:27:02	BTRUCK	P	DON	37.94
04-Mar-2014 1	109,763	0	148826	06-100-PMB	Inspect B PMI	12-Mar-2014 14:29:28	BTRUCK	P	DON	41.14
04-Mar-2014 1	109,763	0	148826	09-015	Align Steering	04-Apr-2014 14:09:41	BTRUCK	P	DON	92.54
04-Mar-2014 1	109,763	0	148826	14-002-028	Install Adjuster - Front Seat	21-Mar-2014 14:59:20	BTRUCK	I	DON	377.19
04-Mar-2014 1	109,763	0	148826	14-002-059	Install Protector - Tail Gate	12-Mar-2014 07:36:04	BDETL	C	DON	53.38
04-Mar-2014 1	109,763	0	148826	14-034-006	Install Warning Lamps - Special Application	12-Mar-2014 08:46:28	BDETL	C	DON	426.26
04-Mar-2014 1	109,763	0	148826	14-053-004	Install Safety Equipment	12-Mar-2014 08:21:08	BDETL	C	DON	226.34
04-Mar-2014 1	109,763	0	148826	14-071-011	Install Scuff Liner / Bed Mat	12-Mar-2014 07:36:00	BDETL	C	DON	74.50
04-Mar-2014 1	109,763	0	148826	14-079-003	Install Strap, Anti-Static	12-Mar-2014 07:36:23	BDETL	C	DON	4.59
04-Mar-2014 1	109,763	0	148826	14-510-002	Install Tool Box	11-Mar-2014 16:38:27	BDETL	C	DON	398.41
04-Mar-2014 1	109,763	0	148826	24-013-026	Repair Handle - Parking Brake Release	17-Mar-2014 16:04:39	BTRUCK	I	DON	42.95
04-Mar-2014 1	109,763	0	148826	24-034-008	Repair Trailer Light Cord	12-Mar-2014 15:59:06	BTRUCK	I	DON	21.14
04-Mar-2014 1	109,763	0	148826	31-017-001	Rotate Tire - Pneumatic	13-Mar-2014 09:21:55	BTRUCK	I	DON	24.93
04-Mar-2014 1	109,763	0	148826	38-045	Service Power Plant	13-Mar-2014 10:00:28	BTRUCK	P	DON	51.87
06-Jun-2014 1(	109,763	0	160769	02-002	Clean Cab & Sheet Metal	12-Jun-2014 14:02:40	BSETUP	S	DON	200.67
06-Jun-2014 1(	109,763	0	160769	24-001-001	Repair Air Conditioning Assembly	11-Jun-2014 14:25:34	BTRUCK	O	DON	66.43
06-Jun-2014 1(	109,763	0	160769	14-506-001	Install Fuel Tank	27-Jun-2014 11:33:58	BSETUP	C	DON	209.31
24-Sep-2014 1.	122,491	0	173449	24-044	Repair Fuel System	26-Sep-2014 09:37:26	BTRUCK	O	DON	92.34
24-Sep-2014 1.	122,491	0	173449	03-016-012	Replace Torque Rod	26-Sep-2014 12:00:42	BTRUCK	I	DON	86.62
24-Sep-2014 1.	122,491	0	173449	06-100-PMB	Inspect B PMI	26-Sep-2014 13:54:59	BTRUCK	P	DON	15.83
24-Sep-2014 1.	122,491	0	173449	38-045	Service Power Plant	26-Sep-2014 13:26:20	BTRUCK	P	DON	53.84
24-Sep-2014 1.	122,491	0	173449	24-034-002	Repair Stop, Tail, Turn & License	26-Sep-2014 15:15:36	BTRUCK	I	DON	40.47

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B1570 - 2011 F250 CREWCAB										
11-Nov-2014 0	124,995	0	180103	03-044-020	Replace Vapor Cannister	18-Nov-2014 11:39:45	BTRUCK	I	DON	124.67
11-Nov-2014 0	124,995	0	180103	03-013	Replace Brakes	12-Nov-2014 13:23:37	BTRUCK	O	DON	276.25
11-Nov-2014 0	124,995	0	180103	06-100-PMB	Inspect B PMI	12-Nov-2014 15:47:16	BTRUCK	P	DON	16.39
11-Nov-2014 0	124,995	0	180103	38-045	Service Power Plant	12-Nov-2014 15:22:24	BTRUCK	P	DON	76.02
11-Nov-2014 0	124,995	0	180103	24-018-001	Repair Front Axle Hubs & Bearings	12-Nov-2014 12:00:03	BTRUCK	I	DON	722.13
11-Nov-2014 0	124,995	0	180103	24-034-002	Repair Stop, Tail, Turn & License	12-Nov-2014 06:53:30	BTRUCK	I	DON	33.10
11-Nov-2014 0	124,995	0	180103	06-032-001	Inspect Battery	11-Nov-2014 09:00:06	BTRUCK	I	DON	119.90
11-Nov-2014 0	124,995	0	180103	01-042-002	Adjust Radiator	14-Nov-2014 10:16:14	BTRUCK	I	DON	69.96
16-Dec-2014 1	125,015	0	184894	03-032-001	Replace Battery	05-Jan-2015 09:29:40	BTRUCK	I	DON	106.48
16-Dec-2014 1	125,015	0	184894	06-100-DOT	Inspect DOT Federal Inspection	07-Jan-2015 07:16:25	BTRUCK	P	DON	46.60
16-Dec-2014 1	125,015	0	184894	01-027	Adjust Transmission - Main, Automatic	07-Jan-2015 07:31:11	BTRUCK	I	DON	14.18
16-Dec-2014 1	125,015	0	184894	03-051-009	Replace Fire Extinguisher	09-Jan-2015 13:40:05	BTRUCK	I	DON	120.35
16-Dec-2014 1	125,015	0	184894	03-016-020	Replace Ball Joint - Upper Control Arm	07-Jan-2015 09:27:33	BTRUCK	I	DON	239.77
16-Dec-2014 1	125,015	0	184894	03-016-021	Replace Ball Joint - Lower Control Arm	07-Jan-2015 11:48:24	BTRUCK	I	DON	191.83
16-Dec-2014 1	125,015	0	184894	02-002-044	Clean Cab - Complete	09-Jan-2015 06:05:20	BSETUP	J	DON	157.66
04-Jun-2015 0	130,464	0	203008	03-033-001	Replace Ignition Switch	16-Jun-2015 08:59:29	BVLOFC	O	DON	862.08
04-Jun-2015 0	130,464	0	203008	24-045	Repair Power Plant		BVLOFC	O	CAN	0.00
09-Jul-2015 14	131,152	0	207134	02-001-013	Clean Evaporator Core	09-Jul-2015 14:39:23	BVLOFC	O	DON	1,570.49
12-Aug-2015 1	131,152	0	211144	03-034-001	Replace Headlamps / Fog Lamps	13-Aug-2015 10:37:59	MPNFLD	I	DON	17.14
24-Nov-2015 1	140,350	0	223111	03-024-001	Replace Drive Shaft - Front Driving Axles	25-Nov-2015 12:31:53	BVLOFC	O	DON	463.72
24-Nov-2015 1	140,350	0	223111	03-002-024	Replace Glass / Windshield	25-Nov-2015 12:28:39	BVLOFC	O	DON	210.58
24-Nov-2015 1	140,350	0	223111	03-016	Replace Suspension	25-Nov-2015 12:20:37	BVLOFC	I	DON	1,716.86
24-Nov-2015 1	140,350	0	223111	09-015	Align Steering	25-Nov-2015 12:24:30	BVLOFC	I	DON	111.42
13-Dec-2015 0	141,424	0	236999	03-002-024	Replace Glass / Windshield	13-Dec-2015 09:17:10	BVLOFC	O	DON	210.58
14-Dec-2015 0	141,180	0	237005	06-100-PMA	Inspect A PMI	14-Dec-2015 09:21:47	BVLOFC	P	DON	63.17
28-Dec-2015 1	141,423	0	226687	06-100-DOT	Inspect DOT Federal Inspection	04-Jan-2016 15:59:52	BTRUCK	P	DON	27.56
28-Dec-2015 1	141,423	0	226687	03-013-001	Replace Front Brakes & Drums	04-Jan-2016 14:12:59	BTRUCK	I	DON	117.83
28-Dec-2015 1	141,423	0	226687	06-100-PMB	Inspect B PMI	04-Jan-2016 11:22:28	BTRUCK	P	DON	34.94
28-Dec-2015 1	141,423	0	226687	38-045	Service Power Plant	04-Jan-2016 12:00:13	BTRUCK	P	DON	55.39

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B1570 - 2011 F250 CREWCAB										
28-Dec-2015 1	141,423	0	226687	24-017-001	Repair Tire - Pneumatic	04-Jan-2016 14:24:53	BTRUCK	I	DON	25.95
28-Dec-2015 1	141,423	0	226687	03-051-009	Replace Fire Extinguisher	04-Jan-2016 15:21:28	BTRUCK	I	DON	84.90
28-Dec-2015 1	141,423	0	226687	24-001	Repair Air Conditioning, Heating & Ventilating	04-Jan-2016 15:14:57	BTRUCK	I	DON	43.79
14-Jan-2016 0	141,424	0	228871	06-100-DOT	Inspect DOT Federal Inspection	14-Jan-2016 15:19:53	BTRUCK	P	DON	16.54
14-Jan-2016 0	141,424	0	228871	03-032-001	Replace Battery	15-Jan-2016 12:48:26	BTRUCK	I	DON	90.04
14-Jan-2016 0	141,424	0	228871	06-100-009	Inspect Safety Check	14-Jan-2016 16:11:44	BTRUCK	P	DON	37.21
14-Jan-2016 0	141,424	0	228871	24-013-034	Repair Parking Brake - Complete	15-Jan-2016 12:00:04	BTRUCK	I	DON	387.93
14-Jan-2016 0	141,424	0	228871	24-001-023	Repair Ductwork and Dash Louvres	14-Jan-2016 17:04:26	BTRUCK	I	DON	74.23
14-Jan-2016 0	141,424	0	228871	24-002-010	Repair Mirrors	14-Jan-2016 16:15:51	BTRUCK	I	DON	34.74
14-Jan-2016 0	141,424	0	228871	03-079-003	Replace Strap, Anti-Static	15-Jan-2016 13:17:45	BTRUCK	I	DON	20.98
26-Feb-2016 0	141,424	0	235056	02-002	Clean Cab & Sheet Metal	11-Mar-2016 08:28:02	BSETUP	J	DON	267.12
17-Aug-2016 1	145,422	0	255987	24-001-012	Repair Condenser Assembly	17-Aug-2016 15:18:29	BVLOFC	O	DON	538.42
17-Aug-2016 1	145,422	0	255987	06-100-PMA	Inspect A PMI	17-Aug-2016 15:20:16	BVLOFC	P	DON	187.90
18-Oct-2016 0	145,422	0	274327	03-017-001	Replace Tire - Pneumatic	18-Oct-2016 07:38:40	BTIRE	E	DON	1,331.69
17-Nov-2016 1	145,422	0	287366	06-100-PMA	Inspect A PMI	17-Nov-2016 14:12:12	BVLOFC	P	DON	43.33
06-Apr-2017 1	145,422	0	284206	06-100-DOT	Inspect DOT Federal Inspection		LAVSHP	P	CAN	0.00
26-May-2017 1	158,282	0	290609	02-001-002	Clean Heating & Ventilating	02-Jun-2017 09:15:54	BTRUCK	I	DON	47.83
26-May-2017 1	158,282	0	290609	03-001-010	Replace Compressor Assembly - Air Cond	02-Jun-2017 10:35:25	BTRUCK	I	DON	351.14
26-May-2017 1	158,282	0	290609	03-002-035	Replace Windshield Wiper & Washer	03-Jun-2017 05:23:29	BTRUCK	I	DON	28.57
26-May-2017 1	158,282	0	290609	03-022-008	Replace Pinion Seal	02-Jun-2017 11:34:54	BTRUCK	I	DON	56.15
26-May-2017 1	158,282	0	290609	06-100-DOT	Inspect DOT Federal Inspection	02-Jun-2017 09:34:29	BTRUCK	P	DON	33.74
26-May-2017 1	158,282	0	290609	24-002-029	Repair Trim - Seat	06-Jun-2017 08:04:29	BTRUCK	I	DON	195.68
26-May-2017 1	158,282	0	290609	03-052-006	Replace CD Player	02-Jun-2017 12:00:48	BTRUCK	I	DON	178.90
26-May-2017 1	158,282	0	290609	38-045	Service Power Plant	02-Jun-2017 07:49:57	BTRUCK	P	DON	62.08
26-May-2017 1	158,282	0	290609	06-100-PMB	Inspect B PMI	02-Jun-2017 06:59:54	BTRUCK	P	DON	40.86
26-May-2017 1	158,282	0	290609	14-051-009	Install Fire Extinguisher	03-Jun-2017 05:13:00	BTRUCK	I	DON	136.69
26-May-2017 1	158,282	0	290609	24-002-024	Repair Glass / Windshield	05-Jun-2017 05:52:21	BTRUCK	I	DON	51.83
28-Jun-2017 0	158,282	0	294734	02-002	Clean Cab & Sheet Metal	03-Jul-2017 10:43:42	BSETUP	J	DON	638.06
28-Jun-2017 0	158,282	0	294734	03-052-003	Replace Radio Equipment	29-Jun-2017 09:36:24	BSETUP	I	DON	861.33

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B1570 - 2011 F250 CREWCAB										
04-Apr-2018 1	173,024	0	329978	03-043-027	Replace Catalytic Converter	26-Apr-2018 09:57:24	BVLOFC	E	DON	2,650.19
04-Apr-2018 1	173,024	0	329978	06-100-PMA	Inspect A PMI	26-Apr-2018 09:57:28	BVLOFC	P	DON	204.71
04-Apr-2018 1	173,024	0	329978	24-013-011	Repair Anti-Lock Sensor Assembly	26-Apr-2018 09:57:21	BVLOFC	O	DON	311.87
19-Sep-2018 0	179,425	0	352761	03-001-013	Replace Evaporator Core	26-Sep-2018 10:00:26	BVLOFC	O	DON	2,444.45
19-Sep-2018 0	179,425	0	352761	03-002-001	Replace Radiator Grille	26-Sep-2018 10:00:26	BVLOFC	I	DON	405.19
19-Sep-2018 0	179,425	0	352761	03-013-002	Replace Rear Brakes & Drums	26-Sep-2018 10:00:26	BVLOFC	I	DON	651.79
19-Sep-2018 0	179,425	0	352761	03-016	Replace Suspension	26-Sep-2018 10:00:26	BVLOFC	I	DON	452.64
19-Sep-2018 0	179,425	0	352761	03-017-001	Replace Tire - Pneumatic	26-Sep-2018 10:00:26	BVLOFC	O	DON	1,096.54
19-Sep-2018 0	179,425	0	352761	03-027	Replace Transmission - Main, Automatic	26-Sep-2018 10:00:26	BVLOFC	I	DON	465.65
19-Sep-2018 0	179,425	0	352761	03-033-003	Replace Spark Plugs	26-Sep-2018 10:00:26	BVLOFC	I	DON	551.24
19-Sep-2018 0	179,425	0	352761	03-043-003	Replace Muffler	26-Sep-2018 10:00:26	BVLOFC	I	DON	907.85
19-Sep-2018 0	179,425	0	352761	03-044	Replace Fuel System	26-Sep-2018 10:00:26	BVLOFC	O	DON	250.34
19-Sep-2018 0	179,425	0	352761	06-100-DOT	Inspect DOT Federal Inspection	26-Sep-2018 10:00:26	BVLOFC	P	DON	70.63
19-Sep-2018 0	179,425	0	352761	06-100-PMA	Inspect A PMI	26-Sep-2018 10:00:26	BVLOFC	P	DON	67.09
19-Sep-2018 0	179,425	0	352761	24-034-004	Repair Clearance & Marker Lamps	26-Sep-2018 10:00:26	BVLOFC	I	DON	35.06
03-Oct-2018 0	179,574	0	354828	03-002-022	Replace Rear Door Mechanism	03-Oct-2018 06:33:07	BVLOFC	O	DON	483.20
03-Oct-2018 0	179,574	0	354828	03-044-013	Replace Cap - Fuel Tank	03-Oct-2018 06:33:53	BVLOFC	O	DON	74.87
03-Oct-2018 0	179,574	0	354828	02-002	Clean Cab & Sheet Metal	03-Oct-2018 06:33:53	BVLOFC	O	DON	335.19
08-Jan-2019 1	183,922	0	367336	06-100-PMA	Inspect A PMI	08-Jan-2019 12:49:09	BVLOFC	E	DON	63.69
11-Jan-2019 0	184,271	0	367880	35-049-002	Diagnose ECM Module		BVLOFC	I	CAN	0.00
11-Jan-2019 0	184,271	0	367880	03-043-002	Replace Exhaust Manifold	11-Jan-2019 09:37:13	BVLOFC	E	DON	567.78
11-Jan-2019 0	184,271	0	367880	03-002-018	Replace Cab Or Front Door Mechanism	11-Jan-2019 09:37:13	BVLOFC	E	DON	370.80
11-Jan-2019 0	184,271	0	367880	03-002-023	Replace Handles - Inner & Outer	11-Jan-2019 09:37:13	BVLOFC	E	DON	0.00
11-Jan-2019 0	184,271	0	367880	03-014-006	Replace Fuel Tank Support	11-Jan-2019 09:37:13	BVLOFC	E	DON	0.00
11-Jan-2019 0	184,271	0	367880	06-100-PMA	Inspect A PMI	11-Jan-2019 09:37:13	BVLOFC	E	DON	0.00
11-Jan-2019 0	184,271	0	367880	03-041-007	Replace Filter - Outer	11-Jan-2019 09:37:13	BVLOFC	E	DON	283.31
11-Jan-2019 0	184,271	0	367880	03-034-016	Replace Turn Signal Switch	11-Jan-2019 09:34:44	BVLOFC	E	DON	114.76
29-Oct-2019 1	189,194		410072	03-002-067	Replace Keys - Door / Ignition	30-Oct-2019 00:00:00	BVLOFC	O	DON	497.76
29-Oct-2019 1	189,194		410072	06-100-DOT	Inspect DOT Federal Inspection	31-Oct-2019 00:00:00	BVLOFC	P	DON	34.56

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B1570 - 2011 F250 CREWCAB										
10-Oct-2020 0(	197,720		466530	06-100-DOT	Inspect DOT Federal Inspection	10-Oct-2020 00:00:00	BVLOFC	P	DON	34.56
05-Dec-2020 0	197,720		475374	03-052-003	Replace Radio Equipment	05-Dec-2020 07:46:04	ELEC03	Q	DON	756.96
05-Dec-2020 0	197,720		475374	24-063-003	Repair Transceiver - GPS Tracker	05-Dec-2020 07:46:14	ELEC03	Q	DON	0.07
27-Jul-2021 07	201,246		521024	06-100-PMA	Inspect A PMI	27-Jul-2021 09:38:27	SCHED	P	DON	38.27
29-Sep-2021 1(	201,246		535063	06-100-009	Inspect Safety Check	29-Sep-2021 11:23:24	BTRUCK	I	DON	40.55
01-Oct-2021 1(	201,246		535864	25-079-002	Remove Headache Rack	01-Oct-2021 11:50:32	BSETUP	Z	DON	22.87
01-Oct-2021 1(	201,246		535864	02-002	Clean Cab & Sheet Metal	04-Oct-2021 16:23:41	BSETUP	Z	DON	473.81
01-Oct-2021 1(	201,246		535864	25-052-003	Remove Radio Equipment	01-Oct-2021 11:20:05	BSETUP	Z	DON	25.25
01-Oct-2021 1(	201,246		535864	25-063-003	Remove Transceiver - GPS Tracker	01-Oct-2021 10:46:28	BSETUP	Z	DON	14.78
01-Oct-2021 1(	201,246		535864	25-053-005	Remove Markings - Vehicle - Decals	04-Oct-2021 05:57:37	BSETUP	Z	DON	145.44

Unit No: B1570 **Count: 184** **52,528.89**