Unit Job History

Michels Corporation
Report Printed: 28-Dec-2021 10:13:51 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Z1065 - 2015 VERMEER D24X40II										
14-Apr-2015 1	7	0	197815	14-063-003	Install Transceiver - GPS Tracker	16-Apr-2015 10:48:17	BSMEQP	C	DON	273.73
13-Jul-2015 08	172	0	207388	06-100-ELE	Inspect Periodic Electrical Inspection	13-Jul-2015 08:53:04	BSMEQP	P	DON	209.66
13-Jul-2015 08	172	0	207388	06-100-PMA	Inspect A PMI	13-Jul-2015 08:53:24	BSMEQP	P	DON	538.63
10-Dec-2015 0	469	0	224819	OS-065-001	Out-Service Hydraulic Systems	30-Dec-2015 15:20:05	BSMEQP	B	DON	284.75
05-Jan-2016 08	469	0	227399	24-040	Repair Engine / Motor Systems Group	02-Feb-2016 09:45:04	BSMEQP	B	DON	451.44
05-Jan-2016 08	469	0	227399	38-040	Service Engine / Motor Systems Group	02-Feb-2016 09:45:09	BSMEQP	J	DON	2,988.58
16-May-2016 1	469	0	244720	03-267-001	Replace Boom Structure	16-Aug-2016 21:37:41	ME1287	B	DON	35.21
16-May-2016 1	469	0	244720	03-267-011	Replace Auger	16-Aug-2016 21:37:12	MPNFLD	I	DON	35.21
16-May-2016 1	469	0	244720	24-267-009	Repair Flushing Assembly		BSMEQP	B	CAN	0.00
16-Aug-2016 1	469	0	255810	24-702-001	Repair Liners, Valves, and Seals	21-Sep-2016 09:51:12	BSMEQP	B	DON	475.17
16-Aug-2016 1	469	0	255810	24-267-008	Repair Rod Holder	16-Aug-2016 11:15:28	BSMEQP	E	DON	529.94
03-Nov-2016 0	469	0	265624	03-704-018	Replace Operator Console / Station	15-Mar-2017 11:26:47	ME1287	B	DON	33.18
26-Jan-2017 12	1,158	0	274986	24-704	Repair Drill Rig	30-Jan-2017 07:38:36	BSMEQP	J	DON	4,086.31
24-Feb-2017 0	1,158	0	278601	02-704	Clean Drill Rig	24-Feb-2017 17:03:24	BWASH	J	DON	370.77
21-Mar-2017 1	1,277	0	281982	06-704	Inspect Drill Rig	21-Mar-2017 16:00:17	BSMEQP	J	DON	649.43
21-Mar-2017 1	1,277	0	281982	24-704	Repair Drill Rig	27-Mar-2017 09:47:47	BSMEQP	J	DON	4,236.10
29-Mar-2017 1	1,277	0	283091	24-704-017	Repair Rod Loader System	30-Mar-2017 08:36:58	BSMEQP	J	DON	406.33
29-Mar-2017 1	1,277	0	283091	24-406	Repair Pressure Washer	04-Apr-2017 08:03:05	BSDRIL	J	DON	37.77
29-Mar-2017 1	1,277	0	283091	24-704	Repair Drill Rig	05-Apr-2017 09:16:08	BSMEQP	J	DON	2,469.25
25-Apr-2017 0	1,277	0	286530	01-065-015	Adjust Pump - Variable Displacement Type	26-Apr-2017 13:11:04	BDDRIL	F	DON	31.29
25-Apr-2017 0	1,277	0	286530	IS-MSC-004	In-Service Travel Time - To/From Job Site	26-Apr-2017 13:11:08	BDDRIL	F	DON	125.16
10-May-2017 (	1,277	0	288376	95-MSC-004	Travel Travel Time - To/From Job Site	12-May-2017 07:58:50	BSDRIL	F	DON	179.63
10-May-2017 (	1,277	0	288376	24-702-001	Repair Liners, Valves, and Seals	12-May-2017 07:58:55	BSDRIL	F	DON	46.93
01-Jun-2017 0(	1,277	0	291506	14-034-006	Install Warning Lamps - Special Application	25-Jul-2017 08:32:39	BSDRIL	F	DON	268.50
28-Aug-2017 1	1,277	0	302737	95-MSC-004	Travel Travel Time - To/From Job Site	29-Aug-2017 06:39:27	BSDRIL	F	DON	197.57
28-Aug-2017 1	1,277	0	302737	38-045-011	Service Filter Assembly - Oil	28-Aug-2017 11:35:40	BSDRIL	J	DON	22.64
28-Sep-2017 1(	1,277	0	306800	06-704	Inspect Drill Rig	28-Sep-2017 12:00:43	BSDRIL	J	DON	51.30
28-Sep-2017 1(	1,277	0	306800	24-704-017	Repair Rod Loader System	10-Oct-2017 08:44:03	BSDRIL	I	DON	2,072.03
28-Sep-2017 1(	1,277	0	306800	24-705	Repair Vise	28-Sep-2017 16:10:55	BSDRIL	I	DON	856.52

Unit Job History

Michels Corporation

Report Printed: 28-Dec-2021 10:13:51 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Z1065 - 2015 VERMEER D24X40II										
28-Sep-2017 1	1,277	0	306800	01-704-017	Adjust Rod Loader System	29-Sep-2017 16:40:20	BSDRIL	I	DON	153.81
28-Sep-2017 1	1,277	0	306800	38-045-011	Service Filter Assembly - Oil	10-Oct-2017 08:38:23	BSDRIL	J	DON	69.68
28-Sep-2017 1	1,277	0	306800	24-704-022	Repair Rotation Thrust / Bearing Box	10-Oct-2017 10:37:26	BSDRIL	I	DON	1,655.11
28-Sep-2017 1	1,277	0	306800	38-041	Service Air Intake System	28-Sep-2017 16:59:59	BSDRIL	J	DON	48.26
28-Sep-2017 1	1,277	0	306800	38-044	Service Fuel System	10-Oct-2017 08:39:12	BSDRIL	J	DON	152.37
28-Sep-2017 1	1,277	0	306800	02-704	Clean Drill Rig	30-Sep-2017 08:58:23	BWASH	J	DON	162.37
13-Dec-2017 0	1,277	0	315842	02-704	Clean Drill Rig	08-Jan-2018 08:35:16	BWASH	J	DON	7.09
13-Dec-2017 0	1,277	0	315842	06-704	Inspect Drill Rig	08-Jan-2018 08:45:00	BSDRIL	J	DON	75.43
13-Dec-2017 0	1,277	0	315842	24-111	Repair Undercarriage	08-Jan-2018 08:35:33	BSDRIL	I	DON	705.05
13-Dec-2017 0	1,277	0	315842	24-704-017	Repair Rod Loader System	08-Jan-2018 08:35:29	BSDRIL	I	DON	1,629.81
13-Dec-2017 0	1,277	0	315842	24-705	Repair Vise	08-Jan-2018 08:35:26	BSDRIL	I	DON	1,003.08
13-Dec-2017 0	1,277	0	315842	38-704	Service Drill Rig	08-Jan-2018 08:35:22	BSDRIL	I	DON	566.02
21-May-2018 (	1,277	0	336569	24-704-018	Repair Operator Console / Station	22-May-2018 07:35:45	BSDRIL	F	DON	821.56
21-May-2018 (	1,277	0	336569	95-MSC-004	Travel Travel Time - To/From Job Site	22-May-2018 07:35:50	BSDRIL	F	DON	93.02
23-May-2018 1		0	341240	24-065-007	Repair Hoses & Fittings	23-May-2018 13:52:00	BVLOFC	F	DON	56.20
24-May-2018 (	1,277	0	337233	95-MSC-004	Travel Travel Time - To/From Job Site	25-May-2018 16:40:48	BSDRIL	F	DON	297.20
24-May-2018 (	1,277	0	337233	24-704-018	Repair Operator Console / Station	04-Jun-2018 11:21:23	BSDRIL	F	DON	20.08
11-Jun-2018 0	2,263	0	339126	06-704-010	Inspect Wiring	11-Jun-2018 12:35:37	BSDRIL	F	DON	762.40
01-Aug-2018 C	2,263	0	346406	02-002	Clean Cab & Sheet Metal	04-Dec-2018 11:28:58	BSETUP	I	DON	100.10
01-Aug-2018 C	2,263	0	346406	03-045-014	Replace Ventilating System	01-Aug-2018 20:36:28	ME1287	B	DON	183.27
01-Aug-2018 C	2,263	0	346406	03-065-022	Replace Flow Control Valve	06-Dec-2018 12:40:14	ME1287	B	DON	314.66
01-Aug-2018 C	2,263	0	346598	24-267-003	Repair Hydraulics	23-Aug-2018 11:15:36	BSDRIL	B	DON	4,661.10
21-Aug-2018 C	2,263	0	349074	02-704	Clean Drill Rig	21-Aug-2018 14:10:03	BSETUP	N	DON	97.68
23-Aug-2018 1	2,263	0	349465	38-704-022	Service Rotation Thrust / Bearing Box	28-Aug-2018 12:30:58	BSDRIL	I	DON	2,150.12
23-Aug-2018 1	2,263	0	349465	38-702	Service Mud Pump	05-Sep-2018 13:55:24	BSDRIL	I	DON	117.20
23-Aug-2018 1	2,263	0	349465	24-704-017	Repair Rod Loader System	05-Sep-2018 17:00:14	BSDRIL	I	DON	2,700.56
23-Aug-2018 1	2,263	0	349465	06-704	Inspect Drill Rig	11-Sep-2018 10:45:38	BSDRIL	I	DON	313.41
23-Aug-2018 1	2,263	0	349465	14-065-007	Install Hoses & Fittings	04-Sep-2018 12:09:44	BSDRIL	I	DON	787.60
23-Aug-2018 1	2,263	0	349465	24-705	Repair Vise	10-Sep-2018 14:12:14	BSDRIL	I	DON	1,872.86

Unit Job History

Michels Corporation
Report Printed: 28-Dec-2021 10:13:51 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Z1065 - 2015 VERMEER D24X40II										
23-Aug-2018 1	2,263	0	349465	38-040	Service Engine / Motor Systems Group	06-Sep-2018 06:26:39	BSDRIL	I	DON	292.85
18-Dec-2018 1	2,263	0	365269	03-708-007	Replace Sub Saver	21-Dec-2018 09:35:08	BSDRIL	N	DON	296.49
18-Dec-2018 1	2,263	0	365269	09-704-017	Align Rod Loader System	27-Dec-2018 16:47:09	BSDRIL	I	DON	372.22
18-Dec-2018 1	2,263	0	365269	11-702	Rebuild Mud Pump	27-Dec-2018 16:46:38	BSDRIL	N	DON	7,091.91
18-Dec-2018 1	2,263	0	365269	24-704-022	Repair Rotation Thrust / Bearing Box	27-Dec-2018 07:41:44	BSDRIL	I	DON	835.52
18-Dec-2018 1	2,263	0	365269	38-040	Service Engine / Motor Systems Group	27-Dec-2018 16:46:48	BSDRIL	N	DON	382.33
18-Dec-2018 1	2,263	0	365269	38-704-017	Service Rod Loader System	27-Dec-2018 16:46:43	BSDRIL	I	DON	610.12
18-Dec-2018 1	2,263	0	365269	38-705	Service Vise	27-Dec-2018 16:46:51	BSDRIL	I	DON	612.46
18-Dec-2018 1	2,263	0	365269	24-702-001	Repair Liners, Valves, and Seals	27-Dec-2018 16:46:27	BSDRIL	I	DON	146.42
06-Feb-2019 0	2,783	0	371486	24-065-007	Repair Hoses & Fittings	06-Feb-2019 19:50:12	ME1287	B	DON	71.44
06-Feb-2019 0	2,783	0	371486	02-267	Clean Drilling and Boring	17-Jun-2019 15:35:24	BWASH	N	DON	219.49
20-Jun-2019 0	3,026	0	391012	24-705	Repair Vise	26-Jun-2019 14:48:03	BSDRIL	I	DON	663.39
20-Jun-2019 0	3,026	0	391012	06-704	Inspect Drill Rig	20-Jun-2019 09:54:51	BSDRIL	I	DON	54.67
20-Jun-2019 0	3,026	0	391012	24-410-002	Repair Lights	26-Jun-2019 14:48:07	BSDRIL	I	DON	243.14
20-Jun-2019 0	3,026	0	391012	01-704-016	Adjust Stem Rack	20-Jun-2019 16:31:35	BSDRIL	N	DON	93.24
20-Jun-2019 0	3,026	0	391012	38-706-001	Service Engine	24-Jun-2019 12:00:45	BSDRIL	P	DON	318.56
20-Jun-2019 0	3,026	0	391012	24-705-010	Repair Grease System	20-Jun-2019 14:51:20	BSDRIL	I	DON	185.19
20-Jun-2019 0	3,026	0	391012	03-002-037	Replace Seat Assembly	26-Jun-2019 14:48:26	BSDRIL	N	DON	505.16
20-Jun-2019 0	3,026	0	391012	24-702	Repair Mud Pump	26-Jun-2019 14:48:12	BSDRIL	I	DON	228.30
20-Jun-2019 0	3,026	0	391012	24-704-017	Repair Rod Loader System	21-Jun-2019 07:48:55	BSDRIL	I	DON	1,667.71
20-Jun-2019 0	3,026	0	391012	03-033-001	Replace Ignition Switch	20-Jun-2019 16:09:43	BSDRIL	I	DON	77.12
03-Jul-2019 07	3,050	0	392904	02-704	Clean Drill Rig	03-Jul-2019 13:27:05	BWASH	N	DON	150.46
05-Jul-2019 05	3,051	0	393078	24-003-006	Repair Monitoring Devices	11-Sep-2019 11:18:12	BSDRIL	B	DON	401.39
05-Jul-2019 05	3,051	0	393078	06-704	Inspect Drill Rig	05-Jul-2019 11:21:41	BSDRIL	P	DON	338.44
05-Jul-2019 05	3,051	0	393078	24-044-007	Repair Throttle Controls	04-Sep-2019 07:30:24	BSDRIL	I	DON	405.68
05-Jul-2019 05	3,051	0	393078	03-002-028	Replace Adjuster - Front Seat	04-Sep-2019 07:29:03	BSDRIL	I	DON	26.16
05-Jul-2019 05	3,051	0	393078	38-053-999	Service Vehicle Fluids, Lubricants, Gases, & Pa	04-Sep-2019 07:29:19	BSDRIL	P	DON	8.20
12-Mar-2020 0	3,470	0	430847	01-704-015	Adjust Track	13-Mar-2020 06:38:22	MB2290	I	DON	113.97
08-Apr-2020 1	3,488	0	435044	24-704-017	Repair Rod Loader System	24-Apr-2020 07:50:58	BSDRIL	N	DON	2,028.23

Unit Job History

Michels Corporation
Report Printed: 28-Dec-2021 10:13:51 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Z1065 - 2015 VERMEER D24X40II										
08-Apr-2020 1	3,488	0	435044	24-267-003	Repair Hydraulics	24-Apr-2020 07:50:46	BSDRIL	B	DON	17,506.05
08-Apr-2020 1	3,488	0	435044	24-704-022	Repair Rotation Thrust / Bearing Box	24-Apr-2020 07:50:54	BSDRIL	N	DON	4,584.62
08-Apr-2020 1	3,488	0	435044	38-040	Service Engine / Motor Systems Group	24-Apr-2020 07:51:03	BSDRIL	P	DON	2,412.99
20-May-2020 1	3,536	0	441788	02-706	Clean Power Unit	21-May-2020 17:00:53	BWASH	N	DON	350.03
04-Jun-2020 1	3,601	0	443788	24-704-017	Repair Rod Loader System	08-Jun-2020 13:41:08	BSDRIL	B	DON	5,952.58
11-Jun-2020 1	3,640	0	444990	24-704-018	Repair Operator Console / Station	14-Jul-2020 10:10:41	BSDRIL	I	DON	104.04
11-Jun-2020 1	3,640	0	444990	03-043-028	Replace Rain Cap	14-Jul-2020 12:01:54	BSDRIL	I	DON	72.30
11-Jun-2020 1	3,640	0	444990	95-MSC-004	Travel Travel Time - To/From Job Site	17-Jun-2020 10:59:46	BSDRIL	B	DON	1,215.64
11-Jun-2020 1	3,640	0	444990	02-704	Clean Drill Rig	27-Jul-2020 16:34:33	BVLYRD	N	DON	200.83
11-Jun-2020 1	3,640	0	444990	03-034-014	Replace Auxiliary Work / Flood Light	13-Jul-2020 10:16:57	BSDRIL	I	DON	137.42
11-Jun-2020 1	3,640	0	444990	38-704-002	Service Guide Rollers	10-Jul-2020 14:00:00	BSDRIL	N	DON	132.13
11-Jun-2020 1	3,640	0	444990	24-111-001	Repair Track	22-Jul-2020 09:45:23	BSDRIL	B	DON	3,026.17
11-Jun-2020 1	3,640	0	444990	38-704-017	Service Rod Loader System	27-Jul-2020 16:34:03	BSDRIL	N	DON	3,614.40
11-Jun-2020 1	3,640	0	444990	38-053-999	Service Vehicle Fluids, Lubricants, Gases, & Pa	16-Jul-2020 07:23:55	BSDRIL	N	DON	602.83
11-Jun-2020 1	3,640	0	444990	03-034-019	Replace Switch (Other)	16-Jul-2020 07:24:00	BSDRIL	I	DON	22.95
11-Jun-2020 1	3,640	0	444990	03-704-007	Replace Hydraulic Motor	10-Jul-2020 13:06:11	BSDRIL	I	DON	3,975.26
11-Jun-2020 1	3,640	0	444990	03-708-007	Replace Sub Saver	13-Jul-2020 17:00:01	BSDRIL	N	DON	310.39
11-Jun-2020 1	3,640	0	444990	24-267-008	Repair Rod Holder	17-Jul-2020 09:32:10	BSDRIL	I	DON	220.91
11-Jun-2020 1	3,640	0	444990	03-267-003	Replace Hydraulics	16-Jul-2020 15:42:08	BSDRIL	I	DON	424.17
11-Jun-2020 1	3,640	0	444990	12-002	Refinish Cab & Sheet Metal	17-Jul-2020 16:24:12	BSETUP	N	DON	84.25
11-Jun-2020 1	3,640	0	444990	38-705	Service Vise	14-Jul-2020 06:45:50	BSDRIL	N	DON	4,159.78
11-Jun-2020 1	3,640	0	444990	38-267-005	Service Controls	22-Jul-2020 09:46:17	BSDRIL	I	DON	1,587.52
11-Jun-2020 1	3,640	0	444990	03-002-065	Replace Hood Latch	17-Jul-2020 12:00:02	BSDRIL	I	DON	77.64
11-Jun-2020 1	3,640	0	444990	38-704-015	Service Track	16-Jul-2020 07:24:49	BSDRIL	N	DON	789.18
11-Jun-2020 1	3,640	0	444990	03-065-004	Replace Cylinder	16-Jul-2020 14:37:00	BSDRIL	I	DON	1,024.22
25-Aug-2020 0	3,782	0	457836	06-704	Inspect Drill Rig	07-Oct-2020 15:26:27	BSDRIL	P	DON	31.51
25-Aug-2020 0	3,782	0	457836	24-042	Repair Cooling System	07-Oct-2020 15:26:22	BSDRIL	I	DON	47.27
25-Aug-2020 0	3,782	0	457836	24-704-015	Repair Track	07-Oct-2020 15:26:17	BSDRIL	B	DON	559.55
16-Sep-2020 0	3,838	0	461701	01-042-014	Adjust Coolant Overflow Reservoir	16-Sep-2020 06:56:56	ROGSHP	P	DON	31.22

Unit Job History

Michels Corporation
Report Printed: 28-Dec-2021 10:13:51 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Z1065 - 2015 VERMEER D24X40II										
16-Sep-2020 1	3,838	0	461851	06-704	Inspect Drill Rig	16-Sep-2020 16:03:24	LAVSHP	O	DON	14.88
17-Sep-2020 1	3,846	0	462038	06-708-004	Inspect Starter Rod	17-Sep-2020 17:55:34	ME1371	O	DON	79.73
16-Oct-2020 1	3,908	0	466956	03-065-004	Replace Cylinder	16-Oct-2020 13:54:36	ROGSHP	I	DON	727.85
22-Oct-2020 0	3,930	0	468112	01-042-014	Adjust Coolant Overflow Reservoir	22-Oct-2020 07:19:33	ROGSHP	P	DON	10.41
12-Nov-2020 0	4,000	0	471713	03-065-004	Replace Cylinder	12-Nov-2020 13:07:53	ROGSHP	B	DON	808.38
24-Nov-2020 0	4,030	0	473618	01-042-014	Adjust Coolant Overflow Reservoir	24-Nov-2020 06:45:47	ROGSHP	P	DON	20.81
07-Dec-2020 1	4,068	0	475638	02-704	Clean Drill Rig	07-Dec-2020 17:00:02	BWASH	N	DON	192.50
23-Feb-2021 0	4,069	0	489715	24-704-016	Repair Stem Rack	04-Mar-2021 07:30:28	BSDRIL	I	DON	655.81
23-Feb-2021 0	4,069	0	489715	24-002-065	Repair Hood Latch	04-Mar-2021 07:30:26	BSDRIL	I	DON	286.88
23-Feb-2021 0	4,069	0	489715	06-704	Inspect Drill Rig	04-Mar-2021 07:30:17	BSDRIL	P	DON	55.05
23-Feb-2021 0	4,069	0	489715	24-704-017	Repair Rod Loader System	04-Mar-2021 07:30:19	BSDRIL	I	DON	2,616.47
23-Feb-2021 0	4,069	0	489715	24-705	Repair Vise	04-Mar-2021 07:30:24	BSDRIL	I	DON	1,976.13
23-Feb-2021 0	4,069	0	489715	38-040	Service Engine / Motor Systems Group	04-Mar-2021 07:30:22	BSDRIL	N	DON	4,871.11
23-Feb-2021 0	4,069	0	489715	24-704-011	Repair Frame / Chassis	04-Mar-2021 07:30:32	BSDRIL	I	DON	311.77
23-Feb-2021 0	4,069	0	489715	03-704-015	Replace Track	04-Mar-2021 07:30:37	BSDRIL	I	DON	1,670.36
23-Feb-2021 0	4,069	0	489715	24-702	Repair Mud Pump	04-Mar-2021 07:30:30	BSDRIL	I	DON	1,078.55
23-Feb-2021 0	4,069	0	489715	03-708-007	Replace Sub Saver	04-Mar-2021 07:30:40	BSDRIL	I	DON	221.64
05-Mar-2021 1	4,069	0	492191	12-002	Refinish Cab & Sheet Metal	05-Mar-2021 17:01:32	BSETUP	N	DON	268.25
08-Apr-2021 1	4,069	0	499251	03-704-016	Replace Stem Rack	14-Apr-2021 08:15:37	BSDRIL	O	DON	18,546.87
21-May-2021 1	4,069	0	508314	38-704-017	Service Rod Loader System	21-May-2021 14:36:18	BSDRIL	O	DON	500.07
21-May-2021 1	4,069	0	508314	95-MSC-004	Travel Travel Time - To/From Job Site	21-May-2021 14:36:23	BSDRIL	B	DON	891.48
21-May-2021 1	4,069	0	508314	24-704-017	Repair Rod Loader System	21-May-2021 14:36:23	BSDRIL	B	DON	850.71
14-Jun-2021 0	4,069	0	512471	03-079-008	Replace Dock Lock Mechanism	14-Jun-2021 17:00:01	BSDRIL	I	DON	64.93
14-Jun-2021 0	4,069	0	512471	24-030	Repair Electrical Group	23-Jun-2021 11:32:01	BSDRIL	I	DON	134.10
14-Jun-2021 0	4,069	0	512471	24-406	Repair Pressure Washer	15-Jun-2021 12:54:45	BSDRIL	O	DON	296.51
14-Jun-2021 0	4,069	0	512471	38-705	Service Vise	15-Jun-2021 11:46:53	BSDRIL	O	DON	291.67
14-Jun-2021 0	4,069	0	512471	38-704-018	Service Operator Console / Station	15-Jun-2021 11:46:55	BSDRIL	O	DON	326.40
14-Jun-2021 0	4,069	0	512471	03-705-010	Replace Grease System	14-Jun-2021 16:24:44	BSDRIL	I	DON	259.05
14-Jun-2021 0	4,069	0	512471	38-053-999	Service Vehicle Fluids, Lubricants, Gases, & Pa	22-Jun-2021 11:11:19	BSDRIL	N	DON	427.54

Unit Job History

Michels Corporation

Report Printed: 28-Dec-2021 10:13:51 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Z1065 - 2015 VERMEER D24X40II										
14-Jun-2021 0(	4,069	0	512471	03-065	Replace Hydraulic Systems - Special Applicatio	23-Jun-2021 11:31:41	BSDRIL	I	DON	444.84
27-Jul-2021 06	4,069	0	521282	24-704-018	Repair Operator Console / Station	06-Aug-2021 07:30:04	BSDRIL	O	DON	387.24
27-Jul-2021 06	4,069	0	521282	95-MSC-004	Travel Travel Time - To/From Job Site	06-Aug-2021 07:30:01	BSDRIL	O	DON	196.33
11-Aug-2021 1	4,069	0	524441	03-063-003	Replace Transceiver - GPS Tracker	11-Aug-2021 13:18:23	ELEC03	Q	DON	297.50
13-Aug-2021 C	4,069	0	524858	38-704-018	Service Operator Console / Station	16-Aug-2021 07:49:40	BSDRIL	O	DON	9,776.19
13-Aug-2021 C	4,069	0	524858	95-MSC-004	Travel Travel Time - To/From Job Site	16-Aug-2021 07:49:38	BSDRIL	O	DON	1,789.53
18-Aug-2021 C	4,069	0	525925	24-702	Repair Mud Pump	25-Aug-2021 08:23:38	BSDRIL	O	DON	525.48
18-Aug-2021 C	4,069	0	525925	06-030	Inspect Electrical Group	19-Aug-2021 06:21:39	BSDRIL	I	DON	773.89
18-Aug-2021 C	4,069	0	525925	95-MSC-004	Travel Travel Time - To/From Job Site	19-Aug-2021 06:21:36	BSDRIL	O	DON	957.84
03-Nov-2021 C	4,069	0	543673	03-708-004	Replace Starter Rod	03-Nov-2021 06:41:32	OTSSHP	N	DON	501.62
08-Nov-2021 1	4,069	0	545127	01-042-014	Adjust Coolant Overflow Reservoir	08-Nov-2021 15:53:41	OTSSHP	O	DON	25.34
29-Nov-2021 C	4,069	0	549420	06-042-002	Inspect Radiator	10-Dec-2021 07:31:50	OTSSHP	N	DON	605.66
01-Dec-2021 0	4,069	0	549982	02-704	Clean Drill Rig	14-Dec-2021 14:16:18	BWASH	N	DON	342.72
01-Dec-2021 0	4,069	0	549982	12-002	Refinish Cab & Sheet Metal	09-Dec-2021 07:52:43	BSETUP	Z	DON	219.56
06-Dec-2021 0	4,069	0	551327	24-704	Repair Drill Rig	07-Dec-2021 07:20:48	BSDRIL	Z	DON	1,120.32

Unit No: Z1065 **Count: 160** **171,658.18**