Unit Job History

Michels Corporation

Report Printed: 06-Jul-2022 07:41:56 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: D0649 - 1993 TRAILEZE D14RS24										
07-Jan-2010 1:	0	0	33193	03-032-001	Replace Battery	07-Jan-2010 13:22:12	HARRIS	P	DON	176.11
07-Jan-2010 1:	0	0	33193	06-100-002	Inspect DO NOT USE - DOT Federal Insp	07-Jan-2010 13:22:12	HARRIS	P	DON	89.57
07-Jan-2010 1:	0	0	33193	19-049-003	Wire/Rewire ECM Wiring Harness	07-Jan-2010 13:22:12	HARRIS	P	DON	99.45
30-Mar-2011 0	0	0	62599	01-017-001	Adjust Tire - Pneumatic	04-Apr-2011 08:19:18	HARRIS	I	DON	27.74
30-Mar-2011 0	0	0	62599	03-013-012	Replace Electric Brakes	04-Apr-2011 08:17:32	HARRIS	I	DON	69.35
30-Mar-2011 0	0	0	62599	06-100-002	Inspect DO NOT USE - DOT Federal Insp	04-Apr-2011 08:21:13	HARRIS	P	DON	27.74
30-Mar-2011 0	0	0	62599	07-018-001	Lubricate Front Axle Hubs & Bearings	04-Apr-2011 08:16:13	HARRIS	I	DON	83.22
30-Mar-2011 0	0	0	62599	14-034-004	Install Clearance & Marker Lamps	04-Apr-2011 08:20:13	HARRIS	I	DON	27.74
30-Mar-2011 0	0	0	62599	24-013-020	Repair Break Away Battery	04-Apr-2011 08:15:03	HARRIS	I	DON	110.96
30-Mar-2011 0	0	0	62599	24-034-002	Repair Stop, Tail, Turn & License	04-Apr-2011 08:13:54	HARRIS	I	DON	83.22
25-Apr-2011 0	0	0	64667	26-077-006	Weld Sub-Frame - Upper	02-May-2011 14:30:22	HARRIS	I	DON	166.44
13-Feb-2013 0	0	0	109178	06-100-DOT	Inspect DOT Federal Inspection	13-Feb-2013 07:35:00	BVLOFC	P	DON	86.40
13-Feb-2013 0	0	0	109178	26-077-001	Weld Support - Frame Assembly	13-Feb-2013 17:00:00	BVLOFC	F	DON	201.92
16-Aug-2013 0	0	0	127530	19-034	Wire/Rewire Lighting System	16-Aug-2013 17:00:00	HARRIS	I	DON	55.96
19-Aug-2013 0	0	0	128487	24-034-002	Repair Stop, Tail, Turn & License	19-Aug-2013 17:00:00	HARRIS	I	DON	321.77
26-Aug-2013 0	0	0	129357	06-100-DOT	Inspect DOT Federal Inspection	26-Aug-2013 17:00:00	HARRIS	P	DON	0.00
12-Dec-2013 0	0	0	142868	03-063-003	Replace Transceiver - GPS Tracker	12-Dec-2013 00:00:00	HARRIS	C	DON	302.13
16-Jun-2015 0	0	0	204516	06-100-DOT	Inspect DOT Federal Inspection	16-Jun-2015 08:17:50	HARRIS	P	DON	34.46
16-Jun-2015 0	0	0	204516	23-055-034	Burn / Cut Shaft - Reel Carrier	22-Oct-2015 06:05:09	HARSHP	I	DON	543.32
15-Feb-2016 1	0	0	233387	06-100-PMB	Inspect B PMI	16-Feb-2016 11:57:45	HARSHP	P	DON	108.29
15-Feb-2016 1	0	0	233387	24-014-001	Repair Frame Assembly	16-Feb-2016 10:42:40	HARSHP	I	DON	120.80
29-Jul-2016 09	0	0	253757	03-071-001	Replace Floor / Decking / Flatbed	11-Aug-2016 10:23:31	HARSHP	I	DON	1,494.24
29-Jul-2016 09	0	0	253757	06-100-DOT	Inspect DOT Federal Inspection	20-Aug-2016 09:42:40	HARRIS	P	DON	32.66
29-Jul-2016 09	0	0	253757	06-100-PMA	Inspect A PMI	16-Aug-2016 16:37:10	HARRIS	P	DON	113.36
12-Dec-2016 1	0	0	269398	14-014-007	Install License Carrier	12-Dec-2016 14:04:40	HARSHP	I	DON	8.01
24-Jul-2018 14	0	0	345191	03-013-012	Replace Electric Brakes	05-Dec-2018 08:06:29	BTRLR	I	DON	861.62
24-Jul-2018 14	0	0	345191	03-013-020	Replace Break Away Battery	05-Dec-2018 13:48:15	BTRLR	I	DON	98.79
24-Jul-2018 14	0	0	345191	03-017-001	Replace Tire - Pneumatic	04-Dec-2018 15:29:57	BTIRE	I	DON	1,984.90
24-Jul-2018 14	0	0	345191	03-018-011	Replace Seal - Wheel	05-Dec-2018 11:02:38	BTRLR	I	DON	210.15

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: D0649 - 1993 TRAILEZE D14RS24										
24-Jul-2018 14	0	0	345191	03-063-003	Replace Transceiver - GPS Tracker	24-Jul-2018 14:34:13	GPSINS	Q	DON	325.27
24-Jul-2018 14	0	0	345191	06-100-DOT	Inspect DOT Federal Inspection	05-Dec-2018 15:16:16	BTRLR	P	DON	21.78
24-Jul-2018 14	0	0	345191	06-100-PMA	Inspect A PMI	05-Dec-2018 14:37:06	BTRLR	P	DON	208.32
24-Jul-2018 14	0	0	345191	14-053-012	Install Pad lock	05-Dec-2018 14:47:02	BTRLR	I	DON	18.99
05-Dec-2019 1			415435	01-013-012	Adjust Electric Brakes	05-Dec-2019 14:00:52	ROGSHP	N	DON	6.35
05-Dec-2019 1			415435	03-034-011	Replace Plug - Trailer Light Cord	05-Dec-2019 15:15:46	ROGSHP	N	DON	61.07
05-Dec-2019 1			415435	03-079-009	Replace Tape - Reflective, Conspicuity	05-Dec-2019 15:54:01	ROGSHP	I	DON	10.43
05-Dec-2019 1			415435	06-100-DOT	Inspect DOT Federal Inspection	05-Dec-2019 13:38:07	ROGSHP	P	DON	36.56
05-Dec-2019 1			415435	24-013-012	Repair Electric Brakes	05-Dec-2019 13:50:24	ROGSHP	I	DON	7.46
05-Dec-2019 1			415435	26-077-021	Weld Jack - Leveling	05-Dec-2019 15:36:50	ROGSHP	I	DON	12.79
14-Dec-2020 0			476981	03-014-005	Replace Battery Support	14-Dec-2020 17:21:15	LAVSHP	I	DON	133.47
14-Dec-2020 0			476981	03-034-004	Replace Clearance & Marker Lamps	14-Dec-2020 17:34:17	LAVSHP	I	DON	15.53
14-Dec-2020 0			476981	06-100-DOT	Inspect DOT Federal Inspection	14-Dec-2020 10:20:51	LAVSHP	P	DON	64.00
29-Dec-2021 1			556166	03-063-003	Replace Transceiver - GPS Tracker	29-Dec-2021 13:31:54	ELEC03	Q	DON	365.01
12-Jan-2022 08			558541	03-018-012	Replace Cap - Hub	13-Jan-2022 11:45:07	OTSSHP	I	DON	13.12
12-Jan-2022 08			558541	03-077-021	Replace Jack - Leveling	13-Jan-2022 13:57:13	OTSSHP	I	DON	422.17
12-Jan-2022 08			558541	06-100-DOT	Inspect DOT Federal Inspection	13-Jan-2022 11:27:13	OTSSHP	P	DON	97.94
24-Feb-2022 1.			569735	03-034-011	Replace Plug - Trailer Light Cord	24-Feb-2022 14:23:51	OTSSHP	O	DON	53.14
28-Jun-2022 08			599038	06-100-009	Inspect Safety Check	28-Jun-2022 10:36:47	BTRLR	Z	DON	39.45
28-Jun-2022 08			599038	25-053-005	Remove Markings - Vehicle - Decals	28-Jun-2022 09:42:02	BTRLR	Z	DON	13.50
28-Jun-2022 08			599038	25-063-003	Remove Transceiver - GPS Tracker	28-Jun-2022 09:23:18	BTRLR	Z	DON	17.44

Unit No: D0649 **Count: 50** **9,484.10**