Unit Job History

Michels Corporation
Report Printed: 15-Sep-2022 05:24:20 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: A0960 - 2001 INTERNATIO 4900										
14-Oct-2016 0	108,559	0	302560	03-011-002	Replace King Pin	19-Oct-2016 07:01:00	BVLOFC	N	DON	433.84
14-Oct-2016 0	108,559	0	302560	06-100-PMA	Inspect A PMI	19-Oct-2016 07:01:00	BVLOFC	P	DON	185.93
14-Oct-2016 0	108,559	0	302560	14-034-011	Install Plug - Trailer Light Cord	19-Oct-2016 07:01:00	BVLOFC	J	DON	46.48
09-Dec-2016 0	108,556	0	269128	14-063-003	Install Transceiver - GPS Tracker	09-Dec-2016 09:12:12	BTRUCK	Q	DON	246.75
30-Jan-2017 1	108,556	0	275640	03-017-001	Replace Tire - Pneumatic	30-Jan-2017 11:39:58	BTIRE	F	DON	554.39
30-Mar-2017 0	108,556	0	283233	02-002-044	Clean Cab - Complete	31-Mar-2017 13:25:17	WTNSHP	P	DON	274.66
30-Mar-2017 0	108,556	0	283233	03-017-001	Replace Tire - Pneumatic	30-Mar-2017 09:57:37	WTNSHP	I	DON	2,257.72
30-Mar-2017 0	108,556	0	283233	03-032-001	Replace Battery	04-Jun-2017 15:07:50	WTNSHP	I	DON	301.08
31-Oct-2017 0	108,556	0	310734	02-002	Clean Cab & Sheet Metal	02-Nov-2017 09:52:48	WTNSHP	I	DON	121.94
31-Oct-2017 0	108,556	0	310734	03-013-016	Replace Air Drier / Purge Valve	01-Nov-2017 16:03:21	WTNSHP	I	DON	361.00
31-Oct-2017 0	108,556	0	310734	03-034-002	Replace Stop, Tail, Turn & License	01-Nov-2017 07:44:42	WTNSHP	I	DON	55.63
31-Oct-2017 0	108,556	0	310734	03-042	Replace Cooling System	01-Nov-2017 09:49:06	WTNSHP	P	DON	120.42
31-Oct-2017 0	108,556	0	310734	06-100-006	Inspect Post-Trip Inspection	31-Oct-2017 08:37:25	WTNSHP	P	DON	70.61
31-Oct-2017 0	108,556	0	310734	18-100-000	Test On Road Equip / Field Service	02-Nov-2017 11:05:24	WTNSHP	P	DON	37.50
31-Oct-2017 0	108,556	0	310734	24-056	Repair Power Take Off	01-Nov-2017 06:36:20	WTNSHP	I	DON	237.59
31-Oct-2017 0	108,556	0	310734	38-027	Service Transmission - Main, Automatic	01-Nov-2017 14:42:12	WTNSHP	P	DON	398.29
31-Oct-2017 0	108,556	0	310734	38-100-PMA	Service A PMI	01-Nov-2017 12:02:12	WTNSHP	P	DON	105.54
30-Jan-2018 0	110,657	0	321541	06-100-DOT	Inspect DOT Federal Inspection	30-Jan-2018 09:52:19	WTNSHP	P	DON	55.74
31-Jan-2018 1	110,657	0	321843	03-017-001	Replace Tire - Pneumatic	02-Feb-2018 07:14:22	WTNSHP	P	DON	597.95
23-May-2018 1	112,786	0	336936	01-013-002	Adjust Rear Brakes & Drums	30-May-2018 09:48:48	WTNSHP	P	DON	327.85
07-Jun-2018 1	112,786	0	338903	14-052-003	Install Radio Equipment	24-Aug-2018 08:55:12	GPSINS	I	DON	635.04
22-Oct-2018 1	113,977	0	357620	03-173-003	Replace Hydraulics	05-Nov-2018 12:17:12	WTNSHP	P	DON	1,902.53
05-Jan-2019 0	115,176	0	366970	03-003-001	Replace Gauges & Warning Devices	26-Feb-2019 11:53:13	WTNSHP	I	DON	358.11
05-Jan-2019 0	115,176	0	366970	03-013-010	Replace Air Brake Valve	26-Feb-2019 11:53:13	WTNSHP	I	DON	517.32
05-Jan-2019 0	115,176	0	366970	06-100-DOT	Inspect DOT Federal Inspection	26-Feb-2019 11:53:07	WTNSHP	P	DON	143.90
17-May-2019 (	117,182	0	388025	03-034-002	Replace Stop, Tail, Turn & License	31-May-2019 00:00:00	BVLOFC	O	DON	257.39
17-May-2019 (	117,182	0	388025	19-003	Wire/Rewire Instruments, Gauges, Warning & S	31-May-2019 00:00:00	BVLOFC	O	DON	1,339.66
17-May-2019 (	117,182	0	388025	24-001-001	Repair Air Conditioning Assembly		BVLOFC	O	CAN	0.00
17-May-2019 (	117,182	0	388025	24-030	Repair Electrical Group	31-May-2019 00:00:00	BVLOFC	O	DON	197.25

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: A0960 - 2001 INTERNATIO 4900										
27-Jun-2019 0(		861	393381	03-001-011	Replace Clutch Assembly - Compressor	09-Jul-2019 00:00:00	BVLOFC	B	DON	548.93
27-Jun-2019 0(		861	393381	03-003	Replace Instruments, Gauges, Warning & Shutd	09-Jul-2019 00:00:00	BVLOFC	B	DON	1,521.04
27-Jun-2019 0(		861	393381	03-015-004	Replace Steering Linkage	09-Jul-2019 00:00:00	BVLOFC	N	DON	572.95
27-Jun-2019 0(		861	393381	03-078-014	Replace Tarpaulin/ Tonneau Cover	09-Jul-2019 00:00:00	BVLOFC	N	DON	827.24
07-Nov-2019 C	120,569	995	411505	02-002	Clean Cab & Sheet Metal	20-Nov-2019 11:00:42	WTNSHP	I	DON	123.14
07-Nov-2019 C	120,569	995	411505	03-002-010	Replace Mirrors	11-Nov-2019 09:41:14	WTNSHP	I	DON	40.67
07-Nov-2019 C	120,569	995	411505	03-002-035	Replace Windshield Wiper & Washer	18-Nov-2019 10:27:57	WTNSHP	I	DON	13.74
07-Nov-2019 C	120,569	995	411505	03-013-003	Replace Brake Chamber - Parking	18-Nov-2019 14:41:42	WTNSHP	I	DON	436.17
07-Nov-2019 C	120,569	995	411505	03-013-004	Replace Brake Chamber - Service	20-Nov-2019 08:19:09	WTNSHP	I	DON	93.62
07-Nov-2019 C	120,569	995	411505	03-013-007	Replace Brake Lines & Fittings - Hydraulic & A	12-Nov-2019 07:29:12	WTNSHP	I	DON	120.94
07-Nov-2019 C	120,569	995	411505	03-013-009	Replace Air Compressor	15-Nov-2019 14:15:38	WTNSHP	I	DON	1,302.62
07-Nov-2019 C	120,569	995	411505	03-013-016	Replace Air Drier / Purge Valve	14-Nov-2019 10:31:55	WTNSHP	I	DON	225.73
07-Nov-2019 C	120,569	995	411505	03-018-012	Replace Cap - Hub	14-Nov-2019 12:47:02	WTNSHP	I	DON	55.18
07-Nov-2019 C	120,569	995	411505	03-031-001	Replace Generator/Alternator	22-Nov-2019 10:38:05	WTNSHP	I	DON	617.38
07-Nov-2019 C	120,569	995	411505	03-034-002	Replace Stop, Tail, Turn & License	14-Nov-2019 11:54:45	WTNSHP	I	DON	50.05
07-Nov-2019 C	120,569	995	411505	03-034-016	Replace Turn Signal Switch	11-Nov-2019 10:26:57	WTNSHP	I	DON	221.92
07-Nov-2019 C	120,569	995	411505	03-042-008	Replace Oil Cooler	18-Nov-2019 13:17:32	WTNSHP	I	DON	1,208.25
07-Nov-2019 C	120,569	995	411505	03-045-026	Replace Tensioner - Engine Belts	22-Nov-2019 08:39:49	WTNSHP	I	DON	253.30
07-Nov-2019 C	120,569	995	411505	03-051-009	Replace Fire Extinguisher	18-Nov-2019 13:55:30	WTNSHP	I	DON	35.07
07-Nov-2019 C	120,569	995	411505	03-053-017	Replace First Aid Kit	18-Nov-2019 13:57:27	WTNSHP	I	DON	65.49
07-Nov-2019 C	120,569	995	411505	03-078-009	Replace Mud Flaps and Hanger Brackets	18-Nov-2019 13:17:45	WTNSHP	I	DON	116.29
07-Nov-2019 C	120,569	995	411505	06-100-006	Inspect Post-Trip Inspection	25-Nov-2019 07:45:21	WTNSHP	P	DON	203.18
07-Nov-2019 C	120,569	995	411505	06-100-PMA	Inspect A PMI	25-Nov-2019 07:46:09	WTNSHP	P	DON	0.00
07-Nov-2019 C	120,569	995	411505	24-003	Repair Instruments, Gauges, Warning & Shutdo	18-Nov-2019 13:18:05	WTNSHP	I	DON	96.71
07-Nov-2019 C	120,569	995	411505	24-044-023	Repair Primer Pump (Hand)	20-Nov-2019 09:56:57	WTNSHP	I	DON	50.52
07-Nov-2019 C	120,569	995	411505	38-100-PMA	Service A PMI	25-Nov-2019 07:45:14	WTNSHP	P	DON	259.00
10-Dec-2019 0	120,570	996	416101	24-173-001	Repair Body or Bed	11-Dec-2019 10:33:41	WTNSHP	I	DON	237.56
27-Jan-2020 0(	120,570	996	423012	03-034-007	Replace Signaling Devices	27-Jan-2020 09:51:05	WTNSHP	I	DON	22.55
27-Jan-2020 0(	120,570	996	423012	03-051-009	Replace Fire Extinguisher	27-Jan-2020 09:59:23	WTNSHP	I	DON	158.67

Unit Job History

Michels Corporation
Report Printed: 15-Sep-2022 05:24:20 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: A0960 - 2001 INTERNATIO 4900										
27-Jan-2020 0(	120,570	996	423012	06-100-DOT	Inspect DOT Federal Inspection	27-Jan-2020 16:00:28	WTNSHP	P	DON	35.98
27-Jan-2020 0(	120,570	996	423012	06-100-PMA	Inspect A PMI	30-Jan-2020 13:44:54	WTNSHP	P	DON	92.59
27-Jan-2020 0(	120,570	996	423012	14-034-006	Install Warning Lamps - Special Application	27-Jan-2020 15:07:30	WTNSHP	I	DON	417.23
27-Aug-2020 1	120,882	1,027	458554	02-002	Clean Cab & Sheet Metal	09-Sep-2020 12:56:42	WTNSHP	I	DON	98.30
27-Aug-2020 1	120,882	1,027	458554	03-015-013	Replace Steering Gear - Rack & Pinion Type	09-Sep-2020 09:18:50	WTNSHP	I	DON	3,049.41
27-Aug-2020 1	120,882	1,027	458554	03-022-002	Replace Shaft - Rear Axle	02-Sep-2020 15:00:31	WTNSHP	P	DON	569.71
27-Aug-2020 1	120,882	1,027	458554	03-034-004	Replace Clearance & Marker Lamps	08-Sep-2020 14:23:12	WTNSHP	I	DON	40.70
27-Aug-2020 1	120,882	1,027	458554	24-071-002	Repair Front Wall / Headboard Assembly	31-Aug-2020 14:15:09	WTNSHP	I	DON	118.59
27-Aug-2020 1	120,882	1,027	458554	24-173-010	Repair Spring - Tailgate	08-Sep-2020 13:58:27	WTNSHP	I	DON	496.72
08-Jan-2021 0(	121,977	1,136	480807	03-032-001	Replace Battery	14-Jan-2021 06:23:53	WTNSHP	I	DON	230.54
18-Mar-2021 1	122,723	1,216	495125	06-100-DOT	Inspect DOT Federal Inspection	22-Mar-2021 06:26:07	SCHED	P	DON	61.27
18-Mar-2021 1	122,723	1,216	495125	38-100-DOT	Service DOT Federal Inspection	22-Mar-2021 06:26:07	BVLOFC	P	DON	0.00
07-Jul-2021 09	123,933	1,344	516918	03-051-009	Replace Fire Extinguisher	09-Sep-2021 07:23:54	WTNSHP	I	DON	0.00
07-Jul-2021 09	123,933	1,344	516918	06-100-PMA	Inspect A PMI	09-Sep-2021 07:21:35	SCHED	P	DON	15.04
31-Mar-2022 1	123,941	1,344	578601	03-063-003	Replace Transceiver - GPS Tracker	31-Mar-2022 11:08:10	ELEC01	Q	DON	254.58
03-Jun-2022 0(		7,490	593240	03-002-010	Replace Mirrors	03-Jun-2022 15:39:07	TRK001	I	DON	92.33
03-Jun-2022 0(		7,490	593240	03-030-005	Replace Batteries (Fiber Optic)	03-Jun-2022 09:29:11	BTRUCK	I	DON	226.81
03-Jun-2022 0(		7,490	593240	06-100-009	Inspect Safety Check	06-Jun-2022 05:21:00	TRK001	I	DON	113.06
03-Jun-2022 0(		7,490	593240	25-063-003	Remove Transceiver - GPS Tracker	03-Jun-2022 16:14:57	TRK001	I	DON	24.75
29-Aug-2022 0		7,490	612601	02-002	Clean Cab & Sheet Metal	29-Aug-2022 15:00:05	BSETUP	Z	DON	84.42

Unit No: A0960 **Count: 78** **27,642.04**