Unit Job History

Michels Corporation

Report Printed: 15-Sep-2022 09:32:51 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2693 - 2014 F150 CREWCAB										
02-Jul-2014 05	26	0	163835	06-100-009	Inspect Safety Check	02-Jul-2014 13:35:06	BTRUCK	P	DON	15.84
02-Jul-2014 05	26	0	163835	14-002-029	Install Trim - Seat	28-Jul-2014 07:43:48	BSETUP	C	DON	471.23
02-Jul-2014 05	26	0	163835	14-034-006	Install Warning Lamps - Special Application	02-Jul-2014 08:11:08	BSETUP	C	DON	350.51
02-Jul-2014 05	26	0	163835	14-052-005	Install Transmitter - CB	02-Jul-2014 10:26:57	BSETUP	C	DON	155.82
02-Jul-2014 05	26	0	163835	14-078-009	Install Mud Flaps and Hanger Brackets	02-Jul-2014 09:42:33	BSETUP	C	DON	82.82
02-Jul-2014 05	26	0	163835	14-078-014	Install Tarpaulin/ Tonneau Cover	02-Jul-2014 09:26:35	BSETUP	C	DON	480.00
02-Jul-2014 05	26	0	163835	14-510-002	Install Tool Box	02-Jul-2014 08:51:01	BSETUP	C	DON	320.44
02-Jul-2014 05	26	0	163835	14-052-011	Install Auxiliary Power	02-Jul-2014 08:15:02	BSETUP	C	DON	174.95
02-Jul-2014 05	26	0	163835	14-053-014	Install Floor Mats	02-Jul-2014 10:43:42	BSETUP	C	DON	80.92
02-Jul-2014 05	26	0	163835	14-071-011	Install Scuff Liner / Bed Mat	02-Jul-2014 06:52:57	BSETUP	C	DON	74.62
02-Jul-2014 05	26	0	163835	14-052-014	Install Cellular Telephone Accessories	02-Jul-2014 09:57:44	BSETUP	C	DON	58.09
02-Jul-2014 05	26	0	163835	14-053-005	Install Markings - Vehicle - Decals	02-Jul-2014 11:42:54	BSETUP	C	DON	79.99
27-Aug-2014 1	5,133	0	170698	06-100-PMB	Inspect B PMI	28-Aug-2014 08:04:43	BTRUCK	P	DON	9.46
27-Aug-2014 1	5,133	0	170698	38-045	Service Power Plant	28-Aug-2014 07:47:36	BTRUCK	P	DON	52.43
27-Oct-2014 0	10,054	0	177683	38-045	Service Power Plant	27-Oct-2014 13:02:49	BTRUCK	P	DON	53.92
27-Oct-2014 0	10,054	0	177683	06-100-PMB	Inspect B PMI	27-Oct-2014 13:37:39	BTRUCK	P	DON	19.25
07-Nov-2014 1	10,054	0	179817	06-013	Inspect Brakes	07-Nov-2014 11:21:53	BTRUCK	P	DON	17.71
25-Nov-2014 0	10,054	0	182253	03-032-001	Replace Battery	25-Nov-2014 07:56:53	BTRUCK	I	DON	102.51
22-Jan-2015 0	15,129	0	188702	06-100-PMB	Inspect B PMI	23-Jan-2015 08:11:00	BTRUCK	P	DON	16.77
22-Jan-2015 0	15,129	0	188702	31-017-001	Rotate Tire - Pneumatic	23-Jan-2015 08:44:54	BTRUCK	I	DON	4.23
22-Jan-2015 0	15,129	0	188702	38-045	Service Power Plant	23-Jan-2015 08:37:15	BTRUCK	P	DON	48.72
25-Feb-2015 0	18,193	0	192561	03-002-024	Replace Glass / Windshield	02-Mar-2015 15:04:45	BTRUCK	I	DON	363.67
25-Feb-2015 0	18,193	0	192561	24-002-018	Repair Cab Or Front Door Mechanism	02-Mar-2015 09:58:50	BTRUCK	I	DON	104.47
13-Apr-2015 0	20,767	0	197603	38-045	Service Power Plant	13-Apr-2015 10:38:33	BTRUCK	P	DON	106.28
13-Apr-2015 0	20,767	0	197603	06-100-PMB	Inspect B PMI	13-Apr-2015 11:07:17	BTRUCK	P	DON	15.88
13-Apr-2015 0	20,767	0	197603	24-034-020	Repair Dome / Reading Light		BTRUCK	O	CAN	0.00
12-Jun-2015 1	26,227	0	204203	06-100-PMB	Inspect B PMI	12-Jun-2015 15:29:20	BTRUCK	P	DON	79.69
12-Jun-2015 1	26,227	0	204203	38-045	Service Power Plant	12-Jun-2015 16:02:58	BTRUCK	P	DON	59.24
15-Jun-2015 1	26,410	0	204459	24-002-027	Repair Seat Frames & Springs	16-Jun-2015 10:39:55	BTRUCK	W	DON	231.01

Unit Job History

Michels Corporation

Report Printed: 15-Sep-2022 09:32:51 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2693 - 2014 F150 CREWCAB										
19-Jun-2015 0(	26,861	0	204977	14-052-015	Install Power Inverter/Converter	19-Jun-2015 08:17:07	BSETUP	C	DON	251.36
05-Aug-2015 0	30,911	0	210150	38-045	Service Power Plant	05-Aug-2015 12:00:12	BTRUCK	P	DON	53.59
05-Aug-2015 0	30,911	0	210150	06-100-PMB	Inspect B PMI	05-Aug-2015 11:24:30	BTRUCK	P	DON	9.05
06-Oct-2015 0:	33,826	0	217332	24-032-001	Repair Battery	06-Oct-2015 10:29:18	BTRUCK	O	DON	32.76
06-Oct-2015 0:	33,826	0	217332	38-045	Service Power Plant	06-Oct-2015 13:13:32	BTRUCK	P	DON	59.61
06-Oct-2015 0:	33,826	0	217332	03-002-035	Replace Windshield Wiper & Washer	06-Oct-2015 12:01:34	BTRUCK	I	DON	15.01
06-Oct-2015 0:	33,826	0	217332	06-100-PMB	Inspect B PMI	06-Oct-2015 11:41:51	BTRUCK	P	DON	40.09
18-Oct-2015 0(	38,929	0	218694	06-100-009	Inspect Safety Check	18-Oct-2015 06:30:00	TUMFLD	P	DON	17.11
18-Oct-2015 0(	38,929	0	218694	07-100-PMB	Lubricate B PMI	18-Oct-2015 07:00:00	TUMFLD	P	DON	44.45
30-Nov-2015 0	36,880	0	223418	38-045	Service Power Plant	03-Dec-2015 09:20:37	BTRUCK	P	DON	36.68
30-Nov-2015 0	36,880	0	223418	06-100-PMB	Inspect B PMI	03-Dec-2015 09:01:07	BTRUCK	P	DON	30.32
17-Dec-2015 1	36,880	0	225895	03-052-005	Replace Transmitter - CB	17-Dec-2015 15:48:58	BSETUP	O	DON	231.84
18-Jan-2016 0:	39,028	0	229346	24-032-001	Repair Battery	18-Jan-2016 08:18:37	BTRUCK	B	DON	268.33
18-Mar-2016 1	42,017	0	238195	38-045	Service Power Plant	21-Mar-2016 08:55:29	BTRUCK	P	DON	44.16
18-Mar-2016 1	42,017	0	238195	31-017-001	Rotate Tire - Pneumatic	21-Mar-2016 08:37:05	BTRUCK	I	DON	8.28
18-Mar-2016 1	42,017	0	238195	06-100-PMB	Inspect B PMI	21-Mar-2016 08:22:12	BTRUCK	P	DON	33.18
08-Apr-2016 1	42,017	0	240577	02-002	Clean Cab & Sheet Metal	08-Apr-2016 14:17:38	BSETUP	J	DON	42.04
12-Apr-2016 0	42,017	0	240844	24-017-001	Repair Tire - Pneumatic	12-Apr-2016 07:36:12	BTIRE	I	DON	9.80
19-May-2016 (	47,350	0	245101	06-100-PMB	Inspect B PMI	20-May-2016 09:22:10	BTRUCK	P	DON	61.50
19-May-2016 (	47,350	0	245101	38-045	Service Power Plant	20-May-2016 09:37:42	BTRUCK	P	DON	42.89
19-May-2016 (	47,350	0	245101	03-002-035	Replace Windshield Wiper & Washer	20-May-2016 10:01:10	BTRUCK	O	DON	34.79
29-Jul-2016 07	52,812	0	253735	03-013-002	Replace Rear Brakes & Drums	29-Jul-2016 14:33:09	BTRUCK	I	DON	130.95
29-Jul-2016 07	52,812	0	253735	06-100-PMB	Inspect B PMI	29-Jul-2016 10:01:06	BTRUCK	P	DON	43.93
29-Jul-2016 07	52,812	0	253735	31-017-001	Rotate Tire - Pneumatic	29-Jul-2016 15:00:30	BTRUCK	I	DON	19.77
29-Jul-2016 07	52,812	0	253735	03-013-001	Replace Front Brakes & Drums	29-Jul-2016 12:00:23	BTRUCK	I	DON	116.68
29-Jul-2016 07	52,812	0	253735	38-045	Service Power Plant	29-Jul-2016 10:39:31	BTRUCK	P	DON	55.71
16-Sep-2016 1:	58,456	0	259780	03-002-035	Replace Windshield Wiper & Washer	19-Sep-2016 09:16:13	BTRUCK	I	DON	39.21
16-Sep-2016 1:	58,456	0	259780	38-045	Service Power Plant	19-Sep-2016 08:44:52	BTRUCK	P	DON	42.83
16-Sep-2016 1:	58,456	0	259780	06-100-PMB	Inspect B PMI	19-Sep-2016 08:29:51	BTRUCK	P	DON	15.49

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2693 - 2014 F150 CREWCAB										
02-Dec-2016 1	63,947	0	268433	06-100-PMB	Inspect B PMI	06-Dec-2016 09:00:25	BTRUCK	P	DON	25.11
02-Dec-2016 1	63,947	0	268433	38-045	Service Power Plant	06-Dec-2016 09:00:31	BTRUCK	P	DON	34.54
02-Dec-2016 1	63,947	0	268433	03-002-035	Replace Windshield Wiper & Washer	06-Dec-2016 09:16:40	BTRUCK	I	DON	30.75
29-Mar-2017 1	68,490	0	283131	06-100-PMB	Inspect B PMI	31-Mar-2017 11:06:02	BTRUCK	P	DON	22.21
29-Mar-2017 1	68,490	0	283131	24-013-034	Repair Parking Brake - Complete	31-Mar-2017 12:59:27	BTRUCK	O	DON	32.46
29-Mar-2017 1	68,490	0	283131	38-045	Service Power Plant	31-Mar-2017 11:32:32	BTRUCK	P	DON	45.93
08-May-2017 1	71,751	0	287988	02-002	Clean Cab & Sheet Metal	08-May-2017 19:01:12	BSETUP	J	DON	183.43
08-May-2017 1	71,751	0	287988	06-100-PMB	Inspect B PMI	08-May-2017 13:06:56	BTRUCK	P	DON	22.45
08-May-2017 1	71,751	0	287988	25-052-005	Remove Transmitter - CB	09-May-2017 09:14:14	BSETUP	I	DON	21.98
08-May-2017 1	71,751	0	287988	38-045	Service Power Plant	08-May-2017 13:28:21	BTRUCK	P	DON	46.20
08-May-2017 1	71,751	0	287988	03-002-035	Replace Windshield Wiper & Washer	08-May-2017 13:32:19	BTRUCK	I	DON	24.95
08-May-2017 1	71,751	0	287988	03-034-002	Replace Stop, Tail, Turn & License	08-May-2017 13:59:09	BTRUCK	I	DON	20.86
14-Nov-2017 1	84,922	0	312520	06-100-PMA	Inspect A PMI	15-Nov-2017 10:44:00	BVLOFC	P	DON	29.32
14-Nov-2017 1	84,922	0	312520	03-017-001	Replace Tire - Pneumatic	15-Nov-2017 10:43:00	BVLOFC	O	DON	1,028.72
14-Nov-2017 1	84,922	0	312520	09-015	Align Steering	15-Nov-2017 10:43:00	BVLOFC	O	DON	167.57
27-Feb-2018 1	94,444	0	325254	06-100-PMA	Inspect A PMI	27-Feb-2018 10:50:27	BVLOFC	P	DON	78.14
27-Feb-2018 1	94,444	0	325254	03-013	Replace Brakes	27-Feb-2018 11:01:49	BVLOFC	O	DON	1,136.28
27-Feb-2018 1	94,444	0	325254	03-016	Replace Suspension	27-Feb-2018 11:01:52	BVLOFC	O	DON	1,367.22
27-Feb-2018 1	94,444	0	325254	38-022-003	Service Differential Carrier	27-Feb-2018 11:00:47	BVLOFC	P	DON	274.72
27-Feb-2018 1	94,444	0	325254	03-032-001	Replace Battery	27-Feb-2018 10:56:03	BVLOFC	O	DON	206.61
27-Feb-2018 1	94,444	0	325254	03-045-026	Replace Tensioner - Engine Belts	27-Feb-2018 10:55:27	BVLOFC	I	DON	260.35
27-Feb-2018 1	94,444	0	325254	38-025-001	Service Transfer Case Assembly	27-Feb-2018 10:59:15	BVLOFC	P	DON	174.16
27-Feb-2018 1	94,444	0	325254	38-027	Service Transmission - Main, Automatic	27-Feb-2018 10:59:47	BVLOFC	P	DON	313.63
27-Feb-2018 1	94,444	0	325254	38-044	Service Fuel System	27-Feb-2018 10:51:39	BVLOFC	P	DON	230.07
27-Feb-2018 1	94,444	0	325254	38-013	Service Brakes	27-Feb-2018 11:01:32	BVLOFC	P	DON	234.54
27-Feb-2018 1	94,444	0	325254	03-002-035	Replace Windshield Wiper & Washer	27-Feb-2018 10:58:09	BVLOFC	O	DON	31.23
27-Feb-2018 1	94,444	0	325254	03-041-007	Replace Filter - Outer	27-Feb-2018 10:57:41	BVLOFC	P	DON	404.81
01-Jun-2018 1	102,322	0	338068	03-002-024	Replace Glass / Windshield	05-Jun-2018 13:01:38	BVLOFC	E	DON	290.49
07-Jun-2018 1	102,720	0	338896	03-015-004	Replace Steering Linkage	20-Jul-2018 14:07:15	BVLOFC	I	DON	2,362.01

Unit Job History

Michels Corporation
Report Printed: 15-Sep-2022 09:32:51 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2693 - 2014 F150 CREWCAB										
07-Jun-2018 1:	102,720	0	338896	06-100-PMA	Inspect A PMI	20-Jul-2018 14:07:12	BVLOFC	P	DON	117.92
17-Jan-2019 0:	116,554	0	368663	02-032-001	Clean Battery	23-Jan-2019 06:52:26	BTRUCK	I	DON	18.14
17-Jan-2019 0:	116,554	0	368663	31-017-001	Rotate Tire - Pneumatic	23-Jan-2019 09:22:49	BTRUCK	I	DON	47.77
17-Jan-2019 0:	116,554	0	368663	02-002	Clean Cab & Sheet Metal	28-Jan-2019 14:30:06	BSETUP	I	DON	69.62
17-Jan-2019 0:	116,554	0	368663	14-053-005	Install Markings - Vehicle - Decals	31-Jan-2019 13:39:19	BSETUP	I	DON	124.51
17-Jan-2019 0:	116,554	0	368663	03-002-035	Replace Windshield Wiper & Washer	23-Jan-2019 07:04:54	BTRUCK	I	DON	22.83
17-Jan-2019 0:	116,554	0	368663	03-013-034	Replace Parking Brake - Complete	24-Jan-2019 10:26:29	BTRUCK	I	DON	320.24
17-Jan-2019 0:	116,554	0	368663	38-045	Service Power Plant	23-Jan-2019 07:55:45	BTRUCK	P	DON	42.04
17-Jan-2019 0:	116,554	0	368663	06-100-009	Inspect Safety Check	17-Jan-2019 07:58:39	BTRUCK	P	DON	71.43
17-Jan-2019 0:	116,554	0	368663	03-034-002	Replace Stop, Tail, Turn & License	23-Jan-2019 07:04:23	BTRUCK	I	DON	91.18
17-Jan-2019 0:	116,554	0	368663	03-034-004	Replace Clearance & Marker Lamps	23-Jan-2019 06:19:22	BTRUCK	I	DON	17.07
17-Jan-2019 0:	116,554	0	368663	06-100-PMB	Inspect B PMI	23-Jan-2019 07:46:40	BTRUCK	P	DON	22.92
17-Jan-2019 0:	116,554	0	368663	24-002-024	Repair Glass / Windshield	18-Jan-2019 09:25:16	BTRUCK	I	DON	51.13
17-Jan-2019 0:	116,554	0	368663	14-078-014	Install Tarpaulin/ Tonneau Cover	01-Feb-2019 06:47:12	BSETUP	I	DON	53.28
17-Jan-2019 0:	116,554	0	368663	14-510-002	Install Tool Box	31-Jan-2019 11:59:44	BSETUP	I	DON	64.52
27-Feb-2019 1:	117,739	0	374332	03-042-004	Replace Water Pump	04-Mar-2019 14:22:01	WSHSHP	B	DON	238.08
23-May-2019 (	126,573	0	387047	03-017-001	Replace Tire - Pneumatic	23-May-2019 09:22:37	BVLOFC	O	DON	1,121.40
23-May-2019 (	126,573	0	387047	03-041-007	Replace Filter - Outer	23-May-2019 09:22:41	BVLOFC	P	DON	16.34
23-May-2019 (	126,573	0	387047	06-100-PMA	Inspect A PMI	23-May-2019 09:18:52	BVLOFC	P	DON	58.03
30-Jul-2019 07	137,321	0	396369	06-100-PMA	Inspect A PMI	30-Jul-2019 07:43:33	BTRUCK	P	DON	0.00
30-Jul-2019 07	137,321	0	396369	38-100-PMA	Service A PMI	30-Jul-2019 07:43:33	BVLOFC	P	DON	40.43
30-Oct-2019 1	139,967	0	410261	03-033-003	Replace Spark Plugs	04-Nov-2019 06:03:06	BVLOFC	O	DON	828.03
30-Oct-2019 1	139,967	0	410261	06-100-PMA	Inspect A PMI	04-Nov-2019 06:03:06	BVLOFC	P	DON	0.00
30-Oct-2019 1	139,967	0	410261	37-049-002	Calibrate ECM Module	04-Nov-2019 06:03:06	BVLOFC	I	DON	262.51
30-Oct-2019 1	139,967	0	410261	03-002-035	Replace Windshield Wiper & Washer	04-Nov-2019 06:03:06	BVLOFC	O	DON	57.99
30-Oct-2019 1	139,967	0	410261	03-013-001	Replace Front Brakes & Drums	04-Nov-2019 06:03:06	BVLOFC	I	DON	623.97
30-Oct-2019 1	139,967	0	410261	03-045-023	Replace Engine Belts	04-Nov-2019 06:03:06	BVLOFC	I	DON	179.46
30-Oct-2019 1	139,967	0	410261	03-002-024	Replace Glass / Windshield	04-Nov-2019 06:03:06	BVLOFC	O	DON	391.06
30-Oct-2019 1	139,967	0	410261	38-027-001	Service Case Assembly - Automatic Transmissi	04-Nov-2019 06:03:06	BVLOFC	P	DON	241.19

Unit Job History

Michels Corporation
Report Printed: 15-Sep-2022 09:32:51 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2693 - 2014 F150 CREWCAB										
30-Oct-2019 1	139,967	0	410261	38-100-PMA	Service A PMI	04-Nov-2019 06:03:06	BVLOFC	P	DON	74.69
17-Jun-2020 0	147,233	0	445934	03-063-003	Replace Transceiver - GPS Tracker	17-Jun-2020 06:54:24	ELEC01	Q	DON	232.36
27-Dec-2021 1	163,795		555799	03-002-035	Replace Windshield Wiper & Washer	28-Dec-2021 15:15:10	HARSHP	I	DON	24.95
27-Dec-2021 1	163,795		555799	03-002-047	Replace Vent Assembly	04-Jan-2022 13:36:54	HARSHP	I	DON	168.37
27-Dec-2021 1	163,795		555799	03-052-014	Replace Cellular Telephone Accessories	29-Dec-2021 07:10:35	HARSHP	I	DON	37.48
27-Dec-2021 1	163,795		555799	03-053-017	Replace First Aid Kit	05-Jan-2022 10:33:33	HARSHP	I	DON	94.59
27-Dec-2021 1	163,795		555799	03-021-108	Replace Pinion Seal	04-Jan-2022 13:14:16	HARSHP	I	DON	171.37
27-Dec-2021 1	163,795		555799	06-013-038	Inspect Caliper - Rear	28-Dec-2021 12:57:58	HARSHP	I	DON	19.81
27-Dec-2021 1	163,795		555799	03-051-009	Replace Fire Extinguisher	05-Jan-2022 09:43:35	HARSHP	I	DON	61.79
27-Dec-2021 1	163,795		555799	14-053-004	Install Safety Equipment	04-Jan-2022 14:48:30	HARSHP	I	DON	127.54
27-Dec-2021 1	163,795		555799	03-063-003	Replace Transceiver - GPS Tracker	29-Dec-2021 06:29:14	HARSHP	Q	DON	342.73
27-Dec-2021 1	163,795		555799	38-100-PMA	Service A PMI	28-Dec-2021 15:03:23	HARSHP	P	DON	144.31
27-Dec-2021 1	163,795		555799	03-032-001	Replace Battery	28-Dec-2021 13:15:54	HARSHP	I	DON	135.62
27-Dec-2021 1	163,795		555799	03-037-021	Replace Circuit Breaker/Fuse - Multiple Use	29-Dec-2021 08:27:32	HARSHP	I	DON	37.88
27-Dec-2021 1	163,795		555799	35-040	Diagnose Engine / Motor Systems Group	05-Jan-2022 08:55:27	HARSHP	I	DON	178.41
27-Dec-2021 1	163,795		555799	06-100-PMA	Inspect A PMI	28-Dec-2021 10:11:37	HARSHP	P	DON	127.21
27-Dec-2021 1	163,795		555799	14-053	Install Expendable Items	07-Jan-2022 14:06:49	HARSHP	I	DON	62.64
17-Feb-2022 0	163,795		568845	24-410-002	Repair Lights	13-May-2022 12:51:52	HARFLD	B	DON	189.74
23-Mar-2022 0	168,381		576619	38-100-PMA	Service A PMI	23-Mar-2022 07:12:29	BVLOFC	P	DON	51.09
23-Mar-2022 0	168,381		576619	03-013-002	Replace Rear Brakes & Drums	23-Mar-2022 07:12:29	BVLOFC	I	DON	706.93
23-Mar-2022 0	168,381		576619	09-015	Align Steering	23-Mar-2022 07:12:29	BVLOFC	I	DON	122.54
23-Mar-2022 0	168,381		576619	03-017-001	Replace Tire - Pneumatic	23-Mar-2022 07:12:29	BVLOFC	O	DON	1,015.92
23-Mar-2022 0	168,381		576619	06-100-PMA	Inspect A PMI	23-Mar-2022 07:12:29	BVLOFC	P	DON	0.00
29-Jul-2022 09	174,265		605919	06-100-PMA	Inspect A PMI	29-Jul-2022 11:57:46	HARSHP	P	DON	61.72
29-Jul-2022 09	174,265		605919	OS-010-001	Out-Service All Axles	02-Aug-2022 12:40:34	HARSHP	Z	DON	49.94
13-Sep-2022 0	174,265		615838	25-051	Remove General Accessories	13-Sep-2022 12:05:41	BSETUP	Z	DON	168.31
13-Sep-2022 0	174,265		615838	02-002	Clean Cab & Sheet Metal	14-Sep-2022 10:12:07	BSETUP	Z	DON	86.81
						Unit No: B2693		**Count: 143**		**24,250.43**