Unit Job History

Michels Corporation

Report Printed: 13-Dec-2022 09:15:28 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Z0929 - 2013 VERMEER V800LE										
21-Mar-2013 1	1	0	111696	14-063-003	Install Transceiver - GPS Tracker	25-Apr-2013 08:15:38	BSMEQP	J	DON	481.42
21-Mar-2013 1	1	0	111696	14-079-009	Install Tape - Reflective, Conspicuity	27-Mar-2013 17:06:40	BTRLR	C	DON	26.88
21-Mar-2013 1	1	0	111696	06-100-001	Inspect DO NOT USE - PMI Service	28-Mar-2013 09:47:26	BTRLR	C	DON	10.45
21-Mar-2013 1	1	0	111696	03-059-011	Replace Hook - Safety Chain	27-Mar-2013 15:21:27	BTRLR	C	DON	95.29
21-Mar-2013 1	1	0	111696	03-034-008	Replace Trailer Light Cord	27-Mar-2013 16:23:33	BTRLR	C	DON	66.26
21-Mar-2013 1	1	0	111696	03-018-012	Replace Cap - Hub	28-Mar-2013 07:00:04	BTRLR	C	DON	59.47
21-Mar-2013 1	1	0	111696	14-034-002	Install Stop, Tail, Turn & License	28-Mar-2013 09:40:22	BTRLR	C	DON	107.78
04-Nov-2013 0	532	0	139339	03-063-003	Replace Transceiver - GPS Tracker	04-Nov-2013 00:00:00	BDDRIL	C	DON	244.35
04-Mar-2014 0	532	0	151432	07-100-000	Lubricate On Road Equip / Field Service	04-Mar-2014 17:00:00	LAKEVL	P	DON	21.01
04-Mar-2014 0	532	0	151432	06-100-PMA	Inspect A PMI	04-Mar-2014 17:00:00	LAKEVL	P	DON	21.01
05-Mar-2014 0	532	0	151688	06-100-DOT	Inspect DOT Federal Inspection	05-Mar-2014 17:00:00	LAKEVL	P	DON	73.65
11-Feb-2015 0	532	0	194138	06-100-DOT	Inspect DOT Federal Inspection	11-Feb-2015 17:00:00	LAKEVL	P	DON	21.01
04-May-2015 1	532	0	203656	03-098	Replace Valves & Controls - Bulk Product Tran	04-May-2015 14:50:43	LAVOFC	B	DON	92.72
16-Jun-2015 0	532	0	204661	03-017-001	Replace Tire - Pneumatic	16-Jun-2015 07:09:05	BTIRE	F	DON	365.38
08-Jul-2015 15	532	0	207036	03-707	Replace Swivel		BDDRIL	O	CAN	0.00
08-Jul-2015 15	532	0	207036	03-708	Replace Drilling Sub / Monel		BDDRIL	O	CAN	0.00
08-Jul-2015 15	532	0	207036	18-704	Test Drill Rig		BDDRIL	J	CAN	0.00
08-Jul-2015 15	532	0	207036	03-065	Replace Hydraulic Systems - Special Applicatio		BDDRIL	J	CAN	0.00
08-Jul-2015 15	532	0	207036	24-518	Repair Step / Ladder / Catwalk		BDDRIL	J	CAN	0.00
08-Jul-2015 15	532	0	207036	03-704-002	Replace Guide Rollers		BDDRIL	O	CAN	0.00
08-Jul-2015 15	532	0	207036	19-704	Wire/Rewire Drill Rig		BDDRIL	J	CAN	0.00
08-Jul-2015 15	532	0	207036	24-705	Repair Vise		BDDRIL	O	CAN	0.00
08-Jul-2015 15	532	0	207036	03-706-006	Replace Hydraulic Hoses and Lines		BDDRIL	O	CAN	0.00
04-Feb-2016 1		0	232183	06-100-PMA	Inspect A PMI	11-Feb-2016 09:23:13	LAVSHP	I	DON	286.01
04-Feb-2016 1		0	232183	03-406	Replace Pressure Washer	11-Feb-2016 09:27:56	LAVSHP	I	DON	226.44
04-Feb-2016 1		0	232183	03-078-009	Replace Mud Flaps and Hanger Brackets	09-Feb-2016 16:48:06	LAVSHP	I	DON	19.29
04-Feb-2016 1		0	232183	24-077-009	Repair Spring Hangers	09-Feb-2016 16:14:08	LAVSHP	I	DON	16.37
04-Feb-2016 1		0	232183	03-013-036	Replace Trailer Brakes and Drums	09-Feb-2016 15:45:40	LAVSHP	I	DON	16.19
04-Feb-2016 1		0	232183	03-065-007	Replace Hoses & Fittings	16-Feb-2016 16:41:27	LAVSHP	I	DON	53.87

Unit Job History

Michels Corporation

Report Printed: 13-Dec-2022 09:15:28 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Z0929 - 2013 VERMEER V800LE										
04-Feb-2016 1		0	232183	06-100-DOT	Inspect DOT Federal Inspection	16-Feb-2016 17:34:53	LAVSHP	P	DON	56.69
08-Sep-2016 0	594	0	260877	24-077-021	Repair Jack - Leveling	08-Sep-2016 07:00:00	LAVSHP	P	DON	22.36
08-Sep-2016 0	594	0	260877	11-016-022	Rebuild Equalizer & Mounting Assy	08-Sep-2016 07:00:00	LAVSHP	P	DON	44.71
30-Nov-2016 0	594	0	268217	03-017-001	Replace Tire - Pneumatic	30-Nov-2016 06:51:26	BTIRE	F	DON	236.77
13-Jan-2017 0	594	0	273149	24-013-012	Repair Electric Brakes		LAVSHP	I	CAN	0.00
13-Jan-2017 0	594	0	273149	38-100-PMA	Service A PMI		LAVSHP	I	CAN	0.00
13-Jan-2017 0	594	0	273149	24-002-002	Repair Fenders		LAVSHP	I	CAN	0.00
09-Feb-2017 0	650	0	276685	06-100-DOT	Inspect DOT Federal Inspection	09-Feb-2017 11:07:11	LAVSHP	P	DON	36.62
09-Feb-2017 0	650	0	276685	06-100-PMB	Inspect B PMI	09-Feb-2017 11:35:29	LAVSHP	I	DON	16.31
30-Mar-2017 1	650	0	283287	19-034-004	Wire/Rewire Clearance & Marker Lamps		ROGSHP	B	CAN	0.00
30-Mar-2017 1	650	0	283287	03-033-001	Replace Ignition Switch		ROGSHP	B	CAN	0.00
17-Jul-2017 16	650	0	297087	03-049-204	Replace LMI Sensor	18-Jul-2017 11:45:53	ROGSHP	B	DON	80.58
25-Sep-2017 1	708	0	306286	03-013-021	Replace Break Away Switch	25-Sep-2017 11:36:16	ROGSHP	B	DON	12.70
25-Sep-2017 1	708	0	306286	19-034-008	Wire/Rewire Trailer Light Cord	25-Sep-2017 12:03:55	ROGSHP	B	DON	37.91
20-Feb-2018 1	719	0	324327	03-506	Replace Tank	21-Feb-2018 09:03:24	LAVSHP	I	DON	45.97
20-Feb-2018 1	719	0	324327	24-034-006	Repair Warning Lamps - Special Application	21-Feb-2018 07:49:10	LAVSHP	I	DON	109.39
20-Feb-2018 1	719	0	324327	06-100-DOT	Inspect DOT Federal Inspection	20-Feb-2018 13:50:45	LAVSHP	P	DON	49.04
20-Feb-2018 1	719	0	324327	06-100-PMA	Inspect A PMI	21-Feb-2018 08:45:32	LAVSHP	P	DON	64.43
17-Jul-2018 11	800	0	344068	03-707	Replace Swivel	17-Jul-2018 13:42:04	ROGSHP	N	DON	161.06
17-Dec-2018 0	800	0	364826	03-017-001	Replace Tire - Pneumatic	17-Dec-2018 15:22:45	LAVSHP	I	DON	319.06
17-Dec-2018 0	800	0	364826	06-100-DOT	Inspect DOT Federal Inspection	17-Dec-2018 15:37:39	LAVSHP	P	DON	57.18
17-Dec-2018 0	800	0	364826	06-100-PMA	Inspect A PMI	18-Dec-2018 07:50:35	LAVSHP	P	DON	334.71
15-Apr-2019 1		0	381261	03-034-011	Replace Plug - Trailer Light Cord	15-Apr-2019 15:26:25	ROGSHP	N	DON	21.57
16-Apr-2019 1	815	0	381466	03-053-008	Replace Hoses & Tubings & Fittings	17-Apr-2019 09:37:16	ROGSHP	N	DON	352.06
16-Apr-2019 1	815	0	381466	03-079-009	Replace Tape - Reflective, Conspicuity	17-Apr-2019 11:00:21	ROGSHP	I	DON	20.44
16-Apr-2019 1	815	0	381466	03-098	Replace Valves & Controls - Bulk Product Tran	17-Apr-2019 10:23:42	ROGSHP	B	DON	91.46
02-Jul-2019 11	886		392764	03-053-008	Replace Hoses & Tubings & Fittings	02-Jul-2019 13:06:40	ROGSHP	N	DON	114.05
02-Jul-2019 11	886		392764	03-511-002	Replace Reel Stand	02-Jul-2019 11:57:44	ROGSHP	N	DON	138.54
02-Jul-2019 11	886		392764	03-034-011	Replace Plug - Trailer Light Cord	02-Jul-2019 12:45:27	ROGSHP	N	DON	26.23

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Z0929 - 2013 VERMEER V800LE										
31-Oct-2019 1:	885		410494	19-034-012	Wire/Rewire Box - Junction	31-Oct-2019 18:02:57	ROGSHP	I	DON	65.71
31-Oct-2019 1:	885		410494	24-077-021	Repair Jack - Leveling	05-Nov-2019 11:14:57	ROGSHP	E	DON	175.18
20-Dec-2019 0	925		417850	06-100-DOT	Inspect DOT Federal Inspection	02-Jan-2020 06:14:36	LAVSHP	P	DON	76.21
20-Dec-2019 0	925		417850	07-018	Lubricate Wheels, Rims, Hubs & Bearings	20-Dec-2019 11:46:49	LAVSHP	P	DON	192.71
20-Dec-2019 0	925		417850	03-017-001	Replace Tire - Pneumatic	21-Dec-2019 13:16:00	LAVSHP	I	DON	852.26
07-Apr-2020 1	925		434831	03-065-006	Replace Filters, Strainers, Screens & Housing	08-Apr-2020 07:50:27	ME1371	O	DON	56.78
07-Apr-2020 1	925		434831	03-032-001	Replace Battery	07-Apr-2020 14:21:48	ME1371	O	DON	202.10
26-Jun-2020 1(	925		447737	03-053-013	Replace Permit Holder	26-Jun-2020 16:14:11	ROGSHP	I	DON	10.88
26-Jun-2020 1(	925		447737	03-065-026	Replace Regulator Valve	30-Jun-2020 13:33:20	ROGSHP	I	DON	383.75
26-Jun-2020 1(	925		447737	26-002-034	Weld Exterior Body Ornamentation	30-Jun-2020 16:01:14	ROGSHP	I	DON	78.81
26-Jun-2020 1(	925		447737	01-013-012	Adjust Electric Brakes	26-Jun-2020 16:04:34	ROGSHP	O	DON	10.43
26-Jun-2020 1(	925		447737	03-003-001	Replace Gauges & Warning Devices	26-Jun-2020 15:50:03	ROGSHP	I	DON	113.11
26-Jun-2020 1(	925		447737	06-097	Inspect Pump - Product Transfer	30-Jun-2020 14:36:56	ROGSHP	O	DON	112.09
26-Jun-2020 1(	925		447737	03-071-005	Replace Side Door Assembly - Hinged	30-Jun-2020 16:17:27	ROGSHP	I	DON	23.81
26-Jun-2020 1(	925		447737	03-097	Replace Pump - Product Transfer	29-Jun-2020 11:44:53	ROGSHP	I	DON	1,344.45
17-Aug-2020 1	930		456451	24-034-004	Repair Clearance & Marker Lamps	17-Aug-2020 11:51:18	ROGSHP	O	DON	17.93
25-Aug-2020 1	933		457971	01-013-012	Adjust Electric Brakes	25-Aug-2020 13:20:50	ROGSHP	O	DON	19.93
09-Feb-2021 1'	935		487205	38-100-PMA	Service A PMI	10-Feb-2021 12:06:08	TRK400	I	DON	455.40
09-Feb-2021 1'	935		487205	03-034-014	Replace Auxiliary Work / Flood Light	10-Feb-2021 13:48:03	TRK400	I	DON	190.23
09-Feb-2021 1'	935		487205	06-034-014	Inspect Auxiliary Work / Flood Light	10-Feb-2021 13:06:59	TRK400	I	DON	49.23
09-Feb-2021 1'	935		487205	06-100-DOT	Inspect DOT Federal Inspection	10-Feb-2021 07:25:41	TRK400	P	DON	185.33
09-Feb-2021 1'	935		487205	06-100-PMA	Inspect A PMI	10-Feb-2021 08:39:24	TRK400	P	DON	119.70
09-Feb-2021 1'	935		487205	03-032-001	Replace Battery	10-Feb-2021 09:58:27	TRK400	I	DON	258.87
23-Feb-2021 1'	935		489906	03-506-004	Replace Reservoir Tank	23-Feb-2021 18:05:22	TRK400	I	DON	82.63
23-Feb-2021 1'	935		489906	06-016-022	Inspect Equalizer & Mounting Assy	24-Feb-2021 08:21:02	TRK400	P	DON	74.59
08-Apr-2021 1	935		499357	03-098-002	Replace Butterfly Valve Assembly	08-Apr-2021 16:59:37	ROGSHP	I	DON	284.95
08-Apr-2021 1	935		499357	06-098-002	Inspect Butterfly Valve Assembly	08-Apr-2021 15:31:47	ROGSHP	I	DON	16.19
10-May-2021 1	935		505790	03-065-026	Replace Regulator Valve	25-May-2021 16:25:54	ROGSHP	N	DON	550.43
10-May-2021 1	935		505790	03-097	Replace Pump - Product Transfer	11-May-2021 16:20:20	ROGSHP	I	DON	161.93

Unit Job History

Michels Corporation

Report Printed: 13-Dec-2022 09:15:28 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Z0929 - 2013 VERMEER V800LE										
10-May-2021 1	935		505790	03-098-007	Replace One-Way Check Valve Assembly	10-May-2021 18:15:55	ROGSHP	I	DON	48.09
10-May-2021 1	935		505790	24-053-008	Repair Hoses & Tubings & Fittings	24-May-2021 16:52:16	ROGSHP	I	DON	144.35
10-May-2021 1	935		505790	03-003-001	Replace Gauges & Warning Devices	10-May-2021 17:46:15	ROGSHP	I	DON	65.03
01-Jun-2021 0	935		509911	01-013	Adjust Brakes		LAVSHP	O	CAN	0.00
01-Jun-2021 0	935		509911	03-072-006	Replace Door Latch Mechanism		LAVSHP	B	CAN	0.00
28-Mar-2022 1	935		577665	03-018-012	Replace Cap - Hub	28-Mar-2022 13:52:21	OTSSHP	I	DON	147.68
28-Mar-2022 1	935		577665	24-034-008	Repair Trailer Light Cord	28-Mar-2022 13:27:32	OTSSHP	I	DON	41.65
28-Mar-2022 1	935		577665	03-032-001	Replace Battery	28-Mar-2022 11:06:47	OTSSHP	I	DON	114.71
28-Mar-2022 1	935		577665	06-100-DOT	Inspect DOT Federal Inspection	28-Mar-2022 12:30:42	OTSSHP	P	DON	26.53
28-Mar-2022 1	935		577665	03-051-006	Replace Safety Devices	28-Mar-2022 11:27:51	OTSSHP	I	DON	173.64
28-Mar-2022 1	935		577665	03-063-003	Replace Transceiver - GPS Tracker	28-Mar-2022 10:45:58	OTSSHP	Q	DON	291.70
08-Dec-2022 0			637797	02-506-005	Clean Retention Tank		BVLYRD	E	WND	127.45
12-Dec-2022 0			638477	18-165-001	Test Vacuum Assembly	12-Dec-2022 08:44:14	BSDRIL	I	DON	120.48
12-Dec-2022 0			638477	25-053-005	Remove Markings - Vehicle - Decals	12-Dec-2022 12:05:02	BSDRIL	Z	DON	73.27
12-Dec-2022 0			638477	25-063-003	Remove Transceiver - GPS Tracker	12-Dec-2022 10:21:28	BSDRIL	Z	DON	68.79
12-Dec-2022 0			638477	03-P01-004	Replace Water	12-Dec-2022 13:49:09	BSDRIL	Z	DON	78.34
12-Dec-2022 0			638477	26-077-021	Weld Jack - Leveling	12-Dec-2022 16:00:01	BSDRIL	Z	DON	92.59

Unit No: Z0929 **Count: 104** **12,534.63**