Unit Job History

Michels Corporation

Report Printed: 04-May-2023 09:44:28 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: D1005 - 1999 TRAILKING TK12U										
03-Mar-2009 0	0	0	9937	03-018-011	Replace Seal - Wheel	03-Mar-2009 10:45:11	BTRLR	I	DON	45.60
03-Mar-2009 0	0	0	9937	06-100-002	Inspect DO NOT USE - DOT Federal Insp	03-Mar-2009 12:04:07	BTRLR	J	DON	137.85
03-Mar-2009 0	0	0	9937	24-071-001	Repair Floor / Decking / Flatbed	03-Mar-2009 09:00:00	BTRLR	I	DON	47.76
08-Apr-2010 0	0	0	37967	03-013-012	Replace Electric Brakes	08-Apr-2010 14:20:22	BTRLR	I	DON	338.13
08-Apr-2010 0	0	0	37967	03-017-001	Replace Tire - Pneumatic	08-Apr-2010 14:25:23	BTIRE	I	DON	189.98
08-Apr-2010 0	0	0	37967	03-034-012	Replace Box - Junction	09-Apr-2010 05:45:36	BTRLR	I	DON	44.88
08-Apr-2010 0	0	0	37967	03-055-008	Replace Ramp Assembly	09-Apr-2010 08:06:32	BTRLR	I	DON	53.33
08-Apr-2010 0	0	0	37967	03-077-003	Replace Leg Assembly / Landing Gear	09-Apr-2010 12:18:26	BTRLR	I	DON	68.63
08-Apr-2010 0	0	0	37967	03-013-020	Replace Break Away Battery	09-Apr-2010 05:46:20	BTRLR	I	DON	70.65
08-Apr-2010 0	0	0	37967	06-100-002	Inspect DO NOT USE - DOT Federal Insp	01-May-2010 12:00:06	BTRLR	J	DON	29.87
08-Apr-2010 0	0	0	37967	24-071-001	Repair Floor / Decking / Flatbed	01-May-2010 11:12:11	BTRLR	I	DON	207.92
08-Apr-2010 0	0	0	37967	24-077-004	Repair Frame Assembly - Front	08-Apr-2010 15:00:00	BTRLR	I	DON	61.82
08-Apr-2010 0	0	0	37967	12-071	Refinish Body	28-Apr-2010 15:00:00	BBODY	K	DON	375.50
08-Apr-2010 0	0	0	37967	14-053-005	Install Markings - Vehicle - Decals	01-May-2010 07:56:22	BTRLR	Q	DON	88.80
08-Apr-2010 0	0	0	37967	15-071	Paint Prep Body	29-Apr-2010 08:41:38	BTRLR	I	DON	537.68
08-Apr-2010 0	0	0	37967	06-100-001	Inspect DO NOT USE - PMI Service	09-Apr-2010 08:05:41	BTRLR	P	DON	99.69
08-Apr-2010 0	0	0	37967	19-034	Wire/Rewire Lighting System	01-May-2010 05:33:54	BTRLR	Q	DON	134.64
09-Feb-2011 0	0	0	58277	06-100-002	Inspect DO NOT USE - DOT Federal Insp	09-Feb-2011 14:21:22	BTRLR	P	DON	50.74
09-Feb-2011 0	0	0	58277	03-018-011	Replace Seal - Wheel	09-Feb-2011 10:55:28	BTRLR	P	DON	50.97
09-Feb-2011 0	0	0	58277	03-059-011	Replace Hook - Safety Chain	09-Feb-2011 12:15:33	BTRLR	I	DON	12.40
09-Feb-2011 0	0	0	58277	06-100-001	Inspect DO NOT USE - PMI Service	09-Feb-2011 14:29:47	BTRLR	P	DON	139.08
22-Jun-2012 1	0	0	91497	24-063	Repair Satellite Communications System	22-Jun-2012 15:03:31	BTRLR	J	DON	0.00
04-Jul-2014 07	0	0	174515	06-100-CVI	Inspect CVIP Inspection	04-Jul-2014 17:00:00	NISKU	P	DON	1,041.96
09-Aug-2014 0	0	0	168646	03-063-003	Replace Transceiver - GPS Tracker	09-Aug-2014 00:00:00	BTRLR	C	DON	316.98
24-Mar-2015 0	0	0	197839	21-077-003	Fabricate Leg Assembly / Landing Gear	29-Jun-2015 16:14:13	NISKU	B	DON	137.85
24-Mar-2015 0	0	0	197839	06-100-CVI	Inspect CVIP Inspection	10-Apr-2015 16:48:09	NISKU	P	DON	1,984.96
07-Oct-2015 1	0	0	217573	03-013-020	Replace Break Away Battery	08-Oct-2015 10:58:22	BTRLR	I	DON	93.51
07-Oct-2015 1	0	0	217573	03-059-008	Replace Tow Ring Assembly	08-Oct-2015 14:46:53	BTRLR	I	DON	157.54
07-Oct-2015 1	0	0	217573	03-055-008	Replace Ramp Assembly	08-Oct-2015 15:30:50	BTRLR	O	DON	1,503.68

Unit Job History

Michels Corporation

Report Printed: 04-May-2023 09:44:28 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: D1005 - 1999 TRAILKING TK12U										
07-Oct-2015 1(	0	0	217573	03-059-011	Replace Hook - Safety Chain	08-Oct-2015 12:00:29	BTRLR	I	DON	154.02
07-Oct-2015 1(	0	0	217573	06-100-DOT	Inspect DOT Federal Inspection	08-Oct-2015 16:11:10	BTRLR	P	DON	66.58
07-Oct-2015 1(	0	0	217573	06-100-PMA	Inspect A PMI	08-Oct-2015 17:09:32	BTRLR	P	DON	61.90
07-Oct-2015 1(	0	0	217573	24-063-003	Repair Transceiver - GPS Tracker	08-Oct-2015 09:43:21	BTRLR	Q	DON	771.22
07-Oct-2015 1(	0	0	217573	03-034-011	Replace Plug - Trailer Light Cord	08-Oct-2015 11:36:40	BTRLR	I	DON	37.64
18-Mar-2016 1	0	0	238155	01-034-002	Adjust Stop, Tail, Turn & License	19-Mar-2016 06:23:13	BTRLR	I	DON	120.05
18-Mar-2016 1	0	0	238155	06-100-DOT	Inspect DOT Federal Inspection		BTRLR	P	CAN	0.00
18-Mar-2016 1	0	0	238155	03-077-003	Replace Leg Assembly / Landing Gear	18-Mar-2016 15:34:42	BTRLR	O	DON	93.99
18-Mar-2016 1	0	0	238155	06-100-PMA	Inspect A PMI		BTRLR	P	CAN	0.00
05-Jul-2016 15	0	0	250736	03-017-001	Replace Tire - Pneumatic	06-Jul-2016 12:00:30	BTIRE	I	DON	1,203.67
05-Jul-2016 15	0	0	250736	03-018-005	Replace Bearings - General	06-Jul-2016 10:50:10	BTRLR	O	DON	79.71
05-Jul-2016 15	0	0	250736	24-059-006	Repair Towing Hitch Assembly	06-Jul-2016 07:08:12	BTRLR	O	DON	11.17
03-Nov-2016 1	0	0	265465	03-018-011	Replace Seal - Wheel	03-Nov-2016 14:33:18	BTRLR	I	DON	459.05
03-Nov-2016 1	0	0	265465	06-100-DOT	Inspect DOT Federal Inspection	03-Nov-2016 14:33:03	BTRLR	P	DON	169.50
03-Nov-2016 1	0	0	265465	06-100-PMA	Inspect A PMI	03-Nov-2016 14:33:11	BTRLR	P	DON	44.94
03-Nov-2016 1	0	0	265465	26-002-002	Weld Fenders	03-Nov-2016 14:33:24	BTRLR	I	DON	134.00
24-Jul-2018 00	0	0	345470	24-MSC	Repair Miscellanous	24-Jul-2018 00:00:00	BVLOFC	I	DON	303.48
24-Jul-2018 00	0	0	345470	06-100-DOT	Inspect DOT Federal Inspection	24-Jul-2018 00:00:00	BVLOFC	P	DON	84.27
28-May-2019 (	0	0	387945	06-100-DOT	Inspect DOT Federal Inspection	23-Aug-2019 15:36:20	BVLOFC	P	DON	87.73
28-May-2019 (	0	0	387945	24-MSC	Repair Miscellanous	23-Aug-2019 15:36:17	BVLOFC	I	DON	907.75
06-Jan-2020 0(			419428	06-100-DOT	Inspect DOT Federal Inspection	06-Jan-2020 00:00:00	BVLOFC	P	DON	95.24
06-Jan-2020 0(			419428	24-MSC	Repair Miscellanous	06-Jan-2020 00:00:00	BVLOFC	I	DON	749.64
07-Dec-2020 1			476620	03-063-008	Replace Transceiver - GPS Grade Control	14-Dec-2020 08:00:00	FKVSHP	B	DON	435.36
07-Dec-2020 1			476620	06-100-DOT	Inspect DOT Federal Inspection	11-Dec-2020 12:00:00	FKVSHP	P	DON	104.61
16-Sep-2021 0			531930	19-034-002	Wire/Rewire Stop, Tail, Turn & License	16-Sep-2021 15:00:00	FKVSHP	B	DON	540.51
30-Mar-2022 0			578297	06-018	Inspect Wheels, Rims, Hubs & Bearings	21-Apr-2022 08:55:17	FKVFLD	I	DON	99.15
30-Mar-2022 0			578297	06-100-PMA	Inspect A PMI	21-Apr-2022 08:50:23	FKVFLD	P	DON	0.00
30-Mar-2022 0			578297	24-013-021	Repair Break Away Switch	21-Apr-2022 08:53:22	FKVFLD	I	DON	255.32
30-Mar-2022 0			578297	24-071-001	Repair Floor / Decking / Flatbed	21-Apr-2022 08:54:43	FKVFLD	I	DON	70.67

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: D1005 - 1999 TRAILKING TK12U										
30-Mar-2022 0			578297	24-077-021	Repair Jack - Leveling	21-Apr-2022 08:55:38	FKVFLD	I	DON	143.41
30-Mar-2022 0			578297	38-100-PMA	Service A PMI	21-Apr-2022 08:50:42	FKVFLD	P	DON	44.56
30-Mar-2022 0			578297	03-059-002	Replace Pintle Hook Assembly	21-Apr-2022 08:54:57	FKVFLD	I	DON	262.83
30-Mar-2022 0			578297	03-059-010	Replace Safety Chains	21-Apr-2022 08:56:56	FKVFLD	I	DON	118.06
30-Mar-2022 0			578297	06-100-DOT	Inspect DOT Federal Inspection	21-Apr-2022 08:50:27	FKVFLD	P	DON	89.12
30-Mar-2022 0			578297	95-034-002	Travel Stop, Tail, Turn & License	21-Apr-2022 08:50:56	FKVFLD	B	DON	833.30
30-Mar-2022 0			578297	19-034-002	Wire/Rewire Stop, Tail, Turn & License	21-Apr-2022 08:50:53	FKVFLD	B	DON	146.15
29-Jun-2022 1			600240	03-077-029	Replace Mount - Landing Gear	01-Nov-2022 13:12:38	FKVFLD	I	DON	1,139.22
29-Jun-2022 1			599458	03-077-029	Replace Mount - Landing Gear		FKVFLD	I	CAN	0.00
19-Apr-2023 1			668463	03-034-011	Replace Plug - Trailer Light Cord	02-May-2023 13:33:45	BTRLR	Z	DON	35.23
19-Apr-2023 1			668463	06-100-PMA	Inspect A PMI	02-May-2023 14:37:04	BTRLR	P	DON	193.69
19-Apr-2023 1			668463	25-053-005	Remove Markings - Vehicle - Decals	02-May-2023 12:51:33	BTRLR	Z	DON	43.58
19-Apr-2023 1			668463	25-063-003	Remove Transceiver - GPS Tracker	02-May-2023 12:48:28	BTRLR	Z	DON	6.57
19-Apr-2023 1			668463	35-013-020	Diagnose Break Away Battery	02-May-2023 13:57:15	BTRLR	Z	DON	14.57

Unit No: D1005 **Count: 72** **18,233.86**