

# Unit Job History

Michels Corporation  
Report Printed: 02-Mar-2021 08:33:17 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Z0845 - 2011 VERMEER V500LE										
07-Apr-2011 1	0	0	62898	03-018-012	Replace Cap - Hub	08-Apr-2011 09:00:00	BTRLR	C	DON	39.18
07-Apr-2011 1	0	0	62898	03-059-011	Replace Hook - Safety Chain	08-Apr-2011 08:12:32	BTRLR	C	DON	80.92
07-Apr-2011 1	0	0	62898	06-100-001	Inspect DO NOT USE - PMI Service	08-Apr-2011 08:58:21	BTRLR	C	DON	77.63
07-Apr-2011 1	0	0	62898	06-100-002	Inspect DO NOT USE - DOT Federal Insp	08-Apr-2011 13:14:23	BTRLR	C	DON	30.12
07-Apr-2011 1	0	0	62898	14-053-013	Install Permit Holder	08-Apr-2011 10:51:16	BTRLR	C	DON	13.27
07-Apr-2011 1	0	0	62898	14-079-009	Install Tape - Reflective, Conspicuity	08-Apr-2011 10:37:55	BTRLR	C	DON	10.24
07-Apr-2011 1	0	0	62898	19-034-008	Wire/Rewire Trailer Light Cord	08-Apr-2011 11:50:05	BTRLR	C	DON	32.95
07-Apr-2011 1	0	0	62898	21-053-101	Fabricate License Plate	08-Apr-2011 10:19:38	BTRLR	C	DON	77.67
21-Nov-2011 C	243	77	76934	06-100-001	Inspect DO NOT USE - PMI Service	29-Nov-2011 14:44:18	BSMEOQ	J	DON	255.43
20-Mar-2012 1	0	0	84184	06-100-001	Inspect DO NOT USE - PMI Service	21-Mar-2012 08:35:16	BSMEOQ	P	DON	871.39
20-Mar-2012 1	0	0	84184	06-100-002	Inspect DO NOT USE - DOT Federal Insp	21-Mar-2012 07:45:27	BTRLR	P	DON	16.76
15-Aug-2012 1	0	0	94360	24-017-001	Repair Tire - Pneumatic	20-Aug-2012 08:36:37	BTIRE	F	DON	52.92
05-Nov-2012 C	0	0	100099	02-071	Clean Body	05-Nov-2012 15:00:00	BWASH	J	DON	101.65
05-Nov-2012 C	0	0	100099	06-100-001	Inspect DO NOT USE - PMI Service	07-Nov-2012 16:22:57	BSMEOQ	J	DON	633.00
19-Jan-2013 0:	0	0	105191	02-165	Clean Vacuum	21-Jan-2013 07:56:15	BWASH	J	DON	45.43
19-Jan-2013 0:	0	0	105191	14-041	Install Air Intake System	01-Feb-2013 15:20:27	BSMEOQ	M	DON	484.74
19-Jan-2013 0:	0	0	105191	24-063-003	Repair Transceiver - GPS Tracker	24-Jan-2013 12:54:59	BDDRIL	J	DON	0.00
19-Jan-2013 0:	0	0	105191	38-100-001	Service DO NOT USE - PMI Service	01-Feb-2013 15:20:27	BSMEOQ	S	DON	426.21
28-Feb-2013 1:	253	0	109670	03-013-021	Replace Break Away Switch	01-Mar-2013 12:44:26	BTRLR	I	DON	26.21
28-Feb-2013 1:	253	0	109670	03-017-001	Replace Tire - Pneumatic	01-Mar-2013 12:55:16	BTRLR	I	DON	659.39
28-Feb-2013 1:	253	0	109670	03-034-008	Replace Trailer Light Cord	01-Mar-2013 10:52:42	BTRLR	I	DON	168.65
28-Feb-2013 1:	253	0	109670	03-079-009	Replace Tape - Reflective, Conspicuity	01-Mar-2013 12:00:05	BTRLR	I	DON	28.31
28-Feb-2013 1:	253	0	109670	06-100-001	Inspect DO NOT USE - PMI Service	01-Mar-2013 14:10:55	BTRLR	P	DON	62.94
28-Feb-2013 1:	253	0	109670	06-100-002	Inspect DO NOT USE - DOT Federal Insp	01-Mar-2013 13:16:35	BTRLR	P	DON	12.59
28-Feb-2013 1:	253	0	109670	21-002-006	Fabricate Roof Panel & Reinforcements	21-Mar-2013 10:42:36	BSMEOQ	P	DON	79.59
28-Feb-2013 1:	253	0	109670	26-165-006	Weld Filter Canister	21-Mar-2013 10:43:02	BSMEOQ	I	DON	278.49
28-Feb-2013 1:	253	0	109670	38-100-001	Service DO NOT USE - PMI Service	28-Feb-2013 14:20:15	BSMEOQ	J	DON	243.44
13-Sep-2013 0	253	0	130584	24-165	Repair Vacuum	07-Nov-2013 12:41:45	BSMEOQ	O	DON	337.02
07-Nov-2013 1	253	0	136262	02-056	Clean Power Take Off	30-Dec-2013 10:55:33	BWASH	J	DON	47.23

# Unit Job History

Michels Corporation  
Report Printed: 02-Mar-2021 08:33:17 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost	
Unit No: Z0845 - 2011 VERMEER V500LE											
07-Nov-2013	1	253	0	136262	38-165-001	Service Vacuum Assembly	07-Jan-2014 13:37:32	BSMEQP	O	DON	1,401.83
07-Nov-2013	1	253	0	136262	03-063-003	Replace Transceiver - GPS Tracker	07-Jan-2014 18:04:32	BDDRIL	C	DON	510.69
07-Nov-2013	1	253	0	136262	19-030	Wire/Rewire Electrical Group	10-Jan-2014 14:21:32	BSMEQP	O	DON	210.40
10-Dec-2013	1	253	0	140299	03-712-002	Replace Belts / Drive System	10-Dec-2013 15:29:46	MPNSHP	B	DON	33.87
10-Dec-2013	1	253	0	140299	24-066-007	Repair Doors - Engine Compartment	10-Dec-2013 15:29:31	MPNSHP	B	DON	4,907.37
10-Dec-2013	1	253	0	139570	06-100-DOT	Inspect DOT Federal Inspection	11-Dec-2013 15:37:16	MPNSHP	J	DON	54.71
17-Dec-2013	0	521	0	140575	03-034-011	Replace Plug - Trailer Light Cord	17-Dec-2013 07:49:02	MPNSHP	B	DON	33.88
19-Dec-2013	0	536	0	142449	24-077-003	Repair Leg Assembly	19-Dec-2013 08:26:33	MPNSHP	B	DON	50.87
17-Feb-2014	1	546	0	147051	03-016-022	Replace Equalizer & Mounting Assy	10-Mar-2014 11:07:38	BTRLR	I	DON	221.91
17-Feb-2014	1	546	0	147051	03-079-009	Replace Tape - Reflective, Conspicuity	10-Mar-2014 06:21:46	BTRLR	I	DON	31.32
17-Feb-2014	1	546	0	147051	06-100-DOT	Inspect DOT Federal Inspection	10-Mar-2014 12:00:05	BTRLR	P	DON	18.31
17-Feb-2014	1	546	0	147051	06-100-PMA	Inspect A PMI	10-Mar-2014 13:33:38	BTRLR	P	DON	95.11
17-Feb-2014	1	546	0	147051	12-059-006	Refinish Towing Hitch Assembly	20-Feb-2014 13:23:00	BDETL	K	DON	141.21
17-Feb-2014	1	546	0	147051	13-040	Assemble Engine / Motor Systems Group	12-Jun-2014 13:05:16	BSMEQP	J	DON	1,106.84
17-Feb-2014	1	546	0	147051	14-053-102	Install VIN Tag/Plate	10-Mar-2014 13:31:45	BTRLR	I	DON	22.60
17-Feb-2014	1	546	0	147051	15-059-006	Paint Prep Towing Hitch Assembly	21-Feb-2014 06:44:15	BDETL	K	DON	56.21
17-Feb-2014	1	546	0	147051	19-034-008	Wire/Rewire Trailer Light Cord	10-Mar-2014 11:30:07	BTRLR	I	DON	194.21
17-Feb-2014	1	546	0	147051	24-059-006	Repair Towing Hitch Assembly	19-Feb-2014 16:25:43	BSMEQP	E	DON	1,049.24
09-Feb-2015	0	546	0	196822	02-704	Clean Drill Rig	10-Feb-2015 17:00:00	BVLOFC	P	DON	58.62
18-Mar-2015	0	546	0	199346	06-100-DOT	Inspect DOT Federal Inspection	18-Mar-2015 17:00:00	LAKEVL	P	DON	55.48
18-Mar-2015	0	546	0	199346	24-013	Repair Brakes	18-Mar-2015 17:00:00	LAKEVL	S	DON	83.22
24-Apr-2015	1	546	0	199801	03-017-001	Replace Tire - Pneumatic	24-Apr-2015 16:00:20	BTIRE	E	DON	325.18
17-Mar-2016	0	546	0	237876	03-002-026	Replace Weather Stripping, Gaskets & Bumpers	23-Mar-2016 13:42:54	LAVSHP	I	DON	111.67
17-Mar-2016	0	546	0	237876	03-017-001	Replace Tire - Pneumatic	18-Mar-2016 09:22:13	LAVSHP	I	DON	300.75
17-Mar-2016	0	546	0	237876	03-032-001	Replace Battery	21-Mar-2016 13:12:32	LAVSHP	I	DON	164.14
17-Mar-2016	0	546	0	237876	06-100-DOT	Inspect DOT Federal Inspection	21-Mar-2016 13:49:01	LAVSHP	P	DON	44.54
17-Mar-2016	0	546	0	237876	06-100-PMA	Inspect A PMI	21-Mar-2016 11:04:28	LAVSHP	P	DON	242.53
17-Mar-2016	0	546	0	237876	24-013-012	Repair Electric Brakes	21-Mar-2016 07:44:39	LAVSHP	I	DON	115.26
17-Mar-2016	0	546	0	237876	24-034-023	Repair Harness - Rear	21-Mar-2016 07:42:49	LAVSHP	I	DON	13.69

# Unit Job History

Michels Corporation  
Report Printed: 02-Mar-2021 08:33:17 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Z0845 - 2011 VERMEER V500LE										
17-Mar-2016 0	546	0	237876	24-077-009	Repair Spring Hangers	21-Mar-2016 08:42:00	LAVSHP	I	DON	30.97
11-May-2016 0	546	0	248691	03-019-005	Replace Solenoid & Wiring	11-May-2016 07:00:00	LAVSHP	O	DON	22.36
11-May-2016 0	546	0	248691	03-034-019	Replace Switch (Other)	11-May-2016 07:00:00	LAVSHP	I	DON	22.36
11-May-2016 0	546	0	248691	03-701-002	Replace Plumbing / Valves (water)	13-May-2016 07:00:00	LAVSHP	N	DON	22.36
17-Aug-2016 1	792	0	255989	03-065-007	Replace Hoses & Fittings	22-Aug-2016 11:01:01	LAVSHP	B	DON	119.95
02-Mar-2017 1	792		279484	01-013-012	Adjust Electric Brakes	02-Mar-2017 13:52:51	LAVSHP	I	DON	10.16
02-Mar-2017 1	792		279484	06-100-DOT	Inspect DOT Federal Inspection	02-Mar-2017 13:32:12	LAVSHP	P	DON	41.59
02-Mar-2017 1	792		279484	11-002-046	Rebuild Side Door - Special Application	02-Mar-2017 16:10:33	LAVSHP	I	DON	133.00
17-Jul-2017 09	792		296969	03-002-064	Replace Washer Fluid Reservoir	26-Jul-2017 12:27:07	ROGSHP	B	DON	184.12
17-Jul-2017 09	792		296969	03-013-021	Replace Break Away Switch	17-Jul-2017 10:05:15	ROGSHP	B	DON	21.97
17-Jul-2017 09	792		296969	03-034-015	Replace Headlamp Switch	20-Jul-2017 11:59:11	ROGSHP	B	DON	51.15
17-Jul-2017 09	792		296969	03-041-001	Replace Air Cleaner	18-Jul-2017 09:15:58	ROGSHP	P	DON	18.36
17-Jul-2017 09	792		296969	03-044-007	Replace Throttle Controls	24-Jul-2017 09:44:39	ROGSHP	B	DON	66.51
17-Jul-2017 09	792		296969	03-053-008	Replace Hoses & Tubings & Fittings	18-Jul-2017 06:30:37	ROGSHP	B	DON	43.51
17-Jul-2017 09	792		296969	03-098-001	Replace Ball Valve Assembly (Blowdown Valve)	18-Jul-2017 08:33:00	ROGSHP	B	DON	36.08
17-Jul-2017 09	792		296969	03-100-PMB	Replace B PMI	18-Jul-2017 09:09:41	ROGSHP	P	DON	24.09
17-Jul-2017 09	792		296969	03-165-007	Replace Instruments and Gauges	24-Jul-2017 10:35:25	ROGSHP	B	DON	145.33
17-Jul-2017 09	792		296969	24-013-012	Repair Electric Brakes	17-Jul-2017 19:18:29	ROGSHP	B	DON	1.310.48
13-Oct-2017 11	806		308728	03-077-021	Replace Jack - Leveling	13-Oct-2017 11:03:36	ROGSHP	N	DON	34.49
13-Oct-2017 11	806		308728	03-701-002	Replace Plumbing / Valves (water)	20-Oct-2017 14:09:51	ROGSHP	N	DON	538.21
26-Mar-2018 0	806	0	328717	03-034-014	Replace Auxiliary Work / Flood Light	26-Mar-2018 16:44:35	LAVSHP	I	DON	103.62
26-Mar-2018 0	806	0	328717	06-100-DOT	Inspect DOT Federal Inspection	26-Mar-2018 16:05:28	LAVSHP	P	DON	55.01
26-Mar-2018 0	806	0	328717	24-017-008	Repair Valve Assembly	26-Mar-2018 17:23:57	LAVSHP	I	DON	21.62
10-Jul-2018 10		0	343130	24-097	Repair Pump - Product Transfer	11-Jul-2018 17:01:08	ROGSHP	N	DON	82.24
31-Jul-2018 13		0	346167	01-013-012	Adjust Electric Brakes	31-Jul-2018 13:25:58	ROGSHP	O	DON	7.03
25-Oct-2018 1:		0	358245	03-003	Replace Instruments, Gauges, Warning & Shud	26-Oct-2018 10:30:42	ROGSHP	N	DON	87.36
25-Oct-2018 1:		0	358245	03-079-009	Replace Tape - Reflective, Conspicuity	26-Oct-2018 10:46:03	ROGSHP	Q	DON	8.56
25-Oct-2018 1:		0	358245	03-098	Replace Valves & Controls - Bulk Product Tran	25-Oct-2018 16:19:59	ROGSHP	N	DON	212.78

# Unit Job History

Michels Corporation  
Report Printed: 02-Mar-2021 08:33:17 By User: RHEENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
<b>Unit No: Z0845 - 2011 VERMEER V500LE</b>										
25-Oct-2018 1:	481	0	358245	26-701-001	Weld Tank	26-Oct-2018 10:08:53	ROGSHP	N	DON	38.61
25-Oct-2018 1:	481	0	358245	03-165-006	Replace Filter Canister	26-Oct-2018 08:59:39	ROGSHP	P	DON	204.22
25-Oct-2018 1:	481	0	358245	03-097	Replace Pump - Product Transfer	31-Oct-2018 12:21:59	ROGSHP	N	DON	1,897.68
05-Mar-2019 1		0	375229	03-013-012	Replace Electric Brakes	07-Mar-2019 16:19:57	LAVSHP	I	DON	2,654.35
05-Mar-2019 1		0	375229	06-100-DOT	Inspect DOT Federal Inspection	07-Mar-2019 16:32:52	LAVSHP	P	DON	95.21
04-Jun-2019 1:	491	0	388637	03-511-002	Replace Reel Stand	04-Jun-2019 15:53:51	ROGSHP	N	DON	171.43
26-Sep-2019 0	1,112		404678	03-034-011	Replace Plug - Trailer Light Cord	26-Sep-2019 09:57:05	ROGSHP	N	DON	22.87
26-Sep-2019 0	1,112		404678	24-034-004	Repair Clearance & Marker Lamps	26-Sep-2019 09:42:45	ROGSHP	N	DON	19.67
26-Sep-2019 0	1,112		404678	24-078-009	Repair Mud Flaps and Hanger Brackets	26-Sep-2019 09:58:56	ROGSHP	N	DON	1.03
04-Mar-2020 1	1,114		429459	06-100-DOT	Inspect DOT Federal Inspection	04-Mar-2020 14:22:09	LAVSHP	P	DON	50.68
04-Mar-2020 1	1,114		429459	38-100-PMA	Service A PMI	05-Mar-2020 07:41:56	LAVSHP	P	DON	112.97
04-Mar-2020 1	1,114		429459	06-100-PMA	Inspect A PMI	05-Mar-2020 07:57:31	LAVSHP	P	DON	0.00
30-Sep-2020 0	1,123		463948	38-044	Service Fuel System	30-Sep-2020 17:00:02	BSDRIL	I	DON	298.66
30-Sep-2020 0	1,123		463948	03-032-002	Replace Starter	30-Oct-2020 08:25:44	BSDRIL	I	DON	191.00
22-Feb-2021 1:	1,124		489519	25-063-003	Remove Transceiver - GPS Tracker	22-Feb-2021 13:47:15	BSDRIL	Z	DON	61.93
22-Feb-2021 1:	1,124		489519	25-053-005	Remove Markings - Vehicle - Decals	22-Feb-2021 13:47:26	BSDRIL	Z	DON	142.10
22-Feb-2021 1:	1,124		489519	03-098	Replace Valves & Controls - Bulk Product Tran	22-Feb-2021 16:15:33	BSDRIL	Z	DON	549.76

Unit No: Z0845

Count: 104

27,007.80