

Unit Job History

Michels Corporation
Report Printed: 22-Jul-2021 12:55:53 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: P1009 - 2007 CAT D6T										
05-Mar-2010 1	0	0	35556	02-002-011	Clean Cab Accessories - Interior	16-Mar-2010 10:58:42	BDETL	Q	DON	107.75
05-Mar-2010 1	0	0	35556	12-320	Refinish Bull Dozer	16-Mar-2010 10:58:54	BDETL	Q	DON	106.86
05-Mar-2010 1	0	0	35556	15-320	Paint Prep Bull Dozer	16-Mar-2010 10:58:49	BDETL	Q	DON	235.16
09-Mar-2010 0	1,752	0	35676	03-032-001	Replace Battery	15-Mar-2010 15:00:00	BHVEEQ	I	DON	74.51
09-Mar-2010 0	1,752	0	35676	03-044-017	Replace Indicator/Sender - Fuel Level	18-Mar-2010 10:08:34	BHVEEQ	I	DON	176.91
09-Mar-2010 0	1,752	0	35676	06-320-002	Inspect Undercarriage (Tracks&Rollers)	09-Mar-2010 06:20:09	BHVEEQ	I	DON	0.00
09-Mar-2010 0	1,752	0	35676	14-051-009	Install Fire Extinguisher	18-Mar-2010 11:06:41	BHVEEQ	E	DON	38.30
09-Mar-2010 0	1,752	0	35676	38-100-001	Service DO NOT USE - PMI Service	17-Mar-2010 09:00:00	BHVEEQ	P	DON	790.07
01-Aug-2010 0	2,100	0	49929	03-031-001	Replace Generator/Alternator	01-Nov-2010 17:20:13	U91012	I	DON	1,112.52
01-Aug-2010 0	2,100	0	49929	03-045-023	Replace Engine Belts	01-Nov-2010 17:20:13	U91012	I	DON	235.55
01-Aug-2010 0	2,100	0	49929	06-100	Inspect PMI	01-Nov-2010 17:20:13	U91012	J	DON	530.38
01-Jan-2011 00	2,100	0	61424	02-320	Clean Bull Dozer	13-Jun-2011 15:22:41	RB1101	J	DON	270.00
01-Jan-2011 00	2,140	0	62341	03-320	Replace Bull Dozer	08-Jul-2011 12:00:00	RB1102	I	DON	233.38
01-Jan-2011 00	2,140	0	62341	06-100-001	Inspect DO NOT USE - PMI Service	08-Jul-2011 12:00:00	RB1102	J	DON	319.09
01-Jun-2011 00	2,345	0	70292	02-002	Clean Cab & Sheet Metal	09-Mar-2012 11:58:25	RB1105	Q	DON	270.00
01-Jun-2011 00	2,345	0	70292	06-100-001	Inspect DO NOT USE - PMI Service	09-Mar-2012 11:58:25	RB1105	Q	DON	430.37
01-Aug-2011 0	3,538	0	76427	03-001-002	Replace Heating & Ventilating	14-Feb-2013 11:40:44	U91012	F	DON	380.32
01-Aug-2011 0	3,538	0	76427	03-002-004	Replace Hood	14-Feb-2013 11:40:44	U91012	F	DON	336.49
01-Aug-2011 0	3,538	0	76427	06-100-001	Inspect DO NOT USE - PMI Service	14-Feb-2013 11:40:44	U91012	J	DON	855.16
01-Aug-2011 0	3,538	0	76427	24-320-001	Repair Blade and Mounting	14-Feb-2013 11:40:44	U91012	F	DON	292.26
01-Dec-2012 0	3,538	0	103815	24-063	Repair Satellite Communications System	01-Dec-2012 09:53:56	GPSINS	C	DON	243.53
01-Apr-2013 0	3,538	0	117165	35-003-006	Diagnose Monitoring Devices	28-Aug-2013 14:51:20	U31010	I	DON	609.92
01-Aug-2013 0	3,538	0	128866	06-100-001	Inspect DO NOT USE - PMI Service	21-Sep-2013 05:43:47	U91012	F	DON	366.84
01-Sep-2013 0	0	0	131387	03-032-001	Replace Battery	31-Dec-2013 00:00:00	U31010	F	DON	337.80
20-Apr-2014 0	0	0	191596	08-320	Overhaul Bull Dozer	30-May-2014 17:00:00	BVLOFC	U	DON	1,033.87
21-Aug-2014 0	3,612	0	190201	03-065-002	Replace Accumulator	21-Aug-2014 17:00:00	BVLOFC	B	DON	34.46
28-Aug-2014 0	0	0	190389	03-320-009	Replace Cutting Edge - Blade	28-Aug-2014 17:00:00	BVLOFC	I	DON	68.92
23-Sep-2014 0	3,719	0	190317	24-016	Repair Suspension	23-Sep-2014 17:00:00	BVLOFC	O	DON	34.46
14-Oct-2014 0	3,761	0	191081	07-100-300	Lubricate Off Road Equip / Field Service	14-Oct-2014 17:00:00	BVLOFC	P	DON	34.46

Unit Job History

Michels Corporation
Report Printed: 22-Jul-2021 12:55:53 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost	
Unit No: P1009 - 2007 CAT D6T											
20-Aug-2015	1	3,769	0	212039	03-063-003	Replace Transceiver - GPS Tracker	20-Aug-2015 17:33:38	GPSINS	Q	DON	250.77
29-Dec-2016	0	3,802	0	271149	06-049	Inspect Electronic Management System	30-Dec-2016 00:00:00	BHVEEQ	O	DON	427.30
11-Jan-2017	1	3,802	0	272911	06-100-PMB	Inspect B PMI	11-Jan-2017 15:52:06	BHVEEQ	P	DON	1,995.62
31-Jan-2017	0	3,802	0	286033	24-320-010	Repair Equalizer Bar	31-Jan-2017 00:00:00	BVLOFC	I	DON	2,311.04
11-Sep-2017	0	3,806	0	304320	03-044-003	Replace Fuel Pump	15-Sep-2017 06:56:08	BHVEEQ	N	DON	655.59
11-Sep-2017	0	3,806	0	304320	06-320	Inspect Bull Dozer	15-Sep-2017 07:39:11	BHVEEQ	J	DON	190.84
11-Sep-2017	0	3,806	0	304320	24-063-003	Repair Transceiver - GPS Tracker	11-Sep-2017 07:45:19	BHVEEQ	Q	DON	0.00
11-Sep-2017	0	3,806	0	304320	34-044-014	Rescal Injectors - Electronic	15-Sep-2017 07:39:20	BHVEEQ	N	DON	1,286.40
11-Sep-2017	0	3,806	0	304320	35-044	Diagnose Fuel System	12-Sep-2017 07:19:54	BHVEEQ	J	DON	160.45
11-Sep-2017	0	3,806	0	304320	35-320-013	Diagnose Operator Controls	11-Sep-2017 14:33:38	BHVEEQ	J	DON	74.38
15-Mar-2018	0	3,809	0	327457	02-320	Clean Bull Dozer	21-Mar-2018 06:28:23	BWASH	J	DON	239.97
15-Mar-2018	0	3,809	0	327457	03-065-029	Replace Bushing - Cylinder	24-Mar-2018 07:42:46	BHVEEQ	I	DON	9,592.60
15-Mar-2018	0	3,809	0	327457	06-100-PMB	Inspect B PMI	05-Apr-2018 14:22:34	BHVEEQ	P	DON	3,526.06
15-Mar-2018	0	3,809	0	327457	06-320	Inspect Bull Dozer	05-Apr-2018 14:24:45	BHVEEQ	J	DON	1,116.80
15-Mar-2018	0	3,809	0	327457	12-002-061	Refinish Seat Cushion	24-Mar-2018 07:42:44	BHVEEQ	I	DON	614.59
15-Mar-2018	0	3,809	0	327457	24-320-001	Repair Blade and Mounting	27-Mar-2018 10:17:22	BHVEEQ	I	DON	1,992.52
29-Jul-2018	10	4,106	0	369503	03-100-PM/A	Replace A PMI	29-Jul-2018 23:00:00	709520	P	DON	51.09
30-Aug-2018	0	4,106	0	352104	03-049-002	Replace ECM Module	16-Sep-2018 00:00:00	BVLOFC	E	DON	3,977.74
30-Aug-2018	0	4,106	0	352104	95-MSC	Travel Miscellaneous	16-Sep-2018 00:00:00	BVLOFC	E	DON	234.59
20-Dec-2018	0	4,106	0	368302	03-003	Replace Instruments, Gauges, Warning & Shurd	16-Jan-2019 00:00:00	BVLOFC	E	DON	4,281.55
20-Dec-2018	0	4,106	0	368302	95-MSC	Travel Miscellaneous	16-Jan-2019 00:00:00	BVLOFC	E	DON	527.95
09-Jun-2020	1	4,305	0	444507	02-320	Clean Bull Dozer	16-Jun-2020 17:01:03	BVLYRD	N	DON	563.95
09-Jun-2020	1	4,305	0	444507	03-032-001	Replace Battery	01-Sep-2020 14:48:01	BHVEEQ	I	DON	472.90
09-Jun-2020	1	4,305	0	444507	06-100-PM/A	Inspect A PMI	02-Sep-2020 05:35:22	BHVEEQ	P	DON	82.73
27-May-2021	1	4,307	0	509410	02-320	Clean Bull Dozer	28-Jun-2021 13:03:02	BWASH	Z	DON	197.84
27-May-2021	1	4,307	0	509410	06-100-008	Inspect Out-Service Inspection	27-May-2021 17:08:45	BHVEEQ	I	DON	347.24
27-May-2021	1	4,307	0	509410	06-100-PM/A	Inspect A PMI	28-May-2021 12:01:30	SCHED	P	DON	34.11
27-May-2021	1	4,307	0	509410	12-320	Refinish Bull Dozer		BBODY	Z	WFA	0.00
27-May-2021	1	4,307	0	509410	14-111-010	Install Belly Pan	02-Jun-2021 09:21:19	BHVEEQ	Z	DON	207.94

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: P1009 - 2007 CAT D6T										
27-May-2021 (4,307	0	509410	14-320-001	Install Blade and Mounting	24-Jun-2021 09:35:34	BHVEEQ	Z	DON	559.75
27-May-2021 (4,307	0	509410	15-320	Paint Prep Bull Dozer		BBODY	Z	WND	496.92
27-May-2021 (4,307	0	509410	22-515	Design Blade	03-Jun-2021 10:50:08	BWELD	D	DON	794.98
27-May-2021 (4,307	0	509410	25-063-003	Remove Transceiver - GPS Tracker	02-Jun-2021 09:26:14	BHVEEQ	Z	DON	67.06
27-May-2021 (4,307	0	509410	25-320-001	Remove Blade and Mounting	28-May-2021 11:06:29	BHVEEQ	Z	DON	215.12
27-May-2021 (4,307	0	509410	38-100-PMA	Service A PMI	28-May-2021 16:00:12	BHVEEQ	P	DON	199.52
27-May-2021 (4,307	0	509410	99-513-004	Machine Specialty Attachment	13-Jul-2021 05:06:07	BWELD	N	DON	1,258.63

Unit No: P1009

Count: 65

48,565.92