

Unit Job History

Michels Corporation
Report Printed: 20-Sep-2022 13:07:28 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2518 - 2014 F150 CREWCAB										
28-Apr-2014 0	63	0	155631	14-052-014	Install Cellular Telephone Accessories	28-Apr-2014 07:22:59	BDETL	C	DON	90.89
28-Apr-2014 0	63	0	155631	14-052-015	Install Power Inverter/Converter	28-Apr-2014 15:18:44	BDETL	C	DON	250.66
28-Apr-2014 0	63	0	155631	14-053-005	Install Markings - Vehicle - Decals	29-Apr-2014 13:33:57	BDETL	C	DON	249.13
28-Apr-2014 0	63	0	155631	14-053-014	Install Floor Mats	29-Apr-2014 07:51:03	BDETL	C	DON	78.55
28-Apr-2014 0	63	0	155631	14-071-011	Install Scuff Liner / Bed Mat	28-Apr-2014 17:02:49	BDETL	C	DON	128.19
28-Apr-2014 0	63	0	155631	14-078-009	Install Mud Flaps and Hanger Brackets	29-Apr-2014 08:30:19	BDETL	C	DON	93.45
28-Apr-2014 0	63	0	155631	14-078-014	Install Tarpsaulin/ Tomneau Cover	29-Apr-2014 07:19:31	BDETL	C	DON	431.83
28-Apr-2014 0	63	0	155631	14-002-063	Install Computer Stand / Dock	29-Apr-2014 07:39:29	BDETL	C	DON	323.96
28-Apr-2014 0	63	0	155631	14-052-003	Install Radio Equipment	28-Apr-2014 10:09:10	BDETL	C	DON	978.05
28-Apr-2014 0	63	0	155631	14-052-011	Install Auxiliary Power	28-Apr-2014 13:44:50	BDETL	C	DON	194.10
28-Apr-2014 0	63	0	155631	14-063-003	Install Transceiver - GPS Tracker	29-Apr-2014 06:17:04	BDETL	C	DON	230.93
28-Apr-2014 0	63	0	155631	06-100-009	Inspect Safety Check	29-Apr-2014 12:00:05	BTRUCK	P	DON	41.10
06-May-2014 1	63	0	156719	06-100-DOT	Inspect DOT Federal Inspection	09-May-2014 13:27:35	MPNSHP	I	DON	26.26
06-May-2014 1	63	0	156719	06-100-009	Inspect Safety Check	09-May-2014 12:28:10	MPNSHP	P	DON	0.11
06-May-2014 1	63	0	156719	14-053-007	Install Hardware - Expendable Items	09-May-2014 12:37:03	MPNSHP	I	DON	997.91
17-Jun-2014 1	4,703	0	163611	06-100-PMA	Inspect A PMI	17-Jun-2014 14:04:48	MPNSHP	P	DON	83.79
02-Sep-2014 1	15,362	0	172225	06-032	Inspect Cranking System	09-Sep-2014 00:00:00	MPNSHP	W	DON	0.00
02-Sep-2014 1	15,362	0	172225	06-100-PMA	Inspect A PMI	02-Sep-2014 11:49:30	MPNSHP	P	DON	99.68
01-Oct-2014 0	18,151	0	185530	03-002-024	Replace Glass / Windshield	01-Oct-2014 17:00:00	BVLOFC	F	DON	457.87
14-Oct-2014 0	19,800	0	179608	06-100-PMA	Inspect A PMI	14-Oct-2014 17:00:00	BVLOFC	P	DON	127.19
02-Dec-2014 1	24,271	0	182955	06-100-PMA	Inspect A PMI	02-Dec-2014 14:00:00	MPNFLD	P	DON	62.26
02-Dec-2014 1	24,271	0	182955	03-002-035	Replace Windshield Wiper & Washer	02-Dec-2014 14:00:00	MPNFLD	J	DON	48.76
02-Dec-2014 1	24,271	0	182955	03-041-006	Replace Filter - Inner	02-Dec-2014 14:00:00	MPNFLD	J	DON	18.84
02-Dec-2014 1	24,271	0	182955	06-063-003	Inspect Transceiver - GPS Tracker	02-Dec-2014 13:36:24	MPNSHP	P	DON	232.31
24-Feb-2015 1	24,271	0	192495	06-100-PMA	Inspect A PMI	25-Feb-2015 00:00:00	BTRUCK	P	DON	31.28
01-Apr-2015 0	28,776	0	203549	24-017-001	Repair Tire - Pneumatic	01-Apr-2015 00:00:00	MPNSHP	B	DON	30.96
01-Apr-2015 1	28,776	0	196567	14-071-024	Install Cover/Cap - Fiberglass	03-Apr-2015 15:00:17	MPNSHP	P	DON	543.57
01-Apr-2015 1	28,776	0	196567	14-051-009	Install Fire Extinguisher	03-Apr-2015 15:00:33	MPNSHP	I	DON	18.93
27-Aug-2015 0	41,567	0	212652	03-002-020	Replace Side Door Mechanism	27-Aug-2015 05:50:29	BVLOFC	O	DON	373.52

Unit Job History

Michels Corporation
Report Printed: 20-Sep-2022 13:07:28 By User: RHEINING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Job Status	Total Cost
Unit No: B2518 - 2014 F150 CREWCAB											
30-Sep-2015 1	45,267	0	224873	06-100-PMA	Inspect A PMI	30-Sep-2015 12:45:23	BVLOFC	P	DON		30.50
30-Sep-2015 1	45,267	0	224873	14-002-020	Install Side Door Mechanism	30-Sep-2015 12:45:23	BVLOFC	B	DON		128.13
30-Sep-2015 1	45,267	0	224873	31-017-001	Rotate Tire - Pneumatic	30-Sep-2015 12:45:23	BVLOFC	P	DON		11.09
01-Oct-2015 1	45,267	0	224870	24-002-020	Repair Side Door Mechanism	01-Oct-2015 12:21:14	BVLOFC	B	DON		137.58
11-Jan-2016 1	55,338	0	228366	38-045	Service Power Plant	11-Jan-2016 13:50:51	BTRUCK	P	DON		151.08
11-Jan-2016 1	55,338	0	228366	06-100-PMB	Inspect B PMI	11-Jan-2016 13:27:21	BTRUCK	P	DON		13.12
11-Jan-2016 1	55,338	0	228366	03-032-001	Replace Battery	11-Jan-2016 17:00:41	BTRUCK	I	DON		131.29
13-May-2016 1	61,731	0	254594	06-100-PMA	Inspect A PMI	13-May-2016 10:38:24	BVLOFC	P	DON		75.04
12-Jul-2016 06	62,359	0	252611	03-017-001	Replace Tire - Pneumatic	15-Jul-2016 16:04:59	BTIRE	N	DON		1,743.84
12-Jul-2016 06	62,359	0	252611	06-100-PMA	Inspect A PMI	20-Jul-2016 15:06:54	BTRUCK	P	DON		67.84
12-Sep-2016 0	71,572	0	259033	02-002-044	Clean Cab - Complete	13-Sep-2016 14:18:51	MPNSHP	I	DON		81.05
12-Sep-2016 0	71,572	0	259033	03-013-001	Replace Front Brakes & Drums	13-Sep-2016 08:22:27	MPNSHP	I	DON		283.39
12-Sep-2016 0	71,572	0	259033	06-100-PMA	Inspect A PMI	12-Sep-2016 16:30:23	MPNSHP	P	DON		153.27
12-Sep-2016 0	71,572	0	259033	14-053-005	Install Markings - Vehicle - Decals	13-Sep-2016 10:24:48	MPNSHP	I	DON		57.18
12-Sep-2016 0	71,572	0	259033	03-051-009	Replace Fire Extinguisher	13-Sep-2016 08:22:39	MPNSHP	I	DON		10.47
07-Mar-2017 0	71,572	0	279948	03-032-001	Replace Battery	12-Oct-2016 07:33:31	MPNSHP	P	DON		29.75
15-Mar-2017 0	71,572	0	282667	06-100-PMA	Inspect A PMI	07-Mar-2017 08:59:28	MPNSHP	B	DON		141.46
31-Jul-2017 12	78,456	0	298902	38-042	Service Cooling System	31-Jul-2017 15:40:55	BVLOFC	P	DON		108.81
31-Jul-2017 12	78,456	0	298902	03-042-004	Replace Water Pump	31-Jul-2017 15:42:08	BVLOFC	O	DON		644.00
12-Oct-2017 1	80,050	0	308593	06-100-PMA	Inspect A PMI	12-Oct-2017 11:04:24	BVLOFC	P	DON		61.11
12-Oct-2017 1	80,050	0	308593	31-017-001	Rotate Tire - Pneumatic	12-Oct-2017 11:22:15	BVLOFC	P	DON		18.98
18-Jan-2018 1	83,667	0	320062	06-100-009	Inspect Safety Check	28-Mar-2018 11:43:12	MPNSHP	I	DON		12.30
18-Jan-2018 1	83,667	0	320062	03-027-033	Replace Range Selector Or Manual Linkage	02-Feb-2018 10:02:07	BVLOFC	B	DON		732.78
18-Jan-2018 1	83,667	0	320062	20-027-033	Tow Range Selector Or Manual Linkage	06-Feb-2018 04:38:45	HARFLD	E	DON		177.27
12-Feb-2018 1	83,930	0	323204	02-002	Clean Cab & Sheet Metal	12-Feb-2018 11:11:53	BVLOFC	O	DON		178.68
23-Apr-2018 1	89,574	0	336400	06-100-PMA	Inspect A PMI	23-Apr-2018 13:24:00	BVLOFC	P	DON		156.37
30-Aug-2018 1	99,778	0	357403	06-100-PMA	Inspect A PMI	30-Aug-2018 11:18:00	BVLOFC	P	DON		62.24

Unit Job History

Michels Corporation
Report Printed: 20-Sep-2022 13:07:28 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2518 - 2014 F150 CREWCAB										
17-Dec-2018 0	108,019	0	364802	03-041-007	Replace Filter - Outer	18-Dec-2018 10:47:25	BVLOFC	P	DON	28.56
17-Dec-2018 0	108,019	0	364802	38-033-003	Service Spark Plugs	18-Dec-2018 10:47:25	BVLOFC	I	DON	216.63
17-Dec-2018 0	108,019	0	364802	24-032-002	Repair Starter	18-Dec-2018 10:47:25	BVLOFC	O	DON	407.01
17-Dec-2018 0	108,019	0	364802	38-042	Service Cooling System	18-Dec-2018 10:47:25	BVLOFC	P	DON	197.84
17-Dec-2018 0	108,019	0	364802	06-100-PM A	Inspect A PMI	18-Dec-2018 10:47:25	BVLOFC	P	DON	51.66
17-Dec-2018 0	108,019	0	364802	03-013-002	Replace Rear Brakes & Drums	18-Dec-2018 10:47:25	BVLOFC	I	DON	508.51
17-Dec-2018 0	108,019	0	364802	38-013	Service Brakes	18-Dec-2018 10:47:25	BVLOFC	P	DON	134.02
15-May-2019 0	114,239	0	386024	03-034-001	Replace Headlamps / Fog Lamps	15-May-2019 12:00:00	HARFLD	O	DON	69.97
04-Oct-2019 0	125,800	0	406000	03-034-001	Replace Headlamps / Fog Lamps	04-Oct-2019 13:00:00	HARFLD	O	DON	122.95
17-Jan-2020 1	130,660	0	421668	38-100-PM A	Service A PMI	20-Jan-2020 05:56:05	BVLOFC	P	DON	71.17
17-Jan-2020 1	130,660	0	421668	24-017-001	Repair Tire - Pneumatic	20-Jan-2020 05:56:05	BVLOFC	O	DON	16.70
17-Jan-2020 1	130,660	0	421668	03-013-001	Replace Front Brakes & Drums	20-Jan-2020 05:56:05	BVLOFC	O	DON	602.35
17-Jan-2020 1	130,660	0	421668	06-100-PM A	Inspect A PMI	20-Jan-2020 05:56:05	BVLOFC	P	DON	0.00
12-May-2020 0	135,086	0	440277	03-002-024	Replace Glass / Windshield	09-Jun-2020 12:31:08	HARFLD	E	DON	393.12
12-May-2020 0	135,086	0	440277	24-017-001	Repair Tire - Pneumatic	09-Jun-2020 12:31:08	HARFLD	E	DON	24.58
18-Jun-2020 0	152,455	0	447004	06-100-PM A	Inspect A PMI	18-Jun-2020 00:00:00	BVLOFC	P	DON	0.00
18-Jun-2020 0	152,455	0	447004	38-100-PM A	Service A PMI	18-Jun-2020 00:00:00	BVLOFC	P	DON	0.00
29-Jul-2020 05	140,785	0	453024	03-041-007	Replace Filter - Outer	29-Jul-2020 05:36:27	BVLOFC	P	DON	27.92
29-Jul-2020 05	140,785	0	453024	06-100-PM A	Inspect A PMI	29-Jul-2020 05:36:27	BVLOFC	P	DON	0.00
29-Jul-2020 05	140,785	0	453024	38-100-PM A	Service A PMI	29-Jul-2020 05:36:27	BVLOFC	P	DON	87.67
29-Jul-2020 05	140,785	0	453024	03-034-001	Replace Headlamps / Fog Lamps	29-Jul-2020 05:36:27	BVLOFC	O	DON	33.51
26-Aug-2020 0	142,256	0	458117	06-013	Inspect Brakes	26-Aug-2020 09:44:11	BVLOFC	O	DON	32.35
26-Aug-2020 0	142,256	0	458117	03-017-001	Replace Tire - Pneumatic	26-Aug-2020 09:44:11	BVLOFC	O	DON	792.89
26-Aug-2020 0	142,256	0	458117	35-016	Diagnose Suspension	26-Aug-2020 09:44:11	BVLOFC	O	DON	139.66
26-Aug-2020 0	142,256	0	458117	03-034-002	Replace Stop, Tail, Turn & License	26-Aug-2020 09:44:11	BVLOFC	I	DON	28.01
26-Aug-2020 0	142,256	0	458117	24-043-006	Repair Heat Shield	26-Aug-2020 09:44:11	BVLOFC	O	DON	139.66
26-Aug-2020 0	142,256	0	458117	24-022-003	Repair Differential Carrier	26-Aug-2020 09:44:11	BVLOFC	O	DON	295.69
19-Jul-2021 06	147,190	0	520612	38-100-PM A	Service A PMI	26-Jul-2021 08:37:03	SCHED	P	DON	177.65

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2518 - 2014 F150 CREWCAB										
19-Jul-2021 06	147,190	0	520612	95-034-001	Travel Headlamps / Fog Lamps	25-Jul-2021 07:39:37	NHFLD	O	DON	47.43
19-Jul-2021 06	147,190	0	520612	24-034-001	Repair Headlamps / Fog Lamps	25-Jul-2021 07:39:32	NHFLD	O	DON	58.59
19-Jul-2021 06	147,190	0	520612	06-100-PMA	Inspect A PMI	26-Jul-2021 08:36:53	SCHED	P	DON	43.73
19-Jul-2021 06	147,190	0	520612	06-100-PMB	Inspect B PMI	26-Jul-2021 08:36:58	SCHED	P	DON	43.73
24-Aug-2021 0	147,190	0	528065	03-013-002	Replace Rear Brakes & Drums	28-Aug-2021 09:18:53	NHFLD	I	DON	494.36
25-Oct-2021 1	147,190	0	541684	06-100-PMA	Inspect A PMI	25-Oct-2021 13:07:21	NHFLD	P	DON	0.00
25-Oct-2021 1	147,190	0	541684	38-100-PMA	Service A PMI	25-Oct-2021 13:07:21	NHFLD	P	DON	92.55
01-Nov-2021 0	147,190	0	544381	03-002-061	Replace Seat Cushion	18-Nov-2021 19:00:36	NHFLD	O	DON	402.15
24-Jan-2022 0	147,190	0	561522	38-100-PMA	Service A PMI	25-Jan-2022 10:34:05	NHFLD	P	DON	187.42
24-Jan-2022 0	147,190	0	561522	06-100-PMB	Inspect B PMI	25-Jan-2022 10:34:11	NHFLD	P	DON	94.87
22-Mar-2022 0	147,190	0	577505	95-033-001	Travel Ignition Switch	27-Mar-2022 12:19:33	NHFLD	B	DON	118.58
22-Mar-2022 0	147,190	0	577505	03-037-021	Replace Circuit Breaker/Fuse - Multiple Use	27-Mar-2022 12:19:37	NHFLD	I	DON	118.58
22-Mar-2022 0	147,190	0	577505	03-063-003	Replace Transceiver - GPS Tracker	27-Mar-2022 13:47:25	NHFLD	Q	DON	488.32
27-Jun-2022 0	175,047	0	598866	38-100-PMA	Service A PMI	01-Aug-2022 13:53:11	NHFLD	P	DON	104.93
27-Jun-2022 0	175,047	0	598866	03-017-001	Replace Tire - Pneumatic	28-Jun-2022 05:04:40	NHFLD	E	DON	1,017.04
27-Jun-2022 0	175,047	0	598866	06-100-PMA	Inspect A PMI	30-Jun-2022 07:44:45	NHFLD	P	DON	94.87
27-Jun-2022 0	175,047	0	598866	06-100-PMB	Inspect B PMI	30-Jun-2022 07:44:49	NHFLD	P	DON	94.87
13-Sep-2022 1	179,548	0	616114	02-002	Clean Cab & Sheet Metal	20-Sep-2022 07:27:30	BSETUP	Z	DON	311.57
13-Sep-2022 1	179,548	0	616114	25-051	Remove General Accessories	14-Sep-2022 08:24:21	BSETUP	Z	DON	197.17

Unit No: B2518

Count: 106

20,469.54