

# Unit Job History

Michels Corporation  
Report Printed: 20-Sep-2022 05:49:37 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
--------------	---------	---------	------------	----------	-----------------	----------------	--------------	------------	------------	------------

Unit No: N1068 - 2016 CAT 336FL

12-May-2016	1	0	244329	14-053-005	Install Markings - Vehicle - Decals	12-May-2016 10:32:16	BHVYEQ	Q	DON	209.48
12-May-2016	1	0	244329	14-063-003	Install Transceiver - GPS Tracker	12-May-2016 10:31:15	BHVYEQ	Q	DON	539.74
04-Nov-2016	618	0	265573	06-330	Inspect Excavator	08-Nov-2016 05:11:00	BHVYEQ	J	DON	580.34
04-Nov-2016	618	0	265573	06-330-002	Inspect Undercarriage (Tracks&Rollers)	04-Nov-2016 08:57:07	BHVYEQ	J	DON	245.47
29-Dec-2016	658	0	271295	01-042-014	Adjust Coolant Overflow Reservoir	04-Jan-2017 00:00:00	BHVYEQ	J	DON	0.00
29-Dec-2016	658	0	271295	01-044	Adjust Fuel System	04-Jan-2017 00:00:00	BHVYEQ	O	DON	38.52
29-Dec-2016	658	0	271295	01-049	Adjust Electronic Management System	04-Jan-2017 00:00:00	BHVYEQ	J	DON	0.00
29-Dec-2016	658	0	271295	02-002	Clean Cab & Sheet Metal	04-Jan-2017 00:00:00	BHVYEQ	J	DON	102.75
29-Dec-2016	658	0	271295	02-330	Clean Excavator	04-Jan-2017 00:00:00	BHVYEQ	J	DON	1,428.16
29-Dec-2016	658	0	271295	03-041-007	Replace Filter - Outer	04-Jan-2017 00:00:00	BHVYEQ	P	DON	239.00
29-Dec-2016	658	0	271295	03-509-001	Replace Machine Guard	04-Jan-2017 00:00:00	BHVYEQ	J	DON	194.32
29-Dec-2016	658	0	271295	06-100-PMA	Inspect A PMI	04-Jan-2017 00:00:00	BHVYEQ	P	DON	830.90
29-Dec-2016	658	0	271295	14-042-009	Install Coolant Pre-Heater- Electrical	04-Jan-2017 00:00:00	BHVYEQ	O	DON	804.25
29-Dec-2016	658	0	271295	24-033-001	Repair Ignition Switch	04-Jan-2017 00:00:00	BHVYEQ	J	DON	286.37
29-Dec-2016	658	0	271295	D0-330	Start Excavator	04-Jan-2017 00:00:00	BHVYEQ	J	DON	410.54
13-Apr-2017	736	0	285121	03-065-007	Replace Hoses & Fittings	04-May-2017 16:13:08	BHVYEQ	I	DON	52.97
13-Apr-2017	736	0	285121	06-100-PMA	Inspect A PMI	17-Apr-2017 09:39:49	BHVYEQ	P	DON	554.79
13-Apr-2017	736	0	285121	06-100-PMB	Inspect B PMI	04-May-2017 16:13:43	BHVYEQ	P	CAN	0.00
13-Apr-2017	736	0	285121	14-052-005	Install Transmitter - CB	04-May-2017 16:13:06	BHVYEQ	O	DON	123.37
08-Jun-2017	736	0	292031	24-063-003	Repair Transceiver - GPS Tracker	04-May-2017 16:13:06	BHVYEQ	Q	DON	0.00
08-Jun-2017	736	0	292031	03-044-002	Replace Filters	09-Jun-2017 10:55:43	BHVYEQ	J	DON	47.90
08-Jun-2017	736	0	292031	03-052-005	Replace Transmitter - CB	08-Jun-2017 06:39:01	BHVYEQ	J	DON	123.37
19-Jul-2017	975	0	297310	06-100-PMA	Inspect A PMI	19-Jul-2017 05:24:23	BHVYEQ	P	DON	750.98
30-Aug-2017	975	0	303058	03-065-007	Replace Hoses & Fittings	01-Sep-2017 11:36:14	ROGSH	B	DON	418.81
18-Jan-2018	1,453	0	320112	06-100-PMA	Inspect A PMI	24-Jan-2018 12:52:35	BHVYEQ	P	DON	205.49
18-Jan-2018	1,453	0	320112	06-100-PMB	Inspect B PMI	25-Jan-2018 08:49:27	BHVYEQ	P	DON	518.31
11-Apr-2018	1,453	0	330975	03-514-002	Replace Shanks or Tech	11-Apr-2018 09:57:43	BHVYEQ	E	DON	0.00
28-Jun-2018	1,924	0	341843	06-049-001	Inspect ECM Fault Code	02-Jul-2018 12:48:29	BHVYEQ	J	DON	1,468.29
23-Jul-2018	1,957	0	345044	02-330	Clean Excavator	24-Jul-2018 17:00:22	BWASH	N	DON	276.91

# Unit Job History

Mitchels Corporation  
Report Printed: 20-Sep-2022 05:49:37 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: N1068 - 2016 CAT 336FL										
23-Jul-2018 15	1,957	0	345044	06-100-PMA	Inspect A PMI	27-Jul-2018 05:25:29	BHYYEQ	P	DON	318.26
26-Oct-2018 04	2,290	0	358875	03-002-024	Replace Glass / Windshield	30-Oct-2018 00:00:00	BYLOFC	E	DON	1,883.21
26-Oct-2018 04	2,290	0	358875	95-MISC	Travel Miscellaneous	30-Oct-2018 00:00:00	BYLOFC	E	DON	368.87
30-Oct-2018 11		0	358779	03-065-007	Replace Hoses & Fittings	30-Oct-2018 10:51:01	BYLOFC	O	DON	884.67
08-Nov-2018 1	2,338	0	359958	02-330	Clean Excavator	09-Nov-2018 14:23:25	BWASH	N	DON	351.40
08-Nov-2018 1	2,338	0	359958	06-100-PMA	Inspect A PMI	08-Nov-2018 13:05:11	BHYYEQ	P	DON	233.14
08-Nov-2018 1	2,338	0	359958	06-330	Inspect Excavator	14-Nov-2018 05:32:15	BHYYEQ	P	DON	10.42
18-Feb-2019 11	2,371	0	372867	03-002-024	Replace Glass / Windshield	18-Feb-2019 13:26:34	BHYYEQ	E	DON	336.27
18-Feb-2019 11	2,371	0	372867	06-100-PMB	Inspect B PMI	18-Feb-2019 16:23:01	BHYYEQ	P	DON	329.78
18-Feb-2019 11	2,371	0	372867	34-045-013	Rescal Oil Pan	22-Feb-2019 09:49:29	BHYYEQ	I	DON	201.82
17-Apr-2019 1	2,371	0	381706	02-330	Clean Excavator	18-Apr-2019 09:15:02	BWASH	N	DON	134.84
15-Aug-2019 1	2,955	0	398804	24-042	Repair Cooling System	03-Sep-2019 07:32:49	MONSHP	B	DON	505.91
13-Jan-2020 06	3,176	0	420637	01-330-001	Adjust Bucket and Attachments	14-Jan-2020 08:25:56	BHYYEQ	I	DON	110.40
13-Jan-2020 06	3,176	0	420637	02-002	Clean Cab & Sheet Metal	13-Jan-2020 13:35:17	BHYYEQ	N	DON	32.06
13-Jan-2020 06	3,176	0	420637	02-330	Clean Excavator	16-Jan-2020 13:11:51	BWASH	N	DON	230.95
13-Jan-2020 06	3,176	0	420637	03-034-019	Replace Switch (Other)	14-Jan-2020 07:46:46	BHYYEQ	I	DON	17.35
13-Jan-2020 06	3,176	0	420637	03-042-013	Replace Fan Belt	13-Jan-2020 16:41:31	BHYYEQ	I	DON	192.79
13-Jan-2020 06	3,176	0	420637	03-519-001	Replace Front Bumper	15-Jan-2020 10:00:34	BHYYEQ	I	DON	302.29
13-Jan-2020 06	3,176	0	420637	06-100-PMB	Inspect B PMI	14-Jan-2020 08:24:23	BHYYEQ	P	DON	56.53
13-Jan-2020 06	3,176	0	420637	38-100-PMB	Service B PMI	14-Jan-2020 08:24:30	BHYYEQ	P	DON	693.13
30-Apr-2020 0	3,246	0	438674	03-514-002	Replace Shanks or Teeth	05-May-2020 06:03:43	BHYYEQ	E	DON	1,331.59
14-May-2020 1	3,268	0	440778	03-043-030	Replace Aftertreatment Regeneration Device (A	14-May-2020 11:17:43	BHYYEQ	B	DON	2,902.45
24-Jul-2020 05	3,344	0	452358	03-002-024	Replace Glass / Windshield	29-Jul-2020 05:23:32	BHYYEQ	E	DON	631.74
13-Oct-2020 11	3,441	0	466394	03-002-010	Replace Mirrors	14-Oct-2020 10:38:50	BHYYEQ	I	DON	52.03
13-Oct-2020 11	3,441	0	466394	03-019-007	Replace Hose, Tubing & Connectors	26-Oct-2020 17:00:02	BHYYEQ	I	DON	185.79
13-Oct-2020 11	3,441	0	466394	03-051-009	Replace Fire Extinguisher	14-Oct-2020 10:20:35	BHYYEQ	Q	DON	118.93
13-Oct-2020 11	3,441	0	466394	03-065-007	Replace Hoses & Fittings	21-Oct-2020 11:45:44	BHYYEQ	I	DON	460.66
13-Oct-2020 11	3,441	0	466394	03-513-002	Replace Quick Attachment	23-Oct-2020 09:58:41	BHYYEQ	I	DON	401.55
13-Oct-2020 11	3,441	0	466394	06-100-PMA	Inspect A PMI	27-Oct-2020 06:36:11	BHYYEQ	P	DON	46.70

# Unit Job History

Michels Corporation  
Report Printed: 20-Sep-2022 05:49:37 By User: RHEENING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: N1068 - 2016 CAT 336FL										
13-Oct-2020	1	3,441	0	466394	38-100-PMA Service A PMI	14-Oct-2020 10:15:46	BHVEEQ	Q	DON	280.29
02-Nov-2020	1	3,452	0	469947	02-330 Clean Excavator	03-Nov-2020 07:00:16	BWASH	N	DON	196.26
03-Jan-2021	0	3,514	0	481945	06-100-PMA Inspect A PMI	13-Jan-2021 16:48:03	PIPE12	P	DON	0.00
28-Feb-2021	0	4,249	0	493086	06-100-PMA Inspect A PMI	10-Mar-2021 08:26:42	PIPE11	P	DON	0.00
28-Feb-2021	0	4,249	0	493086	06-100-PMB Inspect B PMI	10-Mar-2021 08:26:42	PIPE11	P	DON	0.00
28-Feb-2021	0	4,249	0	493086	06-100-PMC Inspect C PMI	10-Mar-2021 08:26:42	PIPE11	P	DON	0.00
16-Mar-2021	0	4,284	0	496237	06-100-PMA Inspect A PMI	24-Mar-2021 10:32:59	PIPE12	P	DON	0.00
06-Jul-2021	0	4,368	0	519772	24-040 Repair Engine / Motor Systems Group	20-Jul-2021 16:16:46	PIPE12	B	DON	306.10
08-Aug-2021	0	4,368	0	525387	06-100-PMA Inspect A PMI	16-Aug-2021 12:51:58	SCHED	P	DON	0.00
11-Aug-2021	0	4,368	0	533642	03-002-010 Replace Mirrors	23-Sep-2021 11:58:38	PIPE12	B	DON	0.00
11-Aug-2021	0	4,368	0	533642	03-002-069 Replace Support Hood Lift-Gas Charged	23-Sep-2021 11:58:38	PIPE12	B	DON	0.00
11-Aug-2021	0	4,368	0	533642	03-034 Replace Lighting System	23-Sep-2021 11:58:38	PIPE12	B	DON	0.00
14-Aug-2021	0	4,368	0	565441	03-330-001 Replace Bucket and Attachments	09-Feb-2022 16:15:55	PIPE15	B	DON	0.00
16-Nov-2021	0	4,368	0	550303	06-100-PMA Inspect A PMI	16-Nov-2021 06:00:00	SCHED	P	DON	0.00
17-Feb-2022	0	4,368	0	567684	03-063-003 Replace Transceiver - GPS Tracker	17-Feb-2022 09:34:23	ELEC02	Q	DON	500.77
17-May-2022	1	5,116	0	589240	02-002-044 Clean Cab - Complete	17-May-2022 13:07:11	BHVEEQ	Z	DON	27.38
17-May-2022	1	5,116	0	589240	06-100-PMA Inspect A PMI	17-May-2022 11:10:15	BHVEEQ	P	DON	40.88
17-May-2022	1	5,116	0	589240	25-051-009 Remove Fire Extinguisher	17-May-2022 12:02:55	BHVEEQ	Z	DON	23.99
17-May-2022	1	5,116	0	589240	25-063-003 Remove Transceiver - GPS Tracker	17-May-2022 11:28:09	BHVEEQ	Z	DON	12.35
29-Aug-2022	1	5,116	0	612749	02-330 Clean Excavator	31-Aug-2022 11:18:26	BWASH	Z	DON	488.59

Unit No: N1068

Count: 78

25,653.17