

Unit Job History

Michels Corporation
Report Printed: 28-Jul-2023 07:43:35 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: G0339 - 2004 INTERNATIONAL 7300										
29-Apr-2009 1	4,213	31,860	12487	06-100-001	Inspect DO NOT USE - PMI Service	05-May-2009 12:37:51	MPNSHP	P	DON	261.88
29-Apr-2009 1	4,213	31,860	12487	06-100-002	Inspect DO NOT USE - DOT Federal Insp	07-May-2009 07:27:59	MPNSHP	P	DON	110.71
29-Apr-2009 1	4,213	31,860	12487	06-100-011	Inspect Annual Aerial/Boom Inspection	30-Apr-2009 08:07:36	MPNSHP	P	DON	108.12
29-Apr-2009 1	4,213	31,860	12487	18-100-011	Test Annual Aerial/Boom Inspection	01-May-2009 07:21:52	MPNSHP	J	DON	101.54
29-Apr-2009 1	4,213	31,860	12487	38-268	Service Lifting and Pulling	30-Apr-2009 11:15:51	MPNSHP	I	DON	17.69
29-Apr-2009 1	4,213	31,860	12487	21-514-003	Fabricate Liner	30-Apr-2009 13:10:38	MPNSHP	I	DON	35.32
29-Apr-2009 1	4,213	31,860	12487	03-051	Replace General Accessories		MPNSHP	I	CAN	0.00
29-Apr-2009 1	4,213	31,860	12487	02-065-006	Clean Filters, Strainers, Screens & Housing	30-Apr-2009 15:00:00	MPNSHP	I	DON	68.41
29-Apr-2009 1	4,213	31,860	12487	03-079	Replace Safety Devices	01-May-2009 08:38:47	MPNSHP	I	DON	35.56
29-Apr-2009 1	4,213	31,860	12487	03-517	Replace Safety Equipment	01-May-2009 09:00:00	MPNSHP	I	DON	27.29
29-Apr-2009 1	4,213	31,860	12487	07-098	Lubricate Valves & Controls - Bulk Product Trai	01-May-2009 09:59:31	MPNSHP	I	DON	5.42
29-Apr-2009 1	4,213	31,860	12487	24-100-011	Repair Annual Aerial/Boom Inspection	04-May-2009 09:00:00	MPNSHP	I	DON	266.58
29-Apr-2009 1	4,213	31,860	12487	07-100-000	Lubricate On Road Equip / Field Service	06-May-2009 06:23:28	MPNSHP	J	DON	42.63
29-Apr-2009 1	4,213	31,860	12487	38-045	Service Power Plant	05-May-2009 15:00:00	MPNSHP	I	DON	75.54
29-Apr-2009 1	4,213	31,860	12487	11-013-015	Rebuild Desiccant Cartridge Kit - Air	06-May-2009 09:00:00	MPNSHP	I	DON	144.73
29-Apr-2009 1	4,213	31,860	12487	07-025	Lubricate Transfer Case	06-May-2009 11:20:25	MPNSHP	I	DON	26.89
29-Apr-2009 1	4,213	31,860	12487	06-021	Inspect Axles - Driven, Front Steering	07-May-2009 07:23:46	MPNSHP	I	DON	0.00
29-Apr-2009 1	4,213	31,860	12487	18-062-003	Test Compressor Assembly	06-May-2009 13:24:02	MPNSHP	I	DON	57.15
29-Apr-2009 1	4,213	31,860	12487	03-034-010	Replace Socket - Trailer Light Cord	07-May-2009 10:48:02	MPNSHP	I	DON	94.27
29-Apr-2009 1	4,213	31,860	12487	03-013-022	Replace Glad Hands (Service/Emergency)	07-May-2009 14:13:53	MPNSHP	I	DON	81.05
29-Apr-2009 1	4,213	31,860	12487	03-519	Replace Bumper		MPNSHP	I	CAN	0.00
29-Apr-2009 1	4,213	31,860	12487	24-004-002	Repair Faring - Nose	07-May-2009 15:00:00	MPNSHP	I	DON	25.42
29-Apr-2009 1	4,213	31,860	12487	24-021	Repair Axles - Driven, Front Steering	15-May-2009 15:00:00	MPNSHP	I	DON	274.67
29-Apr-2009 1	4,213	31,860	12487	06-014-002	Inspect Bumpers & Attaching Parts	01-Jun-2009 10:46:56	MPNSHP	I	DON	99.58
29-Apr-2009 1	4,213	31,860	12487	14-054-001	Install Horn & Mounting	08-May-2009 15:00:00	MPNSHP	I	DON	685.04
29-Apr-2009 1	4,213	31,860	12487	21-519-002	Fabricate Rear Bumper	01-Jun-2009 10:46:56	MPNSHP	P	DON	204.27
29-Apr-2009 1	4,213	31,860	12487	03-514-003	Replace Liner	21-May-2009 08:43:51	MPNSHP	O	DON	86.26
29-Apr-2009 1	4,213	31,860	12487	03-002-004	Replace Hood	01-Jun-2009 10:46:56	MPNSHP	I	DON	79.51
14-Aug-2009 1	4,221	34,001	19261	03-015-004	Replace Steering Linkage	22-Sep-2009 15:48:50	MPNSHP	I	DON	50.63

Unit Job History

Michels Corporation
Report Printed: 28-Jul-2023 07:43:33 By User: RHEENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: G0339 - 2004 INTERNATIONAL 7300										
14-Aug-2009 1	4,221	34,001	19261	06-100-001	Inspect DO NOT USE - PMI Service	22-Sep-2009 15:48:50	MPNSHP	P	DON	172.04
14-Aug-2009 1	4,221	34,001	19261	24-002	Repair Cab & Sheet Metal	21-Aug-2009 09:25:14	MPNSHP	I	DON	5,647.30
09-Sep-2009 0	4,221	34,001	22191	24-022-008	Repair Pinion Seal	21-Sep-2009 09:38:10	TUMSHP	I	DON	15.47
09-Sep-2009 0	4,221	34,001	22191	38-100-001	Service DO NOT USE - PMI Service	21-Sep-2009 09:38:10	TUMSHP	P	DON	92.79
05-Nov-2009 1	4,221	34,001	29219	06-100-001	Inspect DO NOT USE - PMI Service	05-Nov-2009 11:40:17	TUMSHP	F	DON	283.73
05-Nov-2009 1	4,221	34,001	29219	24-026	Repair Transmission - Main, Manual	05-Nov-2009 11:38:34	TUMSHP	F	DON	1,248.16
09-Apr-2010 0	4,221	37,547	39326	01-013	Adjust Brakes	22-Apr-2010 14:12:32	TUMSHP	I	DON	30.93
09-Apr-2010 0	4,221	37,547	39326	06-100-002	Inspect DO NOT USE - DOT Federal Insp	22-Apr-2010 14:09:59	TUMSHP	P	DON	61.86
09-Apr-2010 0	4,221	37,547	39326	07-268-009	Lubricate Boom Structure	22-Apr-2010 14:12:32	TUMSHP	I	DON	15.47
25-May-2010 1	4,528	37,548	42312	06-100-001	Inspect DO NOT USE - PMI Service	01-Jun-2010 10:57:49	TUMSHP	P	DON	46.40
13-Aug-2010 1	4,528	37,548	47870	02-002-044	Clean Cab - Complete	17-Aug-2010 07:15:07	MPNSHP	Q	DON	281.49
13-Aug-2010 1	4,528	37,548	47870	24-268-005	Repair Controls		MPNSHP	B	WR	0.00
21-Sep-2010 1	4,528	37,548	50444	14-002-048	Install Upholstery Trim - Cab	29-Sep-2010 06:38:41	MPNSHP	I	DON	20.29
21-Sep-2010 1	4,528	37,548	50444	14-033	Install Ignition System	28-Sep-2010 14:44:53	MPNSHP	I	DON	18.50
21-Sep-2010 1	4,528	37,548	50444	03-002-020	Replace Side Door Mechanism	01-Oct-2010 09:00:00	MPNSHP	I	DON	94.27
21-Sep-2010 1	4,528	37,548	50444	24-001-008	Repair Motor - Blower	23-Sep-2010 15:00:00	MPNSHP	I	DON	53.98
21-Sep-2010 1	4,528	37,548	50444	24-002-036	Repair Tilting Mechanism	25-Sep-2010 11:08:33	MPNSHP	I	DON	35.85
21-Sep-2010 1	4,528	37,548	50444	24-003-010	Repair Air Pressure Gauge (Pri/Sec)		MPNSHP	I	CAN	0.00
21-Sep-2010 1	4,528	37,548	50444	24-268-003	Repair Hydraulics	01-Oct-2010 11:59:54	MPNSHP	I	DON	277.18
21-Sep-2010 1	4,528	37,548	50444	24-268-005	Repair Controls		MPNSHP	B	CAN	0.00
21-Sep-2010 1	4,528	37,548	50444	06-100-009	Inspect Safety Check	23-Sep-2010 09:00:00	MPNSHP	P	DON	80.09
21-Sep-2010 1	4,528	37,548	50444	06-100-011	Inspect Annual Aerial/Boom Inspection	09-Nov-2010 16:55:24	MPNSHP	P	DON	630.89
21-Sep-2010 1	4,528	37,548	50444	24-065	Repair Hydraulic Systems - Special Application	13-Oct-2010 15:00:00	MPNSHP	I	DON	1,648.53
21-Sep-2010 1	4,528	37,548	50444	03-268-015	Replace Shields and Guards	01-Oct-2010 12:02:50	MPNSHP	I	DON	1,262.74
21-Sep-2010 1	4,528	37,548	50444	03-051	Replace General Accessories	23-Sep-2010 11:59:09	MPNSHP	I	DON	221.13
21-Sep-2010 1	4,528	37,548	50444	03-051-009	Replace Fire Extinguisher	23-Sep-2010 10:41:26	MPNSHP	Q	DON	1,630.82
21-Sep-2010 1	4,528	37,548	50444	03-053-005	Replace Markings - Vehicle - Decals	01-Oct-2010 11:08:13	MPNSHP	I	DON	99.96
21-Sep-2010 1	4,528	37,548	50444	03-002-026	Replace Weather Stripping, Gaskets & Bumpers	23-Sep-2010 15:08:34	MPNSHP	I	DON	119.82
21-Sep-2010 1	4,528	37,548	50444	24-268-008	Repair Personnel Bucket	25-Sep-2010 09:39:58	MPNSHP	I	DON	210.13

Unit Job History

Michels Corporation
Report Printed: 28-Jul-2023 07:43:33 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
--------------	---------	---------	------------	----------	-----------------	----------------	--------------	------------	------------	------------

Unit No: G0339 - 2004 INTERNATIONAL 7300

21-Sep-2010 1	4,528	37,548	50444	24-268-009	Repair Boom Structure	25-Sep-2010 10:58:21	MPNSHP	I	DON	644.93
21-Sep-2010 1	4,528	37,548	50444	24-013-012	Repair Electric Brakes	27-Sep-2010 08:32:29	MPNSHP	I	DON	221.99
21-Sep-2010 1	4,528	37,548	50444	06-100-001	Inspect DO NOT USE - PMI Service	27-Sep-2010 09:00:00	MPNSHP	I	DON	231.69
21-Sep-2010 1	4,528	37,548	50444	24-002-020	Repair Side Door Mechanism	01-Oct-2010 12:02:06	MPNSHP	I	DON	16.13
21-Sep-2010 1	4,528	37,548	50444	11-268-016	Rebuild Gearbox / Actuator Assembly	01-Oct-2010 12:00:33	MPNSHP	I	DON	334.64
21-Sep-2010 1	4,528	37,548	50444	24-044-007	Repair Throttle Controls	01-Oct-2010 07:22:37	MPNSHP	I	DON	188.56
21-Sep-2010 1	4,528	37,548	50444	03-053-999	Replace Vehicle Fluids, Lubricants, Gases, & Pa	01-Oct-2010 14:38:58	MPNSHP	I	DON	918.63
21-Sep-2010 1	4,528	37,548	50444	02-002-044	Clean Cab - Complete	18-Oct-2010 15:00:00	MPNSHP	Q	DON	239.44
21-Sep-2010 1	4,528	37,548	50444	14-051	Install General Accessories	05-Oct-2010 13:02:41	MPNSHP	I	DON	70.78
21-Sep-2010 1	4,528	37,548	50444	26-077-001	Weld Support - Frame Assembly	20-Oct-2010 13:27:25	MPNSHP	I	DON	163.57
15-Nov-2010 0	4,717	40,717	54221	06-100-009	Inspect Safety Check	19-Nov-2010 07:18:54	MPNSHP	P	DON	78.22
15-Nov-2010 0	4,717	40,717	54221	24-268-005	Repair Controls	19-Nov-2010 07:20:34	MPNSHP	B	DON	78.22
09-Mar-2011 0	4,749	61,183	61183	03-041-001	Replace Air Cleaner	16-Mar-2011 07:47:29	MPNSHP	B	DON	35.71
23-Mar-2011 0	4,780	61,838	61838	03-001-008	Replace Motor - Blower	24-Mar-2011 07:40:30	MPNSHP	B	DON	35.71
13-Jun-2011 0	4,921	67,544	67544	06-100-001	Inspect DO NOT USE - PMI Service	15-Jun-2011 10:37:18	MPNSHP	P	DON	178.56
13-Jun-2011 0	4,921	67,544	67544	06-100-002	Inspect DO NOT USE - DOT Federal Insp	15-Jun-2011 10:38:41	MPNSHP	P	DON	35.71
18-Oct-2011 0	4,921	41,724	74811	06-100-011	Inspect Annual Aerial/Boom Inspection	03-Nov-2011 12:57:03	MPNSHP	P	DON	1,110.78
18-Oct-2011 0	4,921	41,724	74811	14-055-012	Install Cargo Restraints	26-Oct-2011 07:47:31	MPNSHP	P	DON	178.56
18-Oct-2011 0	4,921	41,724	74811	24-268-009	Repair Boom Structure	26-Oct-2011 07:48:36	MPNSHP	I	DON	71.42
13-Feb-2012 0	5,367	43,610	82656	03-043-003	Replace Muffler	21-Feb-2012 17:00:00	MPNSHP	I	DON	169.13
13-Feb-2012 0	5,367	43,610	82656	03-268-015	Replace Shields and Guards	13-Feb-2012 17:00:00	MPNSHP	E	DON	33.83
13-Feb-2012 0	5,367	43,610	82656	06-100-001	Inspect DO NOT USE - PMI Service	16-Feb-2012 17:00:00	MPNSHP	P	DON	202.95
13-Feb-2012 0	5,367	43,610	82656	24-024-006	Repair Center Bearing	28-Feb-2012 17:00:00	MPNSHP	B	DON	101.48
23-Apr-2012 0	5,380	87,672	87672	24-268-005	Repair Controls	08-May-2012 17:00:00	MPNSHP	B	DON	202.95
26-Jul-2012 14		93,094	93094	06-100-011	Inspect Annual Aerial/Boom Inspection		MPNOFC	P	CAN	0.00
30-Aug-2012 1		43,639	95838	06-100-011	Inspect Annual Aerial/Boom Inspection	30-Aug-2012 13:12:59	MPNSHP	P	DON	894.56
28-Sep-2012 1		43,639	99862	06-100-009	Inspect Safety Check	23-Oct-2012 10:42:49	MPNSHP	P	DON	622.12
09-Oct-2012 1		43,639	98037	06-100-DOT	Inspect DOT Federal Inspection	11-Oct-2012 10:12:07	MPNSHP	P	DON	1,236.16
15-Oct-2012 1		43,639	99860	03-268-014	Replace Leveling Assembly	23-Oct-2012 10:33:32	MPNSHP	P	DON	5,419.65

Unit Job History

Michels Corporation
Report Printed: 28-Jul-2023 07:43:35 By User: RHEINING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: G0339 - 2004 INTERNATIONAL 7300										
30-Oct-2012 1			102784	01-013	Adjust Brakes	30-Oct-2012 17:00:00	SYRCNY	B	DON	67.93
30-Oct-2012 1			102784	24-013-011	Repair Anti-Lock Sensor Assembly	30-Oct-2012 17:00:00	SYRCNY	B	DON	152.15
27-Dec-2012 1	5,773	46,883	115836	06-100-PMA	Inspect A PMI	27-Dec-2012 11:45:48	BVLOFC	P	DON	284.36
27-Dec-2012 1	5,773	46,883	115836	38-022	Service Axles - Driven, Rear	27-Dec-2012 11:45:48	BVLOFC	I	DON	59.12
27-Dec-2012 1	5,773	46,883	115836	38-027	Service Transmission - Main, Automatic	27-Dec-2012 11:45:48	BVLOFC	I	DON	203.17
28-Dec-2012 0	5,773	46,865	116716	06-100-PMA	Inspect A PMI	28-Dec-2012 08:38:21	BVLOFC	P	DON	233.73
28-Dec-2012 0	5,773	46,865	116716	03-044-002	Replace Filters	28-Dec-2012 08:32:23	BVLOFC	F	DON	89.84
28-Dec-2012 0	5,773	46,865	116716	03-065-006	Replace Filters, Strainers, Screens & Housing	28-Dec-2012 08:38:21	BVLOFC	F	DON	250.84
04-Jan-2013 06	5,773	46,865	104223	06-100-PMA	Inspect A PMI	04-Jan-2013 17:00:00	MPNOFC	P	DON	290.88
04-Jan-2013 06	5,773	46,865	104223	24-022-003	Repair Differential Carrier	04-Jan-2013 17:00:00	MPNSHP	I	DON	101.53
04-Jan-2013 06	5,773	46,865	104223	38-027	Service Transmission - Main, Automatic	04-Jan-2013 17:00:00	MPNSHP	P	DON	185.17
04-Jan-2013 06	5,773	46,865	104223	38-268-009	Service Boom Structure	04-Jan-2013 17:00:00	MPNOFC	P	DON	92.79
13-Feb-2013 1	5,773	46,865	107894	14-052-003	Install Radio Equipment	13-Feb-2013 12:56:11	BBODY	C	DON	25.24
15-May-2013 1	5,885	47,418	117105	03-268-003	Replace Hydraulics	15-May-2013 17:00:00	MPNOFC	B	DON	61.86
25-Jun-2013 06	5,992	47,869	122459	24-268-009	Repair Boom Structure	25-Jun-2013 17:00:00	MPNOFC	B	DON	30.93
16-Jul-2013 11	6,058	48,903	124031	06-100-011	Inspect Annual Aerial/Boom Inspection		MPNOFC	P	CAN	0.00
16-Jul-2013 11	6,058	48,903	124031	06-100-PMA	Inspect A PMI	24-Jul-2013 17:00:00	MPNOFC	P	DON	2,148.19
16-Jul-2013 11	6,058	48,903	124031	24-054-002	Repair Alarm - Reverse Signal	26-Sep-2013 17:00:00	MPNOFC	I	DON	30.93
23-Sep-2013 1	6,058	48,903	132274	06-100-011	Inspect Annual Aerial/Boom Inspection	23-Sep-2013 17:00:00	MPNSHP	P	DON	5,731.87
23-Sep-2013 1	6,058	48,903	132274	06-100-DOT	Inspect DOT Federal Inspection	23-Sep-2013 17:00:00	MPNSHP	P	DON	54.71
16-Oct-2013 11	6,058	48,903	141579	03-017-001	Replace Tire - Pneumatic	16-Oct-2013 10:33:30	BTIRE	E	DON	658.76
17-Oct-2013 01	6,058	48,903	134469	03-015-004	Replace Steering Linkage	17-Oct-2013 17:00:00	MPNOFC	E	DON	77.33
25-Nov-2013 1	6,058	48,903	140250	03-034-006	Replace Warning Lamps - Special Application	26-Nov-2013 11:58:35	MPNSHP	E	DON	33.84
25-Nov-2013 1	6,058	48,903	140250	24-268-008	Repair Personnel Bucket	26-Nov-2013 11:58:00	MPNSHP	O	DON	67.69
16-Dec-2013 1	6,058	48,903	141809	03-065-004	Replace Cylinder	30-Dec-2013 09:45:14	MPNSHP	B	DON	0.00
16-Dec-2013 1	6,058	48,903	141809	03-268-005	Replace Controls	30-Dec-2013 09:47:04	MPNSHP	B	DON	0.00
16-Dec-2013 1	6,058	48,903	141809	03-706-005	Replace Hydraulic Pumps	30-Dec-2013 09:51:12	MPNSHP	B	DON	0.00
16-Jan-2014 1	6,466	50,940	143609	02-065-015	Clean Pump - Variable Displacement Type	16-Jan-2014 10:36:30	MPNSHP	I	DON	68.94
16-Jan-2014 1	6,466	50,940	143609	03-268-007	Replace Winches	16-Jan-2014 10:36:10	MPNSHP	I	DON	68.94

Unit Job History

Michels Corporation
Report Printed: 28-Jul-2023 07:43:35 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: G0339 - 2004 INTERNATIONAL 7300										
16-Apr-2014 0	6,466	50,940	154301	11-040	Rebuild Engine / Motor Systems Group		MPNSHP	O	CAN	0.00
16-Apr-2014 0	6,466	50,940	154301	25-024	Remove Driveshafts	21-Apr-2014 10:08:33	MPNSHP	P	DON	1,366.53
16-Apr-2014 0	6,466	50,940	154301	35-040	Diagnose Engine / Motor Systems Group		MPNSHP	I	CAN	0.00
16-Apr-2014 0	6,466	50,940	154301	03-027-029	Replace Oil Pump Assembly	21-Apr-2014 10:16:35	MPNSHP	I	DON	2,345.52
16-Apr-2014 0	6,466	50,940	154301	03-042-008	Replace Oil Cooler	21-Apr-2014 10:11:49	MPNSHP	O	DON	1,008.35
16-Apr-2014 0	6,466	50,940	154301	03-044-004	Replace Injectors - Mechanical	21-Apr-2014 10:14:29	MPNSHP	O	DON	12,842.51
05-May-2014 1	6,705	51,486	158373	06-065	Inspect Hydraulic Systems - Special Application	05-May-2014 14:33:26	MPNSHP	I	DON	109.95
05-May-2014 1	6,705	51,486	158373	07-100	Lubricate PMI	05-May-2014 14:33:01	MPNSHP	P	DON	54.97
09-May-2014 1	6,706	51,543	158018	03-063-003	Replace Transceiver - GPS Tracker	09-May-2014 00:00:00	MPNSHP	C	DON	222.90
04-Jun-2014 01	6,706	51,543	162169	03-043	Replace Exhaust System	04-Jun-2014 08:13:10	MPNSHP	I	DON	54.97
08-Aug-2014 1	7,502	169045	169045	24-003-001	Repair Gauges & Warning Devices	08-Aug-2014 15:12:40	MPNSHP	B	DON	34.46
08-Aug-2014 1	7,502	169045	169045	24-268-015	Repair Shields and Guards	08-Aug-2014 15:12:26	MPNSHP	B	DON	34.46
05-Sep-2014 1	6,839	52,098	171422	06-100-DOT	Inspect DOT Federal Inspection	16-Sep-2014 00:00:00	MPNSHP	P	DON	0.00
05-Sep-2014 1	6,839	52,098	171422	06-100-011	Inspect Annual Aerial/Boom Inspection	15-Sep-2014 10:04:07	MPNSHP	P	DON	1,064.13
25-Nov-2014 1	6,857	53,078	182316	06-100-009	Inspect Safety Check	26-Nov-2014 06:50:19	MPNSHP	P	DON	243.52
25-Nov-2014 1	6,857	53,078	182316	03-002-010	Replace Mirrors	26-Nov-2014 11:45:35	MPNSHP	I	DON	121.67
25-Nov-2014 1	6,857	53,078	182316	06-100-PMMA	Inspect A PMI	26-Nov-2014 13:46:29	MPNSHP	P	DON	240.71
25-Nov-2014 1	6,857	53,078	182316	03-002-023	Replace Handles - Inner & Outer	26-Nov-2014 09:55:46	MPNSHP	I	DON	27.07
25-Nov-2014 1	6,857	53,078	182316	24-042-002	Repair Radiator	26-Nov-2014 15:22:22	MPNSHP	I	DON	55.78
25-Nov-2014 1	6,857	53,078	182316	03-053-005	Replace Markings - Vehicle - Decals	17-Dec-2014 13:03:17	MPNSHP	I	DON	146.35
25-Nov-2014 1	6,857	53,078	182316	03-053-007	Replace Hardware - Expendable Items	17-Dec-2014 13:03:14	MPNSHP	I	DON	157.46
25-Nov-2014 1	6,857	53,078	182316	03-065	Replace Hydraulic Systems - Special Application	26-Nov-2014 15:23:31	MPNSHP	I	DON	20.84
25-Nov-2014 1	6,857	53,078	182316	03-079	Replace Safety Devices	17-Dec-2014 13:02:31	MPNSHP	I	DON	741.96
25-Nov-2014 1	6,857	53,078	182316	24-002-068	Repair Service Body / Utility Box	26-Nov-2014 11:29:39	MPNSHP	I	DON	2.57
25-Nov-2014 1	6,857	53,078	182316	03-013-035	Replace Clevis Pins	26-Nov-2014 09:55:32	MPNSHP	I	DON	71.22
25-Nov-2014 1	6,857	53,078	182316	03-017-001	Replace Tire - Pneumatic	26-Nov-2014 08:07:40	MPNSHP	I	DON	555.19
19-Jan-2015 05	6,857	53,078	188169	03-065-004	Replace Cylinder	09-Jun-2015 00:00:00	MPNSHP	P	DON	6,894.88
19-Jan-2015 05	6,857	53,078	188169	06-100-011	Inspect Annual Aerial/Boom Inspection	09-Jun-2015 00:00:00	MPNSHP	P	DON	587.17
19-Jan-2015 05	6,857	53,078	188169	38-065	Service Hydraulic Systems - Special Applicator	09-Jun-2015 00:00:00	MPNSHP	I	DON	178.27

Unit Job History

Michels Corporation
Report Printed: 28-Jul-2023 07:43:35 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Job Status	Total Cost
Unit No: G0339 - 2004 INTERNATIONAL 7300											
19-Jan-2015 05	6,857	53,078	188169	38-268-009	Service Boom Structure	09-Jun-2015 00:00:00	MPNSHP	I	DON		1,354.60
19-Jan-2015 05	6,857	53,078	188169	38-098-007	Service One-Way Check Valve Assembly	09-Jun-2015 00:00:00	MPNSHP	I	DON		1,366.08
19-Jan-2015 05	6,857	53,078	188169	07-268-014	Lubricate Leveling Assembly	09-Jun-2015 00:00:00	MPNSHP	I	DON		432.17
19-Jan-2015 05	6,857	53,078	188169	01-079	Adjust Safety Devices	09-Jun-2015 00:00:00	MPNSHP	I	DON		444.46
19-Jan-2015 05	6,857	53,078	188169	02-010	Clean Chassis Group	09-Jun-2015 00:00:00	MPNSHP	I	DON		94.26
23-Jul-2015 07	6,938	53,921	208720	06-100-009	Inspect Safety Check	07-Oct-2015 07:06:00	MPNSHP	P	DON		132.82
23-Jul-2015 07	6,938	53,921	208720	14-055-012	Install Cargo Restraints	02-Nov-2015 17:34:52	MPNSHP	P	DON		841.63
23-Jul-2015 07	6,938	53,921	208720	01-053-999	Adjust Vehicle Fluids, Lubricants, Gases, & Part	06-Oct-2015 14:00:40	MPNSHP	I	DON		218.65
23-Jul-2015 07	6,938	53,921	208720	03-002	Replace Cab & Sheet Metal	06-Oct-2015 14:01:06	MPNSHP	I	CAN		0.00
23-Jul-2015 07	6,938	53,921	208720	02-268-008	Clean Personnel Bucket	07-Oct-2015 07:05:20	MPNSHP	I	DON		25.19
23-Jul-2015 07	6,938	53,921	208720	03-013-031	Replace Drain Valve - Air Tank	07-Oct-2015 14:01:24	MPNSHP	I	DON		54.63
23-Jul-2015 07	6,938	53,921	208720	14-002-067	Install Keys - Door / Ignition	06-Oct-2015 14:01:24	MPNSHP	I	DON		10.17
23-Jul-2015 07	6,938	53,921	208720	24-268-008	Repair Personnel Bucket	07-Oct-2015 06:28:03	MPNSHP	I	DON		137.39
23-Jul-2015 07	6,938	53,921	208720	03-002-035	Replace Windshield Wiper & Washer	06-Oct-2015 12:51:36	MPNSHP	I	DON		10.28
23-Jul-2015 07	6,938	53,921	208720	03-013-022	Replace Glad Hands (Service/Emergency)	06-Oct-2015 14:00:52	MPNSHP	I	DON		15.74
23-Jul-2015 07	6,938	53,921	208720	03-041-001	Replace Air Cleaner	06-Oct-2015 12:48:56	MPNSHP	I	DON		45.71
23-Jul-2015 07	6,938	53,921	208720	24-002-025	Repair Glass Channels	06-Oct-2015 12:02:02	MPNSHP	I	DON		30.10
23-Jul-2015 07	6,938	53,921	208720	03-053-007	Replace Hardware - Expendable Items	06-Oct-2015 17:30:33	MPNSHP	I	DON		133.83
23-Jul-2015 07	6,938	53,921	208720	24-506-002	Repair Hydraulic Tank	06-Oct-2015 16:54:42	MPNSHP	I	DON		92.44
23-Jul-2015 07	6,938	53,921	208720	26-112-006	Weld Outrigger Assembly	02-Nov-2015 17:35:02	MPNSHP	I	DON		43.19
23-Jul-2015 07	6,938	53,921	208720	15-002	Paint Prep Cab & Sheet Metal	06-Oct-2015 17:33:50	MPNSHP	I	DON		20.23
23-Jul-2015 07	6,938	53,921	208720	06-100-DOT	Inspect DOT Federal Inspection	07-Oct-2015 09:23:10	MPNSHP	I	DON		12.99
23-Jul-2015 07	6,938	53,921	208720	03-002-002	Replace Fenders	06-Oct-2015 12:49:23	MPNSHP	E	DON		388.87
21-Oct-2015 21	6,857		219169	06-268-004	Inspect Supports	14-Jan-2016 11:05:36	MPNFLD	O	DON		93.06
28-Oct-2015 0:	6,857	54,307	219885	06-026	Inspect Transmission - Main, Manual	28-Oct-2015 06:18:14	BTRUCK	O	DON		386.22
28-Oct-2015 0:	6,857	54,307	219885	24-027	Repair Transmission - Main, Automatic	28-Oct-2015 06:18:14	BTRUCK	I	DON		688.20
28-Mar-2016 1	7,080	54,938	239146	02-002-044	Clean Cab - Complete	29-Mar-2016 11:12:21	MPNSHP	I	DON		240.33
28-Mar-2016 1	7,080	54,938	239146	03-001-002	Replace Heating & Ventilating	16-Jun-2016 07:41:52	MPNSHP	I	DON		92.29
28-Mar-2016 1	7,080	54,938	239146	03-013-016	Replace Air Dryer / Purge Valve	23-May-2016 15:13:11	MPNSHP	I	DON		189.78

Unit Job History

Michels Corporation
Report Printed: 28-Jul-2023 07:43:35 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: G0339 - 2004 INTERNATIONAL 7300										
28-Mar-2016	7,080	54,938	239146	03-034-006	Replace Warning Lamps - Special Application	31-May-2016 09:31:04	MPNSHP	I	DON	82.42
28-Mar-2016	7,080	54,938	239146	03-034-020	Replace Dome / Reading Light	24-May-2016 12:04:05	MPNSHP	I	DON	164.71
28-Mar-2016	7,080	54,938	239146	03-045-023	Replace Engine Belts	23-May-2016 15:47:46	MPNSHP	I	DON	79.24
28-Mar-2016	7,080	54,938	239146	03-051-009	Replace Fire Extinguisher	16-Jun-2016 07:41:41	MPNSHP	I	DON	20.06
28-Mar-2016	7,080	54,938	239146	03-053-004	Replace Safety Equipment	24-May-2016 09:57:03	MPNSHP	I	DON	158.56
28-Mar-2016	7,080	54,938	239146	03-053-005	Replace Markings - Vehicle - Decals	24-May-2016 16:32:29	MPNSHP	I	DON	124.59
28-Mar-2016	7,080	54,938	239146	03-059-002	Replace Pintle Hook Assembly	16-Jun-2016 07:41:49	MPNSHP	I	DON	84.37
28-Mar-2016	7,080	54,938	239146	06-100-009	Inspect Safety Check	23-May-2016 15:14:58	MPNSHP	P	DON	274.66
28-Mar-2016	7,080	54,938	239146	06-100-011	Inspect Annual Aerial/Boom Inspection	04-Apr-2016 00:00:00	MPNSHP	P	DON	1,253.96
28-Mar-2016	7,080	54,938	239146	06-100-DOT	Inspect DOT Federal Inspection	23-May-2016 16:33:02	MPNSHP	P	DON	24.03
28-Mar-2016	7,080	54,938	239146	06-100-PMA	Inspect A PMI	23-May-2016 15:15:02	MPNSHP	P	DON	270.92
28-Mar-2016	7,080	54,938	239146	21-518-001	Fabricate Steps	26-May-2016 06:59:21	MPNSHP	I	DON	207.28
28-Mar-2016	7,080	54,938	239146	24-510-002	Repair Tool Box	16-Jun-2016 07:41:46	MPNSHP	I	DON	5.75
15-Aug-2016	7,080	54,938	255646	03-065-007	Replace Hoses & Fittings	15-Aug-2016 15:29:22	MPNSHP	E	DON	697.10
15-Aug-2016	7,080	54,938	255646	24-268	Repair Lifting and Pulling	15-Aug-2016 16:30:22	MPNSHP	E	DON	104.80
15-Aug-2016	7,080	54,938	255646	35-056	Diagnose Power Take Off	24-Feb-2017 08:22:10	MPNSHP	I	DON	0.00
15-Aug-2016	7,080	54,938	255646	06-100-011	Inspect Annual Aerial/Boom Inspection	27-Mar-2017 08:01:46	MPNSHP	P	DON	734.29
15-Aug-2016	7,080	54,938	255646	06-100-DOT	Inspect DOT Federal Inspection	23-Feb-2017 11:21:54	MPNSHP	P	DON	17.06
15-Aug-2016	7,080	54,938	255646	03-053-100	Replace Manual	24-Feb-2017 08:38:23	MPNSHP	I	DON	220.62
15-Aug-2016	7,080	54,938	255646	06-100-009	Inspect Safety Check	20-Feb-2017 16:30:27	MPNSHP	P	DON	250.29
15-Aug-2016	7,080	54,938	255646	03-065-006	Replace Filters, Strainers, Screens & Housing	16-Feb-2017 15:08:27	MPNSHP	I	DON	67.54
15-Aug-2016	7,080	54,938	255646	24-065-001	Repair Hydraulic Systems	20-Feb-2017 09:48:38	MPNSHP	I	DON	1,285.01
15-Aug-2016	7,080	54,938	255646	24-059-002	Repair Pintle Hook Assembly	17-Feb-2017 13:47:38	MPNSHP	I	DON	33.38
15-Aug-2016	7,080	54,938	255646	03-051-009	Replace Fire Extinguisher	17-Feb-2017 16:31:03	MPNSHP	I	DON	97.76
15-Aug-2016	7,080	54,938	255646	07-002-044	Lubricate Cab - Complete	23-Feb-2017 11:57:15	MPNSHP	I	DON	18.77
15-Aug-2016	7,080	54,938	255646	01-112-006	Adjust Outrigger Assembly	27-Mar-2017 08:04:26	MPNFLD	I	DON	1,438.99
15-Aug-2016	7,080	54,938	255646	03-053-005	Replace Markings - Vehicle - Decals	27-Mar-2017 08:02:08	MPNFLD	I	DON	41.60
15-Mar-2017	7,080	54,938	281520	24-002-003	Repair Running Boards / Step Tubes	17-Mar-2017 09:28:54	MEO546	P	DON	31.86
15-Mar-2017	7,080	54,938	281520	06-065-017	Inspect Reservoir/Tank	24-Mar-2017 10:33:45	MEO546	P	DON	31.86

Unit Job History

Michels Corporation
Report Printed: 28-Jul-2023 07:43:35 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: G0339 - 2004 INTERNATIONAL 7300										
20-Jun-2017 11	7,291	55,747	293678	06-100-009	Inspect Safety Check	22-Jun-2017 15:14:58	MPNSHP	P	DON	169.90
20-Jun-2017 11	7,291	55,747	293678	03-045-024	Replace Seal - Crankshaft (Front)		MPNSHP	I	WR	0.00
20-Jun-2017 11	7,291	55,747	293678	06-100-PMA	Inspect A PMI	21-Jun-2017 14:44:25	MPNSHP	P	DON	312.06
20-Jun-2017 11	7,291	55,747	293678	03-018-003	Replace Wheels	21-Jun-2017 16:30:20	MPNSHP	I	DON	2,123.17
20-Jun-2017 11	7,291	55,747	293678	03-032-001	Replace Battery	21-Jun-2017 14:07:06	MPNSHP	I	DON	228.28
20-Jun-2017 11	7,291	55,747	293678	03-053-007	Replace Hardware - Expendable Items	22-Jun-2017 15:10:09	MPNSHP	I	DON	315.41
20-Jun-2017 11	7,291	55,747	293678	03-013-035	Replace Clevis Pins	22-Jun-2017 11:44:36	MPNSHP	I	DON	37.07
20-Jun-2017 11	7,291	55,747	293678	24-001-001	Repair Air Conditioning Assembly	21-Jun-2017 15:41:48	MPNSHP	I	DON	24.07
20-Jun-2017 11	7,291	55,747	293678	24-015-005	Repair Power Steering Pump	21-Jun-2017 16:30:03	MPNSHP	I	DON	25.62
20-Jun-2017 11	7,291	55,747	293678	03-054-001	Replace Horn & Mounting	22-Jun-2017 11:41:53	MPNSHP	I	DON	215.94
20-Jun-2017 11	7,291	55,747	293678	02-002-044	Clean Cab - Complete	23-Jun-2017 08:46:22	MPNSHP	P	DON	0.00
20-Jun-2017 11	7,291	55,747	293678	24-071-001	Repair Floor / Decking / Flatbed		MPNSHP	P	WR	0.00
01-Aug-2017 00	7,291	55,747	299020	03-777-041	Replace Gearbox	02-Jan-2018 13:37:40	MPNFLD	I	DON	3,826.92
09-Nov-2017 00	7,291	55,747	312865	06-100-PMA	Inspect A PMI		ME0656	P	CAN	0.00
11-Jan-2018 11	7,300	58,164	319121	03-051-009	Replace Fire Extinguisher	23-Mar-2018 16:30:37	MPNSHP	I	DON	72.39
11-Jan-2018 11	7,300	58,164	319121	03-065-006	Replace Filters, Strainers, Screens & Housing	27-Mar-2018 07:31:15	MPNSHP	I	DON	102.52
11-Jan-2018 11	7,300	58,164	319121	24-013-007	Repair Brake Lines & Fittings - Hydraulic & Air	23-Mar-2018 11:57:14	MPNSHP	I	DON	220.47
11-Jan-2018 11	7,300	58,164	319121	24-013-016	Repair Air Dryer / Purge Valve	27-Mar-2018 07:58:19	MPNSHP	I	DON	131.50
11-Jan-2018 11	7,300	58,164	319121	24-045-013	Repair Oil Pan	26-Mar-2018 13:56:35	MPNSHP	I	DON	380.23
11-Jan-2018 11	7,300	58,164	319121	03-065-007	Replace Hoses & Fittings	23-Mar-2018 10:44:29	MPNSHP	I	DON	263.83
11-Jan-2018 11	7,300	58,164	319121	06-100-009	Inspect Safety Check	22-Mar-2018 13:15:04	MPNSHP	I	DON	505.37
11-Jan-2018 11	7,300	58,164	319121	02-002-044	Clean Cab - Complete	12-Jan-2018 16:29:46	MPNSHP	P	DON	158.29
11-Jan-2018 11	7,300	58,164	319121	24-071-001	Repair Floor / Decking / Flatbed	17-Jan-2018 07:02:20	MPNSHP	P	DON	325.40
11-Jan-2018 11	7,300	58,164	319121	06-100-011	Inspect Annual Aerial/Boom Inspection	21-May-2018 14:01:21	MPNSHP	P	DON	1,004.19
11-Jan-2018 11	7,300	58,164	319121	24-078-009	Repair Mud Flaps and Hanger Brackets	27-Mar-2018 15:31:10	MPNSHP	I	DON	221.03
11-Jan-2018 11	7,300	58,164	319121	07-002-044	Lubricate Cab - Complete	30-Mar-2018 10:27:07	MPNSHP	I	DON	119.62
11-Jan-2018 11	7,300	58,164	319121	06-100-DOT	Inspect DOT Federal Inspection	17-Apr-2018 06:21:19	MPNSHP	P	DON	27.50
11-Jan-2018 11	7,300	58,164	319121	24-002-024	Repair Glass / Windshield	16-Apr-2018 15:03:07	MPNSHP	I	DON	866.02
11-Jan-2018 11	7,300	58,164	319121	03-031-001	Replace Generator/Alternator	17-Apr-2018 11:58:10	MPNSHP	I	DON	471.05

Unit Job History

Michels Corporation
Report Printed: 28-Jul-2023 07:43:35 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: G0339 - 2004 INTERNATIONAL 7300										
11-Jan-2018 10	7,300	58,164	319121	03-031-006	Replace Belt - Alternator		MPNSHP	I	CAN	0.00
11-Jan-2018 10	7,300	58,164	319121	24-268-009	Repair Boom Structure	17-Apr-2018 12:47:57	MPNSHP	I	DON	708.84
11-Jan-2018 10	7,300	58,164	319121	24-510-002	Repair Tool Box	23-Mar-2018 14:35:03	MPNSHP	I	DON	237.66
14-Aug-2018 00	7,805	58,278	348085	03-013-002	Replace Rear Brakes & Drums	31-Aug-2018 16:29:49	MPNSHP	I	DON	866.52
14-Aug-2018 00	7,805	58,278	348085	03-065-007	Replace Hoses & Fittings	29-Aug-2018 14:52:09	MPNSHP	I	DON	72.20
14-Aug-2018 00	7,805	58,278	348085	03-017-001	Replace Tire - Pneumatic	05-Nov-2018 10:28:48	MPNSHP	I	DON	1,015.34
14-Aug-2018 00	7,805	58,278	348085	06-100-009	Inspect Safety Check	14-Aug-2018 15:24:52	MPNSHP	P	DON	286.23
14-Aug-2018 00	7,805	58,278	348085	24-065-010	Repair Gear Motor	05-Nov-2018 10:28:41	MPNSHP	I	DON	50.34
14-Aug-2018 00	7,805	58,278	348085	34-065-020	Reseal Control Valve	05-Nov-2018 10:28:44	MPNSHP	I	DON	13.15
14-Aug-2018 00	7,805	58,278	348085	03-268-008	Replace Personnel Bucket	29-Aug-2018 14:12:04	MPNSHP	I	DON	213.30
14-Aug-2018 00	7,805	58,278	348085	03-042-014	Replace Coolant Overflow Reservoir	28-Aug-2018 11:13:24	MPNSHP	I	DON	323.08
14-Aug-2018 00	7,805	58,278	348085	03-053-007	Replace Hardware - Expendable Items	31-Aug-2018 11:57:34	MPNSHP	I	DON	630.65
14-Aug-2018 00	7,805	58,278	348085	14-051-006	Install Safety Devices	04-Sep-2018 16:36:39	MPNSHP	G	DON	199.33
05-Nov-2018 00	7,805	58,278	359900	03-002-037	Replace Seat Assembly	08-Nov-2018 06:47:40	HARFLD	B	DON	879.99
30-Jul-2019 11	8,042	61,814	396450	06-100-011	Inspect Annual Aerial/Boom Inspection	13-Sep-2019 14:02:51	HARFLD	P	DON	195.53
30-Jul-2019 11	8,042	61,814	396450	06-100-PMA	Inspect A PMI	13-Sep-2019 14:02:51	HARFLD	P	DON	0.00
30-Jul-2019 11	8,042	61,814	396450	38-100-PMA	Service A PMI	13-Sep-2019 14:02:51	HARFLD	P	DON	1,308.68
15-Oct-2019 00	8,118	63,928	407483	24-043-007	Repair Exhaust Pipe/Elbow	31-Oct-2019 12:05:00	HARFLD	B	DON	768.88
11-Nov-2019 00	8,189	64,537	411978	03-051-006	Replace Safety Devices	19-Nov-2019 09:52:15	HARFLD	B	DON	1,020.59
11-Nov-2019 00	8,189	64,537	411978	03-065-020	Replace Control Valve	19-Nov-2019 09:52:22	HARFLD	B	DON	195.19
11-Nov-2019 00	8,189	64,537	411978	03-268-009	Replace Boom Structure	22-Dec-2019 11:05:28	HARFLD	N	DON	14,188.64
11-Nov-2019 00	8,189	64,537	411978	38-100-PMA	Service A PMI	20-Nov-2019 06:11:22	HARFLD	P	DON	456.43
11-Nov-2019 00	8,189	64,537	411978	06-100-PMA	Inspect A PMI	20-Nov-2019 06:11:00	HARFLD	P	DON	33.33
28-Apr-2020 00	8,393	66,143	438445	35-015-003	Diagnose Steering Gear	01-May-2020 08:45:51	SYRFLD	B	DON	69.12
28-Apr-2020 00	8,393	66,143	438445	03-015-003	Replace Steering Gear	07-May-2020 15:38:05	SYRFLD	B	DON	3,421.08
09-Jun-2020 10	8,435	66,546	444573	03-052-003	Replace Radio Equipment	09-Jun-2020 17:19:00	ELEC02	Q	DON	28.31
28-Jun-2020 00	8,456	66,633	447940	06-034-004	Inspect Clearance & Marker Lamps	06-Jul-2020 08:29:48	SYRFLD	I	DON	62.52
28-Jun-2020 00	8,456	66,633	447940	06-100-PMA	Inspect A PMI	06-Jul-2020 08:29:41	SYRFLD	P	DON	62.52

Unit Job History

Michels Corporation
Report Printed: 28-Jul-2023 07:43:35 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: G0339 - 2004 INTERNATIONAL 7300										
28-Jun-2020 04	8,456	66,633	447940	19-034-004	Wire/Rewire Clearance & Marker Lamps	06-Jul-2020 08:29:50	SYRFLD	I	DON	125.05
28-Jun-2020 04	8,456	66,633	447940	38-100-PMA	Service A PMI	06-Jul-2020 08:29:58	SYRFLD	P	DON	429.65
18-Jul-2020 08	8,480	66,861	451353	03-013-033	Replace ABS - Extension Cable	23-Jul-2020 07:31:10	SYRFLD	I	DON	362.51
18-Jul-2020 08	8,480	66,861	451353	06-013-033	Inspect ABS - Extension Cable	23-Jul-2020 06:16:37	SYRFLD	O	DON	125.05
30-Jul-2020 06	8,490	66,992	453389	06-100-011	Inspect Annual Aerial/Boom Inspection	15-Sep-2020 10:19:58	SYRFLD	P	DON	602.40
30-Jul-2020 06	8,490	66,992	453389	24-003-010	Repair Air Pressure Gauge (Pri/Sec)	30-Jul-2020 08:36:23	SYRFLD	I	DON	16.66
30-Jul-2020 06	8,490	66,992	453389	34-065-004	Reseal Cylinder	30-Jul-2020 08:36:21	SYRFLD	P	DON	16.66
30-Jul-2020 06	8,490	66,992	453389	06-100-DOT	Inspect DOT Federal Inspection	07-Aug-2020 05:58:47	SYRFLD	P	DON	62.52
30-Jul-2020 06	8,490	66,992	453389	03-045-024	Replace Seal - Crankshaft (Front)	30-Jul-2020 08:36:18	SYRFLD	I	DON	16.66
30-Jul-2020 06	8,490	66,992	453389	03-002-035	Replace Windshield Wiper & Washer	17-Aug-2020 07:30:35	SYRFLD	O	DON	33.53
30-Jul-2020 06	8,490	66,992	453389	03-041-007	Replace Filter - Outer	17-Aug-2020 07:30:39	SYRFLD	O	DON	103.47
30-Jul-2020 06	8,490	66,992	453389	03-065-007	Replace Hoses & Fittings	31-Aug-2020 06:21:56	SYRFLD	O	DON	133.32
14-Sep-2020 04	8,567	67,191	462361	03-024-006	Replace Center Bearing	02-Oct-2020 17:24:45	SYRFLD	I	DON	721.01
14-Sep-2020 04	8,567	67,191	462361	03-054	Replace Horns, Mounting, Signal Alarms	02-Oct-2020 17:24:45	SYRFLD	B	DON	274.09
14-Sep-2020 04	8,567	67,191	462361	06-020	Inspect Drivetrain Group	02-Oct-2020 17:24:45	SYRFLD	O	DON	125.05
03-Nov-2020 04	8,615	67,418	470322	03-015-005	Replace Power Steering Pump	30-Nov-2020 14:45:21	SYRFLD	B	DON	396.59
03-Nov-2020 04	8,615	67,418	470322	03-040	Replace Engine / Motor Systems Group	30-Nov-2020 14:45:21	SYRFLD	B	DON	34.56
03-Nov-2020 04	8,615	67,418	470322	35-015-005	Diagnose Power Steering Pump	30-Nov-2020 14:45:21	SYRFLD	B	DON	34.56
03-Nov-2020 04	8,615	67,418	470322	35-040	Diagnose Engine / Motor Systems Group	30-Nov-2020 14:45:21	SYRFLD	B	DON	34.56
01-Dec-2020 04	8,622	67,421	474831	06-100-007	Inspect In-Service Inspection	10-Dec-2020 11:41:46	SYRFLD	P	DON	34.56
12-Feb-2021 04	8,629	67,423	488145	03-042-012	Replace Clamps and Hoses	24-Feb-2021 15:36:03	SYRFLD	B	DON	340.41
02-Mar-2021 04	8,629	67,423	492326	03-078-009	Replace Mud Flaps and Hanger Brackets	14-Mar-2021 10:07:25	SYRFLD	B	DON	94.87
02-Mar-2021 04	8,629	67,423	492326	03-065-007	Replace Hoses & Fittings	14-Mar-2021 10:07:25	SYRFLD	B	DON	426.91
18-May-2021 04	8,629	67,423	508467	06-100-PMB	Inspect B PMI	02-Jun-2021 09:29:03	SCHED	P	DON	174.92
18-May-2021 04	8,629	67,423	508467	24-002	Repair Cab & Sheet Metal	02-Jun-2021 09:29:03	SYRFLD	E	DON	948.68
18-May-2021 04	8,629	67,423	508467	35-030-001	Diagnose Outrigger Interlock Switch	02-Jun-2021 09:29:03	SYRFLD	B	DON	284.60
20-Aug-2021 04	8,629	67,423	526764	06-100-PMB	Service B PMI	02-Jun-2021 09:29:03	SYRFLD	P	DON	641.94
20-Aug-2021 04	8,629	67,423	526764	06-100-011	Inspect Annual Aerial/Boom Inspection	01-Sep-2021 07:37:08	SCHED	P	DON	0.00
20-Aug-2021 04	8,629	67,423	526764	06-100-DIE	Inspect Dielectric Inspection	01-Sep-2021 07:37:08	SCHED	P	DON	586.10

Unit Job History

Michels Corporation
Report Printed: 28-Jul-2023 07:43:35 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: G0339 - 2004 INTERNATIONAL 7300										
20-Aug-2021 0	8,629	67,423	526764	06-100-DOT	Inspect DOT Federal Inspection	24-Aug-2021 09:21:15	SYRFLD	P	DON	189.74
20-Aug-2021 0	8,629	67,423	526764	24-065	Repair Hydraulic Systems - Special Application:	01-Sep-2021 07:37:08	SYRFLD	B	DON	1,506.65
15-Sep-2021 0	8,629	67,423	532451	03-065-020	Replace Control Valve	29-Sep-2021 14:04:08	SYRFLD	B	DON	2,711.95
12-Oct-2021 0:	8,629	67,423	539847	03-065-007	Replace Hoses & Fittings	18-Oct-2021 09:16:57	SYRFLD	B	DON	379.47
18-Oct-2021 0:	8,629	67,423	539908	03-042-014	Replace Coolant Overflow Reservoir	04-Nov-2021 08:41:50	SYRFLD	B	DON	619.74
03-Dec-2021 0	8,629	67,423	551319	03-063-003	Replace Transceiver - GPS Tracker	06-Dec-2021 06:44:48	SYRFLD	Q	DON	535.76
28-Feb-2022 0	8,629	67,423	580487	03-030-006	Replace Outrigger Interlock Switch	08-Apr-2022 08:23:19	SYRFLD	B	DON	1,600.46
28-Feb-2022 0	8,629	67,423	580487	03-268-045	Replace Man Bucket	14-Apr-2022 06:43:33	SYRFLD	E	DON	211.45
08-Mar-2022 0	8,629	67,423	574160	03-268-022	Replace Boom Strap	20-Mar-2022 11:59:44	SYRFLD	B	DON	189.74
15-Mar-2022 0	8,629	67,423	575904	03-268-042	Replace Console Cover	02-Apr-2022 10:05:27	SYRFLD	E	DON	760.29
02-Jun-2022 0:			593576	06-100-PMA	Inspect A PMI	08-Jun-2022 15:13:29	SYRFLD	P	DON	94.87
02-Jun-2022 0:			593576	07-024-002	Lubricate Drive Shaft, Behind Main Transmissic	08-Jun-2022 15:13:29	SYRFLD	P	DON	94.87
02-Jun-2022 0:			593576	07-268-009	Lubricate Boom Structure	08-Jun-2022 15:13:29	SYRFLD	P	DON	189.74
06-Jun-2022 0:	8,947	67,439	594482	03-044-001	Replace Tank - Fuel, Liquid	08-Jul-2022 09:50:51	SYRFLD	I	DON	2,311.81
06-Jun-2022 0:	8,947	67,439	594482	03-049-004	Replace ECM Sensor	22-Jul-2022 10:02:57	SYRFLD	I	DON	301.03
06-Jun-2022 0:	8,947	67,439	594482	06-100-DOT	Inspect DOT Federal Inspection	23-Jun-2022 09:49:00	SYRFLD	P	DON	94.87
06-Jun-2022 0:	8,947	67,439	594482	03-013-024	Replace Air Tank (Pri / Sec / Wet)	08-Jul-2022 09:50:40	SYRFLD	I	DON	2,355.86
06-Jun-2022 0:	8,947	67,439	594482	03-016-003	Replace Shock Absorber - Front	22-Jul-2022 10:02:53	SYRFLD	I	DON	242.28
06-Jun-2022 0:	8,947	67,439	594482	03-002-035	Replace Windshield Wiper & Washer	08-Jul-2022 09:50:43	SYRFLD	I	DON	121.77
06-Jun-2022 0:	8,947	67,439	594482	24-078-010	Repair Quarter Fender Assembly	08-Jul-2022 09:50:58	SYRFLD	I	DON	47.43
08-Aug-2022 0	9,045	67,452	609483	03-030-001	Replace Outrigger Interlock Switch	23-Aug-2022 09:08:39	SYRFLD	B	DON	189.74
19-Sep-2022 0:	9,047	67,461	619431	03-034-004	Replace Clearance & Marker Lamps	05-Oct-2022 14:54:26	SYRFLD	I	DON	379.47
19-Sep-2022 0:	9,047	67,461	619431	35-031-001	Diagnose Generator/Alternator	05-Oct-2022 14:54:26	SYRFLD	B	DON	94.87
19-Sep-2022 0:	9,047	67,461	619431	03-032-001	Replace Battery	05-Oct-2022 14:54:26	SYRFLD	B	DON	455.19
06-Mar-2023 0	9,073	67,550	657408	06-100-011	Inspect Annual Aerial/Boom Inspection	13-Mar-2023 05:52:55	SYRFLD	P	DON	1,032.50
06-Mar-2023 0	9,073	67,550	657408	06-100-DIE	Inspect Dielectric Inspection	13-Mar-2023 05:52:52	SYRFLD	P	DON	0.00
15-Apr-2023 0	9,098	67,890	667404	03-065-007	Replace Hoses & Fittings	16-Apr-2023 12:51:38	SYRFLD	B	DON	174.92
26-Apr-2023 1	9,105	68,141	670165	06-100-DOT	Inspect DOT Federal Inspection	26-Apr-2023 14:16:22	HARSHP	P	DON	133.94

Unit Job History

Michels Corporation
Report Printed: 28-Jul-2023 07:43:35 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: G0339 - 2004 INTERNATIONAL 7300										
24-Jun-2023 07	9,106		683847	14-017-001	Install Tire - Pneumatic	24-Jun-2023 10:01:31	BTRUCK	O	DON	165.24
24-Jun-2023 07	9,106		683847	06-100-009	Inspect Safety Check	27-Jun-2023 17:00:02	BTRUCK	I	DON	122.25
17-Jul-2023 07	9,106		688591	25-050	Remove Accessories Group	26-Jul-2023 06:39:47	BSETUP	Z	DON	174.37
17-Jul-2023 07	9,106		688591	02-002	Clean Cab & Sheet Metal	28-Jul-2023 05:08:24	BSETUP	Z	DON	319.79

Unit No: G0339

Count: 323

151,887.90