

Unit Job History

Michels Corporation
Report Printed: 09-Aug-2023 11:35:17 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Q1275 - 2017 JOHN DEERE 310HL										
04-Jan-2017 1:	5	0	271832	14-059-002	Install Pintle Hook Assembly	06-Apr-2017 09:00:56	BBKHOE	Q	DON	425.08
04-Jan-2017 1:	5	0	271832	14-063-003	Install Transceiver - GPS Tracker	12-Jan-2017 11:00:00	BHVEEQ	Q	DON	320.30
04-Jan-2017 1:	5	0	271832	IS-310	In-Service Backhoe (Rubber Tire)	06-Apr-2017 09:01:04	BBKHOE	Q	DON	374.35
01-Mar-2017 1	5	0	281214	38-017-011	Service Tire - Foam Filled	01-Mar-2017 13:30:00	BTIRE	F	DON	1,034.22
28-Mar-2017 0	7	0	282825	03-065-032	Replace Seal / O-Ring General	28-Mar-2017 09:54:22	LAVSHP	B	DON	119.32
25-May-2017 1	198	0	290526	24-034-006	Repair Warning Lamps - Special Application	26-May-2017 12:50:21	LAVSHP	E	DON	73.33
10-Aug-2017 1	418	0	300481	24-017-001	Repair Tire - Pneumatic	10-Aug-2017 14:40:35	BBKHOE	B	DON	204.87
14-Dec-2017 0	1,071	0	316067	03-002-001	Replace Radiator Grille		LAVSHP	E	CAN	0.00
14-Dec-2017 0	1,071	0	316067	06-310	Inspect Backhoe (Rubber Tire)	21-Dec-2017 10:15:49	LAVSHP	S	DON	134.86
02-Jan-2018 1:	1,071	0	317838	06-100-PMC	Inspect C PMI	03-Jan-2018 06:00:44	LAVSHP	P	DON	834.81
02-Jun-2018 0:	1,226	0	338106	06-100-PMA	Inspect A PMI	02-Jun-2018 12:04:03	LAVSHP	P	DON	86.52
23-Jul-2018 08	1,458	0	344908	35-044	Diagnose Fuel System	24-Jul-2018 14:10:36	LAVSHP	B	DON	533.93
23-Jul-2018 08	1,458	0	344908	95-MSC-004	Travel Travel Time - To/From Job Site	24-Jul-2018 14:10:39	LAVSHP	B	DON	217.16
21-Aug-2018 C	1,509	0	349129	03-065-007	Replace Hoses & Fittings	31-Aug-2018 11:36:37	LAVSHP	B	DON	521.70
21-Aug-2018 C	1,509	0	349129	06-100-PMA	Inspect A PMI	21-Aug-2018 14:03:55	LAVSHP	P	DON	154.03
10-Nov-2018 1	1,764	0	360227	06-100-PMA	Inspect A PMI	10-Nov-2018 11:52:14	LAVSHP	P	DON	77.12
28-Nov-2018 1	1,787	0	362172	03-017-001	Replace Tire - Pneumatic	02-Jan-2019 14:54:00	BTIRE	P	DON	2,214.13
28-Nov-2018 1	1,787	0	362172	24-002-027	Repair Seat Frames & Springs	28-Nov-2018 15:59:47	LAVSHP	I	DON	6.76
28-Nov-2018 1	1,787	0	362172	03-017-011	Replace Tire - Foam Filled	02-Jan-2019 14:54:00	BTIRE	P	DON	0.00
22-Jan-2019 0:	1,912	0	369272	03-034-002	Replace Stop, Tail, Turn & License	22-Jan-2019 13:16:25	LAVSHP	I	DON	22.30
22-Jan-2019 0:	1,912	0	369272	06-100-007	Inspect In-Service Inspection	22-Jan-2019 09:27:55	LAVSHP	P	DON	49.06
22-Jan-2019 0:	1,912	0	369272	06-100-PMA	Inspect A PMI	22-Jan-2019 11:01:43	LAVSHP	P	DON	439.94
22-Jan-2019 0:	1,912	0	369272	24-065-007	Repair Hoses & Fittings	22-Jan-2019 12:40:17	LAVSHP	I	DON	224.47
14-Jun-2019 0:	2,174	0	390117	06-100-PMA	Inspect A PMI	14-Jun-2019 07:42:25	LAVSHP	P	DON	26.15
14-Jun-2019 0:	2,174	0	390117	38-100-PMA	Service A PMI	14-Jun-2019 07:00:03	LAVSHP	O	DON	183.74
02-Aug-2019 C	2,327	0	396953	03-034-006	Replace Warning Lamps - Special Application	02-Aug-2019 06:22:56	LAVSHP	O	DON	203.17
08-Aug-2019 C	2,340	0	397751	03-310-017	Replace Cutting Edges	08-Aug-2019 07:05:32	LAVSHP	O	DON	255.77
15-Aug-2019 1	2,382	0	398923	03-017-001	Replace Tire - Pneumatic	15-Aug-2019 15:34:53	LAVSHP	O	DON	25.55
15-Aug-2019 1	2,382	0	398923	06-002-037	Inspect Seat Assembly	15-Aug-2019 15:38:33	LAVSHP	O	DON	2.26

Unit Job History

Michels Corporation
Report Printed: 09-Aug-2023 11:35:17 By User: RHEINING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Q1275 - 2017 JOHN DEERE 310HL										
09-Sep-2019 1	2,484	0	402030	03-046-004	Replace Controls - Electronic (Solid State), Elec	11-Sep-2019 14:11:14	ME1371	I	DON	501.63
09-Sep-2019 1	2,484	0	402030	06-100-PMA	Inspect A PMI	09-Sep-2019 10:41:48	ME1371	P	DON	6.62
09-Sep-2019 1	2,484	0	402030	24-034	Repair Lighting System	09-Sep-2019 11:12:22	ME1371	I	DON	9.55
09-Sep-2019 1	2,484	0	402030	38-100-PMA	Service A PMI	09-Sep-2019 10:30:54	ME1371	P	DON	52.54
29-Oct-2019 1	2,825	0	410067	06-100-PMA	Inspect A PMI	29-Oct-2019 12:01:52	ME1371	P	DON	13.33
29-Oct-2019 1	2,825	0	410067	38-100-PMA	Service A PMI	29-Oct-2019 13:46:30	ME1371	P	DON	74.55
13-Jan-2020 08	3,082	0	421339	03-034-014	Replace Auxiliary Work / Flood Light	16-Jan-2020 11:36:51	LAVSHP	I	DON	44.16
13-Jan-2020 08	3,082	0	421339	03-094-011	Replace Coupler - Quick Disconnect	16-Jan-2020 11:36:45	LAVSHP	I	DON	204.97
13-Jan-2020 08	3,082	0	421339	03-310-005	Replace Boom Lock	16-Jan-2020 11:36:54	LAVSHP	I	DON	73.74
13-Jan-2020 08	3,082	0	421339	03-310-007	Replace Outrigger Pads	16-Jan-2020 11:36:57	LAVSHP	I	DON	1,030.39
13-Jan-2020 08	3,082	0	421339	06-100-PMB	Inspect B PMI	16-Jan-2020 11:37:00	LAVSHP	P	DON	36.99
13-Jan-2020 08	3,082	0	421339	38-100-PMC	Service C PMI	16-Jan-2020 11:36:48	LAVSHP	P	DON	825.74
27-Feb-2020 1	3,082	0	428497	03-017-001	Replace Tire - Pneumatic	27-Feb-2020 13:17:42	BTIRE	P	DON	1,546.31
27-Feb-2020 1	3,082	0	428497	03-017-011	Replace Tire - Foam Filled	27-Feb-2020 13:15:40	BTIRE	P	DON	1,704.83
19-May-2020 0	3,342	0	441374	06-100-PMA	Inspect A PMI	19-May-2020 09:40:14	ME1371	P	DON	10.75
19-May-2020 0	3,342	0	441374	38-100-PMA	Service A PMI	19-May-2020 09:22:31	ME1371	P	DON	59.35
02-Jul-2020 09	3,477	0	448644	24-034	Repair Lighting System	02-Jul-2020 10:36:28	ME1371	I	DON	11.11
02-Jul-2020 09	3,477	0	448644	24-268-027	Repair Operator Controls	02-Jul-2020 10:22:15	ME1371	O	DON	23.90
28-Jul-2020 12	3,552	0	452937	06-100-PMA	Inspect A PMI	04-Aug-2020 07:51:13	ROGSHP	P	DON	0.00
28-Jul-2020 12	3,552	0	452937	38-100-PMA	Service A PMI	28-Jul-2020 14:29:44	ROGSHP	P	DON	287.99
19-Nov-2020 1	3,764	0	473043	06-100-PMC	Inspect C PMI	19-Nov-2020 13:34:30	LAVSHP	P	DON	38.00
19-Nov-2020 1	3,764	0	473043	24-065-007	Repair Hoses & Fittings	03-Dec-2020 13:30:57	LAVSHP	I	DON	106.39
19-Nov-2020 1	3,764	0	473043	38-100-PMC	Service C PMI	19-Nov-2020 14:53:07	LAVSHP	I	DON	95.99
29-Jun-2021 11	4,083	0	515709	03-017-011	Replace Tire - Foam Filled	02-Aug-2021 11:57:16	ROGSHP	N	DON	2,504.87
09-Jul-2021 07	4,120	0	517423	06-100-PMA	Inspect A PMI	09-Jul-2021 07:36:47	ME1371	P	DON	14.41
09-Jul-2021 07	4,120	0	517423	38-100-PMA	Service A PMI	09-Jul-2021 08:17:13	ME1371	P	DON	118.83
28-Jul-2021 15	4,218	0	521473	03-310-017	Replace Cutting Edges	28-Jul-2021 16:00:42	TRK400	O	DON	298.04
29-Jul-2021 07	4,233	0	521564	24-017-001	Repair Tire - Pneumatic	12-Aug-2021 11:18:24	OTSSHP	N	DON	668.66
10-Sep-2021 1	4,363	0	530442	06-100-PMA	Inspect A PMI	10-Sep-2021 14:33:25	ME1371	P	DON	33.54

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Q1275 - 2017 JOHN DEERE 310HL										
10-Sep-2021 1	4,363	0	530442	38-100-PMA	Service A PMI	10-Sep-2021 14:13:57	ME1371	P	DON	125.66
20-Oct-2021 1	4,471	0	540667	03-017-001	Replace Tire - Pneumatic	08-Nov-2021 09:58:10	TRK401	O	DON	2,182.51
18-Feb-2022 1	4,547	0	568283	03-063-003	Replace Transceiver - GPS Tracker	19-Feb-2022 13:14:12	ME1371	Q	DON	306.64
18-Feb-2022 1	4,547	0	568283	38-063-003	Service Transceiver - GPS Tracker	21-Feb-2022 11:17:31	SCHEP	N	DON	0.00
23-Feb-2022 0	4,547	0	569195	03-024-005	Replace Universal Joint	28-Feb-2022 05:41:48	LAVSHP	I	DON	555.50
23-Feb-2022 0	4,547	0	569195	03-053-014	Replace Floor Mats	03-Mar-2022 10:24:30	LAVSHP	I	DON	474.16
23-Feb-2022 0	4,547	0	569195	03-065-004	Replace Cylinder	09-Mar-2022 10:36:24	LAVSHP	I	DON	227.15
23-Feb-2022 0	4,547	0	569195	03-310-003	Replace Boom Pins	28-Feb-2022 13:18:52	LAVSHP	I	DON	1,847.62
23-Feb-2022 0	4,547	0	569195	03-528	Replace Bushing	28-Feb-2022 12:37:29	LAVSHP	I	DON	845.49
23-Feb-2022 0	4,547	0	569195	06-065-007	Inspect Hoses & Fittings	23-Feb-2022 14:10:02	LAVSHP	I	DON	77.97
23-Feb-2022 0	4,547	0	569195	06-100-PMA	Inspect A PMI	23-Feb-2022 11:35:18	LAVSHP	P	DON	141.27
23-Feb-2022 0	4,547	0	569195	06-100-PMB	Inspect B PMI	01-Apr-2022 13:41:09	SCHEP	P	DON	0.00
23-Feb-2022 0	4,547	0	569195	34-065-004	Reseal Cylinder	01-Apr-2022 13:40:49	LAVSHP	I	DON	561.01
23-Feb-2022 0	4,547	0	569195	38-100-PMB	Service B PMI	23-Feb-2022 12:59:06	LAVSHP	P	DON	421.92
01-Jun-2022 1	4,721	0	592762	06-100-PMA	Inspect A PMI	01-Jun-2022 14:45:47	TRK401	P	DON	62.92
01-Jun-2022 1	4,721	0	592762	38-100-PMA	Service A PMI	03-Jun-2022 11:30:43	TRK401	P	DON	110.00
05-Oct-2022 0	4,890	0	621906	06-100-PMA	Inspect A PMI	05-Oct-2022 14:21:20	TRK400	P	DON	63.71
05-Oct-2022 0	4,890	0	621906	38-100-PMA	Service A PMI	05-Oct-2022 14:50:34	TRK400	I	DON	113.18
15-Feb-2023 1	4,979	0	652934	03-002-061	Replace Seat Cushion	15-Feb-2023 14:32:34	LAVSHP	I	DON	447.38
15-Feb-2023 1	4,979	0	652934	06-100-WIN	Inspect Winterization Inspection	15-Feb-2023 13:45:27	LAVSHP	P	DON	54.45
27-Apr-2023 1	5,010	0	670512	03-013-026	Replace Handle - Parking Brake Release	27-Apr-2023 17:09:48	TRK401	B	DON	827.31
27-Apr-2023 1	5,010	0	670512	06-013-034	Inspect Parking Brake - Complete	27-Apr-2023 11:48:46	TRK401	O	DON	11.88
12-May-2023 1	5,275	0	673989	95-MSA-004	Travel Travel Time - To/From Job Site	27-Apr-2023 13:50:11	TRK401	B	DON	213.82
25-May-2023 1	5,276	0	676900	06-100-PMA	Inspect A PMI	12-May-2023 10:36:46	ME1371	P	DON	13.12
19-Jul-2023 08	5,031	0	689321	03-063-003	Replace Transceiver - GPS Tracker	25-May-2023 10:37:51	LAVSHP	Q	DON	234.82
19-Jul-2023 08	5,031	0	689321	OS-310	Out-Service Backhoe (Rubber Tire)		BBKH0E	Z	WNID	91.01
19-Jul-2023 08	5,031	0	689321	02-310	Clean Backhoe (Rubber Tire)	28-Jul-2023 16:15:49	BWASH	Z	DON	427.01

Unit No: Q1275

Count: 85

29,599.57