

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2456 - 2013 F250 EXT CAB										
16-Oct-2013 1:	214	0	134081	14-016-005	Install Chassis Spring - Rear	17-Oct-2013 06:55:36	BTRUCK	C	DON	555.95
16-Oct-2013 1:	214	0	134081	06-100-DOT	Inspect DOT Federal Inspection	17-Oct-2013 08:04:03	BTRUCK	P	DON	58.25
16-Oct-2013 1:	214	0	134081	12-519-002	Refinish Rear Bumper	18-Nov-2013 10:55:22	BBODY	C	DON	78.42
16-Oct-2013 1:	214	0	134081	14-002-003	Install Running Boards / Step Tubes	15-Nov-2013 09:36:59	BBODY	C	DON	224.81
16-Oct-2013 1:	214	0	134081	14-002-023	Install Handles - Inner & Outer		BBODY	C	CAN	0.00
16-Oct-2013 1:	214	0	134081	14-002-063	Install Computer Stand / Dock	15-Nov-2013 07:19:38	BBODY	C	DON	339.40
16-Oct-2013 1:	214	0	134081	14-034-006	Install Warning Lamps - Special Application	15-Nov-2013 15:52:01	BBODY	C	DON	215.43
16-Oct-2013 1:	214	0	134081	14-052-003	Install Radio Equipment	14-Nov-2013 13:49:44	BBODY	C	DON	1,176.37
16-Oct-2013 1:	214	0	134081	14-052-011	Install Auxiliary Power	14-Nov-2013 07:26:35	BBODY	C	DON	103.45
16-Oct-2013 1:	214	0	134081	14-052-014	Install Cellular Telephone Accessories	14-Nov-2013 15:14:17	BBODY	C	DON	319.02
16-Oct-2013 1:	214	0	134081	14-052-015	Install Power Inverter/Converter	15-Nov-2013 07:05:48	BBODY	C	DON	122.69
16-Oct-2013 1:	214	0	134081	14-053-005	Install Markings - Vehicle - Decals	15-Nov-2013 12:58:39	BBODY	C	DON	27.75
16-Oct-2013 1:	214	0	134081	14-053-014	Install Floor Mats	15-Nov-2013 07:19:55	BBODY	C	DON	78.54
16-Oct-2013 1:	214	0	134081	14-063-003	Install Transceiver - GPS Tracker	14-Nov-2013 07:35:21	BBODY	C	DON	242.97
16-Oct-2013 1:	214	0	134081	14-078-009	Install Mud Flaps and Hanger Brackets	15-Nov-2013 07:45:30	BBODY	C	DON	34.57
16-Oct-2013 1:	214	0	134081	14-078-012	Install Tie-Down - Tarpaulin	18-Nov-2013 08:21:07	BBODY	C	DON	368.28
16-Oct-2013 1:	214	0	134081	14-079-002	Install Headache Rack	15-Nov-2013 12:00:46	BBODY	C	DON	541.10
16-Oct-2013 1:	214	0	134081	14-506-001	Install Fuel Tank	18-Nov-2013 09:28:17	BBODY	C	DON	999.85
16-Oct-2013 1:	214	0	134081	14-517	Install Safety Equipment	15-Nov-2013 07:24:37	BBODY	C	DON	276.32
19-Nov-2013 1	214	0	137484	06-100-007	Inspect In-Service Inspection	19-Nov-2013 14:11:13	MPNSHP	P	DON	11.78
19-Nov-2013 1	214	0	137484	24-034-014	Repair Auxiliary Work / Flood Light	19-Nov-2013 15:02:31	MPNSHP	I	DON	69.77
19-Nov-2013 1	214	0	137484	14-050	Install Accessories Group	19-Nov-2013 14:13:27	MPNSHP	I	DON	15.13
09-Oct-2014 0:	63,219	0	177855	06-100-DOT	Inspect DOT Federal Inspection	09-Oct-2014 06:15:12	MPNSHP	P	DON	54.70
16-Dec-2014 0	63,219	0	185485	03-034-006	Replace Warning Lamps - Special Application	22-Dec-2014 11:35:54	MPNFLD	I	DON	169.41
17-Jun-2015 1:	63,219	0	204794	24-055-012	Repair Cargo Restraints	18-Jun-2015 09:42:45	MPNFLD	O	DON	157.68
25-Aug-2015 1	0	0	212501	06-100-DOT	Inspect DOT Federal Inspection	26-Aug-2015 08:47:23	ME0547	P	DON	41.97
19-Nov-2015 1	0	0	222582	03-017-001	Replace Tire - Pneumatic	20-Nov-2015 10:15:11	MPNSHP	P	DON	1,071.73
08-Feb-2016 1:	0	0	232558	03-034-006	Replace Warning Lamps - Special Application	08-Feb-2016 14:22:25	ME0547	O	DON	208.09
23-Feb-2016 1:	0	0	234546	14-510-002	Install Tool Box		MPNFLD	I	CAN	0.00

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2456 - 2013 F250 EXT CAB										
23-Feb-2016	0	234546		24-017-001	Repair Tire - Pneumatic	25-Feb-2016 21:32:59	MPNFLD	B	DON	28.23
12-May-2016	0	244468		06-100-PMA	Inspect A PMI	13-May-2016 09:19:13	ME0546	P	DON	147.63
12-May-2016	0	244468		03-013-001	Replace Front Brakes & Drums	13-May-2016 09:17:44	ME0546	N	DON	95.57
12-May-2016	0	244468		03-032-001	Replace Battery	03-Jun-2016 13:39:59	ME0546	N	DON	203.19
13-May-2016	0	244539		03-017-001	Replace Tire - Pneumatic	13-May-2016 14:05:23	BTIRE	N	DON	823.32
23-Sep-2016	0	260675		03-052-009	Replace Speakers	17-Mar-2017 11:03:50	ME0546	N	DON	4.79
23-Sep-2016	0	260675		06-100-DOT	Inspect DOT Federal Inspection	25-Sep-2016 14:25:20	ME0546	P	DON	31.86
23-Sep-2016	0	260675		06-100-PMA	Inspect A PMI	25-Sep-2016 14:23:27	ME0546	P	DON	119.05
25-Mar-2017	0	282590		02-002-044	Clean Cab - Complete	03-Apr-2017 14:01:41	MPNSHP	P	DON	0.00
25-Mar-2017	0	282590		03-018-011	Replace Seal - Wheel	04-Apr-2017 07:17:35	MPNSHP	I	DON	44.18
25-Mar-2017	0	282590		03-034-002	Replace Stop, Tail, Turn & License	25-Mar-2017 12:00:01	MPNSHP	I	DON	35.20
25-Mar-2017	0	282590		03-043-002	Replace Exhaust Manifold	27-Mar-2017 07:40:28	MPNSHP	I	CAN	0.00
25-Mar-2017	0	282590		03-044-018	Replace Fuel Hose / Line	27-Mar-2017 08:11:16	MPNSHP	I	DON	31.52
25-Mar-2017	0	282590		03-051-009	Replace Fire Extinguisher	27-Mar-2017 06:47:25	MPNSHP	I	DON	26.63
25-Mar-2017	0	282590		03-052-003	Replace Radio Equipment	27-Mar-2017 08:48:02	MPNSHP	E	DON	65.93
25-Mar-2017	0	282590		03-053-007	Replace Hardware - Expendable Items	31-Mar-2017 08:22:46	MPNSHP	I	DON	158.87
25-Mar-2017	0	282590		06-100-009	Inspect Safety Check	25-Mar-2017 10:26:42	MPNSHP	P	DON	70.12
25-Mar-2017	0	282590		06-100-PMA	Inspect A PMI	04-Apr-2017 07:16:58	MPNSHP	P	DON	21.00
25-Mar-2017	0	282590		14-055-012	Install Cargo Restraints	27-Mar-2017 08:22:46	MPNSHP	I	DON	85.95
30-Mar-2017	1	283267		03-043-002	Replace Exhaust Manifold	30-Mar-2017 14:55:52	BVLOFC	O	DON	1,042.90
30-Mar-2017	1	283267		34-022-002	Reseal Shaft - Rear Axle	30-Mar-2017 14:55:52	BVLOFC	B	DON	446.84
30-Mar-2017	1	283267		06-100-PMA	Inspect A PMI	30-Mar-2017 14:55:52	BVLOFC	P	DON	51.79
30-Mar-2017	1	283267		03-033-002	Replace Distributor / Coil Pack	30-Mar-2017 14:55:52	BVLOFC	B	DON	185.27
30-Mar-2017	1	283267		02-002-035	Clean Windshield Wiper & Washer	30-Mar-2017 14:55:52	BVLOFC	I	DON	24.77
30-Mar-2017	1	283267		38-025	Service Transfer Case	30-Mar-2017 14:55:52	BVLOFC	P	DON	80.67
12-May-2017	1	288753		02-002-044	Clean Cab - Complete	15-May-2017 15:05:15	MPNSHP	P	DON	0.00
12-May-2017	1	288753		03-002-024	Replace Glass / Windshield	02-Jun-2017 12:43:45	MPNSHP	E	DON	385.01
12-May-2017	1	288753		03-032-001	Replace Battery	23-May-2017 10:37:49	MPNSHP	I	DON	14.72
12-May-2017	1	288753		06-100-DOT	Inspect DOT Federal Inspection	23-May-2017 11:02:43	MPNSHP	P	DON	13.22

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2456 - 2013 F250 EXT CAB										
12-May-2017		0	288753	06-100-PMA	Inspect A PMI	23-May-2017 11:33:00	MPNSHP	P	DON	133.29
30-Aug-2017	95,750	0	303023	03-013-001	Replace Front Brakes & Drums	30-Aug-2017 09:53:51	BVLOFC	O	DON	426.71
30-Aug-2017	95,750	0	303023	03-017-010	Replace Sensor - Air Pressure	30-Aug-2017 09:53:46	BVLOFC	O	DON	254.68
30-Aug-2017	95,750	0	303023	06-100-PMA	Inspect A PMI	30-Aug-2017 09:53:55	BTRUCK	P	DON	37.97
05-Sep-2017	98,608	0	307507	03-002-002	Replace Fenders	26-Oct-2017 10:36:22	MPNFLD	E	DON	1,361.65
24-Jan-2018	105,483	0	321300	01-017-001	Adjust Tire - Pneumatic	13-Feb-2018 07:07:00	MB2290	I	DON	84.26
24-Jan-2018	105,483	0	321300	03-044-002	Replace Filters	28-Jan-2018 08:18:33	MB2290	I	DON	290.15
24-Jan-2018	105,483	0	321300	06-100-PMA	Inspect A PMI	28-Jan-2018 07:09:40	MB2290	P	DON	132.35
24-Jan-2018	105,483	0	321300	03-044-013	Replace Cap - Fuel Tank	12-Mar-2018 16:06:13	MB2290	I	DON	28.09
25-May-2018	105,483	0	337239	03-017-001	Replace Tire - Pneumatic	11-Sep-2018 15:35:07	MPNFLD	B	DON	288.07
25-May-2018	105,483	0	337239	03-034-014	Replace Auxiliary Work / Flood Light	25-May-2018 08:15:02	HARFLD	O	DON	373.80
10-Jul-2018	108,875	0	343168	03-032-001	Replace Battery	11-Jul-2018 12:49:21	BVLOFC	O	DON	180.30
10-Jul-2018	108,875	0	343168	06-100-PMA	Inspect A PMI	11-Jul-2018 12:49:21	BVLOFC	P	DON	66.97
12-Dec-2018	108,875	0	364105	03-053-004	Replace Safety Equipment		HARFLD	E	CAN	0.00
10-Jan-2019	108,875	0	367685	02-002-044	Clean Cab - Complete	21-Jan-2019 11:05:57	MPNSHP	P	DON	135.41
10-Jan-2019	108,875	0	367685	03-013-002	Replace Rear Brakes & Drums	17-Jan-2019 16:30:58	MPNSHP	I	DON	496.70
10-Jan-2019	108,875	0	367685	03-017-001	Replace Tire - Pneumatic	28-Apr-2019 09:01:30	MPNSHP	P	DON	795.99
10-Jan-2019	108,875	0	367685	03-032-001	Replace Battery	12-Jan-2019 07:28:41	MPNSHP	I	DON	125.68
10-Jan-2019	108,875	0	367685	03-033-002	Replace Distributor / Coil Pack	16-Jan-2019 10:31:15	MPNSHP	I	DON	1,425.12
10-Jan-2019	108,875	0	367685	03-034-004	Replace Clearance & Marker Lamps	14-Jan-2019 11:57:49	MPNSHP	I	DON	175.31
10-Jan-2019	108,875	0	367685	03-042-012	Replace Clamps and Hoses	12-Jan-2019 10:17:23	MPNSHP	I	DON	203.79
10-Jan-2019	108,875	0	367685	03-051-009	Replace Fire Extinguisher	18-Jan-2019 10:54:32	MPNSHP	I	DON	12.70
10-Jan-2019	108,875	0	367685	03-052-015	Replace Power Inverter/Converter	11-Jan-2019 16:30:27	MPNSHP	I	DON	450.89
10-Jan-2019	108,875	0	367685	03-053-004	Replace Safety Equipment	18-Jan-2019 10:54:37	MPNSHP	I	DON	65.62
10-Jan-2019	108,875	0	367685	03-053-007	Replace Hardware - Expendable Items	18-Jan-2019 11:58:01	MPNSHP	I	DON	232.12
10-Jan-2019	108,875	0	367685	03-065-006	Replace Filters, Strainers, Screens & Housing	12-Jan-2019 12:00:12	MPNSHP	I	DON	180.65
10-Jan-2019	108,875	0	367685	06-017	Inspect Tires, Tubes, Liners & Valves	18-Jan-2019 10:55:06	MPNSHP	O	DON	0.00
10-Jan-2019	108,875	0	367685	06-100-007	Inspect In-Service Inspection	12-Feb-2019 11:55:13	MPNSHP	P	DON	1,705.78
10-Jan-2019	108,875	0	367685	06-100-009	Inspect Safety Check	10-Jan-2019 16:30:32	MPNSHP	P	DON	133.15

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2456 - 2013 F250 EXT CAB										
10-Jan-2019 0:	108,875	0	367685	06-100-DOT	Inspect DOT Federal Inspection	18-Jan-2019 10:05:19	MPNSHP	P	DON	11.17
10-Jan-2019 0:	108,875	0	367685	06-100-PMA	Inspect A PMI	18-Jan-2019 09:44:35	MPNSHP	P	DON	136.84
10-Jan-2019 0:	108,875	0	367685	24-055-012	Repair Cargo Restraints	17-Jan-2019 10:54:26	MPNSHP	I	DON	525.97
15-Mar-2019 1	118,230	0	383379	06-100-PMA	Inspect A PMI	15-Mar-2019 14:05:00	BVLOFC	P	DON	80.55
03-May-2019 (113,749	0	384176	06-100-009	Inspect Safety Check	06-May-2019 15:28:59	MPNSHP	P	DON	65.91
03-May-2019 (113,749	0	384176	03-053	Replace Expendable Items	06-May-2019 15:28:53	MPNSHP	I	DON	19.87
03-May-2019 (113,749	0	384176	02-002-044	Clean Cab - Complete	06-May-2019 15:28:30	MPNSHP	P	DON	46.83
03-May-2019 (113,749	0	384176	03-002-035	Replace Windshield Wiper & Washer	06-May-2019 12:32:12	MPNSHP	I	DON	9.25
03-May-2019 (113,749	0	384176	06-100-PMA	Inspect A PMI	03-May-2019 15:02:01	MPNSHP	P	DON	129.98
03-May-2019 (113,749	0	384176	35-013	Diagnose Brakes	06-May-2019 12:31:57	MPNSHP	I	DON	0.16
03-May-2019 (113,749	0	384176	03-015-004	Replace Steering Linkage	06-May-2019 13:40:06	MPNSHP	I	DON	342.66
03-May-2019 (113,749	0	384176	03-016-003	Replace Shock Absorber - Front	03-May-2019 16:28:50	MPNSHP	I	DON	125.59
03-May-2019 (113,749	0	384176	03-018-001	Replace Front Axle Hubs & Bearings	06-May-2019 09:42:46	MPNSHP	I	DON	640.18
03-May-2019 (113,749	0	384176	03-054-002	Replace Alarm - Reverse Signal	06-May-2019 13:21:08	MPNSHP	I	DON	91.40
03-May-2019 (113,749	0	384176	03-054	Replace Horns, Mounting, Signal Alarms	06-May-2019 10:03:17	MPNSHP	I	DON	51.53
03-May-2019 (113,749	0	384176	24-052-015	Repair Power Inverter/Converter	06-May-2019 14:18:20	MPNSHP	I	DON	20.59
03-May-2019 (113,749	0	384176	09-010-001	Align All Axles	17-May-2019 11:47:18	MPNSHP	P	DON	84.29
14-May-2019 (113,749	0	385672	03-017-001	Replace Tire - Pneumatic	14-May-2019 09:04:44	BTIRE	P	DON	1,094.31
22-May-2019 1	116,358	0	386996	03-034-006	Replace Warning Lamps - Special Application	22-May-2019 19:38:35	MA0722	B	DON	65.75
22-May-2019 1	116,358	0	386996	03-052-015	Replace Power Inverter/Converter	30-May-2019 07:31:32	MA0722	B	DON	268.25
27-Jun-2019 0:	128,593		400700	38-100-PMA	Service A PMI	27-Jun-2019 08:35:00	BVLOFC	P	DON	115.26
11-Dec-2019 1	132,350		416407	03-079-002	Replace Headache Rack	26-Dec-2019 06:21:03	BSETUP	I	DON	706.45
11-Dec-2019 1	132,350		416407	03-510-002	Replace Tool Box	26-Dec-2019 06:21:05	BSETUP	I	DON	600.54
25-Feb-2020 0	135,736		428789	06-100-DOT	Inspect DOT Federal Inspection	01-Mar-2020 18:02:54	MA0722	P	DON	32.88
25-Feb-2020 0	135,736		428789	06-100-PMA	Inspect A PMI	16-Mar-2020 19:03:04	MA0722	P	DON	65.75
20-Jul-2020 00	142,126		451550	06-100-PMA	Inspect A PMI	20-Jul-2020 19:25:29	ME0546	P	DON	71.44
20-Jul-2020 00	142,126		451550	03-044-016	Replace Tank - Fuel Auxiliary	29-Jul-2020 20:17:36	ME0546	B	DON	1,144.34
19-Aug-2020 C	149,060		457530	06-100-PMA	Inspect A PMI	22-Aug-2020 11:25:35	TRK021	P	DON	35.72
19-Aug-2020 C	149,060		457530	31-017	Rotate Tires, Tubes, Liners & Valves	22-Aug-2020 11:26:51	TRK021	P	DON	17.86

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2456 - 2013 F250 EXT CAB										
21-Aug-2020 C			457426	03-013-001	Replace Front Brakes & Drums	23-Aug-2020 13:41:06	MA0722	B	DON	364.02
21-Aug-2020 C			457426	14-034-014	Install Auxiliary Work / Flood Light	23-Aug-2020 13:48:24	MA0722	B	DON	372.70
21-Sep-2020 0	154,298		462401	03-017	Replace Tires, Tubes, Liners & Valves	06-Oct-2020 09:59:27	BVLOFC	N	DON	1,152.92
07-Dec-2020 0	158,410		475725	06-100-PMA	Inspect A PMI	07-Dec-2020 17:56:40	ME0546	P	DON	62.43
01-Mar-2021 0	159,598		491031	03-002-035	Replace Windshield Wiper & Washer	03-Mar-2021 04:15:16	ME0546	B	DON	122.56
01-Mar-2021 0	159,598		491031	06-100-DOT	Inspect DOT Federal Inspection	02-Mar-2021 03:05:14	ME0546	P	DON	130.70
01-Mar-2021 0	159,598		491031	06-100-PMA	Inspect A PMI	02-Mar-2021 03:05:09	ME0546	P	DON	104.56
01-Mar-2021 0	159,598		491031	31-017-001	Rotate Tire - Pneumatic	03-Mar-2021 04:15:21	ME0546	B	DON	365.95
17-Jun-2021 1	159,598		513431	06-100-PMA	Inspect A PMI	17-Jun-2021 14:29:21	SCHED	P	DON	0.00
17-Jun-2021 1	159,598		513431	38-100-PMA	Service A PMI	17-Jun-2021 14:29:24	SCHED	P	DON	110.01
27-Jul-2021 00	159,598		520989	03-042-002	Replace Radiator		ME0546	B	CAN	0.00
27-Jul-2021 00	159,598		520989	03-063-003	Replace Transceiver - GPS Tracker	04-Aug-2021 13:24:54	SCHED	Q	DON	298.63
27-Jul-2021 00	159,598		520989	06-100-PMB	Inspect B PMI	04-Aug-2021 13:24:50	SCHED	P	DON	174.92
27-Jul-2021 00	159,598		520989	38-100-PMB	Service B PMI	09-Aug-2021 13:34:47	TRK022	P	DON	38.53
27-Jul-2021 08	187,074		521035	03-022-008	Replace Pinion Seal	02-Aug-2021 14:53:42	BVLOFC	I	DON	520.17
27-Jul-2021 08	187,074		521035	03-042-002	Replace Radiator	02-Aug-2021 14:53:42	BVLOFC	B	DON	1,370.98
27-Jul-2021 08	187,074		521035	20-010	Tow Chassis Group		BVLOFC	B	DON	233.94
27-Jul-2021 08	187,074		521035	38-042	Service Cooling System	02-Aug-2021 14:53:42	BVLOFC	P	DON	192.62
30-Aug-2021 C	187,074		528435	03-018-001	Replace Front Axle Hubs & Bearings	31-Aug-2021 19:51:19	ME0546	B	DON	252.52
03-Nov-2021 C	187,074		543989	03-031-001	Replace Generator/Alternator	04-Nov-2021 03:55:59	ME0546	I	DON	502.46
03-Nov-2021 C	187,074		543989	03-041-006	Replace Filter - Inner	04-Nov-2021 03:56:10	ME0546	I	DON	175.20
03-Nov-2021 C	187,074		543989	03-042-013	Replace Fan Belt	04-Nov-2021 03:55:57	ME0546	I	DON	209.12
03-Nov-2021 C	187,074		543989	03-043-007	Replace Exhaust Pipe/Elbow	04-Nov-2021 03:55:54	ME0546	I	DON	209.12
03-Nov-2021 C	187,074		543989	06-100-PMB	Inspect B PMI	04-Nov-2021 03:55:49	SCHED	P	DON	87.46
03-Nov-2021 C	187,074		543989	14-034-010	Install Socket - Trailer Light Cord	04-Nov-2021 03:56:06	ME0546	I	DON	351.91
03-Nov-2021 C	187,074		543989	31-017-001	Rotate Tire - Pneumatic	04-Nov-2021 03:56:03	ME0546	P	DON	104.56
14-Feb-2022 0	196,865		566900	06-100-PMA	Inspect A PMI	19-Feb-2022 10:59:26	ME0546	P	DON	0.00
14-Feb-2022 0	196,865		566900	38-100-PMA	Service A PMI	14-Feb-2022 20:48:41	ME0546	P	DON	109.40
24-Mar-2022 0	196,865		577159	06-100-DOT	Inspect DOT Federal Inspection		MA0722	P	CAN	0.00

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2456 - 2013 F250 EXT CAB										
24-Mar-2022 0	196,865		577159	06-100-PMA	Inspect A PMI	24-Mar-2022 18:38:04	MA0722	P	DON	209.12
24-Mar-2022 0	196,865		577159	03-013-002	Replace Rear Brakes & Drums	24-Mar-2022 18:34:38	MA0722	B	DON	466.79
24-Mar-2022 0	196,865		577159	03-013-038	Replace Caliper - Rear	24-Mar-2022 18:35:01	MA0722	B	DON	246.14
24-Mar-2022 0	196,865		577159	03-016-024	Replace Leaf Spring		MA0722	B	WR	0.00
24-Mar-2022 0	196,865		577159	14-053-009	Install Steel Stock	08-Apr-2022 15:13:27	MPNSHP	B	DON	7.71
11-Apr-2022 0	196,865		580955	03-016-024	Replace Leaf Spring	14-Dec-2022 15:16:31	BVLOFC	I	DON	2,488.47
12-Apr-2022 0	196,865		581446	21-044-016	Fabricate Tank - Fuel Auxiliary	12-Apr-2022 18:47:08	ME0546	B	DON	156.84
19-Jul-2022 13	205,305		603650	06-100-PMA	Inspect A PMI	19-Jul-2022 13:51:21	MPNOFC	P	DON	0.00
19-Jul-2022 13	205,305		603650	38-100-PMA	Service A PMI	19-Jul-2022 13:51:15	MPNOFC	P	DON	92.63
25-Jul-2022 00	205,649		604997	03-016-024	Replace Leaf Spring	27-Jul-2022 19:57:32	ME0546	B	DON	52.28
25-Jul-2022 00	205,649		604997	06-100-DOT	Inspect DOT Federal Inspection	27-Jul-2022 19:57:36	ME0546	P	DON	104.56
05-Dec-2022 0	209,157		637027	06-100-PMB	Inspect B PMI	07-Dec-2022 04:43:43	ME0546	P	DON	0.00
05-Dec-2022 0	209,157		637027	38-100-PMA	Service A PMI	05-Dec-2022 19:08:30	ME0546	P	DON	237.83
05-Dec-2022 0	209,157		637027	03-013-001	Replace Front Brakes & Drums	07-Dec-2022 04:43:46	ME0546	I	DON	1,010.09
05-Dec-2022 0	209,157		637027	03-018-001	Replace Front Axle Hubs & Bearings	13-Dec-2022 04:36:32	ME0546	I	DON	1,350.45
05-Dec-2022 0	209,157		637027	31-017-001	Rotate Tire - Pneumatic	07-Dec-2022 04:43:51	ME0546	I	DON	313.68
04-Apr-2023 0	216,368		664252	06-100-PMA	Inspect A PMI	05-Apr-2023 05:58:43	ME0546	P	DON	218.65
04-Apr-2023 0	216,368		664252	38-100-PMA	Service A PMI	05-Apr-2023 05:55:37	ME0546	P	DON	386.11
19-May-2023 1	219,471		675715	03-017-001	Replace Tire - Pneumatic	19-May-2023 14:03:56	BTIRE	O	DON	1,080.98
31-May-2023 1	219,775		677854	03-017-001	Replace Tire - Pneumatic	01-Jun-2023 05:39:44	ME0546	B	DON	174.92
19-Jul-2023 05	222,428		689249	06-100-009	Inspect Safety Check	19-Jul-2023 07:00:14	BTRUCK	P	DON	20.41
24-Jul-2023 08	222,428		690528	02-002	Clean Cab & Sheet Metal	25-Jul-2023 08:03:22	BSETUP	Z	DON	47.07
24-Jul-2023 08	222,428		690528	25-050	Remove Accessories Group	24-Jul-2023 14:09:20	BSETUP	Z	DON	186.37

Unit No: B2456

Count: 168

44,668.56