

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: D0958 - 1995 WELLS CARG WW2011										
10-Feb-2010	0	0	33643	03-528	Replace Bushing	16-Feb-2010 12:52:13	MPNSHP	I	DON	46.73
10-Feb-2010	0	0	33643	06-100-002	Inspect DO NOT USE - DOT Federal Insp	18-Feb-2010 06:19:38	MPNSHP	I	DON	30.70
10-Feb-2010	0	0	33643	06-100-009	Inspect Safety Check	16-Feb-2010 14:35:40	MPNSHP	P	DON	176.45
10-Feb-2010	0	0	33643	26-014-001	Weld Frame Assembly	11-Feb-2010 08:05:52	MPNSHP	I	DON	124.40
10-Feb-2010	0	0	33643	26-016-005	Weld Chassis Spring - Rear	17-Feb-2010 09:00:00	MPNSHP	I	DON	275.01
07-May-2010	0	0	40526	01-013-012	Adjust Electric Brakes	11-May-2010 15:00:00	MPNSHP	I	DON	154.74
07-May-2010	0	0	40526	03-034	Replace Lighting System	07-May-2010 15:00:00	MPNSHP	I	DON	126.88
07-May-2010	0	0	40526	06-100-009	Inspect Safety Check	07-May-2010 11:54:18	MPNSHP	P	DON	86.31
07-May-2010	0	0	40526	14-053-012	Install Pad lock	10-May-2010 13:04:08	MPNSHP	I	DON	348.95
07-May-2010	0	0	40526	24-002	Repair Cab & Sheet Metal	10-May-2010 15:00:00	MPNSHP	I	DON	104.96
18-May-2010	0	0	43926	03-017-001	Replace Tire - Pneumatic	18-May-2010 07:31:16	MPNSHP	F	DON	89.54
20-Sep-2011	0	0	73557	06-100-002	Inspect DO NOT USE - DOT Federal Insp	26-Sep-2011 13:04:13	MPNSHP	P	DON	71.42
19-Mar-2012	1	0	84087	03-013-021	Replace Break Away Switch	19-Mar-2012 16:30:25	MPNSHP	O	DON	39.96
13-Mar-2013	0	0	111129	06-100-DOT	Inspect DOT Federal Inspection	13-Mar-2013 17:00:00	MPNOFC	P	DON	61.86
02-Oct-2013	0	0	132830	03-063-003	Replace Transceiver - GPS Tracker	02-Oct-2013 17:00:00	MPNOFC	C	DON	15.47
09-Oct-2013	0	0	133960	24-063-003	Repair Transceiver - GPS Tracker	09-Oct-2013 17:00:00	MPNSHP	I	DON	16.92
11-Nov-2013	0	0	140570	24-071-003	Repair Side Wall Assembly	17-Dec-2013 07:42:54	MPNSHP	E	DON	169.29
20-Oct-2014	0	0	177004	06-100-DOT	Inspect DOT Federal Inspection	20-Oct-2014 07:43:18	MPNSHP	P	DON	68.58
20-Oct-2014	0	0	177004	24-034-002	Repair Stop, Tail, Turn & License	20-Oct-2014 07:43:46	MPNSHP	B	DON	34.29
03-Nov-2014	0	0	179259	03-063-003	Replace Transceiver - GPS Tracker	03-Nov-2014 06:29:57	MPNFLD	B	DON	34.29
02-Apr-2015	1	0	196720	03-077	Replace Trailer Frame & Support	22-Apr-2015 00:00:00	MPNSHP	E	DON	991.76
27-Jul-2015	15	0	209224	03-013-020	Replace Break Away Battery	29-Jul-2015 09:33:03	MPNSHP	I	DON	167.22
27-Jul-2015	15	0	209224	03-051-009	Replace Fire Extinguisher	28-Jul-2015 07:44:10	MPNSHP	I	DON	84.10
27-Jul-2015	15	0	209224	06-100-009	Inspect Safety Check	29-Aug-2015 09:23:39	MPNSHP	I	DON	77.70
27-Jul-2015	15	0	209224	06-100-DOT	Inspect DOT Federal Inspection	31-Jul-2015 13:28:25	MPNSHP	I	DON	28.00
27-Jul-2015	15	0	209224	24-014-001	Repair Frame Assembly	28-Jul-2015 13:53:26	MPNSHP	I	DON	15.41
27-Jul-2015	15	0	209224	24-053-007	Repair Hardware - Expendable Items	31-Jul-2015 12:52:42	MPNSHP	I	DON	41.20
27-Jul-2015	15	0	209224	24-072-003	Repair Door Assembly - Hinged, Rear	29-Jul-2015 11:46:13	MPNSHP	I	DON	100.36
27-Jul-2015	15	0	209224	35-013-012	Diagnose Electric Brakes	29-Jul-2015 11:29:03	MPNSHP	I	DON	127.85

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: D0958 - 1995 WELLS CARG WW2011										
25-Aug-2015	1	0	212473	03-063-003	Replace Transceiver - GPS Tracker	25-Aug-2015 12:17:54	GPSINS	Q	DON	334.51
17-Feb-2017	1	0	277685	06-100-PMA	Inspect A PMI	17-Feb-2017 14:07:18	MPNSHP	P	DON	190.68
31-Oct-2017	0	0	311609	03-018-005	Replace Bearings - General	06-Nov-2017 18:13:48	ME0656	F	DON	92.54
31-Oct-2017	0	0	311609	06-100-DOT	Inspect DOT Federal Inspection	06-Nov-2017 18:12:12	ME0656	P	DON	35.21
05-Feb-2018	0	0	323116	03-072-003	Replace Door Assembly - Hinged, Rear	10-Feb-2018 19:16:06	ME0546	B	DON	63.71
05-Feb-2018	0	0	323116	06-034-002	Inspect Stop, Tail, Turn & License	22-May-2018 18:34:55	ME0546	P	DON	15.93
05-Feb-2018	0	0	323116	19-034-004	Wire/Rewire Clearance & Marker Lamps	03-Mar-2018 18:41:42	ME0546	B	DON	95.57
08-Jul-2020	00		449558	06-100-DOT	Inspect DOT Federal Inspection	08-Jul-2020 19:36:49	MPNFLD	P	DON	35.72
11-Jan-2022	0		558435	03-063-003	Replace Transceiver - GPS Tracker	11-Jan-2022 14:41:33	SCHED	Q	DON	459.95
31-Mar-2022	0		578710	03-034-011	Replace Plug - Trailer Light Cord	07-Apr-2022 08:23:49	ME0546	I	DON	0.00
31-Mar-2022	0		578710	06-100-DOT	Inspect DOT Federal Inspection	31-Mar-2022 20:52:45	ME0546	P	DON	209.12
31-Mar-2022	0		578710	06-100-PMA	Inspect A PMI	07-Apr-2022 08:23:53	ME0546	P	DON	0.00
27-Apr-2022	0		584968	14-034-011	Install Plug - Trailer Light Cord	27-Apr-2022 20:28:54	ME0546	B	DON	191.99
27-Aug-2022	0		612376	03-017-001	Replace Tire - Pneumatic	27-Aug-2022 07:07:00	BTIRE	O	DON	349.30
10-Oct-2022	0		623152	03-017-001	Replace Tire - Pneumatic	10-Oct-2022 19:18:08	ME0546	B	DON	209.12
10-Oct-2022	0		623152	95-017-001	Travel Tire - Pneumatic	10-Oct-2022 19:18:04	ME0546	B	DON	418.23
10-May-2023	0		673601	06-100-DOT	Inspect DOT Federal Inspection	10-May-2023 19:38:29	ME0546	P	DON	87.46
10-May-2023	0		673601	06-100-PMA	Inspect A PMI	10-May-2023 19:38:31	ME0546	P	DON	0.00
19-Sep-2023	1		706436	06-100-009	Inspect Safety Check	20-Sep-2023 11:30:38	BTRLR	Z	DON	75.84
19-Sep-2023	1		706436	19-013-012	Wire/Rewire Electric Brakes	20-Sep-2023 10:38:02	BTRLR	Z	DON	35.50
19-Sep-2023	1		706436	25-053-005	Remove Markings - Vehicle - Decals	20-Sep-2023 08:20:06	BTRLR	Z	DON	161.34
19-Sep-2023	1		706436	25-063-003	Remove Transceiver - GPS Tracker	20-Sep-2023 08:31:04	BTRLR	Z	DON	6.80

Unit No: D0958 Count: 51

6,778.86