

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Q1236 - 2016 JOHN DEERE 310SL										
07-Mar-2016	2	0	236419	14-063-003	Install Transceiver - GPS Tracker	16-Mar-2016 17:48:25	BBKHOE	Q	DON	269.65
07-Mar-2016	2	0	236419	26-059-002	Weld Pintle Hook Assembly	08-Mar-2016 10:38:51	BBKHOE	Q	DON	156.13
07-Mar-2016	2	0	236419	IS-310	In-Service Backhoe (Rubber Tire)	16-Mar-2016 17:48:30	BBKHOE	Q	DON	282.85
28-Mar-2016	1	0	239193	14-051-009	Install Fire Extinguisher	28-Mar-2016 18:05:33	LAVSHP	Q	DON	12.72
13-Jul-2016	07	310	253170	03-027-040	Replace Tube/Line	13-Jul-2016 07:00:00	LAVSHP	N	DON	39.19
11-Oct-2016	1:	607	262628	06-100-PMA	Inspect A PMI	12-Oct-2016 12:24:23	LAVSHP	P	DON	116.51
23-Nov-2016	1	733	269911	03-017-001	Replace Tire - Pneumatic	23-Nov-2016 13:25:30	BTIRE	F	DON	697.82
26-Jan-2017	0:	818	274888	06-310	Inspect Backhoe (Rubber Tire)	08-Mar-2017 11:28:26	LAVSHP	S	DON	123.61
26-Jan-2017	0:	818	274888	10-310-001	Rebush Boom (Main)	08-Mar-2017 11:28:37	LAVSHP	W	DON	0.00
13-Jul-2017	10	818	296660	06-100-PMA	Inspect A PMI	13-Jul-2017 13:25:21	LAVSHP	P	DON	89.54
14-Jul-2017	12	818	297772	24-017-001	Repair Tire - Pneumatic	14-Jul-2017 12:11:06	BTIRE	F	DON	234.41
24-Aug-2017	1	1,350	302408	11-065-004	Rebuild Cylinder	28-Aug-2017 14:56:17	ROGSHP	B	DON	909.36
24-Aug-2017	1	1,350	302408	24-065-004	Repair Cylinder	24-Aug-2017 14:27:50	ROGSHP	B	DON	15.34
28-Aug-2017	1	1,493	310916	03-017-001	Replace Tire - Pneumatic	28-Aug-2017 16:35:00	BTIRE	F	DON	1,869.77
20-Oct-2017	0:	1,493	309548	07-100-PMA	Lubricate A PMI	20-Oct-2017 10:52:45	ROGSHP	P	DON	29.89
28-Nov-2017	1	1,642	313932	03-034-002	Replace Stop, Tail, Turn & License	28-Nov-2017 15:40:20	LAVSHP	F	DON	13.10
12-Jan-2018	0:	1,657	319243	03-310-017	Replace Cutting Edges	12-Jan-2018 10:57:57	LAVSHP	I	DON	29.10
12-Jan-2018	0:	1,657	319243	06-100-PMC	Inspect C PMI	12-Jan-2018 10:04:54	LAVSHP	P	DON	619.91
12-Jan-2018	0:	1,657	319243	06-310	Inspect Backhoe (Rubber Tire)	12-Jan-2018 07:35:24	LAVSHP	S	DON	52.32
12-Jan-2018	0:	1,657	319243	24-034-006	Repair Warning Lamps - Special Application	15-Jan-2018 12:56:01	LAVSHP	I	DON	200.32
03-May-2018	1	1,657	334155	24-065-007	Repair Hoses & Fittings	03-May-2018 11:53:24	LAVSHP	F	DON	11.57
20-Jun-2018	10	1,905	340521	03-017-011	Replace Tire - Foam Filled	20-Jun-2018 11:23:25	LAVSHP	F	DON	1,804.06
25-Jun-2018	10	1,945	341262	06-100-PMA	Inspect A PMI	25-Jun-2018 15:17:37	LAVSHP	P	DON	73.48
06-Jul-2018	10	1,980	342653	03-514	Replace Bucket	06-Jul-2018 11:42:48	LAVSHP	B	DON	56.89
06-Jul-2018	10	1,980	342653	06-042	Inspect Cooling System	12-Jul-2018 09:31:13	LAVSHP	P	DON	20.98
06-Jul-2018	10	1,980	342653	06-049-001	Inspect ECM Fault Code	12-Jul-2018 08:25:22	LAVSHP	I	DON	8.07
06-Jul-2018	10	1,980	342653	03-034-002	Replace Stop, Tail, Turn & License	12-Jul-2018 08:41:36	LAVSHP	I	DON	11.10
17-Jul-2018	11	1,980	344072	03-044-002	Replace Filters	26-Jul-2018 10:12:36	LAVSHP	I	DON	258.57
17-Jul-2018	11	1,980	344072	06-100-009	Inspect Safety Check	26-Jul-2018 10:12:28	LAVSHP	P	DON	0.00

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Q1236 - 2016 JOHN DEERE 310SL										
17-Jul-2018	1,980	0	344072	25-042-004	Remove Water Pump	26-Jul-2018 10:12:32	LAVSHP	W	DON	0.00
28-Feb-2019	0	2,271	0	375062	Inspect B PMI	04-Mar-2019 15:10:25	LAVSHP	P	DON	581.14
19-Apr-2019	1	2,293	0	382061	Repair Operator Controls	19-Apr-2019 11:16:00	ROGSHP	N	DON	74.90
19-Apr-2019	1	2,293	0	382061	Rebuild Cylinder	30-Apr-2019 13:13:47	ROGSHP	N	DON	1,434.23
19-Apr-2019	1	2,293	0	382061	Remove Cylinder	30-Apr-2019 06:51:48	ROGSHP	N	DON	269.39
19-Apr-2019	1	2,293	0	382061	Replace Cylinder	01-May-2019 09:46:43	ROGSHP	N	DON	344.85
19-Apr-2019	1	2,293	0	382061	Repair Alarm - Reverse Signal	01-May-2019 10:27:34	ROGSHP	N	DON	59.97
19-Apr-2019	1	2,293	0	382061	Replace Shanks or Teeth	02-May-2019 07:16:44	ROGSHP	E	DON	161.92
19-Apr-2019	1	2,293	0	382061	Weld Cutting Edges	02-May-2019 07:19:11	ROGSHP	N	DON	44.04
17-May-2019	1	2,357	0	386295	Replace Headlamps / Fog Lamps	17-May-2019 15:14:22	ROGSHP	N	DON	15.87
17-May-2019	1	2,357	0	386295	Repair Headlamps / Fog Lamps	17-May-2019 13:58:46	ROGSHP	N	DON	109.94
17-May-2019	1	2,357	0	386295	Repair Boom Pins	17-May-2019 15:15:30	ROGSHP	N	DON	141.03
03-Jun-2019	1	2,357	0	388355	Inspect Quick-Attach Coupling Assembly	04-Jun-2019 13:04:55	LAVSHP	O	DON	198.82
18-Jul-2019	08	2,539	0	394750	Inspect A PMI	18-Jul-2019 09:35:32	LAVSHP	P	DON	19.28
18-Jul-2019	08	2,539	0	394750	Service A PMI	18-Jul-2019 09:04:18	LAVSHP	I	DON	91.48
10-Sep-2019	0	2,646	0	402246	Replace Coupler - Quick Disconnect	10-Sep-2019 10:21:51	ME1371	I	DON	74.88
16-Sep-2019	0	2,659	0	403014	Replace Hoses & Tubings & Fittings	17-Sep-2019 10:38:09	ROGSHP	B	DON	544.92
25-Sep-2019	1	2,706	0	404565	Replace Filter Assembly	25-Sep-2019 14:34:19	ROGSHP	O	DON	107.17
25-Sep-2019	1	2,706	0	404565	Repair Hoses & Fittings	25-Sep-2019 15:47:38	ROGSHP	N	DON	50.29
10-Oct-2019	1	2,774	0	407018	Replace Hoses & Tubings & Fittings	11-Oct-2019 07:34:11	ROGSHP	B	DON	612.88
16-Oct-2019	0	2,803	0	407720	Inspect A PMI	16-Oct-2019 16:38:39	ROGSHP	P	DON	0.00
16-Oct-2019	0	2,803	0	407720	Service A PMI	16-Oct-2019 11:47:19	ROGSHP	P	DON	304.68
16-Oct-2019	0	2,803	0	407720	Replace Hoses & Tubings & Fittings	16-Oct-2019 16:40:50	ROGSHP	B	DON	617.49
16-Oct-2019	0	2,803	0	407720	Replace Outriggers	17-Oct-2019 14:58:57	ROGSHP	N	DON	76.64
16-Oct-2019	0	2,803	0	407720	Rebuild Cylinder	21-Nov-2019 11:09:13	ROGSHP	N	DON	1,230.20
21-Nov-2019	1	2,992	0	413898	Inspect Cooling System	25-Nov-2019 15:01:26	ME1371	O	DON	41.33
12-Dec-2019	1	3,054	0	416744	Inspect B PMI	17-Dec-2019 06:51:42	ROGSHP	P	DON	0.00
12-Dec-2019	1	3,054	0	416744	Service B PMI	12-Dec-2019 17:35:30	ROGSHP	P	DON	266.86
10-Jan-2020	0	3,084	0	424847	Replace Tire - Pneumatic	10-Jan-2020 09:55:00	BTIRE	P	DON	1,934.97

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Q1236 - 2016 JOHN DEERE 310SL										
10-Jan-2020 05	3,084	0	424847	03-017-011	Replace Tire - Foam Filled	18-Feb-2020 07:02:25	BTIRE	P	DON	0.00
07-Feb-2020 0	3,084	0	425194	03-034-002	Replace Stop, Tail, Turn & License	07-Feb-2020 09:20:58	LAVSHP	I	DON	14.70
07-Feb-2020 0	3,084	0	425194	03-053-005	Replace Markings - Vehicle - Decals	07-Feb-2020 07:46:42	LAVSHP	I	DON	7.22
07-Feb-2020 0	3,084	0	425194	03-094-011	Replace Coupler - Quick Disconnect	07-Feb-2020 09:46:07	LAVSHP	I	DON	204.00
07-Feb-2020 0	3,084	0	425194	03-310-003	Replace Boom Pins	07-Feb-2020 07:33:45	LAVSHP	I	DON	254.85
07-Feb-2020 0	3,084	0	425194	03-310-006	Replace Outriggers	13-Feb-2020 16:31:23	LAVSHP	I	DON	74.85
07-Feb-2020 0	3,084	0	425194	03-310-007	Replace Outtrigger Pads	07-Feb-2020 08:58:34	LAVSHP	I	DON	292.53
07-Feb-2020 0	3,084	0	425194	06-100-007	Inspect In-Service Inspection	07-Feb-2020 06:02:28	LAVSHP	P	DON	26.48
07-Feb-2020 0	3,084	0	425194	11-065-004	Rebuild Cylinder	05-Mar-2020 09:15:21	LAVSHP	B	DON	1,840.81
07-Feb-2020 0	3,084	0	425194	11-310-006	Rebuild Outriggers	05-Mar-2020 09:06:58	LAVSHP	B	DON	1,109.16
20-May-2020 0	3,283	0	441577	24-065-007	Repair Hoses & Fittings	20-May-2020 07:27:57	ME1371	O	DON	22.32
10-Jun-2020 01	3,321	0	444670	06-100-PMA	Inspect A PMI	10-Jun-2020 09:13:16	ME1371	P	DON	6.13
10-Jun-2020 01	3,321	0	444670	38-100-PMA	Service A PMI	10-Jun-2020 09:03:10	ME1371	P	DON	60.22
01-Jul-2020 09	3,389	0	448487	06-042	Inspect Cooling System	01-Jul-2020 10:25:15	ME1371	O	DON	20.88
08-Dec-2020 0	3,593	0	475814	06-100-PMA	Inspect A PMI	08-Dec-2020 10:06:12	ME1371	P	DON	15.53
08-Dec-2020 0	3,593	0	475814	38-100-PMA	Service A PMI	08-Dec-2020 10:51:47	ME1371	P	DON	74.83
14-Jan-2021 01	3,651	0	481976	03-002-027	Replace Seat Frames & Springs	15-Jan-2021 11:21:20	TRK400	I	DON	66.59
14-Jan-2021 01	3,651	0	481976	03-002-061	Replace Seat Cushion	14-Jan-2021 16:59:01	TRK400	I	DON	351.68
14-Jan-2021 01	3,651	0	481976	03-065-004	Replace Cylinder	15-Jan-2021 13:00:52	TRK400	I	DON	207.66
14-Jan-2021 01	3,651	0	481976	03-065-007	Replace Hoses & Fittings	14-Jan-2021 14:47:42	TRK400	I	DON	284.55
14-Jan-2021 01	3,651	0	481976	03-310-017	Replace Cutting Edges	15-Jan-2021 12:43:34	TRK400	I	DON	311.25
14-Jan-2021 01	3,651	0	481976	06-100-PMC	Inspect C PMI	14-Jan-2021 07:25:13	TRK400	P	DON	155.16
14-Jan-2021 01	3,651	0	481976	10-310-002	Rebush Boom (Dipper)	15-Jan-2021 10:56:36	TRK400	I	DON	2,910.36
14-Jan-2021 01	3,651	0	481976	38-100-PMC	Service C PMI	14-Jan-2021 11:35:18	TRK400	P	DON	885.41
02-Feb-2021 01	3,653	0	485951	03-017-011	Replace Tire - Foam Filled	02-Feb-2021 14:48:00	LAVSHP	I	DON	1,864.57
22-Apr-2021 0	3,744	0	502070	03-065-007	Replace Hoses & Fittings	23-Apr-2021 11:57:53	LAVSHP	B	DON	448.78
22-Apr-2021 0	3,744	0	502070	24-017-001	Repair Tire - Pneumatic	03-May-2021 14:08:16	LAVSHP	B	DON	967.60
12-May-2021 1	3,824	0	506272	38-100-PMA	Service A PMI	12-May-2021 15:07:10	TRK401	P	DON	227.86
12-May-2021 1	3,824	0	506272	06-100-PMA	Inspect A PMI	12-May-2021 14:54:31	SCHED	P	DON	31.95

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Q1236 - 2016 JOHN DEERE 310SL										
16-Jun-2021 08	3,920	0	513050	03-044-017	Replace Indicator/Sender - Fuel Level	18-Jun-2021 07:50:18	ME1371	I	DON	456.46
16-Jun-2021 08	3,920	0	513050	06-049-001	Inspect ECM Fault Code	01-Jul-2021 09:26:29	ME1371	I	DON	69.46
16-Jun-2021 08	3,920	0	513050	03-043-004	Replace Turbocharger	01-Jul-2021 13:42:20	ME1371	I	DON	1,356.82
01-Sep-2021 11	4,071	0	528917	03-094-011	Replace Coupler - Quick Disconnect	01-Sep-2021 17:42:41	ME1371	O	DON	124.39
01-Sep-2021 11	4,071	0	528917	06-100-PMA	Inspect A PMI	01-Sep-2021 13:18:14	ME1371	P	DON	33.37
01-Sep-2021 11	4,071	0	528917	24-065-007	Repair Hoses & Fittings	01-Sep-2021 13:34:56	ME1371	I	DON	28.77
01-Sep-2021 11	4,071	0	528917	38-100-PMA	Service A PMI	01-Sep-2021 12:58:52	ME1371	P	DON	120.63
29-Nov-2021 11	4,246	0	549326	03-034-002	Replace Stop, Tail, Turn & License	29-Nov-2021 10:57:39	LAVSHP	I	DON	11.87
29-Nov-2021 11	4,246	0	549326	03-065-007	Replace Hoses & Fittings	29-Nov-2021 10:15:47	LAVSHP	I	DON	235.34
29-Nov-2021 11	4,246	0	549326	03-310-007	Replace Outrigger Pads	29-Nov-2021 07:43:43	LAVSHP	I	DON	83.92
29-Nov-2021 11	4,246	0	549326	06-034-002	Inspect Stop, Tail, Turn & License	29-Nov-2021 10:41:27	LAVSHP	I	DON	18.81
29-Nov-2021 11	4,246	0	549326	06-100-PMA	Inspect A PMI	29-Nov-2021 07:21:42	LAVSHP	P	DON	65.00
29-Nov-2021 11	4,246	0	549326	38-100-PMA	Service A PMI	29-Nov-2021 14:08:14	LAVSHP	P	DON	324.12
18-Feb-2022 11	4,253	0	568280	03-063-003	Replace Transceiver - GPS Tracker	19-Feb-2022 08:11:03	ME1371	Q	DON	321.00
18-Feb-2022 11	4,253	0	568280	38-063-003	Service Transceiver - GPS Tracker	04-Mar-2022 13:53:23	SCHED	N	DON	0.00
21-Mar-2022 11	4,224	0	576047	03-063-003	Replace Transceiver - GPS Tracker	21-Mar-2022 13:00:31	TRK401	P	DON	252.22
20-Apr-2022 0	4,283	0	582944	03-065-007	Replace Hoses & Fittings	21-Apr-2022 12:33:34	LAVSHP	B	DON	587.22
11-May-2022 11	4,351	0	587953	24-065-020	Repair Control Valve	11-May-2022 16:02:38	ME1371	I	DON	29.46
11-May-2022 11	4,351	0	587953	06-100-PMA	Inspect A PMI	11-May-2022 15:34:17	ME1371	P	DON	14.70
11-May-2022 11	4,351	0	587953	38-100-PMA	Service A PMI	11-May-2022 14:34:24	ME1371	P	DON	156.30
18-Jul-2022 15	4,439	0	603297	06-310-016	Inspect Operator Controls	18-Jul-2022 17:55:01	TRK400	O	DON	49.39
26-Jan-2023 11	4,622	0	648210	03-017-001	Replace Tire - Pneumatic	14-Feb-2023 15:44:30	BTIRE	I	DON	1,584.37
26-Jan-2023 11	4,622	0	648210	03-017-011	Replace Tire - Foam Filled	09-Feb-2023 13:59:49	BTIRE	I	DON	2,352.91
26-Jan-2023 11	4,622	0	648210	03-065-007	Replace Hoses & Fittings	14-Feb-2023 07:19:36	BBKHOE	I	DON	539.12
26-Jan-2023 11	4,622	0	648210	03-032-001	Replace Battery	10-Feb-2023 10:33:20	BBKHOE	I	DON	489.55
26-Jan-2023 11	4,622	0	648210	06-100-PMC	Inspect C PMI	14-Feb-2023 15:44:17	BBKHOE	P	DON	410.70
26-Jan-2023 11	4,622	0	648210	02-310	Clean Backhoe (Rubber Tire)	01-Feb-2023 16:00:03	BWASH	N	DON	703.79
26-Jan-2023 11	4,622	0	648210	03-051-009	Replace Fire Extinguisher	10-Feb-2023 11:05:07	BBKHOE	Q	DON	192.34
26-Jan-2023 11	4,622	0	648210	03-065-004	Replace Cylinder	14-Feb-2023 15:44:21	BBKHOE	I	DON	2,051.46

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Q1236 - 2016 JOHN DEERE 310SL										
26-Jan-2023 1(4,622	0	648210	10-310-001	Rebush Boom (Main)	13-Feb-2023 12:00:01	BBKHOE	I	DON	952.72
26-Jan-2023 1(4,622	0	648210	01-310-017	Adjust Cutting Edges	10-Feb-2023 13:12:23	BBKHOE	I	DON	29.25
26-Jan-2023 1(4,622	0	648210	03-045-023	Replace Engine Belts	09-Feb-2023 12:00:01	BBKHOE	I	DON	110.40
26-Jan-2023 1(4,622	0	648210	14-002-001	Install Radiator Grille	14-Feb-2023 07:19:55	BBKHOE	I	DON	311.45
26-Jan-2023 1(4,622	0	648210	38-100-PMC	Service C PMI	14-Feb-2023 15:44:18	BBKHOE	I	DON	472.91
26-Jan-2023 1(4,622	0	648210	24-034	Repair Lighting System	10-Feb-2023 12:00:00	BBKHOE	I	DON	34.03
26-Jan-2023 1(4,622	0	648210	03-514-002	Replace Shanks or Teeth	14-Feb-2023 15:44:34	BBKHOE	I	DON	156.20
26-Jan-2023 1(4,622	0	648210	26-514-004	Weld Edges	14-Feb-2023 06:59:43	BHVYEQ	N	DON	195.87
22-Jun-2023 1:		0	683509	03-034-003	Replace Signal, Parking, Backup Lamps	22-Jun-2023 14:59:02	OTSSHP	I	DON	11.87
22-Jun-2023 1:		0	683509	03-044-024	Replace Fuel / Water Separator	18-Jul-2023 05:51:48	OTSSHP	I	DON	91.74
22-Jun-2023 1:		0	683509	06-049-001	Inspect ECM Fault Code	29-Jun-2023 08:52:00	OTSSHP	O	DON	184.17
14-Aug-2023 C		0	696573	06-100-PMB	Inspect B PMI	31-Aug-2023 14:32:25	BBKHOE	P	DON	42.59
14-Aug-2023 C		0	696573	02-310	Clean Backhoe (Rubber Tire)	24-Aug-2023 09:20:28	BWASH	N	DON	450.49
14-Aug-2023 C		0	696573	OS-310	Out-Service Backhoe (Rubber Tire)	30-Aug-2023 14:50:12	BBKHOE	Z	DON	109.27
14-Aug-2023 C		0	696573	03-045-023	Replace Engine Belts	30-Aug-2023 14:07:29	BBKHOE	Z	DON	128.73

Unit No: Q1236

Count: 131

46,098.53