

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Z1063 - 2015 VERMEER D36X50II										
21-Apr-2015	1	6	0	198510	14-063	Install Satellite Communications System	BSMEQP	C	DON	359.12
13-Jul-2015	08	55	0	207380	14-111-001	Install Track	BSMEQP	B	DON	376.06
04-Nov-2015	1	669	0	220806	24-040	Repair Engine / Motor Systems Group	BSMEQP	W	DON	36.96
28-Dec-2015	0	669	0	226628	02-704	Clean Drill Rig	BWASH	J	DON	124.63
30-Dec-2015	1	669	0	226911	24-704	Repair Drill Rig	BSMEQP	S	DON	5,374.08
30-Dec-2015	1	669	0	226911	24-003-001	Repair Gauges & Warning Devices	BSMEQP	B	DON	403.61
11-Mar-2016	1	669	0	237023	24-003	Repair Instruments, Gauges, Warning & Shutdo	BSMEQP	B	DON	2,335.16
04-Apr-2016	0	743	0	239909	24-042-002	Repair Radiator	BSMEQP	B	DON	579.97
05-May-2016	1	743	0	243659	24-267	Repair Drilling and Boring	BSMEQP	B	DON	409.74
28-Jun-2016	1	973	0	249999	24-267-002	Repair Feeding Assembly	BSMEQP	B	DON	1,572.31
21-Jul-2016	10	973	0	252742	24-704	Repair Drill Rig	BSMEQP	I	DON	749.96
14-Sep-2016	1	973	0	259428	24-700	Repair Directional Drilling Group	BSMEQP	B	DON	543.32
12-Jan-2017	11	973	0	273052	24-704	Repair Drill Rig	BSMEQP	I	DON	5,767.42
27-Mar-2017	2	973	0	283526	03-267-008	Replace Rod Holder	MPNFLD	I	DON	469.59
27-Mar-2017	2	973	0	283526	03-267	Replace Drilling and Boring	MPNFLD	I	CAN	0.00
18-May-2017	1	973	0	289798	95-MSC-004	Travel Travel Time - To/From Job Site	BSDRIL	F	DON	46.93
18-May-2017	1	973	0	289798	11-702-001	Rebuild Liners, Valves, and Seals	BSDRIL	F	DON	67.22
01-Jun-2017	0	973	0	291511	38-267	Service Drilling and Boring	BSDRIL	J	DON	2,193.10
01-Jun-2017	0	973	0	291511	14-034-006	Install Warning Lamps - Special Application	BSDRIL	F	DON	314.68
01-Jun-2017	0	973	0	291511	22-267-006	Design Frame Chassis	BWELD	D	DON	144.26
01-Jun-2017	0	973	0	291511	02-704	Clean Drill Rig	BSETUP	J	DON	190.37
01-Jun-2017	0	973	0	291511	14-704-010	Install Wiring	BSDRIL	F	DON	2,785.90
01-Jun-2017	0	973	0	291511	24-267-003	Repair Hydraulics	BSDRIL	F	DON	741.03
29-Aug-2017	0	973	0	302835	02-704	Clean Drill Rig	BWASH	J	DON	184.30
26-Oct-2017	0	2,118	0	310596	24-702-001	Repair Liners, Valves, and Seals	BSDRIL	E	DON	5,551.05
26-Oct-2017	0	2,118	0	310596	95-MSC-004	Travel Travel Time - To/From Job Site	BSDRIL	E	DON	197.58
27-Oct-2017	0	2,118	0	310517	24-045-021	Repair Electronic Engine Controls	BVLOFC	B	DON	613.19
27-Oct-2017	0	2,118	0	310517	95-MSC	Travel Miscellaneous	BVLOFC	B	DON	545.64
30-Oct-2017	0	2,118	0	310627	01-704-016	Adjust Stern Rack	BSDRIL	N	DON	3.01

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
<b>Unit No: Z1063 - 2015 VERMEER D36X50II</b>										
30-Oct-2017 0	2,118	0	310627	01-704-017	Adjust Rod Loader System	01-Nov-2017 06:42:26	BSDRIL	I	DON	895.72
30-Oct-2017 0	2,118	0	310627	02-704	Clean Drill Rig	30-Oct-2017 14:09:37	BWASH	I	DON	114.78
30-Oct-2017 0	2,118	0	310627	03-042-013	Replace Fan Belt	31-Oct-2017 17:00:26	BSDRIL	I	DON	230.65
30-Oct-2017 0	2,118	0	310627	03-701-002	Replace Plumbing / Valves (water)	31-Oct-2017 13:30:14	BSDRIL	I	DON	503.38
30-Oct-2017 0	2,118	0	310627	06-704	Inspect Drill Rig	01-Nov-2017 07:05:48	BSDRIL	J	DON	9.06
30-Oct-2017 0	2,118	0	310627	24-002-065	Repair Hood Latch	01-Nov-2017 07:58:01	BSDRIL	I	DON	102.92
30-Oct-2017 0	2,118	0	310627	24-704-017	Repair Rod Loader System	01-Nov-2017 11:43:39	BSDRIL	I	DON	219.77
30-Oct-2017 0	2,118	0	310627	24-704-022	Repair Rotation Thrust / Bearing Box	02-Nov-2017 14:53:24	BSDRIL	I	DON	222.15
30-Oct-2017 0	2,118	0	310627	24-705	Repair Vise	31-Oct-2017 11:39:42	BSDRIL	N	DON	731.77
30-Oct-2017 0	2,118	0	310627	38-704	Service Drill Rig	02-Nov-2017 07:31:10	BSDRIL	J	DON	339.13
18-Nov-2017 0	2,118	0	313122	03-042-006	Replace Thermostat	20-Nov-2017 06:45:43	BSDRIL	F	DON	114.68
18-Nov-2017 0	2,118	0	313122	95-MSC-004	Travel Travel Time - To/From Job Site	20-Nov-2017 06:45:37	BSDRIL	F	DON	141.97
21-Nov-2017 0	2,118	0	313349	18-042	Test Cooling System	22-Nov-2017 08:39:53	BSDRIL	F	DON	781.94
28-Dec-2017 0	2,118	0	317413	38-040	Service Engine / Motor Systems Group	10-Jan-2018 07:01:21	BSDRIL	P	DON	210.84
28-Dec-2017 0	2,118	0	317413	24-704-017	Repair Rod Loader System	10-Jan-2018 07:01:14	BSDRIL	I	DON	2,779.54
28-Dec-2017 0	2,118	0	317413	24-705	Repair Vise	10-Jan-2018 07:09:02	BSDRIL	I	DON	1,663.80
28-Dec-2017 0	2,118	0	317413	03-708-007	Replace Sub Saver	10-Jan-2018 07:09:08	BSDRIL	I	DON	376.63
18-Jan-2018 0	2,301	0	320052	06-702	Inspect Mud Pump	18-Jan-2018 11:40:29	BSDRIL	I	DON	35.35
18-Jan-2018 0	2,301	0	320052	24-702	Repair Mud Pump	18-Jan-2018 16:22:33	BSDRIL	I	DON	3,137.26
22-Jan-2018 0	2,301	0	320439	24-044-025	Repair Fuel Cooler	22-Jan-2018 10:56:04	BSDRIL	I	DON	77.13
22-Jan-2018 0	2,301	0	320439	24-063-003	Repair Transceiver - GPS Tracker	22-Jan-2018 11:38:42	BSDRIL	I	DON	22.03
22-Jan-2018 0	2,301	0	320439	24-042-015	Repair Fan Hub	09-Feb-2018 10:21:45	BSDRIL	I	DON	503.61
22-Jan-2018 0	2,301	0	320439	95-MSC-004	Travel Travel Time - To/From Job Site	09-Feb-2018 10:21:48	BSDRIL	F	DON	297.26
22-Jan-2018 0	2,301	0	320439	24-033	Repair Ignition System	06-Feb-2018 08:08:09	BSDRIL	F	DON	1,349.00
22-Jan-2018 0	2,301	0	320439	03-111	Replace Undercarriage	09-Feb-2018 10:21:48	BSDRIL	F	DON	359.53
22-Jan-2018 0	2,301	0	320439	24-704-016	Repair Stem Rack	09-Feb-2018 10:21:48	BSDRIL	F	DON	162.38
22-Jan-2018 0	2,301	0	320439	24-704-015	Repair Track	09-Feb-2018 10:21:48	BSDRIL	F	DON	46.51
27-Feb-2018 1	2,301	0	325262	02-002	Clean Cab & Sheet Metal	10-Apr-2018 15:31:13	BWASH	J	DON	183.96
28-Feb-2018 1	2,301	0	325530	38-040	Service Engine / Motor Systems Group	01-Mar-2018 08:25:56	BSDRIL	J	DON	197.68

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Z1063 - 2015 VERMEER D36X50H										
28-Feb-2018 1	2,301	0	325530	06-704	Inspect Drill Rig	02-Mar-2018 16:13:17	BSDRIL	P	DON	98.61
28-Feb-2018 1	2,301	0	325530	24-702	Repair Mud Pump	01-Mar-2018 10:21:32	BSDRIL	I	DON	33.54
28-Feb-2018 1	2,301	0	325530	24-705	Repair Vise	02-Mar-2018 16:12:30	BSDRIL	I	DON	512.43
28-Feb-2018 1	2,301	0	325530	06-705	Inspect Vise	02-Mar-2018 06:53:24	BSDRIL	J	DON	33.77
28-Feb-2018 1	2,301	0	325530	06-040	Inspect Engine / Motor Systems Group	15-Mar-2018 15:19:09	BSDRIL	I	DON	100.58
08-May-2018 (		0	335805	06-100-PMA	Inspect A PMI	15-May-2018 00:00:00	BVLOFC	P	DON	849.64
08-May-2018 (		0	335805	95-MSC	Travel Miscellaneous	15-May-2018 00:00:00	BVLOFC	P	DON	287.97
15-May-2018 (	2,301	0	335748	02-002	Clean Cab & Sheet Metal	15-May-2018 11:17:04	BSETUP	J	DON	82.68
15-May-2018 (	2,301	0	335748	06-704	Inspect Drill Rig	16-May-2018 09:38:15	BSDRIL	P	DON	99.30
15-May-2018 (	2,301	0	335748	24-705	Repair Vise	17-May-2018 12:03:02	BSDRIL	I	DON	657.96
15-May-2018 (	2,301	0	335748	38-704-015	Service Track	16-May-2018 17:00:05	BSDRIL	J	DON	775.47
15-May-2018 (	2,301	0	335748	06-705	Inspect Vise	17-May-2018 07:23:01	BSDRIL	P	DON	13.82
11-Jul-2018 07	2,600	0	343324	03-065-007	Replace Hoses & Fittings	11-Jul-2018 07:37:06	BSDRIL	F	DON	68.82
11-Jul-2018 07	2,742	0	343329	03-098-001	Replace Ball Valve Assembly (Blowdown Valve	11-Jul-2018 08:47:31	BSDRIL	F	DON	1,074.30
11-Jul-2018 07	2,742	0	343329	38-045-003	Service Crankshaft	11-Jul-2018 08:46:21	BSDRIL	F	DON	405.39
30-Jul-2018 11	2,788	0	345887	24-704-002	Repair Guide Rollers	31-Jul-2018 11:31:33	BSDRIL	B	DON	4,083.06
06-Aug-2018 C	2,788	0	346779	02-002	Clean Cab & Sheet Metal		BSETUP	N	CAN	0.00
06-Aug-2018 C	2,788	0	346832	02-704	Clean Drill Rig	07-Aug-2018 13:11:04	BWASH	N	DON	402.76
08-Aug-2018 C	2,788	0	347240	06-704	Inspect Drill Rig	08-Aug-2018 08:41:49	BSDRIL	P	DON	71.00
08-Aug-2018 C	2,788	0	347240	24-042-015	Repair Fan Hub	09-Aug-2018 15:17:19	BSDRIL	I	DON	444.64
08-Aug-2018 C	2,788	0	347240	24-705	Repair Vise	08-Aug-2018 17:01:47	BSDRIL	I	DON	1,381.66
08-Aug-2018 C	2,788	0	347240	24-704-017	Repair Rod Loader System	10-Aug-2018 07:06:19	BSDRIL	I	DON	1,792.11
08-Aug-2018 C	2,788	0	347240	38-040	Service Engine / Motor Systems Group	17-Sep-2018 07:58:19	BSDRIL	N	DON	1,211.93
08-Aug-2018 C	2,788	0	347240	24-704-016	Repair Stem Rack	10-Aug-2018 17:06:48	BSDRIL	I	DON	19,681.35
08-Aug-2018 C	2,788	0	347240	24-410-002	Repair Lights	10-Sep-2018 13:00:44	BSDRIL	I	DON	169.36
08-Aug-2018 C	2,788	0	347240	02-704	Clean Drill Rig	10-Sep-2018 17:00:39	BSDRIL	P	DON	148.09
08-Aug-2018 C	2,788	0	347240	03-065-007	Replace Hoses & Fittings	11-Sep-2018 15:32:42	BVLOFC	B	DON	126.49
04-Oct-2018 04	2,788	0	355287	24-704-022	Repair Rotation Thrust / Bearing Box	06-Nov-2018 13:10:53	BSDRIL	E	DON	371.51
04-Oct-2018 04	2,788	0	355287	24-705	Repair Vise	06-Nov-2018 13:10:48	BSDRIL	E	DON	3,122.28

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Z1063 - 2015 VERMEER D36X50II										
04-Oct-2018 0i	2,788	0	355287	02-704	Clean Drill Rig	10-Oct-2018 09:14:30	BSDRIL	Q	DON	168.31
04-Oct-2018 0i	2,788	0	355287	95-MS-004	Travel Travel Time - To/From Job Site	10-Oct-2018 09:30:43	BSDRIL	B	DON	116.36
04-Oct-2018 0i	2,788	0	355287	38-045-011	Service Filter Assembly - Oil	06-Nov-2018 12:56:16	BSDRIL	P	DON	8.21
04-Oct-2018 0i	2,788	0	355287	24-040	Repair Engine / Motor Systems Group	15-Oct-2018 07:21:00	BSDRIL	I	DON	133.79
04-Oct-2018 0i	2,788	0	355287	38-040	Service Engine / Motor Systems Group	15-Oct-2018 07:13:21	BSDRIL	N	DON	29.77
04-Oct-2018 0i	2,788	0	355287	24-704-011	Repair Frame / Chassis	15-Oct-2018 07:13:05	BSDRIL	I	DON	132.35
04-Oct-2018 0i	2,788	0	355287	38-704	Service Drill Rig	15-Oct-2018 07:13:15	BSDRIL	N	DON	300.77
04-Oct-2018 0i	2,788	0	355287	02-506-002	Clean Hydraulic Tank	15-Oct-2018 07:10:50	BSDRIL	I	DON	339.31
08-Oct-2018 1i	2,788	0	355515	02-704	Clean Drill Rig	08-Oct-2018 16:13:00	BWASH	N	DON	157.05
09-Nov-2018 1i	2,788	0	360149	02-704	Clean Drill Rig	16-Nov-2018 16:53:44	BSETUP	I	DON	95.91
12-Nov-2018 0i	2,788	0	360266	06-704	Inspect Drill Rig	21-Nov-2018 08:48:44	BSDRIL	N	DON	17.17
12-Nov-2018 0i	2,788	0	360266	03-704-007	Replace Hydraulic Motor	21-Nov-2018 08:48:40	BSDRIL	O	DON	3,607.15
12-Nov-2018 0i	2,788	0	360266	38-705	Service Vise	13-Nov-2018 11:50:13	BSDRIL	I	DON	887.55
12-Nov-2018 0i	2,788	0	360266	38-040	Service Engine / Motor Systems Group	21-Nov-2018 08:48:22	BSDRIL	N	DON	164.59
12-Nov-2018 0i	2,788	0	360266	24-704-016	Repair Stem Rack	13-Nov-2018 07:32:36	BSDRIL	I	DON	341.66
18-Jan-2019 1i	2,788	0	369016	02-704	Clean Drill Rig	04-Mar-2019 17:00:11	BWASH	I	DON	255.14
21-Jan-2019 0i	2,788	0	369060	06-704	Inspect Drill Rig	22-Jan-2019 07:13:03	BSDRIL	O	DON	6.85
21-Jan-2019 0i	2,788	0	369060	24-704-017	Repair Rod Loader System	22-Jan-2019 09:41:57	BSDRIL	O	DON	289.23
21-Jan-2019 0i	2,788	0	369060	24-704-022	Repair Rotation Thrust / Bearing Box	22-Jan-2019 09:43:03	BSDRIL	O	DON	502.83
21-Jan-2019 0i	2,788	0	369060	38-047-001	Service Engine Filter Kits	21-Jan-2019 16:22:45	BSDRIL	N	DON	551.06
21-Jan-2019 0i	2,788	0	369060	38-705	Service Vise	21-Jan-2019 14:44:41	BSDRIL	I	DON	1,533.07
05-Mar-2019 0i	3,365	0	375121	06-704	Inspect Drill Rig	22-Mar-2019 12:59:37	BSDRIL	I	DON	310.00
05-Mar-2019 0i	3,365	0	375121	09-704-017	Align Rod Loader System	22-Mar-2019 12:59:51	BSDRIL	I	DON	59.51
05-Mar-2019 0i	3,365	0	375121	24-078-003	Repair Hose Carrier	06-Mar-2019 16:01:14	BSDRIL	N	DON	205.89
05-Mar-2019 0i	3,365	0	375121	24-094	Repair Lines, Tubes, Hoses & Fittings - Bulk Pr	22-Mar-2019 12:59:43	BSDRIL	I	DON	792.33
05-Mar-2019 0i	3,365	0	375121	24-704-015	Repair Track	22-Mar-2019 12:59:48	BSDRIL	N	DON	1,284.78
05-Mar-2019 0i	3,365	0	375121	24-705	Repair Vise	06-Mar-2019 11:40:10	BSDRIL	N	DON	1,152.11
05-Mar-2019 0i	3,365	0	375121	38-040	Service Engine / Motor Systems Group	22-Mar-2019 12:59:33	BSDRIL	P	DON	286.92
05-Mar-2019 0i	3,365	0	375121	38-702	Service Mud Pump	22-Mar-2019 12:59:39	BSDRIL	N	DON	1,940.92

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Z1063 - 2015 VERMEER D36X50II										
06-May-2020	3,666	0	439502	03-032-001	Replace Battery	26-May-2020 11:06:51	BSDRIL	N	DON	987.54
06-May-2020	3,666	0	439502	03-034-014	Replace Auxiliary Work / Flood Light	26-May-2020 11:07:06	BSDRIL	I	DON	398.65
06-May-2020	3,666	0	439502	03-065-020	Replace Control Valve	26-May-2020 11:06:47	BSDRIL	B	DON	603.54
06-May-2020	3,666	0	439502	03-708-007	Replace Sub Saver	26-May-2020 11:06:58	BSDRIL	N	DON	513.29
06-May-2020	3,666	0	439502	06-100-PMA	Inspect A PMI	26-May-2020 11:06:29	BSDRIL	P	DON	242.70
06-May-2020	3,666	0	439502	06-100-PMB	Inspect B PMI	26-May-2020 11:06:35	BSDRIL	P	DON	237.35
06-May-2020	3,666	0	439502	11-705	Rebuild Vise	26-May-2020 11:06:55	BSDRIL	N	DON	4,403.44
06-May-2020	3,666	0	439502	24-704-017	Repair Rod Loader System	26-May-2020 11:06:39	BSDRIL	B	DON	6,063.97
06-May-2020	3,666	0	439502	24-705-010	Repair Grease System	26-May-2020 11:07:02	BSDRIL	N	DON	519.55
06-May-2020	3,666	0	439502	38-040	Service Engine / Motor Systems Group	26-May-2020 11:06:43	BSDRIL	P	DON	2,724.07
11-Mar-2021	3,679	0	493652	06-100-PMA	Inspect A PMI	11-Mar-2021 16:44:26	SCHED	P	DON	27.36
11-Mar-2021	3,679	0	493652	06-100-PMB	Inspect B PMI	12-Mar-2021 05:08:34	SCHED	P	DON	74.54
06-Oct-2021	3,679	0	537231	03-065-007	Replace Hoses & Fittings	08-Oct-2021 08:16:27	LAVSHP	B	DON	2,710.95
11-Nov-2021	3,679	0	545944	03-910-001	Replace Dies - Jaw	11-Nov-2021 14:46:58	OTSSHP	N	DON	416.31
16-Nov-2021	4,007	0	546965	03-053-008	Replace Hoses & Tubings & Fittings	18-Nov-2021 11:28:57	OTSSHP	N	DON	217.90
16-Nov-2021	4,007	0	546965	06-100-PMA	Inspect A PMI	18-Nov-2021 11:27:35	OTSSHP	P	DON	0.00
16-Nov-2021	4,007	0	546965	38-100-PMA	Service A PMI	16-Nov-2021 11:19:31	OTSSHP	P	DON	224.16
06-Dec-2021	4,007	0	551530	35-705-007	Diagnose Wiring		LAVSHP	B	CAN	0.00
07-Dec-2021	4,007	0	551743	03-032-001	Replace Battery	10-Dec-2021 11:12:19	OTSSHP	N	DON	0.00
14-Dec-2021	4,007	0	553555	06-706-001	Inspect Engine	14-Dec-2021 16:02:12	OTSSHP	O	DON	93.91
05-Jan-2022	4,090	0	557254	03-031-001	Replace Generator/Alternator	05-Jan-2022 12:06:11	OTSSHP	O	DON	473.06
05-Jan-2022	4,090	0	557254	03-032-001	Replace Battery	10-Jan-2022 10:20:34	OTSSHP	N	DON	192.84
10-Jan-2022	4,090	0	558133	03-708-004	Replace Starter Rod	10-Jan-2022 11:41:03	OTSSHP	P	DON	1,114.39
04-Feb-2022	4,090	0	564304	03-032-001	Replace Battery	07-Feb-2022 10:10:23	OTSSHP	I	DON	248.28
04-Feb-2022	4,090	0	564304	03-063-003	Replace Transceiver - GPS Tracker	07-Feb-2022 07:18:07	OTSSHP	Q	DON	276.07
04-Feb-2022	4,090	0	564304	06-032-002	Inspect Starter	07-Feb-2022 06:56:12	OTSSHP	O	DON	21.95
22-Mar-2022	4,090	0	576503	03-063-003	Replace Transceiver - GPS Tracker	22-Mar-2022 17:00:08	OTSSHP	I	DON	313.47
22-Mar-2022	4,090	0	576503	06-063-003	Inspect Transceiver - GPS Tracker	22-Mar-2022 16:11:30	OTSSHP	Q	DON	39.88
23-Mar-2022	4,090	0	576797	03-708-004	Replace Starter Rod	23-Mar-2022 14:40:37	OTSSHP	N	DON	982.69

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost	
Unit No: Z1063 - 2015 VERMEER D36X50II											
23-Mar-2022	1	4,090	0	576797	03-708-007	Replace Sub Saver	23-Mar-2022 14:43:17	OTSSHP	N	DON	829.94
12-Apr-2022	1	4,090	0	581330	06-049-001	Inspect ECM Fault Code	14-Apr-2022 07:51:36	ME1371	I	DON	156.46
12-Apr-2022	1	4,090	0	581330	24-268-003	Repair Hydraulics	12-Apr-2022 15:04:25	ME1371	I	DON	65.90
28-Apr-2022	1	4,090	0	585106	06-100-WTN	Inspect Winterization Inspection	03-May-2022 07:50:00	OTSSHP	I	DON	139.15
28-Apr-2022	1	4,090	0	585106	06-267	Inspect Drilling and Boring	03-May-2022 07:50:00	OTSSHP	B	DON	1,035.06
28-Apr-2022	1	4,090	0	585106	38-100-WTN	Service Winterization Inspection	03-May-2022 08:01:00	OTSSHP	P	DON	704.31
23-Jun-2022	1		0	598222	03-063-003	Replace Transceiver - GPS Tracker	23-Jun-2022 15:13:47	ELEC02	Q	DON	360.82
29-Jun-2022	1		0	599409	02-704	Clean Drill Rig	30-Jun-2022 07:57:35	BWASH	N	DON	482.98
05-Jul-2022	13		0	600279	06-100-PMA	Inspect A PMI	22-Aug-2022 07:52:27	BSDRIL	P	DON	440.08
05-Jul-2022	13		0	600279	06-100-PMB	Inspect B PMI	02-Sep-2022 10:54:50	BSDRIL	P	DON	8.44
05-Jul-2022	13		0	600279	24-704-015	Repair Track	22-Aug-2022 07:52:49	BSDRIL	I	DON	675.68
05-Jul-2022	13		0	600279	24-704-017	Repair Rod Loader System	22-Aug-2022 07:52:44	BSDRIL	I	DON	5,291.63
05-Jul-2022	13		0	600279	24-704-018	Repair Operator Console / Station	22-Aug-2022 07:52:33	BSDRIL	I	DON	1,062.60
05-Jul-2022	13		0	600279	24-705	Repair Vise	22-Aug-2022 07:52:47	BSDRIL	I	DON	3,593.72
05-Jul-2022	13		0	600279	25-053-005	Remove Markings - Vehicle - Decals	22-Aug-2022 07:52:32	BSDRIL	Z	DON	502.15
05-Jul-2022	13		0	600279	38-040	Service Engine / Motor Systems Group	22-Aug-2022 07:52:30	BSDRIL	N	DON	1,179.46
05-Jul-2022	13		0	600279	38-702	Service Mud Pump	22-Aug-2022 07:53:01	BSDRIL	N	DON	148.97
05-Jul-2022	13		0	600279	38-704-016	Service Stem Rack	22-Aug-2022 07:53:03	BSDRIL	N	DON	122.39
05-Jul-2022	13		0	600279	38-704-022	Service Rotation Thrust / Bearing Box	22-Aug-2022 07:52:59	BSDRIL	I	DON	821.64
21-Jul-2022	13		0	604266	24-267	Repair Drilling and Boring	27-Jul-2022 14:08:00	OTSSHP	B	DON	510.06
21-Jul-2022	13		0	604266	95-MSC-004	Travel Travel Time - To/From Job Site	27-Jul-2022 14:13:48	OTSSHP	B	DON	317.11
22-Aug-2022	C	4,257	0	612459	95-MSC-004	Travel Travel Time - To/From Job Site	28-Aug-2022 20:50:31	MA0722	B	DON	235.26
22-Aug-2022	C	4,257	0	612459	01-030-002	Adjust Dead Man Switch	28-Aug-2022 20:47:51	MA0722	B	DON	418.23
22-Aug-2022	C	4,257	0	612459	03-032-001	Replace Battery	28-Aug-2022 20:44:34	MA0722	B	DON	1,061.32
30-Sep-2022	1	4,363	0	642672	03-065-007	Replace Hoses & Fittings	30-Sep-2022 15:25:00	MPNFLD	N	DON	282.96
07-Oct-2022	1	4,322	0	622678	38-704-015	Service Track	13-Oct-2022 08:26:52	BSDRIL	B	DON	1,278.99
07-Oct-2022	1	4,322	0	622678	95-MSC-004	Travel Travel Time - To/From Job Site	13-Oct-2022 08:27:05	BSDRIL	B	DON	835.86
24-Oct-2022	0	4,346	0	626412	38-705	Service Vise	24-Oct-2022 07:30:36	BSDRIL	O	DON	329.23
31-Oct-2022	1	4,355	0	628512	12-704-015	Refinish Track	01-Nov-2022 05:57:30	BSDRIL	W	DON	0.00

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Z1063 - 2015 VERMEER D36X50H										
31-Oct-2022	1	4,355	0	628512	38-704-015	Service Track	BSDRIL	O	DON	1,749.61
21-Nov-2022	C	4,357	0	633841	02-704	Clean Drill Rig	BWASH	N	DON	273.27
28-Nov-2022	C	4,357	0	634991	38-002-037	Service Seat Assembly	BSDRIL	I	DON	917.12
28-Nov-2022	C	4,357	0	634991	38-034-001	Service Headlamps / Fog Lamps	ESDRIL	I	DON	136.43
28-Nov-2022	C	4,357	0	634991	38-040	Service Engine / Motor Systems Group	ESDRIL	N	DON	528.47
28-Nov-2022	C	4,357	0	634991	38-704-013	Service Stakedown	ESDRIL	I	DON	144.50
28-Nov-2022	C	4,357	0	634991	38-704-015	Service Track	ESDRIL	N	DON	1,909.14
28-Nov-2022	C	4,357	0	634991	38-704-016	Service Stem Rack	ESDRIL	N	DON	177.12
28-Nov-2022	C	4,357	0	634991	38-704-017	Service Rod Loader System	ESDRIL	N	DON	531.20
28-Nov-2022	C	4,357	0	634991	38-704-022	Service Rotation Thrust / Bearing Box	ESDRIL	N	DON	6,075.27
28-Nov-2022	C	4,357	0	634991	38-705	Service Vise	ESDRIL	N	DON	1,418.27
16-Dec-2022	0	4,363	0	639750	38-704-018	Service Operator Console / Station	ESDRIL	I	DON	1,887.43
10-Aug-2023	1		0	695763	25-063-003	Remove Transceiver - GPS Tracker	BSDRIL	N	DON	174.34
21-Aug-2023	C		0	698559	38-002-004	Service Hood	ESDRIL	I	DON	351.03
13-Sep-2023	0		0	704678	03-704-015	Replace Track	BSDRIL	I	DON	625.51

Unit No: Z1063

Count: 189

166,172.73