

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost	
Unit No: Q1190 - 2015 JOHN DEERE 310SK											
16-Feb-2015	1	4	0	191577	14-034-006	Install Warning Lamps - Special Application	16-Feb-2015 17:34:25	BBKHOE	Q	DON	166.72
16-Feb-2015	1	4	0	191577	14-051	Install General Accessories	17-Feb-2015 17:04:55	BBKHOE	Q	DON	866.96
16-Feb-2015	1	4	0	191577	14-052-003	Install Radio Equipment	18-Feb-2015 16:00:03	BBKHOE	Q	DON	869.74
16-Feb-2015	1	4	0	191577	14-059-002	Install Pintle Hook Assembly	18-Feb-2015 10:05:38	BBKHOE	Q	DON	477.06
16-Feb-2015	1	4	0	191577	14-063-003	Install Transceiver - GPS Tracker	16-Feb-2015 16:45:43	BBKHOE	C	DON	42.95
27-May-2015	1	4	0	202256	03-063-003	Replace Transceiver - GPS Tracker	27-May-2015 20:52:12	MPNFLD	B	DON	68.58
27-May-2015	1	4	0	202256	06-018-009	Inspect Nut - Wheel, Outer	27-May-2015 20:49:34	MPNFLD	P	DON	34.29
22-Jan-2016	0	4	0	230431	06-100-PMA	Inspect A PMI	22-Jan-2016 19:41:46	ME0546	P	DON	93.06
22-Jan-2016	0	4	0	230431	06-778-022	Inspect Grease Pump - Mechanical	01-Apr-2016 17:24:29	ME0546	P	DON	15.93
25-Jan-2017	0	4	0	274861	03-094	Replace Lines, Tubes, Hoses & Fittings - Bulk P	18-Apr-2017 09:37:20	ME1287	B	DON	348.78
25-Jan-2017	0	4	0	274861	24-042-009	Repair Coolant Pre-Heater- Electrical	25-Jan-2017 20:11:04	ME1287	B	DON	17.61
27-Feb-2017	1	358	0	279766	03-002-027	Replace Seat Frames & Springs	08-May-2017 10:00:24	MPNFLD	I	DON	954.41
27-Feb-2017	1	358	0	279766	06-100-PMA	Inspect A PMI	05-Mar-2017 18:37:52	BBKHOE	P	DON	70.43
12-Oct-2017	0	358	0	308844	03-052-009	Replace Speakers	15-Oct-2017 09:33:18	ME1287	B	DON	17.61
18-Jun-2018	1	358	0	340846	06-100-PMA	Inspect A PMI	21-Jun-2018 18:26:35	MA0722	P	DON	94.80
20-Aug-2018	1	358	0	349011	03-052-003	Replace Radio Equipment	20-Aug-2018 14:42:19	ELEC02	C	DON	531.90
28-Aug-2018	0	358	0	350106	03-065-007	Replace Hoses & Fittings	11-Jan-2019 13:00:49	ME0547	O	DON	69.95
13-Nov-2018	0	1,023	0	361078	03-044-003	Replace Fuel Pump	09-Jan-2019 10:03:49	ME1287	B	DON	1,224.76
13-Nov-2018	0	1,023	0	361078	38-100-300	Service Off Road Equip / Field Service	20-Dec-2018 20:19:09	ME1287	P	DON	230.15
15-Jan-2019	0	1,142	0	368833	03-310-016	Replace Operator Controls	14-Aug-2019 13:56:12	ME1287	B	DON	103.50
15-Jan-2019	0	1,142	0	368833	25-065-007	Remove Hoses & Fittings	14-Aug-2019 13:56:24	ME1287	B	DON	71.44
21-Oct-2019	0	1,503	0	408667	01-015-010	Adjust Cylinder - Steering Hydraulic	25-Oct-2019 09:49:34	MB2290	I	DON	239.97
21-Oct-2019	0	1,503	0	408667	03-034-006	Replace Warning Lamps - Special Application	07-Nov-2019 09:53:38	ME0547	I	DON	193.54
21-Oct-2019	0	1,503	0	408667	24-017-011	Repair Tire - Foam Filled	22-Oct-2019 07:40:00	BTIRE	B	DON	214.05
04-Feb-2020	1	1,642	0	424742	01-017-001	Adjust Tire - Pneumatic		ME0547	O	WR	0.00
04-Feb-2020	1	1,642	0	424742	06-100-009	Inspect Safety Check	04-Feb-2020 16:39:51	ME0547	P	DON	21.54
04-Feb-2020	1	1,642	0	424742	24-034-002	Repair Stop, Tail, Turn & License	04-Feb-2020 15:55:33	ME0547	O	DON	10.77
19-Feb-2020	1	1,652	0	427048	01-017-001	Adjust Tire - Pneumatic	26-Feb-2020 12:28:26	ME0547	O	DON	8.08
26-May-2020	1	1,773	0	442394	01-017-001	Adjust Tire - Pneumatic	26-May-2020 19:30:56	TRK021	B	DON	17.86

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Q1190 - 2015 JOHN DEERE 310SK										
26-May-2020	1,773	0	442394	03-034-002	Replace Stop, Tail, Turn & License		ME0547	I	WR	58.10
26-May-2020	1,773	0	442394	03-065-006	Replace Filters, Strainers, Screens & Housing		ME0547	O	WR	0.00
26-May-2020	1,773	0	442394	03-065-007	Replace Hoses & Fittings	16-Jun-2020 17:33:45	ME0547	O	DON	163.69
26-May-2020	1,773	0	442394	03-310-007	Replace Outrigger Pads		ME0547	I	WR	0.00
26-May-2020	1,773	0	442394	06-065-001	Inspect Hydraulic Systems	24-Jun-2020 06:02:12	MB2290	I	DON	56.98
26-May-2020	1,773	0	442394	06-100-PMA	Inspect A PMI	16-Jun-2020 17:33:23	ME0547	P	DON	64.63
15-Jul-2020	1,838	0	450734	38-065	Service Hydraulic Systems - Special Applicator	28-Jul-2020 14:15:05	BVLOFC	B	DON	1,557.04
15-Jul-2020	1,838	0	450734	95-010-001	Travel All Axles	28-Jul-2020 14:15:05	BVLOFC	B	DON	232.91
28-Jul-2020	1,844	0	453036	01-043-004	Adjust Turbocharger	25-Aug-2020 05:46:23	MB2290	I	DON	117.97
28-Jul-2020	1,844	0	453036	01-514-005	Adjust Pins	29-Jul-2020 06:24:34	MB2290	I	DON	28.49
28-Jul-2020	1,844	0	453036	03-034-002	Replace Stop, Tail, Turn & License	29-Jul-2020 06:23:16	ME0547	I	DON	28.49
15-Sep-2020	1,920	0	461688	01-017-001	Adjust Tire - Pneumatic	16-Sep-2020 06:04:57	MB2290	I	DON	28.49
27-Oct-2020	1,955	0	469033	03-017-001	Replace Tire - Pneumatic	25-Nov-2020 11:51:50	BVLOFC	N	DON	926.12
27-Oct-2020	1,955	0	469033	38-043	Service Exhaust System	18-Nov-2020 07:40:06	BVLOFC	B	DON	1,379.15
27-Oct-2020	1,955	0	469033	95-MSK-004	Travel Travel Time - To/From Job Site	18-Nov-2020 07:40:12	BVLOFC	N	DON	210.03
27-Oct-2020	1,963	0	469536	01-017-001	Adjust Tire - Pneumatic	30-Oct-2020 06:16:07	MB2290	I	DON	56.98
03-Nov-2020	1,985	0	470193	06-043-030	Inspect Aftertreatment Regeneration Device (AF	04-Nov-2020 05:51:11	MB2290	I	DON	85.47
03-Nov-2020	1,985	0	470193	06-100-PMA	Inspect A PMI	04-Nov-2020 05:53:47	MB2290	P	DON	242.26
27-Apr-2021	2,107	0	503275	03-032-001	Replace Battery	27-Apr-2021 20:03:25	TRK022	B	DON	528.89
17-May-2021	2,124	0	507298	06-100-PMA	Inspect A PMI	20-May-2021 09:41:22	TRK023	P	DON	0.00
17-May-2021	2,124	0	507298	06-100-PMB	Inspect B PMI	23-May-2021 18:01:35	SCHED	P	DON	87.46
17-May-2021	2,124	0	507298	38-100-PMA	Service A PMI	20-May-2021 09:41:27	TRK023	P	DON	165.66
08-Aug-2021	2,205	0	524797	24-052-003	Repair Radio Equipment	13-Aug-2021 06:56:31	TRK023	B	DON	104.56
22-Sep-2021	2,219	0	533369	03-017-001	Replace Tire - Pneumatic	13-Oct-2021 06:34:19	BTIRE	P	DON	3,671.72
22-Sep-2021	2,219	0	533865	03-001-016	Replace Filter - Cab Ventilation	18-Oct-2021 19:55:44	TRK023	B	DON	0.00
22-Sep-2021	2,219	0	533865	03-030	Replace Electrical Group	18-Oct-2021 19:55:47	TRK023	B	DON	87.56
22-Sep-2021	2,219	0	533865	24-017	Repair Tires, Tubes, Liners & Valves	24-Sep-2021 07:44:51	TRK023	B	DON	313.68
12-Dec-2021	0	0	554614	03-065-007	Replace Hoses & Fittings	18-Dec-2021 17:56:02	TRK023	B	DON	1,486.00
09-Feb-2022	0	0	565522	03-030	Replace Electrical Group	10-Feb-2022 06:52:31	TRK024	B	DON	215.55

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Q1190 - 2015 JOHN DEERE 310SK										
01-Mar-2022 0	2,280	0	570709	01-310-007	Adjust Outtrigger Pads	04-Apr-2022 12:00:01	BBKH0E	I	DON	198.46
01-Mar-2022 0	2,280	0	570709	02-310	Clean Backhoe (Rubber Tire)	06-Apr-2022 14:34:40	BWASH	N	DON	232.34
01-Mar-2022 0	2,280	0	570709	03-002-001	Replace Radiator Grille	06-Apr-2022 14:34:37	BBKH0E	E	DON	1,022.35
01-Mar-2022 0	2,280	0	570709	03-002-012	Replace Floor Pan	06-Apr-2022 14:34:32	BBKH0E	I	DON	423.82
01-Mar-2022 0	2,280	0	570709	03-017-011	Replace Tire - Foam Filled	06-Apr-2022 08:03:27	BBKH0E	I	DON	2,323.18
01-Mar-2022 0	2,280	0	570709	03-032-001	Replace Battery	04-Apr-2022 10:08:15	BBKH0E	I	DON	411.72
01-Mar-2022 0	2,280	0	570709	03-059-002	Replace Pintle Hook Assembly	05-Apr-2022 10:08:00	BBKH0E	I	DON	231.86
01-Mar-2022 0	2,280	0	570709	03-063-003	Replace Transceiver - GPS Tracker	04-Apr-2022 07:50:36	BBKH0E	Q	DON	321.36
01-Mar-2022 0	2,280	0	570709	03-065-004	Replace Cylinder	06-Apr-2022 14:34:46	BBKH0E	E	DON	1,089.16
01-Mar-2022 0	2,280	0	570709	03-065-007	Replace Hoses & Fittings	05-Apr-2022 08:43:28	BBKH0E	I	DON	1,362.43
01-Mar-2022 0	2,280	0	570709	06-100-PMC	Inspect C PMI	06-Apr-2022 09:17:14	BBKH0E	P	DON	300.33
01-Mar-2022 0	2,280	0	570709	10-514	Rebush Bucket	06-Apr-2022 05:15:23	BBKH0E	I	DON	661.65
01-Mar-2022 0	2,280	0	570709	24-002-037	Repair Seat Assembly	01-Apr-2022 14:00:10	BBKH0E	I	DON	1,503.13
01-Mar-2022 0	2,280	0	570709	24-034	Repair Lighting System	04-Apr-2022 09:22:01	BBKH0E	I	DON	117.57
01-Mar-2022 0	2,280	0	570709	24-310-003	Repair Boom Pins	05-Apr-2022 13:20:19	BBKH0E	I	DON	383.30
01-Mar-2022 0	2,280	0	570709	38-063-003	Service Transceiver - GPS Tracker	04-Apr-2022 06:15:57	BBKH0E	Q	DON	203.15
01-Mar-2022 0	2,280	0	570709	38-100-PMC	Service C PMI	06-Apr-2022 08:03:13	BBKH0E	P	DON	937.82
21-Apr-2022 0	2,340	0	583227	14-043-007	Install Exhaust Pipe/Elbow	21-Apr-2022 08:01:13	OTSSHP	O	DON	13.40
21-Apr-2022 1	2,340	0	583365	03-310-016	Replace Operator Controls	26-Apr-2022 10:33:17	LAVSHIP	O	DON	300.23
21-Apr-2022 1	2,340	0	583483	06-052	Inspect Electrical Accessories	21-Apr-2022 15:59:38	TRK400	O	DON	163.85
27-Apr-2022 1	2,340	0	584932	03-514-002	Replace Shanks or Teeth	27-Apr-2022 17:00:08	OTSSHP	N	DON	124.04
15-Jul-2022 12	2,544	0	602865	06-100-PMA	Inspect A PMI	21-Jul-2022 09:36:32	TRK401	P	DON	128.42
15-Jul-2022 12	2,544	0	602865	06-268-003	Inspect Hydraulics	15-Jul-2022 14:32:07	TRK401	O	DON	208.31
15-Jul-2022 12	2,544	0	602865	38-100-PMA	Service A PMI	21-Jul-2022 10:20:19	TRK401	P	DON	179.69
16-Aug-2022 1	2,604	0	609896	03-094-011	Replace Coupler - Quick Disconnect	23-Aug-2022 08:45:33	TRK401	I	DON	135.47
16-Aug-2022 1	2,604	0	609896	06-094-011	Inspect Coupler - Quick Disconnect	23-Aug-2022 08:35:00	TRK401	O	DON	71.67
16-Aug-2022 1	2,604	0	609896	25-059-002	Remove Pintle Hook Assembly	16-Aug-2022 12:00:33	TRK401	O	DON	39.65
29-Aug-2022 C	2,636	0	612602	06-065-001	Inspect Hydraulic Systems	29-Aug-2022 10:13:26	TRK400	O	DON	179.00
29-Aug-2022 C	2,636	0	612602	03-094-011	Replace Coupler - Quick Disconnect	29-Aug-2022 10:37:08	TRK400	I	DON	38.49

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Q1190 - 2015 JOHN DEERE 310SK										
29-Aug-2022 C	2,636	0	612602	03-065-007	Replace Hoses & Fittings	29-Aug-2022 12:40:37	TRK400	I	DON	526.20
08-Nov-2022 C	2,783	0	630606	03-034-006	Replace Warning Lamps - Special Application	08-Nov-2022 06:28:17	OTSSHP	O	DON	9.88
05-Dec-2022 I	2,806	0	636833	03-065-007	Replace Hoses & Fittings	13-Dec-2022 09:58:07	LAVSHP	B	DON	558.86
28-Dec-2022 I	2,824	0	641639	06-100-WIN	Inspect Winterization Inspection	29-Dec-2022 06:43:07	LAVSHP	P	DON	48.93
28-Dec-2022 I	2,824	0	641639	38-100-PMA	Service A PMI	29-Dec-2022 06:18:33	LAVSHP	P	DON	257.05
29-Jun-2023 I	2,944	0	685210	24-065-007	Repair Hoses & Fittings	29-Jun-2023 14:45:32	ME1371	I	DON	18.51
29-Jun-2023 I	2,944	0	685210	95-MSC-004	Travel Travel Time - To/From Job Site	29-Jun-2023 14:32:50	ME1371	I	DON	22.40
30-Jun-2023 O	2,949	0	685386	03-065-007	Replace Hoses & Fittings	03-Jul-2023 09:06:37	LAVSHP	B	DON	475.16
15-Aug-2023 C		0	696841	03-514-005	Replace Pins	15-Aug-2023 07:08:28	LAVSHP	P	DON	228.00
29-Aug-2023 C		0	700638	06-100-PMC	Inspect C PMI		BBKHOE	P	WND	34.22
29-Aug-2023 C		0	700638	02-310	Clean Backhoe (Rubber Tire)	05-Oct-2023 06:35:33	BWASH	N	DON	475.32
29-Aug-2023 C		0	700638	OS-310	Out-Service Backhoe (Rubber Tire)		BBKHOE	P	WFA	7.66

Unit No: Q1190

Count: 99

34,942.33