

Unit Job History

Michels Corporation
Report Printed: 15-Aug-2023 09:52:27 By User: RHEENING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
--------------	---------	---------	------------	----------	-----------------	----------------	--------------	------------	------------	------------

Unit No: T0372 - 2003 FORD 5610

30-Jan-2012 00	1,540	0	93046	06-100-007	Inspect In-Service Inspection	30-Jan-2012 06:00:00	BVLOFC	P	DON	55.48
19-Jun-2012 00	1,452	0	104617	06-100-PMB	Inspect B PMI	19-Jun-2012 08:35:38	BVLOFC	P	DON	173.45
19-Jun-2012 00	1,452	0	104617	24-015	Repair Steering	19-Jun-2012 08:34:19	BVLOFC	F	DON	2,604.48
19-Jun-2012 00	1,452	0	104617	OS-MSC-004	Out-Service Travel Time - To/From Job Site	19-Jun-2012 08:36:57	BVLOFC	F	DON	336.28
17-Aug-2012 1	1,700	0	100313	06-100-PMA	Inspect A PMI	17-Aug-2012 15:35:47	BVLOFC	P	DON	178.33
17-Aug-2012 1	1,700	0	100313	OS-MSC-004	Out-Service Travel Time - To/From Job Site	17-Aug-2012 15:36:38	BVLOFC	F	DON	351.55
29-Oct-2012 00	1,776	0	103531	26-043-003	Weld Muffler	29-Oct-2012 13:43:07	BVLOFC	I	DON	55.48
21-May-2013 1	1,776	0	125907	24-040	Repair Engine / Motor Systems Group	31-May-2013 11:28:44	BVLOFC	F	DON	211.78
13-Nov-2013 0	1,776	0	139275	03-063-003	Replace Transceiver - GPS Tracker	13-Nov-2013 00:00:00	BRKH0E	C	DON	244.35
26-Aug-2014 0	1,957	0	176849	06-100-PMA	Inspect A PMI	26-Aug-2014 17:00:00	BVLOFC	P	DON	2,068.51
26-Aug-2014 0	1,957	0	176849	24-023	Repair Clutch	26-Aug-2014 17:00:00	BVLOFC	F	DON	3,431.04
03-Sep-2014 0	1,992	0	178313	03-032-002	Replace Starter	03-Sep-2014 17:00:00	BVLOFC	F	DON	465.97
03-Sep-2014 0	1,992	0	178313	03-065-027	Replace Relief Valve	05-Sep-2014 17:00:00	BVLOFC	F	DON	414.60
03-Sep-2014 0	1,992	0	178313	14-065-027	Install Relief Valve	17-Sep-2014 17:00:00	BVLOFC	F	DON	119.08
04-May-2015 1	1,992	0	203636	06-100-PMA	Inspect A PMI	04-May-2015 13:38:53	LAKEVL	P	DON	92.79
24-Mar-2016 0	2,008	0	238760	03-034-004	Replace Clearance & Marker Lamps	24-Mar-2016 13:46:43	LAVSHP	I	DON	103.77
24-Mar-2016 0	2,008	0	238760	03-034-014	Replace Auxiliary Work / Flood Light	24-Mar-2016 10:37:33	LAVSHP	I	DON	31.04
24-Mar-2016 0	2,008	0	238760	03-054-001	Replace Horn & Mounting	28-Mar-2016 14:27:53	LAVSHP	I	DON	77.63
24-Mar-2016 0	2,008	0	238760	24-034-006	Repair Warning Lamps - Special Application	24-Mar-2016 15:53:41	LAVSHP	I	DON	76.43
17-Aug-2017 0	2,069	0	301415	03-032-001	Replace Battery	18-Aug-2017 06:47:40	LAVSHP	I	DON	239.41
17-Aug-2017 0	2,069	0	301415	06-032-001	Inspect Battery	17-Aug-2017 10:03:35	LAVSHP	P	DON	19.62
17-Aug-2017 0	2,069	0	301415	06-063-003	Inspect Transceiver - GPS Tracker	18-Aug-2017 07:06:36	LAVSHP	I	DON	20.30
17-Aug-2017 0	2,069	0	301415	24-034	Repair Lighting System	17-Aug-2017 07:49:41	LAVSHP	I	DON	17.14
15-Oct-2018 0	0	0	356464	06-045	Inspect Power Plant	15-Oct-2018 08:08:44	LAVSHP	P	DON	28.81
08-Apr-2019 0	0	0	380123	03-034-002	Replace Stop, Tail, Turn & License	12-Apr-2019 08:57:29	LAVSHP	I	DON	12.08
08-Apr-2019 0	0	0	380123	03-054-002	Replace Alarm - Reverse Signal	12-Apr-2019 08:57:29	LAVSHP	I	DON	49.95
08-Apr-2019 0	0	0	380123	06-100-PMA	Inspect A PMI	08-Apr-2019 11:55:26	LAVSHP	P	DON	271.39
03-Apr-2020 0	0	0	434283	03-065-028	Replace Control Cable	03-Apr-2020 13:29:43	LAVSHP	B	DON	448.50
03-Apr-2020 0	0	0	434283	06-065-028	Inspect Control Cable	03-Apr-2020 09:29:17	LAVSHP	B	DON	12.30

Unit Job History

Michels Corporation
 Report Printed: 15-Aug-2023 09:52:27 By User: RHEINING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Job Status	Total Cost
Unit No: T0372 - 2003 FORD 5610											
02-Sep-2020 1		0	459668	06-100-PMB	Inspect B PMI	04-Sep-2020 15:22:06	LAVSHP	P	DON	DON	0.11
02-Sep-2020 1		0	459668	38-100-PMB	Service B PMI	04-Sep-2020 10:39:04	LAVSHP	P	DON	DON	169.12
02-Aug-2021 C		0	522131	03-032-001	Replace Battery	02-Aug-2021 13:57:25	LAVSHP	T	DON	DON	238.24
02-Aug-2021 C		0	522131	06-100-009	Inspect Safety Check		LAVSHP	P	CAN	CAN	0.00
02-Aug-2021 C		0	522131	06-100-PMA	Inspect A PMI	02-Aug-2021 10:47:08	LAVSHP	P	DON	DON	106.25
28-Apr-2022 0		0	585007	03-063-003	Replace Transceiver - GPS Tracker	28-Apr-2022 08:29:11	ELECO2	Q	DON	DON	327.62
12-Jan-2023 1		0	644642	03-063-003	Replace Transceiver - GPS Tracker	13-Jan-2023 14:23:45	ELECO4	Q	DON	DON	296.26
12-Jan-2023 1		0	644642	06-063-003	Inspect Transceiver - GPS Tracker	13-Jan-2023 13:42:37	ELECO4	Q	DON	DON	41.25
11-Aug-2023 1		0	696011	03-032-001	Replace Battery		BHVYEQ	P	WND	WND	201.75
11-Aug-2023 1		0	696011	06-100-PMA	Inspect A PMI	11-Aug-2023 17:00:01	BHVYEQ	P	DON	DON	68.96
11-Aug-2023 1		0	696011	38-100-PMA	Service A PMI		BBKH0E	P	WFA	WFA	114.10

Unit No: T0372

Count: 40

13,775.21