

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: U0350 - 2001 NEW HOLLAN 5610										
02-Apr-2010 1	0	37658	02-340	02-340	Clean Side Boom	05-Apr-2010 08:17:41	BWASH	J	DON	104.42
17-Feb-2014 0	0	147185	03-063-003	03-063-003	Replace Transceiver - GPS Tracker	17-Feb-2014 00:00:00	GPSINS	C	DON	245.35
21-Jul-2015 14	0	208479	03-002-027	03-002-027	Replace Seat Frames & Springs	10-Aug-2015 14:23:01	BBKHOE	I	DON	147.02
21-Jul-2015 14	0	208479	06-058-002	06-058-002	Inspect Cable	10-Aug-2015 15:55:42	BBKHOE	N	DON	200.61
21-Jul-2015 14	0	208479	06-315	06-315	Inspect Tractor - Farm / Implement	10-Aug-2015 13:09:01	BBKHOE	P	DON	63.23
21-Jul-2015 14	0	208479	34-065-005	34-065-005	Reseal Drive - Motor / Pump	05-Oct-2015 12:44:30	BBKHOE	I	DON	397.58
21-Jul-2015 14	0	208479	34-065-020	34-065-020	Reseal Control Valve	28-Oct-2015 10:13:12	BBKHOE	O	DON	387.65
21-Jul-2015 14	0	208479	38-100-PMA	38-100-PMA	Service A PMI	10-Aug-2015 13:09:31	BBKHOE	P	DON	350.57
06-Jun-2016 1	0	247145	03-065-008	03-065-008	Replace Line / Tubing Assembly	01-Nov-2016 08:12:25	BBKHOE	I	DON	137.15
06-Jun-2016 1	0	247145	06-340	06-340	Inspect Side Boom	01-Nov-2016 09:53:34	BBKHOE	P	DON	65.26
06-Jun-2016 1	0	247145	24-063-003	24-063-003	Repair Transceiver - GPS Tracker		BHVVYEQ	Q	WR	0.00
06-Jun-2016 1	0	247145	38-031	38-031	Service Charging System	31-Oct-2016 15:46:56	BBKHOE	Q	DON	89.13
06-Jun-2016 1	0	247145	38-044	38-044	Service Fuel System		BBKHOE	Q	WR	86.50
16-Aug-2018 1	0	348483	03-032-001	03-032-001	Replace Battery	26-Oct-2018 07:17:18	BBKHOE	I	DON	369.59
16-Aug-2018 1	0	348483	03-033-001	03-033-001	Replace Ignition Switch	26-Oct-2018 07:17:30	BBKHOE	I	DON	118.13
16-Aug-2018 1	0	348483	03-065-007	03-065-007	Replace Hoses & Fittings	26-Oct-2018 07:17:34	BBKHOE	I	DON	109.31
16-Aug-2018 1	0	348483	06-100-PMB	06-100-PMB	Inspect B PMI	26-Oct-2018 07:17:14	BBKHOE	P	DON	217.83
16-Aug-2018 1	0	348483	24-063-003	24-063-003	Repair Transceiver - GPS Tracker	24-Aug-2018 14:11:29	BHVVYEQ	Q	DON	41.19
16-Aug-2018 1	0	348483	34-065-013	34-065-013	Reseal Pump - Gear Type	26-Oct-2018 07:17:26	BBKHOE	I	DON	1,084.39
16-Aug-2018 1	0	348483	35-065-005	35-065-005	Diagnose Drive - Motor / Pump	26-Oct-2018 07:17:22	BBKHOE	I	DON	799.36
19-Jul-2019 11	0	395009	02-065-017	02-065-017	Clean Reservoir/Tank	22-Jul-2019 09:19:24	BBKHOE	P	DON	79.33
19-Jul-2019 11	0	395009	03-065-007	03-065-007	Replace Hoses & Fittings	23-Jul-2019 07:20:39	BBKHOE	I	DON	96.23
19-Jul-2019 11	0	395009	06-340-014	06-340-014	Inspect Winch Control Linkage	31-Jul-2019 14:28:07	BBKHOE	P	DON	198.62
19-Jul-2019 11	0	395009	14-032-009	14-032-009	Install Switch - Master Disconnect	31-Jul-2019 16:27:55	BBKHOE	P	DON	95.39
19-Jul-2019 11	0	395009	24-340-014	24-340-014	Repair Winch Control Linkage	31-Jul-2019 14:27:54	BBKHOE	I	DON	904.57
19-Jul-2019 11	0	395009	26-340-009	26-340-009	Weld Counter Weight Assembly	22-Jul-2019 16:08:44	BBKHOE	I	DON	41.70
22-Jul-2021 14	0	520256	03-063-003	03-063-003	Replace Transceiver - GPS Tracker	22-Jul-2021 14:41:39	SCHED	Q	DON	291.18
18-Aug-2022 C	0	610412	01-340-009	01-340-009	Adjust Counter Weight Assembly	19-Aug-2022 08:35:45	BBKHOE	I	DON	114.19
18-Aug-2022 C	0	610412	03-018-003	03-018-003	Replace Wheels		BBKHOE	I	CAN	0.00

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: U0350 - 2001 NEW HOLLAN 5610										
18-Aug-2022 C	0	610412	03-032-001	03-032-001	Replace Battery	18-Aug-2022 17:00:01	BBKHOE	I	DON	331.77
18-Aug-2022 C	0	610412	03-032-009	03-032-009	Replace Switch - Master Disconnect	18-Aug-2022 15:30:52	BBKHOE	I	DON	286.18
18-Aug-2022 C	0	610412	06-315	06-315	Inspect Tractor - Farm / Implement	29-Aug-2022 08:47:58	BBKHOE	P	DON	79.64
26-Aug-2022 I	0	612863	03-018-003	03-018-003	Replace Wheels	02-Sep-2022 06:44:34	BTIRE	P	DON	740.63
29-Sep-2022 O	0	620833	03-018-003	03-018-003	Replace Wheels	29-Dec-2022 09:18:57	BTIRE	P	DON	1,067.26
10-Aug-2023 I	0	695824	03-032-001	03-032-001	Replace Battery	21-Aug-2023 14:29:49	BHVYEQ	I	DON	251.07
10-Aug-2023 I	0	695824	06-100-PMA	06-100-PMA	Inspect A PMI	11-Aug-2023 12:00:03	BHVYEQ	P	DON	148.65
10-Aug-2023 I	0	695824	38-100-PMA	38-100-PMA	Service A PMI	21-Aug-2023 14:29:48	BBKHOE	P	DON	84.55
20-Sep-2023 O	0	706550	25-340-001	25-340-001	Remove Boom Assembly	20-Sep-2023 13:15:43	BHVYEQ	Z	DON	217.57
27-Oct-2023 O	0	716196	25-266-004	25-266-004	Remove Counterweight	27-Oct-2023 12:00:02	BBKHOE	Z	DON	114.13

Unit No: U0350

Count: 39

10,156.95