

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost		
Unit No: B2377 - 2013 F250 EXT CAB												
03-Oct-2013	1	220	0	132743	06-100-DOT	Inspect DOT Federal Inspection	08-Oct-2013	07:34:48	BTRUCK	P	DON	37.31
03-Oct-2013	1	220	0	132743	12-519-002	Refinish Rear Bumper	05-Oct-2013	10:03:12	BBODY	C	DON	64.48
03-Oct-2013	1	220	0	132743	14-002-003	Install Running Boards / Step Tubes	07-Oct-2013	12:00:02	BBODY	C	DON	227.66
03-Oct-2013	1	220	0	132743	14-002-023	Install Handles - Inner & Outer	08-Oct-2013	06:27:16	BBODY	C	CAN	0.00
03-Oct-2013	1	220	0	132743	14-016-005	Install Chassis Spring - Rear	07-Oct-2013	12:00:41	BTRUCK	C	DON	552.93
03-Oct-2013	1	220	0	132743	14-034-006	Install Warning Lamps - Special Application	07-Oct-2013	08:38:13	BBODY	C	DON	223.80
03-Oct-2013	1	220	0	132743	14-052-003	Install Radio Equipment	07-Oct-2013	06:55:37	BBODY	C	DON	1,118.33
03-Oct-2013	1	220	0	132743	14-052-011	Install Auxiliary Power	07-Oct-2013	09:49:43	BBODY	C	DON	130.14
03-Oct-2013	1	220	0	132743	14-052-014	Install Cellular Telephone Accessories	07-Oct-2013	10:51:15	BBODY	C	DON	310.23
03-Oct-2013	1	220	0	132743	14-052-015	Install Power Inverter/Converter	07-Oct-2013	14:53:47	BBODY	C	DON	88.07
03-Oct-2013	1	220	0	132743	14-053-005	Install Markings - Vehicle - Decals	04-Oct-2013	10:52:37	BBODY	J	DON	17.58
03-Oct-2013	1	220	0	132743	14-053-014	Install Floor Mats	07-Oct-2013	07:05:11	BBODY	C	DON	87.94
03-Oct-2013	1	220	0	132743	14-063-003	Install Transceiver - GPS Tracker	07-Oct-2013	12:17:41	BBODY	C	DON	243.62
03-Oct-2013	1	220	0	132743	14-078-009	Install Mud Flaps and Hanger Brackets	07-Oct-2013	14:04:42	BBODY	C	DON	33.00
03-Oct-2013	1	220	0	132743	14-078-012	Install Tie-Down - Tarpaulin	07-Oct-2013	08:08:56	BBODY	C	DON	433.13
03-Oct-2013	1	220	0	132743	14-079-002	Install Headache Rack	07-Oct-2013	09:26:22	BBODY	C	DON	324.51
03-Oct-2013	1	220	0	132743	14-506-001	Install Fuel Tank	07-Oct-2013	11:00:01	BBODY	C	DON	1,058.71
03-Oct-2013	1	220	0	132743	14-517	Install Safety Equipment	07-Oct-2013	11:00:13	BSAND	J	DON	81.16
03-Oct-2013	1	220	0	132743	15-079-002	Paint Prep Headache Rack	09-Oct-2013	11:31:37	MPNSHP	C	DON	230.08
09-Oct-2013	0	220	0	133262	06-100-009	Inspect Safety Check	03-Dec-2013	07:30:11	MPNSHP	P	DON	73.86
03-Dec-2013	0	3,051	0	139913	06-100-PMA	Inspect A PMI	01-Apr-2014	09:42:12	MPNSHP	P	DON	52.62
01-Apr-2014	0	6,117	0	153749	06-100-PMA	Inspect A PMI	24-Jul-2014	11:09:40	MPNSHP	P	DON	53.54
24-Jul-2014	11	9,461	0	167849	06-100-PMA	Inspect A PMI	16-Sep-2014	12:57:24	MPNSHP	P	DON	53.54
16-Sep-2014	1	13,040	0	175248	06-100-PMA	Inspect A PMI	27-Oct-2014	00:00:00	MPNSHP	P	DON	76.81
27-Oct-2014	0	16,139	0	178669	03-041-006	Replace Filter - Inner	27-Oct-2014	00:00:00	MPNFLD	P	DON	21.99
27-Oct-2014	0	16,139	0	178669	06-100-PMA	Inspect A PMI	21-Nov-2014	10:40:04	MPNFLD	P	DON	50.98
21-Nov-2014	0	18,309	0	181913	06-100-DOT	Inspect DOT Federal Inspection	17-Dec-2014	11:25:25	MPNSHP	P	DON	61.93
21-Nov-2014	0	18,309	0	181913	14-053	Install Expendable Items	24-Nov-2014	05:53:03	MPNSHP	I	DON	2.31
21-Nov-2014	0	18,309	0	181913	35-034-006	Diagnose Warning Lamps - Special Application			MPNSHP	I	DON	163.15

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2377 - 2013 F250 EXT CAB										
16-Dec-2014 0	19,401	0	185681	06-100-PMA	Inspect A PMI	16-Dec-2014 00:00:00	BTRUCK	P	DON	54.28
16-Dec-2014 0	19,401	0	185681	31-017	Rotate Tires, Tubes, Liners & Valves	16-Dec-2014 00:00:00	MPNFLD	J	DON	22.16
11-Feb-2015 0	22,753	0	191800	06-100-PMA	Inspect A PMI	11-Feb-2015 00:00:00	MPNSHP	P	DON	53.28
01-Apr-2015 0	25,815	0	197261	06-100-PMA	Inspect A PMI	01-Apr-2015 00:00:00	MPNSHP	P	DON	46.64
01-Apr-2015 0	25,815	0	197261	31-017	Rotate Tires, Tubes, Liners & Valves	01-Apr-2015 00:00:00	MPNSHP	J	DON	22.16
23-Jun-2015 0	30,348	0	206492	03-001-016	Replace Filter - Cab Ventilation	23-Jun-2015 00:00:00	MPNSHP	P	DON	18.84
23-Jun-2015 0	30,348	0	206492	06-100-PMA	Inspect A PMI	23-Jun-2015 00:00:00	MPNSHP	P	DON	40.90
23-Jun-2015 0	30,348	0	206492	38-021-103	Service Differential Carrier	23-Jun-2015 00:00:00	MPNSHP	P	DON	33.25
23-Jun-2015 0	30,348	0	206492	38-025-001	Service Transfer Case Assembly	23-Jun-2015 00:00:00	MPNSHP	P	DON	66.50
11-Aug-2015 0	33,960	0	211788	06-100-PMA	Inspect A PMI	11-Aug-2015 00:00:00	MPNFLD	P	DON	30.11
07-Oct-2015 1		0	226697	06-100-PMA	Inspect A PMI	07-Oct-2015 11:51:46	BVLOFC	P	DON	47.41
03-Dec-2015 0	40,719	0	234634	06-100-PMA	Inspect A PMI	03-Dec-2015 06:05:16	BVLOFC	P	DON	51.33
08-Dec-2015 1	41,011	0	224569	02-002-044	Clean Cab - Complete	09-Dec-2015 06:23:30	MPNSHP	I	DON	2.21
08-Dec-2015 1	41,011	0	224569	06-100-DOT	Inspect DOT Federal Inspection	09-Dec-2015 06:23:38	MPNSHP	P	DON	101.69
29-Jan-2016 1	44,008	0	237287	03-002-035	Replace Windshield Wiper & Washer	29-Jan-2016 10:09:02	BVLOFC	O	DON	25.99
29-Jan-2016 1	44,008	0	237287	06-100-PMA	Inspect A PMI	29-Jan-2016 10:04:10	BVLOFC	P	DON	54.29
29-Jan-2016 1		0	231506	03-017-001	Replace Tire - Pneumatic	01-Feb-2016 00:00:00	MPNSHP	P	DON	912.79
18-Mar-2016 0	47,143	0	248183	06-100-PMA	Inspect A PMI	18-Mar-2016 07:41:44	BVLOFC	P	DON	53.42
19-May-2016 1	51,654	0	251079	06-100-PMA	Inspect A PMI	19-May-2016 13:32:08	BVLOFC	P	DON	38.62
30-Jun-2016 0	54,703	0	253521	06-100-PMA	Inspect A PMI	30-Jun-2016 07:00:00	BVLOFC	P	DON	53.42
20-Sep-2016 1	60,447	0	260170	06-100-PMA	Inspect A PMI	20-Sep-2016 13:39:04	MPNSHP	P	DON	54.64
28-Dec-2016 1	66,594	0	271019	03-013-001	Replace Front Brakes & Drums	29-Dec-2016 05:43:48	BVLOFC	I	DON	478.44
28-Dec-2016 1	66,594	0	271019	06-100-PMA	Inspect A PMI	29-Dec-2016 05:43:43	BTRUCK	P	DON	51.79
28-Dec-2016 1	66,594	0	271019	31-017-001	Rotate Tire - Pneumatic	29-Dec-2016 05:40:49	BVLOFC	P	DON	18.98
06-Feb-2017 0	69,215	0	276172	06-100-DOT	Inspect DOT Federal Inspection	06-Feb-2017 09:01:20	MPNSHP	P	DON	33.78
08-Mar-2017 1	71,048	0	280229	06-100-PMA	Inspect A PMI	15-Mar-2017 11:29:05	MPNSHP	P	DON	53.76
11-May-2017 1	75,807	0	288622	06-100-PMA	Inspect A PMI	11-May-2017 14:07:44	BVLOFC	P	DON	113.85
14-Jun-2017 1	80,536	0	304825	03-041-007	Replace Filter - Outer	14-Jun-2017 13:03:00	BVLOFC	P	DON	27.66
14-Jun-2017 1	80,536	0	304825	06-100-PMA	Inspect A PMI	14-Jun-2017 13:03:00	BVLOFC	P	DON	55.14

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2377 - 2013 F250 EXT CAB										
05-Dec-2017	0	87,666	315472	06-100-PMA	Inspect A PMI	05-Dec-2017 07:51:00	BVLOFC	P	DON	56.77
20-Mar-2018	0	87,666	327907	03-013-002	Replace Rear Brakes & Drums	25-Apr-2018 13:41:19	MPNSHP	O	DON	323.49
20-Mar-2018	0	87,666	327907	03-032-001	Replace Battery	23-Mar-2018 07:47:14	MPNSHP	I	DON	2.08
20-Mar-2018	0	87,666	327907	06-100-DOT	Inspect DOT Federal Inspection	20-Mar-2018 11:18:29	MPNSHP	P	DON	28.09
20-Mar-2018	0	87,666	327907	06-100-PMA	Inspect A PMI	23-Mar-2018 07:42:47	MPNSHP	P	DON	53.62
25-Apr-2018	0	87,666	332958	03-017-001	Replace Tire - Pneumatic		MPNSHP	P	CAN	0.00
25-Apr-2018	0	87,666	332958	35-040	Diagnose Engine / Motor Systems Group	26-Apr-2018 06:15:08	MPNSHP	O	DON	53.35
28-Jul-2018	0	102,687	347258	06-100-PMA	Inspect A PMI	28-Jul-2018 07:45:00	MPNFLD	P	DON	65.62
27-Mar-2019	0	112,976	378480	03-015-005	Replace Power Steering Pump	06-Jun-2019 15:05:55	MPNSHP	O	DON	264.55
09-Sep-2019	1	124,028	402080	06-100-PMA	Inspect A PMI	09-Sep-2019 12:17:40	BTRUCK	P	DON	0.00
09-Sep-2019	1	124,028	402080	38-100-PMA	Service A PMI	09-Sep-2019 12:17:40	BVLOFC	P	DON	61.72
14-Nov-2019	0	129,716	412638	06-100-PMB	Inspect B PMI		BTRUCK	P	CAN	0.00
14-Nov-2019	0	129,716	412638	38-045	Service Power Plant		BTRUCK	P	CAN	0.00
22-Jan-2020	0	134,311	422253	03-013-001	Replace Front Brakes & Drums	22-Jan-2020 15:17:09	MPNSHP	I	DON	415.90
22-Jan-2020	0	134,311	422253	03-016-003	Replace Shock Absorber - Front	03-Feb-2020 10:42:56	MPNSHP	I	DON	78.83
22-Jan-2020	0	134,311	422253	06-100-009	Inspect Safety Check	22-Jan-2020 08:08:30	MPNSHP	I	DON	31.08
22-Jan-2020	0	134,311	422253	06-100-DOT	Inspect DOT Federal Inspection	22-Jan-2020 16:12:19	MPNSHP	P	DON	27.99
22-Jan-2020	0	134,311	422253	38-100-PMA	Service A PMI	22-Jan-2020 15:20:47	MPNSHP	P	DON	171.83
02-Jun-2020	1	145,949	451738	38-100-PMA	Service A PMI	02-Jun-2020 12:53:00	BVLOFC	P	DON	46.24
29-Sep-2020	1	150,686	467923	38-100-PMA	Service A PMI	29-Sep-2020 10:37:00	BVLOFC	P	DON	47.97
05-Oct-2020	0	150,686	464730	03-002-061	Replace Seat Cushion	07-Oct-2020 13:24:19	MPNSHP	I	DON	256.85
05-Oct-2020	0	150,686	464730	03-017-001	Replace Tire - Pneumatic	20-Oct-2020 11:26:37	MPNSHP	I	DON	975.25
05-Oct-2020	0	150,686	464730	03-034	Replace Lighting System	07-Oct-2020 08:42:49	MPNSHP	I	DON	161.66
05-Oct-2020	0	150,686	464730	03-044-002	Replace Filters	07-Oct-2020 08:43:19	MPNSHP	I	DON	30.72
05-Oct-2020	0	150,686	464730	03-051-009	Replace Fire Extinguisher	07-Oct-2020 08:43:47	MPNSHP	I	DON	17.81
05-Oct-2020	0	150,686	464730	03-052-003	Replace Radio Equipment	08-Oct-2020 06:31:52	MPNSHP	I	DON	147.06
05-Oct-2020	0	150,686	464730	03-053-007	Replace Hardware - Expendable Items	08-Oct-2020 06:31:56	MPNSHP	I	DON	61.87
05-Oct-2020	0	150,686	464730	03-054-002	Replace Alarm - Reverse Signal	08-Oct-2020 06:32:01	MPNSHP	I	DON	43.24
05-Oct-2020	0	150,686	464730	06-100-009	Inspect Safety Check	07-Oct-2020 08:43:38	MPNSHP	P	DON	154.52

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2377 - 2013 F250 EXT CAB										
05-Oct-2020 01	150,686	464730		06-100-DOT	Inspect DOT Federal Inspection	07-Oct-2020 12:00:46	MPNSHP	P	DON	106.34
28-Jan-2021 11	157,206	485138		03-033-003	Replace Spark Plugs	28-Jan-2021 11:19:26	BVLOFC	O	DON	487.50
28-Jan-2021 11	157,206	485138		03-016-006	Replace Shock Absorber - Rear	28-Jan-2021 11:19:26	BVLOFC	I	DON	345.75
28-Jan-2021 11	157,206	485138		38-020	Service Drivetrain Group	28-Jan-2021 11:19:26	BVLOFC	P	DON	427.80
28-Jan-2021 11	157,206	485138		38-042	Service Cooling System	28-Jan-2021 11:19:26	BVLOFC	P	DON	195.84
28-Jan-2021 11	157,206	485138		38-100-PMA	Service A PMI	28-Jan-2021 11:19:26	BVLOFC	P	DON	62.58
28-Jan-2021 11	157,206	485138		06-100-PMA	Inspect A PMI	28-Jan-2021 11:19:26	BTRUCK	P	DON	0.00
28-Jan-2021 11	157,206	485138		03-041-007	Replace Filter - Outer	28-Jan-2021 11:19:26	BVLOFC	P	DON	34.99
29-Apr-2021 0	157,206	503619		38-100-PMB	Service B PMI	26-May-2021 11:40:31	BVLOFC	P	DON	89.50
29-Apr-2021 0	157,206	503619		03-013-001	Replace Front Brakes & Drums	26-May-2021 11:40:31	BVLOFC	I	DON	1,410.44
29-Apr-2021 0	157,206	503619		06-100-PMB	Inspect B PMI	26-May-2021 11:40:31	SCHED	P	DON	0.00
29-Apr-2021 0	157,206	503619		38-013-007	Service Brake Lines & Fittings - Hydraulic & A	26-May-2021 11:40:31	BVLOFC	I	DON	169.84
29-Apr-2021 0	157,206	503619		03-013-002	Replace Rear Brakes & Drums	26-May-2021 11:40:31	BVLOFC	I	DON	917.02
01-Jun-2021 01	157,206	509907		03-032-001	Replace Battery	08-Jun-2021 08:18:20	BVLOFC	B	DON	261.56
01-Jun-2021 01	157,206	509907		20-010-001	Tow All Axles	08-Jun-2021 08:18:20	BVLOFC	B	DON	207.43
10-Jun-2021 11	157,206	512032		03-013-001	Replace Front Brakes & Drums	10-Jun-2021 14:45:26	MPNOFC	N	DON	2,775.85
22-Jul-2021 13	171,995	530954		06-100-PMA	Inspect A PMI	22-Jul-2021 13:48:00	SCHED	P	DON	0.00
22-Jul-2021 13	171,995	530954		38-100-PMA	Service A PMI	22-Jul-2021 13:48:00	SCHED	P	DON	157.27
01-Oct-2021 01	171,995	535938		06-100-DOT	Inspect DOT Federal Inspection	01-Oct-2021 12:30:07	SCHED	P	WR	87.46
01-Oct-2021 01	171,995	535938		06-100-PMB	Inspect B PMI	01-Oct-2021 12:30:07	SCHED	P	DON	0.00
01-Oct-2021 01	171,995	535938		38-100-PMA	Service A PMI	03-Oct-2021 15:51:28	SCHED	P	DON	180.10
01-Oct-2021 11	171,995	535956		03-016-024	Replace Leaf Spring	12-Oct-2021 07:45:11	BVLOFC	I	DON	3,612.61
01-Oct-2021 11	171,995	535956		03-043-002	Replace Exhaust Manifold	12-Oct-2021 07:45:11	BVLOFC	I	DON	2,285.38
11-Oct-2021 01	171,995	539736		06-100-DOT	Inspect DOT Federal Inspection	17-Oct-2021 12:53:39	SCHED	P	DON	262.38
11-Oct-2021 01	171,995	539736		03-013-028	Replace Shoe - Parking Brake	17-Oct-2021 12:45:23	TRK023	B	DON	639.78
11-Oct-2021 01	171,995	539736		38-100-DOT	Service DOT Federal Inspection	17-Oct-2021 12:44:32	TRK023	B	DON	0.00
15-Nov-2021 11	171,995	547268		01-034-004	Adjust Clearance & Marker Lamps	16-Nov-2021 17:29:24	MB2290	I	DON	156.84
10-Dec-2021 0	171,995	552571		03-042-006	Replace Thermostat	17-Dec-2021 15:00:17	BVLOFC	I	DON	278.99
10-Dec-2021 0	171,995	552571		03-033-002	Replace Distributor / Coil Pack	17-Dec-2021 15:00:17	BVLOFC	I	DON	331.38

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2377 - 2013 F250 EXT CAB										
10-Dec-2021 0	171,995		552571	03-042	Replace Cooling System	17-Dec-2021 15:00:17	BVLOFC	I	DON	159.55
05-Jan-2022 11	171,995		557231	06-100-PMA	Inspect A PMI	05-Jan-2022 11:33:56	BVLOFC	P	DON	0.00
05-Jan-2022 11	171,995		557231	38-100-PMA	Service A PMI	05-Jan-2022 11:33:56	BVLOFC	P	DON	182.17
21-Mar-2022 1			586999	38-100-PMA	Service A PMI	21-Mar-2022 14:23:00	BVLOFC	P	DON	94.65
04-May-2022 1	171,995		586392	03-063-003	Replace Transceiver - GPS Tracker	04-May-2022 12:04:08	ELEC02	Q	DON	312.61
01-Jun-2022 01	192,091		593494	03-034-001	Replace Headlamps / Fog Lamps	04-Jun-2022 19:59:53	ME1798	B	DON	104.56
01-Jun-2022 01	192,091		593494	06-100-PMA	Inspect A PMI	06-Jun-2022 20:46:54	ME1798	P	DON	209.12
01-Jun-2022 01	192,091		593494	38-100-PMA	Service A PMI	06-Jun-2022 20:48:07	ME1798	P	DON	5.63
26-Jul-2022 14	195,769		605908	06-100-PMA	Inspect A PMI	02-Aug-2022 22:06:14	SCHED	P	DON	0.00
26-Jul-2022 14	195,769		605908	38-100-PMA	Service A PMI	29-Jul-2022 09:32:51	MB2290	P	DON	319.43
17-Oct-2022 01	202,490		625516	06-100-DOT	Inspect DOT Federal Inspection	19-Oct-2022 15:12:06	TRK023	P	DON	235.26
17-Oct-2022 01	202,490		625516	06-100-PMA	Inspect A PMI	19-Oct-2022 15:12:10	TRK023	P	DON	0.00
17-Oct-2022 01	202,490		625516	06-100-PMA	Service A PMI	19-Oct-2022 15:12:13	TRK023	P	DON	210.67
11-May-2023 01	206,372		673997	06-100-PMA	Inspect A PMI		MB2290	P	CAN	0.00
11-May-2023 01	206,372		673997	06-100-PMB	Inspect B PMI	12-May-2023 09:40:07	MB2290	P	DON	0.00
11-May-2023 01	206,372		673997	38-100-PMA	Service A PMI	12-May-2023 09:40:13	MB2290	P	DON	179.53
11-May-2023 01	206,372		673997	01-001-001	Adjust Air Conditioning Assembly	12-May-2023 09:40:43	MB2290	I	DON	174.92
19-May-2023 01	206,372		675692	03-001-010	Replace Compressor Assembly - Air Cond	22-May-2023 00:00:00	BVLOFC	O	DON	1,599.11
19-May-2023 01	206,372		675692	03-018-001	Replace Front Axle Hubs & Bearings	22-May-2023 00:00:00	BVLOFC	I	DON	999.81
17-Aug-2023 01	216,665		698126	06-100-PMA	Inspect A PMI	17-Aug-2023 00:00:00	BVLOFC	P	DON	77.26
17-Aug-2023 01	216,665		698126	31-017-001	Rotate Tire - Pneumatic	17-Aug-2023 00:00:00	BVLOFC	P	DON	24.95
17-Aug-2023 01	216,665		698126	38-100-PMA	Service A PMI	17-Aug-2023 00:00:00	BVLOFC	P	DON	0.00
25-Sep-2023 01	220,677		709437	06-100-DOT	Inspect DOT Federal Inspection	01-Oct-2023 22:11:28	TRK030	P	DON	174.92
25-Sep-2023 01	220,677		709437	06-100-PMA	Inspect A PMI	01-Oct-2023 22:11:39	TRK030	P	DON	0.00
25-Sep-2023 01	220,677		709437	38-100-PMA	Service A PMI	01-Oct-2023 22:11:50	TRK030	P	DON	305.26
03-Jan-2024 01	227,342		729927	03-031-001	Replace Generator/Alternator	03-Jan-2024 08:10:00	BVLOFC	B	DON	1,061.22
24-Jan-2024 11			734438	06-100-009	Inspect Safety Check	25-Jan-2024 08:32:27	BTRUCK	N	DON	142.58
07-Feb-2024 11			737465	25-050	Remove Accessories Group	08-Feb-2024 11:46:14	BSETUP	Z	DON	396.62
07-Feb-2024 11			737465	02-002	Clean Cab & Sheet Metal	13-Feb-2024 10:06:50	BSETUP	Z	DON	346.09

Unit Job History

Michels Corporation
Report Printed: 15-Feb-2024 11:45:55 By User: RHENNING

Unit No: B2377

Count: 145

34,869.42