

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: F0942 - 2010 E350 REG CAB										
09-Apr-2015 0	95,700	0	197360	03-002-026	Replace Weather Stripping, Gaskets & Bumpers	07-May-2015 14:49:31	BTRUCK	I	DON	188.88
09-Apr-2015 0	95,700	0	197360	03-002-035	Replace Windshield Wiper & Washer	26-May-2015 15:00:53	BTRUCK	I	DON	8.21
09-Apr-2015 0	95,700	0	197360	03-013-001	Replace Front Brakes & Drums	07-May-2015 14:37:53	BTRUCK	I	DON	387.57
09-Apr-2015 0	95,700	0	197360	03-015-003	Replace Steering Gear	06-May-2015 09:33:27	BTRUCK	I	DON	948.58
09-Apr-2015 0	95,700	0	197360	03-015-010	Replace Cylinder - Steering Hydraulic	07-May-2015 13:21:11	BTRUCK	I	DON	29.34
09-Apr-2015 0	95,700	0	197360	03-018-011	Replace Seal - Wheel	07-May-2015 11:11:04	BTRUCK	I	DON	111.51
09-Apr-2015 0	95,700	0	197360	03-027-033	Replace Range Selector Or Manual Linkage	06-May-2015 15:00:05	BTRUCK	I	DON	226.38
09-Apr-2015 0	95,700	0	197360	03-027-043	Replace Seal - Output	06-May-2015 12:00:26	BTRUCK	I	DON	110.31
09-Apr-2015 0	95,700	0	197360	03-043-002	Replace Exhaust Manifold	05-May-2015 17:00:10	BTRUCK	I	DON	590.72
09-Apr-2015 0	95,700	0	197360	03-051-006	Replace Safety Devices	26-May-2015 15:00:50	BTRUCK	I	DON	7.76
09-Apr-2015 0	95,700	0	197360	03-051-009	Replace Fire Extinguisher	07-May-2015 15:22:26	BTRUCK	I	DON	49.06
09-Apr-2015 0	95,700	0	197360	03-054-002	Replace Alarm - Reverse Signal	07-May-2015 09:47:39	BTRUCK	I	DON	56.20
09-Apr-2015 0	95,700	0	197360	06-100-DOT	Inspect DOT Federal Inspection	19-May-2015 10:24:46	BTRUCK	P	DON	24.45
09-Apr-2015 0	95,700	0	197360	06-100-PMB	Inspect B PMI	04-May-2015 17:00:57	BTRUCK	P	DON	159.84
09-Apr-2015 0	95,700	0	197360	12-513-004	Refinish Specialty Attachment	28-Apr-2015 07:56:07	BBODY	C	DON	300.25
09-Apr-2015 0	95,700	0	197360	12-519-003	Refinish Hitch Assembly		BBODY	C	CAN	0.00
09-Apr-2015 0	95,700	0	197360	14-031-005	Install Battery Charger - Electrically Propelled \		BTRUCK	C	CAN	0.00
09-Apr-2015 0	95,700	0	197360	14-034-006	Install Warning Lamps - Special Application	11-May-2015 16:30:20	BTRUCK	C	DON	349.51
09-Apr-2015 0	95,700	0	197360	14-052-015	Install Power Inverter/Converter	08-May-2015 12:00:07	BTRUCK	C	DON	947.76
09-Apr-2015 0	95,700	0	197360	14-055-022	Install Shelving and Supports	11-May-2015 17:00:15	BTRUCK	C	DON	2,565.41
09-Apr-2015 0	95,700	0	197360	14-063-003	Install Transceiver - GPS Tracker	05-May-2015 13:42:50	BTRUCK	C	DON	267.88
09-Apr-2015 0	95,700	0	197360	15-513-004	Paint Prep Specialty Attachment	28-Apr-2015 07:56:21	BSAND	C	DON	320.29
09-Apr-2015 0	95,700	0	197360	15-519-003	Paint Prep Hitch Assembly	28-Apr-2015 07:56:27	BSAND	C	DON	140.32
09-Apr-2015 0	95,700	0	197360	21-513-004	Fabricate Specialty Attachment	01-May-2015 16:47:32	BWELD	C	DON	1,215.28
09-Apr-2015 0	95,700	0	197360	24-002-018	Repair Cab Or Front Door Mechanism	07-May-2015 07:45:59	BTRUCK	I	DON	62.20
09-Apr-2015 0	95,700	0	197360	25-002-061	Remove Seat Cushion	07-May-2015 15:50:23	BTRUCK	I	DON	189.28
09-Apr-2015 0	95,700	0	197360	25-059-006	Remove Towing Hitch Assembly	05-May-2015 12:00:14	BTRUCK	I	DON	83.02
09-Apr-2015 0	95,700	0	197360	34-002-006	Reseal Roof Panel & Reinforcements	11-May-2015 06:54:41	BBODY	I	DON	145.29
09-Apr-2015 0	95,700	0	197360	38-045	Service Power Plant	07-May-2015 12:00:09	BTRUCK	P	DON	179.00

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: F0942 - 2010 E350 REG CAB										
14-Mar-2016	1	116,089	0	237307	03-013-002	Replace Rear Brakes & Drums	LAVSHP	I	DON	413.75
14-Mar-2016	1	116,089	0	237307	06-100-PMA	Inspect A PMI	LAVSHP	P	DON	101.02
25-Apr-2016	0	118,262	0	245888	06-100-DOT	Inspect DOT Federal Inspection	LAVSHP	P	DON	22.36
25-Apr-2016	0	118,262	0	245888	03-001-018	Replace Fan - Condensor	LAVSHP	P	DON	22.36
26-Apr-2016	1	118,784	0	242469	03-017-001	Replace Tire - Pneumatic	BTIRE	N	DON	507.02
26-Apr-2016	1	118,784	0	242469	09-015	Align Steering	BVLOFC	I	DON	76.92
26-Apr-2016	1	118,784	0	242469	14-016	Install Suspension	BVLOFC	I	DON	190.03
28-Apr-2016	0	118,784	0	252678	09-016	Align Suspension	BVLOFC	O	DON	271.18
03-Apr-2017	1	137,999	0	283646	03-013-001	Replace Front Brakes & Drums	ROGSHP	I	DON	137.04
03-Apr-2017	1	137,999	0	283646	03-013-037	Replace Caliper - Front	ROGSHP	I	DON	199.22
03-Apr-2017	1	137,999	0	283646	03-017-001	Replace Tire - Pneumatic	ROGSHP	I	DON	824.85
03-Apr-2017	1	137,999	0	283646	06-100-DOT	Inspect DOT Federal Inspection	ROGSHP	P	DON	50.16
08-Jan-2018	0	146,292	0	318531	03-032-001	Replace Battery	ROGSHP	N	DON	127.17
08-Jan-2018	0	146,292	0	318531	03-053-005	Replace Markings - Vehicle - Decals	ROGSHP	Q	DON	13.09
08-Jan-2018	0	146,292	0	318531	06-100-DOT	Inspect DOT Federal Inspection	ROGSHP	P	DON	30.26
08-Jan-2018	0	146,292	0	318531	14-002-010	Install Mirrors	ROGSHP	Q	DON	39.65
08-Jan-2018	0	146,292	0	318531	14-465-003	Install Camera Assembly	ROGSHP	Q	DON	146.83
30-May-2018	1	150,474	0	337665	07-100-PMA	Lubricate A PMI	ROGSHP	P	DON	23.49
06-Jun-2018	0	151,151	0	338586	03-013-002	Replace Rear Brakes & Drums	ROGSHP	N	DON	443.51
06-Jun-2018	0	151,151	0	338586	03-013-028	Replace Shoe - Parking Brake	ROGSHP	N	DON	243.94
06-Jun-2018	0	151,151	0	338586	03-018-011	Replace Seal - Wheel	ROGSHP	N	DON	39.50
06-Jun-2018	0	151,151	0	338586	06-013	Inspect Brakes	ROGSHP	O	DON	28.82
06-Jun-2018	0	151,151	0	338586	26-518-001	Weld Steps	ROGSHP	Q	DON	93.08
24-Jul-2018	13	156,427	0	345179	07-100-PMA	Lubricate A PMI	ROGSHP	P	DON	14.75
20-Aug-2018	1	159,369	0	348942	03-017-001	Replace Tire - Pneumatic	ROGSHP	N	DON	486.74
20-Aug-2018	1	159,369	0	348942	06-015-004	Inspect Steering Linkage	ROGSHP	O	DON	13.60
20-Aug-2018	1	159,369	0	348942	07-100-PMA	Lubricate A PMI	ROGSHP	P	DON	5.27
20-Aug-2018	1	159,369	0	348942	09-016-050	Align Alignment.All Wheel	ROGSHP	N	DON	246.14
12-Dec-2018	1	164,404	0	364139	06-100-DOT	Inspect DOT Federal Inspection	ROGSHP	P	DON	30.24

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: F0942 - 2010 E350 REG CAB										
12-Dec-2018	164,404	0	364139	03-002-024	Replace Glass / Windshield	02-Jan-2019 08:59:41	ROGSHP	A	DON	381.23
12-Dec-2018	164,404	0	364139	03-002-060	Replace Seat Belt	18-Dec-2018 08:31:25	ROGSHP	I	DON	468.52
12-Dec-2018	164,404	0	364139	B3-002-060	Program Seat Belt	02-Jan-2019 08:51:57	ROGSHP	Q	DON	110.03
08-May-2019	164,738	0	384820	06-032-001	Inspect Battery	08-May-2019 07:56:28	LAVSHP	Q	DON	19.26
12-Jul-2019	166,513		393943	03-034-004	Replace Clearance & Marker Lamps	12-Jul-2019 10:10:08	ROGSHP	I	DON	14.51
12-Jul-2019	166,513		393943	06-000	Inspect Cab, Climate Cntrl, Instrument	12-Jul-2019 10:43:34	ROGSHP	O	DON	18.65
12-Jul-2019	166,513		393943	06-100-PMA	Inspect A PMI	15-Jul-2019 06:54:09	ROGSHP	P	DON	0.00
12-Jul-2019	166,513		393943	38-100-PMA	Service A PMI	12-Jul-2019 09:35:09	ROGSHP	P	DON	44.15
12-Jul-2019	166,513		393943	24-000	Repair Cab, Climate Cntrl, Instrument	12-Jul-2019 10:00:50	ROGSHP	O	DON	62.01
01-Aug-2019	166,807		396820	24-034-001	Repair Headlamps / Fog Lamps	01-Aug-2019 07:42:05	ROGSHP	N	DON	27.45
18-Sep-2019	167,353		403499	03-013-001	Replace Front Brakes & Drums	18-Sep-2019 16:08:11	ROGSHP	N	DON	710.31
18-Sep-2019	167,353		403499	06-040	Inspect Engine / Motor Systems Group	18-Sep-2019 13:55:52	ROGSHP	O	DON	9.85
18-Sep-2019	167,353		403499	24-034-004	Repair Clearance & Marker Lamps	18-Sep-2019 16:14:27	ROGSHP	N	DON	2.03
18-Sep-2019	167,353		403499	06-020	Inspect Drivetrain Group	18-Sep-2019 14:03:53	ROGSHP	O	DON	14.56
03-Dec-2019	167,355		414984	03-002-035	Replace Windshield Wiper & Washer	03-Dec-2019 13:24:39	ROGSHP	I	DON	24.02
03-Dec-2019	167,355		414984	03-032-001	Replace Battery	03-Dec-2019 13:21:53	ROGSHP	I	DON	150.75
03-Dec-2019	167,355		414984	06-100-DOT	Inspect DOT Federal Inspection	03-Dec-2019 14:08:27	ROGSHP	P	DON	27.61
07-Feb-2020	167,355		425254	24-063-003	Repair Transceiver - GPS Tracker	07-Feb-2020 10:51:14	ROGSHP	Q	DON	49.44
07-Feb-2020	167,355		425254	03-063-003	Replace Transceiver - GPS Tracker	07-Feb-2020 11:56:27	ROGSHP	Q	DON	296.05
17-Mar-2020	167,626		431527	24-034-004	Repair Clearance & Marker Lamps	17-Mar-2020 15:11:39	ROGSHP	N	DON	25.18
28-Apr-2020	167,683		438269	03-032-001	Replace Battery	28-Apr-2020 09:51:03	ROGSHP	O	DON	144.20
28-Apr-2020	167,683		438269	03-164	Replace Blower	28-Apr-2020 10:32:32	ROGSHP	N	DON	128.00
13-Jun-2020	173,088		451587	38-100-PMA	Service A PMI	13-Jun-2020 07:19:00	BVLOFC	P	DON	44.09
24-Aug-2020	174,605		457812	03-034-001	Replace Headlamps / Fog Lamps	24-Aug-2020 17:44:51	ROGSHP	O	DON	32.57
03-Sep-2020	175,378		459910	03-002-035	Replace Windshield Wiper & Washer	03-Sep-2020 15:09:48	ROGSHP	I	DON	33.77
03-Sep-2020	175,378		459910	06-100-PMA	Inspect A PMI	03-Sep-2020 15:05:30	ROGSHP	P	DON	22.74
03-Sep-2020	175,378		459910	38-100-PMA	Service A PMI	03-Sep-2020 15:55:57	ROGSHP	P	DON	51.00
03-Sep-2020	175,378		459910	24-034-001	Repair Headlamps / Fog Lamps	03-Sep-2020 15:21:55	ROGSHP	I	DON	22.34
03-Sep-2020	175,378		459910	03-013-002	Replace Rear Brakes & Drums	03-Sep-2020 17:07:12	ROGSHP	I	DON	117.09

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: F0942 - 2010 E350 REG CAB										
03-Sep-2020 1:	175,378		459910	03-017-001	Replace Tire - Pneumatic	08-Sep-2020 08:45:29	ROGSHP	I	DON	976.07
14-Sep-2020 0:	175,711		461161	24-034-001	Repair Headlamps / Fog Lamps	14-Sep-2020 06:29:34	ROGSHP	O	DON	25.17
06-Oct-2020 0:	176,250		465003	06-100-DOT	Inspect DOT Federal Inspection	06-Oct-2020 07:59:17	ROGSHP	P	DON	76.46
06-Oct-2020 0:	176,250		465003	03-031-001	Replace Generator/Alternator	06-Oct-2020 10:07:11	ROGSHP	I	DON	306.52
06-Oct-2020 0:	176,250		465003	03-045-023	Replace Engine Belts	06-Oct-2020 09:57:54	ROGSHP	I	DON	26.52
06-Oct-2020 0:	176,250		465003	03-045-026	Replace Tensioner - Engine Belts	06-Oct-2020 10:08:10	ROGSHP	I	DON	43.76
06-Oct-2020 0:	176,250		465003	03-045-027	Replace Idler Pulley	06-Oct-2020 10:00:17	ROGSHP	I	DON	24.21
06-Oct-2020 0:	176,250		465003	24-022-003	Repair Differential Carrier	06-Oct-2020 10:20:55	ROGSHP	I	DON	207.16
06-Oct-2020 0:	176,250		465003	03-051-009	Replace Fire Extinguisher	06-Oct-2020 08:28:26	ROGSHP	I	DON	85.84
23-Apr-2021 1:	178,623		502524	03-018-011	Replace Seal - Wheel	23-Apr-2021 15:08:34	ROGSHP	N	DON	38.15
23-Apr-2021 1:	178,623		502524	06-015-004	Inspect Steering Linkage	23-Apr-2021 14:18:33	ROGSHP	O	DON	37.50
23-Apr-2021 1:	178,623		502524	06-706-001	Inspect Engine	23-Apr-2021 14:21:16	ROGSHP	O	DON	2.99
23-Apr-2021 1:	178,623		502524	03-013-001	Replace Front Brakes & Drums	23-Apr-2021 14:44:55	ROGSHP	N	DON	107.74
23-Apr-2021 1:	178,623		502524	03-018-005	Replace Bearings - General	23-Apr-2021 16:10:22	ROGSHP	N	DON	112.00
17-Jun-2021 1:	183,948		513468	24-164	Repair Blower	18-Jun-2021 06:43:52	ROGSHP	O	DON	68.59
17-Jun-2021 1:	183,948		513468	06-002-070	Inspect Air Bag - Safety Restraint	18-Jun-2021 08:36:07	ROGSHP	N	DON	45.55
17-Jun-2021 1:	183,948		513468	06-706-001	Inspect Engine	18-Jun-2021 07:33:57	ROGSHP	N	DON	36.70
17-Jun-2021 1:	183,948		513468	14-053-004	Install Safety Equipment	18-Jun-2021 08:56:00	ROGSHP	N	DON	9.58
17-Jun-2021 1:	183,948		513468	14-002-060	Install Seat Belt	22-Jun-2021 13:52:06	ROGSHP	N	DON	110.58
17-Jun-2021 1:	183,948		513468	24-002-070	Repair Air Bag - Safety Restraint	07-Jul-2021 08:13:41	ROGSHP	N	DON	108.73
17-Jun-2021 1:	183,948		513468	03-043-002	Replace Exhaust Manifold	07-Jul-2021 08:13:29	ROGSHP	N	DON	963.69
17-Jun-2021 1:	183,948		513468	24-044	Repair Fuel System	07-Jul-2021 08:12:54	ROGSHP	N	DON	777.43
11-Aug-2021 0:	183,948		524361	24-034-002	Repair Stop, Tail, Turn & License	11-Aug-2021 09:22:11	OTSSHP	O	DON	7.31
28-Oct-2021 0:	184,928		542505	06-100-DOT	Inspect DOT Federal Inspection	28-Oct-2021 10:45:03	OTSSHP	P	DON	45.96
28-Oct-2021 0:	184,928		542505	03-051-009	Replace Fire Extinguisher	28-Oct-2021 11:03:45	OTSSHP	I	DON	304.19
28-Oct-2021 0:	184,928		542505	03-002-035	Replace Windshield Wiper & Washer	28-Oct-2021 10:51:52	OTSSHP	I	DON	34.10
28-Oct-2021 0:	184,928		542505	06-002-070	Inspect Air Bag - Safety Restraint	28-Oct-2021 11:31:44	OTSSHP	I	DON	20.51
28-Oct-2021 0:	184,928		542505	24-001-022	Repair Switch - Fan Speed	02-Nov-2021 11:09:28	OTSSHP	O	DON	9.16
29-Mar-2022 1:	184,928		578144	03-032-001	Replace Battery	29-Mar-2022 15:38:02	OTSSHP	P	DON	144.75

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: F0942 - 2010 E350 REG CAB										
31-Mar-2022 1	185,520		578673	03-044-013	Replace Cap - Fuel Tank	14-Apr-2022 07:13:06	OTSSHP	I	DON	24.44
31-Mar-2022 1	185,520		578673	03-051-009	Replace Fire Extinguisher	31-Mar-2022 13:33:50	OTSSHP	N	DON	228.02
31-Mar-2022 1	185,520		578673	06-100-PMA	Inspect A PMI	14-Apr-2022 07:01:10	OTSSHP	P	DON	10.30
31-Mar-2022 1	185,520		578673	38-100-PMA	Service A PMI	14-Apr-2022 06:47:07	OTSSHP	P	DON	59.10
25-May-2022 1	185,520		591321	07-040	Lubricate Engine / Motor Systems Group	25-May-2022 11:51:08	OTSSHP	O	DON	4.95
25-Aug-2022 C	190,255		611822	03-013-002	Replace Rear Brakes & Drums	25-Aug-2022 10:19:49	OTSSHP	I	DON	229.43
25-Aug-2022 C	190,255		611822	03-051-009	Replace Fire Extinguisher	25-Aug-2022 07:46:10	OTSSHP	Q	DON	232.92
25-Aug-2022 C	190,255		611822	06-100-PMA	Inspect A PMI	25-Aug-2022 07:39:29	OTSSHP	P	DON	35.64
25-Aug-2022 C	190,255		611822	31-017-001	Rotate Tire - Pneumatic	25-Aug-2022 09:28:24	OTSSHP	I	DON	19.39
25-Aug-2022 C	190,255		611822	38-100-PMA	Service A PMI	25-Aug-2022 08:08:37	OTSSHP	P	DON	46.86
31-Oct-2022 0	192,649		628385	03-002-035	Replace Windshield Wiper & Washer	31-Oct-2022 16:08:27	OTSSHP	I	DON	29.31
31-Oct-2022 0	192,649		628385	03-053-017	Replace First Aid Kit	31-Oct-2022 16:08:33	OTSSHP	Q	DON	48.64
31-Oct-2022 0	192,649		628385	06-100-DOT	Inspect DOT Federal Inspection	31-Oct-2022 16:01:31	OTSSHP	P	DON	18.23
14-Apr-2023 0	194,834		667042	03-002-035	Replace Windshield Wiper & Washer	14-Apr-2023 08:22:32	LAVSHP	O	DON	85.15
14-Apr-2023 0	194,834		667042	03-044-013	Replace Cap - Fuel Tank	20-Apr-2023 10:54:53	LAVSHP	O	DON	18.15
14-Apr-2023 0	194,834		667042	06-100-PMA	Inspect A PMI	14-Apr-2023 06:06:04	LAVSHP	P	DON	38.27
14-Apr-2023 0	194,834		667042	38-100-PMA	Service A PMI	14-Apr-2023 06:47:12	LAVSHP	P	DON	56.28
25-Jan-2024 1	197,226		734727	06-100-009	Inspect Safety Check	26-Jan-2024 08:39:59	BTRUCK	N	DON	135.89
29-Jan-2024 0	197,226		735314	02-002	Clean Cab & Sheet Metal	13-Feb-2024 14:12:07	BSETUP	Z	DON	303.04
29-Jan-2024 0	197,226		735314	25-050	Remove Accessories Group	06-Feb-2024 17:01:27	BSETUP	Z	DON	408.49
29-Jan-2024 0	197,226		735314	12-018-003	Refinish Wheels	13-Feb-2024 08:38:13	BSETUP	Z	DON	175.14