

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: E1513 - 2018 JOHN DEERE 320E										
29-Jan-2018	4	0	321483	03-017-003	Replace Tire - Cushion	30-Jan-2018 15:22:52	BBKHOE	Q	DON	3,885.95
29-Jan-2018	4	0	321483	14-063-003	Install Transceiver - GPS Tracker	30-Jan-2018 15:19:26	BBKHOE	Q	DON	301.71
29-Jan-2018	4	0	321483	21-360-001	Fabricate Bucket and Attachments	30-Jan-2018 09:50:59	BBKHOE	I	DON	107.14
15-Feb-2018	215	0	323782	03-063-003	Replace Transceiver - GPS Tracker	15-Feb-2018 13:42:55	BBKHOE	I	DON	560.10
15-Feb-2018	215	0	323782	24-044-007	Repair Throttle Controls	08-May-2018 16:37:01	BBKHOE	B	DON	286.16
02-Jan-2019	989	0	366426	02-360	Clean Loader / Skid-Steer	10-Jan-2019 10:37:22	BWASH	N	DON	261.22
02-Jan-2019	989	0	366426	03-002-027	Replace Seat Frames & Springs	09-Jan-2019 07:50:34	BBKHOE	Q	DON	34.94
02-Jan-2019	989	0	366426	06-100-PMB	Inspect B PMI	09-Jan-2019 13:20:50	BBKHOE	P	DON	2,059.83
02-Jan-2019	989	0	366426	10-360-011	Rebush Quick-Attach Coupling Assembly	09-Jan-2019 10:59:07	BBKHOE	P	DON	115.43
02-Jan-2019	989	0	366426	24-063-003	Repair Transceiver - GPS Tracker	09-Jan-2019 12:00:13	BBKHOE	I	DON	37.40
23-Aug-2019	1,375	0	400035	03-017-005	Replace Tire - Solid	23-Aug-2019 14:44:23	BBKHOE	I	DON	3,130.36
23-Aug-2019	1,375	0	400035	03-020	Replace Drivetrain Group	23-Aug-2019 13:53:16	BBKHOE	P	DON	686.98
23-Aug-2019	1,375	0	400035	03-021-001	Replace Axle Assembly - Driven, Front Steering	26-Aug-2019 15:58:10	BBKHOE	P	DON	1,346.08
23-Aug-2019	1,375	0	400035	03-031-006	Replace Belt - Alternator	23-Aug-2019 14:58:14	BBKHOE	P	DON	42.85
23-Aug-2019	1,375	0	400035	03-032-009	Replace Switch - Master Disconnect	26-Aug-2019 07:59:39	BBKHOE	I	DON	103.75
23-Aug-2019	1,375	0	400035	03-065-007	Replace Hoses & Fittings	26-Aug-2019 11:34:34	BBKHOE	I	DON	29.32
23-Aug-2019	1,375	0	400035	06-100-PMB	Inspect B PMI	23-Aug-2019 10:23:01	BBKHOE	P	DON	58.80
23-Aug-2019	1,375	0	400035	18-037-001	Test Modules - Multiple Use	26-Aug-2019 10:46:40	BBKHOE	I	DON	102.24
23-Aug-2019	1,375	0	400035	24-360-011	Repair Quick-Attach Coupling Assembly	26-Aug-2019 07:42:06	BBKHOE	I	DON	417.35
23-Aug-2019	1,375	0	400035	38-045	Service Power Plant	23-Aug-2019 16:11:29	BBKHOE	I	DON	220.40
07-Oct-2019	1,420	0	406191	03-021-001	Replace Axle Assembly - Driven, Front Steering	11-Oct-2019 06:19:10	BBKHOE	I	DON	227.08
26-Feb-2020	1,736	0	428347	02-360	Clean Loader / Skid-Steer	28-Feb-2020 17:00:22	BWASH	N	DON	198.91
26-Feb-2020	1,736	0	428347	03-065-004	Replace Cylinder	06-Mar-2020 12:09:00	BBKHOE	P	DON	5,083.19
26-Feb-2020	1,736	0	428347	06-100-PMLA	Inspect A PMI	09-Mar-2020 08:22:32	BBKHOE	P	DON	124.66
26-Feb-2020	1,736	0	428347	10-360-011	Rebush Quick-Attach Coupling Assembly	09-Mar-2020 06:08:21	BBKHOE	P	DON	614.63
26-Feb-2020	1,736	0	428347	14-360-003	Install Drive Train	04-Mar-2020 17:07:32	BBKHOE	P	DON	536.30
26-Feb-2020	1,736	0	428347	24-063-003	Repair Transceiver - GPS Tracker	06-Mar-2020 14:42:22	BBKHOE	B	DON	57.19
26-Feb-2020	1,736	0	428347	38-100-PMC	Service C PMI	04-Mar-2020 16:48:21	BBKHOE	P	DON	786.74
16-Apr-2020	0	0	436229	38-100-PMA	Service A PMI	16-Apr-2020 08:10:56	BHVYEQ	P	DON	183.64

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: E1513 - 2018 JOHN DEERE 320E										
19-Jun-2020 0		0	446424	03-052-005	Replace Transmitter - CB	19-Jun-2020 07:34:03	BHVYEQ	O	DON	76.80
28-Aug-2020 1	1,888	0	458854	06-100-PMA	Inspect A PMI	01-Sep-2020 11:05:23	BSMEQP	P	DON	158.82
30-Dec-2020 1	2,364	0	479494	03-360-003	Replace Drive Train	30-Dec-2020 18:01:01	BHVYEQ	B	DON	2,035.82
04-Mar-2021 1	2,322	0	491909	02-360	Clean Loader / Skid-Steer	10-Mar-2021 11:05:15	BWASH	N	DON	494.69
04-Mar-2021 1	2,322	0	491909	03-065-007	Replace Hoses & Fittings	11-Mar-2021 17:00:21	BBKHoe	I	DON	176.64
04-Mar-2021 1	2,322	0	491909	03-360-011	Replace Quick-Attach Coupling Assembly	11-Mar-2021 15:55:07	BBKHoe	I	DON	795.15
04-Mar-2021 1	2,322	0	491909	06-100-PMA	Inspect A PMI	12-Mar-2021 08:26:54	SCHED	P	DON	184.72
04-Mar-2021 1	2,322	0	491909	06-100-PMB	Inspect B PMI	12-Mar-2021 08:13:36	SCHED	P	DON	0.00
04-Mar-2021 1	2,322	0	491909	24-043-004	Repair Turbocharger	11-Mar-2021 12:59:58	BBKHoe	I	DON	29.89
04-Mar-2021 1	2,322	0	491909	24-052-005	Repair Transmitter - CB	12-Mar-2021 08:24:37	BBKHoe	Q	DON	64.10
04-Mar-2021 1	2,322	0	491909	24-360-003	Repair Drive Train	11-Mar-2021 09:36:30	BBKHoe	P	DON	1,029.47
04-Mar-2021 1	2,322	0	491909	24-514	Repair Bucket	30-Apr-2021 08:34:19	BWELD	N	DON	1,900.57
04-Mar-2021 1	2,322	0	491909	38-100-PMC	Service C PMI	11-Mar-2021 11:52:57	BBKHoe	I	DON	618.27
14-Apr-2021 1	2,370	0	500417	03-041-006	Replace Filter - Inner	14-Apr-2021 10:05:20	BHVYEQ	P	DON	32.14
14-Apr-2021 1	2,370	0	500417	03-041-007	Replace Filter - Outer	14-Apr-2021 10:05:32	BHVYEQ	P	DON	36.51
14-Apr-2021 1	2,370	0	500417	03-044-002	Replace Filters	14-Apr-2021 10:04:33	BHVYEQ	P	DON	81.34
14-Apr-2021 1	2,370	0	500417	03-045-011	Replace Filter Assembly - Oil	14-Apr-2021 10:03:49	BHVYEQ	P	DON	16.29
30-Apr-2021 0		0	503886	24-065-007	Repair Hoses & Fittings	30-Apr-2021 08:34:52	BHVYEQ	B	DON	1,078.28
02-Jun-2021 1	2,492	0	510280	03-059-002	Replace Pintle Hook Assembly	02-Jun-2021 13:24:45	BBKHoe	O	DON	60.22
10-Jun-2021 0	2,511	0	511847	03-065-007	Replace Hoses & Fittings	28-Jun-2021 16:02:06	BHVYEQ	B	DON	2,471.10
10-Jun-2021 0	2,511	0	511847	24-360-003	Repair Drive Train	30-Jun-2021 09:35:14	BBKHoe	B	DON	88.81
10-Jun-2021 0	2,511	0	511847	24-360-011	Repair Quick-Attach Coupling Assembly	10-Jun-2021 16:01:40	BBKHoe	B	DON	1,348.59
25-Jun-2021 1	2,525	0	515086	03-044-002	Replace Filters	25-Jun-2021 10:46:54	BHVYEQ	O	DON	118.32
25-Jun-2021 1	2,525	0	515086	03-045-011	Replace Filter Assembly - Oil	25-Jun-2021 10:47:24	BHVYEQ	O	DON	37.97
29-Sep-2021 1	2,651	0	535204	03-049-003	Replace ECM Wiring Harness	29-Sep-2021 14:51:51	BHVYEQ	B	DON	4,172.07
28-Jan-2022 0	2,688	0	562259	03-017-001	Replace Tire - Pneumatic	01-Feb-2022 07:13:51	BTIRE	I	DON	0.00
09-Feb-2022 1	2,918	0	565344	02-065-004	Clean Cylinder	02-Mar-2022 11:18:49	BBKHoe	I	DON	255.56
09-Feb-2022 1	2,918	0	565344	03-021-001	Replace Axle Assembly - Driven, Front Steering	28-Feb-2022 14:23:40	BBKHoe	I	DON	1,513.89
09-Feb-2022 1	2,918	0	565344	03-031-006	Replace Belt - Alternator	25-Feb-2022 08:52:22	BBKHoe	N	DON	51.61

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: E1513 - 2018 JOHN DEERE 320E -										
09-Feb-2022 1	2,918	0	565344	03-063-003	Replace Transceiver - GPS Tracker	23-Feb-2022 10:43:57	BBKHOE	Q	DON	285.22
09-Feb-2022 1	2,918	0	565344	03-065-004	Replace Cylinder	25-Feb-2022 10:46:56	BBKHOE	P	DON	760.50
09-Feb-2022 1	2,918	0	565344	03-065-008	Replace Line / Tubing Assembly	01-Mar-2022 07:23:45	BBKHOE	I	DON	132.33
09-Feb-2022 1	2,918	0	565344	03-360-003	Replace Drive Train	25-Feb-2022 14:04:59	BBKHOE	N	DON	631.60
09-Feb-2022 1	2,918	0	565344	06-100-PMA	Inspect A PMI	02-Mar-2022 15:28:23	BBKHOE	P	DON	148.80
09-Feb-2022 1	2,918	0	565344	06-100-PMB	Inspect B PMI	02-Mar-2022 15:26:53	BBKHOE	P	DON	0.00
09-Feb-2022 1	2,918	0	565344	14-052-005	Install Transmitter - CB	23-Feb-2022 12:00:29	BHVVEQ	Q	DON	99.34
09-Feb-2022 1	2,918	0	565344	24-002-016	Repair Compartment Lid - Tail & Lift Gate - Re	25-Feb-2022 08:30:30	BBKHOE	I	DON	208.30
09-Feb-2022 1	2,918	0	565344	24-065-007	Repair Hoses & Fittings	23-Feb-2022 09:58:27	BBKHOE	P	DON	131.71
09-Feb-2022 1	2,918	0	565344	24-360-011	Repair Quick-Attach Coupling Assembly	28-Feb-2022 14:21:30	BBKHOE	N	DON	1,330.69
09-Feb-2022 1	2,918	0	565344	26-360-006	Weld Lift Arm Assembly		BBKHOE	N	CAN	0.00
09-Feb-2022 1	2,918	0	565344	38-100-PMC	Service C PMI	28-Feb-2022 16:35:52	BBKHOE	P	DON	467.73
24-Jun-2022 1	2,967	0	598561	06-100-PMA	Inspect A PMI	27-Jun-2022 08:00:50	BBKHOE	P	DON	61.24
24-Jun-2022 1	2,967	0	598561	18-049-004	Test ECM Sensor	27-Jun-2022 08:01:18	BBKHOE	P	DON	191.76
28-Nov-2022 1	3,032	0	635280	02-360	Clean Loader / Skid-Steer	01-Dec-2022 07:56:52	BWASH	N	DON	408.08
28-Nov-2022 1	3,032	0	635280	06-100-PMA	Inspect A PMI	08-Dec-2022 05:48:03	BBKHOE	P	DON	222.91
28-Nov-2022 1	3,032	0	635280	38-100-PMB	Service B PMI	07-Dec-2022 07:25:55	BBKHOE	P	DON	640.01
04-Apr-2023 1	3,054	0	664368	03-065-006	Replace Filters, Strainers, Screens & Housing	04-Apr-2023 10:22:21	BBKHOE	O	DON	60.07
13-Apr-2023 1	3,069	0	666998	24-360-008	Repair Operator Controls	18-Apr-2023 12:28:09	TRK005	B	DON	786.71
11-May-2023 0	3,104	0	673824	03-049-004	Replace ECM Sensor	11-May-2023 13:02:09	BBKHOE	O	DON	80.95
28-Jun-2023 0	3,160	0	684586	03-065-007	Replace Hoses & Fittings	28-Jun-2023 05:07:26	BHVVEQ	O	DON	47.96
27-Feb-2024 0		0	741545	02-360	Clean Loader / Skid-Steer	01-Mar-2024 06:04:13	BWASH	N	DON	274.31
27-Feb-2024 0		0	741545	06-100-PMA	Inspect A PMI	04-Mar-2024 05:22:31	BBKHOE	P	DON	0.00
27-Feb-2024 0		0	741545	06-100-PMB	Inspect B PMI		BBKHOE	P	WND	195.06
27-Feb-2024 0		0	741545	OS-100-008	Out-Service Out-Service Inspection		BBKHOE	N	WND	122.66