

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: P1343 - 2016 CAT 966M										
18-Jan-2017 11	17	0	273836	14-063-003	Install Transceiver - GPS Tracker	18-Jan-2017 15:21:14	BHVYEQ	Q	DON	362.88
18-Jan-2017 11	17	0	273836	14-051-009	Install Fire Extinguisher	18-Jan-2017 12:57:39	BHVYEQ	Q	DON	54.09
18-Jan-2017 11	17	0	273836	14-052-005	Install Transmitter - CB	18-Jan-2017 16:18:41	BHVYEQ	Q	DON	104.33
22-Mar-2017 1	17	0	282259	06-100-PMA	Inspect A PMI	22-Mar-2017 16:19:47	BHVYEQ	P	DON	19.06
30-Mar-2017 1	17	0	283273	14-930	Install Scale	30-Mar-2017 14:54:13	BHVYEQ	Q	DON	1,897.38
09-May-2017 1	17	0	288134	03-047-001	Replace Engine Filter Kits	16-May-2017 06:20:12	BHVYEQ	F	DON	116.84
15-Jun-2017 0	17	0	293001	03-704-008	Replace Lube System	15-Jun-2017 07:52:06	BHVYEQ	J	DON	20.77
19-Jun-2017 0	17	0	293458	03-049-004	Replace ECM Sensor	23-Jun-2017 07:14:28	BHVYEQ	I	DON	184.03
31-Jul-2017 14	982	0	298944	24-360-001	Repair Bucket and Attachments	31-Jul-2017 14:22:48	BHVYEQ	I	DON	272.56
15-Aug-2017 0	982	0	301012	06-100-PMA	Inspect A PMI	15-Aug-2017 06:05:38	BHVYEQ	P	DON	244.37
23-Oct-2017 14	982	0	309875	03-049-004	Replace ECM Sensor	28-Oct-2017 08:30:24	BHVYEQ	J	DON	410.28
13-Nov-2017 1	982	0	313195	03-032-001	Replace Battery	13-Nov-2017 12:48:00	BVLOFC	F	DON	100.11
04-Dec-2017 1	1,540	0	314615	38-100-PMC	Service C PMI	20-Dec-2017 13:32:51	BHVYEQ	J	DON	1,446.57
04-Dec-2017 1	1,540	0	314615	26-360-001	Weld Bucket and Attachments	05-Dec-2017 13:04:13	BHVYEQ	N	DON	418.79
14-Dec-2017 0		0	316071	02-360	Clean Loader / Skid-Steer	03-Jan-2018 11:34:28	BWASH	J	DON	209.95
02-Feb-2018 0	1,540	0	322073	24-002-018	Repair Cab Or Front Door Mechanism	02-Feb-2018 04:43:17	BHVYEQ	W	DON	205.83
02-Feb-2018 0	1,540	0	322073	37-049-002	Calibrate ECM Module	02-Feb-2018 04:44:37	BHVYEQ	I	DON	616.47
21-Mar-2018 0	1,540	0	328095	03-052-005	Replace Transmitter - CB	30-Mar-2018 05:59:00	BHVYEQ	I	DON	152.70
18-Jun-2018 1	1,540	0	340193	03-049-004	Replace ECM Sensor	25-Jun-2018 09:23:42	BHVYEQ	I	DON	260.61
18-Jun-2018 1	1,540	0	340193	03-072-006	Replace Door Latch Mechanism	26-Jun-2018 12:01:40	BHVYEQ	I	DON	357.50
31-Jul-2018 13	1,540	0	346185	03-044-002	Replace Filters	31-Jul-2018 13:50:28	BHVYEQ	P	DON	53.68
31-Jul-2018 13	1,540	0	346185	03-045-011	Replace Filter Assembly - Oil	31-Jul-2018 13:50:35	BHVYEQ	P	DON	19.06
07-Dec-2018 1	3,000	0	363477	02-360	Clean Loader / Skid-Steer	04-Jan-2019 17:01:59	BWASH	N	DON	362.10
07-Dec-2018 1	3,000	0	363477	06-100-PMC	Inspect C PMI	18-Jan-2019 06:19:09	BHVYEQ	P	DON	2,068.82
07-Dec-2018 1	3,000	0	363477	26-514-004	Weld Edges	11-Dec-2018 05:15:30	BHVYEQ	I	DON	1,479.81
07-Dec-2018 1	3,000	0	363477	03-514-004	Replace Edges	14-Jan-2019 16:10:58	BHVYEQ	I	DON	153.81
07-Dec-2018 1	3,000	0	363477	03-034-016	Replace Turn Signal Switch	14-Jan-2019 17:01:56	BHVYEQ	I	DON	235.94
07-Dec-2018 1	3,000	0	363477	24-019-001	Repair Reservoir & Lines	16-Jan-2019 10:21:42	BHVYEQ	I	DON	1,049.35
07-Dec-2018 1	3,000	0	363477	03-065-007	Replace Hoses & Fittings	18-Jan-2019 06:19:13	BHVYEQ	W	DON	939.28

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: P1343 - 2016 CAT 966M										
07-Dec-2018 1	3,000	0	363477	03-065-002	Replace Accumulator	18-Jan-2019 06:19:13	BHVYEQ	W	DON	0.00
07-Dec-2018 1	3,000	0	363477	37-930	Calibrate Scale	18-Jan-2019 06:19:13	BHVYEQ	N	DON	262.05
16-Jan-2019 0:		0	368474	02-360	Clean Loader / Skid-Steer	16-Jan-2019 07:49:53	BWASH	N	DON	64.31
03-Jun-2019 0'	3,254	0	388289	03-001-016	Replace Filter - Cab Ventilation	03-Jun-2019 07:31:30	BHVYEQ	P	DON	54.54
03-Jun-2019 0'	3,254	0	388289	03-019-001	Replace Reservoir & Lines	03-Jun-2019 07:32:18	BHVYEQ	O	DON	214.64
03-Jun-2019 0'	3,254	0	388289	03-045-011	Replace Filter Assembly - Oil	03-Jun-2019 07:39:40	BHVYEQ	P	DON	58.05
14-Jun-2019 0:	3,516	0	390125	24-050	Repair Accessories Group	18-Jun-2019 08:35:32	BHVYEQ	I	DON	231.53
03-Jul-2019 08	3,613	0	392922	06-100-PMA	Inspect A PMI	03-Jul-2019 08:48:15	BHVYEQ	P	DON	0.00
03-Jul-2019 08	3,613	0	392922	38-100-PMA	Service A PMI	03-Jul-2019 08:48:19	BHVYEQ	P	DON	212.37
06-Sep-2019 0:	3,904	0	401767	38-100-PMA	Service A PMI	06-Sep-2019 08:44:44	BHVYEQ	P	DON	230.86
06-Sep-2019 0:	3,904	0	401767	06-100-PMA	Inspect A PMI	06-Sep-2019 08:44:47	BHVYEQ	P	DON	0.00
19-Sep-2019 1:	4,091	0	403772	06-360-003	Inspect Drive Train	20-Sep-2019 11:01:54	BHVYEQ	O	DON	220.88
30-Oct-2019 1:	4,217	0	410337	02-043-009	Clean Diesel Particulate Filter - DPF	06-Nov-2019 11:38:32	BHVYEQ	N	DON	377.23
30-Oct-2019 1:	4,217	0	410337	02-360	Clean Loader / Skid-Steer	04-Nov-2019 08:47:40	BWASH	N	DON	465.12
30-Oct-2019 1:	4,217	0	410337	03-043-025	Replace Filter - DEF	06-Nov-2019 10:55:50	BHVYEQ	I	DON	322.16
30-Oct-2019 1:	4,217	0	410337	03-045-023	Replace Engine Belts	06-Nov-2019 12:02:25	BHVYEQ	I	DON	134.83
30-Oct-2019 1:	4,217	0	410337	03-052-013	Replace Antenna and Mounting	07-Nov-2019 05:56:58	BHVYEQ	I	DON	6.63
30-Oct-2019 1:	4,217	0	410337	06-100-PMB	Inspect B PMI	31-Oct-2019 07:55:01	BHVYEQ	P	DON	66.80
30-Oct-2019 1:	4,217	0	410337	14-043-009	Install Diesel Particulate Filter - DPF	06-Nov-2019 16:53:29	BHVYEQ	P	DON	150.88
30-Oct-2019 1:	4,217	0	410337	24-111-010	Repair Belly Pan	06-Nov-2019 09:32:03	BHVYEQ	I	DON	122.13
30-Oct-2019 1:	4,217	0	410337	25-043-009	Remove Diesel Particulate Filter - DPF	05-Nov-2019 10:40:47	BHVYEQ	P	DON	320.46
30-Oct-2019 1:	4,217	0	410337	31-360-009	Rotate Bucket Tooth / Cutting Edge	07-Nov-2019 06:07:36	BHVYEQ	P	DON	45.98
30-Oct-2019 1:	4,217	0	410337	38-100-PMB	Service B PMI	05-Nov-2019 17:08:30	BHVYEQ	P	DON	752.13
02-Apr-2020 1	4,566	0	434135	03-044-002	Replace Filters	17-Apr-2020 10:26:30	BHVYEQ	P	DON	100.26
02-Apr-2020 1	4,566	0	434135	03-001-016	Replace Filter - Cab Ventilation	17-Apr-2020 10:18:42	BHVYEQ	P	DON	46.13
02-Apr-2020 1	4,566	0	434135	03-041-006	Replace Filter - Inner	17-Apr-2020 10:18:24	BHVYEQ	P	DON	21.83
02-Apr-2020 1	4,566	0	434135	03-041-007	Replace Filter - Outer	17-Apr-2020 10:18:30	BHVYEQ	P	DON	49.37
19-Jun-2020 1:	4,777	0	446546	03-001-016	Replace Filter - Cab Ventilation	19-Jun-2020 14:14:40	BHVYEQ	P	DON	46.13
19-Jun-2020 1:	4,777	0	446546	03-041-006	Replace Filter - Inner	19-Jun-2020 14:13:54	BHVYEQ	P	DON	21.83

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: P1343 - 2016 CAT 966M										
19-Jun-2020 14:14:18	4,777	0	446546	03-041-007	Replace Filter - Outer	19-Jun-2020 14:14:18	BHVEQ	P	DON	49.37
10-Jul-2020 07 4,900	4,900	0	449832	24-019-001	Repair Reservoir & Lines	10-Jul-2020 15:27:57	BHVEQ	B	DON	287.53
10-Jul-2020 07 4,900	4,900	0	449832	03-019-001	Replace Reservoir & Lines	17-Jul-2020 13:14:50	BHVEQ	I	DON	458.34
10-Jul-2020 07 4,900	4,900	0	449832	03-360-009	Replace Bucket Tooth / Cutting Edge	17-Jul-2020 17:00:54	BHVEQ	E	DON	1,249.46
21-Jul-2020 13 4,933	4,933	0	451742	02-360	Clean Loader / Skid-Steer	21-Jul-2020 17:00:15	BWASH	N	DON	136.51
05-Aug-2020 05,005	5,005	0	454348	06-100-PMA	Inspect A PMI	05-Aug-2020 08:13:01	BHVEQ	P	DON	0.00
05-Aug-2020 05,005	5,005	0	454348	38-100-PMA	Service A PMI	05-Aug-2020 08:12:59	BHVEQ	P	DON	181.78
10-Aug-2020 1 5,038	5,038	0	455287	03-019-001	Replace Reservoir & Lines	10-Aug-2020 13:26:47	BHVEQ	B	DON	203.49
23-Sep-2020 0 5,275	5,275	0	462809	06-100-PMA	Inspect A PMI	23-Sep-2020 06:07:52	BHVEQ	P	DON	0.00
23-Sep-2020 0 5,275	5,275	0	462809	38-100-PMA	Service A PMI	23-Sep-2020 06:07:47	BHVEQ	P	DON	181.79
09-Nov-2020 0 5,472	5,472	0	470897	24-360-006	Repair Lift Arm Assembly	09-Nov-2020 04:52:38	BHVEQ	E	DON	2,195.49
03-Dec-2020 1 5,481	5,481	0	475033	24-360	Repair Loader / Skid-Steer	17-Dec-2020 05:54:01	BWELD	N	DON	334.71
07-Jan-2021 0 5,634	5,634	0	480550	03-071-005	Replace Side Door Assembly - Hinged	12-Feb-2021 05:17:57	BHVEQ	I	DON	378.97
07-Jan-2021 0 5,634	5,634	0	480550	06-100-PMC	Inspect C PMI	10-Feb-2021 05:25:03	BHVEQ	P	DON	0.00
07-Jan-2021 0 5,634	5,634	0	480550	26-514	Weld Bucket	13-Jan-2021 06:50:04	BHVEQ	N	DON	46.24
07-Jan-2021 0 5,634	5,634	0	480550	34-045-013	Reseal Oil Pan	10-Feb-2021 05:26:24	BHVEQ	I	DON	1,696.98
07-Jan-2021 0 5,634	5,634	0	480550	38-100-PMC	Service C PMI	10-Feb-2021 05:26:22	BHVEQ	P	DON	3,022.40
21-Jan-2021 0 5,966	5,966	0	483593	02-360	Clean Loader / Skid-Steer	21-Jan-2021 12:15:03	BWASH	N	DON	282.45
19-Mar-2021 1 5,966	5,966	0	495395	03-002-035	Replace Windshield Wiper & Washer	19-Mar-2021 15:58:48	BHVEQ	O	DON	53.35
05-May-2021 1 5,966	5,966	0	504617	06-001-001	Inspect Air Conditioning Assembly	05-May-2021 17:05:11	BHVEQ	O	DON	161.13
05-May-2021 1 5,966	5,966	0	504617	06-100-PMA	Inspect A PMI	05-May-2021 05:19:53	SCHED	P	DON	0.00
05-May-2021 1 5,966	5,966	0	504617	38-100-PMA	Service A PMI	05-May-2021 14:29:30	BHVEQ	P	DON	463.82
17-Sep-2021 0 6,157	6,157	0	532027	03-044-002	Replace Filters	21-Sep-2021 17:10:15	BHVEQ	O	DON	191.30
08-Nov-2021 1 6,377	6,377	0	544962	24-043-026	Repair Exhaust Cooler	10-Nov-2021 11:31:44	BHVEQ	O	DON	671.53
10-Jan-2022 1 6,617	6,617	0	558225	03-019-007	Replace Hose, Tubing & Connectors	05-Apr-2022 07:10:35	BHVEQ	I	DON	114.02
10-Jan-2022 1 6,617	6,617	0	558225	38-100-PMC	Service C PMI	05-Apr-2022 07:10:25	BHVEQ	P	DON	1,095.15
10-Jan-2022 1 6,617	6,617	0	558225	06-100-PMB	Inspect B PMI	05-Apr-2022 07:10:22	BHVEQ	P	DON	129.32
10-Jan-2022 1 6,617	6,617	0	558225	03-063-003	Replace Transceiver - GPS Tracker	24-Feb-2022 17:01:54	BHVEQ	Q	DON	360.69
10-Jan-2022 1 6,617	6,617	0	558225	24-065-002	Repair Accumulator	12-Jan-2022 07:42:50	BHVEQ	I	DON	72.97

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: P1343 - 2016 CAT 966M										
10-Jan-2022 1:	6,617	0	558225	35-037-021	Diagnose Circuit Breaker/Fuse - Multiple Use	11-Jan-2022 15:16:24	BHVYEQ	I	DON	472.05
10-Jan-2022 1:	6,617	0	558225	02-002	Clean Cab & Sheet Metal	13-Jan-2022 09:47:52	BHVYEQ	N	DON	98.37
10-Jan-2022 1:	6,617	0	558225	24-052-005	Repair Transmitter - CB	24-Feb-2022 11:54:25	BHVYEQ	I	DON	23.09
10-Jan-2022 1:	6,617	0	558225	31-360-009	Rotate Bucket Tooth / Cutting Edge	13-Jan-2022 11:45:41	BHVYEQ	N	DON	81.29
10-Jan-2022 1:	6,617	0	558225	03-065-007	Replace Hoses & Fittings	25-Feb-2022 05:45:05	BHVYEQ	I	DON	665.99
10-Jan-2022 1:	6,617	0	558225	03-043-020	Replace Pump - DEF	28-Feb-2022 12:40:55	BHVYEQ	W	DON	0.00
10-Jan-2022 1:	6,617	0	558225	37-049-002	Calibrate ECM Module	28-Feb-2022 12:37:14	BHVYEQ	W	DON	0.00
10-Jan-2022 1:	6,617	0	558225	37-930	Calibrate Scale	28-Feb-2022 12:39:40	BHVYEQ	N	DON	249.28
16-Mar-2022 1	6,617	0	574983	03-017-001	Replace Tire - Pneumatic	17-Mar-2022 14:50:29	BTIRE	P	DON	15,139.21
27-Jun-2022 1:	7,061	0	598935	03-001-016	Replace Filter - Cab Ventilation	27-Jun-2022 15:49:04	BHVYEQ	O	DON	47.10
27-Jun-2022 1:	7,061	0	598935	03-041-006	Replace Filter - Inner	27-Jun-2022 15:49:46	BHVYEQ	O	DON	22.49
27-Jun-2022 1:	7,061	0	598935	03-041-007	Replace Filter - Outer	27-Jun-2022 15:49:31	BHVYEQ	O	DON	53.76
27-Jun-2022 1:	7,061	0	598935	03-044-002	Replace Filters	27-Jun-2022 15:48:35	BHVYEQ	O	DON	48.93
27-Jun-2022 1:	7,061	0	598935	03-045-011	Replace Filter Assembly - Oil	27-Jun-2022 15:47:57	BHVYEQ	O	DON	23.38
01-Jul-2022 14	7,104	0	599976	03-042-004	Replace Water Pump	01-Oct-2022 00:00:00	TRK005	I	DON	831.14
01-Jul-2022 14	7,104	0	599976	03-065-006	Replace Filters, Strainers, Screens & Housing	12-Aug-2022 00:00:00	TRK005	O	DON	33.29
01-Jul-2022 14	7,104	0	599976	03-065-007	Replace Hoses & Fittings	12-Jul-2022 00:00:00	TRK005	I	DON	269.70
03-Aug-2022 C	7,339	0	606822	03-001-016	Replace Filter - Cab Ventilation	03-Aug-2022 07:25:39	BHVYEQ	O	DON	47.10
03-Aug-2022 C	7,339	0	606822	03-041-006	Replace Filter - Inner	03-Aug-2022 07:26:27	BHVYEQ	O	DON	22.49
03-Aug-2022 C	7,339	0	606822	03-041-007	Replace Filter - Outer	03-Aug-2022 07:26:01	BHVYEQ	O	DON	53.76
03-Aug-2022 C	7,339	0	606822	03-044-002	Replace Filters	03-Aug-2022 07:25:20	BHVYEQ	O	DON	56.07
03-Aug-2022 C	7,339	0	606822	03-045-011	Replace Filter Assembly - Oil	03-Aug-2022 07:24:23	BHVYEQ	O	DON	47.65
03-Aug-2022 C	7,339	0	606822	06-100-PMA	Inspect A PMI	15-Aug-2022 08:26:45	SCHED	P	DON	0.00
15-Aug-2022 C	7,428	0	609571	35-021-108	Diagnose Pinion Seal	15-Aug-2022 11:00:10	TRK001	O	DON	219.22
15-Aug-2022 1	7,428	0	609644	34-021-001	Reseal Axle Assembly - Driven, Front Steering	15-Sep-2022 07:01:25	BHVYEQ	I	DON	17,347.65
15-Aug-2022 1	7,428	0	609644	06-013	Inspect Brakes	15-Sep-2022 07:01:18	BHVYEQ	O	DON	201.34
15-Aug-2022 1	7,428	0	609644	24-022-001	Repair Axle Housing, Rear		BHVYEQ	I	CAN	0.00
15-Aug-2022 1	7,428	0	609644	02-360	Clean Loader / Skid-Steer	15-Sep-2022 09:35:15	BWASH	N	DON	413.54
15-Aug-2022 1	7,428	0	609644	34-022-001	Reseal Axle Housing, Rear	15-Sep-2022 07:38:28	BHVYEQ	I	DON	14,726.85

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: P1343 - 2016 CAT 966M										
15-Aug-2022 1	7,428	0	609644	38-100-PMA	Service A PMI	21-Sep-2022 06:00:16	BHVYEQ	O	DON	254.68
15-Aug-2022 1	7,428	0	609644	03-049-002	Replace ECM Module	30-Sep-2022 10:36:12	BHVYEQ	B	DON	9,621.89
15-Aug-2022 1	7,428	0	609644	03-041-007	Replace Filter - Outer	24-Oct-2022 13:14:58	BHVYEQ	O	DON	75.34
15-Aug-2022 1	7,428	0	609644	03-044-002	Replace Filters	24-Oct-2022 13:16:19	BHVYEQ	O	DON	117.43
15-Aug-2022 1	7,428	0	609644	03-001-016	Replace Filter - Cab Ventilation	24-Oct-2022 13:15:57	BHVYEQ	O	DON	57.16
15-Aug-2022 1	7,428	0	609644	03-041-006	Replace Filter - Inner	24-Oct-2022 13:15:36	BHVYEQ	O	DON	26.93
31-Oct-2022 1	7,701	0	628550	03-465-003	Replace Camera Assembly	31-Oct-2022 12:48:38	BBKHOE	I	DON	5,165.24
30-Nov-2022 1	7,730	0	635873	03-002-035	Replace Windshield Wiper & Washer	30-Nov-2022 14:38:01	BHVYEQ	O	DON	64.26
06-Dec-2022 1	7,749	0	637360	03-044-002	Replace Filters	06-Dec-2022 15:40:52	BHVYEQ	O	DON	56.47
06-Dec-2022 1	7,749	0	637360	03-045-011	Replace Filter Assembly - Oil	06-Dec-2022 15:40:15	BHVYEQ	O	DON	23.95
09-Jan-2023 0	7,794	0	643431	02-360	Clean Loader / Skid-Steer	27-Jan-2023 11:34:47	BWASH	N	DON	509.38
09-Jan-2023 0	7,794	0	643431	03-034-006	Replace Warning Lamps - Special Application	20-Jan-2023 09:50:40	BHVYEQ	I	DON	132.85
09-Jan-2023 0	7,794	0	643431	03-054-002	Replace Alarm - Reverse Signal	27-Jan-2023 11:34:49	BHVYEQ	I	DON	290.00
09-Jan-2023 0	7,794	0	643431	03-065-007	Replace Hoses & Fittings	11-Jan-2023 09:49:30	BHVYEQ	I	DON	1,058.21
09-Jan-2023 0	7,794	0	643431	03-360-009	Replace Bucket Tooth / Cutting Edge	11-Jan-2023 08:51:07	BHVYEQ	I	DON	1,362.03
09-Jan-2023 0	7,794	0	643431	06-100-PMC	Inspect C PMI	18-Jan-2023 13:42:09	BHVYEQ	P	DON	270.90
09-Jan-2023 0	7,794	0	643431	26-360-001	Weld Bucket and Attachments	18-Jan-2023 14:30:30	BHVYEQ	I	DON	32.16
09-Jan-2023 0	7,794	0	643431	34-027-043	Reseal Seal - Output	10-Jan-2023 11:26:43	BHVYEQ	I	DON	194.09
09-Jan-2023 0	7,794	0	643431	34-032-002	Reseal Starter	09-Jan-2023 12:02:39	BHVYEQ	I	DON	65.74
09-Jan-2023 0	7,794	0	643431	37-930	Calibrate Scale	27-Jan-2023 11:37:22	BHVYEQ	N	DON	239.32
09-Jan-2023 0	7,794	0	643431	38-100-PMC	Service C PMI	18-Jan-2023 14:30:51	BHVYEQ	P	DON	1,256.70
09-Jan-2023 0	7,794	0	643431	B3-049-002	Program ECM Module	27-Jan-2023 11:35:16	BHVYEQ	W	DON	0.00
12-Apr-2023 0	8,023	0	666495	24-518-002	Repair Ladder	13-Apr-2023 08:14:45	BHVYEQ	O	DON	138.18
17-Apr-2023 1	8,057	0	667690	03-065-007	Replace Hoses & Fittings	22-Apr-2023 09:26:35	TRK005	I	DON	902.77
01-May-2023 1	8,154	0	671443	24-930	Repair Scale	01-May-2023 14:45:51	BHVYEQ	O	DON	1,746.89
15-May-2023 1	8,177	0	674352	03-049-004	Replace ECM Sensor	14-Jun-2023 10:43:59	BHVYEQ	B	DON	2,068.49
15-May-2023 1	8,177	0	674352	38-100-PMA	Service A PMI	09-Jun-2023 05:54:43	BHVYEQ	O	DON	237.85
01-Jun-2023 1	8,216	0	678267	03-019-001	Replace Reservoir & Lines	02-Jun-2023 15:10:39	TRK005	I	DON	365.07
01-Jun-2023 1	8,216	0	678267	03-019-002	Replace Grease Pump		BHVYEQ	I	CAN	0.00

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: P1343 - 2016 CAT 966M										
01-Jun-2023 10	8,216	0	678267	03-019-007	Replace Hose, Tubing & Connectors		BHVVYEQ	I	CAN	0.00
01-Jun-2023 10	8,216	0	678267	06-019-002	Inspect Grease Pump	02-Jun-2023 06:14:24	TRK005	I	DON	396.49
12-Jun-2023 00	8,263	0	680513	03-002-035	Replace Windshield Wiper & Washer	19-Jun-2023 14:12:23	TRK005	I	DON	1,090.86
24-Jul-2023 07	8,520	0	690479	03-001-016	Replace Filter - Cab Ventilation	24-Jul-2023 07:23:06	BHVVYEQ	O	DON	57.09
25-Jul-2023 09	8,532	0	691003	02-042-002	Clean Radiator	25-Jul-2023 17:20:15	TRK005	I	DON	642.18
14-Aug-2023 10	8,625	0	696746	03-002-024	Replace Glass / Windshield	16-Aug-2023 06:40:46	BHVVYEQ	E	DON	272.19
20-Sep-2023 10	8,744	0	706705	03-044-002	Replace Filters	20-Sep-2023 12:49:37	BHVVYEQ	O	DON	357.02
25-Sep-2023 00	8,771	0	707617	03-024-001	Replace Drive Shaft - Front Driving Axles	25-Sep-2023 05:16:59	BHVVYEQ	B	DON	2,668.78
27-Nov-2023 10	9,087	0	722869	03-049-004	Replace ECM Sensor	27-Nov-2023 14:19:28	BHVVYEQ	B	DON	506.99
27-Nov-2023 10	9,087	0	722869	04-042-014	Rig / Unrig Coolant Overflow Reservoir	27-Nov-2023 14:19:46	BHVVYEQ	I	DON	1,765.78
01-Mar-2024 10		0	742537	OS-360	Out-Service Loader / Skid-Steer	07-Mar-2024 10:03:10	BHVVYEQ	Z	DON	580.45

Unit No: P1343 Count: 156 118,301.44