

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: P1344 - 2016 CAT 966M										
04-Jan-2017 1	17	0	271864	14-063-003	Install Transceiver - GPS Tracker	19-Jan-2017 05:45:19	BHVYEQ	Q	DON	310.19
04-Jan-2017 1	17	0	271864	14-051-009	Install Fire Extinguisher	19-Jan-2017 05:22:14	BHVYEQ	Q	DON	52.52
04-Jan-2017 1	17	0	271864	14-052-005	Install Transmitter - CB	19-Jan-2017 09:38:57	BHVYEQ	Q	DON	195.91
06-Mar-2017 0	17	0	279784	14-930	Install Scale	06-Mar-2017 08:01:13	BHVYEQ	Q	DON	1,872.01
10-May-2017 1	17	0	288460	03-044-002	Replace Filters	10-May-2017 15:09:43	BHVYEQ	F	DON	30.33
10-May-2017 1	17	0	288460	03-045-011	Replace Filter Assembly - Oil	10-May-2017 15:09:43	BHVYEQ	F	DON	19.06
25-May-2017 1	17	0	290478	03-041-006	Replace Filter - Inner	25-May-2017 12:58:39	BHVYEQ	J	DON	56.63
25-May-2017 1	17	0	290478	03-041-007	Replace Filter - Outer	25-May-2017 12:58:52	BHVYEQ	J	DON	24.58
17-Jul-2017 13	458	0	297057	06-100-PMA	Inspect A PMI	31-Jul-2017 12:03:49	BHVYEQ	P	DON	303.94
10-Aug-2017 0	458	0	300376	06-065	Inspect Hydraulic Systems - Special Application	10-Aug-2017 09:01:54	BHVYEQ	J	DON	75.59
30-Oct-2017 0	707	0	310573	03-049-002	Replace ECM Module	30-Oct-2017 05:12:10	BHVYEQ	W	DON	192.46
04-Dec-2017 1	995	0	314659	24-065-002	Repair Accumulator	04-Dec-2017 14:04:55	BHVYEQ	W	DON	795.54
04-Dec-2017 1	995	0	314659	26-360-001	Weld Bucket and Attachments	04-Dec-2017 14:16:13	BHVYEQ	N	DON	0.00
07-Dec-2017 1	1,022	0	315139	06-100-PMB	Inspect B PMI	06-Feb-2018 16:08:45	BHVYEQ	P	DON	1,479.65
07-Dec-2017 1	1,022	0	315139	24-002-018	Repair Cab Or Front Door Mechanism	02-Feb-2018 04:37:33	BHVYEQ	W	DON	162.53
26-Mar-2018 1	1,022	0	328800	03-027-043	Replace Seal - Output	26-Mar-2018 14:26:21	BHVYEQ	W	DON	0.00
26-Mar-2018 1	1,022	0	328800	03-041-001	Replace Air Cleaner	26-Mar-2018 14:29:06	BHVYEQ	I	DON	830.25
26-Mar-2018 1	1,022	0	328800	03-049-002	Replace ECM Module	26-Mar-2018 14:27:11	BHVYEQ	W	DON	0.00
26-Mar-2018 1	1,022	0	328800	03-049-003	Replace ECM Wiring Harness	26-Mar-2018 14:27:52	BHVYEQ	I	DON	237.11
26-Mar-2018 1	1,022	0	328800	34-022	Reseal Axles - Driven, Rear	26-Mar-2018 14:22:17	BHVYEQ	W	DON	0.00
17-Apr-2018 1	1,207	0	331790	03-045-011	Replace Filter Assembly - Oil	17-Apr-2018 13:29:46	BHVYEQ	P	DON	76.26
17-Apr-2018 1	1,207	0	331790	37-049-002	Calibrate ECM Module	17-Apr-2018 13:27:25	BHVYEQ	W	DON	223.73
14-May-2018 1	1,207	0	335656	06-019	Inspect Automatic/Manual Chassis Lubricator	18-May-2018 15:27:25	BHVYEQ	J	DON	280.22
14-May-2018 1	1,207	0	335656	03-041-007	Replace Filter - Outer	02-Jun-2018 06:19:49	BHVYEQ	P	DON	56.63
14-May-2018 1	1,207	0	335656	03-044-002	Replace Filters	02-Jun-2018 06:19:49	BHVYEQ	P	DON	107.37
14-May-2018 1	1,207	0	335656	03-045-011	Replace Filter Assembly - Oil	02-Jun-2018 06:19:49	BHVYEQ	P	DON	19.06
10-Sep-2018 1	1,207	0	351506	03-019-002	Replace Grease Pump	11-Sep-2018 09:30:42	BHVYEQ	I	DON	157.20
27-Sep-2018 1	2,311	0	354057	06-100-PMA	Inspect A PMI	05-Oct-2018 10:55:55	BHVYEQ	P	DON	205.80
27-Sep-2018 1	2,311	0	354057	06-019	Inspect Automatic/Manual Chassis Lubricator	13-Oct-2018 08:33:48	BHVYEQ	I	DON	435.39

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: P1344 - 2016 CAT 966M										
27-Sep-2018 1	2,311	0	354057	24-360-006	Repair Lift Arm Assembly	15-Oct-2018 06:54:45	BHVYEQ	I	DON	54.64
27-Sep-2018 1	2,311	0	354057	03-049-004	Replace ECM Sensor	28-Sep-2018 12:09:13	BHVYEQ	I	DON	239.77
27-Sep-2018 1	2,311	0	354057	03-024-001	Replace Drive Shaft - Front Driving Axles	08-Oct-2018 14:58:43	BHVYEQ	W	DON	804.37
31-Oct-2018 1	2,311	0	358956	06-360-009	Inspect Bucket Tooth / Cutting Edge	03-Nov-2018 09:03:20	BHVYEQ	I	DON	328.70
02-Jan-2019 0	2,811	0	366395	03-034-001	Replace Headlamps / Fog Lamps	14-Jan-2019 07:11:33	BHVYEQ	I	DON	413.84
02-Jan-2019 0	2,811	0	366395	03-360-009	Replace Bucket Tooth / Cutting Edge	14-Jan-2019 07:11:36	BHVYEQ	I	DON	1,227.35
02-Jan-2019 0	2,811	0	366395	06-100-PMC	Inspect C PMI	09-Jan-2019 06:13:16	BHVYEQ	P	DON	1,429.94
15-Jan-2019 0	2,811	0	368269	24-514	Repair Bucket	16-Jan-2019 08:38:43	BWELD	I	DON	311.07
13-Mar-2019 1	2,813	0	376547	02-360	Clean Loader / Skid-Steer	20-Mar-2019 13:43:12	BWASH	N	DON	158.53
13-Mar-2019 1	2,813	0	376547	03-002-010	Replace Mirrors	15-Mar-2019 11:32:10	BHVYEQ	I	DON	230.48
13-Mar-2019 1	2,813	0	376547	03-049-002	Replace ECM Module	26-Mar-2019 06:07:51	BHVYEQ	I	DON	2,370.81
13-Mar-2019 1	2,813	0	376547	37-049-002	Calibrate ECM Module	26-Mar-2019 06:07:51	BHVYEQ	W	DON	0.00
13-Mar-2019 1	2,813	0	376547	37-930	Calibrate Scale	26-Mar-2019 06:07:51	BHVYEQ	Q	DON	481.64
24-Jun-2019 1	3,307	0	391453	03-044-002	Replace Filters	24-Jun-2019 12:52:10	BHVYEQ	P	DON	54.46
24-Jun-2019 1	3,307	0	391453	03-045-011	Replace Filter Assembly - Oil	24-Jun-2019 12:52:03	BHVYEQ	P	DON	120.13
12-Aug-2019 1	3,630	0	398345	03-360-009	Replace Bucket Tooth / Cutting Edge	28-Aug-2019 05:18:19	BHVYEQ	E	DON	1,182.73
12-Aug-2019 1	3,630	0	398345	31-360-009	Rotate Bucket Tooth / Cutting Edge	19-Aug-2019 17:30:55	BHVYEQ	N	DON	138.94
29-Aug-2019 1	3,770	0	400947	06-100-PMB	Inspect B PMI	29-Aug-2019 14:35:00	BHVYEQ	P	DON	0.00
29-Aug-2019 1	3,770	0	400947	38-100-PMA	Service A PMI	29-Aug-2019 14:35:07	BHVYEQ	P	DON	248.45
25-Sep-2019 1	3,956	0	404566	03-019-001	Replace Reservoir & Lines	10-Oct-2019 08:44:12	BHVYEQ	O	DON	150.31
25-Sep-2019 1	3,956	0	404592	24-017-001	Repair Tire - Pneumatic	25-Sep-2019 14:29:45	BTIRE	B	DON	453.25
14-Oct-2019 1	4,085	0	407456	37-930	Calibrate Scale	14-Oct-2019 15:29:56	BHVYEQ	N	DON	645.72
15-Oct-2019 1	4,096	0	407612	03-001-016	Replace Filter - Cab Ventilation	15-Oct-2019 12:59:55	BHVYEQ	P	DON	54.06
06-Nov-2019 1	4,265	0	411427	38-100-PMA	Service A PMI	06-Nov-2019 14:16:10	BHVYEQ	P	DON	92.42
13-Nov-2019 1	4,318	0	412500	31-360-009	Rotate Bucket Tooth / Cutting Edge	13-Nov-2019 14:39:42	BHVYEQ	N	DON	87.95
15-Jan-2020 0	4,544	0	421075	24-514	Repair Bucket	16-Jan-2020 06:16:03	BWELD	I	DON	395.46
03-Feb-2020 0	4,574	0	424279	02-002	Clean Cab & Sheet Metal	12-Feb-2020 15:43:48	BHVYEQ	N	DON	194.39
03-Feb-2020 0	4,574	0	424279	02-043-009	Clean Diesel Particulate Filter - DPF	18-Feb-2020 07:11:51	BHVYEQ	I	DON	602.81
03-Feb-2020 0	4,574	0	424279	02-360	Clean Loader / Skid-Steer	05-Feb-2020 11:06:01	BWASH	N	DON	336.58

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: P1344 - 2016 CAT 966M										
03-Feb-2020 0	4,574	0	424279	03-031-006	Replace Belt - Alternator	12-Feb-2020 13:03:00	BHVYEQ	I	DON	144.03
03-Feb-2020 0	4,574	0	424279	03-065-007	Replace Hoses & Fittings	12-Feb-2020 13:51:12	BHVYEQ	I	DON	260.55
03-Feb-2020 0	4,574	0	424279	03-360-009	Replace Bucket Tooth / Cutting Edge	12-Feb-2020 08:02:11	BHVYEQ	I	DON	1,142.57
03-Feb-2020 0	4,574	0	424279	37-049-002	Calibrate ECM Module	19-Feb-2020 05:30:11	BHVYEQ	W	DON	0.00
03-Feb-2020 0	4,574	0	424279	37-930	Calibrate Scale	19-Feb-2020 05:30:11	BHVYEQ	N	DON	443.66
03-Feb-2020 0	4,574	0	424279	38-100-PMC	Service C PMI	19-Feb-2020 05:27:02	BHVYEQ	P	DON	1,240.75
29-May-2020 1	4,918	0	442943	06-360-001	Inspect Bucket and Attachments	03-Sep-2020 15:51:36	BHVYEQ	O	DON	213.26
29-May-2020 1	4,918	0	442943	03-044-002	Replace Filters	07-Jul-2020 13:14:49	BHVYEQ	P	DON	53.56
29-May-2020 1	4,918	0	442943	03-001-016	Replace Filter - Cab Ventilation	13-Jul-2020 11:54:32	BHVYEQ	N	DON	46.38
29-May-2020 1	4,918	0	442943	03-041-001	Replace Air Cleaner	13-Jul-2020 11:54:55	BHVYEQ	P	DON	71.20
07-Oct-2020 0	5,772	0	465232	03-041-006	Replace Filter - Inner	07-Oct-2020 07:43:27	BHVYEQ	P	DON	25.93
07-Oct-2020 0	5,772	0	465232	03-041-007	Replace Filter - Outer	07-Oct-2020 07:43:51	BHVYEQ	P	DON	22.78
07-Oct-2020 0	5,772	0	465232	03-044-002	Replace Filters	07-Oct-2020 07:44:44	BHVYEQ	P	DON	21.91
07-Oct-2020 0	5,772	0	465232	03-045-011	Replace Filter Assembly - Oil	07-Oct-2020 07:44:09	BHVYEQ	P	DON	16.69
07-Oct-2020 0	5,772	0	465232	07-019-002	Lubricate Grease Pump	07-Oct-2020 07:46:11	BHVYEQ	P	DON	177.35
21-Oct-2020 0	5,873	0	467913	03-045-011	Replace Filter Assembly - Oil	16-Nov-2020 13:07:56	BHVYEQ	P	DON	16.70
21-Oct-2020 0	5,873	0	467913	03-065-008	Replace Line / Tubing Assembly	11-Nov-2020 09:23:18	BHVYEQ	I	DON	376.98
21-Dec-2020 0	6,207	0	478367	02-360	Clean Loader / Skid-Steer	10-Feb-2021 05:20:43	BWASH	N	DON	496.77
21-Dec-2020 0	6,207	0	478367	03-002-035	Replace Windshield Wiper & Washer	28-Jan-2021 12:00:37	BHVYEQ	O	DON	121.54
21-Dec-2020 0	6,207	0	478367	03-045-013	Replace Oil Pan	10-Feb-2021 05:20:46	BHVYEQ	O	DON	1,472.34
21-Dec-2020 0	6,207	0	478367	03-063-001	Replace Antenna - RF	08-Feb-2021 12:51:09	BHVYEQ	W	DON	118.20
21-Dec-2020 0	6,207	0	478367	06-100-PMC	Inspect C PMI	10-Feb-2021 05:25:18	BHVYEQ	P	DON	0.00
21-Dec-2020 0	6,207	0	478367	24-514-004	Repair Edges	22-Dec-2020 11:45:28	BHVYEQ	N	DON	583.20
21-Dec-2020 0	6,207	0	478367	37-049-002	Calibrate ECM Module	08-Feb-2021 12:50:15	BHVYEQ	W	DON	0.00
21-Dec-2020 0	6,207	0	478367	38-100-PMC	Service C PMI	22-Feb-2021 05:36:43	BHVYEQ	P	DON	3,118.36
25-Mar-2021 1	6,217	0	496546	03-049-004	Replace ECM Sensor	25-Mar-2021 12:47:50	BHVYEQ	B	DON	987.88
31-Mar-2021 1		0	497814	03-041-007	Replace Filter - Outer	31-Mar-2021 15:28:32	BHVYEQ	P	DON	52.07
31-Mar-2021 1		0	497814	03-041-006	Replace Filter - Inner	31-Mar-2021 15:28:55	BHVYEQ	P	DON	22.01
31-Mar-2021 1		0	497814	03-044-002	Replace Filters	31-Mar-2021 15:29:41	BHVYEQ	P	DON	42.02

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: P1344 - 2016 CAT 966M										
31-Mar-2021	0	497814	0	03-045-011	Replace Filter Assembly - Oil	31-Mar-2021 15:30:31	BHVEEQ	P	DON	66.42
07-Apr-2021	6,234	499470	0	03-017-001	Replace Tire - Pneumatic	09-Apr-2021 13:50:06	BTIRE	B	DON	2,810.50
25-May-2021	6,374	508802	0	03-044-026	Replace Solenoid - Fuel Control	25-May-2021 07:22:09	BHVEEQ	B	DON	32.09
25-May-2021	6,374	508802	0	24-049-001	Repair ECM Fault Code	25-May-2021 07:09:54	BHVEEQ	B	DON	1,194.19
03-Jun-2021	6,498	510389	0	03-049-001	Replace ECM Fault Code	03-Jun-2021 12:03:12	BHVEEQ	I	DON	192.65
03-Jun-2021	6,498	510389	0	38-100-PMA	Service A PMI	09-Jun-2021 13:00:07	BHVEEQ	I	DON	435.86
03-Jun-2021	6,498	510389	0	06-100-PMA	Inspect A PMI	23-Jun-2021 06:26:55	SCHED	P	DON	0.00
13-Jul-2021	6,650	518265	0	24-049-001	Repair ECM Fault Code	13-Jul-2021 09:25:13	BHVEEQ	B	DON	1,486.10
13-Jul-2021	6,650	518265	0	24-360-013	Repair Ride Control Accumulator	13-Jul-2021 09:27:36	BHVEEQ	O	DON	199.21
16-Jul-2021	6,650	518965	0	03-001-016	Replace Filter - Cab Ventilation	16-Jul-2021 07:22:58	BHVEEQ	O	DON	50.69
16-Jul-2021	6,650	518965	0	03-041-006	Replace Filter - Inner	16-Jul-2021 07:22:47	BHVEEQ	O	DON	26.35
16-Jul-2021	6,650	518965	0	03-041-007	Replace Filter - Outer	16-Jul-2021 07:22:29	BHVEEQ	O	DON	62.66
29-Jul-2021	6,708	521729	0	24-019	Repair Automatic/Manual Chassis Lubricator	30-Jul-2021 07:46:29	BHVEEQ	O	DON	839.91
28-Sep-2021	6,998	534676	0	03-360-009	Replace Bucket Tooth / Cutting Edge	28-Sep-2021 08:33:06	BHVEEQ	E	DON	1,128.68
28-Sep-2021	6,998	534676	0	38-100-PMA	Service A PMI	30-Sep-2021 14:45:48	BHVEEQ	O	DON	188.24
10-Nov-2021	7,118	545600	0	03-052-013	Replace Antenna and Mounting	10-Nov-2021 11:35:51	BHVEEQ	O	DON	55.49
10-Nov-2021	7,118	545600	0	03-019-007	Replace Hose, Tubing & Connectors	10-Nov-2021 11:34:47	BHVEEQ	O	DON	33.46
10-Dec-2021	7,372	552831	0	03-043-020	Replace Pump - DEF	03-Jan-2022 06:22:51	BHVEEQ	W	DON	0.00
10-Dec-2021	7,372	552831	0	03-065-007	Replace Hoses & Fittings	14-Dec-2021 12:00:29	BHVEEQ	I	DON	543.24
10-Dec-2021	7,372	552831	0	03-777-062	Replace Grease Ports - Hydraulic	27-Dec-2021 15:48:40	BHVEEQ	I	DON	900.17
10-Dec-2021	7,372	552831	0	06-100-PMB	Inspect B PMI	27-Dec-2021 15:47:32	BHVEEQ	P	DON	113.84
10-Dec-2021	7,372	552831	0	24-043-030	Repair Aftertreatment Regeneration Device (AR	20-Dec-2021 14:16:40	BHVEEQ	I	DON	2,166.47
10-Dec-2021	7,372	552831	0	37-049-002	Calibrate ECM Module	03-Jan-2022 06:20:23	BHVEEQ	W	DON	0.00
10-Dec-2021	7,372	552831	0	37-930	Calibrate Scale	03-Jan-2022 06:23:19	BHVEEQ	I	DON	393.42
10-Dec-2021	7,372	552831	0	38-100-PMC	Service C PMI	13-Dec-2021 16:15:59	BHVEEQ	I	DON	821.53
22-Dec-2021	7,118	555365	0	02-360	Clean Loader / Skid-Steer	03-Jan-2022 11:00:38	BWASH	N	DON	421.85
08-Feb-2022	7,372	565113	0	24-360-001	Repair Bucket and Attachments	10-Mar-2022 14:13:09	BHVEEQ	B	DON	6,137.09
08-Feb-2022	7,372	565113	0	24-019-002	Repair Grease Pump	10-Mar-2022 14:05:15	BHVEEQ	I	DON	70.48
08-Feb-2022	7,372	565113	0	02-002-044	Clean Cab - Complete	10-Mar-2022 12:01:44	BHVEEQ	I	DON	37.40

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: P1344 - 2016 CAT 966M										
08-Feb-2022 1	7,372	0	565113	03-051-009	Replace Fire Extinguisher	10-Mar-2022 12:45:18	BHVYEQ	Q	DON	50.26
08-Feb-2022 1	7,372	0	565113	03-063-003	Replace Transceiver - GPS Tracker	10-Mar-2022 10:41:33	BHVYEQ	Q	DON	334.34
08-Feb-2022 1	7,372	0	565113	06-100-PMA	Inspect A PMI	10-Mar-2022 11:07:32	BHVYEQ	P	DON	17.93
08-Feb-2022 1	7,372	0	565113	02-360	Clean Loader / Skid-Steer	05-Apr-2022 09:44:26	BWASH	N	DON	196.76
22-Mar-2022 0	7,372	0	577922	03-017-001	Replace Tire - Pneumatic	30-Mar-2022 16:38:03	BTIRE	P	DON	14,337.52
10-Jun-2022 0	7,538	0	594936	06-019-007	Inspect Hose, Tubing & Connectors	15-Jun-2022 14:49:21	BHVYEQ	I	DON	204.48
13-Jul-2022 05	7,688	0	602126	38-100-PMA	Service A PMI	14-Sep-2022 12:42:52	TRK005	P	DON	385.74
13-Jul-2022 05	7,688	0	602126	06-100-PMA	Inspect A PMI	14-Sep-2022 12:42:52	TRK005	P	DON	0.00
14-Sep-2022 1		0	616352	06-100-PMA	Inspect A PMI	15-Sep-2022 08:26:19	SCHED	P	DON	0.00
14-Sep-2022 1		0	616352	38-100-PMA	Service A PMI	15-Sep-2022 08:25:49	TRK001	P	DON	349.27
21-Oct-2022 1		0	626098	03-930-001	Replace Printer	21-Oct-2022 14:33:01	BHVYEQ	O	DON	2,949.66
31-Oct-2022 1	7,927	0	628620	24-043-023	Repair Tank - DEF	31-Oct-2022 15:15:05	BHVYEQ	I	DON	789.37
31-Oct-2022 1	7,927	0	628620	24-930	Repair Scale	31-Oct-2022 15:12:57	BHVYEQ	O	DON	667.74
10-Mar-2023 0	8,112	0	658290	24-514	Repair Bucket	28-Apr-2023 10:27:28	BWELD	I	DON	1,060.75
10-Mar-2023 0	8,112	0	658290	01-360-013	Adjust Ride Control Accumulator	28-Apr-2023 10:34:12	BHVYEQ	I	DON	230.92
10-Mar-2023 0	8,112	0	658290	03-002-002	Replace Fenders	01-May-2023 07:49:55	BHVYEQ	I	DON	319.59
10-Mar-2023 0	8,112	0	658290	03-027-038	Replace Electronic Controls, Transmission, Aut	01-May-2023 09:52:03	BHVYEQ	I	DON	790.69
10-Mar-2023 0	8,112	0	658290	24-043-030	Repair Aftertreatment Regeneration Device (AR	28-Apr-2023 12:04:02	BHVYEQ	I	DON	44.98
10-Mar-2023 0	8,112	0	658290	34-040	Reseal Engine / Motor Systems Group	12-Apr-2023 13:39:08	BHVYEQ	I	DON	126.08
10-Mar-2023 0	8,112	0	658290	03-099-004	Replace Wiring Harness	18-Apr-2023 14:18:12	BHVYEQ	I	DON	267.04
10-Mar-2023 0	8,112	0	658290	B3-049-002	Program ECM Module	01-May-2023 15:19:54	BHVYEQ	W	DON	0.00
10-Mar-2023 0	8,112	0	658290	37-930	Calibrate Scale	01-May-2023 15:20:31	BHVYEQ	N	DON	570.20
10-Mar-2023 0	8,112	0	658290	34-032-002	Reseal Starter	12-Apr-2023 15:25:53	BHVYEQ	I	DON	103.16
10-Mar-2023 0	8,112	0	658290	38-100-PMC	Service C PMI	28-Apr-2023 06:29:35	BHVYEQ	I	DON	1,393.07
10-Mar-2023 0	8,112	0	658290	31-360-009	Rotate Bucket Tooth / Cutting Edge	17-Apr-2023 16:19:58	BHVYEQ	I	DON	202.37
10-Mar-2023 0	8,112	0	658290	06-100-PMA	Inspect A PMI	01-May-2023 15:18:38	BHVYEQ	P	DON	197.89
10-Mar-2023 0	8,112	0	658290	34-010-001	Reseal All Axles	20-Apr-2023 10:16:01	BHVYEQ	I	DON	3,141.86
10-Mar-2023 0	8,112	0	658290	03-065-007	Replace Hoses & Fittings	20-Apr-2023 16:17:55	BHVYEQ	I	DON	5,562.43
10-Mar-2023 0	8,112	0	658290	03-360-012	Replace Heel Plate	10-Mar-2023 11:25:00	BHVYEQ	I	DON	427.92

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: P1344 - 2016 CAT 966M										
10-Mar-2023 0	8,112	0	658290	03-031-006	Replace Belt - Alternator	10-Mar-2023 08:51:39	BHVEQ	I	DON	116.34
10-Mar-2023 0	8,112	0	658290	03-019-001	Replace Reservoir & Lines	10-Apr-2023 14:35:33	BHVEQ	I	DON	1,588.52
10-Mar-2023 0	8,112	0	658290	03-052-013	Replace Antenna and Mounting	10-Mar-2023 08:16:48	BHVEQ	I	DON	41.87
10-Mar-2023 0	8,112	0	658290	34-027-043	Reseal Seal - Output	18-Apr-2023 12:02:37	BHVEQ	I	DON	259.87
10-Mar-2023 1		0	658470	02-360	Clean Loader / Skid-Steer	25-Apr-2023 09:05:09	BWASH	N	DON	550.85
25-May-2023 1		0	734950	38-100-PMA	Service A PMI	25-May-2023 08:00:00	C00152	N	DON	55.80
05-Jul-2023 08	8,217	0	685770	03-044-002	Replace Filters	05-Jul-2023 08:02:50	BHVEQ	O	DON	165.24
05-Jul-2023 08	8,217	0	685770	03-045-011	Replace Filter Assembly - Oil	05-Jul-2023 08:01:07	BHVEQ	O	DON	263.40
18-Jul-2023 15	8,333	0	690751	24-017-001	Repair Tire - Pneumatic	25-Jul-2023 07:27:23	BTIRE	B	DON	731.00
26-Oct-2023 0:	8,568	0	715798	06-019-002	Inspect Grease Pump	28-Oct-2023 09:01:03	TRK005	I	DON	634.04
26-Oct-2023 0:	8,568	0	715798	24-019-002	Repair Grease Pump	30-Oct-2023 09:29:09	TRK005	I	DON	151.93
16-Nov-2023 1	8,608	0	721085	06-065	Inspect Hydraulic Systems - Special Application		TRK005	I	CAN	0.00
01-Mar-2024 1		0	742538	OS-360	Out-Service Loader / Skid-Steer	07-Mar-2024 10:56:14	BHVEQ	Z	DON	204.96
01-Mar-2024 1		0	742538	02-360	Clean Loader / Skid-Steer	07-Mar-2024 09:16:52	BWASH	Z	DON	451.78

Unit No: P1344

Count: 159

92,643.04