

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Q1397 - 2020 JOHN DEERE 310SL										
26-Mar-2020	0	7	432935	01-310	Adjust Backhoe (Rubber Tire)	02-Apr-2020 05:35:36	BBKHOE	Q	DON	9.36
26-Mar-2020	0	7	432935	14-059-002	Install Pintle Hook Assembly	27-Mar-2020 07:45:03	BBKHOE	Q	DON	61.95
26-Mar-2020	0	7	432935	14-063-003	Install Transceiver - GPS Tracker	01-Apr-2020 15:45:02	BBKHOE	Q	DON	288.97
26-Mar-2020	0	7	432935	14-065-007	Install Hoses & Fittings	27-Mar-2020 15:47:39	BBKHOE	Q	DON	237.35
26-Mar-2020	0	7	432935	14-017-011	Install Tire - Foam Filled	02-Apr-2020 06:39:34	BBKHOE	Q	DON	919.08
26-Mar-2020	0	7	432935	14-034-006	Install Warning Lamps - Special Application	27-Mar-2020 15:48:21	BBKHOE	Q	DON	317.24
26-Mar-2020	0	7	432935	14-051	Install General Accessories	03-Apr-2020 05:31:35	BBKHOE	Q	DON	29.27
26-Mar-2020	0	7	432935	14-051-009	Install Fire Extinguisher	27-Mar-2020 10:48:31	BBKHOE	Q	DON	43.00
26-Mar-2020	0	7	432935	14-052-003	Install Radio Equipment	01-Apr-2020 17:00:26	BBKHOE	Q	DON	760.45
26-Mar-2020	0	7	432935	26-053-005	Weld Markings - Vehicle - Decals	27-Mar-2020 07:23:13	BBKHOE	Q	DON	8.47
06-Apr-2020	1	4	434612	14-051-009	Install Fire Extinguisher	06-Apr-2020 14:41:49	LAVSHP	O	DON	89.96
15-May-2020	1	204	441048	03-065-020	Replace Control Valve	27-May-2020 06:49:38	ROGSHP	I	DON	0.00
15-May-2020	1	204	441048	03-094-011	Replace Coupler - Quick Disconnect	18-May-2020 10:46:38	ROGSHP	N	DON	201.37
15-May-2020	1	204	441048	06-100-PMB	Inspect B PMI	18-May-2020 10:23:58	ROGSHP	P	DON	76.63
15-May-2020	1	204	441048	38-100-PMB	Service B PMI	18-May-2020 10:55:50	ROGSHP	P	DON	178.03
21-Jul-2020	09	520	451682	06-100-PMA	Inspect A PMI	04-Aug-2020 06:27:18	ROGSHP	P	DON	0.00
21-Jul-2020	09	520	451682	38-100-PMA	Service A PMI	21-Jul-2020 10:28:43	ROGSHP	P	DON	289.19
05-Aug-2020	1	530	454410	03-310-003	Replace Boom Pins	05-Aug-2020 12:26:24	ROGSHP	O	DON	27.87
08-Aug-2020	1	590	455082	03-052-003	Replace Radio Equipment	08-Aug-2020 17:18:57	ELEC03	I	DON	547.82
13-Oct-2020	0	805	466162	01-042-014	Adjust Coolant Overflow Reservoir	13-Oct-2020 06:20:33	ROGSHP	P	DON	20.61
19-Oct-2020	1	850	467362	06-100-PMA	Inspect A PMI	22-Oct-2020 06:53:21	ROGSHP	P	DON	0.00
19-Oct-2020	1	850	467362	38-100-PMA	Service A PMI	20-Oct-2020 08:38:15	ROGSHP	P	DON	300.20
03-Dec-2020	0	993	474858	03-026-016	Replace Gear Shifter & Linkage	03-Dec-2020 06:59:43	ROGSHP	W	DON	296.42
12-Jan-2021	1	1,160	481598	06-100-PMA	Inspect A PMI	14-Jan-2021 15:21:17	ROGSHP	P	DON	0.00
12-Jan-2021	1	1,160	481598	24-018	Repair Wheels, Rims, Hubs & Bearings	14-Jan-2021 15:21:47	ROGSHP	B	DON	118.19
12-Jan-2021	1	1,160	481598	38-100-PMA	Service A PMI	14-Jan-2021 16:15:29	ROGSHP	P	DON	257.22
11-Feb-2021	0	1,279	487525	03-017-011	Replace Tire - Foam Filled	24-Feb-2021 14:31:38	ROGSHP	I	DON	1,837.37
11-Feb-2021	0	1,279	487525	03-045-010	Replace Oil Filler & Level Indicator	15-Feb-2021 12:01:54	ROGSHP	I	DON	49.24
11-Feb-2021	0	1,279	487525	06-100-PMA	Inspect A PMI	12-Feb-2021 07:31:52	ROGSHP	P	DON	0.00

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Q1397 - 2020 JOHN DEERE 310SL										
11-Feb-2021 0:	1,279	0	487525	06-706-001	Inspect Engine	11-Feb-2021 10:05:14	ROGSHP	O	DON	16.26
11-Feb-2021 0:	1,279	0	487525	24-053-008	Repair Hoses & Tubings & Fittings	11-Feb-2021 13:58:47	ROGSHP	I	DON	20.19
11-Feb-2021 0:	1,279	0	487525	24-752-003	Repair Grease System	11-Feb-2021 13:31:14	ROGSHP	I	DON	21.23
11-Feb-2021 0:	1,279	0	487525	38-100-PMA	Service A PMI	11-Feb-2021 13:11:23	ROGSHP	P	DON	338.50
19-Apr-2021 0	1,484	0	501387	03-045-026	Replace Tensioner - Engine Belts	28-Apr-2021 11:33:25	ROGSHP	N	DON	215.09
19-Apr-2021 0	1,484	0	501387	03-310-001	Replace Boom (Main)	28-Apr-2021 09:52:25	ROGSHP	E	DON	6,587.18
14-May-2021 1	1,558	0	506810	06-100-PMA	Inspect A PMI	27-May-2021 06:53:05	SCHEDE	P	DON	0.00
14-May-2021 1	1,558	0	506810	38-100-PMA	Service A PMI	17-May-2021 09:57:06	TRK401	P	DON	168.23
09-Aug-2021 C	1,872	0	523815	03-045-010	Replace Oil Filler & Level Indicator	10-Aug-2021 08:24:33	ME1371	I	DON	115.82
09-Aug-2021 C	1,872	0	523815	06-100-PMA	Inspect A PMI	09-Aug-2021 09:43:56	ME1371	P	DON	27.31
09-Aug-2021 C	1,872	0	523815	24-065-001	Repair Hydraulic Systems	10-Aug-2021 08:30:15	ME1371	I	DON	28.03
09-Aug-2021 C	1,872	0	523815	38-100-PMA	Service A PMI	09-Aug-2021 09:28:05	ME1371	P	DON	129.27
23-Aug-2021 1	1,926	0	526869	03-017-001	Replace Tire - Pneumatic	31-Aug-2021 14:47:13	LAVSHP	O	DON	2,304.89
06-Dec-2021 0	2,340	0	551286	38-100-PMA	Service A PMI	06-Dec-2021 09:47:52	OTSSHP	P	DON	319.01
06-Dec-2021 0	2,340	0	551286	06-100-PMA	Inspect A PMI	06-Dec-2021 07:36:13	OTSSHP	P	DON	55.28
06-Dec-2021 0	2,340	0	551286	24-065-001	Repair Hydraulic Systems	06-Dec-2021 09:56:33	OTSSHP	I	DON	26.41
06-Dec-2021 0	2,340	0	551286	01-506-002	Adjust Hydraulic Tank	06-Dec-2021 09:56:36	OTSSHP	I	DON	0.62
06-Dec-2021 0	2,340	0	551286	02-042-002	Clean Radiator	06-Dec-2021 09:56:29	OTSSHP	I	DON	0.51
06-Dec-2021 0	2,340	0	551286	03-051-009	Replace Fire Extinguisher	06-Dec-2021 09:56:25	OTSSHP	I	DON	228.59
28-Dec-2021 1	2,440	0	555925	03-051-009	Replace Fire Extinguisher	29-Dec-2021 08:52:26	OTSSHP	I	DON	252.60
28-Dec-2021 1	2,440	0	555925	06-017-001	Inspect Tire - Pneumatic	28-Dec-2021 11:29:00	OTSSHP	O	DON	45.27
28-Dec-2021 1	2,440	0	555925	06-065-007	Inspect Hoses & Fittings	28-Dec-2021 13:11:51	OTSSHP	O	DON	51.59
28-Dec-2021 1	2,440	0	555925	24-017-001	Repair Tire - Pneumatic	28-Dec-2021 15:39:30	OTSSHP	I	DON	91.95
28-Dec-2021 1	2,440	0	555925	24-065-007	Repair Hoses & Fittings	29-Dec-2021 14:14:48	OTSSHP	I	DON	341.75
10-Feb-2022 0	2,611	0	565491	01-310-017	Adjust Cutting Edges	10-Feb-2022 10:55:01	OTSSHP	I	DON	26.00
10-Feb-2022 0	2,611	0	565491	03-051-009	Replace Fire Extinguisher	10-Feb-2022 07:30:22	OTSSHP	I	DON	62.81
10-Feb-2022 0	2,611	0	565491	03-310-007	Replace Outrigger Pads	10-Feb-2022 08:00:09	OTSSHP	I	DON	290.58
10-Feb-2022 0	2,611	0	565491	06-100-PMA	Inspect A PMI	10-Feb-2022 07:29:12	OTSSHP	P	DON	52.39
10-Feb-2022 0	2,611	0	565491	38-100-PMA	Service A PMI	10-Feb-2022 10:19:32	OTSSHP	P	DON	372.89

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Q1397 - 2020 JOHN DEERE 310SL										
26-May-2022	1	2,967	0	591691	06-100-PMA Inspect A PMI	27-May-2022 09:12:13	TRK401	P	DON	133.42
26-May-2022	1	2,967	0	591691	03-043-025 Replace Filter - DEF	27-May-2022 10:28:31	TRK401	P	DON	103.31
26-May-2022	1	2,967	0	591691	38-100-PMA Service A PMI	31-May-2022 07:43:02	TRK401	P	DON	167.08
29-Jun-2022	0	3,130	0	599313	03-017-011 Replace Tire - Foam Filled	25-Jul-2022 07:18:18	TRK400	I	DON	2,711.63
29-Jun-2022	0	3,130	0	599313	03-094-011 Replace Coupler - Quick Disconnect	29-Jun-2022 11:38:33	TRK400	I	DON	188.60
29-Jun-2022	0	3,130	0	599313	06-017-011 Inspect Tire - Foam Filled	29-Jun-2022 10:44:25	TRK400	P	DON	47.77
29-Jun-2022	0	3,130	0	599313	14-017-011 Install Tire - Foam Filled	29-Jun-2022 11:21:05	TRK400	I	DON	59.54
19-Aug-2022	1	3,397	0	610803	06-100-PMA Inspect A PMI	19-Aug-2022 15:07:35	TRK400	P	DON	58.76
19-Aug-2022	1	3,397	0	610803	38-100-PMA Service A PMI	19-Aug-2022 15:37:26	TRK400	I	DON	101.29
08-Sep-2022	0	3,479	0	614754	01-042-014 Adjust Coolant Overflow Reservoir	08-Sep-2022 07:06:52	LAVSHP	P	DON	23.65
27-Sep-2022	1	3,566	0	619644	03-017-001 Replace Tire - Pneumatic	30-Sep-2022 13:34:00	LAVSHP	O	DON	2,885.57
03-Nov-2022	1	3,791	0	629617	06-100-PMA Inspect A PMI	04-Nov-2022 09:30:24	TRK401	P	DON	164.85
03-Nov-2022	1	3,791	0	629617	38-100-PMA Service A PMI	04-Nov-2022 09:43:27	TRK401	P	DON	200.72
09-Nov-2022	1	3,815	0	631085	06-268-027 Inspect Operator Controls	09-Nov-2022 12:19:40	TRK401	O	DON	189.80
13-Dec-2022	1	4,018	0	639094	03-043-023 Replace Tank - DEF	14-Dec-2022 11:07:00	LAVSHP	W	DON	0.00
13-Dec-2022	1	4,018	0	639094	03-043-029 Replace Sensor - DEF	14-Dec-2022 11:07:00	LAVSHP	W	DON	0.00
13-Dec-2022	1	4,018	0	639094	24-094 Repair Lines, Tubes, Hoses & Fittings - Bulk Pr	14-Dec-2022 11:07:00	LAVSHP	I	DON	1,133.24
13-Dec-2022	1	4,018	0	639094	95-MSC-004 Travel Travel Time - To/From Job Site	14-Dec-2022 11:07:00	LAVSHP	B	DON	224.44
21-Dec-2022	1	4,062	0	640844	03-044-024 Replace Fuel / Water Separator	21-Dec-2022 12:32:15	MEI371	I	DON	150.93
21-Dec-2022	1	4,062	0	640844	95-MSC-004 Travel Travel Time - To/From Job Site	21-Dec-2022 12:02:28	MEI371	I	DON	129.67
22-Dec-2022	0	4,062	0	641103	01-065-001 Adjust Hydraulic Systems	04-Jan-2023 08:53:17	OTSSHP	I	DON	45.86
22-Dec-2022	0	4,062	0	641103	03-034-002 Replace Stop, Tail, Turn & License	04-Jan-2023 09:39:52	OTSSHP	I	DON	0.00
22-Dec-2022	0	4,062	0	641103	03-514-002 Replace Shanks or Teeth	04-Jan-2023 08:28:05	OTSSHP	E	DON	55.62
22-Dec-2022	0	4,062	0	641103	06-100-PMA Inspect A PMI	04-Jan-2023 08:53:06	OTSSHP	P	DON	24.01
22-Dec-2022	0	4,062	0	641103	24-310-006 Repair Outriggers	04-Jan-2023 08:18:24	OTSSHP	O	DON	272.69
22-Dec-2022	0	4,062	0	641103	38-100-PMA Service A PMI	04-Jan-2023 08:06:54	OTSSHP	P	DON	275.27
07-Apr-2023	0	4,360	0	665253	06-100-PMA Inspect A PMI	07-Apr-2023 09:07:27	TRK400	P	DON	43.39
07-Apr-2023	0	4,360	0	665253	38-100-PMA Service A PMI	07-Apr-2023 09:59:04	TRK400	I	DON	136.94
07-Apr-2023	0	4,360	0	665253	95-MSC-004 Travel Travel Time - To/From Job Site	07-Apr-2023 09:59:24	TRK400	I	DON	56.51

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Q1397 - 2020 JOHN DEERE 310SL										
11-Apr-2023 0	4,362	0	666084	03-268-014	Replace Leveling Assembly	14-Apr-2023 09:02:10	TRK401	O	DON	481.62
11-Apr-2023 0	4,362	0	666084	03-310-016	Replace Operator Controls	12-Apr-2023 14:01:14	TRK401	I	DON	699.51
11-Apr-2023 0	4,362	0	666084	06-268-003	Inspect Hydraulics	11-Apr-2023 09:50:58	TRK401	O	DON	37.53
11-Apr-2023 0	4,362	0	666084	95-MSC-004	Travel Travel Time - To/From Job Site	12-Apr-2023 12:39:01	TRK401	B	DON	150.99
17-Apr-2023 1	4,381	0	667611	03-053-008	Replace Hoses & Tubings & Fittings	17-Apr-2023 13:15:39	OTSSHP	B	DON	571.87
20-Apr-2023 0	4,393	0	668599	06-100-PMC	Inspect C PMI	20-Apr-2023 11:06:49	ME1371	P	DON	110.64
20-Apr-2023 0	4,393	0	668599	38-100-PMC	Service C PMI	21-Apr-2023 09:32:33	ME1371	P	DON	457.58
20-Apr-2023 0	4,393	0	668599	95-MSC-004	Travel Travel Time - To/From Job Site	21-Apr-2023 09:13:41	ME1371	I	DON	80.66
20-Jul-2023 09	4,624	0	689703	03-002-037	Replace Seat Assembly	26-Jul-2023 10:10:12	TRK401	I	DON	1,540.91
20-Jul-2023 09	4,624	0	689703	06-100-PMA	Inspect A PMI	20-Jul-2023 11:05:22	TRK401	P	DON	85.95
20-Jul-2023 09	4,624	0	689703	38-100-PMA	Service A PMI	20-Jul-2023 11:21:29	TRK401	P	DON	87.50
20-Jul-2023 09	4,624	0	689703	95-MSC-004	Travel Travel Time - To/From Job Site	26-Jul-2023 08:17:31	TRK401	P	DON	312.21
05-Sep-2023 1	4,676	0	702634	03-051-009	Replace Fire Extinguisher	05-Sep-2023 16:59:37	OTSSHP	Q	DON	103.86
27-Sep-2023 0	4,680	0	708337	03-001-016	Replace Filter - Cab Ventilation	27-Sep-2023 10:29:15	OTSSHP	N	DON	67.96
27-Sep-2023 0	4,680	0	708337	03-310-017	Replace Cutting Edges	27-Sep-2023 09:49:26	OTSSHP	N	DON	376.30
27-Sep-2023 0	4,680	0	708337	24-002-025	Repair Glass Channels	02-Oct-2023 12:35:07	OTSSHP	O	DON	154.14
14-Nov-2023 C	4,725	0	720287	24-043-023	Repair Tank - DEF	14-Nov-2023 11:02:09	TRK400	O	DON	156.41
14-Nov-2023 C	4,725	0	720287	95-MSC-004	Travel Travel Time - To/From Job Site	28-Nov-2023 13:43:44	TRK400	I	DON	113.04
14-Nov-2023 C	4,725	0	720287	03-094-011	Replace Coupler - Quick Disconnect	28-Nov-2023 14:03:57	TRK400	O	DON	29.47
19-Dec-2023 0	0	0	727815	02-310	Clean Backhoe (Rubber Tire)	29-Dec-2023 11:36:45	BWASH	N	DON	421.80
19-Dec-2023 0	0	0	727815	03-514	Replace Bucket	20-Feb-2024 07:07:49	BBKHOE	Z	DON	37.76
19-Dec-2023 0	0	0	727815	06-100-PMC	Inspect C PMI	20-Feb-2024 07:07:45	BBKHOE	P	DON	101.62
19-Dec-2023 0	0	0	727815	OS-310	Out-Service Backhoe (Rubber Tire)	20-Feb-2024 07:07:48	BBKHOE	Z	DON	222.82

Unit No: Q1397

Count: 110

35,142.23