

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Y8471 - 2007 MQ DCA70SSJU2										
11-Oct-2010 1	0	0	51706	06-100-001	Inspect DO NOT USE - PMI Service	27-Oct-2010 09:00:00	BSMEQP	J	DON	1,780.29
11-Oct-2010 1	0	0	51706	21-509-002	Fabricate Safety Guard	25-Oct-2010 15:00:00	BDDRJL	I	DON	130.72
13-Oct-2010 1	0	0	56197	03-030	Replace Electrical Group	14-Oct-2010 14:31:04	BVLOFC	C	DON	382.55
21-Oct-2010 1	0	0	56267	19-030	Wire/Rewire Electrical Group	04-Nov-2010 13:42:31	BVLOFC	C	DON	4,731.44
30-Nov-2010 C	0	0	66980	03-030	Replace Electrical Group	30-Nov-2010 08:40:14	BVLOFC	C	DON	108.67
23-Aug-2013 C	0	0	129916	03-063-003	Replace Transceiver - GPS Tracker	23-Aug-2013 00:00:00	GPSINS	C	DON	244.36
28-Aug-2014 C	10,569	0	170741	02-062	Clean Mobile Air Compressor	08-Sep-2014 17:00:10	BWASH	J	DON	23.57
28-Aug-2014 C	10,569	0	170741	03-032-001	Replace Battery	04-Sep-2014 11:47:34	BSMEQP	I	DON	210.66
28-Aug-2014 C	10,569	0	170741	06-064-001	Inspect Portable Generator Assembly	16-Sep-2014 09:46:39	BSMEQP	P	DON	433.41
28-Aug-2014 C	10,569	0	170741	24-040	Repair Engine / Motor Systems Group	08-Sep-2014 11:04:29	BSMEQP	I	DON	794.82
28-Aug-2014 C	10,569	0	170741	38-040	Service Engine / Motor Systems Group	16-Sep-2014 09:46:42	BSMEQP	J	DON	1,349.86
02-Mar-2015 1	10,571	0	193064	03-044-003	Replace Fuel Pump	31-Mar-2015 16:20:53	BSMEQP	I	DON	379.37
02-Mar-2015 1	10,571	0	193064	06-064-001	Inspect Portable Generator Assembly	31-Mar-2015 16:29:53	BSMEQP	P	DON	135.99
02-Mar-2015 1	10,571	0	193064	24-040	Repair Engine / Motor Systems Group	06-Mar-2015 14:09:03	BSMEQP	I	DON	2,293.54
02-Mar-2015 1	10,571	0	193064	35-040	Diagnose Engine / Motor Systems Group	03-Mar-2015 15:51:29	BSMEQP	O	DON	170.89
14-Sep-2015 1	11,354	0	214588	03-044-003	Replace Fuel Pump	02-Oct-2015 07:55:06	BSMEQP	I	DON	127.73
14-Sep-2015 1	11,354	0	214588	06-064-001	Inspect Portable Generator Assembly	02-Oct-2015 07:56:57	BSMEQP	P	DON	168.62
14-Sep-2015 1	11,354	0	214588	12-524	Refinish Enclosure	18-Sep-2015 09:15:01	BBODY	C	DON	177.55
14-Sep-2015 1	11,354	0	214588	14-064-001	Install Portable Generator Assembly	29-Sep-2015 12:00:01	BSMEQP	C	DON	155.46
14-Sep-2015 1	11,354	0	214588	15-524	Paint Prep Enclosure	21-Sep-2015 07:33:32	BSAND	C	DON	190.58
14-Sep-2015 1	11,354	0	214588	21-524	Fabricate Enclosure	16-Sep-2015 14:59:41	BWELD	C	DON	947.72
14-Sep-2015 1	11,354	0	214588	24-040	Repair Engine / Motor Systems Group	18-Sep-2015 16:46:21	BSMEQP	I	DON	274.88
14-Sep-2015 1	11,354	0	214588	24-064-004	Repair Wiring - High Voltage	02-Oct-2015 07:54:54	BSMEQP	I	DON	85.00
14-Sep-2015 1	11,354	0	214588	38-040	Service Engine / Motor Systems Group	17-Sep-2015 14:53:55	BSMEQP	J	DON	2,317.38
22-Jan-2016 11	11,836	0	230344	03-042-006	Replace Thermostat	28-Jan-2016 15:37:54	BSMEQP	I	DON	119.63
22-Jan-2016 11	11,836	0	230344	03-045-023	Replace Engine Belts	28-Jan-2016 14:08:32	BSMEQP	I	DON	170.37
22-Jan-2016 11	11,836	0	230344	06-064-001	Inspect Portable Generator Assembly	29-Jan-2016 11:28:46	BSMEQP	Q	DON	197.16
22-Jan-2016 11	11,836	0	230344	24-064-001	Repair Portable Generator Assembly	27-Jan-2016 16:35:22	BSMEQP	I	DON	71.17
22-Jan-2016 11	11,836	0	230344	38-045-020	Service Engine Assembly	25-Jan-2016 08:48:52	BSMEQP	J	DON	359.17

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Y8471 - 2007 MQ DCA70SSJU2										
18-Jul-2016 13	12,318	0	252296	06-100-PMA	Inspect A PMI	22-Jul-2016 15:40:14	BSMEQP	P	DON	194.79
18-Jul-2016 13	12,318	0	252296	38-045-020	Service Engine Assembly	26-Jul-2016 07:57:45	BSMEQP	J	DON	253.46
18-Oct-2016 04	12,685	0	263366	03-003-007	Replace Voltmeter / Ammeter	19-Oct-2016 14:16:34	BSMEQP	I	DON	65.48
18-Oct-2016 04	12,685	0	263366	03-044-013	Replace Cap - Fuel Tank	18-Oct-2016 10:01:35	BSMEQP	I	DON	22.13
18-Oct-2016 04	12,685	0	263366	06-100-PMA	Inspect A PMI	19-Oct-2016 16:20:51	BSMEQP	P	DON	124.47
18-Oct-2016 04	12,685	0	263366	06-100-PMB	Inspect B PMI	18-Oct-2016 06:38:00	BSMEQP	P	DON	0.00
01-Aug-2018 C	14,640	0	346275	03-053-005	Replace Markings - Vehicle - Decals	10-Aug-2018 14:45:49	BSMEQP	Q	DON	40.08
01-Aug-2018 C	14,640	0	346275	06-100-PMA	Inspect A PMI	15-Aug-2018 10:35:12	BSMEQP	P	DON	351.65
01-Aug-2018 C	14,640	0	346275	06-100-PMB	Inspect B PMI	02-Aug-2018 15:51:02	BSMEQP	P	DON	0.00
01-Aug-2018 C	14,640	0	346275	24-040	Repair Engine / Motor Systems Group	10-Aug-2018 13:41:16	BSMEQP	I	DON	924.56
01-Aug-2018 C	14,640	0	346275	24-064-004	Repair Wiring - High Voltage	13-Aug-2018 08:35:25	BSMEQP	I	DON	109.13
01-Aug-2018 C	14,640	0	346275	38-040	Service Engine / Motor Systems Group	13-Aug-2018 08:35:16	BSMEQP	P	DON	193.54
18-Aug-2020 C		0	456648	06-100-PMA	Inspect A PMI	18-Aug-2020 09:51:55	LAVSHP	P	DON	46.21
18-Aug-2020 C		0	456648	38-100-PMA	Service A PMI	18-Aug-2020 12:02:16	LAVSHP	P	DON	135.11
21-Apr-2021 I		0	501892	02-064	Clean Mobile Generator / Gensets	26-Apr-2021 11:09:44	BWASH	N	DON	171.21
21-Apr-2021 I		0	501892	03-031-001	Replace Generator/Alternator	22-Apr-2021 17:00:02	BSMEQP	I	DON	246.37
21-Apr-2021 I		0	501892	03-032-001	Replace Battery	21-Apr-2021 14:45:48	BSMEQP	I	DON	152.84
21-Apr-2021 I		0	501892	03-042-013	Replace Fan Belt	22-Apr-2021 13:55:33	BSMEQP	I	DON	239.22
21-Apr-2021 I		0	501892	03-063-003	Replace Transceiver - GPS Tracker	22-Apr-2021 08:16:18	BSMEQP	Q	DON	408.04
21-Apr-2021 I		0	501892	06-100-PMB	Inspect B PMI	26-Apr-2021 13:49:08	BSMEQP	P	DON	486.83
21-Apr-2021 I		0	501892	12-071-005	Refinish Side Door Assembly - Hinged	26-Apr-2021 09:47:07	BSETUP	I	DON	44.45
21-Apr-2021 I		0	501892	24-040	Repair Engine / Motor Systems Group	26-Apr-2021 11:09:40	BSMEQP	I	DON	58.04
21-Apr-2021 I		0	501892	38-040	Service Engine / Motor Systems Group	23-Apr-2021 11:11:59	BSMEQP	P	DON	205.03
16-Aug-2021 C	16,782	0	525223	02-064	Clean Mobile Generator / Gensets	17-Aug-2021 08:58:35	BWASH	N	DON	93.36
16-Aug-2021 C	16,782	0	525223	06-100-PMB	Inspect B PMI	18-Aug-2021 14:35:43	BSMEQP	P	DON	241.02
16-Aug-2021 C	16,782	0	525223	38-040	Service Engine / Motor Systems Group	16-Aug-2021 14:06:58	BSMEQP	P	DON	148.35
01-Feb-2022 I	16,784	0	563350	06-100-PMA	Inspect A PMI	07-Mar-2022 08:56:20	BDDRIL	P	DON	77.63
01-Feb-2022 I	16,784	0	563350	25-014-001	Remove Frame Assembly	07-Mar-2022 08:56:24	BDDRIL	I	DON	77.63
13-Sep-2022 I	17,161	0	616065	38-100-PMA	Service A PMI	13-Sep-2022 13:43:00	DRLFLD	P	DON	0.00

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Y8471 - 2007 MQ DCA70SSJU2										
27-Jan-2023 05	0	648547	03-045-011	03-045-011	Replace Filter Assembly - Oil	27-Jan-2023 09:49:19	BDDRIL	O	DON	44.88
01-May-2023 0	0	671226	06-100-PMB	06-100-PMB	Inspect B PMI		PERSHP	P	WR	0.00
08-Sep-2023 0	0	704018	06-100-PMA	06-100-PMA	Inspect A PMI	11-Sep-2023 07:57:00	SCHED	P	DON	0.00
08-Sep-2023 0	0	704018	38-100-PMA	38-100-PMA	Service A PMI	11-Sep-2023 08:00:03	DRLFLD	P	DON	87.46
28-Sep-2023 1	0	708777	03-044-003	03-044-003	Replace Fuel Pump	03-Oct-2023 13:42:58	BDDRIL	O	DON	120.77
01-Oct-2023 1	0	709925	06-100-PMB	06-100-PMB	Inspect B PMI	03-Oct-2023 10:39:00	SCHED	P	DON	0.00
01-Oct-2023 1	0	709925	38-100-PMA	38-100-PMA	Service A PMI	03-Oct-2023 10:37:41	DRLFLD	P	DON	87.46
05-Dec-2023 1	0	724922	06-100-PMB	06-100-PMB	Inspect B PMI	02-Jan-2024 16:17:15	BDDRIL	P	DON	66.81
05-Dec-2023 1	0	724922	24-064-002	24-064-002	Repair Genset (on mobile chassis)	02-Jan-2024 16:17:43	BDDRIL	N	DON	2,037.98
05-Dec-2023 1	0	724922	38-100-PMA	38-100-PMA	Service A PMI	02-Jan-2024 16:17:18	BDDRIL	P	DON	156.17

Unit No: Y8471

Count: 68

26,244.74