

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: P1493 - 2019 CAT 972M										
31-Jan-2020	13	0	424112	12-360	Refinish Loader / Skid-Steer	25-Mar-2020 06:07:53	BBODY	K	DON	0.00
31-Jan-2020	13	0	424112	14-019-001	Install Reservoir & Lines	19-Feb-2020 12:00:49	BHVYEQ	N	DON	94.04
31-Jan-2020	13	0	424112	14-051-009	Install Fire Extinguisher	19-Feb-2020 10:43:56	BHVYEQ	Q	DON	54.30
31-Jan-2020	13	0	424112	14-052-005	Install Transmitter - CB	19-Feb-2020 10:28:09	BHVYEQ	Q	DON	87.60
31-Jan-2020	13	0	424112	14-063-003	Install Transceiver - GPS Tracker	19-Feb-2020 09:40:56	BHVYEQ	Q	DON	366.22
31-Jan-2020	13	0	424112	15-360	Paint Prep Loader / Skid-Steer	25-Mar-2020 06:07:52	BBODY	K	DON	0.00
31-Jan-2020	13	0	424112	26-514-003	Weld Liner	06-Mar-2020 08:40:15	BWELD	Q	DON	4,073.49
19-Mar-2020	28	0	432726	03-017-001	Replace Tire - Pneumatic	27-Mar-2020 14:15:05	BTIRE	P	DON	15,649.25
27-Mar-2020	38	0	433303	03-041-006	Replace Filter - Inner	27-Mar-2020 14:13:26	BHVYEQ	P	DON	21.83
27-Mar-2020	38	0	433303	03-041-007	Replace Filter - Outer	27-Mar-2020 14:13:31	BHVYEQ	P	DON	49.37
27-Mar-2020	38	0	433303	03-044-002	Replace Filters	27-Mar-2020 14:13:20	BHVYEQ	P	DON	44.13
27-Mar-2020	38	0	433303	03-045-011	Replace Filter Assembly - Oil	01-Apr-2020 07:44:39	BHVYEQ	P	DON	36.69
15-Jun-2020	282	0	445669	03-002-024	Replace Glass / Windshield	30-Jun-2020 06:42:48	BHVYEQ	E	DON	378.80
15-Jun-2020	282	0	445669	03-044-002	Replace Filters	02-Jul-2020 10:23:41	BHVYEQ	P	DON	88.21
04-Aug-2020	439	0	454298	03-001-016	Replace Filter - Cab Ventilation	04-Aug-2020 15:44:26	BHVYEQ	P	DON	105.53
04-Aug-2020	439	0	454298	03-041-006	Replace Filter - Inner	04-Aug-2020 15:44:16	BHVYEQ	P	DON	43.83
04-Aug-2020	439	0	454298	03-041-007	Replace Filter - Outer	04-Aug-2020 15:44:21	BHVYEQ	P	DON	99.20
21-Aug-2020	497	0	457393	03-044-002	Replace Filters	21-Aug-2020 09:38:10	BHVYEQ	P	DON	107.54
03-Sep-2020	601	0	459882	03-049-004	Replace ECM Sensor	03-Sep-2020 12:53:46	BHVYEQ	O	DON	139.97
30-Sep-2020	1,104	0	464206	24-049-003	Repair ECM Wiring Harness	30-Sep-2020 16:04:13	BHVYEQ	W	DON	484.14
09-Nov-2020	1,104	0	470910	03-360-009	Replace Bucket Tooth / Cutting Edge	09-Nov-2020 05:46:37	BHVYEQ	E	DON	1,055.79
21-Dec-2020	0	0	478338	06-360	Inspect Loader / Skid-Steer	07-Jan-2021 06:18:20	BHVYEQ	P	DON	531.53
21-Dec-2020	0	0	478338	24-514-004	Repair Edges	23-Dec-2020 17:00:51	BWELD	N	DON	185.72
21-Dec-2020	0	0	478338	38-100-PMC	Service C PMI	07-Jan-2021 06:18:21	BHVYEQ	P	DON	672.18
15-Feb-2021	0	0	488165	24-027-043	Repair Seal - Output	15-Feb-2021 09:45:56	BHVYEQ	W	DON	203.27
18-Feb-2021	1,537	0	488849	03-045-011	Replace Filter Assembly - Oil	18-Feb-2021 07:34:21	BHVYEQ	P	DON	15.90
04-Mar-2021	1,628	0	491691	03-063-001	Replace Antenna - RF	04-Mar-2021 06:13:32	BHVYEQ	W	DON	0.00
04-Mar-2021	1,628	0	491691	24-042-012	Repair Clamps and Hoses	04-Mar-2021 06:12:13	BHVYEQ	W	DON	0.00
04-Mar-2021	1,628	0	491691	37-049-002	Calibrate ECM Module	04-Mar-2021 06:11:21	BHVYEQ	W	DON	0.00

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: P1493 - 2019 CAT 972M										
04-Mar-2021 0	1,628	0	491691	03-043-020	Replace Pump - DEF	04-Mar-2021 06:14:06	BHVYEQ	W	DON	644.68
22-Mar-2021 1	1,756	0	495771	03-044-002	Replace Filters	01-Apr-2021 05:52:18	BHVYEQ	P	DON	38.90
22-Mar-2021 1	1,756	0	495771	03-045-011	Replace Filter Assembly - Oil	01-Apr-2021 05:51:21	BHVYEQ	P	DON	18.36
22-Mar-2021 1	1,756	0	495771	03-360-009	Replace Bucket Tooth / Cutting Edge	27-Mar-2021 10:20:37	BHVYEQ	E	DON	1,352.34
13-Apr-2021 0			500150	03-065-007	Replace Hoses & Fittings	13-Apr-2021 09:41:18	BHVYEQ	B	DON	909.27
14-May-2021 0	2,120	0	506697	03-041-007	Replace Filter - Outer	14-May-2021 09:33:09	BHVYEQ	O	DON	52.07
14-May-2021 0	2,120	0	506697	03-045-011	Replace Filter Assembly - Oil	14-May-2021 09:32:06	BHVYEQ	O	DON	18.65
21-Jun-2021 1	2,369	0	514093	07-360	Lubricate Loader / Skid-Steer	21-Jun-2021 15:24:50	BHVYEQ	O	DON	175.90
02-Aug-2021 1	2,669	0	522318	03-045-011	Replace Filter Assembly - Oil	02-Aug-2021 13:28:54	BHVYEQ	O	DON	18.85
09-Aug-2021 0	2,719	0	523716	24-019-001	Repair Reservoir & Lines	11-Aug-2021 18:35:24	BHVYEQ	O	DON	375.34
09-Aug-2021 0	2,719	0	523716	24-065-002	Repair Accumulator		BHVYEQ	O	CAN	0.00
09-Aug-2021 0	2,719	0	523716	03-001-016	Replace Filter - Cab Ventilation	12-Aug-2021 06:14:13	BHVYEQ	O	DON	58.08
14-Sep-2021 0	2,953	0	531128	03-044-002	Replace Filters	14-Sep-2021 09:43:30	BHVYEQ	O	DON	38.78
14-Sep-2021 0	2,953	0	531128	07-360	Lubricate Loader / Skid-Steer	14-Sep-2021 09:44:54	BHVYEQ	O	DON	175.73
14-Sep-2021 0	2,953	0	531128	03-045-011	Replace Filter Assembly - Oil	14-Sep-2021 09:42:22	BHVYEQ	O	DON	16.25
14-Sep-2021 0	2,953	0	531128	03-041-007	Replace Filter - Outer	14-Sep-2021 09:43:00	BHVYEQ	O	DON	53.76
27-Sep-2021 1	3,050	0	534554	03-360-009	Replace Bucket Tooth / Cutting Edge	05-Oct-2021 13:30:02	BHVYEQ	E	DON	1,301.66
27-Sep-2021 1	3,050	0	534554	03-360-013	Replace Ride Control Accumulator	19-Oct-2021 09:25:28	BHVYEQ	W	DON	345.38
02-Nov-2021 0	3,291	0	543354	03-045-011	Replace Filter Assembly - Oil	02-Nov-2021 06:33:31	BHVYEQ	O	DON	16.33
16-Dec-2021 1	3,291	0	554093	03-019-001	Replace Reservoir & Lines	18-Dec-2021 08:44:09	BHVYEQ	I	DON	384.51
08-Feb-2022 0	3,291	0	564899	03-019-001	Replace Reservoir & Lines	13-Feb-2022 07:36:24	BHVYEQ	I	DON	263.14
08-Feb-2022 0	3,291	0	564899	03-041-006	Replace Filter - Inner	17-Feb-2022 12:51:30	BHVYEQ	O	DON	22.49
08-Feb-2022 0	3,291	0	564899	03-041-007	Replace Filter - Outer	17-Feb-2022 12:51:11	BHVYEQ	O	DON	53.76
08-Feb-2022 0	3,291	0	564899	03-044-002	Replace Filters	17-Feb-2022 12:50:55	BHVYEQ	O	DON	38.78
08-Feb-2022 0	3,291	0	564899	03-045-011	Replace Filter Assembly - Oil	17-Feb-2022 12:50:23	BHVYEQ	O	DON	16.33
08-Feb-2022 0	3,291	0	564899	07-360	Lubricate Loader / Skid-Steer	17-Feb-2022 12:49:54	BHVYEQ	O	DON	190.44
24-Feb-2022 1	4,531	0	569670	02-002-044	Clean Cab - Complete	08-Mar-2022 07:24:22	BHVYEQ	I	DON	51.73
24-Feb-2022 1	4,531	0	569670	02-043-009	Clean Diesel Particulate Filter - DPF	08-Mar-2022 10:18:30	BHVYEQ	I	DON	882.02
24-Feb-2022 1	4,531	0	569670	02-360	Clean Loader / Skid-Steer	05-Apr-2022 16:21:37	BWASH	N	DON	373.16

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: P1493 - 2019 CAT 972M										
24-Feb-2022	1	4,531	0	569670	03-027-043	Replace Seal - Output	BHVYEQ	W	DON	254.37
24-Feb-2022	1	4,531	0	569670	03-031-006	Replace Belt - Alternator	BHVYEQ	I	DON	184.03
24-Feb-2022	1	4,531	0	569670	03-052-013	Replace Antenna and Mounting	BHVYEQ	I	DON	75.19
24-Feb-2022	1	4,531	0	569670	06-100-PMC	Inspect C PMI	BHVYEQ	P	DON	98.89
24-Feb-2022	1	4,531	0	569670	24-034-014	Repair Auxiliary Work / Flood Light	BHVYEQ	I	DON	49.88
24-Feb-2022	1	4,531	0	569670	31-360-009	Rotate Bucket Tooth / Cutting Edge	BHVYEQ	I	DON	134.26
24-Feb-2022	1	4,531	0	569670	38-100-PMC	Service C PMI	BHVYEQ	I	DON	1,181.96
24-Feb-2022	1	4,531	0	569670	B3-049-002	Program ECM Module	BHVYEQ	W	DON	0.00
29-Apr-2022	1	4,531	0	585484	02-360	Clean Loader / Skid-Steer	BHVYEQ	N	DON	451.84
29-Apr-2022	1	4,531	0	585484	03-044-014	Replace Injectors - Electronic	BHVYEQ	W	DON	0.00
29-Apr-2022	1	4,531	0	585484	24-027	Repair Transmission - Main, Automatic	BHVYEQ	W	DON	0.00
29-Apr-2022	1	4,531	0	585484	37-930	Calibrate Scale	BHVYEQ	N	DON	223.61
20-May-2022	1	4,531	0	590111	06-360	Inspect Loader / Skid-Steer	BHVYEQ	I	DON	160.94
23-Jun-2022	0	4,531	0	598054	03-019-007	Replace Hose, Tubing & Connectors	BHVYEQ	I	DON	126.69
23-Jun-2022	0	4,531	0	598054	06-100-PMA	Inspect A PMI	TRK005	P	DON	0.00
23-Jun-2022	0	4,531	0	598054	06-100-PMB	Inspect B PMI	TRK005	P	DON	0.00
23-Jun-2022	0	4,531	0	598054	24-024	Repair Driveshafts	BHVYEQ	I	DON	1,559.01
23-Jun-2022	0	4,531	0	598054	38-100-PMA	Service A PMI	TRK005	P	DON	348.00
16-Aug-2022	1	4,531	0	609963	03-065-007	Replace Hoses & Fittings	BHVYEQ	O	DON	55.03
18-Aug-2022	1	4,531	0	610397	03-065-007	Replace Hoses & Fittings	BHVYEQ	O	DON	64.52
23-Aug-2022	1	4,531	0	611378	38-100-PMA	Service A PMI	BHVYEQ	O	DON	207.20
07-Sep-2022	1	5,152	0	614583	03-045-011	Replace Filter Assembly - Oil	BHVYEQ	O	DON	44.56
10-Oct-2022	1	5,454	0	623107	03-043-031	Replace Manifold - DEF	BHVYEQ	B	DON	2,698.04
08-Dec-2022	1	5,454	0	638052	03-360-009	Replace Bucket Tooth / Cutting Edge	BHVYEQ	I	DON	1,395.87
08-Dec-2022	1	5,454	0	638052	06-100-PMB	Inspect B PMI	BHVYEQ	P	DON	190.68
08-Dec-2022	1	5,454	0	638052	02-002-044	Clean Cab - Complete	BHVYEQ	I	DON	196.91
08-Dec-2022	1	5,454	0	638052	38-100-PMC	Service C PMI	BHVYEQ	I	DON	773.48
08-Dec-2022	1	5,454	0	638052	02-360	Clean Loader / Skid-Steer	BWASH	N	DON	210.63
08-Dec-2022	1	5,454	0	638052	26-514-004	Weld Edges	BHVYEQ	N	DON	327.08

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: P1493 - 2019 CAT 972M										
08-Dec-2022	1	5,454	0	638052	03-065-007	Replace Hoses & Fittings	BHVEEQ	I	DON	1,783.15
08-Dec-2022	1	5,454	0	638052	24-518-001	Repair Steps	BHVEEQ	I	DON	46.97
08-Dec-2022	1	5,454	0	638052	03-360-012	Replace Heel Plate	BHVEEQ	I	DON	520.79
08-Dec-2022	1	5,454	0	638052	B3-049-002	Program ECM Module	BHVEEQ	W	DON	0.00
08-Dec-2022	1	5,454	0	638052	37-930	Calibrate Scale	BHVEEQ	N	DON	215.22
15-Mar-2023	1	5,563	0	659448	03-019-001	Replace Reservoir & Lines	TRK005	O	DON	578.62
21-Mar-2023	0	5,595	0	660552	06-100-PMA	Inspect A PMI	BHVEEQ	P	DON	0.00
21-Mar-2023	0	5,595	0	660552	38-100-PMA	Service A PMI	BHVEEQ	O	DON	233.08
24-May-2023	1	5,931	0	676761	03-041-001	Replace Air Cleaner	BHVEEQ	O	DON	90.45
19-Jun-2023	0	6,097	0	682405	03-001-016	Replace Filter - Cab Ventilation	BHVEEQ	O	DON	64.26
19-Jun-2023	0	6,097	0	682405	03-044-002	Replace Filters	BHVEEQ	O	DON	102.52
19-Jun-2023	0	6,097	0	682405	03-045-011	Replace Filter Assembly - Oil	BHVEEQ	O	DON	41.74
27-Jul-2023	11	6,246	0	691842	38-100-PMB	Service B PMI	PAVFLD	P	DON	169.61
31-Jul-2023	07	6,272	0	692797	24-044	Repair Fuel System	BVLOFC	B	DON	5,056.74
31-Jul-2023	07	6,272	0	692797	95-MS-004	Travel Travel Time - To/From Job Site	BVLOFC	B	DON	1,020.00
31-Jul-2023	07	6,272	0	692797	35-044-003	Diagnose Fuel Pump	BVLOFC	I	DON	555.00
26-Sep-2023	0	6,562	0	708043	03-041-001	Replace Air Cleaner	PAVFLD	O	DON	74.19
26-Sep-2023	0	6,562	0	708043	03-002-035	Replace Windshield Wiper & Washer	PAVFLD	O	DON	90.28
29-Sep-2023	0	6,587	0	709023	35-049-001	Diagnose ECM Fault Code	BHVEEQ	B	DON	802.64
24-Oct-2023	1	6,659	0	715428	02-002-044	Clean Cab - Complete	BHVEEQ	I	DON	36.29
24-Oct-2023	1	6,659	0	715428	02-360	Clean Loader / Skid-Steer	BWASH	N	DON	253.33
24-Oct-2023	1	6,659	0	715428	03-002-060	Replace Seat Belt	BHVEEQ	I	DON	349.16
24-Oct-2023	1	6,659	0	715428	03-054-002	Replace Alarm - Reverse Signal	BHVEEQ	I	DON	240.42
24-Oct-2023	1	6,659	0	715428	06-100-PMB	Inspect B PMI	BHVEEQ	P	DON	133.57
24-Oct-2023	1	6,659	0	715428	31-360-009	Rotate Bucket Tooth / Cutting Edge	BHVEEQ	E	DON	150.11
24-Oct-2023	1	6,659	0	715428	38-100-PMA	Service A PMI	BHVEEQ	I	DON	513.29
10-Nov-2023	C	6,662	0	719603	03-044-002	Replace Filters	BHVEEQ	O	DON	50.20
10-Nov-2023	C	6,662	0	719603	03-045-011	Replace Filter Assembly - Oil	BHVEEQ	O	DON	20.87
12-Dec-2023	0	6,809	0	726261	24-019-007	Repair Hose, Tubing & Connectors	BHVEEQ	N	DON	562.43

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost	
Unit No: P1493 - 2019 CAT 972M											
18-Dec-2023	0	6,838	0	727493	24-034-018	Repair Brake Light Switch	18-Dec-2023 08:04:53	BHVEQ	N	DON	488.12
01-Mar-2024	1	6,881	0	742535	OS-360	Out-Service Loader / Skid-Steer	07-Mar-2024 09:21:54	BHVEQ	Z	DON	232.84
01-Mar-2024	1	6,881	0	742535	03-065-007	Replace Hoses & Fittings	07-Mar-2024 09:32:26	BHVEQ	N	DON	264.70
01-Mar-2024	1	6,881	0	742535	02-360	Clean Loader / Skid-Steer	07-Mar-2024 09:15:44	BWASH	Z	DON	329.17

Unit No: P1493

Count: 120

58,557.62