

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: A0940 - 1998 GMC 3500										
15-Nov-2016 C	131,534	0	275815	24-002-035	Repair Windshield Wiper & Washer	02-Jan-2017 13:38:15	WTNSHP	I	DON	92.97
15-Nov-2016 C	131,534	0	275815	24-058-005	Repair Winch Control / Wiring	02-Jan-2017 13:38:15	WTNSHP	I	DON	61.98
07-Dec-2016 0		0	268860	14-063-003	Install Transceiver - GPS Tracker	07-Dec-2016 08:27:23	BTRUCK	Q	DON	254.64
07-Apr-2017 1	131,835	0	284427	03-013-002	Replace Rear Brakes & Drums	11-Apr-2017 15:54:54	WTNSHP	P	DON	1,791.12
07-Apr-2017 1	131,835	0	284427	03-034-010	Replace Socket - Trailer Light Cord	04-Jun-2017 15:53:14	WTNSHP	I	DON	8.89
07-Apr-2017 1	131,835	0	284427	03-100-PMA	Replace A PMI	11-Apr-2017 15:54:54	WTNSHP	P	DON	116.96
07-Apr-2017 1	131,835	0	284427	06-100-009	Inspect Safety Check	11-Apr-2017 16:21:59	WTNSHP	P	DON	60.82
07-Apr-2017 1	131,835	0	284427	06-100-DOT	Inspect DOT Federal Inspection	10-Apr-2017 00:00:00	WTNSHP	P	DON	30.99
07-Apr-2017 1	131,835	0	284427	24-015-002	Repair Steering Shaft Support	11-Apr-2017 15:54:54	WTNSHP	P	DON	2,417.12
07-Apr-2017 1	131,835	0	284427	35-034-002	Diagnose Stop, Tail, Turn & License	11-Apr-2017 15:54:54	WTNSHP	P	DON	1,057.26
30-Jan-2018 1		0	321615	03-045-028	Replace Valve Cover	31-Jan-2018 09:42:37	WTNSHP	I	DON	190.95
30-Jan-2018 1		0	321615	06-100-DOT	Inspect DOT Federal Inspection	31-Jan-2018 11:19:06	WTNSHP	P	DON	54.70
30-Jan-2018 1		0	321615	06-100-PMA	Inspect A PMI	30-Jan-2018 14:54:28	WTNSHP	P	DON	130.27
30-Jan-2018 1		0	321615	18-100-000	Test On Road Equip / Field Service	31-Jan-2018 12:47:22	WTNSHP	P	DON	33.82
04-Apr-2018 1		0	329964	03-078-009	Replace Mud Flaps and Hanger Brackets	04-Apr-2018 14:09:18	WTNSHP	P	DON	13.58
12-Jul-2018 08		0	343488	03-003-008	Replace Coolant Temperature Gauge	20-Jul-2018 11:26:40	WTNSHP	I	DON	183.31
12-Jul-2018 08		0	343488	03-031-006	Replace Belt - Alternator	19-Jul-2018 14:46:50	WTNSHP	I	DON	570.60
12-Jul-2018 08		0	343488	03-037-001	Replace Modules - Multiple Use	12-Jul-2018 14:43:01	WTNSHP	I	DON	563.77
12-Jul-2018 08		0	343488	03-040	Replace Engine / Motor Systems Group	31-Jul-2018 08:02:59	WTNSHP	I	DON	298.54
12-Jul-2018 08		0	343488	03-042-002	Replace Radiator	19-Jul-2018 12:24:19	WTNSHP	I	DON	550.93
12-Jul-2018 08		0	343488	03-042-004	Replace Water Pump	19-Jul-2018 09:58:44	WTNSHP	I	DON	792.33
12-Jul-2018 08		0	343488	03-042-006	Replace Thermostat	19-Jul-2018 14:47:42	WTNSHP	I	DON	206.43
12-Jul-2018 08		0	343488	03-042-016	Replace Fan Clutch	19-Jul-2018 11:04:20	WTNSHP	I	DON	37.19
12-Jul-2018 08		0	343488	03-044-003	Replace Fuel Pump	30-Jul-2018 12:23:35	WTNSHP	I	DON	30.43
12-Jul-2018 08		0	343488	18-100-000	Test On Road Equip / Field Service	31-Jul-2018 08:59:54	WTNSHP	P	DON	81.89
12-Jul-2018 08		0	343488	20-014-001	Tow Frame Assembly	13-Aug-2018 09:54:53	WTNSHP	B	DON	234.59
12-Jul-2018 08		0	343488	38-027-037	Service Transmission Assembly - Automatic	19-Jul-2018 16:00:03	WTNSHP	I	DON	53.28
15-Oct-2018 0		0	356459	03-410-002	Replace Lights	18-Oct-2018 06:59:40	WTNSHP	I	DON	38.34
06-Mar-2019 1		0	375422	02-002-011	Clean Cab Accessories - Interior	08-Mar-2019 07:45:32	WTNSHP	I	DON	58.73

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: A0940 - 1998 GMC 3500										
06-Mar-2019 1		0	375422	06-100-DOT	Inspect DOT Federal Inspection	07-Mar-2019 16:00:02	WTNSHP	P	DON	107.10
06-Mar-2019 1		0	375422	06-100-PMA	Inspect A PMI	07-Mar-2019 09:29:47	WTNSHP	P	DON	199.30
06-Mar-2019 1		0	375422	14-034-014	Install Auxiliary Work / Flood Light	07-Mar-2019 13:21:02	WTNSHP	P	DON	701.70
06-Mar-2019 1		0	375422	14-051-009	Install Fire Extinguisher	07-Mar-2019 13:30:56	WTNSHP	P	DON	6.19
06-Mar-2019 1		0	375422	24-079-002	Repair Headache Rack	08-Mar-2019 06:01:57	WTNSHP	I	DON	4.73
22-Nov-2019 1	131,958	0	413991	03-016-005	Replace Chassis Spring - Rear	21-Feb-2020 13:01:36	WTNSHP	I	DON	259.58
22-Nov-2019 1	131,958	0	413991	03-017-001	Replace Tire - Pneumatic	20-Apr-2020 08:44:59	WTNSHP	P	DON	2,394.13
22-Nov-2019 1	131,958	0	413991	03-022-008	Replace Pinion Seal	21-Feb-2020 15:02:14	WTNSHP	I	DON	107.67
22-Nov-2019 1	131,958	0	413991	03-033-006	Replace Relay	25-Feb-2020 15:30:19	WTNSHP	I	DON	79.88
22-Nov-2019 1	131,958	0	413991	03-051-009	Replace Fire Extinguisher	20-Feb-2020 13:45:08	WTNSHP	I	DON	169.03
22-Nov-2019 1	131,958	0	413991	06-100-DOT	Inspect DOT Federal Inspection	21-Feb-2020 16:00:17	WTNSHP	P	DON	39.43
22-Nov-2019 1	131,958	0	413991	06-100-PMA	Inspect A PMI	25-Feb-2020 14:48:46	WTNSHP	P	DON	142.97
22-Nov-2019 1	131,958	0	413991	24-034-002	Repair Stop, Tail, Turn & License	07-Apr-2020 11:02:21	WTNSHP	I	DON	16.77
22-Nov-2019 1	131,958	0	413991	38-100-PMA	Service A PMI	21-Feb-2020 09:24:24	WTNSHP	P	DON	66.76
05-Oct-2020 0	132,027	0	464729	02-002	Clean Cab & Sheet Metal	06-Oct-2020 07:15:58	WTNSHP	I	DON	153.03
05-Oct-2020 0	132,027	0	464729	03-002-035	Replace Windshield Wiper & Washer	05-Oct-2020 11:44:17	WTNSHP	I	DON	28.01
05-Oct-2020 0	132,027	0	464729	03-022-001	Replace Axle Housing, Rear	08-Oct-2020 11:00:26	WTNSHP	I	DON	63.35
05-Oct-2020 0	132,027	0	464729	06-100-PMA	Inspect A PMI	05-Oct-2020 09:32:21	WTNSHP	P	DON	91.99
05-Oct-2020 0	132,027	0	464729	14-055-007	Install Hook Assembly	06-Oct-2020 12:10:08	WTNSHP	P	DON	122.95
05-Oct-2020 0	132,027	0	464729	18-100-000	Test On Road Equip / Field Service	06-Oct-2020 07:45:38	WTNSHP	P	DON	15.32
05-Oct-2020 0	132,027	0	464729	38-100-PMA	Service A PMI	05-Oct-2020 11:02:57	WTNSHP	P	DON	65.73
02-Feb-2021 1	132,047	0	486019	02-002	Clean Cab & Sheet Metal	03-Feb-2021 14:00:19	WTNSHP	I	DON	114.51
02-Feb-2021 1	132,047	0	486019	03-003	Replace Instruments, Gauges, Warning & Shutoff	15-Feb-2021 10:40:55	WTNSHP	I	DON	81.65
02-Feb-2021 1	132,047	0	486019	03-037	Replace Electrical - Modules/Relays	15-Feb-2021 11:01:29	WTNSHP	I	DON	169.06
02-Feb-2021 1	132,047	0	486019	03-051-009	Replace Fire Extinguisher	03-Feb-2021 09:45:40	WTNSHP	I	DON	42.48
02-Feb-2021 1	132,047	0	486019	06-100-DOT	Inspect DOT Federal Inspection	03-Feb-2021 11:00:15	WTNSHP	P	DON	51.51
02-Feb-2021 1	132,047	0	486019	06-100-PMA	Inspect A PMI	03-Feb-2021 09:30:03	WTNSHP	P	DON	144.99
12-Apr-2021 1	132,053	0	499884	03-034-010	Replace Socket - Trailer Light Cord	12-Apr-2021 13:04:57	WTNSHP	I	DON	129.29
13-Nov-2021 1	132,065	0	546405	03-063-003	Replace Transceiver - GPS Tracker	13-Nov-2021 16:14:40	ELEC03	Q	DON	362.34

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: A0940 - 1998 GMC 3500										
17-Mar-2022 0	132,993	6	575125	02-002	Clean Cab & Sheet Metal	05-Apr-2022 08:30:01	WTNSHP	I	DON	115.90
17-Mar-2022 0	132,993	6	575125	03-002-035	Replace Windshield Wiper & Washer	18-Mar-2022 06:04:57	WTNSHP	I	DON	26.81
17-Mar-2022 0	132,993	6	575125	03-051-009	Replace Fire Extinguisher	17-Mar-2022 12:11:14	WTNSHP	I	DON	36.82
17-Mar-2022 0	132,993	6	575125	03-053-017	Replace First Aid Kit	17-Mar-2022 12:19:03	WTNSHP	I	DON	10.89
17-Mar-2022 0	132,993	6	575125	06-100-DOT	Inspect DOT Federal Inspection	17-Mar-2022 13:04:50	WTNSHP	P	DON	31.62
17-Mar-2022 0	132,993	6	575125	06-100-PMA	Inspect A PMI	05-Apr-2022 08:33:20	WTNSHP	P	DON	88.46
17-Mar-2022 0	132,993	6	575125	38-100-PMA	Service A PMI	05-Apr-2022 08:33:20	WTNSHP	P	DON	71.14
25-Apr-2022 1	133,082	16	584141	03-013-007	Replace Brake Lines & Fittings - Hydraulic & A	26-Apr-2022 09:44:43	WTNSHP	I	DON	419.84
21-Mar-2023 1	133,556	69	660705	02-002	Clean Cab & Sheet Metal	22-Mar-2023 10:15:43	WTNSHP	I	DON	83.25
21-Mar-2023 1	133,556	69	660705	03-051-009	Replace Fire Extinguisher	21-Mar-2023 14:25:55	WTNSHP	I	DON	31.05
21-Mar-2023 1	133,556	69	660705	03-053-017	Replace First Aid Kit	21-Mar-2023 14:18:33	WTNSHP	I	DON	12.22
21-Mar-2023 1	133,556	69	660705	06-100-DOT	Inspect DOT Federal Inspection	22-Mar-2023 08:01:27	WTNSHP	P	DON	77.68
21-Mar-2023 1	133,556	69	660705	06-100-PMA	Inspect A PMI	21-Mar-2023 14:11:03	WTNSHP	P	DON	96.04
14-Nov-2023 1	134,931	133	720543	03-063-003	Replace Transceiver - GPS Tracker	14-Nov-2023 17:34:18	ELEC01	Q	DON	258.71
14-Nov-2023 1	134,931	133	720543	06-100-PMB	Inspect B PMI	17-Nov-2023 08:24:31	SCHED	P	DON	0.00
06-Mar-2024 0	141,947	133	743468	03-032-001	Replace Battery	06-Mar-2024 12:43:26	WTNSHP	N	DON	311.24
06-Mar-2024 0	141,947	133	743468	03-041-007	Replace Filter - Outer	06-Mar-2024 12:22:47	WTNSHP	N	DON	29.29
06-Mar-2024 0	141,947	133	743468	06-100-PMA	Inspect A PMI	06-Mar-2024 07:32:43	WTNSHP	P	DON	85.52
22-Mar-2024 0	141,947	133	747454	06-002-011	Inspect Cab Accessories - Interior	22-Mar-2024 07:36:04	WTNSHP	Z	DON	31.33
18-Apr-2024 1		133	753784	02-002	Clean Cab & Sheet Metal	23-Apr-2024 07:18:33	BSETUP	Z	DON	329.78
18-Apr-2024 1		133	753784	25-051	Remove General Accessories	23-Apr-2024 10:51:21	BSETUP	Z	DON	146.57

Unit No: A0940

Count: 79

18,242.02