

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost	
<b>Unit No: G0364 - 2001 F350 REGCAB</b>											
17-Dec-2008	1	91,377	0	7184	03-017-001	Replace Tire - Pneumatic	17-Dec-2008 10:13:15	BTIRE	F	DON	905.16
17-Dec-2008	1	91,377	0	7184	09-015	Align Steering	17-Dec-2008 10:17:01	BTIRE	F	DON	311.85
09-Apr-2009	1	95,098	0	17116	06-100-002	Inspect DO NOT USE - DOT Federal Insp	09-Apr-2009 13:10:58	BVLOFC	F	DON	223.53
21-Sep-2009	1	104,973	0	24991	03-193-002	Replace Belts	21-Sep-2009 15:25:43	BVLOFC	F	DON	129.52
22-Feb-2010	0	109,390	0	40560	06-100-011	Inspect Annual Aerial/Boom Inspection	07-May-2010 14:33:56	MPNSHP	P	DON	836.15
01-Apr-2011	0	129,673	0	62540	03-017-001	Replace Tire - Pneumatic	02-Apr-2011 06:15:36	BTIRE	F	DON	885.02
28-Apr-2011	1	129,666	0	64407	06-100-002	Inspect DO NOT USE - DOT Federal Insp	28-Apr-2011 14:13:22	BVLOFC	P	DON	0.00
10-Jan-2012	0	130,018	0	93733	03-034-003	Replace Signal, Parking, Backup Lamps	10-Jan-2012 06:00:00	BVLOFC	N	DON	13.87
10-Jan-2012	0	130,018	0	93733	03-034-004	Replace Clearance & Marker Lamps	10-Jan-2012 06:30:00	BVLOFC	N	DON	6.94
10-Jan-2012	0	130,018	0	93733	03-044-002	Replace Filters	10-Jan-2012 07:15:00	BVLOFC	P	DON	13.87
10-Jan-2012	0	130,018	0	93733	06-100-PMA	Inspect A PMI	10-Jan-2012 06:45:00	BVLOFC	P	DON	13.87
26-Apr-2012	1	130,018	0	97313	06-100-DOT	Inspect DOT Federal Inspection	26-Apr-2012 13:21:29	BVLOFC	P	DON	0.00
09-Jul-2013	06	130,047	0	159276	06-100-DOT	Inspect DOT Federal Inspection	09-Jul-2013 17:00:00	BTRUCK	P	DON	0.00
05-Aug-2013	C	130,440	0	127801	03-045-027	Replace Idler Pulley	05-Aug-2013 17:00:00	BVLOFC	F	DON	34.48
07-Aug-2013	C	130,477	0	133972	03-045-023	Replace Engine Belts	21-Aug-2013 08:04:49	BVLOFC	F	DON	236.95
07-Aug-2013	C	130,477	0	133972	03-045-027	Replace Idler Pulley	21-Aug-2013 08:04:49	BVLOFC	F	DON	218.61
12-Aug-2013	C	130,751	0	131242	03-045-023	Replace Engine Belts	12-Aug-2013 17:00:00	BVLOFC	F	DON	424.21
21-Aug-2013	C	130,440	0	129861	03-063-003	Replace Transceiver - GPS Tracker	21-Aug-2013 00:00:00	BTRUCK	C	DON	221.42
13-Apr-2015	1	130,751	0	197671	06-100-011	Inspect Annual Aerial/Boom Inspection	22-Apr-2015 00:00:00	MPNFLD	P	DON	1,729.68
26-Jul-2015	15	135,068	0	220022	02-002	Clean Cab & Sheet Metal	26-Jul-2015 15:20:41	BVLOFC	O	DON	25.07
07-Aug-2015	1	135,068	0	210571	03-013-001	Replace Front Brakes & Drums	14-Aug-2015 06:35:14	BTRUCK	I	DON	335.91
07-Aug-2015	1	135,068	0	210571	24-027-043	Repair Seal - Output	14-Aug-2015 06:35:05	BTRUCK	I	DON	680.23
07-Aug-2015	1	135,068	0	210571	24-043-004	Repair Turbocharger	14-Aug-2015 06:35:17	BTRUCK	I	DON	678.99
07-Aug-2015	1	135,068	0	210571	38-043-001	Service Emission Controls	14-Aug-2015 06:35:10	BTRUCK	I	DON	272.18
18-Sep-2015	1	135,068	0	220339	02-002	Clean Cab & Sheet Metal	18-Sep-2015 11:31:13	BVLOFC	O	DON	25.07
27-Oct-2015	0	135,093	0	220945	24-268-009	Repair Boom Structure	27-Oct-2015 00:00:00	MPNFLD	B	DON	3,564.85
27-Oct-2015	0	135,093	0	220945	06-100-011	Inspect Annual Aerial/Boom Inspection	27-Oct-2015 00:00:00	MPNFLD	P	DON	547.90
05-Nov-2015	C	136,686	0	229954	03-032-001	Replace Battery	05-Nov-2015 00:00:00	LAVSHP	B	DON	41.03
05-Nov-2015	C	136,686	0	229954	03-054-002	Replace Alarm - Reverse Signal	05-Nov-2015 00:00:00	LAVSHP	B	DON	41.03

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: G0364 - 2001 F350 REGCAB										
20-Jan-2016 00:00:00	136,686	0	235619	06-100-PMA	Inspect A PMI	20-Jan-2016 00:00:00	LAVSHP	P	DON	23.41
20-Jan-2016 00:00:00	136,686	0	235619	07-100-000	Lubricate On Road Equip / Field Service	20-Jan-2016 00:00:00	LAVSHP	P	DON	23.41
09-Feb-2016 00:00:00	137,032	0	236227	06-100-PMA	Inspect A PMI	09-Feb-2016 00:00:00	LAVSHP	P	DON	21.01
09-Feb-2016 00:00:00	137,032	0	236227	07-100-000	Lubricate On Road Equip / Field Service	09-Feb-2016 00:00:00	LAVSHP	P	DON	21.01
10-Feb-2016 00:00:00	137,033	0	236247	03-015-005	Replace Power Steering Pump	10-Feb-2016 00:00:00	LAVSHP	I	DON	42.02
10-Feb-2016 00:00:00	137,033	0	236247	03-045-023	Replace Engine Belts	10-Feb-2016 00:00:00	LAVSHP	N	DON	21.01
10-Feb-2016 00:00:00	137,033	0	236247	03-045-027	Replace Idler Pulley	10-Feb-2016 00:00:00	LAVSHP	N	DON	21.01
10-Feb-2016 00:00:00	137,033	0	236247	24-056-001	Repair Power Take Off	10-Feb-2016 00:00:00	LAVSHP	N	DON	21.01
19-Feb-2016 00:00:00	137,195	0	242342	03-013-001	Replace Front Brakes & Drums	19-Feb-2016 07:21:54	LAVSHP	N	DON	147.30
13-Feb-2017 00:00:00	137,918	0	276921	06-100-DOT	Inspect DOT Federal Inspection	13-Feb-2017 06:19:27	LAVSHP	P	DON	32.92
13-Feb-2017 00:00:00	137,918	0	276921	06-100-PMA	Inspect A PMI	13-Feb-2017 08:20:31	LAVSHP	P	DON	64.14
13-Feb-2017 00:00:00	137,918	0	276921	14-002-061	Install Seat Cushion	16-Feb-2017 10:39:56	LAVSHP	I	DON	14.11
02-Mar-2017 00:00:00	138,138	0	279404	03-045-028	Replace Valve Cover	03-Mar-2017 07:42:15	ROGSHP	B	DON	572.49
02-Mar-2017 00:00:00	138,138	0	279404	06-040	Inspect Engine / Motor Systems Group	02-Mar-2017 10:24:49	ROGSHP	B	DON	212.45
02-Mar-2017 00:00:00	138,138	0	279404	06-042-004	Inspect Water Pump	03-Mar-2017 08:29:19	ROGSHP	I	DON	64.54
02-May-2017 00:00:00	138,138	0	287359	03-268-008	Replace Personnel Bucket	08-May-2017 07:26:09	ROGSHP	B	DON	645.51
02-May-2017 00:00:00	138,138	0	287359	06-100-PMA	Inspect A PMI	05-May-2017 13:27:42	ROGSHP	P	DON	30.62
15-Aug-2017 00:00:00	138,138	0	301191	06-400	Inspect Small Equipment Group	15-Aug-2017 15:28:32	ROGSHP	Q	DON	8.17
15-Aug-2017 00:00:00	138,138	0	301191	24-065-007	Repair Hoses & Fittings	15-Aug-2017 15:57:43	ROGSHP	I	DON	11.42
25-Sep-2017 00:00:00	138,585	0	306333	03-065-007	Replace Hoses & Fittings	25-Sep-2017 16:53:09	ROGSHP	B	DON	236.72
29-Jan-2018 00:00:00	138,585	0	321471	03-053-004	Replace Safety Equipment	29-Jan-2018 15:41:25	ROGSHP	I	DON	10.03
29-Jan-2018 00:00:00	138,585	0	321471	06-100-DOT	Inspect DOT Federal Inspection	29-Jan-2018 15:35:32	ROGSHP	P	DON	12.21
29-Jan-2018 00:00:00	138,585	0	321471	03-051-009	Replace Fire Extinguisher	29-Jan-2018 15:37:39	ROGSHP	I	DON	0.83
29-Jan-2018 00:00:00	138,585	0	321471	03-053-005	Replace Markings - Vehicle - Decals	29-Jan-2018 16:45:09	ROGSHP	Q	DON	24.93
03-Dec-2018 00:00:00	138,893	0	362702	06-056	Inspect Power Take Off	03-Dec-2018 11:30:05	LAVSHP	O	DON	69.12
06-Dec-2018 00:00:00	138,893	0	363349	03-042-004	Replace Water Pump	06-Dec-2018 19:07:43	ROGSHP	N	DON	363.14
06-Dec-2018 00:00:00	138,893	0	363349	03-042-012	Replace Clamps and Hoses	07-Dec-2018 06:32:34	ROGSHP	N	DON	23.58
06-Dec-2018 00:00:00	138,893	0	363349	24-034-002	Repair Stop, Tail, Turn & License	06-Dec-2018 16:05:41	ROGSHP	N	DON	40.20
07-Mar-2019 00:00:00	139,183	0	375482	03-034-002	Replace Stop, Tail, Turn & License	12-Mar-2019 15:36:34	ROGSHP	N	DON	277.46

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
<b>Unit No: G0364 - 2001 F350 REGCAB</b>										
07-Mar-2019 0	139,183	0	375482	03-034-004	Replace Clearance & Marker Lamps	12-Mar-2019 15:39:02	ROGSHP	N	DON	77.56
07-Mar-2019 0	139,183	0	375482	03-034-006	Replace Warning Lamps - Special Application	02-Apr-2019 11:01:40	ROGSHP	I	DON	335.65
07-Mar-2019 0	139,183	0	375482	03-041-007	Replace Filter - Outer	01-Apr-2019 15:54:38	ROGSHP	P	DON	13.46
07-Mar-2019 0	139,183	0	375482	06-100-DOT	Inspect DOT Federal Inspection	07-Mar-2019 09:50:43	ROGSHP	P	DON	50.21
07-Mar-2019 0	139,183	0	375482	15-519-002	Paint Prep Rear Bumper	03-Apr-2019 08:45:07	ROGSHP	Q	DON	3,348.80
07-Mar-2019 0	139,183	0	375482	24-013-006	Repair Brake Master Cylinder	13-Mar-2019 12:24:51	ROGSHP	N	DON	372.24
07-Mar-2019 0	139,183	0	375482	24-034-001	Repair Headlamps / Fog Lamps	07-Mar-2019 10:28:30	ROGSHP	I	DON	31.52
07-Mar-2019 0	139,183	0	375482	26-519-002	Weld Rear Bumper	01-Apr-2019 15:55:15	ROGSHP	I	DON	332.16
07-Mar-2019 0	139,183	0	375482	35-040	Diagnose Engine / Motor Systems Group	13-Mar-2019 07:32:49	ROGSHP	N	DON	18.20
30-Apr-2019 1	139,058	0	383531	24-340-001	Repair Boom Assembly	02-May-2019 09:29:35	ROGSHP	N	DON	963.57
09-May-2019 1	139,058	0	385057	03-013-037	Replace Caliper - Front	09-May-2019 10:57:48	LAVSHP	I	DON	223.07
09-May-2019 1	139,058	0	385057	06-013-001	Inspect Front Brakes & Drums	09-May-2019 08:53:29	LAVSHP	O	DON	62.16
12-Aug-2019 1	139,260	0	398309	03-053-008	Replace Hoses & Tubings & Fittings	12-Aug-2019 16:29:23	ROGSHP	B	DON	13.33
04-Oct-2019 0	139,521	0	405953	03-017-001	Replace Tire - Pneumatic	04-Oct-2019 13:22:10	ROGSHP	N	DON	1,457.20
07-Oct-2019 0	139,791	0	406150	03-034-003	Replace Signal, Parking, Backup Lamps	10-Oct-2019 15:18:09	ROGSHP	O	DON	60.05
07-Oct-2019 0	139,791	0	406150	24-034-002	Repair Stop, Tail, Turn & License	10-Oct-2019 15:43:33	ROGSHP	N	DON	43.34
03-Dec-2019 1	140,016	0	414946	06-100-DOT	Inspect DOT Federal Inspection	03-Dec-2019 11:34:06	ROGSHP	P	DON	24.84
03-Dec-2019 1	140,016	0	414946	24-034-004	Repair Clearance & Marker Lamps	03-Dec-2019 11:35:30	ROGSHP	I	DON	2.96
18-Aug-2020 1	140,208	0	456755	06-002-035	Inspect Windshield Wiper & Washer	18-Aug-2020 14:03:18	ROGSHP	O	DON	19.14
31-Aug-2020 1	140,293	0	459158	03-034-002	Replace Stop, Tail, Turn & License	31-Aug-2020 15:12:30	ROGSHP	I	DON	39.68
14-Sep-2020 1	140,391	0	461306	03-032-001	Replace Battery	14-Sep-2020 15:19:30	ROGSHP	I	DON	292.88
14-Sep-2020 1	140,391	0	461306	03-032-002	Replace Starter	14-Sep-2020 15:12:47	ROGSHP	I	DON	316.14
14-Sep-2020 1	140,391	0	461306	03-032-004	Replace Battery Cables and Ends	15-Sep-2020 07:34:35	ROGSHP	I	DON	87.01
14-Sep-2020 1	140,391	0	461306	06-033	Inspect Ignition System	14-Sep-2020 13:38:54	ROGSHP	B	DON	180.09
29-Dec-2020 1	140,742	0	479180	06-100-DOT	Inspect DOT Federal Inspection	31-Dec-2020 08:53:04	ROGSHP	P	DON	46.85
29-Dec-2020 1	140,742	0	479180	06-100-PMA	Inspect A PMI	02-Jan-2021 10:27:57	ROGSHP	P	DON	0.00
29-Dec-2020 1	140,742	0	479180	38-100-PMA	Service A PMI	31-Dec-2020 09:34:27	ROGSHP	P	DON	125.06
29-Dec-2020 1	140,742	0	479180	03-051-009	Replace Fire Extinguisher	31-Dec-2020 09:01:02	ROGSHP	I	DON	4.84
29-Dec-2020 1	140,742	0	479180	03-053-017	Replace First Aid Kit	31-Dec-2020 09:32:15	ROGSHP	I	DON	62.60

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
<b>Unit No: G0364 - 2001 F350 REGCAR</b>										
29-Dec-2020	140,742		479180	03-034-004	Replace Clearance & Marker Lamps	31-Dec-2020 09:40:10	ROGSHP	I	DON	19.14
04-Feb-2021	140,728		486481	03-015-004	Replace Steering Linkage	18-Mar-2021 14:37:23	ROGSHP	I	DON	481.87
04-Feb-2021	140,728		486481	03-016-003	Replace Shock Absorber - Front	18-Mar-2021 14:53:37	ROGSHP	N	DON	70.92
04-Feb-2021	140,728		486481	03-016-020	Replace Ball Joint - Upper Control Arm	18-Mar-2021 11:56:53	ROGSHP	N	DON	306.72
04-Feb-2021	140,728		486481	03-016-021	Replace Ball Joint - Lower Control Arm	18-Mar-2021 13:13:41	ROGSHP	I	DON	180.29
04-Feb-2021	140,728		486481	03-053-008	Replace Hoses & Tubings & Fittings	18-Mar-2021 16:00:37	ROGSHP	I	DON	1,712.55
04-Feb-2021	140,728		486481	06-268-009	Inspect Boom Structure	01-Mar-2021 12:48:19	ROGSHP	P	DON	738.33
02-May-2022	140,865		585886	03-002-035	Replace Windshield Wiper & Washer	02-May-2022 15:47:54	OTSSHP	I	DON	27.10
02-May-2022	140,865		585886	03-051-009	Replace Fire Extinguisher	02-May-2022 16:03:41	OTSSHP	I	DON	80.81
02-May-2022	140,865		585886	03-063-003	Replace Transceiver - GPS Tracker	02-May-2022 17:00:00	OTSSHP	Q	DON	320.54
02-May-2022	140,865		585886	06-100-DOT	Inspect DOT Federal Inspection	02-May-2022 15:42:14	OTSSHP	P	DON	73.50
02-May-2022	140,865		585886	06-100-PMA	Inspect A PMI	03-May-2022 08:58:42	OTSSHP	P	DON	20.00
02-May-2022	140,865		585886	24-268-027	Repair Operator Controls	02-May-2022 14:35:22	OTSSHP	I	DON	19.58
02-May-2022	140,865		585886	38-100-PMA	Service A PMI	03-May-2022 08:14:04	OTSSHP	P	DON	187.25
05-Jul-2022	140,866		600205	06-340-001	Inspect Boom Assembly	14-Jul-2022 09:19:13	OTSSHP	N	DON	646.46
28-Jul-2022	141,156		605599	24-094	Repair Lines, Tubes, Hoses & Fittings - Bulk Pr	28-Jul-2022 09:33:36	OTSSHP	N	DON	58.54
15-Jun-2023	141,160		681739	03-002-024	Replace Glass / Windshield	28-Jun-2023 14:44:00	OTSSHP	E	DON	80.00
15-Jun-2023	141,160		681739	03-013-001	Replace Front Brakes & Drums	07-Sep-2023 12:04:51	OTSSHP	I	DON	33.29
15-Jun-2023	141,160		681739	03-032-001	Replace Battery	10-Jul-2023 07:24:49	OTSSHP	I	DON	313.72
15-Jun-2023	141,160		681739	03-034-004	Replace Clearance & Marker Lamps	20-Jun-2023 10:58:11	OTSSHP	I	DON	16.06
15-Jun-2023	141,160		681739	03-045-023	Replace Engine Belts	20-Jun-2023 12:40:38	OTSSHP	I	DON	80.23
15-Jun-2023	141,160		681739	03-051-009	Replace Fire Extinguisher	15-Jun-2023 13:39:59	OTSSHP	Q	DON	60.34
15-Jun-2023	141,160		681739	06-040	Inspect Engine / Motor Systems Group	10-Jul-2023 09:04:25	OTSSHP	I	DON	61.75
15-Jun-2023	141,160		681739	06-100-011	Inspect Annual Aerial/Boom Inspection	23-Jun-2023 13:12:00	OTSSHP	N	DON	655.75
15-Jun-2023	141,160		681739	06-100-DOT	Inspect DOT Federal Inspection	07-Jul-2023 15:02:36	OTSSHP	P	DON	147.23
15-Jun-2023	141,160		681739	06-100-PMA	Inspect A PMI	20-Jun-2023 12:55:35	OTSSHP	P	DON	9.26
15-Jun-2023	141,160		681739	24-013-007	Repair Brake Lines & Fittings - Hydraulic & Air	14-Sep-2023 14:07:31	OTSSHP	I	DON	227.94
15-Jun-2023	141,160		681739	24-040	Repair Engine / Motor Systems Group	11-Jul-2023 10:10:24	OTSSHP	I	DON	355.23
15-Jun-2023	141,160		681739	24-052-071	Repair Remote Control Unit	03-Oct-2023 13:21:24	OTSSHP	O	DON	166.37

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
<b>Unit No: G0364 - 2001 F350 REGCAB</b>										
15-Jun-2023	141,160		681739	24-056-003	Repair Powershift PTO	14-Sep-2023 15:10:14	OTSSHP	I	DON	48.00
15-Jun-2023	141,160		681739	38-100-PMA	Service A PMI	20-Jun-2023 12:55:35	OTSSHP	P	DON	79.11
22-Feb-2024	141,192		740777	06-100-009	Inspect Safety Check	26-Feb-2024 10:32:16	BTRUCK	N	DON	54.91
02-Apr-2024	141,190		749654	02-002	Clean Cab & Sheet Metal	04-Apr-2024 08:59:06	BSETUP	Z	DON	365.41
02-Apr-2024	141,190		749654	25-051	Remove General Accessories		BSETUP	Z	WND	64.59

Unit No: G0364 Count: 121 **31,840.53**