

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: N1265 - 2018 CAT 304E2										
11-Apr-2018	3	0	331010	14-051-009	Install Fire Extinguisher	11-Apr-2018 16:09:20	BHVYEQ	Q	DON	29.05
11-Apr-2018	3	0	331010	14-063-003	Install Transceiver - GPS Tracker	11-Apr-2018 16:09:22	BHVYEQ	Q	DON	347.95
08-Feb-2019	657	0	371790	03-051-009	Replace Fire Extinguisher	13-Feb-2019 07:17:22	BHVYEQ	I	DON	28.76
08-Feb-2019	657	0	371790	03-514-002	Replace Shanks or Teeth	13-Feb-2019 07:17:45	BHVYEQ	I	DON	217.69
08-Feb-2019	657	0	371790	06-100-PMA	Inspect A PMI	20-Feb-2019 13:05:14	BHVYEQ	P	DON	427.05
08-Feb-2019	657	0	371790	24-065-004	Repair Cylinder	20-Feb-2019 13:04:36	BHVYEQ	W	DON	71.33
08-Feb-2019	657	0	371790	38-100-PMA	Service A PMI	13-Feb-2019 06:39:08	BHVYEQ	P	DON	0.00
29-Oct-2019	1,337	0	410109	02-330	Clean Excavator	04-Nov-2019 17:00:12	BWASH	N	DON	259.68
29-Oct-2019	1,337	0	410109	03-051-009	Replace Fire Extinguisher	04-Nov-2019 11:23:14	BHVYEQ	P	DON	32.42
29-Oct-2019	1,337	0	410109	03-514-005	Replace Pins	31-Oct-2019 08:25:01	BBKHOE	I	DON	177.91
29-Oct-2019	1,337	0	410109	06-100-PMB	Inspect B PMI	04-Nov-2019 11:22:44	BHVYEQ	P	DON	196.56
29-Oct-2019	1,337	0	410109	14-065-004	Install Cylinder	04-Nov-2019 10:36:21	BBKHOE	I	DON	90.63
29-Oct-2019	1,337	0	410109	24-065-004	Repair Cylinder	08-Nov-2019 08:47:48	BHVYEQ	I	DON	514.41
29-Oct-2019	1,337	0	410109	24-513-002	Repair Quick Attachment	04-Nov-2019 11:22:53	BBKHOE	I	DON	71.02
29-Oct-2019	1,337	0	410109	25-065-004	Remove Cylinder	04-Nov-2019 11:23:08	BBKHOE	I	DON	53.72
29-Oct-2019	1,337	0	410109	38-100-PMC	Service C PMI	04-Nov-2019 11:22:48	BBKHOE	P	DON	431.47
24-Feb-2020	1,342	0	427781	06-330	Inspect Excavator	24-Feb-2020 10:33:23	BHVYEQ	P	DON	30.69
27-Apr-2020	1,355	0	437999	03-002-061	Replace Seat Cushion	19-May-2020 07:50:50	MA0800	I	DON	612.53
27-Apr-2020	1,355	0	437999	03-044-007	Replace Throttle Controls	19-May-2020 07:50:29	MA0800	I	DON	213.84
27-Apr-2020	1,355	0	437999	35-044-007	Diagnose Throttle Controls	19-May-2020 07:50:16	MA0800	O	DON	14.25
20-Jul-2020	1,655	0	452567	06-100-PMA	Inspect A PMI	27-Jul-2020 05:24:27	MA0800	P	DON	28.49
19-Oct-2020	1,887	0	468453	06-100-PMA	Inspect A PMI	23-Oct-2020 11:24:25	MA0722	P	DON	76.57
21-Jan-2021	2,090	0	483647	03-002-031	Replace Body Moldings - Exterior	29-Jan-2021 06:48:20	BHVYEQ	I	DON	78.64
21-Jan-2021	2,090	0	483647	03-032-001	Replace Battery	26-Jan-2021 15:28:06	BHVYEQ	I	DON	292.14
21-Jan-2021	2,090	0	483647	03-045-023	Replace Engine Belts	29-Jan-2021 06:49:09	BHVYEQ	I	DON	137.46
21-Jan-2021	2,090	0	483647	03-065-007	Replace Hoses & Fittings	11-Mar-2021 05:45:25	BHVYEQ	I	DON	205.03
21-Jan-2021	2,090	0	483647	03-065-008	Replace Line / Tubing Assembly	28-Jan-2021 12:46:21	BHVYEQ	I	DON	717.44
21-Jan-2021	2,090	0	483647	03-514-002	Replace Shanks or Teeth	11-Mar-2021 05:45:31	BHVYEQ	I	DON	357.36
21-Jan-2021	2,090	0	483647	06-100-PMC	Inspect C PMI	29-Jan-2021 06:55:35	BHVYEQ	P	DON	473.02

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: N1265 - 2018 CAT 304E2										
21-Jan-2021 08	2,090	0	483647	12-330	Refinish Excavator	11-Mar-2021 10:09:03	BBODY	K	DON	277.66
21-Jan-2021 08	2,090	0	483647	15-330	Paint Prep Excavator	11-Mar-2021 10:09:00	BBODY	K	DON	431.62
21-Jan-2021 08	2,090	0	483647	24-065-004	Repair Cylinder	17-Feb-2021 06:41:09	BHVYEQ	I	DON	5,048.47
21-Jan-2021 08	2,090	0	483647	24-330-002	Repair Undercarriage (Tracks&Rollers)	29-Jan-2021 11:17:15	BHVYEQ	I	DON	566.97
21-Jan-2021 08	2,090	0	483647	24-330-004	Repair Boom and Stick Assembly	17-Feb-2021 06:40:33	BHVYEQ	I	DON	5,129.77
21-Jan-2021 08	2,090	0	483647	24-330-015	Repair Quik-Attach Assembly	11-Mar-2021 05:19:37	BHVYEQ	I	DON	476.41
21-Jan-2021 08	2,090	0	483647	24-515	Repair Blade	16-Feb-2021 06:09:20	BHVYEQ	I	DON	735.28
21-Jan-2021 08	2,090	0	483647	38-100-PMC	Service C PMI	11-Mar-2021 05:19:25	BHVYEQ	P	DON	378.03
17-Feb-2021 1			488650	02-330	Clean Excavator	17-Feb-2021 16:04:31	BWASH	N	DON	220.40
29-Mar-2021 1	2,090	0	497204	03-063-001	Replace Antenna - RF	29-Mar-2021 13:02:40	BHVYEQ	W	DON	0.00
29-Mar-2021 1	2,090	0	497204	24-065-006	Repair Filters, Strainers, Screens & Housing	29-Mar-2021 13:01:54	BHVYEQ	W	DON	317.44
29-Mar-2021 1	2,090	0	497204	37-049-002	Calibrate ECM Module	29-Mar-2021 13:00:09	BHVYEQ	W	DON	0.00
14-Sep-2021 1	2,422	0	531241	03-063-003	Replace Transceiver - GPS Tracker	17-Sep-2021 10:17:50	SCHED	Q	DON	293.97
14-Sep-2021 1	2,422	0	531241	03-065-008	Replace Line / Tubing Assembly	17-Sep-2021 10:18:00	BHVYEQ	E	DON	834.68
14-Sep-2021 1	2,422	0	531241	06-100-PMA	Inspect A PMI	17-Sep-2021 10:17:53	SCHED	P	DON	50.72
14-Sep-2021 1	2,422	0	531241	06-100-PMB	Inspect B PMI	17-Sep-2021 10:17:56	SCHED	P	DON	0.00
14-Sep-2021 1	2,422	0	531241	06-330-015	Inspect Quik-Attach Assembly	17-Sep-2021 10:18:10	BHVYEQ	I	DON	33.30
14-Sep-2021 1	2,422	0	531241	24-002-011	Repair Cab Accessories - Interior	17-Sep-2021 10:17:58	BHVYEQ	I	DON	73.26
14-Sep-2021 1	2,422	0	531241	24-002-037	Repair Seat Assembly	17-Sep-2021 10:18:08	BHVYEQ	I	DON	8.92
14-Sep-2021 1	2,422	0	531241	24-034-014	Repair Auxiliary Work / Flood Light	17-Sep-2021 10:18:03	BHVYEQ	I	DON	10.87
14-Sep-2021 1	2,422	0	531241	24-330-015	Repair Quik-Attach Assembly	17-Sep-2021 10:50:17	BHVYEQ	I	DON	567.00
14-Sep-2021 1	2,422	0	531241	38-100-PMA	Service A PMI	17-Sep-2021 10:18:05	BHVYEQ	I	DON	121.75
05-Jan-2022 1	2,680	0	557325	01-034-014	Adjust Auxiliary Work / Flood Light	06-Jan-2022 10:29:50	OTSSHP	I	DON	7.71
05-Jan-2022 1	2,680	0	557325	03-002-017	Replace Cab Or Front Door Panels	17-Jan-2022 12:29:44	OTSSHP	I	DON	302.84
05-Jan-2022 1	2,680	0	557325	03-051-009	Replace Fire Extinguisher	06-Jan-2022 09:34:22	OTSSHP	I	DON	87.62
05-Jan-2022 1	2,680	0	557325	03-514-002	Replace Shanks or Teeth	06-Jan-2022 08:59:21	OTSSHP	N	DON	42.78
05-Jan-2022 1	2,680	0	557325	06-100-PMA	Inspect A PMI	06-Jan-2022 07:37:00	OTSSHP	P	DON	62.43
05-Jan-2022 1	2,680	0	557325	38-100-PMA	Service A PMI	13-Jan-2022 10:31:28	OTSSHP	P	DON	166.63
14-Apr-2022 0	2,806	0	581768	06-330	Inspect Excavator	14-Apr-2022 10:49:37	TRK400	O	DON	178.62

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: N1265 - 2018 CAT 304E2										
05-Jun-2022 2:	2,959	0	593546	03-065-007	Replace Hoses & Fittings	09-Jun-2022 16:00:03	LAVSHP	I	DON	285.62
05-Jun-2022 2:	2,959	0	593546	03-111-001	Replace Track	17-Jun-2022 12:32:22	LAVSHP	O	DON	3,167.83
05-Jun-2022 2:	2,959	0	593546	03-111-005	Replace Sprocket	17-Jun-2022 12:31:56	LAVSHP	B	DON	746.79
05-Jun-2022 2:	2,959	0	593546	03-514-002	Replace Shanks or Teeth	17-Jun-2022 10:19:21	LAVSHP	O	DON	36.38
05-Jun-2022 2:	2,959	0	593546	06-100-PMA	Inspect A PMI	09-Jun-2022 11:08:51	LAVSHP	P	DON	64.44
05-Jun-2022 2:	2,959	0	593546	38-100-PMA	Service A PMI	10-Jun-2022 06:01:39	LAVSHP	P	DON	133.23
11-Aug-2022 0	3,104	0	608801	06-100-PMA	Inspect A PMI	11-Aug-2022 09:20:44	LAVSHP	P	DON	70.44
11-Aug-2022 0	3,104	0	608801	38-100-PMA	Service A PMI	11-Aug-2022 10:06:14	LAVSHP	P	DON	67.78
06-Oct-2022 0	3,223	0	622187	24-330-013	Repair Operator Controls	06-Oct-2022 07:30:49	LAVSHP	B	DON	283.43
25-Oct-2022 0	3,267	0	626841	07-044-016	Lubricate Tank - Fuel Auxiliary	25-Oct-2022 07:09:09	LAVSHP	P	DON	16.62
08-Mar-2023 0	3,294	0	657692	03-032-001	Replace Battery	08-Mar-2023 17:26:31	LAVSHP	I	DON	134.65
08-Mar-2023 0	3,294	0	657692	04-330-001	Rig / Unrig Bucket and Attachments	09-Mar-2023 13:13:43	LAVSHP	O	DON	22.98
08-Mar-2023 0	3,294	0	657692	06-100-PMB	Inspect B PMI	08-Mar-2023 10:40:23	LAVSHP	P	DON	144.36
08-Mar-2023 0	3,294	0	657692	38-100-PMB	Service B PMI	08-Mar-2023 13:37:02	LAVSHP	P	DON	402.13
04-Apr-2023 0	3,383	0	664269	03-514-002	Replace Shanks or Teeth	04-Apr-2023 06:52:03	LAVSHP	E	DON	136.56
18-Apr-2023 0	3,434	0	667860	03-514-002	Replace Shanks or Teeth	18-Apr-2023 07:10:29	LAVSHP	E	DON	26.44
09-Jun-2023 0:	3,577	0	680099	03-051-003	Replace Hourmeter	09-Jun-2023 12:28:31	LAVSHP	I	DON	163.20
09-Jun-2023 0:	3,577	0	680099	03-514-002	Replace Shanks or Teeth	09-Jun-2023 11:41:10	LAVSHP	E	DON	152.20
09-Jun-2023 0:	3,577	0	680099	06-100-PMA	Inspect A PMI	09-Jun-2023 09:43:28	LAVSHP	P	DON	162.40
09-Jun-2023 0:	3,577	0	680099	24-065-007	Repair Hoses & Fittings	13-Jun-2023 14:41:17	LAVSHP	O	DON	96.89
09-Jun-2023 0:	3,577	0	680099	38-100-PMA	Service A PMI	09-Jun-2023 14:03:29	LAVSHP	P	DON	190.50
19-Oct-2023 0:	3,899	0	714126	06-100-PMA	Inspect A PMI	19-Oct-2023 10:28:42	LAVSHP	P	DON	82.91
19-Oct-2023 0:	3,899	0	714126	38-100-PMA	Service A PMI	19-Oct-2023 13:10:40	LAVSHP	P	DON	159.23
06-Dec-2023 1	4,088	0	725197	03-514-002	Replace Shanks or Teeth	06-Dec-2023 13:54:43	LAVSHP	L	DON	156.75
06-Dec-2023 1	4,088	0	725197	07-044-016	Lubricate Tank - Fuel Auxiliary	06-Dec-2023 13:57:25	LAVSHP	P	DON	16.42
01-Mar-2024 0	4,199	0	742504	06-100-PMA	Inspect A PMI	01-Mar-2024 10:16:12	ME1371	P	DON	174.83
01-Mar-2024 0	4,199	0	742504	38-100-PMA	Service A PMI	04-Mar-2024 11:14:04	ME1371	P	DON	378.06
01-Mar-2024 0	4,199	0	742504	95-MSC-004	Travel Travel Time - To/From Job Site	04-Mar-2024 10:19:31	ME1371	P	DON	52.62
10-Apr-2024 0	4,242	0	751684	06-100-PMA	Inspect A PMI	10-Apr-2024 15:48:44	LAVSHP	P	DON	322.33

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: N1265 - 2018 CAT 304E2										
15-Apr-2024 0	4,247	0	752659	06-330	Inspect Excavator	19-Apr-2024 10:25:43	BHVYEQ	N	DON	209.04
15-Apr-2024 0	4,247	0	752659	03-051-003	Replace Hourmeter	19-Apr-2024 08:14:04	BHVYEQ	N	DON	190.54
15-Apr-2024 0	4,247	0	752659	02-330	Clean Excavator	18-Apr-2024 16:00:01	BWASH	N	DON	208.95

Unit No: N1265      Count: 90      31,068.84