

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: P1486 - 2019 CAT 982M										
30-Jul-2019 09	13	0	396414	03-045-011	Replace Filter Assembly - Oil	31-Jul-2019 05:37:16	BHVEEQ	P	DON	55.13
30-Jul-2019 09	13	0	396414	14-019-007	Install Hose, Tubing & Connectors	31-Jul-2019 05:37:16	BHVEEQ	Q	DON	19.54
30-Jul-2019 09	13	0	396414	14-051-009	Install Fire Extinguisher	31-Jul-2019 05:35:45	BHVEEQ	Q	DON	30.97
30-Jul-2019 09	13	0	396414	14-052-005	Install Transmitter - CB	31-Jul-2019 05:35:47	BHVEEQ	Q	DON	203.55
30-Jul-2019 09	13	0	396414	14-063-003	Install Transceiver - GPS Tracker	31-Jul-2019 05:35:43	BHVEEQ	Q	DON	514.96
30-Jul-2019 09	13	0	396414	24-360-001	Repair Bucket and Attachments	31-Jul-2019 05:35:49	BHVEEQ	I	DON	0.00
25-Sep-2019 0	313	0	404445	06-100-PMA	Inspect A PMI	25-Sep-2019 04:52:07	BHVEEQ	P	DON	0.00
25-Sep-2019 0	313	0	404445	38-100-PMA	Service A PMI	25-Sep-2019 04:52:11	BHVEEQ	P	DON	959.39
06-Nov-2019 1	329	0	411341	24-360-001	Repair Bucket and Attachments	06-Nov-2019 14:17:34	BHVEEQ	O	DON	69.43
22-Nov-2019 1	357	0	414009	03-002-024	Replace Glass / Windshield	02-Dec-2019 06:54:43	BHVEEQ	I	DON	329.06
03-Dec-2019 0	379	0	414875	06-100-PMA	Inspect A PMI	05-Dec-2019 06:55:20	BHVEEQ	P	DON	0.00
03-Dec-2019 0	379	0	414875	38-100-PMA	Service A PMI	03-Dec-2019 06:46:10	BHVEEQ	P	DON	127.86
10-Jan-2020 1	503	0	420545	03-045-011	Replace Filter Assembly - Oil	10-Jan-2020 14:24:21	BHVEEQ	P	DON	18.27
10-Jan-2020 1	503	0	420545	07-019-002	Lubricate Grease Pump	10-Jan-2020 14:24:49	BHVEEQ	O	DON	110.35
28-Jan-2020 1	546	0	423493	03-001-016	Replace Filter - Cab Ventilation	05-Feb-2020 06:16:07	BHVEEQ	P	DON	47.00
28-Jan-2020 1	546	0	423493	03-045-011	Replace Filter Assembly - Oil	05-Feb-2020 06:16:07	BHVEEQ	P	DON	17.20
28-Jan-2020 1	546	0	423493	03-052-005	Replace Transmitter - CB	28-Jan-2020 16:28:02	BHVEEQ	O	DON	88.04
06-Mar-2020 1	0	0	429802	02-360	Clean Loader / Skid-Steer	24-Mar-2020 06:43:11	BWASH	N	DON	338.43
06-Mar-2020 1	0	0	429802	03-930-001	Replace Printer	25-Mar-2020 08:55:15	BHVEEQ	W	DON	0.00
06-Mar-2020 1	0	0	429802	06-100-PMB	Inspect B PMI	25-Mar-2020 08:55:00	BHVEEQ	P	DON	19.27
06-Mar-2020 1	0	0	429802	14-019-001	Install Reservoir & Lines	25-Mar-2020 08:55:03	BHVEEQ	N	DON	185.65
06-Mar-2020 1	0	0	429802	14-052-005	Install Transmitter - CB	09-Mar-2020 16:39:13	BHVEEQ	I	DON	91.42
06-Mar-2020 1	0	0	429802	21-514-003	Fabricate Liner	14-Mar-2020 12:00:28	BWELD	C	DON	4,346.68
06-Mar-2020 1	0	0	429802	31-360-009	Rotate Bucket Tooth / Cutting Edge	25-Mar-2020 08:55:01	BHVEEQ	N	DON	16.98
06-Mar-2020 1	0	0	429802	37-049-002	Calibrate ECM Module	25-Mar-2020 08:55:15	BHVEEQ	W	DON	0.00
06-Mar-2020 1	0	0	429802	37-930	Calibrate Scale	25-Mar-2020 08:55:15	BHVEEQ	N	DON	218.20
06-Mar-2020 1	0	0	429802	38-100-PMC	Service C PMI	10-Mar-2020 08:55:14	BHVEEQ	P	DON	1,116.64
15-May-2020 1	688	0	441029	06-100-PMA	Inspect A PMI	15-May-2020 12:47:29	BHVEEQ	P	DON	0.00
15-May-2020 1	688	0	441029	38-100-PMA	Service A PMI	15-May-2020 12:47:24	BHVEEQ	P	DON	262.98

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: P1486 - 2019 CAT 982M										
15-May-2020	688	0	441029	03-019-001	Replace Reservoir & Lines	15-May-2020 13:10:12	BHVEEQ	O	DON	271.74
15-Jun-2020	0	0	445455	03-065-002	Replace Accumulator	15-Jun-2020 05:52:23	BHVEEQ	W	DON	499.10
19-Jun-2020	784	0	446550	03-041-006	Replace Filter - Inner	19-Jun-2020 14:18:36	BHVEEQ	P	DON	55.99
19-Jun-2020	784	0	446550	03-041-007	Replace Filter - Outer	19-Jun-2020 14:18:50	BHVEEQ	P	DON	23.77
19-Jun-2020	784	0	446550	03-044-002	Replace Filters	19-Jun-2020 14:19:15	BHVEEQ	P	DON	88.23
22-Jul-2020	828	0	451883	06-100-PMA	Inspect A PMI	22-Jul-2020 08:17:07	BHVEEQ	P	DON	0.00
22-Jul-2020	828	0	451883	38-100-PMA	Service A PMI	22-Jul-2020 08:17:04	BHVEEQ	P	DON	195.28
13-Aug-2020	0	0	455794	37-049-002	Calibrate ECM Module	13-Aug-2020 04:47:53	BHVEEQ	W	DON	449.20
21-Aug-2020	887	0	457362	38-100-PMA	Service A PMI	21-Aug-2020 07:15:24	BHVEEQ	P	DON	195.34
14-Sep-2020	1,036	0	461201	24-930-001	Repair Printer	14-Sep-2020 10:35:54	BHVEEQ	B	DON	151.22
30-Sep-2020	1,168	0	463985	03-001-016	Replace Filter - Cab Ventilation	30-Sep-2020 08:31:46	BHVEEQ	P	DON	55.33
30-Sep-2020	1,168	0	463985	03-045-011	Replace Filter Assembly - Oil	30-Sep-2020 08:30:51	BHVEEQ	P	DON	18.34
12-Oct-2020	1,249	0	466044	03-001-016	Replace Filter - Cab Ventilation	12-Oct-2020 12:42:06	BHVEEQ	P	DON	141.09
22-Oct-2020	1,331	0	468144	03-044-002	Replace Filters	22-Oct-2020 08:35:20	BHVEEQ	P	DON	0.00
22-Oct-2020	1,331	0	468144	03-045-011	Replace Filter Assembly - Oil	22-Oct-2020 08:35:03	BHVEEQ	P	DON	143.28
26-Oct-2020	1,362	0	468814	24-930	Repair Scale	26-Oct-2020 15:19:33	BHVEEQ	O	DON	530.87
04-Nov-2020	1,425	0	470402	03-052-005	Replace Transmitter - CB	04-Nov-2020 15:16:55	BHVEEQ	Q	DON	76.05
12-Nov-2020	0	0	471731	03-002-060	Replace Seat Belt	12-Nov-2020 10:04:17	BHVEEQ	O	DON	281.73
12-Nov-2020	0	0	471731	03-049-002	Replace ECM Module	16-Nov-2020 07:51:50	BHVEEQ	W	DON	299.46
19-Nov-2020	1,516	0	473086	03-041-006	Replace Filter - Inner	19-Nov-2020 13:30:00	BHVEEQ	P	DON	27.18
19-Nov-2020	1,516	0	473086	03-041-007	Replace Filter - Outer	19-Nov-2020 13:30:11	BHVEEQ	P	DON	66.44
19-Nov-2020	1,516	0	473086	03-044-002	Replace Filters	19-Nov-2020 13:30:37	BHVEEQ	P	DON	44.11
19-Nov-2020	1,516	0	473086	03-045-011	Replace Filter Assembly - Oil	19-Nov-2020 13:30:26	BHVEEQ	P	DON	18.33
16-Dec-2020	0	0	477696	06-360	Inspect Loader / Skid-Steer	18-Dec-2020 11:24:48	BHVEEQ	P	DON	165.76
16-Dec-2020	0	0	477696	03-019-007	Replace Hose, Tubing & Connectors	17-Dec-2020 16:47:36	BHVEEQ	I	DON	112.33
16-Dec-2020	0	0	477696	03-031-006	Replace Belt - Alternator	17-Dec-2020 16:47:24	BHVEEQ	I	DON	127.96
16-Dec-2020	0	0	477696	03-360-012	Replace Heel Plate	18-Dec-2020 11:25:13	BHVEEQ	I	DON	537.85
16-Dec-2020	0	0	477696	38-100-PMC	Service C PMI	08-Jan-2021 10:52:13	BHVEEQ	N	DON	1,009.33
16-Dec-2020	0	0	477696	24-514	Repair Bucket	31-Dec-2020 12:45:48	BWELD	N	DON	88.40

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: P1486 - 2019 CAT 982M										
16-Dec-2020	0	477696	02-360	02-360	Clean Loader / Skid-Steer	06-Jan-2021 16:18:38	BWASH	N	DON	314.56
26-Apr-2021	1,798	502843	38-100-PMA	38-100-PMA	Service A PMI	26-Apr-2021 11:11:22	BHVEYEQ	P	DON	259.33
26-Apr-2021	1,798	502843	06-100-PMA	06-100-PMA	Inspect A PMI	26-Apr-2021 11:16:06	SCHEDE	P	DON	0.00
12-May-2021	1,847	506150	03-043-026	03-043-026	Replace Exhaust Cooler	12-May-2021 08:44:21	BHVEYEQ	W	DON	152.59
24-May-2021	1,877	508663	24-360-008	24-360-008	Repair Operator Controls	24-May-2021 13:04:48	BHVEYEQ	B	DON	1,197.04
01-Jun-2021	2,017	510052	24-360-006	24-360-006	Repair Lift Arm Assembly	01-Jun-2021 17:35:37	BHVEYEQ	O	DON	281.85
22-Jun-2021	2,017	514220	03-043-004	03-043-004	Replace Turbocharger	22-Jun-2021 08:48:21	BHVEYEQ	W	DON	207.23
23-Jun-2021	2,017	514700	03-044-002	03-044-002	Replace Filters	23-Jun-2021 16:42:16	BHVEYEQ	O	DON	44.96
23-Jun-2021	2,017	514700	03-045-011	03-045-011	Replace Filter Assembly - Oil	23-Jun-2021 16:42:40	BHVEYEQ	O	DON	18.66
02-Jul-2021	2,233	516518	24-049-001	24-049-001	Repair ECM Fault Code	07-Jul-2021 12:52:45	BHVEYEQ	O	DON	245.56
02-Jul-2021	2,176	521059	03-017-001	03-017-001	Repair Bucket Tooth / Cutting Edge	14-Jul-2021 10:25:38	BHVEYEQ	O	DON	33.89
14-Jul-2021	2,233	524490	03-049-003	03-049-003	Replace Tire - Pneumatic	02-Aug-2021 07:37:29	BTIRE	B	DON	1,228.17
11-Aug-2021	2,307	524490	24-049-004	24-049-004	Replace ECM Wiring Harness	11-Aug-2021 14:36:38	BHVEYEQ	B	DON	1,700.31
19-Aug-2021	2,326	526193	03-019-007	03-019-007	Repair ECM Sensor	11-Aug-2021 14:38:55	BHVEYEQ	B	DON	367.25
23-Aug-2021	2,415	526797	24-017-001	24-017-001	Replace Hose, Tubing & Connectors	24-Aug-2021 10:41:46	BHVEYEQ	I	DON	81.76
16-Sep-2021	2,415	531693	03-041-006	03-041-006	Repair Tire - Pneumatic	23-Aug-2021 15:44:35	BTIRE	B	DON	614.08
16-Sep-2021	3,727	548712	03-041-007	03-041-007	Replace Filter - Inner	16-Sep-2021 06:08:34	BHVEYEQ	O	DON	24.51
23-Nov-2021	3,817	551260	03-065-007	03-065-007	Replace Filter - Outer	16-Sep-2021 06:09:44	BHVEYEQ	O	DON	60.90
06-Dec-2021	3,817	551260	03-065-007	03-065-007	Replace Hoses & Fittings	06-Dec-2021 04:38:58	BHVEYEQ	N	DON	63.59
06-Dec-2021	3,817	551260	03-778-041	03-778-041	Replace Control Solenoids - Hydraulic	23-Nov-2021 10:15:41	BHVEYEQ	O	DON	155.07
06-Dec-2021	3,817	551260	03-065-007	03-065-007	Replace Hoses & Fittings	06-Jan-2022 05:12:44	BHVEYEQ	I	DON	660.27
06-Dec-2021	3,817	551260	06-360	06-360	Inspect Loader / Skid-Steer	06-Jan-2022 05:12:34	BHVEYEQ	N	DON	8.28
06-Dec-2021	3,817	551260	06-100-PMC	06-100-PMC	Inspect C PMI	06-Jan-2022 05:12:37	BHVEYEQ	P	DON	7.77
06-Dec-2021	3,817	551260	38-100-PMC	38-100-PMC	Service C PMI	06-Jan-2022 05:12:41	BHVEYEQ	P	DON	1,184.22
06-Dec-2021	3,817	551260	02-043-009	02-043-009	Clean Diesel Particulate Filter - DPF	17-Dec-2021 17:02:39	BHVEYEQ	P	DON	1,186.89
06-Dec-2021	3,817	551260	02-360	02-360	Clean Loader / Skid-Steer	30-Dec-2021 11:13:17	BWASH	N	DON	657.78
06-Dec-2021	3,817	551260	37-049-002	37-049-002	Calibrate ECM Module	14-Feb-2022 06:38:18	BHVEYEQ	W	DON	0.00
06-Dec-2021	3,817	551260	37-930	37-930	Calibrate Scale	14-Feb-2022 06:38:21	BHVEYEQ	N	DON	376.46
06-Dec-2021	3,817	551260	24-360-001	24-360-001	Repair Bucket and Attachments	07-Feb-2022 15:43:52	BWELD	I	DON	315.61

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: P1486 - 2019 CAT 982M										
06-Dec-2021 0	3,817	0	551260	03-051-009	Replace Fire Extinguisher	14-Feb-2022 06:46:19	BHVYEQ	Q	DON	65.83
06-Dec-2021 0	3,817	0	551260	03-930-001	Replace Printer	14-Feb-2022 06:41:53	BHVYEQ	W	DON	0.00
06-Dec-2021 0	3,817	0	551260	24-045-001	Repair Front Covers	14-Feb-2022 06:40:42	BHVYEQ	W	DON	0.00
06-Dec-2021 0	3,817	0	551260	24-065-020	Repair Control Valve	14-Feb-2022 06:43:09	BHVYEQ	W	DON	0.00
31-Jan-2022 1:			563026	03-017-001	Replace Tire - Pneumatic	09-Feb-2022 13:15:51	BTIRE	P	DON	45,374.86
23-Feb-2022 1	3,817	0	569376	03-002-035	Replace Windshield Wiper & Washer	01-Apr-2022 10:21:37	BHVYEQ	I	DON	72.71
23-Feb-2022 1	3,817	0	569376	03-019-007	Replace Hose, Tubing & Connectors	01-Apr-2022 10:21:39	BHVYEQ	O	DON	26.63
11-Apr-2022 1	3,817	0	581075	03-052-005	Replace Transmitter - CB	11-Apr-2022 15:58:07	BHVYEQ	Q	DON	95.06
11-Apr-2022 1	3,817	0	581075	03-052-013	Replace Antenna and Mounting	11-Apr-2022 15:58:52	BHVYEQ	O	DON	127.15
11-Apr-2022 1	3,817	0	581075	14-043	Install Exhaust System	11-Apr-2022 16:00:21	BHVYEQ	O	DON	128.71
29-Apr-2022 1	3,817	0	585451	03-041-006	Replace Filter - Inner	29-Apr-2022 14:45:24	BHVYEQ	O	DON	24.54
29-Apr-2022 1	3,817	0	585451	03-041-007	Replace Filter - Outer	29-Apr-2022 14:45:10	BHVYEQ	O	DON	60.94
29-Apr-2022 1	3,817	0	585451	03-045-011	Replace Filter Assembly - Oil	29-Apr-2022 14:44:56	BHVYEQ	O	DON	49.05
27-May-2022 (4,280	0	591807	24-049-001	Repair ECM Fault Code	27-May-2022 08:21:24	BHVYEQ	O	DON	574.84
17-Jun-2022 0	4,280	0	596515	03-002-035	Replace Windshield Wiper & Washer	17-Jun-2022 07:48:56	BHVYEQ	O	DON	112.58
11-Jul-2022 14	4,531	0	601688	03-043-030	Replace Aftertreatment Regeneration Device (A	11-Jul-2022 14:23:05	BHVYEQ	W	DON	485.61
15-Jul-2022 11	4,531	0	602856	03-002-035	Replace Windshield Wiper & Washer	20-Jul-2022 07:44:43	BHVYEQ	O	DON	351.16
18-Aug-2022 C	4,531	0	610432	06-100-PMA	Inspect A PMI	18-Aug-2022 08:21:11	SCHEDE	P	DON	0.00
18-Aug-2022 C	4,531	0	610432	38-100-PMA	Service A PMI	18-Aug-2022 08:20:55	BHVYEQ	O	DON	215.74
13-Sep-2022 1	4,531	0	616001	24-019-007	Repair Hose, Tubing & Connectors	13-Sep-2022 11:32:20	BHVYEQ	O	DON	61.54
19-Oct-2022 1:	5,344	0	625492	03-360-009	Replace Bucket Tooth / Cutting Edge	19-Oct-2022 14:15:22	BHVYEQ	E	DON	2,064.01
24-Jan-2023 1:	5,602	0	647610	02-002	Clean Cab & Sheet Metal	26-Jan-2023 11:36:36	BHVYEQ	N	DON	82.65
24-Jan-2023 1:	5,602	0	647610	02-360	Clean Loader / Skid-Steer	06-Feb-2023 13:38:56	BWASH	N	DON	510.86
24-Jan-2023 1:	5,602	0	647610	03-019-007	Replace Hose, Tubing & Connectors	16-Feb-2023 10:22:08	BHVYEQ	I	DON	467.06
24-Jan-2023 1:	5,602	0	647610	03-031-006	Replace Belt - Alternator	16-Feb-2023 11:37:09	BHVYEQ	I	DON	138.20
24-Jan-2023 1:	5,602	0	647610	03-034-006	Replace Warning Lamps - Special Application	09-Mar-2023 12:03:07	BHVYEQ	I	DON	61.74
24-Jan-2023 1:	5,602	0	647610	03-043-031	Replace Manifold - DEF	20-Feb-2023 10:11:30	BHVYEQ	I	DON	786.93
24-Jan-2023 1:	5,602	0	647610	03-049-002	Replace ECM Module	30-Mar-2023 09:25:37	BHVYEQ	W	DON	0.00
24-Jan-2023 1:	5,602	0	647610	03-065-007	Replace Hoses & Fittings	21-Feb-2023 06:45:03	BHVYEQ	I	DON	1,487.94

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: P1486 - 2019 CAT 982M										
24-Jan-2023 1:	5,602	0	647610	03-360-012	Replace Heel Plate	26-Jan-2023 15:58:42	BHVYEQ	I	DON	601.46
24-Jan-2023 1:	5,602	0	647610	06-100-PMB	Inspect B PMI	21-Feb-2023 10:17:52	BHVYEQ	P	DON	0.00
24-Jan-2023 1:	5,602	0	647610	06-360	Inspect Loader / Skid-Steer	21-Feb-2023 06:44:49	BHVYEQ	P	DON	64.95
24-Jan-2023 1:	5,602	0	647610	24-052-005	Repair Transmitter - CB	26-Jan-2023 12:52:05	BHVYEQ	I	DON	105.17
24-Jan-2023 1:	5,602	0	647610	34-045-002	Reseal Cylinder Block & Crankcase	20-Feb-2023 07:57:08	BHVYEQ	I	DON	137.84
24-Jan-2023 1:	5,602	0	647610	37-930	Calibrate Scale	30-Mar-2023 09:23:41	BHVYEQ	N	DON	570.20
24-Jan-2023 1:	5,602	0	647610	38-100-PMC	Service C PMI	21-Feb-2023 06:44:55	BHVYEQ	P	DON	1,448.63
24-Jan-2023 1:	5,602	0	647610	B3-049-002	Program ECM Module	30-Mar-2023 09:21:17	BHVYEQ	W	DON	0.00
13-Apr-2023 0	5,652	0	666788	03-052-005	Replace Transmitter - CB		BHVYEQ	O	CAN	0.00
13-Apr-2023 0	5,652	0	666788	03-052-013	Replace Antenna and Mounting	13-Apr-2023 08:00:27	BHVYEQ	O	DON	66.96
13-Apr-2023 1	5,652	0	666924	03-001-016	Replace Filter - Cab Ventilation	13-Apr-2023 13:40:37	BHVYEQ	O	DON	64.12
13-Apr-2023 1	5,652	0	666924	03-041-007	Replace Filter - Outer	13-Apr-2023 13:39:30	BHVYEQ	O	DON	76.93
13-Apr-2023 1	5,652	0	666924	03-041-006	Replace Filter - Inner	13-Apr-2023 13:40:06	BHVYEQ	O	DON	27.72
17-May-2023 1	5,892	0	675104	03-041-007	Replace Filter - Outer	17-May-2023 10:21:41	BHVYEQ	O	DON	78.06
17-May-2023 1	5,892	0	675104	03-052-005	Replace Transmitter - CB	17-May-2023 10:20:49	BHVYEQ	O	DON	103.48
17-May-2023 1	5,892	0	675104	03-041-006	Replace Filter - Inner	17-May-2023 10:22:10	BHVYEQ	O	DON	30.90
07-Jun-2023 1:	6,050	0	679743	03-045-011	Replace Filter Assembly - Oil	07-Jun-2023 14:54:03	BHVYEQ	O	DON	125.10
15-Jun-2023 0:	6,117	0	681618	24-001-001	Repair Air Conditioning Assembly	15-Jun-2023 14:03:46	TRK005	I	DON	388.66
23-Jun-2023 1:	6,185	0	683748	03-001-016	Replace Filter - Cab Ventilation	23-Jun-2023 12:34:20	BHVYEQ	O	DON	64.27
23-Jun-2023 1:	6,185	0	683748	03-041-006	Replace Filter - Inner	23-Jun-2023 12:33:56	BHVYEQ	O	DON	31.64
23-Jun-2023 1:	6,185	0	683748	03-041-007	Replace Filter - Outer	23-Jun-2023 12:33:29	BHVYEQ	O	DON	78.58
17-Jul-2023 11	6,322	0	688723	03-001-016	Replace Filter - Cab Ventilation	17-Jul-2023 11:13:38	BHVYEQ	O	DON	64.27
17-Jul-2023 11	6,322	0	688723	03-041-007	Replace Filter - Outer	17-Jul-2023 11:14:11	BHVYEQ	O	DON	78.59
17-Jul-2023 11	6,322	0	688723	03-041-006	Replace Filter - Inner	17-Jul-2023 11:14:30	BHVYEQ	O	DON	31.71
20-Sep-2023 0:	6,749	0	706524	03-043-020	Replace Pump - DEF	20-Sep-2023 04:43:55	BHVYEQ	B	DON	3,913.27
20-Sep-2023 0:	6,749	0	706524	03-043-024	Replace Lines - DEF	20-Sep-2023 04:45:00	BHVYEQ	B	DON	449.86
20-Sep-2023 0:	6,749	0	706524	03-043-031	Replace Manifold - DEF	20-Sep-2023 04:45:57	BHVYEQ	B	DON	809.83
21-Sep-2023 1:	6,761	0	707165	03-002-060	Replace Seat Belt	21-Sep-2023 16:30:57	BHVYEQ	O	DON	356.97
29-Sep-2023 0:	6,822	0	709087	03-043-024	Replace Lines - DEF	29-Sep-2023 09:28:22	BHVYEQ	B	DON	2,772.88

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: P1486 - 2019 CAT 982M										
11-Oct-2023 1	6,913	0	711977	03-001-016	Replace Filter - Cab Ventilation	11-Oct-2023 11:28:02	BHVYEQ	O	DON	64.27
11-Oct-2023 1	6,913	0	711977	03-041-006	Replace Filter - Inner	11-Oct-2023 11:27:41	BHVYEQ	O	DON	31.73
11-Oct-2023 1	6,913	0	711977	03-041-007	Replace Filter - Outer	11-Oct-2023 11:27:08	BHVYEQ	O	DON	78.57
11-Oct-2023 1	6,913	0	711977	03-045-014	Replace Ventilating System	11-Oct-2023 11:28:47	BHVYEQ	O	DON	29.80
22-Nov-2023 C	7,216	0	722288	06-100-PMB	Inspect B PMI	08-Dec-2023 05:34:30	BHVYEQ	P	DON	54.10
22-Nov-2023 C	7,216	0	722288	14-065-004	Install Cylinder	04-Dec-2023 12:03:30	BHVYEQ	N	DON	183.68
22-Nov-2023 C	7,216	0	722288	24-019-007	Repair Hose, Tubing & Connectors	08-Dec-2023 05:34:35	BHVYEQ	I	DON	168.00
22-Nov-2023 C	7,216	0	722288	25-065-004	Remove Cylinder	08-Dec-2023 05:34:32	BHVYEQ	N	DON	92.43
22-Nov-2023 C	7,216	0	722288	38-100-PMA	Service A PMI	04-Dec-2023 17:06:38	BHVYEQ	P	DON	326.02
16-Feb-2024 0	7,340	0	739404	03-002-024	Replace Glass / Windshield	19-Feb-2024 04:54:53	BHVYEQ	E	DON	318.61
18-Mar-2024 1	7,524	0	746441	02-360	Clean Loader / Skid-Steer	26-Mar-2024 13:17:04	BWASH	Z	DON	784.41
18-Mar-2024 1	7,524	0	746441	OS-360	Out-Service Loader / Skid-Steer	03-Apr-2024 07:47:18	BHVYEQ	Z	DON	304.66

Unit No: P1486

Count: 157

94,713.96