

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Q1267 - 2017 JOHN DEERE 310HL										
03-Jan-2017 1	3	0	271669	14-059-002	Install Pintle Hook Assembly	05-Jan-2017 12:25:45	BBKHOE	Q	DON	391.73
03-Jan-2017 1	3	0	271669	14-063-003	Install Transceiver - GPS Tracker	05-Jan-2017 12:25:41	BBKHOE	Q	DON	281.27
03-Jan-2017 1	3	0	271669	IS-310	In-Service Backhoe (Rubber Tire)	05-Jan-2017 11:15:00	BBKHOE	Q	DON	422.48
15-Feb-2017 1	3	0	283692	38-017-011	Service Tire - Foam Filled	15-Feb-2017 15:37:41	BTIRE	F	DON	1,034.22
09-Jun-2017 0	272	0	292182	03-100-PMA	Replace A PMI	09-Jun-2017 07:49:53	ROGSHP	P	DON	60.92
09-Jun-2017 0	272	0	292182	24-065-007	Repair Hoses & Fittings	09-Jun-2017 08:09:26	ROGSHP	B	DON	43.57
25-Aug-2017 0	547	0	302478	24-065-007	Repair Hoses & Fittings	25-Aug-2017 10:36:16	ROGSHP	B	DON	246.35
19-Sep-2017 0	624	0	305567	03-112-002	Replace Hydraulics - Stabilization	02-Oct-2017 07:37:46	ROGSHP	B	DON	4,071.00
19-Sep-2017 0	624	0	305567	07-100-PMA	Lubricate A PMI	19-Sep-2017 13:22:24	ROGSHP	P	DON	54.37
19-Sep-2017 0	624	0	305567	11-065-004	Rebuild Cylinder	05-Oct-2017 14:19:25	ROGSHP	B	DON	939.11
19-Sep-2017 0	624	0	305567	24-310-016	Repair Operator Controls	19-Sep-2017 13:45:11	ROGSHP	O	DON	43.38
08-Nov-2017 1	624	0	311831	03-065-007	Replace Hoses & Fittings	09-Nov-2017 16:14:33	ROGSHP	B	DON	588.99
07-Dec-2017 1	889	0	315240	03-017-001	Replace Tire - Pneumatic	11-Dec-2017 13:29:28	ROGSHP	N	DON	690.71
07-Dec-2017 1	889	0	315240	03-041-006	Replace Filter - Inner	07-Dec-2017 16:44:14	ROGSHP	P	DON	18.72
07-Dec-2017 1	889	0	315240	03-041-007	Replace Filter - Outer	07-Dec-2017 16:47:13	ROGSHP	P	DON	29.04
07-Dec-2017 1	889	0	315240	03-045-011	Replace Filter Assembly - Oil	07-Dec-2017 17:40:53	ROGSHP	P	DON	46.05
07-Dec-2017 1	889	0	315240	03-514-002	Replace Shanks or Teeth	07-Dec-2017 16:41:29	ROGSHP	N	DON	106.50
07-Dec-2017 1	889	0	315240	07-100-PMA	Lubricate A PMI	07-Dec-2017 16:30:14	ROGSHP	P	DON	23.18
07-Dec-2017 1	889	0	315240	07-100-PMB	Lubricate B PMI	07-Dec-2017 17:28:54	ROGSHP	P	DON	120.67
02-Feb-2018 0	938	0	322111	03-034-018	Replace Brake Light Switch	02-Feb-2018 14:29:17	LAVSHP	I	DON	119.55
02-Feb-2018 0	938	0	322111	03-053-007	Replace Hardware - Expendable Items	05-Feb-2018 06:00:55	LAVSHP	I	DON	97.62
02-Feb-2018 0	938	0	322111	06-100-PMC	Inspect C PMI	02-Feb-2018 13:07:29	LAVSHP	P	DON	321.04
02-Feb-2018 0	938	0	322111	06-310	Inspect Backhoe (Rubber Tire)	02-Feb-2018 09:33:01	LAVSHP	S	DON	19.51
06-Jul-2018 16	1,168	0	342730	07-100-PMA	Lubricate A PMI	06-Jul-2018 17:36:07	ROGSHP	P	DON	21.54
21-Dec-2018 1	1,722	0	365842	03-041-006	Replace Filter - Inner	26-Dec-2018 14:10:38	ROGSHP	P	DON	15.08
21-Dec-2018 1	1,722	0	365842	03-041-007	Replace Filter - Outer	26-Dec-2018 14:13:57	ROGSHP	P	DON	23.79
21-Dec-2018 1	1,722	0	365842	03-047-001	Replace Engine Filter Kits	26-Dec-2018 11:57:02	ROGSHP	P	DON	51.91
21-Dec-2018 1	1,722	0	365842	03-065-007	Replace Hoses & Fittings	27-Dec-2018 12:15:42	ROGSHP	I	DON	177.80
21-Dec-2018 1	1,722	0	365842	03-094-011	Replace Coupler - Quick Disconnect	26-Dec-2018 16:53:04	ROGSHP	I	DON	130.81

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Q1267 - 2017 JOHN DEERE 310HL										
21-Dec-2018 1	1,722	0	365842	06-100-PMA	Inspect A PMI	10-Jan-2019 08:11:47	BHVEQ	P	DON	0.00
21-Dec-2018 1	1,722	0	365842	06-100-PMB	Inspect B PMI	10-Jan-2019 08:11:48	BHVEQ	P	DON	0.00
21-Dec-2018 1	1,722	0	365842	06-310	Inspect Backhoe (Rubber Tire)	21-Dec-2018 15:55:32	ROGSH	P	DON	72.99
21-Dec-2018 1	1,722	0	365842	06-310-001	Inspect Boom (Main)	21-Dec-2018 15:05:49	ROGSH	N	DON	72.52
21-Dec-2018 1	1,722	0	365842	07-100-PMA	Lubricate A PMI	26-Dec-2018 11:46:11	ROGSH	P	DON	18.40
21-Dec-2018 1	1,722	0	365842	07-100-PMB	Lubricate B PMI	26-Dec-2018 13:30:02	ROGSH	P	DON	118.98
21-Dec-2018 1	1,722	0	365842	07-100-PMC	Lubricate C PMI	26-Dec-2018 14:06:12	ROGSH	P	DON	120.91
21-Dec-2018 1	1,722	0	365842	21-065-007	Fabricate Hoses & Fittings	03-Jan-2019 07:21:06	ROGSH	I	DON	295.09
21-Dec-2018 1	1,722	0	365842	24-002-028	Repair Adjuster - Front Seat	26-Dec-2018 14:56:54	ROGSH	I	DON	4.64
25-Mar-2019 0	1,722	0	378783	03-514-005	Replace Pins	28-Mar-2019 21:18:40	MA072	B	DON	518.42
12-Apr-2019 0	1,758	0	380899	06-310	Inspect Backhoe (Rubber Tire)	12-Apr-2019 09:01:50	ROGSH	P	DON	25.91
23-May-2019 1	1,790	0	387187	03-310-007	Replace Outrigger Pads	23-May-2019 17:52:00	ROGSH	I	DON	266.59
02-Aug-2019 C	1,976	0	396988	06-100-PMB	Inspect B PMI	05-Aug-2019 07:33:24	ROGSH	P	DON	0.00
02-Aug-2019 C	1,976	0	396988	38-100-PMB	Service B PMI	02-Aug-2019 10:28:43	ROGSH	P	DON	219.82
21-Oct-2019 1	2,226	0	408554	06-100-PMA	Inspect A PMI	21-Oct-2019 14:45:31	ROGSH	P	DON	0.00
21-Oct-2019 1	2,226	0	408554	38-100-PMA	Service A PMI	21-Oct-2019 13:57:21	ROGSH	P	DON	261.68
26-Mar-2020 1	2,492	0	433051	03-094-011	Replace Coupler - Quick Disconnect	30-Mar-2020 12:04:00	ROGSH	N	DON	213.66
05-Jun-2020 0	2,594	0	443939	06-100-PMA	Inspect A PMI	08-Jun-2020 07:16:44	ROGSH	P	DON	0.00
05-Jun-2020 0	2,594	0	443939	38-100-PMA	Service A PMI	05-Jun-2020 11:46:32	ROGSH	P	DON	430.78
26-Aug-2020 1	2,794	0	458272	03-017-001	Replace Tire - Pneumatic	31-Aug-2020 08:34:18	ROGSH	N	DON	1,498.10
26-Aug-2020 1	2,794	0	458272	03-017-011	Replace Tire - Foam Filled	15-Sep-2020 11:21:36	ROGSH	N	DON	1,813.99
26-Aug-2020 1	2,794	0	458272	06-100-PMA	Inspect A PMI	15-Sep-2020 11:21:31	ROGSH	P	DON	0.00
26-Aug-2020 1	2,794	0	458272	38-100-PMA	Service A PMI	11-Sep-2020 16:27:29	ROGSH	P	DON	277.73
13-Oct-2020 1	2,922	0	466298	24-112-006	Repair Outrigger Assembly	13-Oct-2020 15:11:43	ROGSH	O	DON	29.20
13-Jan-2021 0	3,037	0	481651	02-310	Clean Backhoe (Rubber Tire)	01-Feb-2021 07:04:10	BWASH	N	DON	201.98
13-Jan-2021 0	3,037	0	481651	03-002-029	Replace Trim - Seat	19-Jan-2021 14:43:19	BBKHOE	I	DON	334.17
13-Jan-2021 0	3,037	0	481651	03-002-061	Replace Seat Cushion	19-Jan-2021 16:14:28	BBKHOE	I	DON	307.35
13-Jan-2021 0	3,037	0	481651	03-051-009	Replace Fire Extinguisher	19-Jan-2021 13:48:38	BBKHOE	Q	DON	183.48
13-Jan-2021 0	3,037	0	481651	06-100-PMC	Inspect C PMI	28-Jan-2021 10:23:56	BBKHOE	P	DON	333.53

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Q1267 - 2017 JOHN DEERE 310HL										
13-Jan-2021 0:	3,037	0	481651	14-519-001	Install Front Bumper	19-Jan-2021 15:50:52	BBKHOE	I	DON	300.61
13-Jan-2021 0:	3,037	0	481651	31-310-017	Rotate Cutting Edges	19-Jan-2021 17:00:14	BBKHOE	I	DON	49.08
13-Jan-2021 0:	3,037	0	481651	03-065-004	Replace Cylinder	27-Jan-2021 15:49:26	BBKHOE	I	DON	208.51
13-Jan-2021 0:	3,037	0	481651	03-065-007	Replace Hoses & Fittings	27-Jan-2021 16:30:44	BBKHOE	I	DON	502.32
13-Jan-2021 0:	3,037	0	481651	03-310-003	Replace Boom Pins	28-Jan-2021 08:37:07	BBKHOE	I	DON	4,039.09
13-Jan-2021 0:	3,037	0	481651	34-045-013	Reseal Oil Pan	19-Jan-2021 09:18:04	BBKHOE	I	DON	272.29
13-Jan-2021 0:	3,037	0	481651	38-043-025	Service Filter - DEF	19-Jan-2021 11:03:57	BBKHOE	I	DON	75.70
13-Jan-2021 0:	3,037	0	481651	38-100-PMC	Service C PMI	18-Jan-2021 16:35:26	BBKHOE	P	DON	1,215.90
13-Jan-2021 0:	3,037	0	481651	24-002-030	Repair Interior Moldings	26-Jan-2021 07:26:40	BBKHOE	I	DON	133.42
13-Jan-2021 0:	3,037	0	481651	24-310-006	Repair Outriggers	28-Jan-2021 09:31:46	BBKHOE	I	DON	377.44
13-Jan-2021 0:	3,037	0	481651	26-310-001	Weld Boom (Main)	27-Jan-2021 06:30:43	BHVYEQ	N	DON	233.27
14-Jan-2021 0:	3,037	0	482006	02-310	Clean Backhoe (Rubber Tire)	14-Jan-2021 12:16:05	BWASH	N	DON	260.40
20-Jan-2021 0:	3,038	0	483347	22-513-004	Design Specialty Attachment	16-Feb-2021 05:17:03	BWELD	D	DON	301.45
20-Jan-2021 0:	3,038	0	483347	99-513-004	Machine Specialty Attachment	16-Feb-2021 05:17:06	BWELD	N	DON	931.60
05-Aug-2021 1	3,184	0	523209	03-024-005	Replace Universal Joint	13-Aug-2021 06:46:56	OTSSHP	I	DON	752.28
05-Aug-2021 1	3,184	0	523209	03-034-006	Replace Warning Lamps - Special Application	05-Aug-2021 17:17:39	OTSSHP	I	DON	196.89
05-Aug-2021 1	3,184	0	523209	03-063-003	Replace Transceiver - GPS Tracker	05-Aug-2021 17:04:42	SCHED	Q	DON	299.52
05-Aug-2021 1	3,184	0	523209	06-100-PMA	Inspect A PMI	05-Aug-2021 14:49:51	SCHED	P	DON	62.93
05-Aug-2021 1	3,184	0	523209	38-100-PMA	Service A PMI	05-Aug-2021 16:22:13	OTSSHP	P	DON	328.05
08-Nov-2021 1	3,451	0	544926	06-100-PMA	Inspect A PMI	08-Nov-2021 10:59:38	ME1371	P	DON	22.25
08-Nov-2021 1	3,451	0	544926	38-100-PMA	Service A PMI	08-Nov-2021 10:46:43	ME1371	P	DON	121.71
17-Nov-2021 1	3,484	0	547507	03-065-007	Replace Hoses & Fittings	17-Nov-2021 16:13:12	TRK401	O	DON	91.94
30-Nov-2021 1	3,519	0	549697	06-268-009	Inspect Boom Structure	30-Nov-2021 08:49:36	TRK401	O	DON	32.86
01-Feb-2022 1	3,597	0	563326	03-034-002	Replace Stop, Tail, Turn & License	02-Feb-2022 12:04:53	TRK400	I	DON	67.36
01-Feb-2022 1	3,597	0	563326	03-528	Replace Bushing	04-Feb-2022 16:05:28	TRK400	I	DON	1,288.25
01-Feb-2022 1	3,597	0	563326	06-100-PMC	Inspect C PMI	01-Feb-2022 16:48:26	TRK400	P	DON	250.13
01-Feb-2022 1	3,597	0	563326	24-094	Repair Lines, Tubes, Hoses & Fittings - Bulk Pr	02-Feb-2022 11:00:36	TRK400	I	DON	152.75
01-Feb-2022 1	3,597	0	563326	38-063-003	Service Transceiver - GPS Tracker	02-Feb-2022 13:46:33	TRK400	N	DON	364.41
01-Feb-2022 1	3,597	0	563326	38-100-PMC	Service C PMI	02-Feb-2022 09:26:32	TRK400	I	DON	371.81

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Q1267 - 2017 JOHN DEERE 310HL										
01-Mar-2022 1	3,591	0	570863	03-063-003	Replace Transceiver - GPS Tracker	01-Mar-2022 12:36:57	TRK400	P	DON	298.25
20-Apr-2022 1	3,668	0	583018	03-094-011	Replace Coupler - Quick Disconnect	20-Apr-2022 11:20:00	ME1371	O	DON	104.06
20-Apr-2022 1	3,668	0	583018	06-100-PMA	Inspect A PMI	20-Apr-2022 11:42:39	ME1371	P	DON	39.02
20-Apr-2022 1	3,668	0	583018	03-034-016	Replace Turn Signal Switch	25-Apr-2022 13:21:29	ME1371	I	DON	790.40
20-Apr-2022 1	3,668	0	583018	38-100-PMA	Service A PMI	20-Apr-2022 11:06:00	ME1371	P	DON	110.87
31-May-2022 (3,852	0	592223	03-017-011	Replace Tire - Foam Filled	31-May-2022 09:34:12	ME1371	O	DON	2,943.93
30-Aug-2022 1	4,134	0	613239	06-100-PMA	Inspect A PMI	30-Aug-2022 18:43:21	TRK400	P	DON	41.98
30-Aug-2022 1	4,134	0	613239	38-100-PMA	Service A PMI	30-Aug-2022 19:16:17	TRK400	I	DON	106.08
21-Sep-2022 1	4,178	0	618260	01-002-037	Adjust Seat Assembly	21-Sep-2022 17:07:49	TRK401	I	DON	263.54
08-Nov-2022 1	4,334	0	630873	03-094-011	Replace Coupler - Quick Disconnect	08-Nov-2022 16:50:20	TRK401	O	DON	167.88
08-Nov-2022 1	4,334	0	630873	95-MSC-004	Travel Travel Time - To/From Job Site	08-Nov-2022 16:21:55	TRK401	B	DON	119.19
26-Jan-2023 0:	4,472	0	648121	06-100-PMC	Inspect C PMI	24-Feb-2023 05:22:39	BBKHoe	P	DON	267.25
26-Jan-2023 0:	4,472	0	648121	02-310	Clean Backhoe (Rubber Tire)	24-Feb-2023 15:32:18	BWASH	N	DON	518.29
26-Jan-2023 0:	4,472	0	648121	03-310-017	Replace Cutting Edges	21-Feb-2023 11:16:08	BBKHoe	I	DON	343.16
26-Jan-2023 0:	4,472	0	648121	03-514-002	Replace Shanks or Teeth	23-Feb-2023 08:41:30	BBKHoe	E	DON	184.92
26-Jan-2023 0:	4,472	0	648121	03-065-004	Replace Cylinder	24-Feb-2023 05:22:36	BBKHoe	E	DON	1,813.10
26-Jan-2023 0:	4,472	0	648121	24-042-009	Repair Coolant Pre-Heater- Electrical	21-Feb-2023 08:17:37	BBKHoe	I	DON	77.42
26-Jan-2023 0:	4,472	0	648121	38-100-PMC	Service C PMI	23-Feb-2023 14:48:03	BBKHoe	I	DON	713.48
26-Jan-2023 0:	4,472	0	648121	03-051-009	Replace Fire Extinguisher	23-Feb-2023 14:47:52	BBKHoe	Q	DON	200.01
26-Jan-2023 0:	4,472	0	648121	03-017-001	Replace Tire - Pneumatic	20-Feb-2023 10:20:49	BBKHoe	I	DON	1,165.18
26-Jan-2023 0:	4,472	0	648121	03-065-007	Replace Hoses & Fittings	23-Feb-2023 07:33:58	BBKHoe	E	DON	601.09
26-Jan-2023 0:	4,472	0	648121	24-034	Repair Lighting System	23-Feb-2023 11:28:38	BBKHoe	I	DON	103.62
01-May-2023 1	4,532	0	671392	06-049-001	Inspect ECM Fault Code	01-May-2023 13:25:17	ME1371	I	DON	24.80
01-May-2023 1	4,532	0	671392	24-013-034	Repair Parking Brake - Complete	01-May-2023 14:55:40	ME1371	B	DON	659.67
12-May-2023 (4,592	0	673987	06-100-PMA	Inspect A PMI	12-May-2023 09:53:00	ME1371	P	DON	25.00
24-May-2023 (4,593	0	676585	26-514-002	Weld Shanks or Teeth	05-Jun-2023 16:01:35	BHVYEQ	N	DON	486.01
14-Aug-2023 C	4,631	0	696479	03-051-009	Replace Fire Extinguisher	16-Aug-2023 12:40:30	BBKHoe	Q	DON	121.73
14-Aug-2023 C	4,631	0	696479	06-100-PMB	Inspect B PMI	17-Aug-2023 05:02:13	SCHED	P	DON	206.33
14-Aug-2023 C	4,631	0	696479	24-002-004	Repair Hood	15-Aug-2023 07:03:56	BBKHoe	I	DON	44.64

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost		
Unit No: Q1267 - 2017 JOHN DEERE 310HL												
14-Aug-2023	C	4,631	0	696479	38-100-PMB	Service B PMI	17-Aug-2023	05:02:14	BBKHOE	I	DON	333.87
25-Aug-2023	I	4,631	0	700087	02-310	Clean Backhoe (Rubber Tire)	01-Nov-2023	07:30:08	BWASH	N	DON	332.69
01-Sep-2023	0	4,631	0	702369	26-514-004	Weid Edges	08-Sep-2023	09:59:32	BHVYEQ	N	DON	459.38
18-Mar-2024	0		0	746295	06-100-PMB	Inspect B PMI	04-Apr-2024	07:32:32	BBKHOE	P	DON	125.86
18-Mar-2024	0		0	746295	02-310	Clean Backhoe (Rubber Tire)	21-Mar-2024	15:06:15	BWASH	N	DON	457.11
18-Mar-2024	0		0	746295	OS-310	Out-Service Backhoe (Rubber Tire)	03-Apr-2024	14:54:41	BBKHOE	N	DON	137.30

Unit No: Q1267

Count: 122

45,502.15