

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: N1311 - 2018 CAT 349FL										
05-Jul-2018 12	15	0	342525	14-051-009	Install Fire Extinguisher	05-Jul-2018 15:50:04	BHVEQ	Q	DON	101.67
05-Jul-2018 12	15	0	342525	14-052-005	Install Transmitter - CB	05-Jul-2018 14:11:21	BHVEQ	Q	DON	159.01
05-Jul-2018 12	15	0	342525	14-063-003	Install Transceiver - GPS Tracker	05-Jul-2018 17:06:26	BHVEQ	Q	DON	316.44
05-Jul-2018 12	15	0	342525	14-330-001	Install Bucket and Attachments	06-Jul-2018 12:01:56	BHVEQ	Q	DON	1,911.46
27-Aug-2018 C	205	0	349843	03-514-002	Replace Shanks or Teeth	27-Aug-2018 10:00:37	BHVEQ	E	DON	727.62
27-Aug-2018 C	205	0	349843	14-065-007	Install Hoses & Fittings	27-Aug-2018 05:42:36	BHVEQ	Q	DON	1,615.95
10-Sep-2018 I	205	0	351451	06-100-PMA	Inspect A PMI	10-Sep-2018 13:03:16	BHVEQ	N	DON	235.18
14-Sep-2018 I	205	0	352108	03-514-002	Replace Shanks or Teeth	14-Sep-2018 13:50:14	BHVEQ	E	DON	901.77
18-Sep-2018 I	205	0	352605	13-052-005	Assemble Transmitter - CB	18-Sep-2018 13:15:31	BHVEQ	N	DON	113.89
12-Nov-2018 I	205	0	360323	03-065-007	Replace Hoses & Fittings	14-Nov-2018 05:41:08	BHVEQ	I	DON	119.14
12-Nov-2018 I	205	0	360323	03-514-002	Replace Shanks or Teeth	12-Nov-2018 14:38:05	BHVEQ	E	DON	3,333.39
21-Nov-2018 I	205	0	361448	12-513-004	Refinish Specialty Attachment	29-Nov-2018 14:26:47	BBODY	C	DON	83.11
21-Nov-2018 I	205	0	361448	21-513-004	Fabricate Specialty Attachment	04-Dec-2018 14:32:21	BWELD	C	DON	5,609.74
11-Dec-2018 0	205	0	363848	06-330-013	Inspect Operator Controls	11-Dec-2018 17:00:23	BHVEQ	O	DON	336.28
11-Dec-2018 0	205	0	363848	03-514-002	Replace Shanks or Teeth	11-Dec-2018 14:59:35	BHVEQ	E	DON	338.90
29-Jan-2019 0	727	0	370373	03-002-024	Replace Glass / Windshield	04-Feb-2019 06:16:00	BHVEQ	E	DON	361.10
29-Jan-2019 0	727	0	370373	03-037-011	Replace Relay - Multiple Use	01-Feb-2019 09:28:10	BHVEQ	I	DON	349.28
29-Jan-2019 0	727	0	370373	03-065-007	Replace Hoses & Fittings	01-Feb-2019 07:06:32	BHVEQ	I	DON	179.25
29-Jan-2019 0	727	0	370373	03-111-011	Replace Track Pad	01-Feb-2019 09:27:40	BHVEQ	I	DON	58.17
29-Jan-2019 0	727	0	370373	06-100-PMA	Inspect A PMI	29-Jan-2019 11:16:38	BHVEQ	P	DON	59.58
29-Jan-2019 0	727	0	370373	06-100-PMB	Inspect B PMI	01-Feb-2019 07:45:43	BHVEQ	P	DON	602.89
07-Feb-2019 1	727	0	371633	14-042-009	Install Coolant Pre-Heater- Electrical		BHVEQ	N	CAN	0.00
07-Feb-2019 1	727	0	371633	24-514-002	Repair Shanks or Teeth	18-Feb-2019 15:29:50	BHVEQ	N	DON	1,160.21
07-Feb-2019 1	727	0	371633	21-002-039	Fabricate Cab Guard Assembly	07-Mar-2019 05:48:15	BHVEQ	Q	DON	1,129.37
07-Feb-2019 1	727	0	371633	03-002-024	Replace Glass / Windshield	07-Mar-2019 05:51:02	BHVEQ	E	DON	303.52
25-Mar-2019 1	727	0	378185	21-002-039	Fabricate Cab Guard Assembly		BHVEQ	N	CAN	0.00
15-May-2019 C	905	0	385894	03-065-020	Replace Control Valve	15-May-2019 09:46:14	BHVEQ	W	DON	151.12
27-Jun-2019 0	1,001	0	391968	38-100-PMA	Service A PMI	27-Jun-2019 04:57:40	BHVEQ	P	DON	1,321.27
19-Jul-2019 08	1,140	0	394953	02-330	Clean Excavator	01-Aug-2019 07:05:26	BWASH	N	DON	401.34

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: N1311 - 2018 CAT 349FL										
19-Jul-2019 08	1,140	0	394953	26-514-002	Weld Shanks or Teeth	31-Jul-2019 14:30:06	BHVYEQ	N	DON	260.27
19-Jul-2019 08	1,140	0	394953	06-100-PMB	Inspect B PMI	19-Jul-2019 11:34:59	BHVYEQ	P	DON	113.25
19-Jul-2019 08	1,140	0	394953	38-100-PMA	Service A PMI	22-Jul-2019 09:27:18	BHVYEQ	P	DON	433.80
25-Oct-2019 1	1,187	0	409548	03-514-002	Replace Shanks or Teeth	25-Oct-2019 12:46:56	BHVYEQ	E	DON	1,766.75
04-Nov-2019 0	1,205	0	410853	14-509-001	Install Machine Guard	04-Nov-2019 15:19:55	BHVYEQ	Q	DON	496.52
04-Dec-2019 0	1,370	0	415113	06-100-PMA	Inspect A PMI	04-Dec-2019 08:14:47	BHVYEQ	P	DON	0.00
04-Dec-2019 0	1,370	0	415113	38-100-PMA	Service A PMI	04-Dec-2019 08:14:44	BHVYEQ	P	DON	129.72
04-Dec-2019 1	1,370	0	415261	24-330-015	Repair Quik-Attach Assembly	04-Dec-2019 15:19:07	BHVYEQ	B	DON	11,692.40
23-Jan-2020 1	1,663	0	422601	06-100-PMA	Inspect A PMI	23-Jan-2020 10:21:51	BHVYEQ	P	DON	0.00
23-Jan-2020 1	1,663	0	422601	38-100-PMA	Service A PMI	23-Jan-2020 10:21:48	BHVYEQ	P	DON	119.78
06-Mar-2020 0	1,864	0	429744	38-100-PMA	Service A PMI	06-Mar-2020 06:38:20	BHVYEQ	P	DON	58.15
26-Mar-2020 1	1,951	0	433045	06-100-PMA	Inspect A PMI	26-Mar-2020 11:39:44	BHVYEQ	P	DON	0.00
26-Mar-2020 1	1,951	0	433045	38-100-PMA	Service A PMI	26-Mar-2020 11:39:42	BHVYEQ	P	DON	190.43
14-Apr-2020 0	2,115	0	435738	02-330	Clean Excavator	20-Apr-2020 11:03:30	BWASH	N	DON	128.84
14-Apr-2020 0	2,115	0	435738	03-002-035	Replace Windshield Wiper & Washer	22-Apr-2020 05:45:47	BHVYEQ	I	DON	58.35
14-Apr-2020 0	2,115	0	435738	03-031-006	Replace Belt - Alternator	14-Apr-2020 14:31:50	BHVYEQ	I	DON	121.93
14-Apr-2020 0	2,115	0	435738	03-042-013	Replace Fan Belt	14-Apr-2020 16:30:36	BHVYEQ	I	DON	175.98
14-Apr-2020 0	2,115	0	435738	03-051-009	Replace Fire Extinguisher	14-Apr-2020 17:00:12	BHVYEQ	I	DON	21.16
14-Apr-2020 0	2,115	0	435738	03-065-007	Replace Hoses & Fittings	21-Apr-2020 15:44:49	BHVYEQ	I	DON	27.10
14-Apr-2020 0	2,115	0	435738	14-514-002	Install Shanks or Teeth	22-Apr-2020 05:46:40	BHVYEQ	N	DON	283.42
14-Apr-2020 0	2,115	0	435738	38-100-PMC	Service C PMI	21-Apr-2020 07:17:55	BHVYEQ	P	DON	1,021.04
01-May-2020 1		0	438883	06-100-PMA	Inspect A PMI	01-May-2020 11:11:31	BHVYEQ	P	DON	0.00
01-May-2020 1		0	438883	38-100-PMA	Service A PMI	01-May-2020 11:11:21	BHVYEQ	P	DON	189.29
01-May-2020 1		0	438883	03-514-002	Replace Shanks or Teeth	01-May-2020 13:06:53	BHVYEQ	E	DON	2,367.08
24-Jul-2020 09	2,312	0	452431	03-514-002	Replace Shanks or Teeth	28-Jul-2020 14:38:04	BHVYEQ	E	DON	1,113.48
30-Jul-2020 06	2,352	0	453381	03-514-002	Replace Shanks or Teeth	30-Jul-2020 06:36:50	BHVYEQ	E	DON	1,113.48
30-Jul-2020 06	2,352	0	453381	06-100-PMC	Inspect C PMI	30-Jul-2020 06:37:45	BHVYEQ	P	DON	0.00
30-Jul-2020 06	2,352	0	453381	38-100-PMA	Service A PMI	30-Jul-2020 06:37:50	BHVYEQ	P	DON	188.74
04-Aug-2020 1	2,379	0	454290	03-514-002	Replace Shanks or Teeth	04-Aug-2020 15:21:36	BHVYEQ	E	DON	1,113.48

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost	
Unit No: N1311 - 2018 CAT 349FL											
04-Aug-2020	1	2,379	0	454292	03-044-002	Replace Filters	04-Aug-2020 15:25:55	BHVYEQ	P	DON	125.39
26-Aug-2020	C	2,466	0	458086	03-065-007	Replace Hoses & Fittings	01-Sep-2020 07:08:07	BHVYEQ	O	DON	14.12
07-Oct-2020	0	2,601	0	465236	06-100-PMA	Inspect A PMI	21-Oct-2020 10:04:52	BHVYEQ	P	DON	9.35
07-Oct-2020	0	2,601	0	465236	38-100-PMA	Service A PMI	07-Oct-2020 12:00:41	BHVYEQ	P	DON	286.01
07-Oct-2020	0	2,601	0	465236	03-002-010	Replace Mirrors	07-Oct-2020 12:49:19	BHVYEQ	I	DON	53.76
05-Feb-2021	1	2,878	0	486706	03-044-024	Replace Fuel / Water Separator	23-Jun-2021 05:56:15	BCRUSH	I	DON	49.59
05-Feb-2021	1	2,878	0	486706	03-094	Replace Lines, Tubes, Hoses & Fittings - Bulk P	23-Jun-2021 05:56:19	BHVYEQ	O	DON	71.73
25-Feb-2021	1	2,901	0	490311	03-514-002	Replace Shanks or Teeth	11-Mar-2021 06:08:06	BHVYEQ	E	DON	1,120.66
16-Mar-2021	1	2,987	0	494579	03-065-001	Replace Hydraulic Systems	16-Mar-2021 12:33:51	BHVYEQ	D	DON	98.15
17-Mar-2021	1	2,997	0	494876	24-330-015	Repair Quik-Attach Assembly	18-Mar-2021 04:30:54	BHVYEQ	B	DON	1,014.11
17-Mar-2021	1	2,997	0	494876	03-514-002	Replace Shanks or Teeth	23-Mar-2021 06:55:35	BHVYEQ	E	DON	560.33
17-Mar-2021	1	2,997	0	494876	03-041-007	Replace Filter - Outer	17-Mar-2021 14:14:20	BHVYEQ	P	DON	62.88
17-Mar-2021	1	2,997	0	494876	03-111	Replace Undercarriage	19-Mar-2021 09:18:22	BHVYEQ	O	DON	61.03
31-Mar-2021	0	3,093	0	497639	03-330-016	Replace Frost Hook - Tooth	02-Apr-2021 08:00:24	BHVYEQ	E	DON	323.47
05-Apr-2021	0	3,187	0	498419	06-330	Inspect Excavator	27-Apr-2021 14:22:54	BHVYEQ	N	DON	163.81
05-Apr-2021	0	3,187	0	498419	03-043-020	Replace Pump - DEF	22-Apr-2021 11:03:17	BHVYEQ	W	DON	0.00
05-Apr-2021	0	3,187	0	498419	03-063-001	Replace Antenna - RF	22-Apr-2021 11:02:36	BHVYEQ	W	DON	0.00
05-Apr-2021	0	3,187	0	498419	37-049-002	Calibrate ECM Module	22-Apr-2021 10:46:06	BHVYEQ	W	DON	0.00
05-Apr-2021	0	3,187	0	498419	14-053-005	Install Markings - Vehicle - Decals	22-Apr-2021 10:47:23	BHVYEQ	W	DON	0.00
05-Apr-2021	0	3,187	0	498419	24-049-003	Repair ECM Wiring Harness	22-Apr-2021 11:01:35	BHVYEQ	I	DON	1,011.57
05-Apr-2021	0	3,187	0	498419	24-042-012	Repair Clamps and Hoses	27-Apr-2021 14:23:37	BHVYEQ	I	DON	1,052.32
05-Apr-2021	0	3,187	0	498419	34-043-002	Reseal Exhaust Manifold	27-Apr-2021 14:23:21	BHVYEQ	I	DON	1,421.93
05-Apr-2021	0	3,187	0	498419	38-100-PMB	Service B PMI	27-Apr-2021 14:22:58	BHVYEQ	P	DON	1,365.37
05-Apr-2021	0	3,187	0	498419	03-519-001	Replace Front Bumper	27-Apr-2021 14:24:41	BHVYEQ	I	DON	872.96
05-Apr-2021	0	3,187	0	498419	24-330-004	Repair Boom and Stick Assembly	27-Apr-2021 14:24:26	BHVYEQ	I	DON	9,461.12
05-Apr-2021	0	3,187	0	498419	02-330	Clean Excavator	14-Apr-2021 13:18:46	BWASH	N	DON	475.05
05-Apr-2021	0	3,187	0	498419	03-052-005	Replace Transmitter - CB	14-Apr-2021 07:55:23	BHVYEQ	O	DON	109.68
05-Apr-2021	0	3,187	0	498419	03-514-002	Replace Shanks or Teeth	27-Apr-2021 14:25:17	BHVYEQ	N	DON	1,195.08
05-Apr-2021	0	3,187	0	498419	06-100-PMB	Inspect B PMI	28-Apr-2021 05:09:21	SCHED	P	DON	0.00

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: N1311 - 2018 CAT 349FL										
10-May-2021	0	0	505623	99-330-004	Machine Boom and Stick Assembly	10-May-2021 13:25:35	BHVYEQ	I	DON	1,571.42
03-Jun-2021	0	0	510581	03-514-002	Replace Shanks or Teeth	04-Jun-2021 08:05:00	BHVYEQ	E	DON	1,146.51
07-Jun-2021	3,264	0	511107	03-043-022	Replace Injector - DEF	07-Jun-2021 10:12:28	BHVYEQ	B	DON	1,103.94
07-Jun-2021	3,264	0	511175	03-002-024	Replace Glass / Windshield	23-Jun-2021 06:36:57	BHVYEQ	E	DON	450.28
07-Jun-2021	3,264	0	511175	03-514-002	Replace Shanks or Teeth	23-Jun-2021 06:36:58	BHVYEQ	E	DON	2,295.29
06-Jul-2021	3,370	0	516669	03-514-002	Replace Shanks or Teeth	06-Jul-2021 08:16:08	BHVYEQ	E	DON	4,191.03
28-Jul-2021	3,488	0	521503	03-514-002	Replace Shanks or Teeth	28-Jul-2021 16:52:15	BHVYEQ	E	DON	2,111.25
10-Aug-2021	3,556	0	524041	03-043-024	Replace Lines - DEF	12-Aug-2021 11:24:02	BHVYEQ	B	DON	4,310.03
10-Aug-2021	3,556	0	524041	03-330-015	Replace Quik-Attach Assembly	13-Aug-2021 12:01:53	BHVYEQ	B	DON	293.63
10-Aug-2021	3,556	0	524041	14-041-005	Install Ether Injector Assembly		BHVYEQ	B	CAN	0.00
10-Aug-2021	3,556	0	524041	03-045-011	Replace Filter Assembly - Oil	10-Aug-2021 08:23:57	BHVYEQ	O	DON	19.84
10-Aug-2021	3,556	0	524041	03-041-007	Replace Filter - Outer	10-Aug-2021 08:24:27	BHVYEQ	O	DON	0.00
10-Aug-2021	3,556	0	524041	03-514-002	Replace Shanks or Teeth	10-Aug-2021 08:21:42	BHVYEQ	E	DON	2,111.25
30-Aug-2021	3,664	0	528233	03-514-002	Replace Shanks or Teeth	30-Aug-2021 08:27:15	BHVYEQ	E	DON	2,197.17
03-Sep-2021	3,678	0	529448	26-330-015	Weld Quik-Attach Assembly	29-Sep-2021 10:48:36	BHVYEQ	I	DON	244.36
03-Sep-2021	3,678	0	529448	24-330-001	Repair Bucket and Attachments	27-Sep-2021 10:52:32	BHVYEQ	B	DON	2,988.31
03-Sep-2021	3,678	0	529448	24-065-004	Repair Cylinder	29-Sep-2021 10:48:34	BHVYEQ	I	DON	2,008.79
13-Jan-2022	3,903	0	558970	03-054-002	Replace Alarm - Reverse Signal	13-Jan-2022 11:03:50	BHVYEQ	O	DON	580.81
13-Jan-2022	3,903	0	558970	38-100-PMA	Service A PMI	14-Jan-2022 10:57:28	BHVYEQ	O	DON	184.14
10-Feb-2022	3,903	0	565649	03-065-006	Replace Filters, Strainers, Screens & Housing	13-May-2022 06:05:48	BCRUSH	Q	DON	66.77
17-Feb-2022	3,903	0	567796	03-514-002	Replace Shanks or Teeth	17-Feb-2022 10:36:57	BHVYEQ	E	DON	2,188.38
23-Feb-2022	3,903	0	569426	03-041-006	Replace Filter - Inner	23-Feb-2022 16:06:11	BHVYEQ	O	DON	31.08
23-Feb-2022	3,903	0	569426	03-041-007	Replace Filter - Outer	23-Feb-2022 16:05:35	BHVYEQ	O	DON	56.01
14-Mar-2022	3,903	0	574274	24-043-001	Repair Emission Controls	18-Mar-2022 06:48:04	BHVYEQ	B	DON	3,012.86
16-May-2022	4,601	0	588790	01-330-001	Adjust Bucket and Attachments	03-Jun-2022 14:11:08	BHVYEQ	N	DON	402.52
16-May-2022	4,601	0	588790	02-002-024	Clean Glass / Windshield	08-Jun-2022 07:08:23	BHVYEQ	N	DON	22.90
16-May-2022	4,601	0	588790	02-043-009	Clean Diesel Particulate Filter - DPF	24-May-2022 04:56:49	BHVYEQ	N	DON	379.57
16-May-2022	4,601	0	588790	02-330	Clean Excavator	02-Jun-2022 09:34:07	BWASH	N	DON	230.77
16-May-2022	4,601	0	588790	03-001-006	Replace Dryer Assembly	31-May-2022 06:15:47	BHVYEQ	I	DON	537.45

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: N1311 - 2018 CAT 349FL										
16-May-2022	4,601	0	588790	03-001-010	Replace Compressor Assembly - Air Cond	23-May-2022 12:01:35	BHVYEQ	I	DON	1,067.40
16-May-2022	4,601	0	588790	03-031-001	Replace Generator/Alternator	25-May-2022 08:57:08	BHVYEQ	I	DON	1,636.21
16-May-2022	4,601	0	588790	03-032-001	Replace Battery	17-Jun-2022 15:28:36	BHVYEQ	I	DON	890.50
16-May-2022	4,601	0	588790	03-045-023	Replace Engine Belts	23-May-2022 07:10:34	BHVYEQ	I	DON	472.43
16-May-2022	4,601	0	588790	03-063-003	Replace Transceiver - GPS Tracker	08-Jun-2022 06:35:04	BHVYEQ	Q	DON	36.14
16-May-2022	4,601	0	588790	03-065-007	Replace Hoses & Fittings	23-Jun-2022 07:35:50	BHVYEQ	I	DON	990.82
16-May-2022	4,601	0	588790	06-100-PMC	Inspect C PMI	08-Jun-2022 06:34:43	BHVYEQ	P	DON	195.25
16-May-2022	4,601	0	588790	24-001-006	Repair Dryer Assembly		BHVYEQ	I	CAN	0.00
16-May-2022	4,601	0	588790	24-041-005	Repair Ether Injector Assembly	08-Jun-2022 07:07:42	BHVYEQ	I	DON	331.09
16-May-2022	4,601	0	588790	24-111	Repair Undercarriage	03-Jun-2022 09:35:06	BHVYEQ	I	DON	5,063.15
16-May-2022	4,601	0	588790	24-330-015	Repair Quik-Attach Assembly	08-Jun-2022 06:34:47	BHVYEQ	I	DON	2,301.37
16-May-2022	4,601	0	588790	24-514	Repair Bucket	20-Jun-2022 10:18:37	BWELD	N	DON	2,937.81
16-May-2022	4,601	0	588790	25-043-009	Remove Diesel Particulate Filter - DPF	08-Jun-2022 06:34:52	BHVYEQ	I	DON	1,062.36
16-May-2022	4,601	0	588790	38-100-PMC	Service C PMI	08-Jun-2022 06:35:00	BHVYEQ	P	DON	691.50
18-Aug-2022	5,422	0	610431	38-100-PMA	Service A PMI	18-Aug-2022 08:18:52	BHVYEQ	O	DON	198.83
18-Aug-2022	5,422	0	610431	06-100-PMA	Inspect A PMI	18-Aug-2022 08:19:19	SCHED	P	DON	0.00
18-Aug-2022	5,422	0	610442	03-049-004	Replace ECM Sensor	18-Aug-2022 08:40:42	BHVYEQ	W	DON	383.76
31-Aug-2022		0	613277	03-002-024	Replace Glass / Windshield	29-Nov-2022 16:37:02	TRK005	I	DON	299.17
31-Aug-2022		0	613277	03-065-007	Replace Hoses & Fittings	30-Nov-2022 13:00:39	TRK005	I	DON	61.59
01-Sep-2022		0	613746	38-100-PMA	Service A PMI	01-Sep-2022 11:45:23	BHVYEQ	O	DON	203.02
09-Sep-2022		0	615023	03-052-005	Replace Transmitter - CB	09-Sep-2022 09:26:08	BHVYEQ	O	DON	75.93
12-Oct-2022		0	623768	03-002-035	Replace Windshield Wiper & Washer	12-Oct-2022 16:26:14	BHVYEQ	O	DON	41.97
29-Nov-2022		0	635404	03-002-024	Replace Glass / Windshield	29-Nov-2022 08:46:03	BHVYEQ	N	DON	274.74
19-Dec-2022		0	640292	25-263-001	Remove Hammer Assembly	19-Dec-2022 13:56:06	TRK005	I	DON	382.85
30-Jan-2023		0	649051	03-065-027	Replace Relief Valve	30-Jan-2023 11:06:45	BHVYEQ	B	DON	1,901.82
12-Apr-2023	5,459	0	666574	03-051-009	Replace Fire Extinguisher	25-Apr-2023 07:58:02	BHVYEQ	Q	DON	143.84
12-Apr-2023	5,459	0	666574	03-065-007	Replace Hoses & Fittings	24-Apr-2023 16:45:01	BHVYEQ	I	DON	4,177.72
12-Apr-2023	5,459	0	666574	03-002-010	Replace Mirrors	25-Apr-2023 06:59:21	BHVYEQ	I	DON	69.27
12-Apr-2023	5,459	0	666574	03-002-026	Replace Weather Stripping, Gaskets & Bumpers	21-Apr-2023 14:04:59	BHVYEQ	I	DON	149.23

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: N1311 - 2018 CAT 349FL										
12-Apr-2023 1	5,459	0	666574	03-111-006	Replace Shields and Guards	24-Apr-2023 13:00:37	BHVYEQ	I	DON	1,888.43
12-Apr-2023 1	5,459	0	666574	38-100-PMB	Service B PMI	26-Apr-2023 09:52:22	BHVYEQ	P	DON	1,047.99
12-Apr-2023 1	5,459	0	666574	03-032-001	Replace Battery		BHVYEQ	I	CAN	0.00
12-Apr-2023 1	5,459	0	666574	18-032-001	Test Battery	12-Apr-2023 16:48:02	BHVYEQ	I	DON	63.63
12-Apr-2023 1	5,459	0	666574	03-065-022	Replace Flow Control Valve	21-Apr-2023 15:23:42	BHVYEQ	I	DON	819.70
12-Apr-2023 1	5,459	0	666574	02-330	Clean Excavator	25-Apr-2023 15:30:04	BWASH	N	DON	648.80
12-Apr-2023 1	5,459	0	666574	06-100-PMB	Inspect B PMI	26-Apr-2023 14:19:57	BHVYEQ	P	DON	156.74
12-Apr-2023 1	5,459	0	666574	24-002-024	Repair Glass / Windshield	18-Apr-2023 10:56:09	BHVYEQ	I	DON	324.60
12-Apr-2023 1	5,459	0	666574	03-042-012	Replace Clamps and Hoses	21-Apr-2023 13:34:23	BHVYEQ	I	DON	314.56
12-Apr-2023 1	5,459	0	666574	26-513-002	Weld Quick Attachment	26-Apr-2023 05:17:42	BHVYEQ	N	DON	50.03
12-Apr-2023 1	5,459	0	666574	03-514-002	Replace Shanks or Teeth	25-Apr-2023 15:30:07	BHVYEQ	I	DON	2,388.32
12-Apr-2023 1	5,459	0	666574	03-330-015	Replace Quik-Attach Assembly	26-Apr-2023 14:20:17	BHVYEQ	I	DON	149.98
07-Jun-2023 1	6,100	0	679636	03-065-007	Replace Windshield Wiper & Washer	25-Apr-2023 06:25:00	BHVYEQ	I	DON	38.88
07-Jun-2023 1	6,100	0	679636	03-514-002	Replace Hoses & Fittings	12-Jun-2023 08:13:29	BHVYEQ	B	DON	1,090.10
12-Jun-2023 1	6,189	0	680638	03-330-016	Replace Shanks or Teeth	07-Jun-2023 10:21:52	BHVYEQ	E	DON	1,031.64
12-Jun-2023 1	6,189	0	680638	03-514-002	Replace Frost Hook - Tooth	12-Jun-2023 10:36:44	BHVYEQ	E	DON	426.42
22-Jun-2023 1		0	683554	03-032-002	Replace Shanks or Teeth	12-Jun-2023 10:36:04	BHVYEQ	E	DON	2,371.38
22-Jun-2023 1		0	683554	06-100-PMA	Replace Starter	26-Jun-2023 13:47:35	BHVYEQ	I	DON	1,104.09
22-Jun-2023 1		0	683554	35-032	Inspect A PMI	26-Jun-2023 13:48:20	BHVYEQ	P	DON	71.92
22-Jun-2023 1		0	683554	38-100-PMA	Diagnose Cranking System	26-Jun-2023 14:00:24	BHVYEQ	I	DON	78.74
27-Jun-2023 01		0	684324	03-514-002	Service A PMI	26-Jun-2023 13:48:25	BHVYEQ	P	DON	415.94
11-Jul-2023 12		0	687201	03-043-031	Replace Shanks or Teeth	27-Jun-2023 08:15:40	BHVYEQ	E	DON	1,031.64
11-Jul-2023 12		0	687201	24-330-015	Replace Manifold - DEF	11-Jul-2023 13:00:05	BHVYEQ	B	DON	1,603.11
25-Aug-2023 1		0	700054	03-514-002	Repair Quik-Attach Assembly	11-Jul-2023 12:40:45	BHVYEQ	B	DON	1,284.33
17-Oct-2023 1		0	713602	03-514-002	Replace Shanks or Teeth	28-Aug-2023 14:48:07	BHVYEQ	E	DON	149.52
31-Oct-2023 0		0	716938	03-065-027	Replace Shanks or Teeth	17-Oct-2023 14:17:51	BHVYEQ	E	DON	149.52
13-Nov-2023 C		0	719978	03-514-002	Replace Relief Valve	31-Oct-2023 07:26:06	BHVYEQ	B	DON	1,629.18
21-Dec-2023 1		0	728559	03-002-024	Replace Shanks or Teeth	13-Nov-2023 08:34:59	BHVYEQ	E	DON	2,578.32
					Replace Glass / Windshield	29-Dec-2023 11:49:53	BHVYEQ	L	DON	301.73

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: N1311 - 2018 CAT 349FL										
21-Dec-2023 1	0	728559	03-019-007	03-019-007	Replace Hose, Tubing & Connectors	28-Dec-2023 13:43:09	BHVYEQ	N	DON	105.80
03-Jan-2024 05	0	729801	03-065-007	03-065-007	Replace Hoses & Fittings	03-Jan-2024 13:54:04	TRK005	N	DON	397.94
26-Jan-2024 05	0	734882	24-002-065	24-002-065	Repair Hood Latch	26-Jan-2024 09:39:48	BHVYEQ	N	DON	24.97
28-Feb-2024 1	0	741914	38-100-PMA	38-100-PMA	Service A PMI	28-Feb-2024 10:00:52	BHVYEQ	P	DON	235.18
07-Mar-2024 0	0	743949	03-065-007	03-065-007	Replace Hoses & Fittings	07-Mar-2024 08:14:47	BHVYEQ	B	DON	1,449.79
20-Mar-2024 1	0	747073	03-065-007	03-065-007	Replace Hoses & Fittings	20-Mar-2024 13:06:46	BHVYEQ	N	DON	1,356.61
10-Apr-2024 1	0	751782	OS-330	OS-330	Out-Service Excavator	17-Apr-2024 11:15:11	BHVYEQ	Z	DON	359.76
10-Apr-2024 1	0	751782	02-330	02-330	Clean Excavator	13-Apr-2024 03:56:18	BWASH	Z	DON	705.31
10-Apr-2024 1	0	751782	03-065-034	03-065-034	Replace Switch - Pressure	17-Apr-2024 07:55:43	BHVYEQ	Z	DON	598.27
10-Apr-2024 1	0	751782	18-706-003	18-706-003	Test Wiring	19-Apr-2024 15:41:52	BHVYEQ	Z	DON	171.56
10-Apr-2024 1	0	751782	24-049-001	24-049-001	Repair ECM Fault Code	02-May-2024 14:01:38	BHVYEQ	N	DON	1,155.73