

Unit Job History

Michels Corporation

Report Printed: 17-Nov-2023 12:31:00 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: A0600 - 2004 INTERNATIONAL 4300										
27-Jan-2009 05	41,391	1,912	8297	03-017-001	Replace Tire - Pneumatic	30-Jan-2009 15:33:49	BTRUCK	I	DON	1,596.66
27-Jan-2009 05	41,391	1,912	8297	03-034-002	Replace Stop, Tail, Turn & License	30-Jan-2009 16:51:37	BTRUCK	I	DON	51.41
27-Jan-2009 05	41,391	1,912	8297	06-100-001	Inspect DO NOT USE - PMI Service	30-Jan-2009 15:50:15	BTRUCK	P	DON	200.16
27-Jan-2009 05	41,391	1,912	8297	06-100-002	Inspect DO NOT USE - DOT Federal Insp	02-Feb-2009 07:15:21	BTRUCK	J	DON	10.08
08-May-2009 05	42,903	1,962	13020	24-045	Repair Power Plant	20-May-2009 05:42:32	BTRUCK	O	DON	995.15
08-May-2009 05	42,903	1,962	13020	02-032-001	Clean Battery	20-May-2009 05:42:38	BTRUCK	I	DON	0.00
08-May-2009 05	42,903	1,962	13020	03-013-003	Replace Brake Chamber - Parking	20-May-2009 05:42:35	BTRUCK	I	DON	0.00
08-May-2009 05	42,903	1,962	13020	03-054-001	Replace Horn & Mounting	20-May-2009 05:42:43	BTRUCK	I	DON	0.00
08-May-2009 05	42,903	1,962	13020	09-015-001	Align Steering Wheel	20-May-2009 05:42:40	BTRUCK	I	DON	0.00
18-Jun-2009 15	44,651	2,012	15381	03-003-001	Replace Gauges & Warning Devices	18-Jun-2009 16:46:52	BTRUCK	O	DON	54.56
01-Oct-2009 05	48,741	2,012	22952	06-100-001	Inspect DO NOT USE - PMI Service	02-Oct-2009 13:58:59	BTRUCK	P	DON	229.26
01-Oct-2009 05	48,741	2,012	22952	24-013	Repair Brakes	02-Oct-2009 13:58:15	BTRUCK	O	DON	41.40
01-Oct-2009 05	48,741	2,012	22952	03-171	Replace Mixer Body	02-Oct-2009 10:42:32	BTRUCK	I	DON	18.06
01-Oct-2009 05	48,741	2,012	22952	03-059-002	Replace Pintle Hook Assembly	02-Oct-2009 13:34:00	BTRUCK	I	DON	36.96
04-Jan-2010 05	50,999	2,220	30370	01-015-005	Adjust Power Steering Pump	18-Jan-2010 09:35:06	BTRUCK	I	DON	11.24
04-Jan-2010 05	50,999	2,220	30370	01-017-001	Adjust Tire - Pneumatic	15-Jan-2010 08:44:01	BTRUCK	I	DON	13.70
04-Jan-2010 05	50,999	2,220	30370	03-013-009	Replace Air Compressor	18-Jan-2010 09:55:20	BTRUCK	I	DON	29.08
04-Jan-2010 05	50,999	2,220	30370	03-026-009	Replace Cover Assembly	18-Jan-2010 10:58:11	BTRUCK	I	DON	126.58
04-Jan-2010 05	50,999	2,220	30370	03-032-001	Replace Battery	15-Jan-2010 10:22:21	BTRUCK	I	DON	328.84
04-Jan-2010 05	50,999	2,220	30370	03-034-010	Replace Socket - Trailer Light Cord	15-Jan-2010 11:58:28	BTRUCK	I	DON	142.97
04-Jan-2010 05	50,999	2,220	30370	03-002-035	Replace Windshield Wiper & Washer	18-Jan-2010 08:33:03	BTRUCK	I	DON	25.28
04-Jan-2010 05	50,999	2,220	30370	06-056-001	Inspect Power Take Off	18-Jan-2010 11:16:32	BTRUCK	I	DON	26.37
04-Jan-2010 05	50,999	2,220	30370	06-100-001	Inspect DO NOT USE - PMI Service	15-Jan-2010 11:07:10	BDETL	I	DON	321.52
04-Jan-2010 05	50,999	2,220	30370	06-100-002	Inspect DO NOT USE - DOT Federal Insp	11-Jan-2010 15:00:00	BTRUCK	P	DON	75.23
04-Jan-2010 05	50,999	2,220	30370	07-002-018	Lubricate Cab Or Front Door Mechanism	15-Jan-2010 08:34:29	BTRUCK	I	DON	3.91
04-Jan-2010 05	50,999	2,220	30370	07-013-017	Lubricate Slack Adjuster	20-Jan-2010 09:00:00	BTRUCK	I	DON	75.11
04-Jan-2010 05	50,999	2,220	30370	11-013-016	Rebuild Air Dryer / Purge Valve	18-Jan-2010 09:00:00	BTRUCK	I	DON	222.62
04-Jan-2010 05	50,999	2,220	30370	03-001-016	Replace Filter - Cab Ventilation	15-Jan-2010 10:23:47	BTRUCK	I	DON	2.06
04-Jan-2010 05	50,999	2,220	30370	01-071-006	Adjust Bolster & Hold-Down	18-Jan-2010 08:43:20	BTRUCK	I	DON	14.78

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: A0600 - 2004 INTERNATIONAL 4300										
04-Jan-2010 05	50,999	2,220	30370	03-045-024	Replace Seal - Crankshaft (Front)	25-Jan-2010 16:56:38	BTRUCK	I	DON	389.63
04-Jan-2010 05	50,999	2,220	30370	24-051-006	Repair Safety Devices	18-Jan-2010 10:42:05	BTRUCK	I	DON	67.21
04-Jan-2010 05	50,999	2,220	30370	02-032-001	Clean Battery	15-Jan-2010 09:00:00	BTRUCK	I	DON	77.72
04-Jan-2010 05	50,999	2,220	30370	02-002-044	Clean Cab - Complete	15-Jan-2010 11:06:49	BDETL	Q	DON	317.47
23-Aug-2010 C	59,891	2,461	48353	06-100-001	Inspect DO NOT USE - PMI Service	23-Aug-2010 09:00:00	BTRUCK	P	DON	237.12
23-Aug-2010 C	59,891	2,461	48353	31-017-001	Rotate Tire - Pneumatic	23-Aug-2010 08:52:23	BTRUCK	I	DON	14.49
03-Jan-2011 08	66,791	2,725	56223	02-002-044	Clean Cab - Complete	10-Jan-2011 12:32:00	BDETL	Q	DON	20.44
03-Jan-2011 08	66,791	2,725	56223	12-510-002	Refinish Tool Box	10-Jan-2011 12:32:07	BDETL	Q	CAN	0.00
03-Jan-2011 08	66,791	2,725	56223	15-510-002	Paint Prep Tool Box	10-Jan-2011 12:32:07	BDETL	Q	DON	64.75
03-Jan-2011 08	66,791	2,725	56223	06-100-001	Inspect DO NOT USE - PMI Service	11-Jan-2011 07:06:31	BTRUCK	P	DON	195.07
03-Jan-2011 08	66,791	2,725	56223	06-100-002	Inspect DO NOT USE - DOT Federal Insp	11-Jan-2011 10:24:25	BTRUCK	P	DON	24.60
03-Jan-2011 08	66,791	2,725	56223	14-063-003	Install Transceiver - GPS Tracker	11-Jan-2011 08:19:15	BTRUCK	C	DON	353.84
03-Jan-2011 08	66,791	2,725	56223	03-034-003	Replace Signal, Parking, Backup Lamps	11-Jan-2011 08:35:14	BTRUCK	I	DON	8.78
03-Jan-2011 08	66,791	2,725	56223	03-013-023	Replace Air Governor	11-Jan-2011 10:24:13	BTRUCK	I	DON	34.37
06-May-2011 1	69,852	2,844	64932	03-013-003	Replace Brake Chamber - Parking	06-May-2011 17:01:22	BTRUCK	I	DON	136.93
06-May-2011 1	69,852	2,844	64932	24-034-002	Repair Stop, Tail, Turn & License	06-May-2011 15:00:00	BTRUCK	O	DON	28.30
08-Jul-2011 13	71,792	2,928	68714	06-100-001	Inspect DO NOT USE - PMI Service	12-Jul-2011 07:05:57	BTRUCK	P	DON	208.13
08-Jul-2011 13	71,792	2,928	68714	06-045	Inspect Power Plant	11-Jul-2011 15:00:00	BTRUCK	I	DON	2,476.67
08-Jul-2011 13	71,792	2,928	68714	03-002-035	Replace Windshield Wiper & Washer	12-Jul-2011 08:40:58	BTRUCK	I	DON	13.33
08-Jul-2011 13	71,792	2,928	68714	03-054-002	Replace Alarm - Reverse Signal	12-Jul-2011 08:34:58	BTRUCK	I	DON	74.24
21-Jul-2011 10	71,792	2,928	69381	03-052-003	Replace Radio Equipment	21-Jul-2011 11:20:47	BBODY	O	DON	305.18
19-Dec-2011 0	74,809	3,055	78084	24-034-002	Repair Stop, Tail, Turn & License	19-Dec-2011 06:41:18	BTRUCK	O	DON	26.89
10-Feb-2012 1	75,034	3,071	81502	03-017-001	Replace Tire - Pneumatic	14-Feb-2012 06:23:57	BTRUCK	I	DON	853.31
10-Feb-2012 1	75,034	3,071	81502	03-043-003	Replace Muffler	13-Feb-2012 12:02:57	BTRUCK	I	DON	257.61
10-Feb-2012 1	75,034	3,071	81502	06-100-DOT	Inspect DOT Federal Inspection	13-Feb-2012 14:44:38	BTRUCK	P	DON	317.50
10-Feb-2012 1	75,034	3,071	81502	09-016-050	Align Alignment All Wheel	22-Feb-2012 11:39:06	BTRUCK	I	DON	274.15
10-Feb-2012 1	75,034	3,071	81502	24-034-004	Repair Clearance & Marker Lamps	13-Feb-2012 12:54:51	BTRUCK	I	DON	7.39
10-Feb-2012 1	75,034	3,071	81502	24-034-006	Repair Warning Lamps - Special Application	13-Feb-2012 14:15:27	BTRUCK	I	DON	136.92
10-Feb-2012 1	75,034	3,071	81502	31-017-001	Rotate Tire - Pneumatic	14-Feb-2012 07:53:22	BTRUCK	I	DON	53.91

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: A0600 - 2004 INTERNATIONAL 4300										
10-Feb-2012 1	75,034	3,071	81502	24-045	Repair Power Plant	21-Feb-2012 07:36:44	BTRUCK	I	DON	1,415.92
12-Apr-2012 0	77,690	3,159	85738	24-034-002	Repair Stop, Tail, Turn & License	12-Apr-2012 06:18:56	BTRUCK	O	DON	3.19
26-Apr-2012 0	78,614	3,186	86806	03-054-001	Replace Horn & Mounting	01-May-2012 06:17:26	BTRUCK	I	DON	53.49
26-Apr-2012 0	78,614	3,186	86806	06-100-PMB	Inspect B PMI	01-May-2012 05:28:13	BTRUCK	P	DON	217.11
26-Apr-2012 0	78,614	3,186	86806	24-049-004	Repair ECM Sensor	26-Apr-2012 09:00:00	BTRUCK	O	DON	159.18
25-Sep-2012 0	82,505	3,365	97014	06-100-009	Inspect Safety Check	03-Oct-2012 14:33:06	BTRUCK	I	DON	65.84
25-Sep-2012 0	82,505	3,365	97014	24-002-020	Repair Side Door Mechanism	03-Oct-2012 11:36:54	BTRUCK	I	DON	241.84
25-Sep-2012 0	82,505	3,365	97014	24-014-002	Repair Bumpers & Attaching Parts	25-Sep-2012 17:04:38	BTRUCK	I	DON	65.62
17-Jan-2013 1	84,339	3,565	105044	38-052-003	Service Radio Equipment	17-Jan-2013 14:18:35	BBODY	C	DON	0.92
14-Feb-2013 1	84,339	3,565	108058	02-002-044	Clean Cab - Complete	18-Mar-2013 04:57:37	BDETL	J	DON	364.17
14-Feb-2013 1	84,339	3,565	108058	03-002-029	Replace Trim - Seat	14-Feb-2013 16:04:59	BTRUCK	I	DON	163.08
14-Feb-2013 1	84,339	3,565	108058	03-051-009	Replace Fire Extinguisher	12-Mar-2013 12:04:00	BTRUCK	I	DON	15.94
14-Feb-2013 1	84,339	3,565	108058	03-034-010	Replace Socket - Trailer Light Cord	24-Mar-2013 08:25:30	BTRUCK	I	DON	336.46
14-Feb-2013 1	84,339	3,565	108058	06-100-DOT	Inspect DOT Federal Inspection	24-Mar-2013 08:25:27	BTRUCK	P	DON	0.00
14-Feb-2013 1	84,339	3,565	108058	06-100-PMB	Inspect B PMI	24-Mar-2013 08:25:24	BTRUCK	P	DON	772.12
14-Feb-2013 1	84,339	3,565	108058	12-018-003	Refinish Wheels	15-Mar-2013 13:08:38	BDETL	J	DON	255.62
14-Feb-2013 1	84,339	3,565	108058	15-018-003	Paint Prep Wheels	18-Mar-2013 04:57:34	BDETL	J	DON	47.42
14-Feb-2013 1	84,339	3,565	108058	24-096-002	Repair Power Shaft Assembly - PTO	24-Mar-2013 08:25:34	BTRUCK	I	DON	686.28
14-Feb-2013 1	84,339	3,565	108058	24-001-002	Repair Heating & Ventilating	24-Mar-2013 08:25:39	BTRUCK	I	DON	647.21
14-Feb-2013 1	84,339	3,565	108058	24-002-010	Repair Mirrors	24-Mar-2013 08:26:13	BTRUCK	I	DON	139.58
14-Feb-2013 1	84,339	3,565	108058	24-003-010	Repair Air Pressure Gauge (Pri/Sec)	24-Mar-2013 08:26:27	BTRUCK	I	DON	420.48
14-Feb-2013 1	84,339	3,565	108058	24-013-010	Repair Air Brake Valve	24-Mar-2013 08:26:30	BTRUCK	I	DON	318.57
14-Feb-2013 1	84,339	3,565	108058	24-013-017	Repair Slack Adjuster	24-Mar-2013 08:26:05	BTRUCK	I	DON	106.91
14-Feb-2013 1	84,339	3,565	108058	24-015-005	Repair Power Steering Pump	24-Mar-2013 08:25:49	BTRUCK	I	DON	24.55
14-Feb-2013 1	84,339	3,565	108058	03-044-002	Replace Filters	24-Mar-2013 08:26:34	BTRUCK	I	DON	53.24
14-Feb-2013 1	84,339	3,565	108058	06-034	Inspect Lighting System	24-Mar-2013 08:25:41	BTRUCK	I	DON	40.91
14-Feb-2013 1	84,339	3,565	108058	03-032-001	Replace Battery	24-Mar-2013 08:26:02	BTRUCK	I	DON	307.75
14-Feb-2013 1	84,339	3,565	108058	03-002-026	Replace Weather Stripping, Gaskets & Bumpers	24-Mar-2013 08:26:17	BTRUCK	I	DON	276.17
14-Feb-2013 1	84,339	3,565	108058	01-023-002	Adjust Clutch Assembly	24-Mar-2013 08:25:51	BTRUCK	I	DON	296.62

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: A0600 - 2004 INTERNATIONAL-4300										
14-Feb-2013 1	84,339	3,565	108058	24-015-007	Repair Control Valve - Tie Rod Type	24-Mar-2013 08:25:37	BTRUCK	I	DON	728.42
14-Feb-2013 1	84,339	3,565	108058	24-018-001	Repair Front Axle Hubs & Bearings	24-Mar-2013 08:26:19	BTRUCK	I	DON	128.37
14-Feb-2013 1	84,339	3,565	108058	24-034-003	Repair Signal, Parking, Backup Lamps	24-Mar-2013 08:26:07	BTRUCK	I	DON	16.87
14-Feb-2013 1	84,339	3,565	108058	38-013-016	Service Air Dryer / Purge Valve	24-Mar-2013 08:26:00	BTRUCK	I	DON	243.85
14-Feb-2013 1	84,339	3,565	108058	24-041-001	Repair Air Cleaner	24-Mar-2013 08:26:10	BTRUCK	I	DON	83.14
14-Feb-2013 1	84,339	3,565	108058	24-045-001	Repair Front Covers	24-Mar-2013 08:25:57	BTRUCK	I	DON	2,853.74
14-Feb-2013 1	84,339	3,565	108058	24-053-015	Repair Tool Box	24-Mar-2013 08:25:44	BTRUCK	I	DON	90.00
14-Feb-2013 1	84,339	3,565	108058	24-056-001	Repair Power Take Off	24-Mar-2013 08:25:54	BTRUCK	I	DON	122.73
14-Feb-2013 1	84,339	3,565	108058	24-034-010	Repair Socket - Trailer Light Cord	12-Mar-2013 13:30:38	BTRUCK	I	DON	38.05
17-Jul-2013 07	86,601		124121	24-071-001	Repair Floor / Decking / Flatbed	29-Jul-2013 08:30:10	BTRUCK	I	DON	629.04
17-Jul-2013 07	86,601		124121	24-043	Repair Exhaust System	26-Jul-2013 14:08:43	BTRUCK	O	DON	0.00
17-Jul-2013 07	86,601		124121	03-043-004	Replace Turbocharger	26-Jul-2013 14:08:47	BTRUCK	I	DON	3,380.79
09-Dec-2013 0	88,984		139291	03-032-002	Replace Starter	20-Dec-2013 13:29:19	BTRUCK	O	DON	1,162.34
26-Feb-2014 1	89,932		148186	24-013-030	Repair Switch - Parking Brake	28-Feb-2014 08:00:04	BTRUCK	I	DON	323.59
27-May-2014 1	91,446		159244	03-002-010	Replace Mirrors	27-May-2014 05:30:08	BTRUCK	I	DON	127.39
04-Jun-2014 1	91,887		160439	06-100-DOT	Inspect DOT Federal Inspection	04-Jun-2014 16:32:00	BTRUCK	P	DON	76.15
04-Jun-2014 1	91,887		160439	06-100-PMA	Inspect A PMI	04-Jun-2014 16:32:03	BTRUCK	P	DON	439.71
04-Jun-2014 1	91,887		160439	24-043-007	Repair Exhaust Pipe/Elbow	04-Jun-2014 16:31:54	BTRUCK	I	DON	183.98
12-Jun-2014 0	92,549		161350	03-013-030	Replace Switch - Parking Brake	12-Jun-2014 16:46:46	BTRUCK	O	DON	218.05
12-Jun-2014 0	92,549		161350	24-013-011	Repair Anti-Lock Sensor Assembly	12-Jun-2014 11:35:13	BTRUCK	O	DON	151.24
12-Jun-2014 0	92,549		161350	03-051-009	Replace Fire Extinguisher	12-Jun-2014 12:55:53	BTRUCK	I	DON	26.18
12-Jun-2014 0	92,549		161350	03-065-006	Replace Filters, Strainers, Screens & Housing	12-Jun-2014 13:42:49	BTRUCK	I	DON	49.79
12-Jun-2014 0	92,549		161350	03-041-007	Replace Filter - Outer	12-Jun-2014 13:17:32	BTRUCK	I	DON	35.72
12-Jun-2014 0	92,549		161350	03-001-016	Replace Filter - Cab Ventilation	12-Jun-2014 13:06:16	BTRUCK	I	DON	30.68
10-Jan-2015 0	98,981	4,220	187241	03-002-035	Replace Windshield Wiper & Washer	12-Jan-2015 08:10:15	BTRUCK	I	DON	14.31
10-Jan-2015 0	98,981	4,220	187241	03-013-002	Replace Rear Brakes & Drums	16-Jan-2015 09:43:48	BTRUCK	I	DON	474.38
10-Jan-2015 0	98,981	4,220	187241	03-034-001	Replace Headlamps / Fog Lamps	16-Jan-2015 05:34:08	BTRUCK	I	DON	763.05
10-Jan-2015 0	98,981	4,220	187241	03-042-012	Replace Clamps and Hoses	15-Jan-2015 09:29:42	BTRUCK	I	DON	24.94
10-Jan-2015 0	98,981	4,220	187241	03-042-014	Replace Coolant Overflow Reservoir	15-Jan-2015 11:04:22	BTRUCK	I	DON	308.19

Unit Job History

Michels Corporation

Report Printed: 17-Nov-2023 12:31:00 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: A0600 - 2004 INTERNATIONAL-4300										
10-Jan-2015 0:	98,981	4,220	187241	03-042-015	Replace Fan Hub	15-Jan-2015 09:25:40	BTRUCK	I	DON	537.55
10-Jan-2015 0:	98,981	4,220	187241	03-044-001	Replace Tank - Fuel, Liquid	13-Jan-2015 05:51:31	BTRUCK	I	DON	88.15
10-Jan-2015 0:	98,981	4,220	187241	03-045-023	Replace Engine Belts	15-Jan-2015 07:17:42	BTRUCK	I	DON	25.81
10-Jan-2015 0:	98,981	4,220	187241	03-045-024	Replace Seal - Crankshaft (Front)	15-Jan-2015 07:12:34	BTRUCK	I	DON	214.86
10-Jan-2015 0:	98,981	4,220	187241	03-051-009	Replace Fire Extinguisher	13-Jan-2015 06:10:46	BTRUCK	I	DON	0.86
10-Jan-2015 0:	98,981	4,220	187241	03-054-002	Replace Alarm - Reverse Signal	10-Mar-2015 07:31:24	BTRUCK	I	DON	36.56
10-Jan-2015 0:	98,981	4,220	187241	03-059-002	Replace Pintle Hook Assembly	10-Mar-2015 07:28:39	BTRUCK	I	DON	370.26
10-Jan-2015 0:	98,981	4,220	187241	03-063-003	Replace Transceiver - GPS Tracker	13-Jan-2015 07:39:19	BTRUCK	C	DON	260.53
10-Jan-2015 0:	98,981	4,220	187241	03-078-009	Replace Mud Flaps and Hanger Brackets	10-Mar-2015 07:28:50	BTRUCK	I	DON	22.92
10-Jan-2015 0:	98,981	4,220	187241	03-510-002	Replace Tool Box	10-Mar-2015 07:29:02	BTRUCK	I	DON	379.04
10-Jan-2015 0:	98,981	4,220	187241	06-100-DOT	Inspect DOT Federal Inspection	10-Mar-2015 08:25:44	BTRUCK	P	DON	25.09
10-Jan-2015 0:	98,981	4,220	187241	06-100-PMB	Inspect B PMI	12-Jan-2015 07:59:15	BTRUCK	P	DON	272.46
10-Jan-2015 0:	98,981	4,220	187241	11-013-016	Rebuild Air Dryer / Purge Valve	12-Jan-2015 13:17:55	BTRUCK	P	DON	169.93
10-Jan-2015 0:	98,981	4,220	187241	12-002	Refinish Cab & Sheet Metal	04-Mar-2015 18:45:19	BBODY	C	DON	335.01
10-Jan-2015 0:	98,981	4,220	187241	12-071-001	Refinish Floor / Decking / Flatbed	03-Mar-2015 12:15:46	BBODY	C	DON	896.44
10-Jan-2015 0:	98,981	4,220	187241	14-079-009	Install Tape - Reflective, Conspicuity	10-Mar-2015 07:40:20	BTRUCK	I	DON	16.61
10-Jan-2015 0:	98,981	4,220	187241	15-002	Paint Prep Cab & Sheet Metal	10-Mar-2015 07:29:12	BBODY	C	DON	546.17
10-Jan-2015 0:	98,981	4,220	187241	15-071-001	Paint Prep Floor / Decking / Flatbed	06-Mar-2015 13:30:03	BSAND	C	DON	1,261.35
10-Jan-2015 0:	98,981	4,220	187241	18-032-001	Test Battery	13-Jan-2015 06:09:13	BTRUCK	I	DON	43.31
10-Jan-2015 0:	98,981	4,220	187241	19-034-002	Wire/Rewire Stop, Tail, Turn & License	10-Mar-2015 07:25:40	BTRUCK	I	DON	599.53
10-Jan-2015 0:	98,981	4,220	187241	24-002-002	Repair Fenders	12-Jan-2015 14:47:23	BTRUCK	I	DON	19.39
10-Jan-2015 0:	98,981	4,220	187241	24-002-011	Repair Cab Accessories - Interior	12-Jan-2015 13:27:06	BTRUCK	I	DON	5.54
10-Jan-2015 0:	98,981	4,220	187241	24-002-023	Repair Handles - Inner & Outer	13-Jan-2015 09:01:24	BTRUCK	I	DON	92.69
10-Jan-2015 0:	98,981	4,220	187241	24-034-004	Repair Clearance & Marker Lamps	13-Jan-2015 06:29:27	BTRUCK	O	DON	12.43
10-Jan-2015 0:	98,981	4,220	187241	24-173-001	Repair Body or Bed	23-Jan-2015 17:00:06	BWELD	N	DON	1,730.06
10-Jan-2015 0:	98,981	4,220	187241	25-017-001	Remove Tire - Pneumatic	16-Jan-2015 09:59:56	BTRUCK	I	DON	8.91
10-Jan-2015 0:	98,981	4,220	187241	38-045	Service Power Plant	12-Jan-2015 15:34:46	BTRUCK	P	DON	227.22
17-Mar-2015 1	98,981	4,220	194870	02-002	Clean Cab & Sheet Metal	23-Mar-2015 05:50:38	BSETUP	J	DON	201.55
23-Mar-2015 0	98,982	4,221	195466	24-034-010	Repair Socket - Trailer Light Cord	23-Mar-2015 08:08:01	BTRUCK	O	DON	22.79

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: A0600 - 2004 INTERNATIONAL 4300										
26-Mar-2015 0	99,580	4,221	195865	24-045	Repair Power Plant	10-Apr-2015 08:32:24	BTRUCK	I	DON	7,816.52
26-Mar-2015 0	99,580	4,221	195865	03-042-008	Replace Oil Cooler	10-Apr-2015 08:31:47	BTRUCK	I	DON	1,191.85
17-Jul-2015 13	102,203	4,425	208101	24-044-007	Repair Throttle Controls	20-Jul-2015 07:05:25	BTRUCK	O	DON	36.64
17-Jul-2015 13	102,203	4,425	208101	03-002-065	Replace Hood Latch	20-Jul-2015 07:21:03	BTRUCK	I	DON	163.53
05-Aug-2015 1	102,666	4,495	210258	01-023-002	Adjust Clutch Assembly	07-Aug-2015 17:02:21	BTRUCK	O	DON	14.72
05-Oct-2015 1	103,596	4,721	217177	24-026	Repair Transmission - Main, Manual	15-Oct-2015 13:34:43	BTRUCK	O	DON	4,910.19
05-Oct-2015 1	103,596	4,721	217177	06-100-009	Inspect Safety Check	15-Oct-2015 07:19:27	BTRUCK	I	DON	31.00
05-Oct-2015 1	103,596	4,721	217177	06-100-PMB	Inspect B PMI	15-Oct-2015 10:38:17	BTRUCK	P	DON	56.04
05-Oct-2015 1	103,596	4,721	217177	01-013-035	Adjust Clevis Pins	15-Oct-2015 08:10:59	BTRUCK	I	DON	141.91
05-Oct-2015 1	103,596	4,721	217177	03-023-002	Replace Clutch Assembly	15-Oct-2015 08:11:18	BTRUCK	I	DON	867.67
05-Oct-2015 1	103,596	4,721	217177	03-045-024	Replace Seal - Crankshaft (Front)	15-Oct-2015 08:11:06	BTRUCK	I	DON	395.11
05-Oct-2015 1	103,596	4,721	217177	03-045-025	Replace Seal - Crankshaft (Rear)	15-Oct-2015 08:11:15	BTRUCK	I	DON	588.08
05-Oct-2015 1	103,596	4,721	217177	34-045-009	Reseal Oil Pump & Distribution System	15-Oct-2015 08:11:08	BTRUCK	I	DON	403.67
05-Oct-2015 1	103,596	4,721	217177	24-043-004	Repair Turbocharger	15-Oct-2015 08:11:03	BTRUCK	I	DON	181.31
05-Oct-2015 1	103,596	4,721	217177	03-017-001	Replace Tire - Pneumatic	15-Oct-2015 13:33:07	BTRUCK	I	DON	101.58
05-Oct-2015 1	103,596	4,721	217177	01-023-002	Adjust Clutch Assembly	15-Oct-2015 10:55:53	BTRUCK	I	DON	9.53
05-Oct-2015 1	103,596	4,721	217177	38-013-016	Service Air Dryer / Purge Valve	15-Oct-2015 08:11:12	BTRUCK	I	DON	354.96
05-Oct-2015 1	103,596	4,721	217177	38-045	Service Power Plant	15-Oct-2015 08:24:36	BTRUCK	P	DON	170.60
10-Mar-2016 1	110,242	4,902	236839	06-100-DOT	Inspect DOT Federal Inspection	11-Mar-2016 15:57:07	BTRUCK	P	DON	43.63
10-Mar-2016 1	110,242	4,902	236839	24-013-032	Repair ABS - ECU	11-Mar-2016 16:12:46	BTRUCK	O	DON	168.62
10-Mar-2016 1	110,242	4,902	236839	01-051-006	Adjust Safety Devices	11-Mar-2016 14:55:04	BTRUCK	I	DON	3.31
10-Mar-2016 1	110,242	4,902	236839	02-032-001	Clean Battery	11-Mar-2016 15:21:35	BTRUCK	I	DON	17.76
10-Mar-2016 1	110,242	4,902	236839	03-003-014	Replace Oil Pressure Gauge	11-Mar-2016 14:43:47	BTRUCK	I	DON	159.82
10-Mar-2016 1	110,242	4,902	236839	03-034-004	Replace Clearance & Marker Lamps	11-Mar-2016 14:50:29	BTRUCK	I	DON	8.36
10-Mar-2016 1	110,242	4,902	236839	03-051-009	Replace Fire Extinguisher	11-Mar-2016 14:57:01	BTRUCK	I	DON	27.52
15-Mar-2016 0	110,250	4,943	240293	03-063-003	Replace Transceiver - GPS Tracker	15-Mar-2016 00:00:00	GPSINS	Q	DON	464.34
29-Aug-2016 1	116,341	4,943	257520	24-013	Repair Brakes	31-Aug-2016 00:00:00	BVLOFC	N	DON	420.75
01-Dec-2016 0	124,837	4,943	268254	38-100-PMA	Service A PMI	01-Dec-2016 15:34:19	MONSHP	P	DON	72.66
01-Dec-2016 0	124,837	4,943	268254	03-043-003	Replace Muffler	23-Jan-2017 14:03:41	MONSHP	I	DON	49.50

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: A0600 - 2004 INTERNATIONAL-4300										
01-Dec-2016 0	124,837	4,943	268254	06-100-DOT	Inspect DOT Federal Inspection	18-Jul-2017 12:20:26	MONSHP	P	DON	37.17
01-Dec-2016 0	124,837	4,943	268254	06-034-004	Inspect Clearance & Marker Lamps	18-Jul-2017 12:20:50	MONSHP	B	DON	51.02
01-Dec-2016 0	124,837	4,943	268254	06-043-007	Inspect Exhaust Pipe/Elbow	18-Jul-2017 12:21:10	MONSHP	B	DON	42.52
01-Dec-2016 0	124,837	4,943	268254	24-034-004	Repair Clearance & Marker Lamps	18-Jul-2017 12:21:23	MONSHP	O	DON	85.04
07-Aug-2017 1	129,267	5,709	299973	35-040	Diagnose Engine / Motor Systems Group	16-Oct-2017 13:39:31	MONSHP	O	DON	68.03
28-Dec-2017 0	132,506	5,811	317428	14-044	Install Fuel System	28-Dec-2017 09:25:52	MONSHP	P	DON	7.62
13-Mar-2018 1	133,993	5,880	327154	38-100-PMC	Service C PMI	13-Mar-2018 12:29:07	MONSHP	P	DON	153.64
13-Mar-2018 1	133,993	5,880	327154	24-034-004	Repair Clearance & Marker Lamps	13-Mar-2018 14:52:54	MONSHP	I	DON	17.72
13-Mar-2018 1	133,993	5,880	327154	01-023-003	Adjust Pressure Plate	13-Mar-2018 14:52:44	MONSHP	I	DON	8.50
13-Mar-2018 1	133,993	5,880	327154	06-100-DOT	Inspect DOT Federal Inspection	13-Mar-2018 14:52:15	MONSHP	P	DON	25.51
13-Mar-2018 1	133,993	5,880	327154	01-013-001	Adjust Front Brakes & Drums	13-Mar-2018 14:52:26	MONSHP	I	DON	8.50
13-Mar-2018 1	133,993	5,880	327154	01-013-002	Adjust Rear Brakes & Drums	13-Mar-2018 14:52:34	MONSHP	I	DON	8.50
21-Sep-2018 0	134,435	5,901	353127	06-010	Inspect Chassis Group	21-Sep-2018 13:06:07	MONSHP	I	DON	25.51
21-Sep-2018 0	134,435	5,901	353127	01-013-004	Adjust Brake Chamber - Service	21-Sep-2018 13:06:14	MONSHP	I	DON	25.51
21-Sep-2018 0	134,435	5,901	353127	01-023-003	Adjust Pressure Plate	21-Sep-2018 13:06:22	MONSHP	I	DON	34.02
31-Oct-2018 0	140,274	6,049	358892	06-040	Inspect Engine / Motor Systems Group	15-Nov-2018 13:12:33	MONSHP	B	DON	398.25
31-Oct-2018 0	140,274	6,049	358892	06-100-PMA	Inspect A PMI	15-Nov-2018 13:12:37	MONSHP	P	DON	560.93
31-Oct-2018 0	140,274	6,049	358892	01-023	Adjust Clutch	15-Nov-2018 13:13:35	MONSHP	O	DON	166.20
28-Nov-2018 1	142,540	6,109	362093	06-173-003	Inspect Hydraulics	06-Feb-2019 10:20:27	MONSHP	O	DON	1,133.16
28-Nov-2018 1	142,540	6,109	362093	06-002-018	Inspect Cab Or Front Door Mechanism	06-Feb-2019 10:20:38	MONSHP	O	DON	0.00
28-Nov-2018 1	142,540	6,109	362093	06-026-012	Inspect Transmission Assembly - Manual	06-Feb-2019 10:20:32	MONSHP	O	DON	0.00
28-Nov-2018 1	142,540	6,109	362093	03-065-007	Replace Hoses & Fittings	06-Feb-2019 10:28:41	MONSHP	I	DON	111.73
28-Nov-2018 1	142,540	6,109	362093	11-173-003	Rebuild Hydraulics	29-Jan-2019 10:05:46	MONSHP	B	DON	1,266.89
28-Nov-2018 1	142,540	6,109	362093	01-023	Adjust Clutch	06-Feb-2019 10:28:41	MONSHP	O	DON	111.73
28-Nov-2018 1	142,540	6,109	362093	06-003	Inspect Instruments, Gauges, Warning & Shutdo	06-Feb-2019 10:28:41	MONSHP	O	DON	169.29
28-Nov-2018 1	142,540	6,109	362093	06-013-032	Inspect ABS - ECU	06-Feb-2019 10:28:41	MONSHP	O	DON	335.19
28-Nov-2018 1	142,540	6,109	362093	24-071-005	Repair Side Door Assembly - Hinged	06-Feb-2019 10:28:41	MONSHP	O	DON	402.43
06-May-2019 1	142,747	6,116	384476	24-013-032	Repair ABS - ECU	20-May-2019 06:51:10	MONSHP	O	DON	784.59
06-May-2019 1	142,747	6,116	384476	24-040	Repair Engine / Motor Systems Group	20-May-2019 06:50:36	MONSHP	B	DON	2,912.82

Unit Job History

Michels Corporation

Report Printed: 17-Nov-2023 12:31:00 By User: RHEENING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: A0600 - 2004 INTERNATIONAL 4300										
06-May-2019	142,747	6,116	384476	24-054-001	Repair Horn & Mounting	12-Jun-2019 09:58:42	MONSHP	O	DON	187.93
06-May-2019	142,747	6,116	384476	06-054-001	Inspect Horn & Mounting	12-Jun-2019 09:58:30	MONSHP	O	DON	0.00
06-May-2019	142,747	6,116	384476	06-100-DOT	Inspect DOT Federal Inspection	12-Jun-2019 09:58:26	MONSHP	P	DON	25.52
20-Jun-2019	144,963	6,177	391001	24-044-024	Repair Fuel / Water Separator	28-Jun-2019 07:47:50	MONSHP	B	DON	4,461.36
31-Jul-2019	144,404	6,182	396624	03-034-004	Replace Clearance & Marker Lamps	01-Aug-2019 08:17:31	MONSHP	B	DON	36.78
19-Aug-2019	144,771	6,182	399183	03-014-005	Replace Battery Support / Battery Box	20-Aug-2019 10:37:00	MONSHP	B	DON	15.57
11-Nov-2019	150,622	6,601	412136	38-100-PMB	Service B PMI	12-Nov-2019 10:41:36	MONSHP	P	DON	339.81
11-Nov-2019	150,622	6,601	412136	06-100-PMB	Inspect B PMI	13-Nov-2019 11:40:46	BTRUCK	P	DON	0.00
12-May-2020	152,345	6,747	440323	03-034-002	Replace Stop, Tail, Turn & License	13-May-2020 13:35:15	MONSHP	O	DON	25.27
12-May-2020	152,345	6,747	440323	03-034-010	Replace Socket - Trailer Light Cord	03-Jun-2020 12:50:17	MONSHP	I	DON	40.34
12-May-2020	152,345	6,747	440323	06-032-002	Inspect Starter	20-May-2020 10:29:57	MONSHP	B	DON	306.70
12-May-2020	152,345	6,747	440323	06-100-DOT	Inspect DOT Federal Inspection	03-Jun-2020 12:49:59	MONSHP	P	DON	25.52
12-May-2020	152,345	6,747	440323	24-037	Repair Electrical - Modules/Relays	03-Jun-2020 12:49:46	MONSHP	O	DON	229.65
12-May-2020	152,345	6,747	440323	24-040	Repair Engine / Motor Systems Group	16-Jun-2020 14:05:15	MONSHP	I	DON	7,370.79
12-May-2020	152,345	6,747	440323	38-032-004	Service Battery Cables and Ends	03-Jun-2020 12:50:08	MONSHP	P	DON	17.01
12-May-2020	152,345	6,747	440323	95-010	Travel Chassis Group	03-Jun-2020 12:50:28	MONSHP	O	DON	204.13
08-Jun-2020	152,522	6,752	445145	06-001-001	Inspect Air Conditioning Assembly	12-Jun-2020 07:48:33	ME0656	N	DON	107.16
05-Mar-2021	152,522	6,755	492077	06-100-PMA	Inspect A PMI	05-Mar-2021 10:49:27	MONSHP	P	DON	71.06
05-Mar-2021	152,522	6,755	492077	06-100-DOT	Inspect DOT Federal Inspection	05-Mar-2021 10:49:32	MONSHP	P	DON	106.60
05-Oct-2021	152,522	6,755	536880	24-017-001	Repair Tire - Pneumatic	05-Oct-2021 12:59:15	MONSHP	O	DON	186.54
05-Oct-2021	152,522	6,755	536880	03-013-032	Replace ABS - ECU	14-Oct-2021 14:25:55	MONSHP	I	DON	939.60
05-Oct-2021	152,522	6,755	536880	35-013-032	Diagnose ABS - ECU	14-Oct-2021 14:25:50	MONSHP	O	DON	53.30
05-Oct-2021	152,522	6,755	536880	03-043	Replace Exhaust System	01-Nov-2021 14:23:02	MONSHP	O	DON	1,556.04
05-Oct-2021	152,522	6,755	536880	03-034-004	Replace Clearance & Marker Lamps	01-Nov-2021 14:23:07	MONSHP	I	DON	10.10
08-Dec-2021	152,522	6,755	552299	14-052-015	Install Power Inverter/Converter	09-Dec-2021 06:56:22	ME0656	N	DON	470.51
21-Dec-2021	152,522	6,755	555582	14-053-013	Install Permit Holder	26-Dec-2021 16:24:50	ME0656	N	DON	209.12
24-Feb-2022	157,785	6,755	569682	03-063-003	Replace Transceiver - GPS Tracker	24-Feb-2022 14:36:57	MONSHP	Q	DON	495.40
24-Feb-2022	157,785	6,755	569682	06-100-DOT	Inspect DOT Federal Inspection	25-Feb-2022 10:08:31	MONSHP	P	DON	106.60
24-Feb-2022	157,785	6,755	569682	06-100-PMB	Inspect B PMI	25-Feb-2022 10:08:34	MONSHP	P	DON	106.60

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: A0600 - 2004 INTERNATIONAL 4300										
24-Feb-2022 1	157,785		569682	35-042	Diagnose Cooling System	24-Feb-2022 14:37:09	MONSHP	O	DON	106.60
24-Feb-2022 1	157,785		569682	38-100-PMB	Service B PMI	25-Feb-2022 10:08:38	MONSHP	P	DON	377.74
30-Mar-2022 0	157,785		578243	34-018-001	Reseal Front Axle Hubs & Bearings	30-Mar-2022 10:24:04	MONSHP	O	DON	162.70
30-Mar-2022 0	157,785		578243	03-034-013	Replace Bracket - Tail Light	05-Apr-2022 07:43:28	MONSHP	O	DON	10.10
18-Oct-2022 1	157,785		625118	03-031-001	Replace Generator/Alternator	19-Oct-2022 14:26:29	MTIFLD	I	DON	341.48
18-Oct-2022 1	157,785		625118	35-031	Diagnose Charging System	18-Oct-2022 11:21:57	MTIFLD	O	DON	17.38
02-Feb-2023 0	162,960	6,999	649980	06-100-PMB	Inspect B PMI	13-Feb-2023 08:21:36	MTIFLD	P	DON	78.03
02-Feb-2023 0	162,960	6,999	649980	38-100-PMA	Service A PMI	13-Feb-2023 08:21:33	MTIFLD	P	DON	173.51
02-Feb-2023 0	162,960	6,999	649980	06-100-DOT	Inspect DOT Federal Inspection	13-Feb-2023 08:22:04	MTIFLD	P	DON	62.42
02-Feb-2023 0	162,960	6,999	649980	01-013-001	Adjust Front Brakes & Drums	13-Feb-2023 08:22:18	MTIFLD	P	DON	15.61
02-Feb-2023 0	162,960	6,999	649980	01-013-002	Adjust Rear Brakes & Drums	13-Feb-2023 08:22:22	MTIFLD	P	DON	15.61
02-Feb-2023 0	162,960	6,999	649980	03-054-002	Replace Alarm - Reverse Signal	13-Feb-2023 08:22:14	MTIFLD	P	DON	59.29
02-Feb-2023 0	162,960	6,999	649980	03-053-004	Replace Safety Equipment	13-Feb-2023 08:22:26	MTIFLD	Q	DON	49.60
22-Sep-2023 1	162,960	6,999	707382	06-100-009	Inspect Safety Check	22-Sep-2023 14:44:55	BTRUCK	P	DON	93.33
22-Sep-2023 1	162,960	6,999	707382	25-051	Remove General Accessories	27-Sep-2023 10:28:42	BSETUP	Z	DON	241.61
22-Sep-2023 1	162,960	6,999	707382	02-002	Clean Cab & Sheet Metal	04-Oct-2023 11:34:16	BSETUP	Z	DON	208.19