

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: N1138 - 2017 CAT 349FL										
23-May-2017	15	0	290033	14-063-003	Install Transceiver - GPS Tracker	23-May-2017 11:02:18	BHVEEQ	Q	DON	286.54
23-May-2017	15	0	290033	14-051-009	Install Fire Extinguisher	23-May-2017 11:00:05	BHVEEQ	Q	DON	53.23
18-Dec-2017	15	0	316507	14-051-009	Install Fire Extinguisher	10-Jan-2018 08:18:38	BHVEEQ	Q	DON	101.80
18-Dec-2017	15	0	316507	14-330-012	Install Counter Weight Assembly	18-Dec-2017 11:45:28	BHVEEQ	J	DON	98.33
31-Mar-2018	665	0	330391	06-100-PMB	Inspect B PMI	31-Mar-2018 11:00:00	70951M	P	DON	120.66
16-May-2018	915	0	336351	18-053-999	Test Vehicle Fluids, Lubricants, Gases, & Partic	16-May-2018 11:00:00	70951M	P	DON	27.74
18-Jul-2018	1,327	0	352397	06-100-PMB	Inspect B PMI	18-Jul-2018 11:00:00	70951M	P	DON	301.31
23-Aug-2018	1,666	0	351482	06-100-PMB	Inspect B PMI	23-Aug-2018 11:00:00	70951M	P	DON	187.51
30-Aug-2018	1,689	0	357499	03-041-007	Replace Filter - Outer	30-Aug-2018 11:00:00	70951M	P	DON	73.73
02-Oct-2018	1,832	0	357914	01-049	Adjust Electronic Management System	25-Oct-2018 00:00:00	BVLOFC	E	DON	593.23
02-Oct-2018	1,832	0	357914	01-065	Adjust Hydraulic Systems - Special Application:	25-Oct-2018 00:00:00	BVLOFC	E	DON	396.64
02-Oct-2018	1,832	0	357914	01-330-013	Adjust Operator Controls	25-Oct-2018 00:00:00	BVLOFC	W	DON	0.00
02-Oct-2018	1,832	0	357914	02-330	Clean Excavator	25-Oct-2018 00:00:00	BVLOFC	E	DON	396.64
02-Oct-2018	1,832	0	357914	03-071-005	Replace Side Door Assembly - Hinged	25-Oct-2018 00:00:00	BVLOFC	E	DON	1,870.34
02-Oct-2018	1,832	0	357914	06-100-PMC	Inspect C PMI	25-Oct-2018 00:00:00	BVLOFC	P	DON	1,411.80
02-Oct-2018	1,832	0	357914	06-330	Inspect Excavator	25-Oct-2018 00:00:00	BVLOFC	E	DON	713.95
02-Oct-2018	1,832	0	357914	24-465	Repair Camera Unit	25-Oct-2018 00:00:00	BVLOFC	E	DON	694.47
10-Apr-2019	1,833	0	380611	14-330-014	Install Counterweight Fork	10-Apr-2019 13:20:56	BVLOFC	O	DON	313.62
16-Jan-2020	1,929	0	422064	06-330	Inspect Excavator	23-Jan-2020 00:00:00	BVLOFC	E	DON	281.21
17-Apr-2020	1,914	0	436508	24-514	Repair Bucket	24-Apr-2020 10:51:32	BWELD	I	DON	24.79
18-Apr-2020	1,915	0	437490	01-049	Adjust Electronic Management System	24-Apr-2020 00:00:00	BVLOFC	E	DON	238.82
18-Apr-2020	1,915	0	437490	02-043-023	Clean Tank - DEF	24-Apr-2020 00:00:00	BVLOFC	E	DON	1,680.83
18-Apr-2020	1,915	0	437490	06-330	Inspect Excavator	24-Apr-2020 00:00:00	BVLOFC	E	DON	796.08
18-Apr-2020	1,915	0	437490	34-042	Reseal Cooling System	24-Apr-2020 00:00:00	BVLOFC	E	DON	478.83
23-Apr-2020	1,915	0	437557	02-330	Clean Excavator	30-Apr-2020 13:00:27	BWASH	N	DON	314.41
23-Apr-2020	1,915	0	437557	03-002-035	Replace Windshield Wiper & Washer	28-Apr-2020 06:21:50	BHVEEQ	I	DON	60.32
23-Apr-2020	1,915	0	437557	03-051-009	Replace Fire Extinguisher	28-Apr-2020 12:00:41	BHVEEQ	I	DON	88.08
23-Apr-2020	1,915	0	437557	03-065-004	Replace Cylinder	28-Apr-2020 10:25:18	BHVEEQ	I	DON	138.91
23-Apr-2020	1,915	0	437557	03-111-011	Replace Track Pad	05-May-2020 13:50:14	BHVEEQ	I	DON	24.52

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: N1138 - 2017 CAT 349FL										
23-Apr-2020 1	1,915	0	437557	03-330-004	Replace Boom and Stick Assembly	15-Jun-2020 10:58:55	BHVEEQ	Q	DON	21,472.95
23-Apr-2020 1	1,915	0	437557	06-100-PMC	Inspect C PMI	29-Apr-2020 14:26:54	BHVEEQ	P	DON	128.56
23-Apr-2020 1	1,915	0	437557	12-330	Refinish Excavator	08-May-2020 07:45:27	BBODY	K	DON	674.61
23-Apr-2020 1	1,915	0	437557	14-052-005	Install Transmitter - CB	29-Apr-2020 05:46:51	BHVEEQ	Q	DON	221.84
23-Apr-2020 1	1,915	0	437557	14-063	Install Satellite Communications System	15-Jun-2020 10:54:05	BHVEEQ	Q	DON	15,263.21
23-Apr-2020 1	1,915	0	437557	14-330-012	Install Counter Weight Assembly	28-Apr-2020 06:14:57	BHVEEQ	Q	DON	59.49
23-Apr-2020 1	1,915	0	437557	14-514	Install Bucket	05-May-2020 17:00:12	BHVEEQ	Q	DON	141.42
23-Apr-2020 1	1,915	0	437557	15-330	Paint Prep Excavator	08-May-2020 07:45:19	BBODY	K	DON	598.32
23-Apr-2020 1	1,915	0	437557	24-065-004	Repair Cylinder	15-Jun-2020 10:59:35	BHVEEQ	I	DON	4,050.84
23-Apr-2020 1	1,915	0	437557	25-330-015	Remove Quik-Attach Assembly	27-Apr-2020 13:16:35	BHVEEQ	Q	DON	27.74
23-Apr-2020 1	1,915	0	437557	38-100-PMC	Service C PMI	05-May-2020 14:47:08	BHVEEQ	P	DON	187.52
29-Jun-2020 1:	1,955	0	448044	14-052-005	Install Transmitter - CB	29-Jun-2020 13:00:42	BHVEEQ	O	DON	108.56
01-Jul-2020 19	1,965	0	448599	14-052-003	Install Radio Equipment	01-Jul-2020 20:28:02	ELEC01	Q	DON	815.09
15-Jul-2020 09	2,051	0	450670	03-002-024	Replace Glass / Windshield	20-Jul-2020 06:11:08	BHVEEQ	E	DON	303.52
24-Jul-2020 13	2,117	0	452478	03-065-007	Replace Hoses & Fittings	24-Jul-2020 13:19:20	BHVEEQ	B	DON	694.47
18-Aug-2020 1	2,256	0	456749	06-100-PMB	Inspect B PMI	18-Aug-2020 12:35:00	BHVEEQ	P	DON	0.00
18-Aug-2020 1	2,256	0	456749	38-100-PMA	Service A PMI	18-Aug-2020 12:35:24	BHVEEQ	P	DON	1,351.00
21-Sep-2020 0:	2,391	0	462386	03-514-002	Replace Shanks or Teeth	21-Sep-2020 06:53:54	BHVEEQ	E	DON	1,485.83
21-Oct-2020 1:	2,538	0	467961	02-330	Clean Excavator	21-Oct-2020 12:32:39	BHVEEQ	N	DON	570.54
21-Oct-2020 1:	2,538	0	467961	24-065-021	Repair Counter Balance Valve	21-Oct-2020 12:33:42	BHVEEQ	W	DON	110.23
05-Jan-2021 1:	2,543	0	480192	06-100-PMB	Inspect B PMI	07-Jan-2021 11:12:38	BHVEEQ	P	DON	70.06
05-Jan-2021 1:	2,543	0	480192	38-100-PMB	Service B PMI	07-Jan-2021 11:12:56	BHVEEQ	P	DON	1,257.26
05-Jan-2021 1:	2,543	0	480192	03-051-009	Replace Fire Extinguisher	07-Jan-2021 10:48:40	BHVEEQ	Q	DON	50.20
05-Jan-2021 1:	2,543	0	480192	03-042-012	Replace Clamps and Hoses	07-Jan-2021 09:36:14	BHVEEQ	I	DON	226.81
05-Jan-2021 1:	2,543	0	480192	03-019-005	Replace Solenoid & Wiring	07-Jan-2021 09:35:55	BHVEEQ	I	DON	225.48
05-Jan-2021 1:	2,543	0	480192	03-514-002	Replace Shanks or Teeth	08-Jan-2021 10:12:02	BHVEEQ	I	DON	1,299.56
08-Apr-2021 1	0	0	499321	03-002-024	Replace Glass / Windshield	13-Apr-2021 07:10:36	BHVEEQ	O	DON	167.06
08-Apr-2021 1	0	0	499321	06-002-024	Inspect Glass / Windshield		BHVEEQ	O	CAN	0.00
21-May-2021 1	2,808	0	508273	06-100-PMA	Inspect A PMI	21-May-2021 11:37:11	SCHED	P	DON	0.00

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: N1138 - 2017 CAT 349FL										
21-May-2021	2,808	0	508273	06-100-PMB	Inspect B PMI	21-May-2021 11:37:12	SCHED	P	DON	0.00
21-May-2021	2,808	0	508273	38-100-PMA	Service A PMI	21-May-2021 11:37:54	BHVEYEQ	P	DON	2,297.74
24-May-2021	2,808	0	508501	03-514-002	Replace Shanks or Teeth	26-May-2021 05:53:55	BHVEYEQ	E	DON	1,513.08
25-Jun-2021	2,894	0	514967	24-065-001	Repair Hydraulic Systems	25-Jun-2021 05:51:08	BHVEYEQ	B	DON	1,865.15
12-Jul-2021	2,903	0	517794	03-514-002	Replace Shanks or Teeth	12-Jul-2021 10:47:33	BHVEYEQ	E	DON	1,115.17
02-Aug-2021	2,961	0	522376	14-360-001	Install Bucket and Attachments	02-Aug-2021 16:33:38	BHVEYEQ	O	DON	3,172.94
17-Aug-2021	3,048	0	525501	03-330-001	Replace Bucket and Attachments	23-Aug-2021 08:27:38	BHVEYEQ	E	DON	850.01
20-Sep-2021	3,284	0	532728	03-063-001	Replace Antenna - RF	20-Sep-2021 14:31:07	BHVEYEQ	W	DON	0.00
20-Sep-2021	3,284	0	532728	06-100-PMA	Inspect A PMI	20-Sep-2021 14:33:06	SCHED	P	DON	0.00
20-Sep-2021	3,284	0	532728	38-100-PMA	Service A PMI	20-Sep-2021 14:29:58	BHVEYEQ	P	DON	1,594.28
07-Oct-2021	3,395	0	537407	03-002-024	Replace Glass / Windshield	15-Oct-2021 12:39:44	BHVEYEQ	E	DON	168.74
18-Oct-2021	3,449	0	540036	06-100-PMA	Inspect A PMI	20-Oct-2021 15:03:17	SCHED	P	DON	0.00
18-Oct-2021	3,449	0	540036	38-100-PMA	Service A PMI	20-Oct-2021 15:03:23	TRK001	N	DON	424.43
11-Nov-2021	3,496	0	545923	03-002-035	Replace Windshield Wiper & Washer	11-Nov-2021 13:28:06	BHVEYEQ	O	DON	41.97
16-Nov-2021	3,496	0	546975	03-514-002	Replace Shanks or Teeth	16-Nov-2021 13:05:03	TRK001	E	DON	2,156.80
09-Dec-2021	3,685	0	552390	02-360	Clean Loader / Skid-Steer	27-Dec-2021 17:00:24	BWASH	N	DON	837.13
09-Dec-2021	3,685	0	552390	03-002-024	Replace Glass / Windshield	13-Dec-2021 10:21:34	BHVEYEQ	E	DON	335.80
09-Dec-2021	3,685	0	552390	03-002-035	Replace Windshield Wiper & Washer	13-Dec-2021 10:57:23	BHVEYEQ	N	DON	79.75
09-Dec-2021	3,685	0	552390	03-041	Replace Air Intake System	09-Dec-2021 16:30:29	BHVEYEQ	I	DON	88.34
09-Dec-2021	3,685	0	552390	03-042-012	Replace Clamps and Hoses	16-Dec-2021 13:54:23	BHVEYEQ	I	DON	411.19
09-Dec-2021	3,685	0	552390	03-043-025	Replace Filter - DEF	03-Jan-2022 07:45:46	BHVEYEQ	I	DON	104.95
09-Dec-2021	3,685	0	552390	03-051-009	Replace Fire Extinguisher	09-Dec-2021 16:15:09	BHVEYEQ	Q	DON	52.40
09-Dec-2021	3,685	0	552390	06-100-PMB	Inspect B PMI	03-Jan-2022 10:00:32	BHVEYEQ	P	DON	55.05
09-Dec-2021	3,685	0	552390	24-042-012	Repair Clamps and Hoses		BHVEYEQ	Q	CAN	0.00
09-Dec-2021	3,685	0	552390	38-100-PMB	Service B PMI	03-Jan-2022 10:09:01	BHVEYEQ	N	DON	808.93
21-Feb-2022	3,685	0	568553	03-063-003	Replace Transceiver - GPS Tracker	21-Feb-2022 09:57:47	ELEC02	Q	DON	435.74
13-May-2022	3,685	0	588586	03-065-001	Replace Hydraulic Systems	25-May-2022 13:53:50	TRK001	O	DON	44.89
13-May-2022	3,685	0	588586	03-065-032	Replace Seal / O-Ring General	25-May-2022 13:54:33	TRK001	O	DON	41.44
07-Jun-2022	3,769	0	594161	06-100-007	Inspect In-Service Inspection	07-Jun-2022 14:44:28	TRK001	I	DON	41.44

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: N1138 - 2017 CAT 349FL										
07-Jun-2022 01	3,769	0	594161	24-042	Repair Cooling System	07-Jun-2022 14:46:02	TRK001	I	DON	51.80
11-Jul-2022 06	3,887	0	601435	24-065-004	Repair Cylinder	08-Aug-2022 16:08:36	BHVYEQ	B	DON	6,409.12
11-Jul-2022 06	3,887	0	601651	03-065-004	Replace Cylinder	12-Jul-2022 12:32:37	TRK001	O	DON	682.01
13-Jul-2022 00	4,001	0	602414	38-100-PMA	Service A PMI	14-Jul-2022 07:32:20	TRK001	N	DON	392.44
13-Jul-2022 00	4,001	0	602414	06-100-PMA	Inspect A PMI	14-Jul-2022 07:32:15	TRK001	P	DON	0.00
15-Jul-2022 00		0	602810	03-514-002	Replace Shanks or Teeth	10-Nov-2022 09:57:13	TRK001	E	DON	756.95
26-Sep-2022 11	4,340	0	619219	06-330	Inspect Excavator	03-Oct-2022 07:50:12	BHVYEQ	P	DON	178.88
26-Sep-2022 11	4,340	0	619219	38-100-PMB	Service B PMI	27-Sep-2022 08:52:26	BHVYEQ	P	DON	628.89
26-Sep-2022 11	4,340	0	619219	02-002-044	Clean Cab - Complete	06-Oct-2022 08:15:45	BHVYEQ	N	DON	69.83
26-Sep-2022 11	4,340	0	619219	02-330	Clean Excavator	01-Oct-2022 09:00:07	BWASH	N	DON	950.64
06-Mar-2023 0	4,488	0	657024	02-043-009	Clean Diesel Particulate Filter - DPF	20-Mar-2023 08:45:59	BHVYEQ	N	DON	1,186.78
06-Mar-2023 0	4,488	0	657024	02-330	Clean Excavator	28-Mar-2023 16:00:26	BWASH	N	DON	311.48
06-Mar-2023 0	4,488	0	657024	03-002-024	Replace Glass / Windshield	30-Mar-2023 15:31:05	BHVYEQ	I	DON	1,192.87
06-Mar-2023 0	4,488	0	657024	03-033-003	Replace Spark Plugs	06-Mar-2023 11:42:38	BHVYEQ	N	DON	32.34
06-Mar-2023 0	4,488	0	657024	03-043-022	Replace Injector - DEF	06-Mar-2023 13:43:43	BHVYEQ	N	DON	473.54
06-Mar-2023 0	4,488	0	657024	03-051-009	Replace Fire Extinguisher	06-Mar-2023 13:45:54	BHVYEQ	Q	DON	40.96
06-Mar-2023 0	4,488	0	657024	03-065-007	Replace Hoses & Fittings	30-Mar-2023 15:29:29	BHVYEQ	I	DON	227.70
06-Mar-2023 0	4,488	0	657024	06-100-PMA	Inspect A PMI	30-Mar-2023 15:29:24	BHVYEQ	P	DON	44.44
06-Mar-2023 0	4,488	0	657024	23-513-004	Burn / Cut Specialty Attachment	30-Mar-2023 15:29:45	BWELD	N	DON	1,230.21
06-Mar-2023 0	4,488	0	657024	26-514-004	Weld Edges	23-Mar-2023 14:04:53	BHVYEQ	N	DON	1,661.22
06-Mar-2023 0	4,488	0	657024	38-100-PMA	Service A PMI	30-Mar-2023 15:31:10	BHVYEQ	P	DON	514.58
06-Mar-2023 0	4,488	0	657024	B3-049-002	Program ECM Module	03-Apr-2023 06:16:48	BHVYEQ	W	DON	0.00
13-Apr-2023 1	4,534	0	666914	03-514-002	Replace Shanks or Teeth	13-Apr-2023 13:16:52	BHVYEQ	E	DON	544.36
16-May-2023 1	4,642	0	674800	24-065-004	Repair Cylinder	16-May-2023 09:54:07	BHVYEQ	B	DON	2,879.68
19-May-2023 1	4,654	0	675733	03-065-007	Replace Hoses & Fittings	19-May-2023 12:50:22	BHVYEQ	B	DON	1,166.71
25-May-2023 1	4,687	0	676888	03-514-002	Replace Shanks or Teeth	25-May-2023 08:55:11	BHVYEQ	E	DON	393.74
01-Jun-2023 1	4,731	0	678411	34-330	Reseal Excavator	01-Jun-2023 16:23:46	BHVYEQ	O	DON	527.50
26-Jun-2023 01	4,912	0	684095	38-100-PMA	Service A PMI	26-Jun-2023 09:58:50	BHVYEQ	P	DON	1,778.10
10-Jul-2023 10	4,989	0	686811	03-514-002	Replace Shanks or Teeth	10-Jul-2023 10:38:35	BHVYEQ	E	DON	852.46

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: N1138 - 2017 CAT 349FL										
10-Jul-2023 10	4,989	0	686811	01-514	Adjust Bucket	10-Jul-2023 10:54:28	BHVYEQ	I	DON	89.17
20-Jul-2023 07	5,065	0	689656	03-001-014	Replace Switch - A/C Thermostat	04-Dec-2023 06:34:32	TRK004	O	DON	12.40
20-Jul-2023 07	5,065	0	689656	03-514-002	Replace Shanks or Teeth	04-Dec-2023 06:41:20	TRK004	E	DON	2,035.95
20-Jul-2023 07	5,065	0	689656	38-100-PMA	Service A PMI	04-Dec-2023 06:34:34	TRK004	P	DON	445.71
18-Oct-2023 0:	5,567	0	713789	03-042-012	Replace Clamps and Hoses	27-Oct-2023 06:19:30	BHVYEQ	O	DON	95.13
22-Mar-2024 0		0	747447	OS-330	Out-Service Excavator	22-Mar-2024 16:41:26	BHVYEQ	Z	DON	228.08
22-Mar-2024 0		0	747447	26-513-002	Weld Quick Attachment	22-Mar-2024 16:00:39	BHVYEQ	N	DON	249.93
22-Mar-2024 0		0	747447	02-330	Clean Excavator	27-Mar-2024 10:49:57	BWASH	Z	DON	970.00

Unit No: N1138

Count: 124

111,173.46