

Unit Job History

Michels Corporation
Report Printed: 08-Dec-2021 12:57:51 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: N0728 - 1999 LIEBHERR R984HDLSL										
08-Oct-2012 0*	0	0	97860	24-002-016	Repair Compartment Lid - Tail & Lift Gate - Re	17-Oct-2012 09:00:00	BWELD	E	DON	182.13
08-Oct-2012 0*	0	0	97860	12-002-004	Refinish Hood	18-Oct-2012 11:39:51	BBODY	C	DON	517.42
08-Oct-2012 0*	0	0	97860	15-002-004	Paint Prep Hood	19-Oct-2012 10:58:52	BBODY	C	DON	317.58
25-Oct-2012 1*	0	0	99474	24-002-004	Repair Hood	30-Oct-2012 11:29:55	BBODY	I	DON	42.89
25-Oct-2012 1*	0	0	99474	12-002	Refinish Cab & Sheet Metal	30-Oct-2012 15:26:24	BBODY	K	DON	297.28
25-Oct-2012 1*	0	0	99474	15-002	Paint Prep Cab & Sheet Metal	31-Oct-2012 07:36:14	BSAND	K	DON	121.24
11-Feb-2013 1*	16,109	0	119697	24-330-004	Repair Boom and Stick Assembly	11-Feb-2013 10:47:52	BVLOFC	F	DON	17,384.30
21-Mar-2013 1	16,109	0	123191	24-330	Repair Excavator	21-Mar-2013 13:38:46	BVLOFC	F	DON	0.00
21-Mar-2013 1	16,109	0	123191	26-330	Weld Excavator	21-Mar-2013 13:38:46	BVLOFC	F	DON	8,874.41
24-Jul-2013 16	0	0	125121	06-001-014	Inspect Switch - A/C Thermostat	27-Aug-2015 10:36:48	NBYARD	O	DON	172.45
24-Jul-2013 16	0	0	125121	06-001-010	Inspect Compressor Assembly - Air Cond	27-Aug-2015 10:36:48	NBYARD	O	DON	2,127.57
24-Jul-2013 16	0	0	125121	06-019-002	Inspect Grease Pump - Automatic Lubricator	27-Oct-2014 10:45:20	NBYARD	O	DON	4,574.98
24-Jul-2013 16	0	0	125121	06-044-024	Inspect Fuel / Water Separator	27-Aug-2015 10:36:48	NBYARD	O	DON	139.09
24-Jul-2013 16	0	0	125121	03-002-020	Replace Side Door Mechanism	27-Aug-2015 10:36:48	NBYARD	I	DON	275.94
24-Jul-2013 16	0	0	125121	06-045-010	Inspect Oil Filler & Level Indicator	27-Aug-2015 10:36:48	NBYARD	O	DON	617.71
24-Jul-2013 16	0	0	125121	14-052-003	Install Radio Equipment	27-Aug-2015 10:36:48	BTRUCK	I	DON	382.95
24-Jul-2013 16	0	0	125121	38-040	Service Engine / Motor Systems Group	27-Aug-2015 10:36:48	NBYARD	P	DON	568.87
24-Jul-2013 16	0	0	125121	06-065-004	Inspect Cylinder	27-Oct-2014 10:45:31	NBYARD	O	DON	46,437.68
12-May-2015 1	16,246	0	200820	38-100-PMA	Service A PMI	12-May-2015 14:07:27	BHVEEQ	J	DON	5,880.62
26-May-2015 1	16,246	0	202108	03-065-005	Replace Drive - Motor / Pump	26-May-2015 13:51:11	BHVEEQ	F	DON	24,799.02
27-Aug-2015 1	16,246	0	212727	06-707	Inspect Swivel	01-Oct-2015 13:14:18	NBYARD	O	DON	2,855.64
20-Oct-2017 0*	16,246	0	309577	03-032-001	Replace Battery	20-Oct-2017 13:23:34	BCRANE	B	DON	131.37
02-Dec-2017 0	16,579	0	314487	03-094-001	Replace Lines - Crossover	28-Dec-2017 00:00:00	BCRANE	B	DON	2,200.29
02-Dec-2017 0	16,579	0	314487	04-330	Rig / Unrig Excavator	15-Dec-2017 11:36:15	BCRANE	E	DON	3,252.36
02-Dec-2017 0	16,579	0	314487	24-049	Repair Electronic Management System	28-Dec-2017 00:00:00	BVLOFC	I	DON	13,727.81
02-Dec-2017 0	16,579	0	314487	95-MSC	Travel Miscellaneous	28-Dec-2017 00:00:00	BCRANE	J	DON	1,493.84
02-Dec-2017 0	16,579	0	314487	06-100-PMA	Inspect A PMI	20-Dec-2017 09:00:00	BCRANE	P	DON	662.00
02-Dec-2017 0	16,579	0	314487	24-037-021	Repair Circuite Breaker/Fuse - Multiple Use	28-Dec-2017 00:00:00	BCRANE	B	DON	934.19
23-Mar-2018 1	16,579	0	328569	03-063-003	Replace Transceiver - GPS Tracker	09-May-2018 09:30:00	BHVEEQ	I	DON	264.04

Unit Job History

Michels Corporation
Report Printed: 08-Dec-2021 12:57:51 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: N0728 - 1999 LIEBHERR R984HDSL										
23-Mar-2018 1	16,579	0	328569	03-065-007	Replace Hoses & Fittings	11-Jun-2018 10:32:48	BCRANE	J	DON	17,034.36
23-Mar-2018 1	16,579	0	328569	35-003-001	Diagnose Gauges & Warning Devices	11-Jun-2018 10:32:32	BCRANE	J	DON	11,455.51
23-Mar-2018 1	16,579	0	328569	24-514	Repair Bucket	14-May-2018 13:21:25	BWELD	N	DON	6,697.72
23-Mar-2018 1	16,579	0	328569	06-100-PMB	Inspect B PMI	11-Jun-2018 10:32:40	BHVEYEQ	P	DON	2,836.49
23-Mar-2018 1	16,579	0	328569	12-514	Refinish Bucket	21-May-2018 10:43:34	BBODY	N	DON	157.86
23-Mar-2018 1	16,579	0	328569	24-330-015	Repair Quik-Attach Assembly	11-Jun-2018 10:32:19	BCRANE	B	DON	11,777.81
06-Aug-2018 1	16,579	0	347018	03-065-007	Replace Hoses & Fittings	09-Aug-2018 18:15:00	BVLOFC	B	DON	1,961.90
06-Aug-2018 1	16,579	0	347018	24-019-002	Repair Grease Pump - Automatic Lubricator	08-Aug-2018 09:00:00	BCRANE	B	DON	459.40
06-Aug-2018 1	16,579	0	347018	24-330-015	Repair Quik-Attach Assembly	22-Oct-2018 13:07:18	BCRANE	B	DON	469.89
15-Apr-2019 0	16,579	0	381147	02-330	Clean Excavator	10-Jul-2019 16:53:23	BCRANE	I	DON	770.20
15-Apr-2019 0	16,579	0	381147	03-002-024	Replace Glass / Windshield	10-Jul-2019 16:53:28	BCRANE	I	DON	171.97
15-Apr-2019 0	16,579	0	381147	03-016-010	Replace Air Spring	10-Jul-2019 16:51:10	BCRANE	B	DON	578.18
15-Apr-2019 0	16,579	0	381147	03-065-003	Replace Cooler - Oil (Heat Exchanger)	10-Jul-2019 16:52:31	BCRANE	I	DON	426.07
15-Apr-2019 0	16,579	0	381147	03-514-002	Replace Shanks or Teeth	10-Jul-2019 16:53:13	BCRANE	E	DON	3,099.56
15-Apr-2019 0	16,579	0	381147	03-014-004	Replace Cab & Body Mountings	28-May-2019 18:30:00	BCRANE	I	DON	1,015.23
15-Apr-2019 0	16,579	0	381147	38-330	Service Excavator	03-Jun-2019 12:30:09	BCRANE	P	DON	3,357.10
15-Apr-2019 0	16,579	0	381147	35-706	Diagnose Power Unit	10-Jul-2019 16:52:49	BCRANE	O	DON	11,349.99
15-Apr-2019 0	16,579	0	381147	95-330	Travel Excavator	10-Jul-2019 16:51:44	BVLOFC	N	DON	323.53
15-Apr-2019 0	16,579	0	381147	14-063-003	Install Transceiver - GPS Tracker	10-Jul-2019 16:53:41	BCRANE	M	DON	1,706.82
15-Apr-2019 0	16,579	0	381147	14-063	Install Satellite Communications System	10-Jul-2019 16:53:07	BHVEYEQ	Q	DON	38,472.66
15-Apr-2019 0	16,579	0	381147	06-014-001	Inspect Frame Assembly	10-Jul-2019 16:52:26	BCRANE	I	DON	3,087.42
15-Apr-2019 0	16,579	0	381147	11-330-001	Rebuild Bucket and Attachments	10-Jul-2019 16:51:33	BVLOFC	N	DON	1,101.26
15-Apr-2019 0	16,579	0	381147	35-097-004	Diagnose Diaphragm Pump	10-Jul-2019 16:51:25	BCRANE	B	DON	24,530.29
15-Apr-2019 0	16,579	0	381147	23-513-004	Burn / Cut Specialty Attachment	06-May-2019 17:00:02	BWELD	T	DON	1,044.83
15-Apr-2019 0	16,579	0	381147	14-065-007	Install Hoses & Fittings	26-Jun-2019 17:00:00	BCRANE	B	DON	5,330.88
09-Jul-2019 16	16,579	0	393734	03-065-007	Replace Hoses & Fittings	27-Sep-2019 00:00:00	BCRANE	I	DON	18,879.94
09-Jul-2019 16	16,579	0	393734	03-032-002	Replace Starter	27-Sep-2019 00:00:00	BCRANE	I	DON	1,024.96
09-Jul-2019 16	16,579	0	393734	06-100-PMB	Inspect B PMI	27-Sep-2019 00:00:00	BCRANE	P	DON	0.00

Unit Job History

Michels Corporation
Report Printed: 08-Dec-2021 12:57:51 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: N0728 - 1999 LIEBHERR R984HDSL										
09-Jul-2019 16	16,579	0	393734	14-065-007	Install Hoses & Fittings	27-Sep-2019 00:00:00	BCRANE	Q	DON	385.45
09-Jul-2019 16	16,579	0	393734	03-031-001	Replace Generator/Alternator	27-Sep-2019 00:00:00	BCRANE	I	DON	0.00
09-Jul-2019 16	16,579	0	393734	24-019-006	Repair Block Assembly - Grease Distribution	27-Sep-2019 00:00:00	BCRANE	I	DON	178.09
09-Jul-2019 16	16,579	0	393734	24-P01-001	Repair Oil	27-Sep-2019 00:00:00	BCRANE	O	DON	9,481.47
09-Jul-2019 16	16,579	0	393734	34-040	Reseal Engine / Motor Systems Group	27-Sep-2019 00:00:00	BCRANE	I	DON	3,642.82
09-Jul-2019 16	16,579	0	393734	35-041-010	Diagnose Air Filter Restriction Gauge	27-Sep-2019 00:00:00	BCRANE	I	DON	452.33
09-Jul-2019 16	16,579	0	393734	24-065-003	Repair Cooler - Oil (Heat Exchanger)	27-Sep-2019 00:00:00	BCRANE	O	DON	47,190.17
09-Jul-2019 16	16,579	0	393734	38-100-PMB	Service B PMI	27-Sep-2019 00:00:00	BCRANE	P	DON	10,997.65
20-Sep-2019 0	16,579	0	403808	99-513-004	Machine Specialty Attachment	23-Sep-2019 07:11:21	BWELD	N	DON	307.93
24-Oct-2019 0		0	409712	03-019-006	Replace Block Assembly - Grease Distribution	10-Dec-2019 12:47:06	FKVSHHP	P	DON	729.08
24-Oct-2019 0		0	409712	14-065	Install Hydraulic Systems - Special Applications	10-Dec-2019 12:47:09	FKVSHHP	P	DON	3,335.70
30-Dec-2019 1		0	418671	07-330	Lubricate Excavator	22-Jan-2020 07:27:17	FKVSHHP	O	DON	653.24
06-Mar-2020 0		0	430007	24-042	Repair Cooling System	09-Apr-2020 11:49:50	FKVSHHP	O	DON	274.99
06-Mar-2020 0		0	430007	03-042-002	Replace Radiator	06-Jul-2020 09:12:23	FKVSHHP	O	WR	0.00
24-Apr-2020 0		0	437956	24-002-024	Repair Glass / Windshield	03-Aug-2020 14:34:38	FKVSHHP	O	DON	70.40
24-Apr-2020 0		0	437956	03-111-011	Replace Track Pad	06-Jul-2020 09:11:56	FKVSHHP	O	DON	265.60
24-Apr-2020 0		0	437956	14-330-004	Install Boom and Stick Assembly	10-Jul-2020 17:00:00	FKVSHHP	O	DON	462.72
24-Apr-2020 0		0	437956	09-264-001	Align Grapple Assembly	03-Aug-2020 14:34:32	FKVSHHP	O	DON	276.73
24-Apr-2020 0		0	437956	03-513-002	Replace Quick Attachment	29-May-2020 13:53:21	FKVSHHP	O	DON	69.74
24-Apr-2020 0		0	437956	04-264-001	Rig / Unrig Grapple Assembly	09-Jul-2020 17:00:00	FKVSHHP	O	DON	7,984.60
24-Apr-2020 0		0	437956	24-065-007	Repair Hoses & Fittings	06-May-2020 05:43:27	FKVSHHP	O	DON	2,945.88
24-Apr-2020 0		0	437956	24-002-065	Repair Hood Latch	06-Jul-2020 09:11:52	FKVSHHP	O	DON	156.92
24-Apr-2020 0		0	437956	34-065-001	Reseal Hydraulic Systems	22-Sep-2020 14:07:15	FKVSHHP	O	DON	17,764.53
24-Apr-2020 0		0	437956	35-019-002	Diagnose Grease Pump - Automatic Lubricator	16-Jun-2020 12:00:00	FKVSHHP	O	DON	814.86
24-Apr-2020 0		0	437956	35-330-001	Diagnose Bucket and Attachments	06-Jul-2020 09:17:54	FKVSHHP	O	DON	1,005.53
24-Apr-2020 0		0	437956	35-042-002	Diagnose Radiator	19-May-2020 16:00:00	FKVSHHP	O	DON	12,375.04
24-Apr-2020 0		0	437956	35-330-004	Diagnose Boom and Stick Assembly	17-Nov-2020 06:50:57	FKVSHHP	O	DON	397.80
29-Oct-2020 0		0	469362	03-065-007	Replace Hoses & Fittings	17-Nov-2020 06:50:34	FKVSHHP	O	DON	1,251.76
29-Oct-2020 0		0	469362	03-042-010	Replace Coolant Pre-Heater - Self-Contained, L		FKVSHHP	O	DON	192.64

Unit Job History

Michels Corporation
Report Printed: 08-Dec-2021 12:57:51 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: N0728 - 1999 LIEBHERR R984HDSL										
29-Oct-2020 0			469362	35-065-027	Diagnose Relief Valve	25-Nov-2020 13:02:13	FKVSHP	O	DON	207.55
26-Feb-2021 0			490745	24-042-012	Repair Clamps and Hoses	19-Apr-2021 06:56:48	FKVSHP	O	DON	859.45
26-Feb-2021 0			490745	03-042-002	Replace Radiator	19-Apr-2021 06:56:54	FKVSHP	O	DON	0.00
26-Apr-2021 1			503696	02-330	Clean Excavator	18-May-2021 10:26:25	FKVSHP	O	DON	296.08
26-Apr-2021 1			503696	24-065-008	Repair Line / Tubing Assembly	18-May-2021 10:26:28	FKVSHP	O	DON	312.02
04-Jun-2021 1			511105	24-042	Repair Cooling System	18-Jun-2021 09:53:55	FKVSHP	O	DON	74.90
04-Jun-2021 1			511105	24-065	Repair Hydraulic Systems - Special Application	18-Jun-2021 09:53:58	FKVSHP	O	DON	610.01
30-Jun-2021 0			516261	03-032-002	Replace Starter	06-Jul-2021 16:11:04	FKVSHP	O	DON	886.96
30-Jun-2021 0			516261	24-002-065	Repair Hood Latch		FKVFLD	O	WR	0.00
30-Jun-2021 0			516261	24-330-002	Repair Undercarriage (Tracks&Rollers)	29-Nov-2021 16:22:19	FKVSHP	B	DON	10,242.68
30-Jun-2021 0			516261	24-065-001	Repair Hydraulic Systems	29-Nov-2021 16:21:59	FKVSHP	O	DON	1,535.07
30-Jun-2021 0			516261	24-330	Repair Excavator	29-Nov-2021 16:23:47	FKVSHP	O	DON	4,576.87
29-Nov-2021 1			549609	24-002-065	Repair Hood Latch		FKVFLD	O	WIP	0.00

Unit No: N0728

Count: 100

452,011.33