

Unit Job History

Michels Corporation
Report Printed: 20-Sep-2022 12:10:15 By User: RHEINING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B3510 - 2018 F150 CREWCAB										
26-Sep-2018 0	76		353777	03-017-001	Replace Tire - Pneumatic	01-Oct-2018 12:42:35	BTRUCK	I	DON	1,063.81
26-Sep-2018 0	76		353777	06-100-007	Inspect In-Service Inspection	01-Oct-2018 11:56:33	BTRUCK	P	DON	19.52
26-Sep-2018 0	76		353777	14-051-005	Install Recorder - Fuel & Mileage	01-Oct-2018 11:20:58	BTRUCK	C	DON	174.27
26-Sep-2018 0	76		353777	14-002-059	Install Protector - Tail Gate	28-Sep-2018 08:45:38	BSETUP	C	DON	72.05
26-Sep-2018 0	76		353777	14-034-006	Install Warning Lamps - Special Application	28-Sep-2018 10:31:58	BSETUP	C	DON	469.53
26-Sep-2018 0	76		353777	14-053-005	Install Markings - Vehicle - Decals	26-Sep-2018 13:46:39	BSETUP	C	DON	135.31
26-Sep-2018 0	76		353777	14-053-014	Install Floor Mats	28-Sep-2018 11:40:15	BSETUP	C	DON	110.67
26-Sep-2018 0	76		353777	14-063-003	Install Transceiver - GPS Tracker	28-Sep-2018 11:40:03	BSETUP	Q	DON	756.65
26-Sep-2018 0	76		353777	14-052-015	Install Power Inverter/Converter	28-Sep-2018 11:40:29	BSETUP	C	DON	257.85
26-Sep-2018 0	76		353777	14-002-063	Install Computer Stand / Dock	28-Sep-2018 12:07:08	BSETUP	C	DON	364.76
26-Sep-2018 0	76		353777	14-052-003	Install Radio Equipment	28-Sep-2018 09:39:13	BSETUP	C	DON	988.27
26-Sep-2018 0	76		353777	14-052-011	Install Auxiliary Power	27-Sep-2018 12:18:56	BSETUP	C	DON	161.12
26-Sep-2018 0	76		353777	14-052-014	Install Cellular Telephone Accessories	28-Sep-2018 10:49:14	BSETUP	C	DON	54.91
26-Sep-2018 0	76		353777	14-078-009	Install Mud Flaps and Hanger Brackets	28-Sep-2018 09:59:36	BSETUP	C	DON	93.22
26-Sep-2018 0	76		353777	14-078-014	Install Tarps/Tarpaulin/Tombeau Cover	28-Sep-2018 08:19:37	BSETUP	C	DON	542.55
26-Sep-2018 0	76		353777	14-071-011	Install Scuff Liner / Bed Mat	28-Sep-2018 08:46:07	BSETUP	C	DON	101.57
26-Sep-2018 0	76		353777	14-510-002	Install Tool Box	28-Sep-2018 07:58:11	BSETUP	C	DON	433.87
26-Sep-2018 0	76		353777	14-517	Install Safety Equipment	28-Sep-2018 08:45:50	BSETUP	C	DON	134.97
15-Oct-2018 0*	2,491		356503	03-017-001	Replace Tire - Pneumatic	19-Oct-2018 10:49:16	BTRUCK	O	DON	949.48
15-Oct-2018 0*	2,491		356503	14-013-012	Install Electric Brakes	20-Oct-2018 08:18:52	BTRUCK	O	DON	270.39
06-Nov-2018 1	4,884		359673	38-045	Service Power Plant	07-Nov-2018 08:11:13	BTRUCK	P	DON	73.91
06-Nov-2018 1	4,884		359673	06-100-PMB	Inspect B PMI	07-Nov-2018 07:45:31	BTRUCK	P	DON	37.30
06-Nov-2018 1	4,884		359673	14-052-016	Install Remote Starting System	06-Nov-2018 15:16:21	BTRUCK	O	DON	406.88
12-Apr-2019 1	14,289		380947	06-100-PMB	Inspect B PMI	15-Apr-2019 13:17:01	BTRUCK	P	DON	27.40
12-Apr-2019 1	14,289		380947	24-016-005	Repair Chassis Spring - Rear		BTRUCK	O	CAN	0.00
12-Apr-2019 1	14,289		380947	38-045	Service Power Plant	15-Apr-2019 14:07:04	BTRUCK	P	DON	58.35
12-Apr-2019 1	14,289		380947	01-042-009	Adjust Coolant Pre-Heater- Electrical	15-Apr-2019 15:02:00	BTRUCK	G	DON	30.14
18-May-2019 1	22,817		386960	03-045-011	Replace Filter Assembly - Oil	18-May-2019 14:40:55	BVLOFC	P	DON	211.05
06-Nov-2019 1	47,280		411372	03-002-024	Replace Glass / Windshield	11-Nov-2019 06:29:29	BVLOFC	O	DON	504.67

Unit Job History

Michels Corporation
Report Printed: 20-Sep-2022 12:10:15 By User: RHEINING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B3510 - 2018 F150 CREWCAB										
14-Nov-2019	49,418		412731	38-100-PMA	Service A PMI	20-Nov-2019 09:37:28	BVLOFC	P	DON	119.18
14-Nov-2019	49,418		412731	24-033-002	Repair Distributor / Coil Pack	20-Nov-2019 09:37:28	BVLOFC	O	DON	277.92
14-Nov-2019	49,418		412731	06-100-PMA	Inspect A PMI	20-Nov-2019 09:37:28	BSETUP	P	DON	0.00
14-Nov-2019	49,418		412731	03-044-017	Replace Indicator/Sender - Fuel Level	20-Nov-2019 09:37:28	BVLOFC	O	DON	818.02
14-Nov-2019	49,418		412731	03-022-008	Replace Pinion Seal	20-Nov-2019 09:28:03	BVLOFC	W	DON	0.00
12-Feb-2020	61,883		425950	03-034-002	Replace Stop, Tail, Turn & License	12-Feb-2020 12:15:51	BVLOFC	O	DON	733.86
12-Feb-2020	61,883		425950	24-042-009	Repair Coolant Pre-Heater- Electrical	12-Feb-2020 12:16:01	BVLOFC	W	DON	0.00
13-Feb-2020	61,914		426045	01-042-009	Adjust Coolant Pre-Heater- Electrical		BTRUCK	G	WR	0.00
13-Feb-2020	61,914		426045	03-017-001	Replace Tire - Pneumatic	13-Feb-2020 14:59:27	BTRUCK	O	DON	1,024.80
13-Feb-2020	61,914		426045	03-042-009	Replace Coolant Pre-Heater- Electrical		BTRUCK	G	WR	0.00
13-Feb-2020	61,914		426045	06-020	Inspect Drivetrain Group	13-Feb-2020 14:59:45	BTRUCK	O	DON	32.79
01-Jul-2020	87,621		448454	06-100-PMB	Inspect B PMI	04-Aug-2020 11:53:17	BSETUP	P	DON	0.00
01-Jul-2020	87,621		448454	38-045	Service Power Plant	04-Aug-2020 11:53:17	BVLOFC	I	DON	62.97
01-Jul-2020	87,621		448454	38-100-PMB	Service B PMI	04-Aug-2020 11:53:17	BVLOFC	P	DON	63.99
12-Aug-2020	96,393		455746	06-100-PMA	Inspect A PMI	25-Aug-2020 12:57:36	BVLOFC	P	DON	0.00
12-Aug-2020	96,393		455746	38-100-PMA	Service A PMI	25-Aug-2020 12:57:36	BVLOFC	P	DON	75.63
12-Aug-2020	96,393		455746	09-010-001	Align All Axles	25-Aug-2020 12:57:36	BVLOFC	I	DON	112.87
12-Aug-2020	96,393		455746	31-017	Rotate Tires, Tubes, Liners & Valves	25-Aug-2020 12:57:36	BVLOFC	I	DON	20.11
12-Sep-2020	110,297		467945	38-100-PMA	Service A PMI	12-Sep-2020 11:26:00	BVLOFC	P	DON	56.87
17-Sep-2020			462044	38-100-PMA	Service A PMI	17-Sep-2020 13:22:00	BVLOFC	P	DON	58.68
03-Oct-2020	116,971		474758	38-100-PMA	Service A PMI	03-Oct-2020 13:55:00	BVLOFC	P	DON	75.58
17-Oct-2020	116,971		474760	38-100-PMA	Service A PMI	17-Oct-2020 13:58:00	BVLOFC	P	DON	59.27
10-Feb-2021	126,608		487302	03-033-003	Replace Spark Plugs	10-Feb-2021 10:44:05	BVLOFC	B	DON	566.85
27-Mar-2021	133,351		504923	06-100-PMA	Inspect A PMI	27-Mar-2021 07:45:00	SCHED	P	DON	0.00
27-Mar-2021	133,351		504923	38-100-PMA	Service A PMI	27-Mar-2021 07:46:00	SCHED	P	DON	77.28
08-May-2021	141,613		516938	38-100-PMA	Service A PMI	08-May-2021 10:13:00	SCHED	P	DON	75.05
08-May-2021	141,613		516938	06-100-PMA	Inspect A PMI	08-May-2021 10:12:00	SCHED	P	DON	0.00
14-May-2021			506651	03-017-001	Replace Tire - Pneumatic	14-May-2021 06:29:04	BVLOFC	O	DON	792.90
05-Aug-2021	159,791		523263	03-017-001	Replace Tire - Pneumatic	12-Aug-2021 13:47:35	BTTRE	I	DON	861.52

Unit Job History

Mitchels Corporation
Report Printed: 30-Sep-2022 12:10:15 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
--------------	---------	---------	------------	----------	-----------------	----------------	--------------	------------	------------	------------

Unit No: B3510 - 2018 F150 CREWCAB

05-Aug-2021 1	159,791		523263	06-100-PMA	Inspect A PMI	09-Aug-2021 16:25:29	BTRUCK	P	DON	34.21
05-Aug-2021 1	159,791		523263	38-100-PMA	Service A PMI	10-Aug-2021 06:42:48	BTRUCK	P	DON	101.71
05-Aug-2021 1	159,791		523263	24-027	Repair Transmission - Main, Automatic	13-Aug-2021 08:52:14	BTRUCK	O	DON	88.30
05-Aug-2021 1	159,791		523263	24-013-001	Repair Front Brakes & Drums	13-Aug-2021 08:54:26	BTRUCK	I	DON	74.67
05-Aug-2021 1	159,791		523263	03-013-002	Replace Rear Brakes & Drums	10-Aug-2021 08:32:11	BTRUCK	I	DON	236.52
05-Aug-2021 1	159,791		523263	03-034-002	Replace Stop, Tail, Turn & License	10-Aug-2021 17:03:21	BTRUCK	I	DON	187.85
05-Aug-2021 1	159,791		523263	03-002-035	Replace Windshield Wiper & Washer	10-Aug-2021 06:41:31	BTRUCK	I	DON	41.82
12-Aug-2021 1			524724	06-100-PMA	Inspect A PMI	12-Aug-2021 14:13:55	MPNOC	P	DON	0.00
12-Aug-2021 1			524724	38-100-PMA	Service A PMI	12-Aug-2021 14:13:46	MPNOC	P	DON	108.92
14-Oct-2021 0	159,791		540752	03-033-002	Replace Distributor / Coil Pack	20-Oct-2021 20:20:43	TRK023	B	DON	423.67
14-Oct-2021 0	159,791		540752	95-MSC-004	Travel Travel Time - To/From Job Site	20-Oct-2021 20:21:12	TRK023	B	DON	156.84
18-Oct-2021 1	159,791		540057	38-100-PMA	Service A PMI	18-Oct-2021 15:30:09	SCHED	P	DON	104.87
18-Oct-2021 1	159,791		540057	06-100-PMA	Inspect A PMI	18-Oct-2021 15:30:06	SCHED	P	DON	0.00
27-Oct-2021 0	176,604		542189	03-002-035	Replace Windshield Wiper & Washer	02-Nov-2021 09:39:17	BTRUCK	I	DON	64.21
27-Oct-2021 0	176,604		542189	03-002-065	Replace Hood Latch	04-Nov-2021 12:00:49	BTRUCK	I	DON	116.03
27-Oct-2021 0	176,604		542189	03-034-001	Replace Headlamps / Fog Lamps	03-Nov-2021 08:07:08	BTRUCK	I	DON	190.97
27-Oct-2021 0	176,604		542189	14-051-009	Install Fire Extinguisher	02-Nov-2021 10:30:58	BTRUCK	Q	DON	38.64
27-Oct-2021 0	176,604		542189	24-027-038	Repair Electronic Controls, Transmission, Autor	04-Nov-2021 07:13:35	BTRUCK	O	DON	141.99
27-Oct-2021 0	176,604		542189	03-001-016	Replace Filter - Cab Ventilation	02-Nov-2021 10:16:48	BTRUCK	I	DON	35.39
27-Oct-2021 0	176,604		542189	31-017-001	Rotate Tire - Pneumatic	02-Nov-2021 11:23:54	BTRUCK	P	DON	34.89
27-Oct-2021 0	176,604		542189	14-051-006	Install Safety Devices	02-Nov-2021 10:21:26	BTRUCK	I	DON	21.73
27-Oct-2021 0	176,604		542189	24-049-001	Repair ECM Fault Code	03-Nov-2021 16:18:40	BTRUCK	O	DON	1,023.43
27-Oct-2021 0	176,604		542189	24-002-016	Repair Compartment Lid - Tail & Lift Gate - Re	03-Nov-2021 17:05:01	BTRUCK	I	DON	161.30
27-Oct-2021 0	176,604		542189	24-022-003	Repair Differential Carrier	04-Nov-2021 11:10:19	BTRUCK	I	DON	739.89
27-Oct-2021 0	176,604		542189	06-100-PMB	Inspect B PMI	02-Nov-2021 07:41:57	BTRUCK	P	DON	68.90
27-Oct-2021 0	176,604		542189	38-100-PMA	Service A PMI	02-Nov-2021 08:35:14	BTRUCK	P	DON	114.80
17-Nov-2021 1	176,604		547503	06-100-PMA	Inspect A PMI	17-Nov-2021 14:52:37	MPNOC	P	DON	0.00
17-Nov-2021 1	176,604		547503	38-100-PMA	Service A PMI	17-Nov-2021 14:52:47	MPNOC	P	DON	155.46
21-Dec-2021 0	176,604		555336	03-033-003	Replace Spark Plugs	05-Jan-2022 19:35:14	TRK023	B	DON	776.14

Unit Job History

Michels Corporation
Report Printed: 20-Sep-2022 12:10:15 By User: RHEENING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B3510 - 2018 F150 CREWCAB										
21-Dec-2021 0	176,604		555336	06-100-PMA	Inspect A PMI	05-Jan-2022 19:35:08	TRK023	P	DON	0.00
21-Dec-2021 0	176,604		555336	38-100-PMA	Service A PMI	05-Jan-2022 19:35:11	TRK023	P	DON	228.67
15-Feb-2022 1	193,643		597852	06-100-PMA	Inspect A PMI	15-Feb-2022 11:50:00	MPNFELD	P	DON	0.00
15-Feb-2022 1	193,643		597852	38-100-PMA	Service A PMI	15-Feb-2022 11:51:00	MPNFELD	P	DON	137.19
08-Mar-2022 1	194,593		572767	03-022-008	Replace Pinion Seal	23-May-2022 15:43:59	BTRUCK	I	DON	381.56
08-Mar-2022 1	194,593		572767	03-042-012	Replace Clamps and Hoses	23-May-2022 15:43:47	BTRUCK	I	DON	656.48
08-Mar-2022 1	194,593		572767	03-043-027	Replace Catalytic Converter	23-May-2022 15:43:42	BTRUCK	I	DON	3,179.41
08-Mar-2022 1	194,593		572767	03-053-005	Replace Markings - Vehicle - Decals	27-May-2022 07:35:36	BSETUP	I	DON	14.33
08-Mar-2022 1	194,593		572767	06-100-PMB	Inspect B PMI	26-May-2022 07:45:51	BTRUCK	P	DON	222.17
08-Mar-2022 1	194,593		572767	38-100-PMA	Service A PMI	23-May-2022 15:43:34	BTRUCK	P	DON	65.62
08-Mar-2022 1	194,593		572767	03-034-004	Replace Clearance & Marker Lamps	23-May-2022 15:43:50	BTRUCK	I	DON	28.32
08-Mar-2022 1	194,593		572767	31-017	Rotate Tires, Tubes, Liners & Valves	23-May-2022 15:43:37	BTRUCK	P	DON	21.21
08-Mar-2022 1	194,593		572767	02-002	Clean Cab & Sheet Metal	27-May-2022 08:41:29	BSETUP	N	DON	161.35
08-Mar-2022 1	194,593		572767	03-034-002	Replace Stop, Tail, Turn & License	23-May-2022 15:43:54	BTRUCK	I	DON	318.13
15-Aug-2022 0	203,034		609558	06-100-PMA	Inspect A PMI	15-Aug-2022 09:20:54	BVLOFC	P	DON	0.00
15-Aug-2022 0	203,034		609558	38-100-PMA	Service A PMI	15-Aug-2022 09:20:54	BVLOFC	P	DON	204.30
15-Sep-2022 0	203,365		616591	02-002	Clean Cab & Sheet Metal	20-Sep-2022 07:29:08	BSETUP	Z	DON	345.86
15-Sep-2022 0	203,365		616591	25-051	Remove General Accessories	16-Sep-2022 07:40:03	BSETUP	Z	DON	243.08

Unit No: B3510

Count: 105

25,921.44