

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
14-Jan-2009 14	0	0	7815	03-017-001	Replace Tire - Pneumatic	14-Jan-2009 16:46:38	BTIRE	F	DON	626.00
01-Sep-2009 1	0	0	21932	03-MSC	Replace Miscellaneous	01-Sep-2009 13:09:53	U91008	J	DON	827.37
19-Oct-2009 1	0	0	25454	03-017-001	Replace Tire - Pneumatic	19-Oct-2009 11:02:35	BTIRE	N	DON	744.97
01-Nov-2009 0	0	0	40215	03-034	Replace Lighting System	04-May-2010 13:56:38	U91010	I	DON	7.72
08-Jan-2010 07	0	0	37509	03-017-001	Replace Tire - Pneumatic	08-Jan-2010 07:37:00	U91010	F	DON	986.52
13-May-2010 0	0	0	45949	24-MSC	Repair Miscellaneous	08-Jul-2010 09:15:14	BVLOFC	F	DON	417.68
13-May-2010 0	0	0	45949	03-022-002	Replace Shaft - Rear Axle	08-Jul-2010 09:15:14	BVLOFC	F	DON	520.07
13-May-2010 0	0	0	45949	03-071-001	Replace Floor / Decking / Flatbed	08-Jul-2010 09:15:14	BVLOFC	F	DON	484.94
13-May-2010 0	0	0	45949	06-100-002	Inspect DO NOT USE - DOT Federal Insp	08-Jul-2010 09:15:14	BVLOFC	P	DON	40.63
13-May-2010 0	0	0	45949	03-034-012	Replace Box - Junction	08-Jul-2010 09:15:14	BVLOFC	F	DON	384.71
13-May-2010 0	0	0	45949	03-016-006	Replace Shock Absorber - Rear	08-Jul-2010 09:15:14	BVLOFC	F	DON	619.38
13-May-2010 0	0	0	45949	03-016-010	Replace Air Spring	08-Jul-2010 09:15:14	BVLOFC	F	DON	827.00
13-May-2010 0	0	0	45949	01-013	Adjust Brakes	08-Jul-2010 09:15:14	BVLOFC	F	DON	421.00
13-May-2010 0	0	0	45949	03-017-008	Replace Valve Assembly	08-Jul-2010 09:15:14	BVLOFC	F	DON	417.68
17-Dec-2010 0	0	0	55587	03-018-011	Replace Seal - Wheel	20-Dec-2010 08:48:05	BTRLR	I	DON	386.28
17-Dec-2010 0	0	0	55587	06-100-001	Inspect DO NOT USE - PMI Service	22-Dec-2010 11:17:38	BTRLR	P	DON	72.28
17-Dec-2010 0	0	0	55587	03-055-012	Replace Cargo Restraints	20-Dec-2010 09:00:00	BTRLR	I	DON	101.12
17-Dec-2010 0	0	0	55587	03-077-023	Replace Sand Shoe/Foot - Landing Gear	20-Dec-2010 13:05:41	BTRLR	I	DON	119.08
17-Dec-2010 0	0	0	55587	25-016-008	Remove Air Ride Suspension	20-Dec-2010 15:00:00	BTRLR	I	DON	102.82
17-Dec-2010 0	0	0	55587	14-078-009	Install Mud Flaps and Hanger Brackets	20-Dec-2010 10:59:09	BTRLR	I	DON	28.47
17-Dec-2010 0	0	0	55587	03-017-001	Replace Tire - Pneumatic	20-Dec-2010 12:02:33	BTRLR	I	DON	78.74
17-Dec-2010 0	0	0	55587	03-079-009	Replace Tape - Reflective, Conspicuity	22-Dec-2010 09:00:00	BTRLR	I	DON	107.44
17-Dec-2010 0	0	0	55587	03-071-001	Replace Floor / Decking / Flatbed	22-Dec-2010 15:00:00	BTRLR	I	DON	284.49
17-Dec-2010 0	0	0	55587	21-078-006	Fabricate Stake Pocket	22-Dec-2010 16:13:01	BWELD	E	DON	45.96
17-Dec-2010 0	0	0	55587	03-013-010	Replace Air Brake Valve	23-Dec-2010 07:37:22	BTRLR	I	DON	96.75
21-Dec-2010 1	0	0	55769	02-077	Clean Trailer Frame & Support	21-Dec-2010 13:47:20	BWASH	J	DON	7.23
02-Oct-2011 04	0	0	79917	03-078-009	Replace Mud Flaps and Hanger Brackets	02-Oct-2011 17:00:00	BVLOFC	I	DON	73.65

Unit Job History

Michels Corporation
Report Printed: 26-Jun-2023 09:31:35 By User: RHEENING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
--------------	---------	---------	------------	----------	-----------------	----------------	--------------	------------	------------	------------

Unit No: D1218 - 2001 MANAC 10245801

21-Nov-2011 0	0	0	77184	14-063	Install Satellite Communications System	29-Nov-2011 09:11:47	BTRLR	J	DON	0.00
06-Aug-2012 0	0	0	118045	06-100-DOT	Inspect DOT Federal Inspection	06-Aug-2012 14:14:11	BVLOFC	P	DON	0.00
01-Nov-2012 0	0	0	161610	24-077	Repair Trailer Frame & Support	01-Nov-2012 17:00:00	WASHPA	F	DON	4,063.98
16-Jan-2013 1	0	0	112816	03-018-011	Replace Seal - Wheel	16-Jan-2013 13:28:33	BVLOFC	F	DON	1,093.35
16-Jan-2013 1	0	0	112816	06-100-DOT	Inspect DOT Federal Inspection	16-Jan-2013 13:28:33	BVLOFC	P	DON	52.99
13-Jun-2013 0	0	0	120744	03-063-003	Replace Transceiver - GPS Tracker	13-Jun-2013 00:00:00	BTRLR	C	DON	309.26
19-Feb-2014 0	0	0	153149	24-018	Repair Wheels, Rims, Hubs & Bearings	19-Feb-2014 17:00:00	BVLOFC	I	DON	2,988.92
19-Feb-2014 0	0	0	153149	06-100-DOT	Inspect DOT Federal Inspection	19-Feb-2014 17:00:00	BVLOFC	P	DON	58.69
19-Feb-2014 0	0	0	153149	24-079	Repair Safety Devices	19-Feb-2014 17:00:00	BVLOFC	I	DON	261.48
26-Jun-2015 0	0	0	206572	03-017-001	Replace Tire - Pneumatic	26-Jun-2015 08:13:27	BTIRE	F	DON	593.78
03-Sep-2015 1	0	0	213642	11-077	Rebuild Trailer Frame & Support	20-Oct-2015 06:48:20	BTRLR	C	DON	18,747.98
03-Sep-2015 1	0	0	213642	14-053-005	Install Markings - Vehicle - Decals	20-Oct-2015 05:57:39	BTRLR	C	DON	39.96
03-Sep-2015 1	0	0	213642	03-017-001	Replace Tire - Pneumatic	20-Oct-2015 06:49:06	BTRLR	C	DON	3,930.09
03-Sep-2015 1	0	0	213642	06-100-DOT	Inspect DOT Federal Inspection	10-Oct-2015 13:27:52	WASHPA	P	DON	104.15
03-Sep-2015 1	0	0	213642	06-100-PMA	Inspect A PMI	10-Oct-2015 13:28:05	WASHPA	P	DON	108.06
06-Apr-2016 0	0	0	240234	24-063-003	Repair Transceiver - GPS Tracker	06-Apr-2016 09:16:03	WASHPA	Q	DON	338.74
03-Aug-2016 1	0	0	254264	24-077-002	Repair Dolly Crank Handle	03-Aug-2016 13:23:03	LAVSHP	O	DON	79.08
10-Aug-2016 1	0	0	256302	03-017-001	Replace Tire - Pneumatic	10-Aug-2016 10:10:55	BTIRE	F	DON	698.68
22-Aug-2016 1	0	0	256612	24-077-010	Repair Dolly - Complete	23-Aug-2016 08:55:11	LAVSHP	O	DON	117.47
18-Oct-2016 0	0	0	263376	06-100-DOT	Inspect DOT Federal Inspection	19-Oct-2016 14:41:46	WASHPA	P	DON	49.64
22-Aug-2017 1	0	0	302941	38-017-001	Service Tire - Pneumatic	22-Aug-2017 13:55:00	BTIRE	F	DON	120.42
02-Oct-2017 1	0	0	307184	06-100-DOT	Inspect DOT Federal Inspection	02-Oct-2017 15:49:39	LAVSHP	P	DON	32.88
02-Oct-2017 1	0	0	307184	03-016-006	Replace Shock Absorber - Rear	03-Oct-2017 09:31:25	LAVSHP	I	DON	89.98
02-Oct-2017 1	0	0	307184	03-017-001	Replace Tire - Pneumatic	02-Oct-2017 15:33:13	BTIRE	F	DON	394.00
21-Dec-2017 0	0	0	317040	06-100-DOT	Inspect DOT Federal Inspection	29-Dec-2017 05:44:52	BTRLR	P	DON	157.83
21-Dec-2017 0	0	0	317040	06-100-PMA	Inspect A PMI	29-Dec-2017 05:44:52	BTRLR	P	DON	211.48
21-Dec-2017 0	0	0	317040	01-018-005	Adjust Bearings - General	29-Dec-2017 05:44:52	BTRLR	I	DON	266.97
21-Dec-2017 0	0	0	317040	03-013-022	Replace Glad Hands (Service/Emergency)		BTRLR	I	CAN	0.00
21-Dec-2017 0	0	0	317040	01-013-007	Adjust Brake Lines & Fittings - Hydraulic & Air	29-Dec-2017 05:44:52	BTRLR	I	DON	41.93

Unit Job History

Mitchels Corporation
Report Printed: 26-Jun-2023 09:31:35 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
--------------	---------	---------	------------	----------	-----------------	----------------	--------------	------------	------------	------------

Unit No: D1218 - 2001 MANAC 10245801

21-Dec-2017 0			317040	24-014-001	Repair Frame Assembly	29-Dec-2017 05:44:52	BTRLR	I	DON	136.28
21-Dec-2017 0			317040	24-013-010	Repair Air Brake Valve	29-Dec-2017 05:44:52	BTRLR	I	DON	116.29
06-Nov-2018 0			359652	24-077-023	Repair Sand Shoe/Foot - Landing Gear	06-Nov-2018 14:27:52	LAVSHP	O	DON	170.68
06-Nov-2018 0			359652	03-013-022	Replace Glad Hands (Service/Emergency)	06-Nov-2018 15:31:00	LAVSHP	B	DON	44.74
17-Dec-2018 1			364890	06-100-DOT	Inspect DOT Federal Inspection	17-Dec-2018 13:34:17	LAVSHP	P	DON	74.54
09-Oct-2019 1			406741	03-077-021	Replace Jack - Leveling	10-Oct-2019 17:21:06	LAVSHP	E	DON	75.98
09-Oct-2019 1			406741	24-014-001	Repair Frame Assembly	10-Oct-2019 16:34:03	LAVSHP	B	DON	170.34
09-Oct-2019 1			406741	03-078-009	Replace Mud Flaps and Hanger Brackets	10-Oct-2019 18:08:42	LAVSHP	B	DON	51.72
09-Oct-2019 1			406741	03-034-004	Replace Clearance & Marker Lamps	10-Oct-2019 18:47:13	LAVSHP	I	DON	31.10
09-Oct-2019 1			406741	03-034-002	Replace Stop, Tail, Turn & License	10-Oct-2019 17:20:47	LAVSHP	B	DON	35.17
09-Oct-2019 1			406741	26-078	Weld Trim & Miscellaneous Hardware	11-Oct-2019 13:29:44	LAVSHP	B	DON	31.75
06-Nov-2019 1			411366	03-017-001	Replace Tire - Pneumatic	08-Nov-2019 10:31:00	BTRRE	B	DON	1,196.36
06-Nov-2019 1			411366	06-100-DOT	Inspect DOT Federal Inspection	08-Nov-2019 10:07:46	LAVSHP	P	DON	197.80
06-Nov-2019 1			411366	03-034-004	Replace Clearance & Marker Lamps	06-Nov-2019 17:36:21	LAVSHP	I	DON	8.14
06-Nov-2019 1			411366	03-013-022	Replace Glad Hands (Service/Emergency)	06-Nov-2019 12:02:14	LAVSHP	I	DON	28.25
27-Feb-2020 0			428359	03-018-012	Replace Cap - Hub	27-Feb-2020 05:14:31	BTRLR	O	DON	3.63
27-Feb-2020 0			428359	06-063-003	Inspect Transceiver - GPS Tracker		BTRLR	Q	CAN	0.00
18-Mar-2020 1			431718	03-034-002	Replace Stop, Tail, Turn & License	18-Mar-2020 13:48:25	LAVSHP	O	DON	23.82
18-Mar-2020 1			431718	06-063-003	Inspect Transceiver - GPS Tracker		LAVSHP	Q	WR	0.00
18-Mar-2020 1			431718	03-016-011	Replace Leveling Valve	23-Mar-2020 07:58:00	LAVSHP	O	DON	33.33
24-Jun-2020 1			447308	06-063-003	Inspect Transceiver - GPS Tracker	24-Jun-2020 14:45:22	LAVSHP	Q	DON	351.38
08-Sep-2020 1			460316	24-034-002	Repair Stop, Tail, Turn & License	08-Sep-2020 14:49:49	LAVSHP	O	DON	20.40
08-Sep-2020 1			460316	06-063-003	Inspect Transceiver - GPS Tracker	16-Sep-2020 12:58:30	LAVSHP	Q	DON	0.00
18-Sep-2020 0			462142	06-013	Inspect Brakes	18-Sep-2020 08:19:09	LAVSHP	O	DON	64.29
18-Sep-2020 0			462142	06-063-003	Inspect Transceiver - GPS Tracker		LAVSHP	Q	CAN	0.00
04-Nov-2020 1			470360	06-063-003	Inspect Transceiver - GPS Tracker		LAVSHP	Q	CAN	0.00
04-Nov-2020 1			470360	06-100-DOT	Inspect DOT Federal Inspection	05-Nov-2020 09:52:45	LAVSHP	P	DON	48.38
04-Nov-2020 1			470360	03-016-003	Replace Shock Absorber - Front	05-Nov-2020 08:26:00	LAVSHP	I	DON	163.73
04-Nov-2020 1			470360	03-018-011	Replace Seal - Wheel	05-Nov-2020 07:33:04	LAVSHP	I	DON	281.17

Unit Job History

Mitchels Corporation
Report Printed: 26-Jun-2023 09:31:35 By User: RHEVENING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
--------------	---------	---------	------------	----------	-----------------	----------------	--------------	------------	------------	------------

Unit No: D1218 - 2001 MANAC 10245801

30-Sep-2021			535446	06-063-003	Inspect Transceiver - GPS Tracker	30-Sep-2021 10:14:14	RIOSHP	Q	DON	194.86
30-Sep-2021			535446	03-034	Replace Lighting System	30-Sep-2021 10:11:55	RIOSHP	O	DON	24.47
10-Nov-2021			545581	06-100-DOT	Inspect DOT Federal Inspection	10-Nov-2021 13:27:38	TRK400	P	DON	205.88
10-Nov-2021			545581	06-063-003	Inspect Transceiver - GPS Tracker		TRK400	Q	CAN	0.00
29-Nov-2021			549523	06-063-003	Inspect Transceiver - GPS Tracker		TRK400	Q	CAN	0.00
21-Mar-2022			575991	03-013-010	Replace Air Brake Valve	21-Mar-2022 15:38:43	LAVSHP	I	DON	266.69
06-Oct-2022			622381	06-063-003	Inspect Transceiver - GPS Tracker		TRK400	Q	CAN	0.00
06-Oct-2022			622381	24-077-029	Repair Mount - Landing Gear	06-Oct-2022 15:24:49	TRK400	E	DON	80.57
01-Nov-2022			628788	06-063-003	Inspect Transceiver - GPS Tracker		LAVSHP	Q	CAN	0.00
01-Nov-2022			628788	06-100-DOT	Inspect DOT Federal Inspection	01-Nov-2022 10:40:53	LAVSHP	P	DON	101.50
01-Nov-2022			628797	03-017-001	Replace Tire - Pneumatic	14-Nov-2022 10:31:06	TRK400	O	DON	710.10
19-Jun-2023			682476	06-063-003	Inspect Transceiver - GPS Tracker		BDDRIL	Q	CAN	0.00
19-Jun-2023			682476	25-053-005	Remove Markings - Vehicle - Decals	19-Jun-2023 12:03:38	BDDRIL	Z	DON	64.12
19-Jun-2023			682476	25-053-101	Remove License Plate	19-Jun-2023 14:11:16	BDDRIL	Z	DON	13.77
19-Jun-2023			682476	25-063-003	Remove Transceiver - GPS Tracker	19-Jun-2023 13:22:49	BDDRIL	Q	DON	33.22
19-Jun-2023			682476	03-071-001	Replace Floor / Decking / Flatbed	20-Jun-2023 12:16:57	BDDRIL	Z	DON	413.74
19-Jun-2023			682476	03-078-009	Replace Mud Flaps and Hanger Brackets	19-Jun-2023 13:49:03	BDDRIL	Z	DON	16.26

Unit No: D1218

Count: 104

49,297.73