

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: A0859 - 2008 INTERNATIONAL 4300										
03-Dec-2011 0	0	0	124379	06-100-DOT	Inspect DOT Federal Inspection	03-Dec-2011 11:54:32	BVLOFC	P	DON	0.00
05-Jun-2012 0	0	0	124373	06-100-DOT	Inspect DOT Federal Inspection	05-Jun-2012 11:51:43	BVLOFC	P	DON	0.00
18-Jul-2013 06	57,491	0	124552	06-100-DOT	Inspect DOT Federal Inspection	18-Jul-2013 07:34:33	BVLOFC	P	DON	0.00
14-Mar-2014 0	58,316	0	151301	03-063-003	Replace Transceiver - GPS Tracker	14-Mar-2014 00:00:00	GPSINS	C	DON	222.88
29-Sep-2014 0	58,861	0	173996	06-100-DOT	Inspect DOT Federal Inspection	29-Sep-2014 17:00:00	PKIRK	P	DON	0.00
30-Sep-2014 0	59,264	2,967	181213	24-013	Repair Brakes	30-Sep-2014 17:00:00	BVLOFC	F	DON	205.84
30-Sep-2014 0	59,264	2,967	181213	06-034-004	Inspect Clearance & Marker Lamps	30-Sep-2014 17:00:00	BVLOFC	F	DON	0.00
14-Oct-2014 1	59,981	2,967	176107	19-063-003	Wire/Rewire Transceiver - GPS Tracker	15-Oct-2014 12:23:19	GPSINS	C	DON	29.49
05-Aug-2015 C	60,766	3,015	210173	01-023-001	Adjust Linkage - Mechanical Clutch	17-Aug-2015 07:11:55	BTRUCK	I	DON	104.07
05-Aug-2015 C	60,766	3,015	210173	01-042-002	Adjust Radiator	20-Aug-2015 13:49:16	BTRUCK	I	DON	46.11
05-Aug-2015 C	60,766	3,015	210173	01-071-005	Adjust Side Door Assembly - Hinged	17-Aug-2015 07:12:04	BTRUCK	I	CAN	0.00
05-Aug-2015 C	60,766	3,015	210173	03-001-016	Replace Filter - Cab Ventilation	17-Aug-2015 07:12:04	BTRUCK	P	DON	78.22
05-Aug-2015 C	60,766	3,015	210173	03-013-012	Replace Electric Brakes	05-Aug-2015 14:03:55	BTRUCK	I	DON	22.52
05-Aug-2015 C	60,766	3,015	210173	03-017-001	Replace Tire - Pneumatic	20-Aug-2015 13:00:45	BTRUCK	I	DON	24.00
05-Aug-2015 C	60,766	3,015	210173	03-032-001	Replace Battery	17-Aug-2015 07:11:52	BTRUCK	I	DON	431.05
05-Aug-2015 C	60,766	3,015	210173	03-051-009	Replace Fire Extinguisher	20-Aug-2015 08:40:09	BTRUCK	I	DON	43.00
05-Aug-2015 C	60,766	3,015	210173	03-054-001	Replace Horn & Mounting	17-Aug-2015 07:11:49	BTRUCK	I	DON	238.57
05-Aug-2015 C	60,766	3,015	210173	03-059-002	Replace Pintle Hook Assembly	20-Aug-2015 11:23:24	BTRUCK	I	DON	435.56
05-Aug-2015 C	60,766	3,015	210173	03-078-009	Replace Mud Flaps and Hanger Brackets	09-Sep-2015 07:25:09	BTRUCK	I	DON	41.38
05-Aug-2015 C	60,766	3,015	210173	06-010	Inspect Chassis Group	20-Aug-2015 08:02:16	BTRUCK	I	DON	54.40
05-Aug-2015 C	60,766	3,015	210173	06-100-DOT	Inspect DOT Federal Inspection	02-Sep-2015 16:20:26	BTRUCK	P	DON	108.87
05-Aug-2015 C	60,766	3,015	210173	06-100-PMB	Inspect B PMI	17-Aug-2015 07:11:41	BTRUCK	P	DON	572.67
05-Aug-2015 C	60,766	3,015	210173	12-173-001	Refinish Body or Bed	10-Sep-2015 14:37:11	BBODY	C	DON	681.75
05-Aug-2015 C	60,766	3,015	210173	14-001-016	Install Filter - Cab Ventilation	20-Aug-2015 12:01:10	BTRUCK	I	DON	62.00
05-Aug-2015 C	60,766	3,015	210173	14-042-009	Install Coolant Pre-Heater- Electrical	17-Aug-2015 07:12:00	BTRUCK	I	DON	184.58
05-Aug-2015 C	60,766	3,015	210173	15-173-001	Paint Prep Body or Bed	02-Sep-2015 15:40:30	BSAND	C	DON	802.92
05-Aug-2015 C	60,766	3,015	210173	24-002-002	Repair Fenders	17-Aug-2015 07:12:15	BTRUCK	I	DON	63.68
05-Aug-2015 C	60,766	3,015	210173	24-013-035	Repair Clevis Pins	17-Aug-2015 07:11:47	BTRUCK	I	DON	199.18
05-Aug-2015 C	60,766	3,015	210173	24-034-004	Repair Clearance & Marker Lamps	03-Sep-2015 11:12:50	BTRUCK	I	DON	201.47

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: A0859 - 2008 INTERNATIONAL 4300										
05-Aug-2015 C	60,766	3,015	210173	24-071-005	Repair Side Door Assembly - Hinged	17-Aug-2015 07:17:14	BTRUCK	I	DON	199.40
05-Aug-2015 C	60,766	3,015	210173	24-173-001	Repair Body or Bed	27-Aug-2015 06:20:56	BWELD	N	DON	406.36
05-Aug-2015 C	60,766	3,015	210173	34-026-009	Reseal Cover Assembly	17-Aug-2015 07:12:08	BTRUCK	I	DON	231.73
17-Aug-2016 C	71,613		258740	06-100-DOT	Inspect DOT Federal Inspection	17-Aug-2016 07:00:00	LAVSHP	P	DON	22.36
17-Aug-2016 C	71,613		258740	06-100-PMB	Inspect B PMI	17-Aug-2016 07:00:00	LAVSHP	P	DON	22.36
06-Sep-2016 0	72,058		258227	06-100-PMB	Inspect B PMI		BTRUCK	P	CAN	0.00
06-Sep-2016 0	72,058		258227	14-024-002	Install Drive Shaft, Behind Main Transmission	08-Sep-2016 10:23:56	BTRUCK	I	DON	698.15
06-Sep-2016 0	72,058		258227	24-045	Repair Power Plant	08-Sep-2016 10:23:56	BTRUCK	O	DON	593.39
30-Sep-2016 1	72,847		261328	24-013	Repair Brakes	30-Sep-2016 14:55:51	BTRUCK	O	DON	346.96
26-Oct-2016 0	73,167		266789	02-042-002	Clean Radiator	26-Oct-2016 07:00:00	LAVSHP	P	DON	22.36
17-Mar-2017 0	73,167		281474	02-002-011	Clean Cab Accessories - Interior	17-Mar-2017 07:03:02	LAVSHP	I	DON	17.33
17-Mar-2017 0	73,167		281474	06-001-008	Inspect Motor - Blower	17-Mar-2017 07:33:23	LAVSHP	I	DON	14.93
15-Jun-2017 0	76,722	3,925	292981	03-042-013	Replace Fan Belt	16-Jun-2017 09:34:33	ROGSHP	P	DON	130.39
15-Sep-2017 0	78,025	3,974	305166	02-032-004	Clean Battery Cables and Ends	15-Sep-2017 10:25:10	ROGSHP	N	DON	20.16
27-Sep-2017 0	78,025	3,979	306608	06-100-DOT	Inspect DOT Federal Inspection	27-Sep-2017 09:44:04	ROGSHP	P	DON	80.90
27-Sep-2017 0	78,025	3,979	306608	14-079-009	Install Tape - Reflective, Conspicuity	27-Sep-2017 10:20:31	ROGSHP	I	DON	17.81
27-Sep-2017 0	78,025	3,979	306608	03-017-001	Replace Tire - Pneumatic	28-Sep-2017 06:23:22	ROGSHP	I	DON	2,345.18
27-Sep-2017 0	78,025	3,979	306608	03-051-009	Replace Fire Extinguisher	27-Sep-2017 10:10:00	ROGSHP	I	DON	17.39
27-Sep-2017 0	78,025	3,979	306608	02-032-001	Clean Battery	27-Sep-2017 09:57:19	ROGSHP	P	DON	18.17
04-Oct-2017 0	78,025	3,979	308082	06-100-PMA	Inspect A PMI	04-Oct-2017 12:30:00	MAVSHP	P	DON	203.37
01-Nov-2017 C	78,145		310966	03-053-005	Replace Markings - Vehicle - Decals	01-Nov-2017 10:16:20	ROGSHP	Q	DON	44.91
01-Nov-2017 C	78,145		310966	06-300	Inspect Heavy Equipment Group	01-Nov-2017 09:43:35	ROGSHP	P	DON	93.79
08-Nov-2017 C	78,185		311790	03-042-013	Replace Fan Belt	08-Nov-2017 06:50:51	ROGSHP	N	DON	79.11
28-Nov-2017 C	79,159	3,999	313788	06-001-008	Inspect Motor - Blower	08-Dec-2017 11:00:14	ROGSHP	O	DON	4.18
28-Nov-2017 C	79,159	3,999	313788	01-023-004	Adjust Clutch Disc	28-Nov-2017 06:56:45	ROGSHP	N	DON	27.10
28-Nov-2017 C	79,159	3,999	313788	24-002-025	Repair Glass Channels	11-Jan-2018 07:49:34	ROGSHP	N	DON	22.50
28-Nov-2017 C	79,159	3,999	313788	03-034-001	Replace Headlamps / Fog Lamps	05-Dec-2017 18:18:54	ROGSHP	B	DON	19.35
19-Feb-2018 1			324238	03-001-008	Replace Motor - Blower	20-Feb-2018 18:06:55	ROGSHP	B	DON	213.40
19-Feb-2018 1			324238	03-001-025	Replace Resistor - Blower Motor	20-Feb-2018 18:07:32	ROGSHP	B	DON	183.59

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: A0859 - 2008 INTERNATIONAL 4300										
12-Jun-2018 1	82,195	4,333	339407	01-023	Adjust Clutch	12-Jun-2018 14:27:53	ROGSHP	N	DON	5.68
27-Jun-2018 0	82,854	4,355	341552	24-034-001	Repair Headlamps / Fog Lamps	27-Jun-2018 07:09:41	ROGSHP	N	DON	8.08
28-Jun-2018 0	83,011		341763	03-031-006	Replace Belt - Alternator	28-Jun-2018 09:26:57	ROGSHP	N	DON	114.57
29-Jun-2018 1	83,066	4,361	342038	06-045-027	Inspect Idler Pulley	29-Jun-2018 14:25:43	ROGSHP	N	DON	354.23
02-Jul-2018 14	83,066	4,361	342259	03-031-001	Replace Generator/Alternator	03-Jul-2018 12:10:25	ROGSHP	N	DON	408.19
16-Jul-2018 14	83,171	4,365	343942	03-032-001	Replace Battery	16-Jul-2018 15:35:22	ROGSHP	N	DON	422.45
25-Jul-2018 08	83,171	4,365	345281	03-013-010	Replace Air Brake Valve	26-Jul-2018 13:25:52	ROGSHP	N	DON	285.17
25-Jul-2018 08	83,171	4,365	345281	06-013-010	Inspect Air Brake Valve	27-Jul-2018 08:19:41	ROGSHP	O	DON	27.78
07-Aug-2018 1	83,324	4,383	347221	03-042-013	Replace Fan Belt	07-Aug-2018 18:15:49	ROGSHP	O	DON	104.72
07-Aug-2018 1	83,324	4,383	347221	06-045-027	Inspect Idler Pulley	07-Aug-2018 18:21:00	ROGSHP	O	DON	2.70
14-Aug-2018 1	83,340	4,385	348134	35-033	Diagnose Ignition System	14-Aug-2018 14:19:11	ROGSHP	B	DON	209.78
14-Aug-2018 1	83,340	4,385	348134	03-100-PMB	Replace B PMI	14-Aug-2018 14:21:47	ROGSHP	B	DON	50.95
14-Aug-2018 1	83,340	4,385	348134	03-045-023	Replace Engine Belts	14-Aug-2018 16:08:07	ROGSHP	N	DON	93.95
14-Aug-2018 1	83,340	4,385	348134	24-044	Repair Fuel System	20-Aug-2018 17:32:15	ROGSHP	N	DON	629.65
14-Aug-2018 1	83,340	4,385	348134	03-045-028	Replace Valve Cover	16-Aug-2018 09:49:56	ROGSHP	N	DON	542.15
14-Aug-2018 1	83,340	4,385	348134	03-044-004	Replace Injectors - Mechanical	20-Aug-2018 15:38:01	ROGSHP	N	DON	3,129.30
06-Sep-2018 1	83,684	4,388	351074	03-013-001	Replace Front Brakes & Drums	02-Oct-2018 10:21:01	ROGSHP	I	DON	509.73
06-Sep-2018 1	83,684	4,388	351074	03-013-002	Replace Rear Brakes & Drums	02-Oct-2018 15:21:21	ROGSHP	I	DON	596.38
06-Sep-2018 1	83,684	4,388	351074	03-053-004	Replace Safety Equipment	02-Oct-2018 16:37:45	ROGSHP	I	DON	28.99
06-Sep-2018 1	83,684	4,388	351074	03-053-101	Replace License Plate	02-Oct-2018 15:30:03	ROGSHP	I	DON	4.85
06-Sep-2018 1	83,684	4,388	351074	06-100-DOT	Inspect DOT Federal Inspection	02-Oct-2018 16:35:31	ROGSHP	P	DON	44.09
06-Sep-2018 1	83,684	4,388	351074	24-013-010	Repair Air Brake Valve	07-Sep-2018 10:04:29	ROGSHP	N	DON	53.95
06-Sep-2018 1	83,684	4,388	351074	24-034-002	Repair Stop, Tail, Turn & License	02-Oct-2018 16:36:39	ROGSHP	I	DON	19.52
08-Jan-2019 1	84,824		367358	03-026-012	Replace Transmission Assembly - Manual	09-Jan-2019 12:41:25	LAVSHP	C	DON	5,854.87
14-Jan-2019 0	84,836	4,390	368050	06-100-PMA	Inspect A PMI	14-Jan-2019 17:27:44	LAVSHP	P	DON	266.01
01-Feb-2019 0	84,824	4,388	371163	03-034-004	Replace Clearance & Marker Lamps	01-Apr-2019 13:52:11	MAVSHP	I	DON	100.20
15-Apr-2019 1	84,966		381308	14-052-003	Install Radio Equipment	29-Apr-2019 15:50:27	ROGSHP	Q	DON	169.74
15-Apr-2019 1	84,966	4,513	381308	24-173-011	Repair Hinge As - Tailgate	18-Apr-2019 07:06:13	ROGSHP	N	DON	40.59
15-Apr-2019 1	84,966	4,513	381308	03-034-006	Replace Warning Lamps - Special Application	26-Apr-2019 16:04:19	ROGSHP	N	DON	177.43

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost		
Unit No: A0859 - 2008 INTERNATIONAL 4300												
15-Apr-2019	1	84,966	4,513	381308	24-054-002	Repair Alarm - Reverse Signal	30-Apr-2019	07:29:04	ROGSHP	N	DON	18.82
15-Apr-2019	1	84,966	4,513	381308	03-054-002	Replace Alarm - Reverse Signal	30-Apr-2019	07:56:12	ROGSHP	N	DON	57.52
12-Jul-2019	07	87,059	4,612	393947	24-034-002	Repair Stop, Tail, Turn & License	12-Jul-2019	08:51:55	ROGSHP	N	DON	39.51
29-Jul-2019	15	88,449	4,658	396324	06-026	Inspect Transmission - Main, Manual	29-Jul-2019	17:33:56	ROGSHP	O	DON	51.92
29-Jul-2019	15	88,449	4,658	396324	24-026-010	Repair Rails, Forks & Internal Shift Mechanism	30-Jul-2019	09:42:26	ROGSHP	N	DON	79.88
07-Aug-2019	C	88,592		397552	06-044	Inspect Fuel System	07-Aug-2019	07:02:26	ROGSHP	N	DON	39.54
21-Aug-2019	C	90,158		399616	24-002-035	Repair Windshield Wiper & Washer	21-Aug-2019	06:43:47	ROGSHP	N	DON	10.30
18-Sep-2019	1	90,518		403508	06-026	Inspect Transmission - Main, Manual	02-Oct-2019	11:27:51	ROGSHP	N	DON	325.78
18-Sep-2019	1	90,518		403508	03-049-003	Replace ECM Wiring Harness	02-Oct-2019	11:27:57	ROGSHP	N	DON	3,538.03
18-Sep-2019	1	90,518		403508	03-026	Replace Transmission - Main, Manual	02-Oct-2019	11:28:03	ROGSHP	C	DON	7,769.20
18-Sep-2019	1	90,518		403508	03-034-001	Replace Headlamps / Fog Lamps	02-Oct-2019	11:28:08	ROGSHP	N	DON	45.85
18-Sep-2019	1	90,518		403508	24-015-002	Repair Steering Shaft Support	02-Oct-2019	11:28:13	ROGSHP	N	DON	946.17
18-Sep-2019	1	90,518		403508	06-040	Inspect Engine / Motor Systems Group	02-Oct-2019	11:27:47	ROGSHP	O	DON	494.37
17-Oct-2019	0	90,734	4,735	407991	03-034-004	Replace Clearance & Marker Lamps	17-Oct-2019	10:22:27	ROGSHP	I	DON	7.84
17-Oct-2019	0	90,734	4,735	407991	06-100-DOT	Inspect DOT Federal Inspection	17-Oct-2019	10:20:43	ROGSHP	P	DON	17.48
28-Oct-2019	1	90,945	4,751	409881	24-002-035	Repair Windshield Wiper & Washer	28-Oct-2019	16:38:15	ROGSHP	O	DON	545.70
07-Nov-2019	C	91,138	4,763	411509	06-013	Inspect Brakes	07-Nov-2019	06:46:47	ROGSHP	O	DON	4.36
07-Nov-2019	C	91,138	4,763	411509	03-034-011	Replace Plug - Trailer Light Cord	07-Nov-2019	08:03:23	ROGSHP	N	DON	65.37
07-Nov-2019	C	91,138	4,763	411509	24-034-002	Repair Stop, Tail, Turn & License	07-Nov-2019	08:08:15	ROGSHP	N	DON	2.71
07-Nov-2019	C	91,138	4,763	411509	14-013-022	Install Glad Hands (Service/Emergency)	07-Nov-2019	08:08:37	ROGSHP	N	DON	19.86
11-Nov-2019	1	91,435		412177	24-034-002	Repair Stop, Tail, Turn & License	11-Nov-2019	18:38:39	ROGSHP	N	DON	76.13
21-Feb-2020	1	93,840		427653	06-032-009	Inspect Switch - Master Disconnect			LAVSHP	I	CAN	0.00
21-Feb-2020	1	93,840		427653	06-032	Inspect Cranking System	21-Feb-2020	18:40:44	LAVSHP	O	DON	26.56
21-Feb-2020	1	93,840		427653	06-032-001	Inspect Battery	26-Feb-2020	06:00:23	LAVSHP	O	DON	15.50
21-Feb-2020	1	93,840		427653	06-043-004	Inspect Turbocharger	26-Feb-2020	10:03:23	LAVSHP	O	DON	91.61
21-Feb-2020	1	93,840		427653	03-032-001	Replace Battery	26-Feb-2020	07:19:08	LAVSHP	I	DON	224.58
21-Feb-2020	1	93,840		427653	02-041	Clean Air Intake System	28-Feb-2020	05:16:54	LAVSHP	I	DON	104.84
21-Feb-2020	1	93,840		427653	03-018-011	Replace Seal - Wheel	28-Feb-2020	14:52:12	LAVSHP	I	DON	360.11
21-Feb-2020	1	93,840		427653	03-043-004	Replace Turbocharger	27-Feb-2020	10:51:58	LAVSHP	I	DON	2,859.74

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: A0859 - 2008 INTERNATIONAL 4300										
21-Feb-2020 01	93,840		427653	03-041-004	Replace Aftercooler / Intercooler	28-Feb-2020 10:39:59	LAVSHP	I	DON	1,477.60
30-Jun-2020 01	94,608		448205	06-706-001	Inspect Engine	13-Aug-2020 08:01:45	ROGSHP	O	DON	9.89
30-Jun-2020 01	94,608		448205	06-100-PMA	Inspect A PMI	13-Aug-2020 09:23:51	BTRUCK	P	DON	0.00
30-Jun-2020 01	94,608		448205	03-044-014	Replace Injectors - Electronic	13-Aug-2020 08:08:19	ROGSHP	N	DON	5,432.09
30-Jun-2020 01	94,608		448205	24-041-008	Repair Hose Air Intake	13-Aug-2020 09:15:01	ROGSHP	N	DON	673.42
30-Jun-2020 01	94,608		448205	38-100-PMA	Service A PMI	13-Aug-2020 09:15:05	ROGSHP	P	DON	599.81
30-Jun-2020 01	94,608		448205	03-045-026	Replace Tensioner - Engine Belts	13-Aug-2020 09:15:09	ROGSHP	N	DON	693.02
30-Jun-2020 01	94,608		448205	03-044-003	Replace Fuel Pump	13-Aug-2020 09:21:23	ROGSHP	N	DON	556.10
06-Oct-2020 11	94,751		465094	03-051-009	Replace Fire Extinguisher	06-Oct-2020 14:02:47	ROGSHP	I	DON	1.95
06-Oct-2020 11	94,751		465094	06-100-DOT	Inspect DOT Federal Inspection	06-Oct-2020 12:58:17	ROGSHP	P	DON	28.54
06-Oct-2020 11	94,751		465094	02-034-001	Clean Headlamps / Fog Lamps	06-Oct-2020 13:59:17	ROGSHP	I	DON	77.38
06-Oct-2020 11	94,751		465094	03-002-035	Replace Windshield Wiper & Washer	06-Oct-2020 14:11:25	ROGSHP	I	DON	36.26
13-Apr-2021 01	94,832		500095	01-042-014	Adjust Coolant Overflow Reservoir	13-Apr-2021 07:26:17	ROGSHP	P	DON	16.17
23-Jun-2021 11	94,832		514599	03-051-009	Replace Fire Extinguisher	23-Jun-2021 15:08:57	ROGSHP	N	DON	19.57
23-Jun-2021 11	94,832		514599	24-026-016	Repair Gear Shifter & Linkage	23-Jun-2021 14:51:09	ROGSHP	O	DON	27.31
01-Sep-2021 11	94,832		528952	24-034-012	Repair Box - Junction	01-Sep-2021 14:32:42	OTSSHP	O	DON	0.33
01-Sep-2021 11	94,832		528952	24-173-011	Repair Hinge As - Tailgate	01-Sep-2021 14:27:16	OTSSHP	O	DON	18.60
20-Oct-2021 01	94,832		540479	03-018-011	Replace Seal - Wheel	20-Oct-2021 12:09:23	OTSSHP	I	DON	209.01
20-Oct-2021 01	94,832		540479	03-063-003	Replace Transceiver - GPS Tracker	20-Oct-2021 12:50:40	SCHED	Q	DON	389.12
20-Oct-2021 01	94,832		540479	06-100-DOT	Inspect DOT Federal Inspection	20-Oct-2021 13:49:06	SCHED	P	DON	60.32
20-Oct-2021 01	94,832		540479	07-010	Lubricate Chassis Group	20-Oct-2021 12:31:10	OTSSHP	I	DON	15.96
21-Oct-2021 01	94,832		540824	20-400	Tow Small Equipment Group	28-Oct-2021 14:08:46	OTSSHP	B	DON	234.29
21-Oct-2021 01	94,832		540824	03-018-011	Replace Seal - Wheel	03-Nov-2021 09:37:19	OTSSHP	N	DON	155.26
21-Oct-2021 01	94,832		540824	24-022-001	Repair Axle Housing, Rear	25-Oct-2021 10:53:47	OTSSHP	B	DON	1,374.94
21-Oct-2021 01	94,832		540824	03-018-002	Replace Drive Axle Hubs & Bearings	03-Nov-2021 09:19:04	OTSSHP	B	DON	711.39
24-Feb-2022 01	94,832		569516	03-002-035	Replace Windshield Wiper & Washer	24-Feb-2022 06:53:36	OTSSHP	N	DON	29.29
24-Feb-2022 11	94,832		569790	03-059-002	Replace Pintle Hook Assembly	28-Feb-2022 09:55:39	OTSSHP	A	DON	1,140.14
24-Feb-2022 11	94,832		569790	03-013-022	Replace Glad Hands (Service/Emergency)	28-Feb-2022 12:50:50	OTSSHP	A	DON	51.14
24-Feb-2022 11	94,832		569790	03-017-001	Replace Tire - Pneumatic	01-Mar-2022 12:54:17	OTSSHP	A	DON	298.93

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: A0859 - 2008 INTERNATIONAL 4300										
24-Feb-2022 1	94,832		569790	03-034-002	Replace Stop, Tail, Turn & License	28-Feb-2022 13:44:30	OTSSHP	A	DON	69.73
24-Feb-2022 1	94,832		569790	01-078-009	Adjust Mud Flaps and Hanger Brackets	28-Feb-2022 11:33:02	OTSSHP	A	DON	71.36
06-Jun-2022 0	98,201	5,419	593584	06-100-009	Inspect Safety Check	06-Jun-2022 10:27:57	BTRUCK	I	DON	154.82
06-Jun-2022 0	98,201	5,419	593584	24-015-001	Repair Steering Wheel	06-Jun-2022 11:29:03	BTRUCK	I	DON	280.78
06-Jun-2022 0	98,201	5,419	593584	24-034-010	Repair Socket - Trailer Light Cord	08-Jun-2022 11:19:45	BTRUCK	I	DON	405.17
06-Jun-2022 0	98,201	5,419	593584	03-079-009	Replace Tape - Reflective, Conspicuity	08-Jun-2022 06:55:51	BTRUCK	I	DON	41.96
06-Jun-2022 0	98,201	5,419	593584	38-018-001	Service Front Axle Hubs & Bearings	08-Jun-2022 08:53:18	BTRUCK	I	DON	101.90
06-Jun-2022 0	98,201	5,419	593584	38-100-PMMA	Service A PMI	20-Jun-2022 09:31:51	BTRUCK	P	DON	448.03
06-Jun-2022 0	98,201	5,419	593584	03-051-009	Replace Fire Extinguisher	06-Jun-2022 12:47:38	BTRUCK	Q	DON	50.19
06-Jun-2022 0	98,201	5,419	593584	03-002-009	Replace Sun Visor	06-Jun-2022 11:18:34	BTRUCK	I	DON	75.58
06-Jun-2022 0	98,201	5,419	593584	03-002-035	Replace Windshield Wiper & Washer	06-Jun-2022 11:41:02	BTRUCK	I	DON	27.35
06-Jun-2022 0	98,201	5,419	593584	03-002-061	Replace Seat Cushion	06-Jun-2022 12:00:41	BTRUCK	I	DON	182.43
06-Jun-2022 0	98,201	5,419	593584	03-049-004	Replace ECM Sensor		BTRUCK	I	CAN	0.00
06-Jun-2022 0	98,201	5,419	593584	24-510-002	Repair Tool Box	08-Jun-2022 09:47:18	BTRUCK	I	DON	35.59
06-Jun-2022 0	98,201	5,419	593584	06-100-PMMA	Inspect A PMI	20-Jun-2022 08:50:08	BTRUCK	P	DON	60.23
06-Jun-2022 0	98,201	5,419	593584	03-042-014	Replace Coolant Overflow Reservoir	09-Jun-2022 16:00:16	BTRUCK	I	DON	391.72
07-Jul-2022 15	98,202		600872	02-002	Clean Cab & Sheet Metal	25-Jul-2022 11:43:59	BSETUP	Q	DON	363.90
07-Jul-2022 15	98,202		600872	03-013-012	Replace Electric Brakes	05-Aug-2022 12:03:29	BTRUCK	I	DON	256.47
07-Jul-2022 15	98,202		600872	03-013-016	Replace Air Dryer / Purge Valve	05-Aug-2022 17:04:51	BTRUCK	I	DON	181.37
07-Jul-2022 15	98,202		600872	03-034-006	Replace Warning Lamps - Special Application	05-Aug-2022 15:36:29	BSETUP	C	DON	649.42
07-Jul-2022 15	98,202		600872	03-034-010	Replace Socket - Trailer Light Cord	05-Aug-2022 09:20:11	BTRUCK	I	DON	478.60
07-Jul-2022 15	98,202		600872	03-051-006	Replace Safety Devices	25-Jul-2022 09:43:08	BSETUP	Q	DON	64.68
07-Jul-2022 15	98,202		600872	03-053-005	Replace Markings - Vehicle - Decals	23-Jul-2022 07:51:21	BSETUP	Q	DON	63.46
07-Jul-2022 15	98,202		600872	03-065-006	Replace Filters, Strainers, Screens & Housing	04-Aug-2022 13:39:21	BTRUCK	I	DON	119.72
07-Jul-2022 15	98,202		600872	03-078-009	Replace Mud Flaps and Hanger Brackets	28-Jul-2022 09:19:37	BSETUP	Q	DON	197.43
07-Jul-2022 15	98,202		600872	06-100-DOT	Inspect DOT Federal Inspection	08-Aug-2022 06:38:17	BTRUCK	P	DON	67.59
07-Jul-2022 15	98,202		600872	12-173-001	Refinish Body or Bed	25-Jul-2022 06:41:14	BBODY	K	DON	1,079.32
07-Jul-2022 15	98,202		600872	14-034	Install Lighting System	08-Aug-2022 07:00:38	BSETUP	C	DON	556.45
07-Jul-2022 15	98,202		600872	14-173-008	Install Tarp Assemblies	04-Aug-2022 13:39:21	BTRUCK	C	DON	3,284.65

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: A0859 - 2008 INTERNATIONAL 4300										
07-Jul-2022	15	98,202	600872	15-173-001	Paint Prep Body or Bed	25-Jul-2022 06:41:11	BBODY	K	DON	651.31
04-Oct-2022	0	98,727	5,446	01-000	Adjust Cab, Climate Cntrl, Instrument		BTRUCK	I	CAN	0.00
04-Oct-2022	0	98,727	5,446	01-015-007	Adjust Control Valve - Tie Rod Type		BTRUCK	I	CAN	0.00
04-Oct-2022	0	98,727	5,446	06-100-009	Inspect Safety Check	04-Oct-2022 08:01:10	BTRUCK	P	DON	4.49
04-Oct-2022	0	98,727	5,446	07-010-001	Lubricate All Axles	04-Oct-2022 09:52:07	BTRUCK	I	DON	11.40
04-Oct-2022	0	98,727	5,446	14-079-009	Install Tape - Reflective, Conspicuity	04-Oct-2022 10:51:24	BTRUCK	I	DON	28.78
04-Oct-2022	0	98,727	5,446	24-002-035	Repair Windshield Wiper & Washer		BTRUCK	I	CAN	0.00
04-Oct-2022	0	98,727	5,446	24-753-022	Repair Lighting	04-Oct-2022 08:47:47	BTRUCK	I	DON	61.19
11-Nov-2022	1	98,741	5,448	24-173-008	Repair Tarp Assemblies		BTRUCK	O	CAN	0.00
23-Jan-2023	1	100,668	5,506	02-002	Clean Cab & Sheet Metal	24-Jan-2023 16:00:03	BSETUP	N	DON	382.42
23-Jan-2023	1	100,668	5,506	12-018-003	Refinish Wheels	24-Jan-2023 13:29:47	BSETUP	I	DON	140.85
28-Feb-2023	1	100,776	5,507	06-100-PMB	Inspect B PMI	02-Mar-2023 09:28:48	BTRUCK	P	DON	31.97
28-Feb-2023	1	100,776	5,507	24-013-035	Repair Clevis Pins	02-Mar-2023 08:23:03	BTRUCK	I	DON	56.37
28-Feb-2023	1	100,776	5,507	24-034-004	Repair Clearance & Marker Lamps	02-Mar-2023 05:45:11	BTRUCK	I	DON	10.59
28-Feb-2023	1	100,776	5,507	06-100-DOT	Inspect DOT Federal Inspection	02-Mar-2023 09:27:42	BTRUCK	P	DON	28.48
28-Feb-2023	1	100,776	5,507	24-013-022	Repair Glad Hands (Service/Emergency)	02-Mar-2023 06:25:01	BTRUCK	I	DON	24.70
28-Feb-2023	1	100,776	5,507	03-051-009	Replace Fire Extinguisher	02-Mar-2023 06:29:56	BTRUCK	Q	DON	42.65
28-Feb-2023	1	100,776	5,507	14-051-006	Install Safety Devices	02-Mar-2023 06:52:08	BTRUCK	Q	DON	19.09
07-Jun-2023	1	101,510	5,539	24-042-014	Repair Coolant Overflow Reservoir	07-Jun-2023 13:55:39	BTRUCK	I	DON	104.45
14-Aug-2023	0	101,652	5,541	06-100-009	Inspect Safety Check	14-Aug-2023 08:36:57	BTRUCK	I	DON	25.74
23-Aug-2023	0	101,652	5,541	02-002	Clean Cab & Sheet Metal	29-Aug-2023 07:57:48	BSETUP	Z	DON	140.78
23-Aug-2023	0	101,652	5,541	25-050	Remove Accessories Group	28-Aug-2023 15:13:00	BSETUP	Z	DON	105.75

Unit No: A0859

Count: 196

69,014.56