

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost	
Unit No: G0837 - 2017 INTERNATIONAL HX620											
16-Mar-2020	1	666	16,713	431237	03-017-001	Replace Tire - Pneumatic	07-Apr-2020 17:00:01	BTRUCK	I	DON	50.99
16-Mar-2020	1	666	16,713	431237	06-100-DOT	Inspect DOT Federal Inspection	13-Apr-2020 10:22:24	BTRUCK	P	DON	11.44
16-Mar-2020	1	666	16,713	431237	14-051-006	Install Safety Devices	07-Apr-2020 12:46:07	BTRUCK	I	DON	59.12
16-Mar-2020	1	666	16,713	431237	14-051-009	Install Fire Extinguisher	07-Apr-2020 13:20:22	BTRUCK	I	DON	51.69
16-Mar-2020	1	666	16,713	431237	14-053-005	Install Markings - Vehicle - Decals	18-Mar-2020 11:17:50	BDECAL	C	DON	357.68
16-Mar-2020	1	666	16,713	431237	14-053-101	Install License Plate	09-Apr-2020 06:41:17	BTRUCK	I	DON	51.10
16-Mar-2020	1	666	16,713	431237	14-063-003	Install Transceiver - GPS Tracker	07-Apr-2020 12:44:16	BTRUCK	Q	DON	763.19
16-Mar-2020	1	666	16,713	431237	14-078-009	Install Mud Flaps and Hanger Brackets	07-Apr-2020 15:41:43	BTRUCK	I	DON	118.48
08-Apr-2020	1	666	16,714	435051	14-052-003	Install Radio Equipment	08-Apr-2020 16:06:51	ELEC01	Q	DON	871.56
09-Jun-2020	1	670	16,772	444479	06-100-007	Inspect In-Service Inspection	11-Jun-2020 10:31:34	MPNSHP	Q	DON	135.89
09-Jun-2020	1	670	16,772	444479	06-100-011	Inspect Annual Aerial/Boom Inspection	23-Jun-2020 13:35:03	MPNSHP	P	DON	0.00
09-Jun-2020	1	670	16,772	444479	14-100-007	Install In-Service Inspection	11-Jun-2020 10:32:04	MPNSHP	Q	DON	264.70
09-Jun-2020	1	670	16,772	444479	24-044-017	Repair Indicator/Sender - Fuel Level	12-Jun-2020 09:40:12	MPNSHP	I	DON	333.26
06-Jul-2020	11	725	18,023	453504	03-013-031	Replace Drain Valve - Air Tank	17-Aug-2020 07:30:01	SYRFLD	B	DON	34.56
06-Jul-2020	11	725	18,023	453504	03-065-004	Replace Cylinder	30-Jul-2020 11:36:23	SYRFLD	W	DON	0.00
06-Jul-2020	11	725	18,023	453504	03-065-007	Replace Hoses & Fittings	30-Jul-2020 11:38:00	SYRFLD	W	DON	399.04
06-Jul-2020	11	725	18,023	453504	03-065-010	Replace Gear Motor	17-Aug-2020 07:30:01	SYRFLD	W	DON	676.41
06-Jul-2020	11	725	18,023	453504	24-065-001	Repair Hydraulic Systems	17-Aug-2020 07:30:01	SYRFLD	W	DON	628.67
06-Jul-2020	11	725	18,023	453504	24-065-034	Repair Switch - Pressure	17-Aug-2020 07:30:01	SYRFLD	W	DON	362.86
06-Jul-2020	11	725	18,023	453504	24-079-011	Repair Stud, Ground	17-Aug-2020 07:30:01	SYRFLD	W	DON	34.56
06-Jul-2020	11	725	18,023	453504	24-518-005	Repair Grab Handle	17-Aug-2020 07:30:01	SYRFLD	W	DON	34.56
06-Jul-2020	11	725	18,023	453504	35-065-034	Diagnose Switch - Pressure	17-Aug-2020 07:30:01	SYRFLD	W	DON	138.23
09-Jul-2020	04	699	17,959	450086	24-044-025	Repair Fuel Cooler	13-Jul-2020 06:39:00	SYRFLD	B	DON	34.56
09-Jul-2020	04	699	17,959	450086	35-044-025	Diagnose Fuel Cooler	13-Jul-2020 06:00:00	SYRFLD	B	DON	34.56
27-Jul-2020	04	723	17,991	452795	01-013-001	Adjust Front Brakes & Drums	28-Jul-2020 08:44:23	SYRFLD	P	DON	14.40
27-Jul-2020	04	723	17,991	452795	01-013-002	Adjust Rear Brakes & Drums	28-Jul-2020 08:44:27	SYRFLD	P	DON	20.16
27-Jul-2020	04	723	17,991	452795	06-100-007	Inspect In-Service Inspection	28-Jul-2020 08:44:19	SYRFLD	P	DON	69.12
17-Aug-2020	C	798	18,068	456873	03-037	Replace Electrical - Modules/Relays	04-Sep-2020 10:52:56	SYRFLD	B	DON	103.67
17-Aug-2020	C	798	18,068	456873	24-112-006	Repair Outrigger Assembly	04-Sep-2020 10:52:56	SYRFLD	B	DON	103.67

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: G0837 - 2017 INTERNATIONAL HX620										
17-Aug-2020 C	798	18,068	456873	35-037	Diagnose Electrical - Modules/Relays	04-Sep-2020 10:52:56	SYRFLD	B	DON	103.67
17-Aug-2020 C	798	18,068	456873	35-112-006	Diagnose Outrigger Assembly	04-Sep-2020 10:52:56	SYRFLD	B	DON	69.12
04-Sep-2020 I	855		460084	13-053-012	Assemble Pad lock	08-Sep-2020 14:08:31	SYRFLD	A	DON	0.00
04-Sep-2020 I	855		460084	20-010-001	Tow All Axles	16-Sep-2020 13:49:18	SYRFLD	A	DON	22,385.88
04-Sep-2020 I	855		460084	OS-065	Out-Service Hydraulic Systems - Special Applic	02-Oct-2020 17:09:26	SYRFLD	A	DON	866.56
27-Jan-2021 I	990	21,514	484843	03-002-031	Replace Body Moldings - Exterior	19-Jan-2022 14:52:17	BVLOFC	A	DON	11,006.54
27-Jan-2021 I	990	21,514	484843	03-044-001	Replace Tank - Fuel, Liquid	19-Jan-2022 14:51:06	BVLOFC	A	DON	2,293.68
27-Jan-2021 I	990	21,514	484843	03-045-004	Replace Flywheel	19-Jan-2022 14:49:06	BVLOFC	A	DON	22,695.85
27-Jan-2021 I	990	21,514	484843	03-268-009	Replace Boom Structure	19-Jan-2022 14:48:52	BVLOFC	A	DON	964,779.70
29-Oct-2021 I	857		542886	03-002	Replace Cab & Sheet Metal	23-Feb-2022 15:33:36	MPNSHP	I	DON	475.14
29-Oct-2021 I	857		542886	03-002-035	Replace Windshield Wiper & Washer	03-Feb-2022 08:30:40	MPNSHP	I	DON	159.34
29-Oct-2021 I	857		542886	03-051-009	Replace Fire Extinguisher	23-Feb-2022 15:33:36	MPNSHP	I	DON	0.00
29-Oct-2021 I	857		542886	03-065-007	Replace Hoses & Fittings	23-Feb-2022 15:33:36	MPNSHP	I	DON	2,046.03
29-Oct-2021 I	857		542886	06-100-009	Inspect Safety Check	23-Feb-2022 15:09:42	MPNSHP	P	DON	1,324.18
29-Oct-2021 I	857		542886	06-100-011	Inspect Annual Aerial/Boom Inspection		MPNSHP	P	CAN	0.00
29-Oct-2021 I	857		542886	06-100-DOT	Inspect DOT Federal Inspection	23-Feb-2022 15:33:36	MPNSHP	I	DON	855.53
29-Oct-2021 I	857		542886	35-043-024	Diagnose Lines - DEF	02-Feb-2022 16:31:33	MPNSHP	I	DON	152.63
24-Jun-2022 0	1,093	24,412	598385	03-017-001	Replace Tire - Pneumatic	29-Aug-2022 15:47:03	MPNSHP	I	DON	3,045.27
24-Jun-2022 0	1,093	24,412	598385	03-043-029	Replace Sensor - DEF	17-Aug-2022 14:01:02	MPNSHP	I	DON	407.81
24-Jun-2022 0	1,093	24,412	598385	06-100-011	Inspect Annual Aerial/Boom Inspection	22-Sep-2022 10:07:18	MPNSHP	P	DON	0.00
24-Jun-2022 0	1,093	24,412	598385	06-100-DOT	Inspect DOT Federal Inspection	22-Sep-2022 10:07:03	MPNSHP	P	DON	152.62
24-Jun-2022 0	1,093	24,412	598385	06-268-009	Inspect Boom Structure	31-Aug-2022 09:25:59	MPNSHP	P	DON	306.91
24-Jun-2022 0	1,093	24,412	598385	24-002	Repair Cab & Sheet Metal	31-Aug-2022 09:30:32	MPNSHP	I	DON	698.48
24-Jun-2022 0	1,093	24,412	598385	24-065-004	Repair Cylinder	22-Sep-2022 10:09:34	MPNSHP	W	DON	1,872.73
24-Jun-2022 0	1,093	24,412	598385	24-065-007	Repair Hoses & Fittings	22-Sep-2022 10:07:36	MPNSHP	I	DON	15,566.54
06-Sep-2023 0	1,117		702713	03-032-001	Replace Battery	07-Sep-2023 10:27:00	BTRUCK	Z	DON	320.51
06-Sep-2023 0	1,117		702713	06-100-009	Inspect Safety Check		BTRUCK	P	CAN	0.00

Unit No: G0837 Count: 56 1,057,342.86