

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: G0390 - 2007 INTERNATIONAL 4300										
30-Oct-2009 01	0	25048		06-100-001	Inspect DO NOT USE - PMI Service	30-Oct-2009 09:25:47	MPNSHP	P	DON	441.00
18-Nov-2009 1	0	26843		03-051	Replace General Accessories	19-Nov-2009 15:00:00	MPNSHP	I	DON	75.73
18-Nov-2009 1	0	26843		06-100-001	Inspect DO NOT USE - PMI Service	19-Nov-2009 09:00:00	MPNSHP	P	DON	127.39
18-Nov-2009 1	0	26843		06-267-001	Inspect Boom Structure	25-Nov-2009 10:46:17	MPNSHP	P	DON	69.07
18-Nov-2009 1	0	26843		24-052-011	Repair Auxiliary Power	25-Nov-2009 10:47:38	BTRUCK	G	DON	10.39
15-Feb-2010 1	1,085	8,327	34398	03-002-024	Replace Glass / Windshield	19-Feb-2010 14:00:28	MPNSHP	B	DON	431.45
26-Apr-2010 0	1,085	8,327	39546	21-517	Fabricate Safety Equipment	29-Apr-2010 08:07:02	MPNSHP	R	DON	471.10
16-Jul-2010 13	1,085	8,327	46171	01-013-024	Adjust Air Tank (Pri / Sec / Wet)	26-Jul-2010 12:33:11	MPNSHP	I	DON	22.16
16-Jul-2010 13	1,085	8,327	46171	01-053-005	Adjust Markings - Vehicle - Decals	26-Jul-2010 11:24:13	MPNSHP	I	DON	18.02
16-Jul-2010 13	1,085	8,327	46171	01-059-002	Adjust Pintle Hook Assembly	24-Jul-2010 07:27:35	MPNSHP	I	DON	20.06
16-Jul-2010 13	1,085	8,327	46171	02-002-044	Clean Cab - Complete	02-Aug-2010 09:00:00	MPNSHP	Q	DON	181.11
16-Jul-2010 13	1,085	8,327	46171	03-002-035	Replace Windshield Wiper & Washer	28-Jul-2010 11:05:37	MPNSHP	I	DON	20.42
16-Jul-2010 13	1,085	8,327	46171	03-051-009	Replace Fire Extinguisher	24-Jul-2010 06:54:12	MPNSHP	I	DON	25.97
16-Jul-2010 13	1,085	8,327	46171	06-100-001	Inspect DO NOT USE - PMI Service	21-Sep-2010 11:27:41	MPNSHP	P	DON	516.47
16-Jul-2010 13	1,085	8,327	46171	06-100-002	Inspect DO NOT USE - DOT Federal Insp	24-Jul-2010 10:18:16	MPNSHP	Q	DON	19.31
16-Jul-2010 13	1,085	8,327	46171	06-268-008	Inspect Personnel Bucket	26-Jul-2010 13:04:50	MPNSHP	I	DON	31.67
16-Jul-2010 13	1,085	8,327	46171	14-051	Install General Accessories	28-Jul-2010 08:32:14	MPNSHP	I	DON	147.58
16-Jul-2010 13	1,085	8,327	46171	24-002-014	Repair Panel Deadeners	24-Jul-2010 08:43:34	MPNSHP	I	DON	41.70
16-Jul-2010 13	1,085	8,327	46171	24-052-009	Repair Speakers	24-Jul-2010 09:46:08	MPNSHP	I	DON	37.60
16-Jul-2010 13	1,085	8,327	46171	24-065	Repair Hydraulic Systems - Special Application:	26-Jul-2010 11:27:16	MPNSHP	I	DON	22.91
16-Jul-2010 13	1,085	8,327	46171	24-065-007	Repair Hoses & Fittings	24-Jul-2010 11:42:39	MPNSHP	I	DON	32.70
16-Jul-2010 13	1,085	8,327	46171	24-268-005	Repair Controls	28-Jul-2010 08:08:39	MPNSHP	I	DON	187.91
16-Jul-2010 13	1,085	8,327	46171	24-268-016	Repair Gearbox / Actuator Assembly	26-Jul-2010 07:36:51	MPNSHP	I	DON	77.71
16-Jul-2010 13	1,085	8,327	46171	24-705	Repair Visor	24-Jul-2010 08:22:13	MPNSHP	I	DON	32.84
01-Dec-2010 0	1,638	14,077	54835	07-268-009	Lubricate Boom Structure	02-Dec-2010 13:37:00	MPNSHP	P	DON	58.67
06-Dec-2010 1	1,640	14,087	55269	06-100-001	Inspect DO NOT USE - PMI Service	10-Dec-2010 15:04:34	MPNSHP	P	DON	849.63
15-Dec-2010 1	1,640	14,279	55485	24-042	Repair Cooling System	16-Dec-2010 06:08:12	BTRUCK	I	DON	230.19
15-Dec-2010 1	1,640	14,279	55485	24-015-005	Repair Power Steering Pump	16-Dec-2010 06:09:23	BTRUCK	I	DON	0.00
19-Apr-2011 0	1,885	14,796	63617	01-015	Adjust Steering	22-Apr-2011 05:56:31	MPNSHP	Q	DON	20.38

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: C0390 - 2007 INTERNATIONAL 4300										
19-Apr-2011 0	1,885	14,796	63617	06-100-009	Inspect Safety Check	22-Apr-2011 05:12:28	MPNSHP	P	DON	178.21
19-Apr-2011 0	1,885	14,796	63617	06-267-001	Inspect Boom Structure	22-Apr-2011 05:08:19	MPNSHP	P	DON	56.78
19-Apr-2011 0	1,885	14,796	63617	38-100-001	Service DO NOT USE - PMI Service	20-Apr-2011 08:50:31	MPNSHP	Q	DON	189.38
19-Apr-2011 0	1,885	14,796	63617	03-002-035	Replace Windshield Wiper & Washer	19-Apr-2011 16:25:36	MPNSHP	Q	DON	16.77
19-Apr-2011 0	1,885	14,796	63617	03-051-009	Replace Fire Extinguisher	19-Apr-2011 16:30:52	MPNSHP	Q	DON	14.24
19-Apr-2011 0	1,885	14,796	63617	24-034-014	Repair Auxiliary Work / Flood Light	20-Apr-2011 06:58:20	MPNSHP	Q	DON	99.00
19-Apr-2011 0	1,885	14,796	63617	07-010	Lubricate Chassis Group	19-Apr-2011 15:00:00	MPNSHP	Q	DON	36.15
19-Apr-2011 0	1,885	14,796	63617	03-053-005	Replace Markings - Vehicle - Decals	19-Apr-2011 16:13:48	MPNSHP	Q	DON	18.15
19-Apr-2011 0	1,885	14,796	63617	24-059-002	Repair Pintle Hook Assembly	20-Apr-2011 09:00:00	MPNSHP	Q	DON	91.43
19-Apr-2011 0	1,885	14,796	63617	14-002-011	Install Cab Accessories - Interior	22-Apr-2011 05:18:40	MPNSHP	Q	DON	14.91
19-Apr-2011 0	1,885	14,796	63617	24-044-011	Repair Speed Control System	20-Apr-2011 13:13:14	MPNSHP	Q	DON	20.65
19-Apr-2011 0	1,885	14,796	63617	24-268-009	Repair Boom Structure	21-Apr-2011 09:00:00	MPNSHP	E	DON	169.26
19-Apr-2011 0	1,885	14,796	63617	24-518-001	Repair Steps	21-Apr-2011 11:41:46	MPNSHP	E	DON	40.93
19-Apr-2011 0	1,885	14,796	63617	03-042-012	Replace Clamps and Hoses	20-Apr-2011 15:00:00	MPNSHP	Q	DON	81.23
19-Apr-2011 0	1,885	14,796	63617	01-041-008	Adjust Hose Air Intake	20-Apr-2011 15:09:14	MPNSHP	Q	DON	30.89
19-Apr-2011 0	1,885	14,796	63617	24-033	Repair Ignition System	22-Apr-2011 05:17:58	MPNSHP	Q	DON	137.74
19-Apr-2011 0	1,885	14,796	63617	14-065-007	Install Hoses & Fittings	20-Apr-2011 10:49:38	MPNSHP	Q	DON	50.48
19-Apr-2011 0	1,885	14,796	63617	14-051	Install General Accessories	04-May-2011 06:43:53	MPNSHP	Q	DON	58.06
19-Apr-2011 0	1,885	14,796	63617	02-002-044	Clean Cab - Complete	26-Apr-2011 15:00:00	MPNSHP	P	DON	239.93
28-Jun-2011 1	1,896	15,114	68264	06-100-002	Inspect DO NOT USE - DOT Federal Insp	28-Jun-2011 14:41:40	MPNSHP	P	DON	17.74
28-Jun-2011 1	1,896	15,114	68264	06-100-009	Inspect Safety Check	20-Jul-2011 15:36:56	MPNSHP	P	DON	54.20
28-Jun-2011 1	1,896	15,114	68264	14-002	Install Cab & Sheet Metal	29-Jun-2011 09:00:00	MPNSHP	I	DON	80.06
28-Jun-2011 1	1,896	15,114	68264	06-100-011	Inspect Annual Aerial/Boom Inspection	29-Jun-2011 14:50:43	MPNSHP	Q	DON	99.21
14-Oct-2011 0	1,896	18,074	74675	24-045	Repair Power Plant	01-Nov-2011 06:04:43	BTRUCK	I	DON	497.45
07-Nov-2011 1	18,074	18,074	76067	03-027-033	Replace Range Selector Or Manual Linkage	07-Nov-2011 14:30:53	MPNSHP	I	DON	1.96
07-Nov-2011 1	18,074	18,074	76067	06-100-009	Inspect Safety Check	21-Nov-2011 13:07:54	MPNSHP	I	DON	23.55
07-Nov-2011 1	18,074	18,074	76067	03-027-038	Replace Electronic Controls, Transmission, Aut	07-Nov-2011 14:43:56	MPNSHP	O	DON	7.03
07-Nov-2011 1	18,074	18,074	76067	02-002-044	Clean Cab - Complete	08-Nov-2011 15:00:00	MPNSHP	P	DON	219.08
11-Jan-2012 0	2,175	19,964	80858	24-267-011	Repair Auger	11-Jan-2012 16:00:00	SYRCNY	B	DON	83.94

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: G0390 - 2007 INTERNATIONAL 4300										
11-Jan-2012 0:	2,175	19,964	80858	24-268-015	Repair Shields and Guards	11-Jan-2012 16:00:00	SYRCNY	B	DON	27.98
12-Jan-2012 0:			79523	06-100-001	Inspect DO NOT USE - PMI Service	12-Jan-2012 16:00:00	HARRIS	P	DON	97.93
17-Jan-2012 1:			80844	03-044-002	Replace Filters	30-Jan-2012 12:50:08	SYRCNY	B	DON	334.70
17-Jan-2012 1:			80844	03-044-003	Replace Fuel Pump	30-Jan-2012 12:43:45	SYRCNY	B	DON	2,021.16
17-Jan-2012 1:			80844	07-010	Lubricate Chassis Group	30-Jan-2012 12:48:55	SYRCNY	P	DON	82.30
21-Feb-2012 1:			83481	24-044-004	Repair Injectors - Mechanical	09-Mar-2012 10:14:01	SYRCNY	B	DON	2,048.86
22-Feb-2012 0:			82863	26-026-016	Weld Gear Shifter & Linkage	22-Feb-2012 17:00:00	SYRCNY	B	DON	91.58
16-Apr-2012 1:	20,932		86980	06-100-011	Inspect Annual Aerial/Boom Inspection	16-Apr-2012 11:09:02	MPNSHP	P	DON	1,173.29
20-Jun-2012 1:	20,932		90481	06-100-DOT	Inspect DOT Federal Inspection	25-Jul-2012 14:32:04	SYRCNY	P	DON	0.00
20-Jun-2012 1:	20,932		90481	06-100-PMB	Inspect B PMI	18-Jul-2012 14:30:21	SYRCNY	J	DON	378.93
07-Nov-2012 1:	20,932		100576	03-017-001	Replace Tire - Pneumatic	07-Nov-2012 10:56:57	SYRCNY	E	DON	0.00
12-Nov-2012 1:	20,932		100657	03-002-024	Replace Glass / Windshield	12-Nov-2012 15:11:44	SYRCNY	E	DON	341.75
11-Feb-2013 1:	20,932		107374	14-052-003	Install Radio Equipment	11-Feb-2013 11:45:10	BBODY	C	DON	-86.22
22-Mar-2013 0:	2,683		28,883	03-098	Replace Valves & Controls - Bulk Product Trans	22-Mar-2013 17:00:00	SYRCNY	I	DON	24.67
01-Apr-2013 1:	2,683		28,883	06-100-011	Inspect Annual Aerial/Boom Inspection	01-Apr-2013 17:00:00	MPNSHP	P	DON	1,282.24
28-Jun-2013 1:	2,683		28,883	06-100-DOT	Inspect DOT Federal Inspection	28-Jun-2013 17:00:00	SYRCNY	P	DON	1,349.77
19-Sep-2013 1:	2,683		28,883	03-017-001	Replace Tire - Pneumatic	19-Sep-2013 17:00:00	MPNSHP	I	DON	79.85
13-Nov-2013 1:	2,683		28,883	06-100-PMA	Inspect A PMI	14-Nov-2013 17:00:00	SYRCNY	P	DON	924.09
05-May-2014 (2,683		28,883	06-100-011	Inspect Annual Aerial/Boom Inspection	05-May-2014 10:59:36	MPNSHP	P	DON	0.00
21-May-2014 (2,683		28,883	06-100-PMA	Inspect A PMI	21-May-2014 10:00:00	MPNSHP	P	DON	75.94
21-May-2014 (2,683		28,883	06-100-010	Inspect Small Engine Powered Equipment	21-May-2014 10:15:29	MPNSHP	P	DON	1,281.82
29-Jul-2014 12	2,860		31,336	24-051	Repair General Accessories	29-Jul-2014 12:45:25	SYRCNY	B	DON	231.49
29-Jul-2014 12	2,860		31,336	03-017-001	Replace Tire - Pneumatic	04-Aug-2014 00:00:00	BTIRE	F	DON	1,122.30
13-Aug-2014 C	2,860		31,336	14-053-005	Install Markings - Vehicle - Decals	13-Aug-2014 06:42:37	SYRCNY	J	DON	4.43
14-Aug-2014 C	2,862		31,350	03-065-007	Replace Hoses & Fittings	14-Aug-2014 09:23:11	SYRCNY	B	DON	496.04
15-Aug-2014 1	2,862		31,350	03-065-032	Replace Seal / O-Ring General	15-Aug-2014 15:46:16	SYRCNY	I	DON	44.95
24-Mar-2015 0	2,862		31,350	06-100-011	Inspect Annual Aerial/Boom Inspection	01-Apr-2015 00:00:00	HARFLD	I	DON	1,323.57
10-Aug-2015 C	3,067		210777	06-100-DOT	Inspect DOT Federal Inspection	10-Aug-2015 11:00:00	MPNSHP	P	DON	66.14
20-Jan-2016 0:	3,067		230336	03-065-007	Replace Hoses & Fittings	22-Jan-2016 11:38:17	HARFLD	B	DON	325.81

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: G0390 - 2007 INTERNATIONAL 4300										
09-Mar-2016 1	3,242	34,546	236703	03-043-004	Replace Turbocharger	09-Mar-2016 00:00:00	HARFLD	B	DON	2,820.71
09-Mar-2016 1	3,242	34,546	236703	35-044-002	Diagnose Filters	10-Mar-2016 00:00:00	HARFLD	B	DON	176.59
09-Mar-2016 1	3,242	34,546	236703	35-040	Diagnose Engine / Motor Systems Group	10-Mar-2016 00:00:00	HARFLD	B	DON	342.84
01-May-2016 1	3,242	34,546	243015	06-100-011	Inspect Annual Aerial/Boom Inspection	06-May-2016 07:05:12	HARFLD	P	DON	510.97
05-Aug-2016 1			254660	03-063-003	Replace Transceiver - GPS Tracker	05-Aug-2016 16:49:52	MPNSHP	Q	DON	280.70
10-Aug-2016 1	3,242	34,546	255605	06-058-003	Inspect Hook	03-Oct-2016 06:10:32	HARFLD	I	DON	258.51
10-Aug-2016 1	3,242	34,546	255605	03-268-021	Replace Load Line	03-Oct-2016 10:46:10	HARFLD	E	DON	271.67
10-Aug-2016 1	3,242	34,546	255605	06-100-011	Inspect Annual Aerial/Boom Inspection	05-Oct-2016 04:31:09	MPNSHP	P	DON	31.86
10-Aug-2016 1	3,242	34,546	255605	06-100-DOT	Inspect DOT Federal Inspection	05-Oct-2016 04:32:25	MPNSHP	P	DON	31.86
10-Aug-2016 1	3,242	34,546	255605	06-100-PMA	Inspect A PMI	05-Oct-2016 04:32:52	MPNSHP	P	DON	355.43
10-Aug-2016 1	3,242	34,546	255605	06-100-PMB	Inspect B PMI	05-Oct-2016 04:32:57	MPNSHP	P	DON	63.71
15-Nov-2016 2	3,366	35,234	267176	03-065-004	Replace Cylinder	17-Nov-2016 07:19:29	HARFLD	E	DON	868.76
15-Nov-2016 2	3,366	35,234	267176	03-079	Replace Safety Devices	17-Nov-2016 07:19:41	HARFLD	E	DON	607.67
14-Feb-2017 0	3,366	35,234	280844	24-MSC	Repair Miscellaneous	14-Feb-2017 00:00:00	BVLOFC	J	DON	2,102.91
16-Feb-2017 0	3,366	35,234	280857	24-MSC	Repair Miscellaneous	16-Feb-2017 00:00:00	BVLOFC	J	DON	111.41
21-Feb-2017 0	3,366	35,234	280864	24-MSC	Repair Miscellaneous	21-Feb-2017 00:00:00	BVLOFC	J	DON	99.94
28-Mar-2017 0	3,366	35,234	283383	03-002-035	Replace Windshield Wiper & Washer	31-Mar-2017 09:14:58	HARFLD	B	DON	238.25
28-Apr-2017 0	3,366	35,234	288691	03-027-040	Replace Tube/Line	21-Jun-2017 07:56:21	HARFLD	B	DON	1,002.95
28-Apr-2017 0	3,366	35,234	288691	20-027-040	Tow Tube/Line	21-Jun-2017 07:52:12	HARFLD	B	DON	452.31
28-Apr-2017 0	3,366	35,234	288691	06-100-011	Inspect Annual Aerial/Boom Inspection	12-May-2017 07:47:21	HARFLD	P	DON	627.36
11-Aug-2017 0	3,366	35,234	300737	06-100-PMA	Inspect A PMI	05-Sep-2017 08:36:14	MPNSHP	P	DON	310.11
11-Aug-2017 0	3,366	35,234	300737	06-100-PMB	Inspect B PMI	05-Sep-2017 08:36:14	HARSHP	P	DON	48.80
11-Aug-2017 0	3,366	35,234	300737	06-100-DOT	Inspect DOT Federal Inspection	05-Sep-2017 08:33:50	HARSHP	P	DON	65.06
08-Jan-2018 0	3,366	35,234	320345	03-059-002	Replace Pintle Hook Assembly	20-Feb-2018 13:05:58	HARFLD	B	DON	104.67
17-Mar-2018 0	4,429		327681	06-100-PMA	Inspect A PMI	18-Mar-2018 18:01:05	HARFLD	P	DON	108.51
17-Mar-2018 0	4,429		327681	06-100-PMB	Inspect B PMI	18-Mar-2018 18:01:09	HARFLD	P	DON	62.75
11-Jun-2018 0	4,429	42,741	342085	03-017-001	Replace Tire - Pneumatic	11-Jun-2018 08:36:00	BTIRE	F	DON	2,557.32
11-Aug-2018 0	4,429	42,741	347838	06-100-PMA	Inspect A PMI	08-Dec-2018 11:21:48	HARFLD	P	DON	204.28
11-Aug-2018 0	4,429	42,741	347838	03-044-003	Replace Fuel Pump	08-Dec-2018 11:21:48	HARFLD	I	DON	339.74

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: G0390 - 2007 INTERNATIONAL 4300										
11-Aug-2018 0	4,429	42,741	347838	03-043-007	Replace Exhaust Pipe/Elbow	08-Dec-2018 11:21:48	HARFLD	I	DON	2,479.03
11-Aug-2018 0	4,429	42,741	347838	03-268-021	Replace Load Line	01-Dec-2018 05:13:48	HARFLD	E	DON	568.82
11-Aug-2018 0	4,429	42,741	347838	06-100-011	Inspect Annual Aerial/Boom Inspection	08-Dec-2018 11:21:48	HARFLD	P	DON	604.67
25-Feb-2019 0	4,429	42,741	374844	03-001-016	Replace Filter - Cab Ventilation	02-Mar-2019 17:46:39	HARFLD	I	DON	45.23
03-May-2019 1	4,429	42,741	384257	20-022	Tow Axles - Driven, Rear	29-Jun-2019 09:35:19	HARFLD	B	DON	354.24
03-May-2019 1	4,429	42,741	384257	03-032-001	Replace Battery	29-Jun-2019 09:35:19	HARFLD	N	DON	294.93
03-May-2019 1	4,429	42,741	384257	03-043-004	Replace Turbocharger	29-Jun-2019 09:35:19	HARFLD	B	DON	3,839.92
29-Jun-2019 0	4,684	44,702	392450	38-100-PMC	Service C PMI	11-Jul-2019 13:12:06	HARFLD	P	DON	3,895.78
29-Jun-2019 0	4,684	44,702	392450	24-063-003	Repair Transceiver - GPS Tracker	13-Jul-2019 16:18:38	HARFLD	Q	DON	0.00
29-Jun-2019 0	4,684	44,702	392450	06-100-DOT	Inspect DOT Federal Inspection	11-Jul-2019 13:11:58	HARFLD	P	DON	209.49
23-Jul-2019 11	4,701	45,133	395862	24-506-002	Repair Hydraulic Tank	14-Sep-2019 08:34:57	HARFLD	B	DON	277.48
11-Dec-2019 1	4,827	46,887	416410	24-014-005	Repair Battery Support / Battery Box	12-Dec-2019 10:15:27	WTNSHP	I	DON	68.78
11-Dec-2019 1	4,827	46,887	416410	24-519-002	Repair Rear Bumper	16-Dec-2019 10:01:42	WTNSHP	I	DON	70.60
11-Dec-2019 1	4,827	46,887	416410	38-065-001	Service Hydraulic Systems	12-Dec-2019 12:29:18	WTNSHP	P	DON	422.12
11-Dec-2019 1	4,827	46,887	416410	38-100-PMMA	Service A PMI	12-Dec-2019 11:01:40	WTNSHP	P	DON	127.32
11-Dec-2019 1	4,827	46,887	416410	03-013-024	Replace Air Tank (Pri / Sec / Wet)	17-Dec-2019 07:41:39	WTNSHP	I	DON	1,143.26
11-Dec-2019 1	4,827	46,887	416410	03-034-004	Replace Clearance & Marker Lamps	16-Dec-2019 07:57:12	WTNSHP	I	DON	150.88
11-Dec-2019 1	4,827	46,887	416410	03-018-003	Replace Wheels	27-Dec-2019 12:14:27	WTNSHP	I	DON	764.93
11-Dec-2019 1	4,827	46,887	416410	03-054-002	Replace Alarm - Reverse Signal	16-Dec-2019 12:42:37	WTNSHP	I	DON	119.74
11-Dec-2019 1	4,827	46,887	416410	21-002-041	Fabricate Guard - Overhead, Operator Protector	16-Dec-2019 11:05:16	WTNSHP	I	DON	36.04
11-Dec-2019 1	4,827	46,887	416410	06-100-PMMA	Inspect A PMI	08-Jan-2020 06:56:52	MPNSHP	P	DON	0.00
11-Dec-2019 1	4,827	46,887	416410	24-002-010	Repair Mirrors	16-Dec-2019 12:49:35	WTNSHP	I	DON	54.45
11-Dec-2019 1	4,827	46,887	416410	03-078-009	Replace Mud Flaps and Hanger Brackets	17-Dec-2019 11:07:15	WTNSHP	I	DON	37.11
11-Dec-2019 1	4,827	46,887	416410	02-002-044	Clean Cab - Complete	18-Dec-2019 13:30:03	WTNSHP	I	DON	87.81
11-Dec-2019 1	4,827	46,887	416410	03-051-009	Replace Fire Extinguisher	17-Dec-2019 14:32:58	WTNSHP	I	DON	61.57
11-Dec-2019 1	4,827	46,887	416410	03-002-035	Replace Windshield Wiper & Washer	18-Dec-2019 14:38:54	WTNSHP	I	DON	53.99
13-Jan-2020 1			420741	06-100-011	Inspect Annual Aerial/Boom Inspection	15-Jan-2020 05:11:55	HARFLD	P	DON	499.71
07-Feb-2020 1	4,840	47,088	425325	03-053-101	Replace License Plate	18-Feb-2020 07:17:25	HARSHP	N	DON	29.13
07-Feb-2020 1	4,840	47,088	425325	03-267-011	Replace Auger	18-Feb-2020 15:12:54	HARSHP	N	DON	28.41

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: G0390 - 2007 INTERNATIONAL 4300										
07-Feb-2020 1	4,840	47,088	425325	03-268-021	Replace Load Line	18-Feb-2020 07:17:03	HARFLD	N	DON	481.82
17-Mar-2020 0	4,874	47,388	431560	01-MSC	Adjust Miscellaneous	30-Mar-2020 06:41:21	HARFLD	B	DON	172.11
10-Apr-2020 1	4,892	47,480	435706	03-002-035	Replace Windshield Wiper & Washer	13-May-2020 06:51:46	HARFLD	P	DON	27.07
10-Apr-2020 1	4,892	47,480	435706	03-013-004	Replace Brake Chamber - Service	13-May-2020 06:51:46	HARFLD	B	DON	617.40
10-Apr-2020 1	4,892	47,480	435706	03-047-001	Replace Engine Filter Kits	13-May-2020 06:51:46	HARFLD	I	DON	166.67
10-Apr-2020 1	4,892	47,480	435706	03-052-003	Replace Radio Equipment	13-May-2020 06:51:46	HARFLD	B	DON	0.00
10-Apr-2020 1	4,892	47,480	435706	03-053-999	Replace Vehicle Fluids, Lubricants, Gases, & Pa	13-May-2020 06:51:46	HARFLD	I	DON	392.34
10-Apr-2020 1	4,892	47,480	435706	03-268-016	Replace Gearbox / Actuator Assembly	13-May-2020 06:51:46	HARFLD	B	DON	214.40
10-Apr-2020 1	4,892	47,480	435706	06-100-PMB	Inspect B PMI	13-May-2020 06:51:46	HARFLD	P	DON	0.00
10-Apr-2020 1	4,892	47,480	435706	20-040	Tow Engine / Motor Systems Group	13-May-2020 06:51:46	HARFLD	B	DON	1,023.84
10-Apr-2020 1	4,892	47,480	435706	24-030	Repair Electrical Group	13-May-2020 06:51:46	HARFLD	B	DON	346.70
10-Apr-2020 1	4,892	47,480	435706	24-042	Repair Cooling System	13-May-2020 06:51:46	HARFLD	B	DON	1,246.84
10-Apr-2020 1	4,892	47,480	435706	35-042	Diagnose Cooling System	13-May-2020 06:51:46	HARFLD	B	DON	346.70
10-Apr-2020 1	4,892	47,480	435706	35-052-003	Diagnose Radio Equipment	13-May-2020 06:51:46	HARFLD	B	DON	34.56
10-Apr-2020 1	4,892	47,480	435706	38-100-PMB	Service B PMI	13-Apr-2020 16:17:31	HARFLD	B	DON	368.43
16-Jun-2020 1	4,914	47,954	446323	03-002-027	Replace Seat Frames & Springs	24-Jun-2020 14:36:22	HARFLD	I	DON	2,113.79
16-Jun-2020 1	4,914	47,954	446323	03-034-001	Replace Headlamps / Fog Lamps	24-Jun-2020 14:36:33	HARFLD	I	DON	103.67
16-Jun-2020 1	4,914	47,954	446323	95-100-DOT	Travel DOT Federal Inspection	18-Jun-2020 14:18:44	HARFLD	P	DON	69.12
16-Jun-2020 1	4,914	47,954	446323	03-045-028	Replace Valve Cover	24-Jun-2020 14:36:45	HARFLD	I	DON	34.56
16-Jun-2020 1	4,914	47,954	446323	06-100-DOT	Inspect DOT Federal Inspection	18-Jun-2020 14:21:08	HARFLD	P	DON	103.67
16-Jun-2020 1	4,914	47,954	446323	95-002-027	Travel Seat Frames & Springs	23-Jun-2020 05:58:06	HARFLD	I	DON	241.91
16-Jun-2020 1	4,914	47,954	446323	95-034-001	Travel Headlamps / Fog Lamps	24-Jun-2020 10:38:21	HARFLD	I	DON	0.00
28-Jun-2020 0	4,922	47,992	447866	03-052-003	Replace Radio Equipment	28-Jun-2020 09:52:29	ELEC02	Q	DON	544.56
10-Aug-2020 0	4,966	48,504	455628	03-065-013	Replace Pump - Gear Type	23-Aug-2020 05:25:43	HARFLD	B	DON	4,413.63
10-Aug-2020 0	4,966	48,504	455628	03-096-002	Replace Power Shaft Assembly - PTO	13-Aug-2020 06:06:08	HARFLD	B	DON	510.91
10-Aug-2020 0	4,966	48,504	455628	03-173-002	Replace Boom Assembly	31-Aug-2020 09:16:20	CTFLD	O	DON	138.23
10-Aug-2020 0	4,966	48,504	455628	20-027-038	Tow Electronic Controls, Transmission, Automa	23-Aug-2020 05:25:56	HARFLD	B	DON	708.48
10-Aug-2020 0	4,966	48,504	455628	24-027-038	Repair Electronic Controls, Transmission, Autor	13-Aug-2020 15:37:06	HARFLD	B	DON	2,138.95
10-Sep-2020 2	5,008	49,214	461192	24-173-002	Repair Boom Assembly	23-Sep-2020 11:53:49	CTFLD	B	DON	551.77

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: G0390 - 2007 INTERNATIONAL 4300										
21-Sep-2020 0	5,107	49,705	462930	03-268-009	Replace Boom Structure	22-Oct-2020 15:13:35	SYRFLD	B	DON	1,568.86
21-Sep-2020 0	5,107	49,705	462930	35-268-009	Diagnose Boom Structure	22-Oct-2020 15:13:35	SYRFLD	B	DON	69.12
21-Sep-2020 0	5,107	49,705	462930	03-268-003	Replace Hydraulics	22-Oct-2020 15:13:35	SYRFLD	B	DON	103.67
21-Sep-2020 0	5,107	49,705	462930	38-100-PMA	Service A PMI	21-Oct-2020 12:46:19	SYRFLD	P	DON	370.33
21-Sep-2020 0	5,107	49,705	462930	20-010-001	Tow All Axles	15-Oct-2020 06:40:51	SYRFLD	B	DON	454.97
21-Sep-2020 0	5,107	49,705	462930	35-040	Diagnose Engine / Motor Systems Group	22-Oct-2020 15:13:35	SYRFLD	B	DON	34.56
21-Sep-2020 0	5,107	49,705	462930	03-043-008	Replace EGR Valve / System	22-Oct-2020 15:13:35	SYRFLD	B	DON	749.51
21-Sep-2020 0	5,107	49,705	462930	06-100-PMA	Inspect A PMI	21-Oct-2020 12:46:11	SYRFLD	P	DON	34.56
21-Sep-2020 0	5,107	49,705	462930	03-044-018	Replace Fuel Hose / Line	22-Oct-2020 15:13:35	SYRFLD	B	DON	336.36
21-Sep-2020 0	5,107	49,705	462930	03-065-007	Replace Hoses & Fittings	22-Oct-2020 15:13:35	SYRFLD	B	DON	34.56
21-Sep-2020 0	5,107	49,705	462930	03-040	Replace Engine / Motor Systems Group	22-Oct-2020 15:13:35	SYRFLD	B	DON	460.64
04-Nov-2020 0	5,162	49,869	470907	38-053-025	Service Wheel Check	09-Nov-2020 05:42:32	CTFLD	P	DON	34.56
04-Nov-2020 0	5,162	49,869	470907	38-100-PMA	Service A PMI	09-Nov-2020 05:44:36	CTFLD	P	DON	0.00
04-Nov-2020 0	5,162	49,869	470907	14-053-025	Install Wheel Check	09-Nov-2020 05:36:32	CTFLD	I	DON	34.56
04-Nov-2020 0	5,162	49,869	470907	06-100-011	Inspect Annual Aerial/Boom Inspection	10-Nov-2020 08:27:44	CTFLD	P	DON	682.59
20-Jan-2021 0	5,167	49,969	484515	03-268-009	Replace Boom Structure	06-Apr-2021 08:35:43	CTFLD	E	DON	13,053.14
20-Jan-2021 0	5,167	49,969	484515	03-065-004	Replace Cylinder	06-Apr-2021 08:35:34	CTFLD	B	DON	4,203.21
20-Jan-2021 0	5,167	49,969	484515	95-002-004	Travel Hood	08-Apr-2021 08:46:11	CTFLD	B	DON	0.00
25-Apr-2021 0	5,167	49,969	504169	35-027-038	Diagnose Electronic Controls, Transmission, Au	03-May-2021 06:33:30	CTFLD	B	DON	189.74
09-Jun-2021 11	5,167	49,969	512592	06-100-DOT	Inspect DOT Federal Inspection	20-Jul-2021 08:07:49	SCHED	P	DON	174.92
09-Jun-2021 11	5,167	49,969	512592	06-100-DIE	Inspect Dielectric Inspection	23-Aug-2021 06:34:44	SCHED	P	DON	892.19
09-Jun-2021 11	5,167	49,969	512592	03-267-011	Replace Auger	22-Aug-2021 15:54:26	CTFLD	B	DON	457.06
09-Jun-2021 11	5,167	49,969	512592	24-268-031	Repair Pole Claws	22-Aug-2021 15:56:09	CTFLD	B	DON	189.74
06-Nov-2021 0	5,167	49,969	546613	01-042-014	Adjust Coolant Overflow Reservoir	15-Nov-2021 08:10:56	CTFLD	P	DON	189.74
17-Jan-2022 0	5,167	49,969	560430	03-063-003	Replace Transceiver - GPS Tracker	22-Jan-2022 08:23:54	SCHED	Q	DON	652.13
02-Mar-2022 0	5,167	49,969	572185	06-100-PMC	Inspect C PMI	05-Mar-2022 09:11:46	CTFLD	P	DON	0.00
02-Mar-2022 0	5,167	49,969	572185	35-040	Diagnose Engine / Motor Systems Group	16-Apr-2022 07:28:36	CTFLD	B	DON	1,423.02
02-Mar-2022 0	5,167	49,969	572185	35-049-001	Diagnose ECM Fault Code	20-Mar-2022 08:30:17	CTFLD	B	DON	569.21
02-Mar-2022 0	5,167	49,969	572185	06-100-PMB	Inspect B PMI	19-Jun-2022 09:56:30	CTFLD	P	DON	94.87

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: G0390 - 2007 INTERNATIONAL 4300										
02-Mar-2022 0	5,167	49,969	572185	20-040	Tow Engine / Motor Systems Group	06-Apr-2022 09:30:13	CTFLD	B	DON	487.99
02-Mar-2022 0	5,167	49,969	572185	24-040	Repair Engine / Motor Systems Group	20-Apr-2022 11:29:59	CTFLD	B	DON	8,204.65
02-Mar-2022 0	5,167	49,969	572185	38-100-PMC	Service C PMI	05-Mar-2022 09:11:46	CTFLD	P	DON	824.72
11-Aug-2022 0	5,274	52,357	611088	03-049-002	Replace ECM Module	20-Sep-2022 04:44:26	CTFLD	B	DON	2,893.32
11-Aug-2022 0	5,274	52,357	611088	06-100-011	Inspect Annual Aerial/Boom Inspection	26-Sep-2022 06:22:30	CTFLD	P	DON	1,195.71
11-Aug-2022 0	5,274	52,357	611088	06-100-DIE	Inspect Dielectric Inspection	26-Sep-2022 06:14:44	CTFLD	P	DON	0.00
11-Aug-2022 0	5,274	52,357	611088	35-044-007	Diagnose Throttle Controls	26-Sep-2022 06:15:27	CTFLD	I	DON	474.34
02-Sep-2022 0	5,276	52,353	620893	03-032-001	Replace Battery	02-Oct-2022 08:38:58	CTFLD	B	DON	1,820.55
02-Sep-2022 0	5,276	52,353	620893	20-010-001	Tow All Axles	19-Oct-2022 09:50:46	CTFLD	B	DON	803.74
02-Sep-2022 0	5,276	52,353	620893	24-045-013	Repair Oil Pan	31-Oct-2022 06:30:10	CTFLD	B	DON	1,694.62
02-Sep-2022 0	5,276	52,353	620893	38-100-PMA	Service A PMI	31-Oct-2022 06:30:14	CTFLD	P	DON	579.16
02-Sep-2022 0	5,276	52,353	620893	24-040	Repair Engine / Motor Systems Group	31-Oct-2022 06:30:20	CTFLD	B	DON	3,768.00
02-Sep-2022 0	5,276	52,353	620893	06-100-PMB	Inspect B PMI	13-Oct-2022 08:48:49	CTFLD	P	DON	0.00
04-Dec-2022 1			639376	20-040	Tow Engine / Motor Systems Group	03-Jan-2023 12:25:52	CTFLD	B	DON	803.74
01-Feb-2023 0			655029	25-065-004	Remove Cylinder	24-Feb-2023 06:13:46	CTFLD	B	DON	524.76
10-Feb-2023 0			653781	20-040	Tow Engine / Motor Systems Group	20-Feb-2023 05:09:06	CTFLD	B	DON	262.38
25-May-2023 1			677115	06-045-020	Inspect Engine Assembly	15-Aug-2023 15:31:01	BTRUCK	O	DON	532.36
25-May-2023 1			677115	24-045	Repair Power Plant	15-Aug-2023 15:31:04	BTRUCK	I	DON	7,889.77
25-May-2023 1			677115	25-063-003	Remove Transceiver - GPS Tracker	15-Aug-2023 10:35:18	BTRUCK	Z	DON	69.50
31-Aug-2023 C			701601	02-002	Clean Cab & Sheet Metal	27-Oct-2023 15:17:09	BSETUP	Z	DON	335.84
31-Aug-2023 C			701601	25-051	Remove General Accessories	25-Oct-2023 16:22:23	BSETUP	Z	DON	387.83