

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost	
Unit No: B2440 - 2013 F250 CREWCAB											
12-Aug-2013	C	62	0	126756	14-063-003	Install Transceiver - GPS Tracker	12-Aug-2013 11:19:05	BDETL	C	DON	247.30
12-Aug-2013	C	62	0	126756	14-002-059	Install Protector - Tail Gate	12-Aug-2013 17:34:30	BBODY	C	DON	51.64
12-Aug-2013	C	62	0	126756	14-034-006	Install Warning Lamps - Special Application	12-Aug-2013 15:27:12	BBODY	C	DON	467.44
12-Aug-2013	C	62	0	126756	14-053-005	Install Markings - Vehicle - Decals	12-Aug-2013 16:28:21	BBODY	C	DON	9.04
12-Aug-2013	C	62	0	126756	14-053-014	Install Floor Mats	12-Aug-2013 17:34:34	BBODY	C	DON	87.93
12-Aug-2013	C	62	0	126756	14-071-011	Install Scuff Liner / Bed Mat	12-Aug-2013 08:00:00	BBODY	C	DON	93.07
12-Aug-2013	C	62	0	126756	14-078-012	Install Tie-Down - Tarpaulin	12-Aug-2013 17:34:44	BBODY	C	DON	0.00
12-Aug-2013	C	62	0	126756	14-079-002	Install Headache Rack	12-Aug-2013 09:00:00	BBODY	C	DON	267.58
12-Aug-2013	C	62	0	126756	14-079-003	Install Strap, Anti-Static		BBODY	C	CAN	0.00
12-Aug-2013	C	62	0	126756	14-510-002	Install Tool Box	12-Aug-2013 09:10:00	BBODY	C	DON	305.69
12-Aug-2013	C	62	0	126756	14-517	Install Safety Equipment	12-Aug-2013 16:11:12	BBODY	C	DON	143.73
12-Aug-2013	C	62	0	126756	14-002-003	Install Running Boards / Step Tubes	12-Aug-2013 17:59:32	BBODY	C	DON	368.80
12-Aug-2013	C	62	0	126756	14-052-014	Install Cellular Telephone Accessories	12-Aug-2013 15:57:14	BBODY	C	DON	71.82
12-Aug-2013	C	62	0	126756	06-100-DOT	Inspect DOT Federal Inspection	13-Aug-2013 10:21:13	BTRUCK	P	DON	44.36
12-Aug-2013	C	62	0	126756	14-052-003	Install Radio Equipment	12-Aug-2013 13:57:19	BDETL	C	DON	1,077.43
12-Aug-2013	C	62	0	126756	14-052-011	Install Auxiliary Power	12-Aug-2013 11:03:01	BDETL	C	DON	164.81
12-Aug-2013	C	62	0	126756	14-052-015	Install Power Inverter/Converter	19-Aug-2013 14:23:57	BBODY	C	DON	87.65
12-Aug-2013	C	62	0	126756	14-002-063	Install Computer Stand / Dock	19-Aug-2013 14:51:37	BBODY	C	DON	346.15
25-Nov-2013	I	9,561	0	137936	06-100-PMB	Inspect B PMI	25-Nov-2013 12:50:56	BTRUCK	P	DON	30.15
25-Nov-2013	I	9,561	0	137936	38-045	Service Power Plant	25-Nov-2013 13:10:51	BTRUCK	P	DON	39.86
14-Dec-2013	I	9,561	0	140144	14-510-002	Install Tool Box	14-Dec-2013 12:08:59	BBODY	C	DON	495.31
06-Jan-2014	O	9,561	0	142053	38-052-003	Service Radio Equipment	06-Jan-2014 09:17:01	BBODY	O	DON	11.22
24-Jan-2014	I	13,840	0	144390	06-100-PMA	Inspect A PMI	31-Jan-2014 15:02:19	BTRUCK	P	DON	41.39
01-May-2014	I	17,625	0	156122	06-100-PMB	Inspect B PMI	01-May-2014 08:39:08	BTRUCK	P	DON	21.75
01-May-2014	I	17,625	0	156122	38-045	Service Power Plant	01-May-2014 09:17:57	BTRUCK	P	DON	51.24
01-May-2014	I	17,625	0	156122	06-100-DOT	Inspect DOT Federal Inspection	01-May-2014 10:07:38	BTRUCK	P	DON	27.45
24-Jun-2014	O	22,271	0	169982	06-100-PMA	Inspect A PMI	25-Jun-2014 17:00:00	BVLOFC	P	DON	42.69
04-Sep-2014	O	26,793	0	171287	06-100-PMB	Inspect B PMI	04-Sep-2014 09:18:50	BTRUCK	P	DON	13.92
04-Sep-2014	O	26,793	0	171287	38-045	Service Power Plant	04-Sep-2014 08:53:38	BTRUCK	P	DON	43.24

Unit Job History

Michels Corporation

Report Printed: 12-Dec-2023 12:03:45 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2440 - 2013 F250 CREWCAB										
04-Sep-2014 0	26,793	0	171287	31-017-001	Rotate Tire - Pneumatic	04-Sep-2014 09:57:21	BTRUCK	I	DON	21.28
23-Dec-2014 0	33,330		185574	03-002-035	Replace Windshield Wiper & Washer	23-Dec-2014 13:25:02	BTRUCK	O	DON	21.25
23-Dec-2014 0	33,330		185574	03-034-002	Replace Stop, Tail, Turn & License	23-Dec-2014 07:10:49	BTRUCK	I	DON	28.61
23-Dec-2014 0	33,330		185574	03-034-014	Replace Auxiliary Work / Flood Light	23-Dec-2014 07:04:52	BTRUCK	I	DON	33.18
23-Dec-2014 0	33,330		185574	06-100-DOT	Inspect DOT Federal Inspection	23-Dec-2014 07:27:51	BTRUCK	P	DON	9.41
23-Dec-2014 0	33,330		185574	06-100-PMB	Inspect B PMI	23-Dec-2014 06:53:11	BTRUCK	P	DON	10.05
23-Dec-2014 0	33,330		185574	38-045	Service Power Plant	23-Dec-2014 08:10:36	BTRUCK	P	DON	54.37
20-Mar-2015 0	36,338		195288	03-017-001	Replace Tire - Pneumatic		BTRUCK	O	CAN	0.00
20-Mar-2015 0	36,338		195288	06-100-PMB	Inspect B PMI	23-Mar-2015 10:32:50	BTRUCK	P	DON	9.80
20-Mar-2015 0	36,338		195288	38-045	Service Power Plant	23-Mar-2015 10:15:06	BTRUCK	P	DON	92.51
20-Mar-2015 0	36,338		195288	03-032-001	Replace Battery	23-Mar-2015 11:01:29	BTRUCK	O	DON	98.29
29-Jun-2015 1	45,390		206115	06-100-PMA	Inspect A PMI	29-Jun-2015 15:00:19	HARFLD	P	DON	34.46
15-Jul-2015 09	45,390		207745	14-002-063	Install Computer Stand / Dock	17-Sep-2015 15:40:08	HARSHP	O	DON	137.85
20-Jul-2015 09	45,390		216400	03-017-001	Replace Tire - Pneumatic	20-Jul-2015 09:53:22	BTIRE	N	DON	937.80
09-Nov-2015 1	57,020		221340	24-002	Repair Cab & Sheet Metal	09-Nov-2015 13:25:15	BVLOFC	A	DON	6,398.97
07-Jan-2016 1	64,442		228668	03-013-001	Replace Front Brakes & Drums	13-Jan-2016 10:33:41	BVLOFC	O	DON	443.37
07-Jan-2016 1	64,442		228668	03-013-002	Replace Rear Brakes & Drums	13-Jan-2016 10:35:07	BVLOFC	O	DON	489.41
07-Jan-2016 1	64,442		228668	24-034-003	Repair Signal, Parking, Backup Lamps	13-Jan-2016 10:37:22	BVLOFC	I	DON	7.94
07-Jan-2016 1	64,442		228668	38-027-001	Service Case Assembly - Automatic Transmissic	07-Jan-2016 10:31:40	BVLOFC	P	DON	151.19
20-Jan-2016 0	67,500		229830	06-100-DOT	Inspect DOT Federal Inspection	21-Jan-2016 13:10:51	BTRUCK	P	DON	25.67
20-Jan-2016 0	67,500		229830	06-100-PMB	Inspect B PMI	21-Jan-2016 08:31:07	BTRUCK	P	DON	55.76
20-Jan-2016 0	67,500		229830	14-016-005	Install Chassis Spring - Rear	21-Jan-2016 12:00:54	BTRUCK	O	DON	415.23
20-Jan-2016 0	67,500		229830	14-051-009	Install Fire Extinguisher	21-Jan-2016 09:20:42	BTRUCK	I	DON	20.85
20-Jan-2016 0	67,500		229830	38-045	Service Power Plant	21-Jan-2016 09:13:45	BTRUCK	P	DON	53.91
10-Feb-2016 0	67,500		234906	03-054-002	Replace Alarm - Reverse Signal	10-Feb-2016 00:00:00	MPNFLD	E	DON	85.72
10-Feb-2016 0	67,500		234906	03-017-001	Replace Tire - Pneumatic	17-Feb-2016 13:30:56	BTIRE	N	DON	1,533.89
31-Mar-2016 0	67,500		239566	06-100-PMB	Inspect B PMI		BTRUCK	P	WR	11.34
31-Mar-2016 0	67,500		239566	38-045	Service Power Plant		BTRUCK	P	WR	246.33
19-May-2016 1	85,624		245137	06-100-PMA	Inspect A PMI	19-May-2016 10:39:44	BVLOFC	P	DON	127.86

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2440 - 2013 F250 CREWCAB										
03-Jan-2017 16	120,437		271635	03-016-003	Replace Shock Absorber - Front	04-Jan-2017 12:02:38	BTRUCK	I	DON	140.38
03-Jan-2017 16	120,437		271635	03-016-006	Replace Shock Absorber - Rear	04-Jan-2017 13:11:57	BTRUCK	I	DON	147.10
03-Jan-2017 16	120,437		271635	06-100-DOT	Inspect DOT Federal Inspection	04-Jan-2017 15:15:20	BTRUCK	P	DON	41.60
03-Jan-2017 16	120,437		271635	06-100-PMB	Inspect B PMI	04-Jan-2017 09:12:39	BTRUCK	P	DON	22.67
03-Jan-2017 16	120,437		271635	14-016-005	Install Chassis Spring - Rear	04-Jan-2017 15:15:55	BTRUCK	O	DON	333.47
03-Jan-2017 16	120,437		271635	14-051-009	Install Fire Extinguisher	04-Jan-2017 15:45:59	BTRUCK	I	DON	50.87
03-Jan-2017 16	120,437		271635	14-054-002	Install Alarm - Reverse Signal	04-Jan-2017 11:27:49	BTRUCK	I	DON	20.75
03-Jan-2017 16	120,437		271635	24-034-010	Repair Socket - Trailer Light Cord	04-Jan-2017 10:50:32	BTRUCK	I	DON	52.83
03-Jan-2017 16	120,437		271635	38-045	Service Power Plant	04-Jan-2017 09:33:38	BTRUCK	P	DON	40.47
24-Jan-2017 16	120,437		280969	38-017-001	Service Tire - Pneumatic	24-Jan-2017 10:40:00	BTIRE	F	DON	273.08
04-Apr-2017 1	120,437		283862	03-017-001	Replace Tire - Pneumatic	04-Apr-2017 12:45:32	BTIRE	N	DON	915.73
21-Aug-2017 1	138,606		313056	06-100-PMA	Inspect A PMI	21-Aug-2017 15:05:00	BTRUCK	P	DON	69.85
29-Sep-2017 1	138,606		306990	02-013	Clean Brakes	01-Nov-2017 11:21:58	BVLOFC	O	DON	328.20
29-Sep-2017 1	138,606		306990	03-013-001	Replace Front Brakes & Drums	01-Nov-2017 11:26:17	BVLOFC	O	DON	1,405.17
29-Sep-2017 1	138,606		306990	03-018-001	Replace Front Axle Hubs & Bearings	01-Nov-2017 11:26:26	BVLOFC	O	DON	0.00
29-Sep-2017 1	138,606		306990	03-032-002	Replace Starter	13-Oct-2017 11:05:20	BVLOFC	O	DON	384.04
29-Sep-2017 1	138,606		306990	03-033-003	Replace Spark Plugs	01-Nov-2017 11:26:22	BVLOFC	I	DON	1,191.02
29-Sep-2017 1	138,606		306990	03-043-002	Replace Exhaust Manifold	01-Nov-2017 11:26:32	BVLOFC	O	DON	752.10
29-Sep-2017 1	138,606		306990	38-020	Service Drivetrain Group	01-Nov-2017 11:20:26	BVLOFC	P	DON	116.18
01-Dec-2017 0	138,607		314352	03-013-001	Replace Front Brakes & Drums	01-Dec-2017 07:42:09	BVLOFC	O	DON	524.33
01-Dec-2017 0	138,607		314352	03-018-001	Replace Front Axle Hubs & Bearings	01-Dec-2017 07:37:42	BVLOFC	O	DON	591.26
01-Dec-2017 0	138,607		314352	03-033-003	Replace Spark Plugs	01-Dec-2017 07:35:42	BVLOFC	O	DON	809.75
01-Dec-2017 0	138,607		314352	03-043-002	Replace Exhaust Manifold	01-Dec-2017 07:28:00	BVLOFC	O	DON	631.90
01-Dec-2017 0	138,607		314352	03-044-020	Replace Vapor Cannister	01-Dec-2017 07:26:08	BVLOFC	B	DON	187.91
01-Dec-2017 0	138,607		314352	38-020	Service Drivetrain Group	01-Dec-2017 07:40:12	BVLOFC	P	DON	341.23
12-Dec-2017 1	144,188		323795	03-032-001	Replace Battery	12-Dec-2017 11:20:00	BVLOFC	N	DON	202.80
12-Dec-2017 1	144,188		323795	06-100-PMA	Inspect A PMI	12-Dec-2017 11:18:00	BVLOFC	P	DON	57.87
02-Jan-2018 05	144,188		317738	06-100-DOT	Inspect DOT Federal Inspection	04-Jan-2018 10:46:10	BTRUCK	P	DON	76.16
02-Jan-2018 05	144,188		317738	03-034-004	Replace Clearance & Marker Lamps	04-Jan-2018 11:00:03	BTRUCK	I	DON	7.73

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2440 - 2013 F250 CREWCAB										
02-Jan-2018 05	144,188		317738	03-051-009	Replace Fire Extinguisher	04-Jan-2018 16:46:15	BTRUCK	I	DON	32.93
02-Jan-2018 05	144,188		317738	24-017-001	Repair Tire - Pneumatic	04-Jan-2018 17:00:30	BTRUCK	I	DON	35.64
02-Jan-2018 05	144,188		317738	03-022-002	Replace Shaft - Rear Axle	04-Jan-2018 15:37:19	BTRUCK	I	DON	44.64
02-Jan-2018 05	144,188		317738	03-015-004	Replace Steering Linkage	04-Jan-2018 16:38:15	BTRUCK	I	DON	297.56
02-Jan-2018 05	144,188		317738	03-013-002	Replace Rear Brakes & Drums	04-Jan-2018 14:17:06	BTRUCK	I	DON	481.58
02-Jan-2018 05	144,188		317738	31-017-001	Rotate Tire - Pneumatic	04-Jan-2018 12:00:15	BTRUCK	I	DON	33.50
16-Mar-2018 0	147,658		327567	35-045-020	Diagnose Engine Assembly	19-Jul-2018 11:51:59	BVLOFC	B	DON	436.34
26-Mar-2018 0	147,661		328699	01-015-004	Adjust Steering Linkage	09-Apr-2018 07:58:04	BTRUCK	I	DON	38.98
26-Mar-2018 0	147,661		328699	02-002	Clean Cab & Sheet Metal	24-Apr-2018 12:47:40	BSETUP	I	DON	549.25
26-Mar-2018 0	147,661		328699	03-002-035	Replace Windshield Wiper & Washer	06-Apr-2018 07:28:19	BTRUCK	I	DON	73.66
26-Mar-2018 0	147,661		328699	03-017-001	Replace Tire - Pneumatic	05-Apr-2018 08:33:10	BTIRE	I	DON	20.60
26-Mar-2018 0	147,661		328699	03-018-001	Replace Front Axle Hubs & Bearings	06-Apr-2018 11:44:49	BTRUCK	I	DON	660.46
26-Mar-2018 0	147,661		328699	03-033-002	Replace Distributor / Coil Pack	05-Apr-2018 14:24:27	BTRUCK	I	DON	553.73
26-Mar-2018 0	147,661		328699	03-045-026	Replace Tensioner - Engine Belts	09-Apr-2018 10:17:35	BTRUCK	I	DON	148.44
26-Mar-2018 0	147,661		328699	06-100-009	Inspect Safety Check	05-Apr-2018 08:40:26	BTRUCK	I	DON	90.56
26-Mar-2018 0	147,661		328699	06-100-PMB	Inspect B PMI	05-Apr-2018 10:32:36	BTRUCK	P	DON	62.42
26-Mar-2018 0	147,661		328699	14-051-006	Install Safety Devices	09-Apr-2018 10:22:39	BTRUCK	I	DON	20.77
26-Mar-2018 0	147,661		328699	24-002-027	Repair Seat Frames & Springs	06-Apr-2018 16:05:05	BTRUCK	I	DON	67.20
26-Mar-2018 0	147,661		328699	24-044-016	Repair Tank - Fuel Auxiliary	06-Apr-2018 14:46:44	BTRUCK	I	DON	86.20
26-Mar-2018 0	147,661		328699	35-045-008	Diagnose Camshaft - Accessory Drive & Valve	06-Apr-2018 14:54:27	BTRUCK	I	DON	634.67
26-Mar-2018 0	147,661		328699	38-045	Service Power Plant	09-Apr-2018 06:48:02	BTRUCK	P	DON	63.18
20-Jul-2018 14	150,948		344800	03-034-001	Replace Headlamps / Fog Lamps	26-Jul-2018 12:52:04	BTRUCK	I	DON	402.60
20-Jul-2018 14	150,948		344800	06-100-009	Inspect Safety Check	23-Jul-2018 06:47:14	BTRUCK	I	DON	106.83
20-Jul-2018 14	150,948		344800	03-043-002	Replace Exhaust Manifold	25-Jul-2018 17:04:50	BTRUCK	I	DON	717.71
20-Jul-2018 14	150,948		344800	06-100-PMB	Inspect B PMI	23-Jul-2018 08:02:05	BTRUCK	P	DON	41.66
20-Jul-2018 14	150,948		344800	24-002-057	Repair Occupant Safety Devices	23-Jul-2018 09:46:39	BTRUCK	I	DON	179.14
20-Jul-2018 14	150,948		344800	24-021-102	Repair Shaft	24-Jul-2018 12:50:27	BTRUCK	I	DON	395.07
20-Jul-2018 14	150,948		344800	38-045	Service Power Plant	26-Jul-2018 06:31:56	BTRUCK	P	DON	32.67
25-Aug-2018 C	154,316		349766	02-002	Clean Cab & Sheet Metal	27-Aug-2018 16:57:49	BSETUP	N	DON	54.47

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2440 - 2013 F250 CREWCAB										
25-Aug-2018 C	154,316		349766	06-100-PMB	Inspect B PMI	25-Aug-2018 10:15:19	BTRUCK	P	DON	46.61
25-Aug-2018 C	154,316		349766	38-045	Service Power Plant	27-Aug-2018 07:12:03	BTRUCK	P	DON	68.13
25-Aug-2018 C	154,316		349766	24-044-016	Repair Tank - Fuel Auxiliary	27-Aug-2018 08:45:27	BTRUCK	I	DON	649.12
25-Aug-2018 C	154,316		349766	03-021-108	Replace Pinion Seal	27-Aug-2018 08:20:19	BTRUCK	I	DON	44.96
29-Aug-2018 C	154,383		350275	24-045-021	Repair Electronic Engine Controls	30-Aug-2018 11:28:08	BTRUCK	O	DON	776.52
22-Sep-2018 I	159,004		353496	06-100-PMB	Inspect B PMI	01-Oct-2018 07:44:18	BTRUCK	P	DON	57.79
22-Sep-2018 I	159,004		353496	38-045	Service Power Plant	01-Oct-2018 08:24:17	BTRUCK	P	DON	49.71
22-Sep-2018 I	159,004		353496	24-044-001	Repair Tank - Fuel, Liquid	01-Oct-2018 09:52:50	BTRUCK	O	DON	171.57
22-Sep-2018 I	159,004		353496	24-017-001	Repair Tire - Pneumatic	22-Sep-2018 16:37:00	BTIRE	B	DON	300.23
19-Oct-2018 O	159,876		357929	24-017-001	Repair Tire - Pneumatic	19-Oct-2018 07:15:00	BTIRE	B	DON	332.29
21-Nov-2018 C	161,917		361631	03-017-001	Replace Tire - Pneumatic	21-Nov-2018 08:21:00	BTIRE	B	DON	683.22
07-Dec-2018 I	162,558		364130	03-017-001	Replace Tire - Pneumatic	07-Dec-2018 13:29:00	BTIRE	B	DON	773.43
02-Jan-2019 O	162,558		366444	03-017-001	Replace Tire - Pneumatic	02-Jan-2019 09:38:37	BTIRE	B	DON	590.38
25-Jan-2019 O	166,610		370021	24-017-001	Repair Tire - Pneumatic	25-Jan-2019 06:06:00	BTIRE	B	DON	36.60
29-Jan-2019 O	167,017		370376	14-051-009	Install Fire Extinguisher	06-Feb-2019 14:11:37	BTRUCK	I	DON	32.00
29-Jan-2019 O	167,017		370376	24-049-004	Repair ECM Sensor	06-Feb-2019 14:53:17	BTRUCK	I	DON	22.86
29-Jan-2019 O	167,017		370376	03-002-035	Replace Windshield Wiper & Washer	06-Feb-2019 14:04:33	BTRUCK	I	DON	26.20
29-Jan-2019 O	167,017		370376	03-034-010	Replace Socket - Trailer Light Cord	04-Feb-2019 14:10:42	BTRUCK	I	DON	58.98
29-Jan-2019 O	167,017		370376	03-018-001	Replace Front Axle Hubs & Bearings	04-Feb-2019 10:52:45	BTRUCK	I	DON	353.14
29-Jan-2019 O	167,017		370376	03-053-016	Replace Cover - Seat	04-Feb-2019 16:00:54	BTRUCK	I	DON	179.44
29-Jan-2019 O	167,017		370376	06-100-PMB	Inspect B PMI	04-Feb-2019 09:13:51	BTRUCK	P	DON	103.82
29-Jan-2019 O	167,017		370376	24-034-003	Repair Signal, Parking, Backup Lamps	04-Feb-2019 14:43:53	BTRUCK	O	DON	18.21
29-Jan-2019 O	167,017		370376	24-043-001	Repair Emission Controls	05-Feb-2019 06:24:43	BTRUCK	O	DON	53.07
29-Jan-2019 O	167,017		370376	38-045	Service Power Plant	04-Feb-2019 13:10:27	BTRUCK	P	DON	89.27
29-Jan-2019 O	167,017		370376	24-013-032	Repair ABS - ECU	04-Feb-2019 12:00:10	BTRUCK	O	DON	89.38
29-Jan-2019 O	167,017		370376	06-100-DOT	Inspect DOT Federal Inspection	06-Feb-2019 16:02:42	BTRUCK	P	DON	38.09
29-Jan-2019 O	167,017		370376	24-043-007	Repair Exhaust Pipe/Elbow	06-Feb-2019 13:57:54	BTRUCK	O	DON	219.26
29-Jan-2019 O	167,017		370376	02-002	Clean Cab & Sheet Metal	08-Feb-2019 17:05:02	BSETUP	N	DON	550.98
08-May-2019 I	167,926		385043	06-100-009	Inspect Safety Check	09-May-2019 07:59:10	BTRUCK	P	DON	67.34

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2440 - 2013 F250 CREWCAB										
08-May-2019	167,926		385043	03-043-002	Replace Exhaust Manifold	09-May-2019 17:15:10	BTRUCK	I	DON	588.00
08-May-2019	167,926		385043	14-051-006	Install Safety Devices	10-May-2019 07:11:53	BTRUCK	I	DON	11.02
08-May-2019	167,926		385043	03-017-001	Replace Tire - Pneumatic	10-May-2019 07:01:39	BTRUCK	I	DON	935.90
08-May-2019	167,926		385043	03-002-035	Replace Windshield Wiper & Washer	09-May-2019 10:02:30	BTRUCK	I	DON	98.64
08-May-2019	167,926		385043	02-002	Clean Cab & Sheet Metal	20-May-2019 16:12:00	BSETUP	I	DON	294.72
08-May-2019	167,926		385043	11-510-002	Rebuild Tool Box	13-May-2019 08:12:40	BSETUP	I	DON	24.79
05-Jun-2019	167,926		388746	03-032-001	Replace Battery	05-Jun-2019 12:00:04	BTRUCK	I	DON	161.93
14-Jun-2019	168,548		390192	24-045-021	Repair Electronic Engine Controls	14-Jun-2019 10:32:45	BTRUCK	O	DON	11.02
14-Jun-2019	168,548		390192	03-042-006	Replace Thermostat	14-Jun-2019 17:14:34	BTRUCK	I	DON	231.01
14-Jun-2019	168,548		390192	24-017-010	Repair Sensor - Air Pressure	15-Jun-2019 10:19:12	BTRUCK	I	DON	0.00
14-Jun-2019	168,548		390192	03-024-005	Replace Universal Joint	15-Jun-2019 10:19:28	BTRUCK	I	DON	111.31
01-Aug-2019	173,011		396813	38-045	Service Power Plant	01-Aug-2019 10:47:14	BTRUCK	P	DON	47.54
01-Aug-2019	173,011		396813	06-100-PMB	Inspect B PMI	01-Aug-2019 10:34:20	BTRUCK	P	DON	91.61
01-Aug-2019	173,011		396813	03-002-035	Replace Windshield Wiper & Washer	01-Aug-2019 13:07:07	BTRUCK	I	DON	26.92
01-Aug-2019	173,011		396813	24-045-021	Repair Electronic Engine Controls	02-Aug-2019 06:53:02	BTRUCK	I	DON	229.88
01-Aug-2019	173,011		396813	31-017-001	Rotate Tire - Pneumatic	01-Aug-2019 14:22:47	BTRUCK	I	DON	41.52
01-Aug-2019	173,011		396813	03-021-109	Replace Universal Joint	01-Aug-2019 16:28:36	BTRUCK	I	DON	236.18
01-Aug-2019	173,011		396813	03-044-002	Replace Filters	01-Aug-2019 12:00:38	BTRUCK	I	DON	37.18
01-Aug-2019	173,011		396813	03-044-018	Replace Fuel Hose / Line	01-Aug-2019 12:59:09	BTRUCK	I	DON	171.75
01-Aug-2019	173,011		396813	03-079-007	Replace Sign, Safety	01-Aug-2019 10:59:14	BTRUCK	I	DON	27.69
05-Aug-2019	173,030		397206	02-002	Clean Cab & Sheet Metal	05-Aug-2019 15:26:32	BSETUP	N	DON	163.02
06-Dec-2019	177,250		415630	03-510-002	Replace Tool Box	10-Dec-2019 17:00:24	BSETUP	I	DON	178.35
06-Dec-2019	177,250		415630	03-052-014	Replace Cellular Telephone Accessories	10-Dec-2019 14:22:52	BSETUP	I	DON	0.00
06-Dec-2019	177,250		415630	02-002	Clean Cab & Sheet Metal	10-Dec-2019 11:59:53	BSETUP	N	DON	397.59
06-Dec-2019	177,250		415630	03-044-003	Replace Fuel Pump	10-Dec-2019 14:22:47	BSETUP	I	DON	4.29
20-Jan-2020	177,319		421884	03-002-035	Replace Windshield Wiper & Washer	21-Jan-2020 06:49:06	BTRUCK	I	DON	26.73
20-Jan-2020	177,319		421884	03-013-001	Replace Front Brakes & Drums	21-Jan-2020 06:43:33	BTRUCK	I	DON	150.39
20-Jan-2020	177,319		421884	03-022-008	Replace Pinion Seal	20-Jan-2020 16:02:17	BTRUCK	I	DON	79.10
20-Jan-2020	177,319		421884	03-034-002	Replace Stop, Tail, Turn & License	21-Jan-2020 06:58:12	BTRUCK	I	DON	63.17

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2440 - 2013 F250 CREWCAB										
20-Jan-2020 11	177,319		421884	06-100-DOT	Inspect DOT Federal Inspection	21-Jan-2020 08:22:55	BTRUCK	P	DON	46.48
20-Jan-2020 11	177,319		421884	06-100-PMB	Inspect B PMI	20-Jan-2020 13:49:18	BTRUCK	P	DON	47.10
20-Jan-2020 11	177,319		421884	14-051-009	Install Fire Extinguisher	21-Jan-2020 06:52:18	BTRUCK	I	DON	34.36
20-Jan-2020 11	177,319		421884	38-045	Service Power Plant	20-Jan-2020 14:39:10	BTRUCK	P	DON	56.28
16-Apr-2020 1	178,439		436387	06-100-PMA	Inspect A PMI		MISSHP	P	CAN	0.00
16-Apr-2020 1	178,439		436387	38-100-PMA	Service A PMI		MISSHP	P	CAN	0.00
01-May-2020 1	181,926		438946	24-017-001	Repair Tire - Pneumatic	01-May-2020 14:59:46	BTIRE	I	DON	7.11
01-May-2020 1	181,926		438946	24-034-003	Repair Signal, Parking, Backup Lamps	26-May-2020 15:43:45	BTRUCK	I	DON	52.80
01-May-2020 1	181,926		438946	06-017-001	Inspect Tire - Pneumatic	26-May-2020 15:17:28	BTRUCK	I	DON	130.42
01-May-2020 1	181,926		438946	06-100-009	Inspect Safety Check	05-Jun-2020 10:59:58	BTRUCK	P	DON	31.89
01-May-2020 1	181,926		438946	03-034-002	Replace Stop, Tail, Turn & License	12-Jun-2020 15:43:26	BTRUCK	I	DON	109.04
01-May-2020 1	181,926		438946	38-045	Service Power Plant	25-Jul-2020 07:04:17	BTRUCK	P	DON	63.37
01-May-2020 1	181,926		438946	06-100-PMB	Inspect B PMI	25-Jul-2020 06:15:56	BTRUCK	P	DON	47.45
01-May-2020 1	181,926		438946	03-002-035	Replace Windshield Wiper & Washer	25-Jul-2020 07:20:49	BTRUCK	N	DON	27.74
29-Jan-2021 11	184,930		485382	02-002	Clean Cab & Sheet Metal	09-Feb-2021 08:53:29	BSETUP	I	DON	702.19
29-Jan-2021 11	184,930		485382	03-002-035	Replace Windshield Wiper & Washer	29-Jan-2021 13:29:33	BTRUCK	I	DON	21.63
29-Jan-2021 11	184,930		485382	03-018-001	Replace Front Axle Hubs & Bearings	29-Jan-2021 15:15:30	BTRUCK	I	DON	536.63
29-Jan-2021 11	184,930		485382	03-044-002	Replace Filters	29-Jan-2021 14:08:37	BTRUCK	I	DON	38.48
29-Jan-2021 11	184,930		485382	06-100-DOT	Inspect DOT Federal Inspection	29-Jan-2021 16:28:21	BTRUCK	P	DON	72.02
29-Jan-2021 11	184,930		485382	06-100-PMB	Inspect B PMI	29-Jan-2021 12:40:24	BTRUCK	P	DON	36.54
29-Jan-2021 11	184,930		485382	14-051-009	Install Fire Extinguisher	29-Jan-2021 13:33:15	BTRUCK	Q	DON	36.02
29-Jan-2021 11	184,930		485382	24-079-002	Repair Headache Rack	09-Feb-2021 10:48:40	BSETUP	I	DON	99.57
29-Jan-2021 11	184,930		485382	38-045	Service Power Plant	29-Jan-2021 13:24:34	BTRUCK	P	DON	58.28
25-Mar-2021 0	184,985		496417	24-042-012	Repair Clamps and Hoses	26-Mar-2021 15:29:55	BTRUCK	I	DON	115.77
21-Jul-2021 11	187,345		519933	24-017-001	Repair Tire - Pneumatic	21-Jul-2021 12:43:22	BTRUCK	I	DON	8.42
09-Aug-2021 11	187,929		523827	24-032-002	Repair Starter	10-Aug-2021 08:36:23	BTRUCK	O	DON	71.35
25-Aug-2021 1	188,139		527489	03-063-003	Replace Transceiver - GPS Tracker	25-Aug-2021 17:02:03	ELEC03	Q	DON	417.64
04-Feb-2022 11	189,090		564198	03-002-035	Replace Windshield Wiper & Washer	04-Feb-2022 11:44:43	BTRUCK	I	DON	32.40
04-Feb-2022 11	189,090		564198	06-100-DOT	Inspect DOT Federal Inspection	04-Feb-2022 13:46:12	BTRUCK	P	DON	52.19

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2440 - 2013 F250 CREWCAB										
04-Feb-2022 1	189,090		564198	06-100-PMB	Inspect B PMI	04-Feb-2022 11:32:25	BTRUCK	P	DON	16.20
04-Feb-2022 1	189,090		564198	14-051-009	Install Fire Extinguisher	04-Feb-2022 11:34:21	BTRUCK	Q	DON	33.64
04-Feb-2022 1	189,090		564198	38-100-PMA	Service A PMI	04-Feb-2022 12:00:19	BTRUCK	P	DON	68.70
24-Feb-2022 0	189,900		569517	02-002	Clean Cab & Sheet Metal	28-Feb-2022 12:59:08	BSETUP	N	DON	396.89
24-Feb-2022 0	189,900		569517	12-002-003	Refinish Running Boards / Step Tubes	28-Feb-2022 14:07:32	BSETUP	I	DON	51.37
24-Feb-2022 0	189,900		569517	03-034-006	Replace Warning Lamps - Special Application	28-Feb-2022 14:34:12	BSETUP	N	DON	29.24
24-Feb-2022 0	189,900		569517	03-053-005	Replace Markings - Vehicle - Decals	28-Feb-2022 15:21:35	BSETUP	I	DON	53.38
04-Oct-2022 1	195,057		621532	03-016-003	Replace Shock Absorber - Front	06-Oct-2022 17:00:06	FKVSHP	I	DON	419.92
04-Oct-2022 1	195,057		621532	03-018-012	Replace Cap - Hub	21-Oct-2022 10:33:37	FKVSHP	I	DON	123.47
04-Oct-2022 1	195,057		621532	03-032-001	Replace Battery	05-Oct-2022 09:27:46	FKVSHP	I	DON	201.14
04-Oct-2022 1	195,057		621532	03-034-004	Replace Clearance & Marker Lamps	06-Oct-2022 10:42:51	FKVSHP	I	DON	86.35
04-Oct-2022 1	195,057		621532	06-100-PMA	Inspect A PMI	05-Oct-2022 08:52:44	FKVSHP	P	DON	0.00
04-Oct-2022 1	195,057		621532	06-100-PMB	Inspect B PMI	07-Oct-2022 07:19:54	FKVSHP	P	DON	0.00
04-Oct-2022 1	195,057		621532	24-002-018	Repair Cab Or Front Door Mechanism	07-Oct-2022 07:13:03	FKVSHP	I	DON	180.30
04-Oct-2022 1	195,057		621532	38-100-PMA	Service A PMI	05-Oct-2022 08:52:48	FKVSHP	P	DON	0.00
04-Oct-2022 1	195,057		621532	38-100-PMB	Service B PMI	05-Oct-2022 12:01:31	FKVSHP	P	DON	177.32
16-Nov-2022 1	195,213		633105	06-100-009	Inspect Safety Check	17-Nov-2022 07:22:38	BTRUCK	P	DON	54.46
16-Nov-2022 1	195,213		633105	24-034-004	Repair Clearance & Marker Lamps	17-Nov-2022 08:36:11	BTRUCK	I	DON	48.47
16-Nov-2022 1	195,213		633105	31-017-001	Rotate Tire - Pneumatic	17-Nov-2022 14:49:50	BTRUCK	P	DON	37.43
16-Nov-2022 1	195,213		633105	24-079-002	Repair Headache Rack	18-Nov-2022 08:45:27	BTRUCK	I	DON	89.81
16-Nov-2022 1	195,213		633105	24-519-002	Repair Rear Bumper	28-Nov-2022 10:41:09	BTRUCK	I	DON	21.53
16-Nov-2022 1	195,213		633105	03-017-001	Replace Tire - Pneumatic	18-Nov-2022 11:40:32	BTRUCK	I	DON	11.27
16-Nov-2022 1	195,213		633105	03-001-023	Replace Ductwork and Dash Louvres	17-Nov-2022 15:28:34	BTRUCK	I	DON	82.48
16-Nov-2022 1	195,213		633105	03-014-004	Replace Cab & Body Mountings	28-Nov-2022 10:08:29	BTRUCK	I	DON	149.43
16-Nov-2022 1	195,213		633105	03-015-004	Replace Steering Linkage	29-Nov-2022 13:23:30	BTRUCK	I	DON	517.31
16-Nov-2022 1	195,213		633105	03-024-005	Replace Universal Joint	18-Nov-2022 11:39:20	BTRUCK	I	DON	181.53
16-Nov-2022 1	195,213		633105	03-033-002	Replace Distributor / Coil Pack	17-Nov-2022 16:00:49	BTRUCK	I	DON	149.39
16-Nov-2022 1	195,213		633105	24-016-003	Repair Shock Absorber - Front	28-Nov-2022 11:28:44	BTRUCK	I	DON	31.36
16-Nov-2022 1	195,213		633105	24-049-001	Repair ECM Fault Code	28-Nov-2022 07:51:49	BTRUCK	I	DON	77.47

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2440 - 2013 F250 CREWCAB										
16-Nov-2022 1	195,213		633105	24-002-065	Repair Hood Latch	18-Nov-2022 17:01:28	BTRUCK	I	DON	44.37
16-Nov-2022 1	195,213		633105	24-013-034	Repair Parking Brake - Complete	17-Nov-2022 14:04:01	BTRUCK	I	DON	276.38
16-Nov-2022 1	195,213		633105	03-043-027	Replace Catalytic Converter	18-Nov-2022 14:30:06	BTRUCK	I	DON	1,675.78
16-Nov-2022 1	195,213		633105	03-044-018	Replace Fuel Hose / Line	18-Nov-2022 11:01:30	BTRUCK	I	DON	72.84
16-Nov-2022 1	195,213		633105	24-034-006	Repair Warning Lamps - Special Application	18-Nov-2022 10:04:49	BTRUCK	I	DON	52.31
16-Nov-2022 1	195,213		633105	14-051-009	Install Fire Extinguisher	29-Nov-2022 14:52:17	BTRUCK	Q	DON	145.41
16-Nov-2022 1	195,213		633105	06-100-DOT	Inspect DOT Federal Inspection	13-Dec-2022 13:43:04	BTRUCK	P	DON	13.41
16-Nov-2022 1	195,213		633105	06-100-PMB	Inspect B PMI	16-Nov-2022 17:01:30	BTRUCK	P	DON	28.59
31-Jan-2023 11	195,228		649422	02-002	Clean Cab & Sheet Metal	01-Feb-2023 15:28:53	BSETUP	I	DON	526.41
11-Aug-2023 1	202,099		696165	06-100-PMB	Inspect B PMI	12-Aug-2023 07:47:11	BTRUCK	P	DON	55.35
11-Aug-2023 1	202,099		696165	38-100-PMA	Service A PMI	12-Aug-2023 08:27:08	BTRUCK	P	DON	95.40
11-Aug-2023 1	202,099		696165	24-034-006	Repair Warning Lamps - Special Application	12-Aug-2023 09:16:15	BTRUCK	I	DON	37.05
11-Aug-2023 1	202,099		696165	03-002-035	Replace Windshield Wiper & Washer	12-Aug-2023 08:36:25	BTRUCK	I	DON	28.11
06-Dec-2023 0			724979	25-051	Remove General Accessories	07-Dec-2023 15:38:32	BSETUP	Z	DON	348.60
06-Dec-2023 0			724979	02-002	Clean Cab & Sheet Metal		BSETUP	Z	WND	289.69
06-Dec-2023 0			724979	06-100-009	Inspect Safety Check	06-Dec-2023 07:16:56	BTRUCK	I	DON	20.48